# AIRCRAFT MAINTENANCE RECORDS

N 4472K

## AIRFRAME

**LOG BOOK** 



	Total Time		F WORK PERFORMED IBER OF PERSON PERFORMING WORK
RRIED			
		vion "A" Tach: 1327.1 TAT: 3080.7	
		ection IAW the scope and detail of FAR 43 s, inspected and lubricated all flight control	
6. Checked	all lights for pr	oper operation.	minuges.
		tion and serviced to proper pressure. lisc, and calipers.	
6. Repacked	RH brake cali	per w/ new MS 28775-222 O-rings & service	
		a, serviced and charged battery as necessary K-450 ELT & replaced with ACK E-04, SN	
This ELT	has been inspe	ected IAW FAR 91.207 (d), new battery exp	piration date of July 2025.
	instrument par elly of aircraft	nel, engine and flight controls in cockpit are as required.	a for any malfunctions.
12. Lubricate	d entire landing	g gear system.	
		eck of landing gear system satisfactorily.  erformed satisfactory with no leaks noted at	this time.
Service of Wine		I certify that this AIRCRAFT has been	I certify that this AIRCRAFT has been
Airport Road Su thester, VA 2260	ite 107	inspected in accordance with a 100 HOUR inspection and determined to be in	inspected in accordance with an ANNUAL inspection and determined to be in
65-0193	,2	airworthy condition	airworthy condition.
		for John	Chile Son
		Levi Jordan A&P 4044180	Charlie Schoenduby A&P 3/52411 IA
<ul><li>Removed</li><li>Installed</li><li>Installation</li><li>The Aircr</li></ul>	Tach 2 Signal Conv on accomplished in aft identified was	stor on R/H Magneto P-Lead. Verter PN: TACH2 SN: T2-3720015. In accordance with Surefly Tach2 Installation manual #3 repaired and inspected in accordance with current Repaired. Pertinent details are on file at this Repair Station.  CRS#20WR084C Date:	gulations of the Federal Aviation Agency and is
Removed     Installed     Installatic     The Aircr     approved	Existing 400k resi Tach 2 Signal Conv on accomplished in aft identified was If for Return to Sen	stor on R/H Magneto P-Lead. Verter PN: TACH2 SN: T2-3720015. In accordance with Surefly Tach2 Installation manual #3 repaired and inspected in accordance with current Reprice. Pertinent details are on file at this Repair Station.  CRS#20WR084C Date:	gulations of the Federal Aviation Agency and is
Removed Installed Installatio The Aircr approved	Existing 400k resi Tach 2 Signal Conv on accomplished in aft identified was if for Return to Sen	stor on R/H Magneto P-Lead. Ferter PN: TACH2 SN: T2-3720015. In accordance with Surefly Tach2 Installation manual #3 repaired and inspected in accordance with current Reprice. Pertinent details are on file at this Repair Station.  CRS#20WR084C Date:  1344.7 TAT: 2098.4	gulations of the Federal Aviation Agency and is
Removed Installed Installed Installation The Aircr approved  0/29/2020 N44  Adjuster Tighten	Existing 400k resistance of 2 Signal Convolution accomplished in aftidentified was all for Return to Sensitive Tach Time of and tightened Coded Jam nut on Igni	stor on R/H Magneto P-Lead. Verter PN: TACH2 SN: T2-3720015. In accordance with Surefly Tach2 Installation manual #3 Verepaired and inspected in accordance with current Repaired.  CRS#20WR084C  Date:  CRS#20WR084C  Date:  Depilot armrest.  Depilot armrest.  Depilot armrest.	gulations of the Federal Aviation Agency and is
Removed Installed Installed Installatio The Aircr approved  O/29/2020 N44  Adjusted Tighten Tighten	Existing 400k resistance 2 Signal Convolution accomplished in aft identified was all for Return to Sender 1 Sender 2 Sen	stor on R/H Magneto P-Lead. Verter PN: TACH2 SN: T2-3720015. In accordance with Surefly Tach2 Installation manual #3 Verepaired and inspected in accordance with current Repaired.  CRS#20WR084C  Date:  1344.7  TAT: 2098.4	gulations of the Federal Aviation Agency and is
Removed Installed Installed Installed Installed Adjuster Tighten Adjuster Adjuster Tighten Tighten Tighten	Existing 400k resistance 2 Signal Convolution accomplished in aft identified was a for Return to Send 172K. Tach Time and and tightened Coded Jam nut on Ignified Jam nuts on Blud the lever that enteraft was repaired and tightened and tightened Coded Jam nuts on Blud the lever that enteraft was repaired and tightened and tightened code and tightened code and tightened code and tightened and tightened and tightened code and tight	creter PN: TACH2 SN: T2-3720015.  accordance with Surefly Tach2 Installation manual #3 repaired and inspected in accordance with current Repaire. Pertinent details are on file at this Repair Station.  CRS#20WR084C Date:  1344.7 TAT: 2098.4  Depilot armrest	gulations of the Federal Aviation Agency and is  9/21/2020
Removed Installed Installed Installed Installed Adjuster Tighten Adjuster Adjuster Tighten Adjuster Tighten	Existing 400k resistant 2 Signal Convolution accomplished in aft identified was also for Return to Sendard Tack Tach Time and and tightened Code Jam nut on Ignied Jam nuts on Blud the lever that enteraft was repaired a Aviation Agency and Columnia Convolution Agency and Columnia	reter PN: TACH2 SN: T2-3720015.  n accordance with Surefly Tach2 Installation manual #3 repaired and inspected in accordance with current Repaire. Pertinent details are on file at this Repair Station.  CRS#20WR084C Date:  1344.7 TAT: 2098.4  Depilot armrest	gulations of the Federal Aviation Agency and is  9/21/2020  of the
Removed Installed Installed Installed Installed Adjuster Tighten Adjuster Adjuster Tighten Adjuster Tighten	Existing 400k resistant 2 Signal Convolution accomplished in aft identified was also for Return to Sendard Tack Tach Time and and tightened Code Jam nut on Ignied Jam nuts on Blud the lever that enteraft was repaired a Aviation Agency and Columnia Convolution Agency and Columnia	stor on R/H Magneto P-Lead. Verter PN: TACH2 SN: T2-3720015. In accordance with Surefly Tach2 Installation manual #3 Verepaired and inspected in accordance with current Repaire.  CRS#20WR084C  Date:  CRS#20WR084C  Date:  1344.7  TAT: 2098.4  Depilot armrest.  Lion.  L	gulations of the Federal Aviation Agency and is  9/21/2020  of the
Removed Installed Installed Installed Installed Installed Adjuste Tighten Adjuste Adjuste Tighten Adjuste The airc	Existing 400k resistant 2 Signal Convolution accomplished in aft identified was also for Return to Sendard Tack Tach Time and and tightened Code Jam nut on Ignied Jam nuts on Blud the lever that enteraft was repaired a Aviation Agency and Columnia Convolution Agency and Columnia	stor on R/H Magneto P-Lead. Verter PN: TACH2 SN: T2-3720015. In accordance with Surefly Tach2 Installation manual #3 Verepaired and inspected in accordance with current Repaire.  CRS#20WR084C  Date:  CRS#20WR084C  Date:  1344.7  TAT: 2098.4  Depilot armrest.  Lion.  L	gulations of the Federal Aviation Agency and is  9/21/2020  of the

TOTAL - CARRY FORWARD TO NEXT PAGE

## AIRCRAFT MAINTENANCE RECORD Page No.

	Total Time	DESCRIPTION OF WOR SIGNATURE & CERTIFICATE NUMBER OF	
RRIED			
WARD			
	November 20, 202	20 N4472K Navion "A" Tach: 3105.5	TAT: 3105.5
		1id Cycle oil service.	
		s to proper pressure.	
	3. Lubricated c		
	4. Post mainten	ance turn performed satisfactory with no leal	ks noted at this time.
	Aero Service of Winche	ester. Inc.	
	615 Airport Road Suite	: 107	
	Winchester, VA 22602 540-665-0193	1/1/10	
	340-003-0193	Charlie Schoenduby A	&P4152411 IA
		Charle Schoelidaby A	at 3132411 IA
	D 1 20 2020	NA450V N : "449 F 1 125/1 FAT	2100.0
	,	N4472K Navion "A" Tach: 1356.1 TAT	: 3109.8
	Model # D3A320	op from H&H Propeller,	
	SN: 832479	С409-В	
		e turn performed satisfactory with no leaks no	ated at this time
	2. Toot mantenance	turn performed substactory with no leaks no	red at this time.
	Aero Service of Winchester,	Inc.	
	615 Airport Road Suite 107 Winchester, VA 22602		
	540-665-0193	Levi Jordan A&P 4044180	
		Levi Jordan A&P 4044180	
Nove	ember 29, 2021 N447	72K Navion "A" Tach: 1371.9 TAT: 312	5.5
1	Performed Annual In	spection IAW the scope and detail of FAR 4	3 Appendix D.
2.	Opened all access pan	els, inspected and lubricated all flight contro	l linkages.
<b>—</b> 3.	Checked all lights for	proper operation.	
4.	Inspected tires for con	dition and serviced to proper pressure.	
5.		s, disc, and calipers, installed new LH & RH	
6.		rea, serviced and charged battery as necessar	
7.		spected IAW FAR 91.207 (d), w/ battery exp	
8.		panel, engine and flight controls in cockpit ar	rea for any malfunctions.
9.	Replaced manifold pro		
	Replaced air induction		
		o switch for gear warning horn.	
10	. Cleaned belly of aircra		
	. Lubricated entire land		
13.		check of landing gear system satisfactorily.	
13.	. Post maintenance turn	performed satisfactory with no leaks noted	at this time.
13.			I certify that this AIRCRAFT has been
13. 14. 15.		Legrify that this AIRCRAFT has been	
13. 14. 15. Aero Se	ervice of Winchester, Inc.	I certify that this AIRCRAFT has been inspected in accordance with a 100 HOUR	inspected in accordance with an ANN
13. 14. 15. Aero So 615 Air		I certify that this AIRCRAFT has been inspected in accordance with a 100 HOUR inspection and determined to be in	inspection and determined to be in
13. 14. 15. Aero So 615 Air	ervice of Winchester, Inc. port Road Suite 107 ster, VA 22602	inspected in accordance with a 100 HOUR	
13. 14. 15. Aero So 615 Air Wincher	ervice of Winchester, Inc. port Road Suite 107 ster, VA 22602	inspected in accordance with a 100 HOUR inspection and determined to be in	inspection and determined to be in
13. 14. 15. Aero So 615 Air Wincher	ervice of Winchester, Inc. port Road Suite 107 ster, VA 22602	inspected in accordance with a 100 HOUR inspection and determined to be in airworthy condition.	
13. 14. 15. Aero So 615 Air Wincher	ervice of Winchester, Inc. port Road Suite 107 ster, VA 22602	inspected in accordance with a 100 HOUR inspection and determined to be in	inspection and determined to be in airworthy condition.
13. 14. 15. Aero So 615 Air Wincher	ervice of Winchester, Inc. port Road Suite 107 ster, VA 22602	inspected in accordance with a 100 HOUR inspection and determined to be in airworthy condition.	inspection and determined to be in airworthy condition.
13. 14. 15. Aero So 615 Air Wincher	ervice of Winchester, Inc. port Road Suite 107 ster, VA 22602 -0193	inspected in accordance with a 100 HOUR inspection and determined to be in airworthy condition.	inspection and determined to be in airworthy condition.

	AIRC	RAFT MAINTENANCE RECORD Page No
Date	Total Time	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK
ARRIED -		
3-4-202	22 N4472K	Navion S/N: NAV-4-1472 TACH 3141.7
system	and performed o	O" rings for RH MLG actuator AN6227-9 and (3) AN6227-23. Serviced hydrau perational check no leaks detected. All work accomplished in accordance with ad maintenance manuals.
615 Air	rvice of Winchester, port Road Suite 107 ster, VA 22602	Inc
540-665		
		1 am
		Nicholas Bousquet AP3359966
Start Date:	07/05/2022 <b>N447</b>	72V Tark Time 44404
- Start Date:	07/05/2022 <b>N447</b>	72K Tach Time: 1410.1
PN:190-02472-01 but will not indic	4 Rev.A, and recalibrated L Rev.11, AC 43.13-1B wit	20232-00, performed Nav database update to G3x, updated G3x Software to 9.01, performed Garmin STC Service of the main and tip tanks. Installation & Operational checkout complied with, ref; Garmin G3x installation manual the change 1, AC 43.13-2 and Navion Service Manual Dated 1949. Main tank will indicate up to 30 gallons correctly is placarded that Main Tank will indicate only to 30 gallons. Similar instances are noted in the Navion Service I.
	lewed Gol	AP# 4432100 Date: 07/12/2022
ts found, unable to re	eplicate pilot reported e epaired and inspected in	accordance with current Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent
101	-	CRS# 20WR084C Date: 03/10/2022

SUB-TOTAL THIS PAGE

TOTAL - CARRY FORWARD TO NEXT PAGE

### AIRCRAFT MAINTENANCE RECORD

DESCRIPTION OF WORK PERFORMED **Total Time** ate SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK anuary 19, 2023 N4472K Navion "A" Tach: 1424.7 TAT: 3178.4 Performed Annual Inspection IAW the scope and detail of FAR 43 Appendix D. Opened all access panels, inspected and lubricated all flight control linkages. 2. 3. Checked all lights for proper operation. Inspected tires for condition and serviced to proper pressure. Checked brake linings, disc, and calipers. Cleaned battery box area, serviced and installed Gill G-35 battery, SN: G03172397. This ELT has been inspected IAW FAR 91.207 (d), w/ battery expiration date of July 2025. Inspected instrument panel, engine and flight controls in cockpit area for any malfunctions. Cleaned belly of aircraft as required. 10. Replaced electric fuel pump with O/H unit, PN: 4140-00-17CJ. SN: 18585-18592. 11. Disassembled, cleaned and resealed right MLG strut. Re-installed and serviced with 5606 & nitrogen. 12. Serviced left MLG and nose strut with nitrogen as necessary. 13. Lubricated entire landing gear system. 14. Performed functional check of landing gear system satisfactorily. 15. Post maintenance turn performed satisfactory with no leaks noted at this time. C/W AD52-26-01Stab spar web - By inspection. Next due @ Tach: 1524.7 C/W AD55-01-01- Fuselage frame cracks - By inspection. Next due @ Tach: 1524.7 C/W AD59-06-04 - Hydraulic actuating cylinders - By inspection per SL 79. Next due 1/2024. C/W AD62-03-03 - Landing gear selector valve - By inspection per SL 81. Next due 1/2024. C/W AD68-20-06 - Rudder horn - By inspection. Next due 1/2024. I certify that this AIRCRAFT has been Aero Service of Winchester, Inc. inspected in accordance with an ANNUAL 615 Airport Road Suite 107 Winchester, VA 22602 inspection and determined to be in airworthy condition. 540-665-0193 Charlie Schoenduby A&P 3152411 IA ebruary 8, 2024 N4472K Navion "A" Tach: 1441.9 TAT: 3195.6 1. Performed Annual Inspection IAW the scope and detail of FAR 43 Appendix D. Opened all access panels, inspected and lubricated all flight control linkages. Replaced RH elevator outboard bearing w/ PN: MS27640-3A. 4. Replaced LH three (3) elevator trimtab bushings w/ PN: NAS75-3-003 bushings. 5. Checked all lights for proper operation. 6. Inspected tires for condition and serviced to proper pressure. Checked brake linings, disc, and calipers. 8. Cleaned battery box area, serviced battery. This ELT has been inspected IAW FAR 91.207 (d), w/ battery expiration date of July 2025. 10. Inspected instrument panel, engine and flight controls in cockpit area for any malfunctions. 11. Cleaned belly of aircraft as required. 12. Lubricated entire landing gear system. 13. Serviced all struts with nitrogen of proper level. 14. Performed functional check of landing gear system satisfactorily. 15. Replaced O-ring at hydraulic pump fitting and serviced reservoir. 16. Replaced induction filter with new BA-8103-1. 17. Post maintenance turn performed satisfactory with no leaks noted at this time. AD52-26-01Stab spar web - By inspection. Next due @ Tach: 1524.7 AD55-01-01- Fuselage frame cracks - By inspection. Next due @ Tach: 1524.7 C/W AD59-06-04 – Hydraulic actuating cylinders – By inspection per SL 79. Next due 2/2025. C/W AD62-03-03 - Landing gear selector valve - By inspection per SL 81. Next due 2/2025.

Aero Service of Winchester, Inc. 615 Airport Road Suite 107 Winchester, VA 22602 540-665-0193

C/W AD68-20-06 - Rudder horn - By inspection. Next due 2/2025.

I certify that this AIRCRAFT has been inspected in accordance with an ANNUAL inspection and determined to be in airworthy condition.

Charlie Schoenduby A&P 3152411 IA