United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SA697SW

This coolificals, issued be

J. W. Miller Aviation, Inc. C. E. Oberholtzer-President HSB Box 7757

Marble Falls, Texas 78654

coolifies that the change in the type design for the following product with the limitations and conditions

therefor as specified horson meets the sireworthiness requirements of Part 3 of the CIVII AIT

Original Fooduct - Type Contificate Number: 1A10

Make: Piper

Model: PA-23, PA-23-160, PA-23-235, PA-23-250

Dissoription of Typo Dissign Change:

Installation of one-piece windshield in accordance with J. W. Miller Aviation Drawing List No. 9000 dated 9/21/66, or later FAA approved revision.

Limitations and Conditions:

Compatibility of this modification with other previously approved modifications must be determined by the installer.

This corlificate and the supporting data which is the basis for approval shall romain in effect until som vendered, suspended, revoked, or a larmination dato is at rowins astablished by the Administrator of the

Federal Aviation Administration

The of opplication: September 22, 1966

The farmer: September 29, 1966

Data reisessed: 7/1/68; 2/16/70; 3/14/83 Revision 3

Dala amended:

By direction of the Ac

ALDon P. Watson

Manager, Aircraft Certification Division

Southwest Region

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.



Autopilots Central, Inc.

Hangar 23, Tulsa International Airport - Tulsa, OK 74115 P.O. Box 582108 - Tulsa, OK 74158 (918)836-6418 - Fax (918)832-0136 FAA CRS CM2R747K

Invoice

Work Order: Acct Number:

Department:

AV04-01158 (817)401-1617

Autopilot

Opened: 6/7/2004 Closed:

6/11/2004

Sold To: Robert W Petrie

7217 Charlene Ct. Azle, TX 76020-4381

		Type:PIPER PA 23-250 AZTE	S/N: 27-3958	
Aircraft Number: N6644Y	N6644Y			Prop Time
Eng# Type	S/N	Time Cycles Prop Type		
1				

Discrepancy: 1

Problem:

Altimatic III, complete autopilot tune up.

Ground test - Removed A/H, D.G., radio coupler, controller, alt. hold, roll servo, pitch servo, trim sensor, relay box, computer and trim servo for bench test.

Discrepancy: 2

Problem:

1C388 Radio Coupler S/N P2173E

Bench test.

Bench check found units serial number below 6000, unit would cost more than an exchange. Exchanged for unit S/N P-18799G.

Discrepancy: 3

Problem:

KT76A Transponder P/N 066-1062-00 S/N 70888

Bench test.

Ident. stuck on. Found photocell recessed with leads severely bent. Ident switch would intermittently bind up in photocell and not release. Straightened photocell leads and refitted cell to faceplate. Ident function now ok. Bench test found pulse width too narrow. Adjusted pulse width to mfgs. specifications.

Discrepancy: 4

Problem:

1D396 Console S/N 1299B

Bench test.

Bench check found all switches need cleaned and regreased, trim meter caps need changed. Replaced trim meter capacitors C1 and C2. Cleaned and regreased mode engage switches. Bench tested to specs IAW Edo Manual 68S371.

Discrepancy: 5

Problem:

1C508-1-184P Pitch Servo S/N 017

Bench test.

Bench check found servo ran in plane, but would not run on bench. Remove direction switch. Replace hex connector.

Suggest O/H, cable and clamps

Overhauled and certified per APC-2 Manual.

Page: 1 of 3 Work Order: AV04-01158 9:51 AM Printed: 6/11/2004

iscrepancy: 13

Problem:

1C515 Computer S/N 3011.

Bench test.

Action Taken:

Bench check found computer has 395 board, should be 1C515-1. Exchanged unit 1C515-1 for S/N 2531B.

Discrepancy: 14

Problem:

Reinstall components.

Action Taken:

Installed all autopilot components, set trim tension/safety wire. Closed up aircraft for test flight.

Discrepancy: 15

Problem:

Test fly and calibrate autopilot.

Action Taken:

Test flew and calibrated autopilot. System test flew good

Discrepancy: 16

Problem:

Close aircraft.

Action Taken:

Reinstalled radio coupler after test flight. Reinstalled interior and ramp tested autopilot after all interior and radio coupler

Miscellaneous Charges:

Totals:

SubTotal:	2	7 504 40
OK Sales Tax:	· ·	7,524.42
	\$	315.82
Total Charges:	\$	7.840.24

Misc Supplies: \$

69.47

The articles and/or work hereon described is/are certified airworthy, (unless otherwise specified). Autopilots Central, Inc.

FAA CRS GM2R747K

toule

Authorized Signature

d: 6/11/2004 9:51 AM

Work Order: AV04-01158

Page: 3 of 3