

N	6644Y			
Front	<input type="checkbox"/>		Rear	<input type="checkbox"/>
Left	<input type="checkbox"/>		Right	<input type="checkbox"/>



*Don't Take-Off Without Us!®*

# PROPELLER LOGBOOK

American Propeller Service  
a division of Ameritech Industries, Inc.

FAA REPAIR STATION #NO3R717L

[www.americanpropeller.com](http://www.americanpropeller.com)  
[service@americanpropeller.com](mailto:service@americanpropeller.com)

20208 Charlanne Drive  
Redding, California 96002, U.S.A.  
(530) 221-4470 / (800) 292-7767



# PROPELLER MAINTENANCE RECORDS

Log No. \_\_\_\_\_

Aircraft Registration No.	N6644Y
Propeller Manufacturer	HARTZELL
Hub Model	HC-E2YR-2RBSF
Hub Serial No.	BP9864B
Blade Design No.	F8465-7R
Blade Serial No.	
1.	F47907
2.	E50124
3.	
4.	
5.	
6.	
7.	
8.	
9.	

Pitch Range:


Low 14.5° High / Latch 20.0°  
Feather 80.0° Reverse \_\_\_\_\_

## Governor Manufacturer

Model No. \_\_\_\_\_

Serial No. \_\_\_\_\_

For technical support call: 800-292-7767

DATE	TSN	TSO	DESCRIPTION OF WORK PERFORMED
5/3/23		0.0	SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
			 <p>AMERITECH INDUSTRIES DBA AMERICAN PROPELLER SERVICE REPAIR STATION No. NO3R717L 20208 CHARLANNIE DRIVE REDDING, CA 96002 USA</p>
			WORK ACCOMPLISHED <u>COMPLETE OVERHAUL</u>
			MODEL NO. <u>HC-E2YR-2RBSF</u>
			SERIAL NO. <u>BP9864B</u>
			THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER
			REPAIR ORDER # <u>27501-03-2023</u>
			DATED: <u>05-04-2023</u>
			SIGNED <u>Todd M. L.</u> TODD MARINKOVICH (AUTHORIZED INDIVIDUAL)
			FORM LB01