OWNER:	GARDINER TRANSPORT LLC	OPERATOR:	EAST COAST FLIGHT SERVICES, INC.	OPERATOR:	AIR REPAIR INC.
ADDRESS:	2124 PRIEST BRIDGE DR CROFTON MD 21114	ADDRESS:	29111 NEWNAM RD EASTON MD 21601	ADDRESS:	29137 NEWNAM ROAD EASTON MD 21601
OFFICE:		OFFICE:	410-822-2999	OFFICE:	4108222999
FAX:		FAX:	410-820-7568 (ANNE)	FAX:	

ANALYST:	SARAH ALY	877-411-CAMP (2267) (OFFICE)	800-787-9749 (EFAX-CARDS)	PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).
EMAIL:	SALY@CAMPSYSTEMS.COM	631-588-3200 (OFFICE) WWW.CAMPSYSTEMS.COM	631-980-4222 (FAX)	

AIRCRAFT

SERIAL/REGNO: 224/N312WM MODEL: FALCON 50 MANUFACTURER: DASSAULT AVIATION S.A.

CERTIFICATION DATE: 24-OCT-1991

LAST ACTUALS:

8992.1	A/C HRS	as of 29-OCT-2023
5796	AFL	as of 29-OCT-2023
5115.9	APH	as of 29-OCT-2023

APU

SERIAL/PART: P-331/3800016-3-1 MODEL: GTCP36-100(A) MANUFACTURER: HONEYWELL

INSTALLED ON: 12-FEB-1992

0	APU HRS	0 A/C HRS
0	APUS	

LAST ACTUALS:

5115.9	APU HRS	as of 29-OCT-2023
1117	APUS	as of 05-NOV-2021

ENGINE NO. 1

SERIAL/PART: P-76815/3072800-5 MODEL: TFE731-3-1C MANUFACTURER: HONEYWELL

INSTALLED ON: 14-AUG-2015

7952.5	ENG. HRS	8241.2 A/C HRS
5124	ENC	

LAST ACTUALS:

8703.4	ENG. HRS	as of 29-OCT-2023
5796	ENC	as of 29-OCT-2023

ENGINE NO. 2

SERIAL/PART: P-76813/3072800-5 MODEL: TFE731-3-1C MANUFACTURER: HONEYWELL

INSTALLED ON: 13-FEB-2014

7993.6	ENG. HRS	8106.6 A/C HRS
5148	ENC	

LAST ACTUALS:

8879.1	ENG. HRS	as of 29-OCT-2023
5704	ENC	as of 29-OCT-2023

ENGINE NO. 3

SERIAL/PART: P-76814/3072800-5 MODEL: TFE731-3-1C MANUFACTURER: HONEYWELL

INSTALLED ON: 12-JUN-2015

8072.7	ENG. HRS	8203.4 A/C HRS
5214	ENC	

LAST ACTUALS:

8861.4	ENG. HRS	as of 29-OCT-2023
5708	ENC	as of 29-OCT-2023

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
3645 STORAGE		REVIEW STORAGE / RETURN TO SERVICE OF AIRCRAFT REQUIREMENTS								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
3645-150915-1		REVIEW DASSAULT AVIATION FALCON 50 AND 50EX MPD CHAPTER 5 REVISION 5, DATED JULY 2015 - SUMMARY CHANGE FORM								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 3645					
3645-150915-2		REVIEW DASSAULT AVIATION FALCON 50/50EX: MPD CHAPTER 5-40 REVISION 23, DATED JULY 2015-SUMMARY CHANGE FORM								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 3645					
3645-150915-3		REVIEW FALCON 50/50EX MAINTENANCE MANUAL CHAPTER 5-40 AIRWORTHINESS LIMITATIONS - REVISION 23 ERRATUM - SUMMARY CHANGE FORM								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 3645					
3645-170701		REVIEW DASSAULT AVIATION FALCON 50 AND 50EX MPD CHAPTER 5 REVISION 6, DATED JULY 2017 - SUMMARY CHANGE FORM								Service ATA:00
	MOS/MSC	EFF	-							
	HRS									
	AFL									
					PROC. REF: GENERIC NO REF					
3645-170809		REVIEW DASSAULT AVIATION FALCON 50 MPD CHAPTER 5-40 REVISION 24, DATED JULY 2017 - SUMMARY CHANGE FORM								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
3645-180322		REVIEW DOCUMENT DISCREPANCIES DD 1-310213311, 1-298499274, AND 1-303915014								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
3645-180405		REVIEW FALCON 50 MPD DOCUMENT DISCREPANCY 1-310597778 CHANGES								Service ATA:00
	MOS/MSC		-							
	HRS									
	AFL									
					PROC. REF: RCF 3645					
3645-180612		REVIEW FALCON 50 MAINTENANCE PLANNING DOCUMENT (MPD) DOCUMENT DISCREPANCIES (DD) DATE 12-JUN-2018								Service ATA:00
	MOS/MSC		-					STC-SUPPLEMENTAL TYPE CERTIFICATE		
	HRS									
	AFL									
					PROC. REF: RCF 3645					
3645-180701		REVIEW MAINTENANCE PLANNING DOCUMENT CHAPTER 5 REVISION 7 - JULY 2018 CHANGES								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 3645					
3645-190808		REVIEW MAINTENANCE PLANNING DOCUMENT (MPD) DOCUMENT DISCREPANCY 1-345369346 RESPONSE DATE 08 AUGUST 2019								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 3645					
3645-200201		REVIEW FALCON 50 MAINTENANCE PLANNING DOCUMENT CHAPTER 5 - REVISION 8 FEBRUARY 2020								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 3645					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
3645-STORAGE		REVIEW STORAGE / RETURN TO SERVICE OF AIRCRAFT REQUIREMENTS								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	AFL									
					PROC. REF: RCF 3645					
A004-161102		APU - REVIEW SIL APU-56 (D199709000077) REVISION 2								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	APUS									
					PROC. REF: RCF A004-161102					
A004-170103		APU - REVIEW HONEYWELL GTCP36-100(A) TR 49-38								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	APUS									
					PROC. REF: RCF A004					
A004-180112		APU - REVIEW HONEYWELL GTCP 36-100(A) APU-49 SIL REV 10								Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS		
	HRS									
	APUS									
					PROC. REF: RCF APU-SIL-49					
ADS-B OUT STATUS		AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT COMPLIANT								Component ATA:00
PN:CONFIRMATION FROM FLIGHT AWARE DATA	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
E005-190122		NO. 1 ENGINE - REVIEW TFE731-3A-200G LMM REV 08								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
					PROC. REF: RCF E005					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
E005-190122		NO. 2 ENGINE - REVIEW TFE731-3A-200G LMM REV 08								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
					PROC. REF: RCF E005					
E005-190122		NO. 3 ENGINE - REVIEW TFE731-3A-200G LMM REV 08								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS		
	HRS									
	ENC									
					PROC. REF: RCF E005					
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-08-00-200-800-15		12 M INSPECTION								Package ATA:05
	MOS	08-Sep-23	12 (+1m)	Adj -1d	07-Sep-24	07-Oct-24	311 d (+30)			
	HRS	8967								
	AFL	5775								
					PROC. REF: MPD 05-10-00					PKG:15
05-08-00-200-800-16		24 M INSPECTION								Package ATA:05
	MOS	08-Sep-23	12 (+1m)	Adj -1d	07-Sep-24	07-Oct-24	311 d (+30)			
	HRS	8967								
	AFL	5775								
					PROC. REF: MPD 05-10-00					PKG:16
05-08-00-200-800-17		36 M INSPECTION								Package ATA:05
	MOS	07-Sep-22	36 (+1m)		07-Sep-25	07-Oct-25	676 d (+30)			
	HRS	8823								
	AFL	5651								
					PROC. REF: MPD 05-10-00					PKG:207
05-08-00-200-800-21		1B INSPECTION								Package ATA:05
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)		10323	10353	1330.9 (+30)			
	AFL	5651								
					PROC. REF: MPD 05-10-00					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-08-00-200-800-22	2B INSPECTION									Package ATA:05
	MOS	17-Dec-10								
	HRS	7458.3	3000 (+30)		10458.3	10488.3	1466.2 (+30)			
	AFL	4759								
					PROC. REF: MPD 05-10-00					PKG:22
05-08-00-200-800-23	3B INSPECTION									Package ATA:05
	MOS	17-Dec-10								
	HRS	7458.3	4500 (+30)		11958.3	11988.3	2966.2 (+30)			
	AFL	4759								
					PROC. REF: MPD 05-10-00					PKG:23
05-08-00-200-800-24	4B INSPECTION									Package ATA:05
	MOS	10-Dec-03								
	HRS	4936.4	6000 (+30)	Adj -478.1	10458.3	10488.3	1466.2 (+30)			
	AFL	3069								
					PROC. REF: MPD 05-10-00					PKG:24
05-08-00-200-800-31	1C INSPECTION									Package ATA:05
	MOS	07-Sep-22	72 (+2m)		07-Sep-28	07-Nov-28	1772 d (+61)			
	HRS	8823								
	AFL	5651								
					PROC. REF: MPD 05-10-00					PKG:31
05-08-00-200-800-32	2C INSPECTION									Package ATA:05
	MOS	07-Mar-16	144 (+2m)	Adj 184d	07-Sep-28	07-Nov-28	1772 d (+61)			
	HRS	8278.1								
	AFL	5347								
					PROC. REF: MPD 05-10-00					PKG:32
05-08-00-200-800-33	3C INSPECTION									Package ATA:05
	MOS/MSC	16-Dec-09	N/A							
	HRS	7169.2								
	AFL	4516								
					PROC. REF: MPD 05-10-00					PKG:33
05-08-00-200-800-34	4C INSPECTION									Package ATA:05
	MOS/MSC	07-Mar-16	N/A							
	HRS	8278.1								
	AFL	5347								
					PROC. REF: MPD 05-10-00					PKG:34

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-08-00-200-800-35	5C INSPECTION									Package ATA:05
	MOS/MSC	07-Sep-22	N/A							
	HRS	8823								
	AFL	5651								
					PROC. REF: MPD 05-10-00					PKG:35
05-50-00-100-801-01	CLEANING AFTER ELECTROLYTE SPILLAGE									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 24.310	AFL	0								
					PROC. REF: AMM 05-50-00-100-801					
05-50-00-200-801-01	CHECK AFTER A TOWING INCIDENT									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 32.160	AFL	0								
					PROC. REF: AMM 05-50-00-200-801					
05-50-00-200-802-01	CHECK AFTER HAILSTORM									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 51.070	AFL	0								
					PROC. REF: AMM 05-50-00-200-802					
05-50-00-200-803-01	CHECK AFTER A LIGHTNING STRIKE									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 51.080	AFL	0								
					PROC. REF: AMM 05-50-00-200-803					
05-50-00-200-804-01	CHECK AFTER A REJECTED TAKE-OFF OR EMERGENCY BRAKING									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 32.205	AFL	0								
					PROC. REF: AMM 05-50-00-200-804					
05-50-00-200-805-01	CHECK AFTER FLYING UNDER EXCESSIVE LOAD FACTOR OR THROUGH EXCESSIVE TURBULENCE									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 51.060	AFL	0								
					PROC. REF: AMM 05-50-00-200-805					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-200-806-01	CHECK AFTER AIRCRAFT TILTING BACKWARD DURING MAINTENANCE OR POWER BACK OPERATIONS								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-200-806					
05-50-00-200-809-01	INSPECTION AFTER SLAT OPERATION IN OVERSPEED CONDITION								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-200-809					
05-50-00-200-810-01	INSPECTION AFTER FLAP OPERATION IN OVERSPEED CONDITION								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-200-810					
05-50-00-200-812-01	INSPECTION AFTER LANDING GEAR EXTENSION IN OVERSPEED CONDITION								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-200-812					
05-50-00-200-813-01	CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE AT TAKE OFF OR LANDING								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 32.260	AFL	0								
					PROC. REF: AMM 05-50-00-200-813					
05-50-00-200-817-01	CHECK AFTER COLLISION WITH FOREIGN OBJECT								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-200-817					
05-50-00-200-822-01	OPERATION TO BE PERFORMED AFTER VMO/MMO EXCEEDANCE								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-200-822					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-200-823-01	CHECK OF THE SLATS AFTER OVERHEATING - LH WING								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-200-823					
05-50-00-200-823-02	CHECK OF THE SLATS AFTER OVERHEATING - RH WING								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-200-823					
05-50-00-620-801-01	SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-620-801					
05-50-00-620-803-01	SPECIFIC MAINTENANCE FOR A/C OPERATING IN COLD WEATHER								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 05.020	AFL	0								
					PROC. REF: AMM 05-50-00-620-803					
05-50-00-620-804-01	PROCEDURE FOR AIRCRAFT PROLONGED OPERATION AT LOW TEMPERATURES								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 51.100	AFL	0								
					PROC. REF: AMM 05-50-00-620-804					
05-50-00-620-805-01	SPECIFIC MAINTENANCE TO PREVENT FUEL CONTAMINATION - CRITERIA TO DEFINE A/C AT RISK OF FUEL CONTAMINATION								Service	ATA:05
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-620-805					
05-50-00-620-805-02	SPECIFIC MAINTENANCE TO PREVENT FUEL CONTAMINATION								Service	ATA:05
	MOS/MSC	08-Sep-23	A/R							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 05-50-00-620-805					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-700-803-01	CHECK AFTER FIRE EXTINGUISHER PERCUSSION									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 20.020	AFL	0								
					PROC. REF: SL 20-350, AMM 05-50-00-700-803					
05-50-00-700-807-01	CHECK AFTER LANDING ON A DRY AND DIRTY RUNWAY									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 32.205	AFL	0								
					PROC. REF: AMM 05-50-00-700-807					
05-50-00-700-808-01	CHECK AFTER HARD / OVERWEIGHT LANDING									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 32.160	AFL	0								
					PROC. REF: AMM 05-50-00-700-808					
05-50-00-700-810-01	CHECK AFTER SAND CONDITION - CHECKS AFTER EACH FLIGHT THROUGH SAND									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-700-810					
05-50-00-700-810-02	CHECK AFTER SAND CONDITION - FURTHER INSPECTIONS IN CASE OF SAND DEPOSITS AFTER FLIGHT THROUGH SAND									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-700-810					
05-50-00-700-810-03	CHECK AFTER SAND CONDITION - PERIODIC INSPECTIONS AND CHECKS AFTER FLIGHTS THROUGH SAND									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-700-810					
05-50-00-700-810-04	CHECK AFTER SAND CONDITION - INSPECTIONS AND CHECKS AFTER A SANDSTORM (AIRCRAFT PARKED)									Service ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-700-810					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-700-818-01	CHECK AFTER AN ELECTRICAL FIRE								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-700-818					
05-50-00-700-822-01	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-700-822					
05-50-00-700-822-02	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - FURTHER CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-700-822					
05-50-00-700-822-03	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS AFTER EXCEPTIONAL FLIGHT THROUGH A HIGH VOLCANIC ASH CONCENTRATION AREA								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-700-822					
05-50-00-700-822-04	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-700-822					
05-50-00-700-822-05	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A HEAVY VOLCANIC ASH FALLOUT AREA								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-700-822					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-730-802-01	CHECK OF THE BRAKING SYSTEM AT ACCELERATION/STOP AFTER TROUBLESHOOTING								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 05-50-00-730-802					
05-50-00-860-801-01	CHECK AND PREPARATION FOR FLIGHT WITH ONE ENGINE INOPERATIVE								Service	ATA:05
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 71.090	AFL	0								
					PROC. REF: AMM 05-50-00-860-801, AMM 05-50-00-860-801					
05-50-00-910-801-01[S]	AIRCRAFT CHECK FLIGHT								Service	ATA:05
	MOS	07-Sep-22	72 (+3%)							
	HRS	8823								
WC#: 51.020	AFL	5651								
					PROC. REF: AMM 05-50-00-910-801					PKG:31
05-60-00-200-801-01	BASIC INSPECTION								Service	ATA:05
	MOS	08-Sep-23	12 (+1m)	Adj -1d	07-Sep-24	07-Oct-24	311 d (+30)			
	HRS	8967	300 (+30)		9267	9297	274.9 (+30)			
WC#: 05.010	AFL	5775								
					PROC. REF: MPD 05-10-00, AMM 05-60-00-200-801					
05-60-00-200-801-03	BASIC INSPECTION - GROUND SERVICING CHECKS								Service	ATA:05
	MOS	08-Sep-23	12 (+1m)	Adj -1d	07-Sep-24	07-Oct-24	311 d (+30)			
	HRS	8967	300 (+30)		9267	9297	274.9 (+30)			
WC#: 05.010	AFL	5775								
					PROC. REF: MPD 05-10-00, AMM 05-60-00-200-801					
057110	NO. 1 ENGINE - 150/250 HOUR INSPECTION								Package	ATA:05
	MOS	07-Jul-23								
	HRS	8674.8	200 (+50)		(8874.8) 9163.5	8924.8	171.4 (+50)			
	ENC	5769								
					PROC. REF: LMM 72-00-00					PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
057110		NO. 2 ENGINE - 150/250 HOUR INSPECTION								Package ATA:05
	MOS	10-Jan-23								
	HRS	8781.4	200 (+50)		(8981.4) 9094.4	9031.4	102.3 (+50)			
	ENC	5622								
					PROC. REF: LMM 72-00-00					PKG:0
057110		NO. 3 ENGINE - 150/250 HOUR INSPECTION								Package ATA:05
	MOS	10-Jan-23								
	HRS	8763.7	200 (+50)		(8963.7) 9094.4	9013.7	102.3 (+50)			
	ENC	5626								
					PROC. REF: LMM 72-00-00					PKG:0
057120		NO. 1 ENGINE - 300/400 HOUR INSPECTION								Package ATA:05
	MOS	07-Jul-23								
	HRS	8674.8	400		(9074.8) 9363.5		371.4			
	ENC	5769								
					PROC. REF: LMM 72-00-00					PKG:0
057120		NO. 2 ENGINE - 300/400 HOUR INSPECTION								Package ATA:05
	MOS	10-Jan-23								
	HRS	8781.4	400		(9181.4) 9294.4		302.3			
	ENC	5622								
					PROC. REF: LMM 72-00-00					PKG:0
057120		NO. 3 ENGINE - 300/400 HOUR INSPECTION								Package ATA:05
	MOS	10-Jan-23								
	HRS	8763.7	400		(9163.7) 9294.4		302.3			
	ENC	5626								
					PROC. REF: LMM 72-00-00					PKG:0
057130		NO. 1 ENGINE - 600/800 HOUR INSPECTION								Package ATA:05
	MOS	03-Dec-18								
	HRS	8308.8	800		(9108.8) 9397.5		405.4			
	ENC	5327								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
057130		NO. 2 ENGINE - 600/800 HOUR INSPECTION								Package ATA:05
	MOS	10-Jan-23								
	HRS	8781.4	800		(9581.4) 9694.4		702.3			
	ENC	5622								
					PROC. REF: LMM 72-00-00					
057130		NO. 3 ENGINE - 600/800 HOUR INSPECTION								Package ATA:05
	MOS	10-Jan-23								
	HRS	8763.7	800	Adj -2	(9561.7) 9692.4		700.3			
	ENC	5626								
					PROC. REF: LMM 72-00-00					
057140		NO. 1 ENGINE - 1000/1500 HOUR INSPECTION								Package ATA:05
	MOS	19-Dec-11								
	HRS	7512.1	1400 (+100)		(8912.1) 9200.8	9012.1	208.7 (+100)			
	ENC	4826								
					PROC. REF: LMM 72-00-00					
057140		NO. 2 ENGINE - 1000/1500 HOUR INSPECTION								Package ATA:05
	MOS	24-Dec-13								
	HRS	7993.6	1400 (+100)		(9393.6) 9506.6	9493.6	514.5 (+100)			
	ENC	5148								
					PROC. REF: LMM 72-00-00					
057140		NO. 3 ENGINE - 1000/1500 HOUR INSPECTION								Package ATA:05
	MOS	13-Dec-13								
	HRS	7961.7	1400 (+100)		(9361.7) 9492.4	9461.7	500.3 (+100)			
	ENC	5141								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty

ATA 07 - LIFTING AND SHORING

07-10-00-910-801-01	JACKING THE AIRCRAFT									Service ATA:07
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 07-10-00-910-801					
07-10-00-910-802-01	JACKING THE AIRCRAFT BY ONE LANDING GEAR LEG									Service ATA:07
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 07-10-00-910-802					
07-10-00-910-804-01	JACKING THE AIRCRAFT BY ONE MLG LEG WITH A WHEEL RAMP									Service ATA:07
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 07-10-00-910-804					
07-10-00-910-805-01	JACKING THE AIRCRAFT FOR DIMENSIONAL CHECKS AND/OR REPAIR OF THE MLG BALL-JOINT BEARING BORES									Service ATA:07
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 07-10-00-910-805					
07-10-00-910-810-01	HOISTING THE COMPLETE AIRCRAFT									Service ATA:07
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 07-10-00-910-810					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 08 - LEVELING AND WEIGHING										
08-10-00-910-801-01	WEIGHING THE AIRCRAFT - WEIGHING THE AIRCRAFT ON WHEELS									Service ATA:08
	MOS	22-Aug-23	36		22-Aug-26		1025 d			
	HRS	8966.7								
	AFL	5774								
					PROC. REF: AMM 08-10-00-910-801					
08-10-00-910-801-02	WEIGHING THE AIRCRAFT - WEIGHING THE AIRCRAFT ON JACKS									Service ATA:08
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 08-10-00-910-801					
08-20-00-910-801-01	LEVELING THE AIRCRAFT									Service ATA:08
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 08-20-00-910-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 09 - TOWING AND TAXING										
09-10-00-910-801-01	TOWING THE AIRCRAFT WITH A TOWBAR									Service ATA:09
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 09-10-00-910-801					
09-10-00-910-802-01	TOWING THE AIRCRAFT WITH A TOWBARLESS TOWING VEHICLE									Service ATA:09
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 09-10-00-910-802					
09-10-00-910-804-01	ADAPTATION OF MY20 TOWBAR TO F50									Service ATA:09
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 09-10-00-910-804					
09-10-00-910-805-01	TOWING THE AIRCRAFT WITH A TOWBARLESS REMOTE CONTROL TUG									Service ATA:09
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 09-10-00-910-805					
09-10-00-910-810-01	DEBOGGING THE AIRCRAFT									Service ATA:09
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 09-10-00-910-810					
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV										
10-10-00-200-801-01	CHECK AFTER PARKING OF THE AIRCRAFT IN HIGH WIND CONDITIONS									Service ATA:10
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 10-10-00-200-801					
10-10-00-550-801-10	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - NON-FLYING AND NON-STORED PERIOD									Service ATA:10
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 10-10-00-550-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV										
10-10-00-550-801-11	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - STORAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 2 MONTHS								Service	ATA:10
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 20.010	AFL	0								
					PROC. REF: AMM 10-10-00-550-801					
10-10-00-550-801-12	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - ADDITIONAL OPERATIONS FOR STORAGE FROM 2 TO 12 MONTHS								Service	ATA:10
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 20.010	AFL	0								
					PROC. REF: AMM 10-10-00-550-801					
10-10-00-550-801-13	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - STORAGE OF THE AIRCRAFT FOR A PERIOD OF 12 TO 18 MONTHS								Service	ATA:10
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 10-10-00-550-801					
10-10-00-550-801-14	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY MONTH								Service	ATA:10
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 20.010	AFL	0								
					PROC. REF: AMM 10-10-00-550-801					
10-10-00-550-801-15	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY 2 MONTHS								Service	ATA:10
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 20.010	AFL	0								
					PROC. REF: AMM 10-10-00-550-801					
10-10-00-550-801-16	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY 6 MONTHS								Service	ATA:10
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 20.010	AFL	0								
					PROC. REF: AMM 10-10-00-550-801					
10-10-00-550-801-17	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - REMOVAL FROM STORAGE AT THE END OF THE 2 MONTHS OR LESS								Service	ATA:10
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 20.010	AFL	0								
					PROC. REF: AMM 10-10-00-550-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV										
10-10-00-550-801-18	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - REMOVAL FROM STORAGE AFTER MORE THAN 2 MONTHS								Service	ATA:10
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 20.010	AFL	0								
					PROC. REF: AMM 10-10-00-550-801					
10-10-00-910-801-01	PARKING THE AIRCRAFT								Service	ATA:10
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 10-10-00-910-801, AMM 10-10-00-910-801					
10-20-00-910-801-01	MOORING THE AIRCRAFT								Service	ATA:10
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 10-20-00-910-801					
10-20-00-910-802-01	MOORING THE AIRCRAFT IN CASE OF SNOWFALL								Service	ATA:10
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 10.010	AFL	0								
					PROC. REF: AMM 10-20-00-910-802					
ATA 11 - PLACARDS AND MARKINGS										
11-00-00-960-801-01	REPLACEMENT OF THE SELF-ADHESIVE PLACARDS								Service	ATA:11
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 11-00-00-960-801					
11-00-00-960-802-01	REPLACEMENT OF THE DECALS								Service	ATA:11
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 11-00-00-960-802					
11-00-00-960-803-01	REPLACEMENT OF THE STERLING TAPE FOR PIPE MARKINGS								Service	ATA:11
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 11-00-00-960-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-00-00-910-801-01	GENERAL MAINTENANCE AND SAFETY PRECAUTIONS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-00-00-910-801					
20-00-00-910-803-01	USE OF THE AIRCRAFT MAINTENANCE PROCEDURES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-00-00-910-803					
20-00-00-910-807-01	GENERAL GUIDANCE AND SAFETY PRECAUTIONS FOR DANGEROUS PRODUCTS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: GENERIC NO REF					
20-00-00-910-810-01	GENERAL SAFETY PRECAUTIONS FOR PARTS CONTAINING ASBESTOS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-00-00-910-810					
20-10-00-280-801-01	GENERAL INSTRUCTIONS FOR 3D SCANNING								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-10-00-280-801					
20-20-00-900-801-01	REMOVAL / INSTALLATION OF THE ELECTRICAL BONDING BRAIDS								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-20-00-900-801					
20-20-00-910-801-01	ELECTRICAL BONDING PRINCIPLES AND CHECK								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-20-00-910-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-20-00-910-802-01	ANTENNA BONDING REPAIR METHOD								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-20-00-910-802					
20-30-00-330-801-01	TEMPORARY REPAIR AFTER MINOR DAMAGE TO A COMPOSITE MATERIAL COMPONENT								Service	ATA:20
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 51.090	AFL	0								
					PROC. REF: AMM 20-30-00-330-801					
20-30-00-910-803-01	ELECTROSTATIC DISCHARGE (ESD) STANDARD PRACTICES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-30-00-910-803					
20-30-00-910-804-01	GENERAL INSTRUCTIONS FOR REMOVAL / INSTALLATION OF ANTENNAS (WITH POLYURETHANE GASKET)								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-30-00-910-804					
20-30-00-910-805-01	GENERAL INSTRUCTIONS FOR REMOVAL / INSTALLATION OF ANTENNAS (WITHOUT O-RING)								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-30-00-910-805					
20-30-00-910-806-01	GENERAL INSTRUCTIONS FOR REMOVAL / INSTALLATION OF ANTENNAS (WITH O-RING)								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-30-00-910-806					
20-30-00-910-807-01	GENERAL INSTRUCTIONS FOR REMOVAL/INSTALLATION OF HYDRAULIC CHECK VALVES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-30-00-910-807					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-30-00-910-808-01	GENERAL INSTRUCTIONS FOR REMOVAL / INSTALLATION OF ACCESS PANELS AND OPENING / CLOSING OF SERVICE DOORS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-30-00-910-808					
20-31-00-100-802-01	CLEANING OF COCKPIT EQUIPMENT AND INTERIOR FURNISHING								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-802					
20-31-00-100-804-01	CLEANING OF THE WING AND AIR INTAKE LEADING EDGES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-804					
20-31-00-100-806-01	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE LH FEEDER TANK								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-806					
20-31-00-100-806-02	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE RH FEEDER TANK								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-806					
20-31-00-100-806-03	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE CTR FEEDER TANK								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-806					
20-31-00-100-806-04	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE CENTER-WING TANK								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-806					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-31-00-100-806-05	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE LH WING TANK								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-806					
20-31-00-100-806-06	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE RH WING TANK								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-806					
20-31-00-100-807-01	DRY CLEANING OF THE AIRCRAFT EXTERIOR								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-807					
20-31-00-100-808-01	WET CLEANING OF THE AIRCRAFT EXTERIOR - CLEANING THE AIRCRAFT EXTERIOR WITH CONVENTIONAL EQUIPMENT								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-808					
20-31-00-100-808-02	WET CLEANING OF THE AIRCRAFT EXTERIOR - CLEANING THE AIRCRAFT EXTERIOR WITH HIGH-PRESSURE EQUIPMENT								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-808					
20-31-00-100-809-01	DRY ICE CLEANING								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-100-809					
20-31-00-140-801-01	RINSING THE AIRCRAFT EXTERIOR								Service	ATA:20
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 20.060	AFL	0								
					PROC. REF: SL 20-318, AMM 20-31-00-140-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-31-00-350-801-01	BRIGHTENING/POLISHING OF CLADDED ALUMINUM SURFACES OR STAINLESS STEEL SURFACES - BRIGHTENING								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-350-801					
20-31-00-350-801-02	BRIGHTENING/POLISHING OF CLADDED ALUMINUM SURFACES OR STAINLESS STEEL SURFACES - POLISHING								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-350-801					
20-31-00-910-801-01	ON-GROUND DE-ICING AND ANTI-ICING TREATMENT - DE-ICING TREATMENT								Service	ATA:20
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 20.050	AFL	0								
					PROC. REF: SL 20-625, AMM 20-31-00-910-801					
20-31-00-910-801-02	ON-GROUND DE-ICING AND ANTI-ICING TREATMENT - ANTI-ICING TREATMENT								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-910-801					
20-31-00-910-803-01	USE OF PUROGENE								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-31-00-910-803					
20-32-00-360-803-01	PROVISIONAL REPAIR OF LEAKY SCREWS OR RIVETS ON FUEL TANKS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-32-00-360-803					
20-32-00-390-801-01	BASIC SEALING METHODS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-32-00-390-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-32-00-390-802-01	BASIC SEALING METHOD USING PR1422, PR1431, PR1432, PR1436 AND PR1750 SEALANTS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-32-00-390-802					
20-32-00-910-801-01	APPLICATION OF FILLERALU								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-32-00-910-801					
20-32-00-910-802-01	ACCEPTANCE CRITERIA FOR HYDRAULIC LEAKS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-32-00-910-802					
20-32-00-910-803-01	ACCEPTANCE CRITERIA FOR DAMAGE TO FUEL TANK SEALANT								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-32-00-910-803					
20-32-00-910-804-01	BONDING OF SEALS ON RETAINERS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-32-00-910-804					
20-33-00-300-801-01	LAGGING OF AIR CONDITIONING LINES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-33-00-300-801					
20-33-00-300-803-01	REPAIR OF A T40 HYDRAULIC PIPE USING PERMASWAGE UNION FITTINGS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-33-00-300-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-33-00-300-804-01	TEMPORARY REPAIR OF A HYDRAULIC OR WATER PIPE USING RYNGLOK FITTINGS								Service	ATA:20
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-33-00-300-804					
20-33-00-300-805-01	REPAIR OF THE F1024 FLEXIBLE WATER HOSES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-33-00-300-805					
20-33-00-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PIPES								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-33-00-900-801					
20-33-00-900-803-01	REMOVAL / INSTALLATION OF THE FOAM INSULATION ON THE WATER PIPES								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-33-00-900-803					
20-33-00-900-806-01	REMOVAL / INSTALLATION OF THE FUEL PIPES								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-33-00-900-806					
20-33-00-910-801-01	ACCEPTANCE CRITERIA FOR HOSES AND PIPES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-33-00-910-801					
20-33-00-910-802-01	STRAPPING OF THE OXYGEN CAPILLARY TUBE								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-33-00-910-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-33-00-910-805-01	ACCEPTANCE CRITERIA FOR WEAR OF HYDRAULIC PIPES IN ENGINE PYLON AREA								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-33-00-910-805					
20-35-01-910-801-01	GENERAL INSTRUCTIONS APPLICABLE TO CABLES - INSPECTION, DAMAGE CRITERIA, LUBRICATION								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-35-01-910-801					
20-35-02-910-801-01	GENERAL INSTRUCTIONS FOR REMOVAL / INSTALLATION OF "TELEFORCE" FLEXIBLE CONTROL CABLE								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-35-02-910-801					
20-35-02-910-802-01	GENERAL INSTRUCTIONS AND REPAIR APPLICABLE TO "TELEFORCE" FLEXIBLE CONTROL CABLES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-35-02-910-802					
20-35-02-910-803-01	TORQUE INSTRUCTIONS APPLICABLE TO "TELEFORCE" CONTROL CABLE NUTS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-35-02-910-803					
20-41-00-400-801-01	INSTALLATION OF HARRISON COUPLINGS ON PIPING								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-41-00-400-801					
20-41-00-900-801-01	REMOVAL / INSTALLATION OF WIGGINS W991 COUPLINGS								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-00-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-41-00-900-803-01	REMOVAL / INSTALLATION OF WIG-O-FLEX COUPLINGS - WIG-O-FLEX 3601, 3605, 3615, 3655, 3665, 3751 AND 3753 COUPLINGS								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-00-900-803					
20-41-00-900-809-01	REMOVAL / INSTALLATION OF FLEXINOX CLAMPS								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-00-900-809					
20-41-00-900-811-01	REMOVAL / INSTALLATION OF JANITROL AND RIGID BESTOBELL CLAMPS								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-00-900-811					
20-41-00-900-813-01	REMOVAL / INSTALLATION OF MARMAN TYPE "18276" AND "234-538" CLAMPS								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-00-900-813					
20-41-00-900-814-01	REMOVAL / INSTALLATION OF GENERAL CONNECTOR HEAT-EXPANSION COUPLINGS								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-00-900-814					
20-41-00-900-815-01	REMOVAL / INSTALLATION OF SEMCA COUPLINGS								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-00-900-815					
20-41-00-900-816-01	REMOVAL / INSTALLATION OF TYPES BA 2755, BA 2755-1, BA 4005 FLEXIBLE COUPLINGS AND FLEXIBLE PIPING								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-00-900-816					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-41-00-900-817-01	REMOVAL / INSTALLATION OF BRIGGS COUPLINGS ON OXYGEN LINE								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-00-900-817					
20-41-00-910-801-01	TIGHTENING TORQUES FOR SINGLE FLARE COUPLINGS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-41-00-910-801					
20-41-00-910-802-01	GENERAL INSTRUCTIONS FOR USE OF QUICK-DISCONNECT SELF-BLANKING COUPLINGS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-41-00-910-802					
20-41-00-960-802-01	REPLACEMENT OF THE TIGHTENING CONES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-41-00-960-802					
20-41-05-900-801-01	TECHNICAL STANDARD ST78651								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-05-900-801					
20-41-05-900-802-01	TECHNICAL STANDARD ST78652								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-05-900-802					
20-41-05-900-803-01	TECHNICAL STANDARD ST78653								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-05-900-803					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-41-05-900-804-01		TECHNICAL STANDARD ST78654								Component ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-05-900-804					
20-41-05-900-805-01		TECHNICAL STANDARD ST78650								Component ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-05-900-805					
20-41-05-900-806-01		TECHNICAL STANDARD ST78750								Component ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-05-900-806					
20-41-05-900-807-01		TECHNICAL STANDARD ST78751								Component ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-41-05-900-807					
20-42-01-960-802-01		REPLACEMENT OF THE LOCKWIRES								Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-42-01-960-802					
20-42-01-960-803-01		REPLACEMENT OF THE SNAP WIRES								Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-42-01-960-803					
20-42-01-960-804-01		REPLACEMENT OF THE SAFE-T CABLES								Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-42-01-960-804					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-43-00-900-801-01	REMOVAL / INSTALLATION OF L'HOTELLIER P710 LOCKS								Component	ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-43-00-900-801					
20-43-00-910-801-01	STANDARD TORQUES APPLICABLE TO THE AIRCRAFT								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-00-910-801					
20-43-00-910-802-01	INSTRUCTIONS TO IDENTIFY DOOR SPECIAL ATTACHMENT SCREWS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-00-910-802					
20-43-00-910-804-01	FASTENERS STANDARD PRACTICES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-00-910-804					
20-43-02-910-801-01	TECHNICAL STANDARD ST38260								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-02-910-801					
20-43-02-910-802-01	TECHNICAL STANDARD ST38150								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-02-910-802					
20-43-02-910-803-01	TECHNICAL STANDARD ST33186								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-02-910-803					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-43-02-910-805-01	TECHNICAL STANDARD ST38145									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-02-910-805					
20-43-02-910-807-01	TECHNICAL STANDARD ST38476									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-02-910-807					
20-43-02-910-809-01	TECHNICAL STANDARD ST38471									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-02-910-809					
20-43-02-910-810-01	TECHNICAL STANDARD ST38472									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-02-910-810					
20-43-02-910-812-01	TECHNICAL STANDARD ST33188									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-02-910-812					
20-43-02-910-813-01	TECHNICAL STANDARD ST39840									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-02-910-813					
20-43-05-910-801-01	TECHNICAL STANDARD ST39584									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-05-910-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-43-05-910-802-01	TECHNICAL STANDARD ST33731									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-05-910-802					
20-43-06-200-801-01	INSPECTION OF THE RIVETS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-200-801					
20-43-06-910-801-01	TECHNICAL STANDARD ST35780									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-801					
20-43-06-910-802-01	TECHNICAL STANDARD ST35770									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-802					
20-43-06-910-803-01	TECHNICAL STANDARD ST35050									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-803					
20-43-06-910-804-01	TECHNICAL STANDARD ST35072									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-804					
20-43-06-910-805-01	TECHNICAL STANDARD ST35053									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-805					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-43-06-910-806-01	TECHNICAL STANDARD ST35067									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-806					
20-43-06-910-807-01	TECHNICAL STANDARD ST35073									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-807					
20-43-06-910-808-01	TECHNICAL STANDARD ST35656									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-808					
20-43-06-910-809-01	TECHNICAL STANDARD ST35655									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-809					
20-43-06-910-810-01	TECHNICAL STANDARD ST35760									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-810					
20-43-06-910-811-01	TECHNICAL STANDARD ST35750									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-811					
20-43-06-910-812-01	TECHNICAL STANDARD NAS1097 - SPECIFIC 4-MM DIA. RIVETS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-812					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-43-06-910-813-01	TECHNICAL STANDARD ST35731									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-813					
20-43-06-910-814-01	TECHNICAL STANDARD ST35075									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-814					
20-43-06-910-815-01	TECHNICAL STANDARD ST35110									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-815					
20-43-06-910-816-01	TECHNICAL STANDARD ST35070									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-816					
20-43-06-910-817-01	TECHNICAL STANDARD ST35660									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-817					
20-43-06-910-818-01	TECHNICAL STANDARD ST35661									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-818					
20-43-06-910-819-01	TECHNICAL STANDARD ST35666									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-06-910-819					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty

ATA 20 - STANDARD PRACTICES - AIRFRAME

20-43-09-910-801-01	REMOVAL / INSTALLATION OF HI-LOK, HI-LITE AND HI-TIGUE FASTENERS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-09-910-801					
20-43-09-910-802-01	REMOVAL / INSTALLATION OF HELI-COIL THREAD INSERTS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-43-09-910-802					
20-44-00-960-801-01	REPLACEMENT OF THE VELCRO TYPE STRAPS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-44-00-960-801					
20-45-00-640-801-01	INSPECTION / GREASING OF BEARINGS AND BALL-JOINTS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-45-00-640-801					
20-45-00-960-802-01	REPLACEMENT OF THE SARMA-ADR BEARINGS AND BALL-JOINTS OR EQUIVALENT									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-45-00-960-802					
20-45-00-960-803-01	REPLACEMENT OF HUB-MOUNTED BEARINGS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-45-00-960-803					
20-49-00-300-801-01	REPAIR / MODIFICATION OF INSULATION BLANKETS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-49-00-300-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty

ATA 20 - STANDARD PRACTICES - AIRFRAME

20-49-00-910-801-01	BONDING OF INSULATION MATERIAL									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-49-00-910-801					
20-49-00-960-801-01	REPLACEMENT OF THE SELF-ADHESIVE INSULATION									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-49-00-960-801					
20-50-00-300-801-01	TREATMENT OF SCRATCHES ON BRIGHTENED SURFACES									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-50-00-300-801					
20-60-00-370-801-01	APPLICATION OF ALODINE									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-801					
20-60-00-370-802-01	GENERAL PAINTING INSTRUCTIONS - COMPLETE PAINT RENEWAL									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-802					
20-60-00-370-802-02	GENERAL PAINTING INSTRUCTIONS - PAINT TOUCH-UPS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-802					
20-60-00-370-802-03	GENERAL PAINTING INSTRUCTIONS - REMOVAL OF PAINT									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-60-00-370-803-01	APPLICATION OF PU66 CELOMER PAINT SCHEME									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-803					
20-60-00-370-804-01	APPLICATION OF CELOGLISS PAINT									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-804					
20-60-00-370-805-01	APPLICATION OF MAP AERO STATIC F PAINT									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-805					
20-60-00-370-806-01	APPLICATION OF BOLICONE M4 BOLLORE PAINT									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-806					
20-60-00-370-809-01	APPLICATION OF TYPE 5014 AND 5015 POLYURETHANE PRIMERS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-809					
20-60-00-370-810-01	APPLICATION OF NEXTEL PAINT									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-810					
20-60-00-370-811-01	APPLICATION OF SINGLE-COAT DIRECT-ADHERENCE PAINT									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-811					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-60-00-370-812-01	APPLICATION OF JET GLO PAINT									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-812					
20-60-00-370-813-01	APPLICATION OF THE PAINT SCHEME ON COMPOSITE COMPONENTS									Service ATA:20
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 20.040	AFL	0								
					PROC. REF: SL 20-615, AMM 20-60-00-370-813					
20-60-00-370-816-03	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG LEG (L2GF)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-816					
20-60-00-370-816-04	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG LEG (R2GF)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-816					
20-60-00-370-816-05	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG SHOCK ABSORBER (L2GF5)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-816					
20-60-00-370-816-06	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG SHOCK ABSORBER (R2GF5)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-816					
20-60-00-370-816-09	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - NLG LEG (3GF)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-816					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty

ATA 20 - STANDARD PRACTICES - AIRFRAME

20-60-00-370-817-01	APPLICATION OF PREKOTE									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-817					
20-60-00-370-818-01	APPLICATION OF THE PPG EXTERIOR UNDERCOAT									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-818					
20-60-00-370-819-01	APPLICATION OF ANTI-SLIP FINISH ON HIGH VOC PAINT SCHEMES									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-819					
20-60-00-370-821-01	APPLICATION OF MAPAERO WATER-BASED PAINT SCHEME									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-821					
20-60-00-370-822-01	GENERAL ANTI-CORROSION PROTECTION FOR FLIGHT IN SALINE ATMOSPHERE									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-822					
20-60-00-370-823-01	APPLICATION OF SOL-GEL PRODUCTS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-823					
20-60-00-370-826-01	APPLICATION OF SHERWIN-WILLIAMS LOW VOC UNDERCOATS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-826					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-60-00-370-827-01	APPLICATION OF TOP COATS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-827					
20-60-00-370-828-01	POLISHING OF PPG CA8800 EXTERIOR FINISH									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-828					
20-60-00-370-829-01	APPLICATION OF PPG INTERIOR PAINT SCHEME									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-829					
20-60-00-370-830-01	REACTIVE POLYMER TREATMENT FOR EXTERNAL SURFACES									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-830					
20-60-00-370-832-01	APPLICATION / REMOVAL OF ANTI-CORROSION PROTECTION									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-832					
20-60-00-370-835-01	POLISHING OF JETGLO EXPRESS 840 SERIES FINISH									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-835					
20-60-00-370-836-01	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - LH HORIZONTAL STABILIZER LEADING EDGE ADHESIVE ANTI-EROSION STRIPS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-836					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-60-00-370-836-02	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - RH HORIZONTAL STABILIZER LEADING EDGE ADHESIVE ANTI-EROSION STRIPS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-836					
20-60-00-370-836-03	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - VERTICAL STABILIZER LEADING EDGE ADHESIVE ANTI-EROSION STRIPS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-836					
20-60-00-370-836-04	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - LH ENGINE PYLONS ADHESIVE ANTI-EROSION STRIPS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-836					
20-60-00-370-836-05	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - RH ENGINE PYLONS ADHESIVE ANTI-EROSION STRIPS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-836					
20-60-00-370-836-08	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - ATC, DME AND VHF ANTENNAS ADHESIVE ANTI-EROSION STRIPS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-836					
20-60-00-370-836-09	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - NOSE CONE ADHESIVE ANTI-EROSION BOOT								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-370-836					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-60-00-970-801-01	MEASUREMENT OF PAINT THICKNESS ON COMPOSITE COMPONENTS USING A PAINT BORER								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-970-801					
20-60-00-970-802-01	MEASUREMENT OF PAINT THICKNESS ON COMPOSITE COMPONENTS USING A RADIOELECTRIC GAGE								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-00-970-802					
20-60-10-370-801-01	GENERAL RULES FOR APPLICATION OF CORROSION INHIBITOR COMPOUND								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-60-10-370-801					
20-70-00-230-801-01	FLUORESCENT PENETRANT DETECTION OF CRACKS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-70-00-230-801					
20-70-00-250-801-01	EDDY-CURRENT DETECTION OF CRACKS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-70-00-250-801					
20-70-00-250-802-01	EDDY-CURRENT INSPECTION OF BORES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-70-00-250-802					
20-70-00-250-803-01	CHECK FOR LOCAL OVERHEAT BY ELECTRICAL CONDUCTIVITY MEASUREMENT ON ALUMINUM ALLOYS								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-70-00-250-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-70-00-270-801-01	ULTRASONIC INSPECTION OF COMPOSITE AND METALLIC COMPONENTS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-70-00-270-801					
20-70-00-270-802-01	ULTRASONIC MEASUREMENT OF PMMA PARTS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-70-00-270-802					
20-70-00-280-801-01	TAP TESTING									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-70-00-280-801					
20-70-00-280-803-01	SETTINGS FOR NON-DESTRUCTIVE TESTS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-70-00-280-803					
20-90-00-200-801-01	INSPECTION / CHECK OF ELECTRICAL AND ELECTRONIC SYSTEMS									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-90-00-200-801					
20-90-05-900-801-01	REMOVAL / INSTALLATION OF THE WIRING FEED-THROUGH FITTINGS									Component ATA:20
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 20-90-05-900-801					
20-91-00-910-801-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH A-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-91-00-910-802-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH B-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-802					
20-91-00-910-803-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH C-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-803					
20-91-00-910-804-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH D-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-804					
20-91-00-910-805-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH E-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-805					
20-91-00-910-807-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH G-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-807					
20-91-00-910-808-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH H-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-808					
20-91-00-910-809-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH I-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-809					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-91-00-910-810-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH J-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-810					
20-91-00-910-812-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH L-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-812					
20-91-00-910-813-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH M-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-813					
20-91-00-910-816-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH P-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-816					
20-91-00-910-818-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH R-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-818					
20-91-00-910-819-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH S-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-819					
20-91-00-910-820-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH T-INITIAL)									Service ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-91-00-910-820					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-94-00-760-803-01	MEASUREMENT OF THE VHF AND HF COAXIAL CABLES INSULATION RESISTANCE								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-94-00-760-803					
20-94-00-760-804-01	MEASUREMENT OF THE INSULATION RESISTANCE OF COAXIAL CABLES (RADIO NAVIGATION)								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-94-00-760-804, AMM 20-94-00-760-804					
20-94-00-760-805-01	CHECK OF COAXIAL CABLES WITH A REFLECTOMETER								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-94-00-760-805					
20-95-00-300-801-01	REPAIR OF OPTICAL FIBER CABLES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-95-00-300-801					
20-95-00-400-801-01	INSTALLATION OF ENGINE ELECTRIC WIRING ON RIGID PIPES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-95-00-400-801					
20-95-00-910-801-01	INSERTION AND EXTRACTION OF A WIRE FITTED WITH A LOCK-IN CONTACT								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-95-00-910-801					
20-95-00-910-802-01	THREADED TERMINAL CONNECTIONS AND TIGHTENING TORQUES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-95-00-910-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 20 - STANDARD PRACTICES - AIRFRAME										
20-95-00-910-803-01	GENERAL INSTRUCTIONS FOR INSTALLATION OF CF- OR DR-TYPE CABLES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-95-00-910-803					
20-95-00-910-804-01	GENERAL INSTRUCTIONS FOR FILOTEX A0861 / A1861 AND FILECA 1741 KAPTON-INSULATED ELECTRICAL CABLES								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-95-00-910-804					
20-95-00-960-801-01	REPLACEMENT OF A FUEL GAGE CUT-OFF SOCKET CONNECTOR, DEUTSCH 9602 OR SN620 TYPE OR EQUIVALENT								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-95-00-960-801					
20-95-00-960-802-01	REPLACEMENT OF THE COAXIAL CABLES IN ENGINE 2 "S-DUCT" AREA								Service	ATA:20
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 20-95-00-960-802					
203559	STORAGE AND STORAGE REMOVAL WHEN AIRCRAFT DOES NOT FLY FOR MORE THAN 65 DAYS								Service	ATA:20
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 20.030	AFL	0								
					PROC. REF: GENERIC NO REF					
ATA 21 - AIR CONDITIONING										
21-00-00-720-801-01	FUNCTIONAL TEST OF THE COCKPIT AND CABIN AIR CONDITIONING VALVES - PASSENGER CABIN AIR CONDITIONING VALVE (13H1)								Service	ATA:21
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-00-00-720-801					
21-00-00-720-801-02	FUNCTIONAL TEST OF THE COCKPIT AND CABIN AIR CONDITIONING VALVES - COCKPIT AIR CONDITIONING VALVE (13H2)								Service	ATA:21
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-00-00-720-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-00-00-790-801	LEAK CHECK OF THE AIR CONDITIONING SYSTEM									Service ATA:21
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-00-00-790-801					
21-00-00-790-801-01	LEAK CHECK OF THE AIR CONDITIONING SYSTEM									Service ATA:21
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-00-00-790-801					
21-20-01-350-801-01	RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - LH FLOW LIMITER (L518H)									Service ATA:21
PN:2725F030100	MOS	25-Jul-18						OVERHAUL		
SN:001002	HRS	8538.7	4500 (+3%)		13038.7	13173.7	4046.6 (+135)			
WC#: 21.070	AFL	5496								
					PROC. REF: AMM 21-20-01-350-801					
21-20-01-350-801-02	RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - RH FLOW LIMITER (R518H)									Service ATA:21
PN:2725F030100	MOS	25-Jul-18						OVERHAUL		
SN:01101	HRS	8538.7	4500 (+3%)		13038.7	13173.7	4046.6 (+135)			
WC#: 21.070	AFL	5496								
					PROC. REF: AMM 21-20-01-350-801					
21-30-00-790-801-01	GROUND CHECK OF CABIN SEALING									Service ATA:21
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-30-00-790-801					
21-30-00-790-802-01	IN-FLIGHT CHECK OF CABIN SEALING									Service ATA:21
	MOS	24-Oct-91								
	HRS	0								
	AFL	0	T:7000		7000		1204			
					PROC. REF: AMM 21-30-00-790-802					
21-30-00-790-802-01A	CHECK (IN-FLIGHT) OF CABIN SEALING (MANDATORY 5-40)									Service ATA:21
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
	AFL	0	T:7000		7000		1204			
					PROC. REF: AMM 21-30-00-790-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-30-00-790-803		PRESSURIZATION LEAK TEST								Service ATA:21
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-30-00-790-803					
21-30-00-790-803-01		PRESSURIZATION LEAK TEST WITH EXTERNAL SOURCE OF AIR								Service ATA:21
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-30-00-790-803					
21-30-01-900-801-01		REMOVAL / INSTALLATION OF THE AUTOMATIC PRESSURIZATION CONTROLLER - PRESSURIZATION CONTROLLER (73H)								Component ATA:21
PN:22201N071001	MOS/MSC	15-May-23	O/C	TSR 0						
SN:01210	HRS	8954.2		TSR 0						
WC#: 21.140	AFL	5760		TSR 0						
					PROC. REF: AMM 21-30-01-900-801					
21-30-09-720-801-01		FUNCTIONAL TEST OF THE ALTITUDE ALERT OF THE TRIPLE INDICATOR - TRIPLE INDICATOR (37F)								Service ATA:21
PN:720-15900-912	MOS/MSC	24-Oct-91	N/A							
SN:2492	HRS	0								
WC#: 21.200	AFL	0								
					PROC. REF: AMM 21-30-09-720-801					
21-30-09-900-801-01		REMOVAL / INSTALLATION OF THE TRIPLE INDICATOR								Component ATA:21
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 21-30-09-900-801					
21-30-17-820-801-01		CALIBRATION OF THE ALTIMETRIC SWITCH - ALTIMETRIC SWITCH (150H)								Service ATA:21
PN:4224ZR21	MOS	17-May-12								
SN:1459	HRS	7862.1	4000		11862.1		2870			
WC#: 21.210	AFL	5094								
					PROC. REF: AMM 21-30-17-820-801					
21-30-17-900-801-01		REMOVAL / INSTALLATION OF THE ALTIMETRIC SWITCH - ALTIMETRIC SWITCH (150H)								Component ATA:21
PN:4224ZR21	MOS/MSC	17-May-12	O/C							
SN:1459	HRS	7862.1		TSN 7862.1						
WC#: 21.210	AFL	5094								
					PROC. REF: AMM 21-30-17-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-31-09-350-801-01	RESTORATION OF THE NOSE CONE VENTILATION FAN (REPLACEMENT OF BEARINGS) - NOSE CONE FAN (83H)								Service	ATA:21
PN:AE0402A00	MOS/MSC		N/A							
SN:137700167	HRS									
WC#: 21.100	AFL									
					PROC. REF: AMM 21-31-09-350-801					
21-31-09-710-801-01	OPERATIONAL TEST OF THE NOSE CONE VENTILATION FAN - NOSE CONE FAN (83H)								Service	ATA:21
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-31-09-710-801					
21-31-09-900-801-01	REMOVAL / INSTALLATION OF THE NOSE CONE VENTILATION FAN - NOSE CONE FAN (83H)								Component	ATA:21
PN:AE0402A00	MOS/MSC	11-Apr-19	O/C	TSR 21						
SN:137700167	HRS	8648.2		TSR 0						
WC#: 21.100	AFL	5560		TSR 0						
					PROC. REF: AMM 21-31-09-900-801					
21-31-13-720-801-01 S	FUNCTIONAL TEST OF THE NOSE CONE PRESSURE REGULATION PNEUMATIC ACTUATOR - PNEUMATIC ACTUATOR								Service	ATA:21
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 21.090	AFL	5651								
					PROC. REF: AMM 21-31-13-720-801					PKG:31
21-31-13-720-801-02 S	FUNCTIONAL TEST OF THE NOSE CONE PRESSURE REGULATION PNEUMATIC ACTUATOR - NOSE CONE PRESSURE-RELIEF VALVE								Service	ATA:21
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 21-31-13-720-801					PKG:31
21-31-25-220-801-01	CHECK / REPLACEMENT OF THE NOSE CONE VENTILATION FAN BRUSHES - NOSE CONE FAN (83H)								Service	ATA:21
PN:AE0402A00	MOS/MSC		N/A							
SN:137700167	HRS									
WC#: 21.100	AFL									
					PROC. REF: AMM 21-31-25-220-801					
21-31-29-710-801-01	OPERATIONAL TEST OF THE NOSE CONE ISOLATION VALVE								Service	ATA:21
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-31-29-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-32-00-710-801-01[S]	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM									Service ATA:21
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 21.120	AFL	5651								
					PROC. REF: AMM 21-32-00-710-801					PKG:21
21-32-00-710-801-01A	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM (MANDATORY 5-40)									Service ATA:21
	MOS/MSC	07-Sep-22	O/C							
	HRS	8823								
WC#: 21.120	AFL	5651								
					PROC. REF: AMM 21-32-00-710-801					
21-32-00-790-801-01[S]	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - LH STATIC PRESSURE PROBE (16F1)									Service ATA:21
	MOS	08-Sep-23	24 (+1m)					RVSM		
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 21-32-00-790-801					PKG:16 ,15
21-32-00-790-801-02[S]	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - RH STATIC PRESSURE PROBE (16F2)									Service ATA:21
	MOS	08-Sep-23	24 (+1m)					RVSM		
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 21-32-00-790-801					PKG:16 ,15
21-32-06-200-801-01	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CLEANING OF ELECTROPNEUMATIC VALVE (L74H)									Service ATA:21
PN:2095D010400	MOS	18-May-12								
SN:693	HRS	7862.1	1640 (+3%)		9502.1	9551.3	510 (+49.2)			
WC#: 21.160	AFL	5094								
					PROC. REF: AMM 21-32-06-200-801					
21-32-06-200-801-02	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CLEANING OF PNEUMATIC VALVE (R74H)									Service ATA:21
PN:2096E010200	MOS	15-Dec-11								
SN:645	HRS	7712.7	1640 (+3%)		9352.7	9401.9	360.6 (+49.2)			
WC#: 21.170	AFL	4979								
					PROC. REF: AMM 21-32-06-200-801					
21-32-06-200-801-03	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE TIGHTNESS OF ELECTROPNEUMATIC VALVE (L74H)									Service ATA:21
PN:2095D010400	MOS	18-May-12								
SN:693	HRS	7862.1	1640		9502.1		510			
WC#: 21.160	AFL	5094								
					PROC. REF: AMM 21-32-06-200-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-32-06-200-801-03A		CHECK ELECTROPNEUMATIC REGULATING VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)								Service ATA:21
PN:2095D010400	MOS	18-May-12						MANDATORY 5-40		
SN:693	HRS	7862.1	1640		9502.1		510			
WC#: 21.320	AFL	5094								
					PROC. REF: AMM 21-32-06-200-801					
21-32-06-200-801-04		INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE TIGHTNESS OF PNEUMATIC VALVE (R74H)								Service ATA:21
PN:2096E010200	MOS	15-Dec-11								
SN:645	HRS	7712.7	1640		9352.7		360.6			
WC#: 21.170	AFL	4979								
					PROC. REF: AMM 21-32-06-200-801					
21-32-06-200-801-04A		CHECK PNEUMATIC REGULATING VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)								Service ATA:21
PN:2096E010200	MOS	15-Dec-11						MANDATORY 5-40		
SN:645	HRS	7712.7	1640		9352.7		360.6			
WC#: 21.315	AFL	4979								
					PROC. REF: AMM 21-32-06-200-801					
21-32-06-200-801-05		INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (975HP) AND (976HP)								Service ATA:21
	MOS	18-May-12								
	HRS	7862.1	7500		15362.1		6370			
WC#: 21.170	AFL	5094								
					PROC. REF: AMM 21-32-06-200-801					
21-32-06-200-801-05A		INSPECTION/CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (MANDATORY 5-40)								Service ATA:21
	MOS	18-May-12						MANDATORY 5-40		
	HRS	7862.1	7500		15362.1		6370			
WC#: 21.170	AFL	5094								
					PROC. REF: AMM 21-32-06-200-801					
21-32-06-720-801-01		FUNCTIONAL TEST OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - ELECTROPNEUMATIC VALVE (L74H)								Service ATA:21
PN:2095D010400	MOS	07-Mar-16								
SN:693	HRS	8278.1	4500 (+3%)		12778.1	12913.1	3786 (+135)			
	AFL	5347								
					PROC. REF: AMM 21-32-06-720-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-32-06-720-801-01A		FUNCTIONAL TEST ELECTROPNEUMATIC REGULATING VALVE (MANDATORY 5-40)								Service ATA:21
PN:2095D010400	MOS	07-Mar-16						MANDATORY 5-40		
SN:693	HRS	8278.1	5000		13278.1		4286			
WC#: 21.160	AFL	5347								
					PROC. REF: AMM 21-32-06-720-801					
21-32-06-720-801-02		FUNCTIONAL TEST OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - PNEUMATIC VALVE (R74H)								Service ATA:21
PN:2096E010200	MOS	07-Mar-16								
SN:645	HRS	8278.1	4500 (+3%)		12778.1	12913.1	3786 (+135)			
	AFL	5347								
					PROC. REF: AMM 21-32-06-720-801					
21-32-06-720-801-02A		FUNCTIONAL TEST PNEUMATIC REGULATING VALVE (ALTITUDE LIMIT) (MANDATORY 5-40)								Service ATA:21
PN:2096E010200	MOS	07-Mar-16						MANDATORY 5-40		
SN:645	HRS	8278.1	5000		13278.1		4286			
WC#: 21.170	AFL	5347								
					PROC. REF: AMM 21-32-06-720-801					
21-32-06-720-802-01 S		FUNCTIONAL TEST OF THE CABIN ALTITUDE LIMITATION - ELECTROPNEUMATIC VALVE (L74H)								Service ATA:21
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 21-32-06-720-802					PKG:31
21-32-06-720-802-02 S		FUNCTIONAL TEST OF THE CABIN ALTITUDE LIMITATION - PNEUMATIC VALVE (R74H)								Service ATA:21
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 21-32-06-720-802					PKG:31
21-32-06-900-801-01		REMOVAL / INSTALLATION OF THE ELECTROPNEUMATIC VALVE - ELECTROPNEUMATIC VALVE (L74H)								Component ATA:21
PN:2095D010400	MOS/MSC	18-May-12	O/C	TSO 11						
SN:693	HRS	7862.1		TSO 0						
WC#: 21.160	AFL	5094		TSO 0						
					PROC. REF: AMM 21-32-06-900-801					
21-32-06-900-802-01		REMOVAL / INSTALLATION OF THE PNEUMATIC VALVE - PNEUMATIC VALVE (R74H)								Component ATA:21
PN:2096E010200	MOS/MSC	07-Mar-16	O/C	TSR 1						
SN:645	HRS	8278.1		TSR 0						
WC#: 21.170	AFL	5347		TSR 0						
					PROC. REF: AMM 21-32-06-900-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-32-17-720-801-01 S		FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - LH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (L536H)								Service ATA:21
	MOS	17-Dec-10								
	HRS	7458.3	3000 (+30)							
WC#: 21.190	AFL	4759								
					PROC. REF: AMM 21-32-17-720-801					PKG:22
21-32-17-720-801-01A		FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - LH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (L536H) (MANDATORY 5-40)								Service ATA:21
	MOS	17-Dec-10						MANDATORY 5-40		
	HRS	7458.3	3700		11158.3		2166.2			
WC#: 21.190	AFL	4759								
					PROC. REF: AMM 21-32-17-720-801					
21-32-17-720-801-02 S		FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - RH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (R536H)								Service ATA:21
	MOS	17-Dec-10								
	HRS	7458.3	3000 (+30)							
WC#: 21.190	AFL	4759								
					PROC. REF: AMM 21-32-17-720-801					PKG:22
21-32-17-720-801-02A		FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - RH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (R536H) (MANDATORY 5-40)								Service ATA:21
	MOS	17-Dec-10						MANDATORY 5-40		
	HRS	7458.3	3700		11158.3		2166.2			
WC#: 21.190	AFL	4759								
					PROC. REF: AMM 21-32-17-720-801					
21-32-33-710-801-01		OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT ISOLATION AND SUPPLY VALVES - BAGGAGE COMPARTMENT ISOLATION VALVE (153H)								Service ATA:21
PN:B97-26-553	MOS	09-Mar-18								
SN:20110	HRS	8497.6	600 (+30)		9097.6	9127.6	105.5 (+30)			
WC#: 21.050	AFL	5470								
					PROC. REF: AMM 21-32-33-710-801					
21-32-33-710-801-01A		OPERATIONAL TEST BAGGAGE COMPARTMENT ISOLATION VALVE (MANDATORY 5-40)								Service ATA:21
PN:B97-26-553	MOS	09-Mar-18						MANDATORY 5-40		
SN:20110	HRS	8497.6	650		9147.6		155.5			
WC#: 21.050	AFL	5470								
					PROC. REF: AMM 21-32-33-710-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-32-33-710-801-02		OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT ISOLATION AND SUPPLY VALVES - BAGGAGE COMPARTMENT HOT AIR SUPPLY VALVE (154H)								Service ATA:21
PN:B97-26-551	MOS	09-Mar-18								
SN:20218	HRS	8497.6	600 (+30)		9097.6	9127.6	105.5 (+30)			
WC#: 21.050	AFL	5470								
					PROC. REF: AMM 21-32-33-710-801					
21-32-33-710-801-02A		OPERATIONAL TEST BAGGAGE COMPARTMENT SUPPLY VALVE (MANDATORY 5-40)								Service ATA:21
PN:B97-26-551	MOS	09-Mar-18						MANDATORY 5-40		
SN:20218	HRS	8497.6	650		9147.6		155.5			
WC#: 21.050	AFL	5470								
					PROC. REF: AMM 21-32-33-710-801					
21-32-33-720-801-01		FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT ISOLATION AND SUPPLY VALVES - BAGGAGE COMPARTMENT ISOLATION VALVE (153H)								Service ATA:21
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-32-33-720-801					
21-32-33-720-801-02		FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT ISOLATION AND SUPPLY VALVES - BAGGAGE COMPARTMENT HOT AIR SUPPLY VALVE (154H)								Service ATA:21
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-32-33-720-801					
21-32-38-710-801-01		OPERATIONAL TEST OF THE CABIN NEGATIVE PRESSURE RELIEF VALVES - UPPER NEGATIVE PRESSURE RELIEF VALVE (977HP)								Service ATA:21
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 21.180	AFL	0								
					PROC. REF: AMM 21-32-38-710-801					
21-32-38-710-801-02		OPERATIONAL TEST OF THE CABIN NEGATIVE PRESSURE RELIEF VALVES - LOWER NEGATIVE PRESSURE RELIEF VALVE (978HP)								Service ATA:21
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 21.180	AFL	0								
					PROC. REF: AMM 21-32-38-710-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-32-38-820-801-01	CALIBRATION OF THE CABIN NEGATIVE PRESSURE RELIEF VALVES - UPPER NEGATIVE PRESSURE RELIEF VALVE (977HP)									Service ATA:21
PN:CYLB50416	MOS/MSC	24-Oct-91	N/A							
SN:UNKNOWN	HRS	0								
WC#: 21.180	AFL	0								
					PROC. REF: AMM 21-32-38-820-801					
21-32-38-820-801-02	CALIBRATION OF THE CABIN NEGATIVE PRESSURE RELIEF VALVES - LOWER NEGATIVE PRESSURE RELIEF VALVE (978HP)									Service ATA:21
PN:CYLB50416	MOS/MSC	24-Oct-91	N/A							
SN:UNKNOWN	HRS	0								
WC#: 21.180	AFL	0								
					PROC. REF: AMM 21-32-38-820-801					
21-32-41-200-801-01[S]	INSPECTION OF THE NICOTINE FILTER CARTRIDGE - NICOTINE FILTER (534H)									Service ATA:21
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 21.150	AFL	5651								
					PROC. REF: AMM 21-32-41-200-801					PKG:21
21-51-29-720-801-01[S]	FUNCTIONAL TEST OF THE LOWER COOLING UNIT AIR INTAKE DOOR									Service ATA:21
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 21.250	AFL	5651								
					PROC. REF: AMM 21-51-29-720-801					PKG:31
21-51-30-640-801-01[S]	LUBRICATION OF THE LOWER COOLING UNIT AIR INTAKE DOOR CONTROL CABLE									Service ATA:21
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 21.260	AFL	5775								
					PROC. REF: AMM 21-51-30-640-801					PKG:16 ,15
21-52-01-350-801-01	RESTORATION OF THE COOLING UNITS (OVERHAUL) - UPPER COOLING UNIT (R519H)									Service ATA:21
PN:3500C01	MOS	07-Mar-13						OVERHAUL		
SN:135	HRS	7960.6	4000		11960.6		2968.5			
WC#: 21.230	AFL	5171								
					PROC. REF: AMM 21-52-01-350-801					
21-52-01-350-801-02	RESTORATION OF THE COOLING UNITS (OVERHAUL) - LOWER COOLING UNIT (L519H)									Service ATA:21
PN:3500C01	MOS	07-Mar-13						OVERHAUL		
SN:00792	HRS	7960.6	4000		11960.6		2968.5			
WC#: 21.240	AFL	5171								
					PROC. REF: AMM 21-52-01-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-52-01-900-801-01	REMOVAL / INSTALLATION OF THE UPPER AND LOWER COOLING UNITS - LOWER COOLING UNIT (L519H)									Component ATA:21
PN:3500C01	MOS/MSC	07-Mar-13	H/T	TSO 0						
SN:00792	HRS	7960.6		TSO 0						
WC#: 21.240	AFL	5171		TSO 0						
					PROC. REF: AMM 21-52-01-900-801					
21-52-01-900-801-02	REMOVAL / INSTALLATION OF THE UPPER AND LOWER COOLING UNITS - UPPER COOLING UNIT (R519H)									Component ATA:21
PN:3500C01	MOS/MSC	07-Mar-13	H/T	TSO 0						
SN:135	HRS	7960.6		TSO 0						
WC#: 21.230	AFL	5171		TSO 0						
					PROC. REF: AMM 21-52-01-900-801					
21-52-05-350-801-01	RESTORATION OF THE TURBOCOOLER (OVERHAUL) - UPPER TURBOCOOLER (R544H)									Service ATA:21
PN:3176C01	MOS	07-Mar-13		TAC 0				OVERHAUL		
SN:UNKNOWN	HRS	7960.6	4000 (+3%)		11960.6	12080.6	2968.5 (+120)			
WC#: 21.230	AFL	5171		TAC 0						
					PROC. REF: AMM 21-52-05-350-801					
21-52-05-350-801-02	RESTORATION OF THE TURBOCOOLER (OVERHAUL) - LOWER TURBOCOOLER (L544H)									Service ATA:21
PN:3176C01	MOS	07-Mar-13		TAC 0				OVERHAUL		
SN:UNKNOWN	HRS	7960.6	4000 (+3%)		11960.6	12080.6	2968.5 (+120)			
WC#: 21.240	AFL	5171		TAC 0						
					PROC. REF: AMM 21-52-05-350-801					
21-52-05-610-801-01	TURBOCOOLER OIL SERVICING - LOWER TURBOCOOLER (L544H)									Service ATA:21
	MOS	09-Mar-18								
	HRS	8497.6	600 (+30)		9097.6	9127.6	105.5 (+30)			
WC#: 21.240	AFL	5470								
					PROC. REF: AMM 21-52-05-610-801					
21-52-05-610-801-02	TURBOCOOLER OIL SERVICING - UPPER TURBOCOOLER (R544H)									Service ATA:21
	MOS	09-Mar-18								
	HRS	8497.6	600 (+30)		9097.6	9127.6	105.5 (+30)			
WC#: 21.230	AFL	5470								
					PROC. REF: AMM 21-52-05-610-801					
21-52-05-700-801-01	TURBOCOOLER OIL LEVEL CHECK - LOWER TURBOCOOLER (L544H)									Service ATA:21
	MOS	07-Sep-22								
	HRS	8823	200 (+10%)		9023	9043	30.9 (+20)			
	AFL	5651								
					PROC. REF: AMM 21-52-05-700-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-52-05-700-801-02	TURBOCOOLER OIL LEVEL CHECK - UPPER TURBOCOOLER (R544H)									Service ATA:21
	MOS	07-Sep-22								
	HRS	8823	200 (+10%)		9023	9043	30.9 (+20)			
	AFL	5651								
					PROC. REF: AMM 21-52-05-700-801					
21-52-05-900-801-01	REMOVAL / INSTALLATION OF THE TURBOCOOLER - LOWER TURBOCOOLER (L544H)									Component ATA:21
PN:3176C01	MOS/MSC	06-Sep-00	H/T	TSO 0						
SN:UNKNOWN	HRS	3962		TSO 0						
WC#: 21.240	AFL	2529		TSO 0						
					PROC. REF: AMM 21-52-05-900-801					
21-52-05-900-801-02	REMOVAL / INSTALLATION OF THE TURBOCOOLER - UPPER TURBOCOOLER (R544H)									Component ATA:21
PN:3176C01	MOS/MSC	05-Sep-00	H/T	TSO 0						
SN:UNKNOWN	HRS	3962		TSO 0						
WC#: 21.230	AFL	2529		TSO 0						
					PROC. REF: AMM 21-52-05-900-801					
21-52-09-210-803-01	GENERAL VISUAL INSPECTION OF THE HEAT EXCHANGER INTAKE FACE OF THE UPPER AND LOWER COOLING UNITS - LOWER HEAT EXCHANGER (L542H)									Service ATA:21
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-52-09-210-803					
21-52-09-210-803-02	GENERAL VISUAL INSPECTION OF THE HEAT EXCHANGER INTAKE FACE OF THE UPPER AND LOWER COOLING UNITS - UPPER HEAT EXCHANGER (R542H)									Service ATA:21
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-52-09-210-803					
21-60-00-710-801-01	OPERATIONAL TEST OF THE COCKPIT / CABIN TEMPERATURE CONTROL FUNCTION									Service ATA:21
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 21-60-00-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
21-64-05-900-801-01		REMOVAL / INSTALLATION OF THE CABIN DUAL TEMPERATURE REGULATING VALVE - COCKPIT DUAL TEMPERATURE REGULATING VALVE (4H)							Component	ATA:21
PN:BYLB50418-12	MOS/MSC	06-Aug-08	O/C	TSR 0						08/06/2010
SN:650	HRS	6784.5		TSR 0						
WC#: 21.280	AFL	4219		TSR 0						
					PROC. REF: AMM 21-64-05-900-801					
21-64-05-900-801-02		REMOVAL / INSTALLATION OF THE CABIN DUAL TEMPERATURE REGULATING VALVE - CABIN DUAL TEMPERATURE REGULATING VALVE (164H)							Component	ATA:21
PN:BYLB50418-12	MOS/MSC	24-Oct-91	O/C							
SN:588	HRS	0		TSN 0						
WC#: 21.280	AFL	0								
					PROC. REF: AMM 21-64-05-900-801					
212101		CABIN AIR CONDITIONING VALVE							Component	ATA:21
PN:BYLB50423-1	MOS/MSC	24-Oct-91	O/C							
SN:829	HRS	0		TSN 0						
WC#: 21.010	AFL	0								
					PROC. REF: GENERIC NO REF					
212121		COCKPIT AIR CONDITIONING VALVE							Component	ATA:21
PN:BYLB50423-1	MOS/MSC	24-Oct-91	O/C							
SN:830	HRS	0		TSN 0						
WC#: 21.010	AFL	0								
					PROC. REF: GENERIC NO REF					
212141		LH COLD AIR NON RETURN VALVE							Component	ATA:21
PN:CYLB50417	MOS/MSC	24-Oct-91	O/C							
SN:458	HRS	0		TSN 0						
WC#: 21.020	AFL	0								
					PROC. REF: GENERIC NO REF					
212146		RH COLD AIR NON RETURN VALVE							Component	ATA:21
PN:CYLB50417	MOS/MSC	24-Oct-91	O/C							
SN:520	HRS	0		TSN 0						
WC#: 21.020	AFL	0								
					PROC. REF: GENERIC NO REF					
212151		LH AIR CONDITIONING NON RETURN VALVE							Component	ATA:21
PN:CYLB50416	MOS/MSC	24-Oct-91	O/C							
SN:695	HRS	0		TSN 0						
WC#: 21.030	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
212156		RH AIR CONDITIONING NON RETURN VALVE								Component ATA:21
PN:CYLB50416	MOS/MSC	24-Oct-91	O/C							
SN:698	HRS	0		TSN 0						
WC#: 21.030	AFL	0								
					PROC. REF: GENERIC NO REF					
212161		BAGGAGE COMPARTMENT ISOLATION VALVE								Component ATA:21
PN:B97-26-553	MOS/MSC	24-Oct-91	O/C							
SN:20110	HRS	0		TSN 0						
WC#: 21.050	AFL	0								
					PROC. REF: GENERIC NO REF					
212171		BAGGAGE COMPARTMENT SUPPLY VALVE								Component ATA:21
PN:B97-26-551	MOS/MSC	24-Oct-91	O/C							
SN:20218	HRS	0		TSN 0						
WC#: 21.050	AFL	0								
					PROC. REF: GENERIC NO REF					
212181		PILOT AERATOR								Component ATA:21
PN:2368	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.060	AFL	0								
					PROC. REF: GENERIC NO REF					
212186		COPILOT AERATOR								Component ATA:21
PN:2368	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.060	AFL	0								
					PROC. REF: GENERIC NO REF					
212201		LH HOT AIR NON RETURN VALVE								Component ATA:21
PN:CYLB50414	MOS/MSC	24-Oct-91	O/C							
SN:1658	HRS	0		TSN 0						
WC#: 21.040	AFL	0								
					PROC. REF: GENERIC NO REF					
212206		RH HOT AIR NON RETURN VALVE								Component ATA:21
PN:CYLB50414	MOS/MSC	24-Oct-91	O/C							
SN:1661	HRS	0		TSN 0						
WC#: 21.040	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
212211		NOSE CONE SHUT OFF VALVE								Component ATA:21
PN:B97M19-201	MOS/MSC	24-Oct-91	O/C							
SN:20129	HRS	0		TSN 0						
WC#: 21.080	AFL	0								
					PROC. REF: GENERIC NO REF					
212241		NOSE CONE PRESSURE RELIEF VALVE								Component ATA:21
PN:P85-533	MOS/MSC	24-Oct-91	O/C							
SN:0101796	HRS	0		TSN 0						
WC#: 21.080	AFL	0								
					PROC. REF: GENERIC NO REF					
212251		LH ELECTRICAL RACK BLOWER								Component ATA:21
PN:125XS01-62-001D	MOS/MSC	24-Oct-91	O/C							
SN:G224	HRS	0		TSN 0						
WC#: 21.110	AFL	0								
					PROC. REF: GENERIC NO REF					
212261		RH ELECTRICAL RACK BLOWER								Component ATA:21
PN:125XS01-62-001D	MOS/MSC	24-Oct-91	O/C							
SN:D224	HRS	0		TSN 0						
WC#: 21.110	AFL	0								
					PROC. REF: GENERIC NO REF					
212271		FRONT TOILET BLOWER								Component ATA:21
PN:125XS01-62-001	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.110	AFL	0								
					PROC. REF: GENERIC NO REF					
213091		NOSE CONE PRESSURE REGULATION PNEUMATIC ACTUATOR								Component ATA:21
PN:7021-000	MOS/MSC	24-Oct-91	O/C							
SN:326	HRS	0		TSN 0						
WC#: 21.090	AFL	0								
					PROC. REF: GENERIC NO REF					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
213106		STAND-BY REGULATOR								Component ATA:21
PN:912K0101	MOS/MSC	28-Oct-20	O/C							
SN:685	HRS	8701								
WC#: 21.140	AFL	5598								
					PROC. REF: GENERIC NO REF					
213131		NICOTINE FILTER								Component ATA:21
PN:234A01-01	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.150	AFL	0								
					PROC. REF: GENERIC NO REF					
213141		UPPER NEGATIVE PRESSURE RELIEF VALVE								Component ATA:21
PN:CYLB50416	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.180	AFL	0								
					PROC. REF: GENERIC NO REF					
213156		LOWER NEGATIVE PRESSURE RELIEF VALVE								Component ATA:21
PN:CYLB50416	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.180	AFL	0								
					PROC. REF: GENERIC NO REF					
213171		LH BAGGAGE COMPARTMENT POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE								Component ATA:21
PN:2832C01	MOS/MSC	24-Oct-91	O/C							
SN:502	HRS	0		TSN 0						
WC#: 21.190	AFL	0								
					PROC. REF: GENERIC NO REF					
213191		RH BAGGAGE COMPARTMENT POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE								Component ATA:21
PN:2832C01	MOS/MSC	24-Oct-91	O/C							
SN:505	HRS	0		TSN 0						
WC#: 21.190	AFL	0								
					PROC. REF: GENERIC NO REF					
213211		TRIPLE ALTITUDE/DIFFERENTIAL PRESSURE INDICATOR								Component ATA:21
PN:720-15900-912	MOS/MSC	24-Oct-91	O/C							
SN:2492	HRS	0		TSN 0						
WC#: 21.200	AFL	0								
					PROC. REF: AMM 21-30-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
213226		JET PUMP								Component ATA:21
PN:F50B722001	MOS/MSC	24-Oct-91	O/C							
SN:280	HRS	0		TSN 0						
WC#: 21.220	AFL	0								
					PROC. REF: GENERIC NO REF					
215113		RH AIR CONDITIONING FLOW LIMITER								Component ATA:21
PN:2725F030100	MOS/MSC	25-Jul-18	H/T	TSO 0						
SN:01101	HRS	8538.7		TSO 0						
WC#: 21.070	AFL	5496		TSO 0						
					PROC. REF: GENERIC NO REF					
215133		LH AIR CONDITIONING FLOW LIMITER								Component ATA:21
PN:2725F030100	MOS/MSC	25-Jul-18	H/T	TSO 0						
SN:001002	HRS	8538.7		TSO 0						
WC#: 21.070	AFL	5496		TSO 0						
					PROC. REF: GENERIC NO REF					
215801[U]		UPPER COOLING UNIT ANTI-ICE VALVE								Component ATA:21
PN:941G0127	MOS/MSC	23-Sep-95	O/C	TSO 0						
SN:1955	HRS	1804		TSO 0						
	AFL	1270		TSO 0						
215802[U]		UPPER ECU THERMISTOR								Component ATA:21
PN:331T21E5	MOS/MSC	23-Sep-95	O/C	TSO 0						
SN:2107	HRS	1804		TSO 0						
	AFL	1270		TSO 0						
215803[U]		UPPER ECU PRESSURE REDUCING VALVE								Component ATA:21
PN:2407G012125	MOS/MSC	23-Sep-95	O/C	TSO 0						
SN:1559	HRS	1804		TSO 0						
	AFL	1270		TSO 0						
215804[U]		UPPER ECU HEAT EXCHANGER								Component ATA:21
PN:11-81860	MOS/MSC	23-Sep-95	O/C	TSO 0						
SN:493	HRS	1804		TSO 0						
	AFL	1270		TSO 0						
215806[U]		LOWER COOLING UNIT ANTI-ICE VALVE								Component ATA:21
PN:941G0127	MOS/MSC	23-Sep-95	O/C							
SN:1947	HRS	1804								
	AFL	1270								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
215807[U]		LOWER ECU THERMISTOR								Component ATA:21
PN:331T21E5	MOS/MSC	23-Sep-95	O/C	TSO 0						
SN:2078	HRS	1804		TSO 0						
	AFL	1270		TSO 0						
215808[U]		LOWER ECU PRESSURE REDUCING VALVE								Component ATA:21
PN:2407G012125	MOS/MSC	23-Sep-95	O/C	TSO 0						
SN:1533	HRS	1804		TSO 0						
	AFL	1270		TSO 0						
215809[U]		LOWER ECU HEAT EXCHANGER								Component ATA:21
PN:11-81860	MOS/MSC	23-Sep-95	O/C	TSO 0						
SN:492	HRS	1804		TSO 0						
	AFL	1270		TSO 0						
215811[U]		INSPECT ECU QUICK DRAIN								Service ATA:21
	MOS	08-Sep-23								
	HRS	8967	100		9067		74.9			
	AFL	5775								
216101		CABIN TEMPERATURE THERMOSTAT								Component ATA:21
PN:150T346	MOS/MSC	24-Oct-91	O/C							
SN:669	HRS	0		TSN 0						
WC#: 21.270	AFL	0								
					PROC. REF: GENERIC NO REF					
216106		COCKPIT TEMPERATURE THERMOSTAT								Component ATA:21
PN:150T325	MOS/MSC	24-Oct-91	O/C							
SN:410	HRS	0		TSN 0						
WC#: 21.270	AFL	0								
					PROC. REF: GENERIC NO REF					
216126		CABIN TEMPERATURE AMPLIFIER PROBE								Component ATA:21
PN:HYLZ50514-11	MOS/MSC	04-Sep-20	O/C	TSO 0						
SN:1470J	HRS	8695.7		TSO 0						
WC#: 21.290	AFL	5595		TSO 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
216136		COCKPIT TEMPERATURE AMPLIFIER PROBE								Component ATA:21
PN:HYLZ50514-11	MOS/MSC	12-Jun-03	O/C	TSR 0						
SN:947H	HRS	4762.6		TSR 0						
WC#: 21.290	AFL	2987		TSR 0						
					PROC. REF: GENERIC NO REF					
216146		CABIN DUCT TEMPERATURE PROBE								Component ATA:21
PN:AYLF50425	MOS/MSC	12-Jun-03	O/C	TSR 0						
SN:2190	HRS	4762.6		TSR 0						
WC#: 21.300	AFL	2987		TSR 0						
					PROC. REF: GENERIC NO REF					
216151		COCKPIT DUCT TEMPERATURE PROBE								Component ATA:21
PN:AYLF50425	MOS/MSC	24-Oct-91	O/C							
SN:1127	HRS	0		TSN 0						
WC#: 21.300	AFL	0								
					PROC. REF: GENERIC NO REF					
216156		AIR CONDITIONING CONTROL BOX								Component ATA:21
PN:5897-651-8	MOS/MSC	24-Oct-91	O/C							
SN:371	HRS	0		TSN 0						
WC#: 21.310	AFL	0								
					PROC. REF: GENERIC NO REF					
ATA 22 - AUTO FLIGHT										
22-10-00-700-801-01[S]		CHECK OF THE AP / FD SYSTEM DISENGAGEMENT PROTECTIONS								Service ATA:22
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 22.100	AFL	5651								
					PROC. REF: AMM 22-10-00-700-801					PKG:21
22-10-00-710-801-01[S]		OPERATIONAL TEST OF THE AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS)								Service ATA:22
	MOS	08-Sep-23	24 (+1m)					RVSM		
	HRS	8967								
WC#: 22.090	AFL	5775								
					PROC. REF: AMM 22-10-00-710-801, AMM 22-10-00-710-801, AMM 22-10-00-710-801, AMM 22-10-00-710-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
22-10-05-720-801-01[S]	FUNCTIONAL TEST OF THE AUTOPILOT SERVOMOTORS - AILERON SERVOMOTOR (210CA)								Service	ATA:22
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
	AFL	5347								
					PROC. REF: AMM 22-10-05-720-801, AMM 22-10-05-720-801, AMM 22-10-05-720-801					PKG:32
22-10-05-720-801-02[S]	FUNCTIONAL TEST OF THE AUTOPILOT SERVOMOTORS - ELEVATOR SERVOMOTOR (211CA)								Service	ATA:22
PN:622-4404-001	MOS	07-Mar-16	144 (+2m)							
SN:315	HRS	8278.1								
	AFL	5347								
					PROC. REF: AMM 22-10-05-720-801, AMM 22-10-05-720-801, AMM 22-10-05-720-801					PKG:32
22-10-05-900-801-01	REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTORS - AILERON SERVOMOTOR (210CA)								Component	ATA:22
PN:622-4404-001	MOS/MSC	04-Apr-96	O/C							
SN:616	HRS	1997		TSN 0, TSO 0						
WC#: 22.050	AFL	1408								
					PROC. REF: AMM 22-10-05-900-801					
22-10-05-900-801-02	REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTORS - ELEVATOR SERVOMOTOR (211CA)								Component	ATA:22
PN:622-4404-001	MOS/MSC	09-Apr-92	O/C							
SN:315	HRS	26								
WC#: 22.060	AFL	13								
					PROC. REF: AMM 22-10-05-900-801					
22-10-05-900-801-03	RUDDER AUTOPILOT SERVOMOTOR								Component	ATA:22
PN:792-6781-001	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 22.070	AFL	0								
					PROC. REF: AMM 22-10-05-900-801					
22-10-07-700-801-01[S]	CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - AILERON								Service	ATA:22
	MOS	08-Sep-23	24 (+1m)					RVSM		
	HRS	8967								
WC#: 22.170	AFL	5775								
					PROC. REF: AMM 22-10-07-700-801, AMM 22-10-07-700-801					PKG:16 ,15
22-10-07-700-801-02[S]	CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - ELEVATOR								Service	ATA:22
	MOS	08-Sep-23	24 (+1m)					RVSM		
	HRS	8967								
WC#: 22.170	AFL	5775								
					PROC. REF: AMM 22-10-07-700-801, AMM 22-10-07-700-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
22-10-07-700-801-03	CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - RUDDER									Service ATA:22
	MOS/MSC	15-Dec-11	N/A							
	HRS	7712.7								
WC#: 22.170	AFL	4979								
					PROC. REF: AMM 22-10-07-700-801					
22-10-13-700-801-01	CHECK / ADJUSTMENT OF THE AUTOPILOT SERVOMOTOR CAPSTAN SLIP TORQUE - AILERON SERVOMOTOR CAPSTAN (502CA)									Service ATA:22
PN:622-5028-001	MOS	24-Oct-91								
SN:324	HRS	0	14000 (+3%)		14000	14420	5007.9 (+420)			
WC#: 22.110	AFL	0								
					PROC. REF: AMM 22-10-13-700-801					
22-10-13-700-801-02	CHECK / ADJUSTMENT OF THE AUTOPILOT SERVOMOTOR CAPSTAN SLIP TORQUE - ELEVATOR SERVOMOTOR CAPSTAN (503CA)									Service ATA:22
PN:622-5028-001	MOS	24-Oct-91								
SN:323	HRS	0	14000 (+3%)		14000	14420	5007.9 (+420)			
WC#: 22.120	AFL	0								
					PROC. REF: AMM 22-10-13-700-801					
22-10-13-720-801-01	RESTORATION OF THE AUTOPILOT SERVOMOTOR CAPSTAN (FUNCTIONAL TEST) - AILERON SERVOMOTOR CAPSTAN (502CA)									Service ATA:22
PN:622-5028-001	MOS/MSC	24-Oct-91	N/A							
SN:324	HRS	0								
WC#: 22.110	AFL	0								
					PROC. REF: AMM 22-10-13-720-801					
22-10-13-720-801-02	RESTORATION OF THE AUTOPILOT SERVOMOTOR CAPSTAN (FUNCTIONAL TEST) - ELEVATOR SERVOMOTOR CAPSTAN (503CA)									Service ATA:22
PN:622-5028-001	MOS/MSC	24-Oct-91	N/A							
SN:323	HRS	0								
WC#: 22.120	AFL	0								
					PROC. REF: AMM 22-10-13-720-801					
22-10-13-720-801-03	RESTORATION OF THE AUTOPILOT SERVOMOTOR CAPSTAN (FUNCTIONAL TEST) - RUDDER SERVOMOTOR CAPSTAN (504CA)									Service ATA:22
PN:792-6785-001	MOS	24-Oct-91								
SN:UNKNOWN	HRS	0	10000 (+3%)		10000	10300	1007.9 (+300)			
WC#: 22.130	AFL	0								
					PROC. REF: AMM 22-10-13-720-801					
22-10-13-900-801-01	REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTOR CAPSTANS - AILERON SERVOMOTOR CAPSTAN (502CA)									Component ATA:22
PN:622-5028-001	MOS/MSC	09-Apr-92	O/C							
SN:324	HRS	26								
WC#: 22.110	AFL	13								
					PROC. REF: AMM 22-10-13-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
22-10-13-900-801-02	REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTOR CAPSTANS - ELEVATOR SERVOMOTOR CAPSTAN (503CA)									Component ATA:22
PN:622-5028-001	MOS/MSC	09-Apr-92	O/C							
SN:323	HRS	26								
WC#: 22.120	AFL	13								
					PROC. REF: AMM 22-10-13-900-801					
22-10-13-900-801-03	REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTOR CAPSTANS - RUDDER SERVOMOTOR CAPSTAN (504CA)									Component ATA:22
PN:792-6785-001	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 22.130	AFL	0								
					PROC. REF: AMM 22-10-13-900-801					
22-13-01-350-801-01	RESTORATION OF THE YAW DAMPER ACTUATOR (OVERHAUL) - YAW DAMPER LINEAR ACTUATOR (220CA) OR (2CJ)									Service ATA:22
PN:622-8171-008	MOS	10-Dec-03						OVERHAUL		
SN:UNKNOWN	HRS	4936.4	5000 (+3%)		9936.4	10086.4	944.3 (+150)			
WC#: 22.160	AFL	3069								
					PROC. REF: AMM 22-13-01-350-801					
22-13-01-350-801-01A	RESTORATION OF THE YAW DAMPER ACTUATOR (OVERHAUL) (MANDATORY 5-40)									Service ATA:22
PN:622-8171-008	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
	AFL	3069								
					PROC. REF: AMM 22-13-01-350-801					
22-13-01-710-801-01	OPERATIONAL TEST OF THE YAW DAMPER ACTUATOR - YAW DAMPER LINEAR ACTUATOR (220CA)									Service ATA:22
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 22-13-01-710-801, AMM 22-13-01-710-801					
22-13-05-710-801-01	OPERATIONAL TEST OF THE YAW DAMPER COMPUTER - YAW DAMPER COMPUTER (1CJ)									Service ATA:22
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 22-13-05-710-801					
22-13-05-850-801-01	TRANSFORMATION OF YAW DAMPER COMPUTER 622-3167-041 INTO 622-3167-045									Service ATA:22
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 22-13-05-850-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
22-15-00-720-801-01		FUNCTIONAL TEST OF MACH TRIM								Service ATA:22
	MOS/MSC	09-Mar-18	O/C							
	HRS	8497.6								
	AFL	5470								
					PROC. REF: AMM 22-15-00-720-801, AMM 22-15-00-720-801					
221001		AUTOPILOT CONTROL PANEL								Component ATA:22
PN:622-6208-303	MOS/MSC	09-Apr-92	O/C							
SN:1001	HRS	26								
WC#: 22.010	AFL	13								
					PROC. REF: GENERIC NO REF					
221003		AUTOPILOT MODE SELECTOR								Component ATA:22
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 22.030	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
221011		PILOT AUTOPILOT COMPUTER								Component ATA:22
PN:622-7978-321	MOS/MSC	17-Aug-07	O/C							
SN:2022	HRS	6338								
WC#: 22.020	AFL	3908								
					PROC. REF: GENERIC NO REF					
221015		COPILOT AUTOPILOT COMPUTER								Component ATA:22
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 22.190	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
221021		AUTOPILOT AMPLIFIER								Component ATA:22
PN:P N	MOS/MSC	24-Oct-91	O/C							
SN:SN-NOT INSTALLED	HRS	0		TSN 0						
WC#: 22.030	AFL	0								
					PROC. REF: GENERIC NO REF					
221056		YAW DAMPER ACTUATOR								Component ATA:22
PN:622-8171-008	MOS/MSC	10-Dec-03	H/T							
SN:UNKNOWN	HRS	4936.4		TSN 4936, TSO 0						
WC#: 22.160	AFL	3069								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
221061		AUTOPILOT YAW COMPUTER								Component ATA:22
PN:622-3167-045	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 22.040	AFL	0								
					PROC. REF: GENERIC NO REF					
221101		PILOT AUTOPILOT PITCH SERVO CABLE								Component ATA:22
PN:59304	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 22.080	AFL	0								
					PROC. REF: GENERIC NO REF					
221106		PILOT AUTOPILOT ROLL SERVO CABLE								Component ATA:22
PN:59309	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 22.080	AFL	0								
					PROC. REF: GENERIC NO REF					
221111		PILOT AUTOPILOT YAW SERVO CABLE								Component ATA:22
PN:59303	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 22.080	AFL	0								
					PROC. REF: GENERIC NO REF					
222001		MACH TRIM UNIT								Component ATA:22
PN:051162-03	MOS/MSC	24-Oct-91	O/C							
SN:353	HRS	0		TSN 0						
WC#: 22.150	AFL	0								
					PROC. REF: GENERIC NO REF					
229999[U]		FLIGHT CONTROL COMPUTER BLOWER								Component ATA:22
PN:028866	MOS/MSC	25-May-06	O/C	TSN 0						
SN:N/A	HRS	5898.7		TSN 0						
	AFL	3593		TSN 0						
ATA 23 - COMMUNICATIONS										
23-00-00-710-802-01		OPERATIONAL TEST OF THE OPTIONAL COMMUNICATION OR SECURITY SYSTEM EQUIPMENT								Service ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-00-00-710-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
23-11-00-710-802-01	OPERATIONAL TEST OF THE VHF COMMUNICATION SYSTEM - VHF 1 SYSTEM								Service	ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-11-00-710-802, AMM 23-11-00-710-802, AMM 23-11-00-710-802					
23-11-00-710-802-02	OPERATIONAL TEST OF THE VHF COMMUNICATION SYSTEM - VHF 2 SYSTEM								Service	ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-11-00-710-802, AMM 23-11-00-710-802, AMM 23-11-00-710-802					
23-11-00-710-802-03	OPERATIONAL TEST OF THE VHF COMMUNICATION SYSTEM - VHF 3 SYSTEM								Service	ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-11-00-710-802, AMM 23-11-00-710-802, AMM 23-11-00-710-802					
23-11-01-710-801-01	OPERATIONAL TEST OF THE VHF 3 COMMUNICATION SYSTEM								Service	ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-11-01-710-801					
23-11-05-900-801-01	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 1 ANTENNA (13RC) OR (L210RC)								Component	ATA:23
PN:ANV142SZ	MOS/MSC	11-Jan-00	O/C							
SN:646	HRS	3664								
WC#: 23.020	AFL	2376								
					PROC. REF: AMM 23-11-05-900-801					
23-11-05-900-801-02	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 2 ANTENNA (23RC) OR (R215RC)								Component	ATA:23
PN:S65-8280-10	MOS/MSC	22-Jan-03	O/C	TSN 0						
SN:10398	HRS	4602.6		TSN 0						
WC#: 23.030	AFL	2905		TSN 0						
					PROC. REF: AMM 23-11-05-900-801					
23-11-05-900-801-03	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 3 ANTENNA (93RC) OR (305RC)								Component	ATA:23
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.150	AFL	0		TSN 0						
					PROC. REF: AMM 23-11-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
23-11-21-900-801-01	REMOVAL / INSTALLATION OF THE VHF TRANSCEIVER - VHF 1 TRANSCEIVER (L220RC)									Component ATA:23
PN:822-1113-001	MOS/MSC	21-Jan-02	O/C							
SN:30409	HRS	4119								
WC#: 23.040	AFL	2647								
					PROC. REF: AMM 23-11-21-900-801					
23-11-21-900-801-02	REMOVAL / INSTALLATION OF THE VHF TRANSCEIVER - VHF 2 TRANSCEIVER (R220RC)									Component ATA:23
PN:822-1113-001	MOS/MSC	21-Jan-02	O/C							
SN:28137	HRS	4119								
WC#: 23.040	AFL	2647								
					PROC. REF: AMM 23-11-21-900-801					
23-11-21-900-801-03	REMOVAL / INSTALLATION OF THE VHF TRANSCEIVER - VHF 3 TRANSCEIVER (320RC)									Component ATA:23
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.090	AFL	0		TSN 0						
					PROC. REF: AMM 23-11-21-900-801					
23-12-00-710-801-01	OPERATIONAL TEST OF THE HF COMMUNICATION SYSTEM - HF 1 SYSTEM									Service ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-12-00-710-801, AMM 23-12-00-710-801, AMM 23-12-00-710-801, AMM 23-12-00-710-801					
23-12-00-710-801-02	OPERATIONAL TEST OF THE HF COMMUNICATION SYSTEM - HF 2 SYSTEM									Service ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-12-00-710-801, AMM 23-12-00-710-801, AMM 23-12-00-710-801, AMM 23-12-00-710-801					
23-12-09-610-801-01	SERVICING OF THE HF ANTENNA COUPLER - HF 1 COUPLER (3RE)									Service ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-12-09-610-801, AMM 23-12-09-610-801					
23-12-09-610-801-02	SERVICING OF THE HF ANTENNA COUPLER - HF 2 COUPLER (23RE)									Service ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-12-09-610-801, AMM 23-12-09-610-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
23-12-13-900-801-01	REMOVAL / INSTALLATION OF THE HF ANTENNA - HF ANTENNA (5RE)								Component	ATA:23
PN:F50B312001A3	MOS/MSC	24-Oct-91	O/C							
SN:51RA224	HRS	0		TSN 0						
WC#: 23.010	AFL	0								
					PROC. REF: AMM 23-12-13-900-801					
23-13-00-710-801-01	OPERATIONAL TEST OF THE V/UHF SYSTEMS - V/UHF 1 SYSTEM								Service	ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-13-00-710-801					
23-13-00-710-801-02	OPERATIONAL TEST OF THE V/UHF SYSTEMS - V/UHF 2 SYSTEM								Service	ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-13-00-710-801					
23-50-00-710-801-01	OPERATIONAL TEST OF THE AUDIO INTEGRATING SYSTEM								Service	ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-50-00-710-801, AMM 23-50-00-710-801					
23-50-01-820-801-01	ADJUSTMENT OF THE INTERCOM SYSTEM								Service	ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-50-01-820-801					
23-60-00-760-801-01[S]	VISUAL INSPECTION AND ELECTRICAL BONDING CHECK OF THE STATIC DISCHARGERS								Service	ATA:23
	MOS	07-Sep-22								
	HRS	8823	1500							
WC#: 23.060	AFL	5651								
					PROC. REF: AMM 23-60-00-760-801					PKG:21
23-60-01-900-801-01	REMOVAL / INSTALLATION OF THE STATIC DISCHARGERS								Component	ATA:23
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 23-60-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
23-81-00-860-801-01		RADIO TUNING UNIT (RTU) CONFIGURATION								Service ATA:23
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 23-81-00-860-801					
23-81-01-900-801-01		REMOVAL / INSTALLATION OF THE RADIO TUNING UNITS (RTU) - RTU 1 (L230RC)								Component ATA:23
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.050	AFL	0		TSN 0						
					PROC. REF: AMM 23-81-01-900-801					
23-81-01-900-801-02		REMOVAL / INSTALLATION OF THE RADIO TUNING UNITS (RTU) - RTU 2 (R230RC)								Component ATA:23
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.050	AFL	0		TSN 0						
					PROC. REF: AMM 23-81-01-900-801					
231801[U]		NO. 1 EMERGENCY COMMUNICATION POWER SUPPLY								Component ATA:23
PN:501-1228-04	MOS/MSC	18-Mar-14	O/C	TSN 0, TSO 0, TSR 0						
SN:11052	HRS	8118		TSN 0, TSO 0, TSR 0						
	AFL	5255		TSN 0, TSO 0, TSR 0						
231802[U]		VOLTAGE CHECK NO. 1 EMERGENCY COMMUNICATION POWER SUPPLY								Service ATA:23
PN:501-1228-04	MOS	08-Sep-23	6		08-Mar-24		128 d			
SN:11052	HRS	8967								
	AFL	5775								
231803[U]		CAPACITY CHECK NO. 1 EMERGENCY COMMUNICATION POWER SUPPLY								Service ATA:23
PN:501-1228-04	MOS	08-Sep-23	12		08-Sep-24		312 d			
SN:11052	HRS	8967								
	AFL	5775								
Special Properties: TRACKED ITEM										
231806[U]		EMERGENCY COMM BATTERY INVERTER								Component ATA:23
PN:501-1318-01	MOS/MSC	09-Apr-92	O/C							
SN:3587	HRS	26								
	AFL	13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
232011		NO. 1 VHF CONTROL								Component ATA:23
PN:822-0836-334	MOS/MSC	14-Apr-10	O/C	TSO 0						
SN:33YDW	HRS	7268.8		TSO 0						
WC#: 23.050	AFL	4606		TSO 0						
					PROC. REF: GENERIC NO REF					
232031		NO. 2 VHF CONTROL								Component ATA:23
PN:822-0836-334	MOS/MSC	17-Dec-04	O/C	TSR 0						
SN:10Y5J	HRS	5382		TSR 0						
WC#: 23.050	AFL	3315		TSR 0						
					PROC. REF: GENERIC NO REF					
232066		NO. 3 VHF CONTROL								Component ATA:23
PN:516-1025-603	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.090	AFL	0								
					PROC. REF: GENERIC NO REF					
232071		HF TRANSCEIVER								Component ATA:23
PN:064-1015-01	MOS/MSC	07-Mar-16	O/C	TSR 0						
SN:27735	HRS	8278.1		TSR 0						
WC#: 23.070	AFL	5347		TSR 0						
					PROC. REF: GENERIC NO REF					
232076		NO. 2 HF TRANSCEIVER								Component ATA:23
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.170	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
232081		HF AMPLIFIER COUPLER								Component ATA:23
PN:064-1017-02	MOS/MSC	07-Mar-16	O/C	TSR 0						
SN:12644	HRS	8278.1		TSR 0						
WC#: 23.070	AFL	5347		TSR 0						
					PROC. REF: GENERIC NO REF					
232083		NO. 2 HF AMPLIFIER/ COUPLER								Component ATA:23
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.130	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
232086		NO. 1 HF CONTROL UNIT								Component ATA:23
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.140	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
232088		NO. 2 HF CONTROL UNIT								Component ATA:23
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.110	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
232111		UHF ANTENNA								Component ATA:23
PN:MDC7-8	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.110	AFL	0								
					PROC. REF: GENERIC NO REF					
232121		UHF TRANSCEIVER								Component ATA:23
PN:9595-102-03301	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.120	AFL	0								
					PROC. REF: GENERIC NO REF					
232131		UHF CONTROL								Component ATA:23
PN:9595-102-00214	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.110	AFL	0								
					PROC. REF: GENERIC NO REF					
232141		UHF DISPLAY								Component ATA:23
PN:2-39388-A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.110	AFL	0								
					PROC. REF: GENERIC NO REF					
232801[U]		HF CONTROL								Component ATA:23
PN:064-1016-03	MOS/MSC	09-Apr-92	O/C							
SN:7861	HRS	26								
	AFL	13								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
232803[U]		NO. 1 AUDIO SELECT PANEL								Component ATA:23
PN:M1045-FBAA-HJF	MOS/MSC	18-Nov-22	O/C							
SN:9109028	HRS	8850.4								
	AFL	5691								
232805[U]		NO. 2 HF CONTROL								Component ATA:23
PN:064-1016-03	MOS/MSC	15-Dec-12	O/C	TSR 1						
SN:7944	HRS	7936		TSR 0						
	AFL	5150		TSR 0						
232807[U]		NO. 2 AUDIO SELECT PANEL								Component ATA:23
PN:M1045-FBAA-HJF	MOS/MSC	18-Nov-22	O/C							
SN:9105062	HRS	8850.4								
	AFL	5691								
232809[U]		NO. 2 HF TRANSCEIVER								Component ATA:23
PN:064-1015-01	MOS/MSC	09-Apr-92	O/C							
SN:27735	HRS	26								
	AFL	13								
232813[U]		NO. 2 HF AMPLIFIER/COUPLER								Component ATA:23
PN:064-1017-02	MOS/MSC	09-Apr-92	O/C							
SN:12644	HRS	26								
	AFL	13								
232817[U]		SELCAL DECODER								Component ATA:23
PN:2800-0012-105	MOS/MSC	09-Apr-92	O/C							
SN:01059	HRS	26								
	AFL	13								
232845[U]		HF SWITCHING UNIT ANTENNA								Component ATA:23
PN:071-1270-01	MOS/MSC	09-Apr-92	O/C							
SN:1735	HRS	26								
	AFL	13								
232849[U]		NO. 1 HF BRIDGING AMPLIFIER								Component ATA:23
PN:071-0019-00	MOS/MSC	07-Mar-16	O/C							
SN:2328	HRS	8278.1								
	AFL	5347								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
232854[U]		NO. 2 HF BRIDGING AMPLIFIER								Component ATA:23
PN:071-0019-00	MOS/MSC	09-Apr-92	O/C							
SN:2328	HRS	26								
	AFL	13								
233001		PUBLIC ADDRESS (TEAM) AMPLIFIER								Component ATA:23
PN:M10505-1	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.080	AFL	0								
					PROC. REF: GENERIC NO REF					
233006		PILOT AUDIO CONTROL								Component ATA:23
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.130	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
233011		COPILOT AUDIO CONTROL								Component ATA:23
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 23.160	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
233801[U]		VIDEO MONITOR-								Component ATA:23
PN:1500-003	MOS/MSC	08-Dec-06	O/C	TSN 0						
SN:0609L008	HRS	5992.2		TSN 0						
	AFL	3650		TSN 0						
233811[U]		AUDIO TAPE RECORDER								Component ATA:23
PN:EV-C3	MOS/MSC	09-Apr-92	O/C							
SN:66063	HRS	26								
	AFL	13								
233816[U]		CABIN STEREO BK AMPLIFIER								Component ATA:23
PN:M1050-L358-02	MOS/MSC	09-Apr-92	O/C							
SN:9201153	HRS	26								
	AFL	13								
234A11[U]		#1 AUDIO INTERFACE UNIT								Component ATA:23
PN:822-0271-001	MOS/MSC	27-Jan-03	O/C	TSN 0						
SN:12J0X	HRS	4602		TSN 0						
	AFL	2905		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
234A16[U]		#2 AUDIO INTERFACE UNIT								Component ATA:23
PN:822-0271-001	MOS/MSC	27-Jan-03	O/C	TSN 0						
SN:12J1B	HRS	4602		TSN 0						
	AFL	2905		TSN 0						
235801[U]		FLITEFONE TRANSCEIVER								Component ATA:23
PN:400-10640-001	MOS/MSC	17-Dec-04	O/C	TSR 0						
SN:300132	HRS	5382		TSR 0						
	AFL	3315		TSR 0						
235811[U]		FLITEFONE ANTENNA								Component ATA:23
PN:015-10306-001	MOS/MSC	08-Dec-06	O/C	TSN 0						
SN:4559	HRS	5992.2		TSN 0						
	AFL	3650		TSN 0						
235813[U]		CABIN NO.1 CONTROL								Component ATA:23
PN:400-0123-211	MOS/MSC	09-Apr-92	O/C							
SN:6728	HRS	26								
	AFL	13								
235815[U]		CABIN NO.2 CONTROL								Component ATA:23
PN:400-0123-210	MOS/MSC	09-Apr-92	O/C							
SN:6713	HRS	26								
	AFL	13								
235820[U]		VIDEO PRESS SWITCH								Component ATA:23
PN:44145	MOS/MSC	09-Apr-92	O/C							
SN:0225	HRS	26								
	AFL	13								
ATA 24 - ELECTRICAL POWER										
24-00-00-860-801-01		ENERGIZATION / DE-ENERGIZATION OF THE AIRCRAFT SYSTEMS - WITH BATTERIES								Service ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-00-00-860-801					
24-00-00-860-801-02		ENERGIZATION / DE-ENERGIZATION OF THE AIRCRAFT SYSTEMS - WITH ELECTRICAL GROUND POWER UNIT								Service ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-00-00-860-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-00-00-910-801-01	ELECTRICAL SYSTEM MAINTENANCE AND SAFETY PRECAUTIONS								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-00-00-910-801					
24-20-00-720-802-01[S]	FUNCTIONAL TEST OF THE AC GENERATION SYSTEM								Service	ATA:24
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 24.040	AFL	5651								
					PROC. REF: AMM 24-20-00-720-802					PKG:21
24-20-01-900-802-01	REMOVAL / INSTALLATION OF THE PILOT, COPILOT, EMERGENCY AND INS INVERTERS - PILOT INVERTER (2X1)								Component	ATA:24
PN:PC17A	MOS/MSC	29-Sep-07	O/C							
SN:3238A	HRS	6412.9		TSO 450.3						
WC#: 24.030	AFL	3963		TSO 403						
					PROC. REF: AMM 24-20-01-900-802					
24-20-01-900-802-02	REMOVAL / INSTALLATION OF THE PILOT, COPILOT, EMERGENCY AND INS INVERTERS - COPILOT INVERTER (2X2)								Component	ATA:24
PN:PC17A	MOS/MSC	24-Oct-91	O/C							
SN:8321A	HRS	0		TSN 0						
WC#: 24.030	AFL	0								
					PROC. REF: AMM 24-20-01-900-802					
24-20-01-900-802-03	REMOVAL / INSTALLATION OF THE PILOT, COPILOT, EMERGENCY AND INS INVERTERS - ST-BY INVERTER (2X3)								Component	ATA:24
PN:PC17A	MOS/MSC	24-Oct-91	O/C							
SN:8759A	HRS	0		TSN 0						
WC#: 24.030	AFL	0								
					PROC. REF: AMM 24-20-01-900-802					
24-20-01-900-802-04	REMOVAL / INSTALLATION OF THE PILOT, COPILOT, EMERGENCY AND INS INVERTERS - INS INVERTER (48X)								Component	ATA:24
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.880	AFL	0		TSN 0						
					PROC. REF: AMM 24-20-01-900-802					
24-30-00-710-801-01[S]	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 1								Service	ATA:24
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 24.230	AFL	5651								
					PROC. REF: AMM 24-30-00-710-801					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-30-00-710-801-02[S]	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 2								Service	ATA:24
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 24.230	AFL	5651								
					PROC. REF: AMM 24-30-00-710-801					PKG:21
24-30-00-710-801-03[S]	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 3								Service	ATA:24
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 24.230	AFL	5651								
					PROC. REF: AMM 24-30-00-710-801					PKG:21
24-30-00-710-801-04[S]	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - APU								Service	ATA:24
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 24.300	AFL	5651								
					PROC. REF: AMM 24-30-00-710-801					PKG:21
24-31-00-720-801-01	FUNCTIONAL TEST OF THE DC GENERATION SYSTEM								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-31-00-720-801					
24-31-05-900-801-01	REMOVAL / INSTALLATION OF THE STARTER-GENERATOR POWER CABLES - ENGINE 1 STARTER-GENERATOR POWER CABLE								Component	ATA:24
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 24-31-05-900-801					
24-31-05-900-801-02	REMOVAL / INSTALLATION OF THE STARTER-GENERATOR POWER CABLES - ENGINE 3 STARTER-GENERATOR POWER CABLE								Component	ATA:24
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 24-31-05-900-801					
24-31-09-700-802-01	CHECK / ADJUSTMENT OF THE GENERATOR CONTROL UNITS - GCU 1 (17P1)								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-31-09-700-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-31-09-700-802-02	CHECK / ADJUSTMENT OF THE GENERATOR CONTROL UNITS - GCU 2 (17P2)								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-31-09-700-802					
24-31-09-700-802-03	CHECK / ADJUSTMENT OF THE GENERATOR CONTROL UNITS - GCU 3 (17P3)								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-31-09-700-802					
24-31-09-700-802-04	CHECK / ADJUSTMENT OF THE GENERATOR CONTROL UNITS - APU GCU (107P) OR (22PA)								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-31-09-700-802					
24-31-09-900-801-01	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 1 (17P1)								Component	ATA:24
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 24-31-09-900-801					
24-31-09-900-801-02	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 2 (17P2)								Component	ATA:24
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 24-31-09-900-801					
24-31-09-900-801-03	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 3 (17P3)								Component	ATA:24
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 24-31-09-900-801					
24-31-09-900-801-04	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - APU GCU (107P)								Component	ATA:24
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 24-31-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-31-13-350-801-01	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 1 STARTER-GENERATOR (3P1)									Service ATA:24
PN:8060-360	MOS	07-Aug-20						OVERHAUL		
SN:229	HRS	8690.7	1200 (+3%)		9890.7	9926.7	898.6 (+36)			
WC#: 24.080	AFL	5593								
					PROC. REF: AMM 24-31-13-350-801					
24-31-13-350-801-02	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 2 STARTER-GENERATOR (3P2)									Service ATA:24
PN:8060-360	MOS	16-Jan-15						OVERHAUL		
SN:513	HRS	8154.7	1200 (+3%)		9354.7	9390.7	362.6 (+36)			
WC#: 24.090	AFL	5279								
					PROC. REF: AMM 24-31-13-350-801					
24-31-13-350-801-03	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 3 STARTER-GENERATOR (3P3)									Service ATA:24
PN:8060-360	MOS	16-Jan-15						OVERHAUL		
SN:1559	HRS	8154.7	1200 (+3%)		9354.7	9390.7	362.6 (+36)			
WC#: 24.085	AFL	5279								
					PROC. REF: AMM 24-31-13-350-801					
24-31-13-350-801-04	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - APU STARTER-GENERATOR (103P) OR (21PA)									Service ATA:24
PN:8060-360	MOS	25-Sep-15						OVERHAUL		
SN:1027	HRS	8249								
WC#: 24.210	AFL	5329								
	APH	4633.8	1200 (+3%)		5833.8	5869.8	717.9 (+36)			
					PROC. REF: AMM 24-31-13-350-801					
24-31-13-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE STARTER-GENERATORS - ENGINE 1 STARTER-GENERATOR (3P1)									Component ATA:24
PN:8060-360	MOS/MSC	07-Aug-20	H/T	TSO 0						
SN:229	HRS	8690.7		TSO 0						
WC#: 24.080	AFL	5593		TSO 0						
					PROC. REF: AMM 24-31-13-900-801					
24-31-13-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE STARTER-GENERATORS - ENGINE 2 STARTER-GENERATOR (3P2)									Component ATA:24
PN:8060-360	MOS/MSC	16-Jan-15	H/T	TSO 0						
SN:513	HRS	8154.7		TSO 0						
WC#: 24.090	AFL	5279		TSO 0						
					PROC. REF: AMM 24-31-13-900-801					
24-31-13-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE STARTER-GENERATORS - ENGINE 3 STARTER-GENERATOR (3P3)									Component ATA:24
PN:8060-360	MOS/MSC	16-Jan-15	H/T	TSO 0						
SN:1559	HRS	8154.7		TSO 0						
WC#: 24.085	AFL	5279		TSO 0						
					PROC. REF: AMM 24-31-13-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-31-17-220-803-01	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 1 STARTER-GENERATOR (3P1)									Service ATA:24
PN:8060-360	MOS	07-Aug-20								
SN:229	HRS	8690.7	T:600 (+60)		9290.7	9350.7	298.6 (+60)			
	AFL	5593								
					PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803					
24-31-17-220-803-02	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 2 STARTER-GENERATOR (3P2)									Service ATA:24
PN:8060-360	MOS	12-Feb-21								
SN:513	HRS	8730.5	T:600 (+60)		9330.5	9390.5	338.4 (+60)			
	AFL	5610								
					PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803					
24-31-17-220-803-03	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 3 STARTER-GENERATOR (3P3)									Service ATA:24
PN:8060-360	MOS	04-Sep-20								
SN:1559	HRS	8695.7	T:600 (+60)		9295.7	9355.7	303.6 (+60)			
	AFL	5595								
					PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803					
24-31-17-480-801-01	MODIFICATION OF STARTER-GENERATOR BRUSH GAUGE - STARTER-GENERATOR BRUSH GAUGE									Service ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-31-17-480-801					
24-31-17-960-801-01	REPLACEMENT OF THE ENGINE AND APU STARTER-GENERATOR BRUSHES - ENGINE 1 STARTER-GENERATOR BRUSHES									Service ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-31-17-960-801					
24-31-17-960-801-02	REPLACEMENT OF THE ENGINE AND APU STARTER-GENERATOR BRUSHES - ENGINE 2 STARTER-GENERATOR BRUSHES									Service ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-31-17-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-31-17-960-801-03	REPLACEMENT OF THE ENGINE AND APU STARTER-GENERATOR BRUSHES - ENGINE 3 STARTER-GENERATOR BRUSHES								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-31-17-960-801					
24-31-17-960-801-04	REPLACEMENT OF THE ENGINE AND APU STARTER-GENERATOR BRUSHES - APU STARTER-GENERATOR BRUSHES								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-31-17-960-801					
24-32-00-710-801-01	OPERATIONAL TEST OF THE BATTERY OVERHEAT DETECTION CIRCUIT								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-32-00-710-801					
24-32-00-710-803-01 S	OPERATIONAL TEST OF THE BATTERY BUS DIODES - DIODE (59P1)								Service	ATA:24
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 24-32-00-710-803					PKG:21
24-32-00-710-803-02 S	OPERATIONAL TEST OF THE BATTERY BUS DIODES - DIODE (59P2)								Service	ATA:24
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 24-32-00-710-803					PKG:21
24-32-00-720-801-01	FUNCTIONAL TEST OF THE BATTERY BUS DIODES - DIODE (59P1)								Service	ATA:24
	MOS/MSC	14-Dec-13	O/C							
	HRS	8092.4								
	AFL	5236								
					PROC. REF: AMM 24-32-00-720-801					
24-32-00-720-801-02	FUNCTIONAL TEST OF THE BATTERY BUS DIODES - DIODE (59P2)								Service	ATA:24
	MOS/MSC	14-Dec-13	O/C							
	HRS	8092.4								
	AFL	5236								
					PROC. REF: AMM 24-32-00-720-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-32-01-700-802-01	REGULAR CHECK OF A MAIN LEAD / ACID BATTERY - BATTERY 1 (2P1)									Service ATA:24
PN:RG390E/LS	MOS	08-Sep-23	6 (+1m)		08-Mar-24	08-Apr-24	128 d (+31)			
SN:41090581	HRS	8967								
WC#: 24.100	AFL	5775								
					PROC. REF: AMM 24-32-01-700-802					
24-32-01-700-802-02	REGULAR CHECK OF A MAIN LEAD / ACID BATTERY - BATTERY 2 (2P2)									Service ATA:24
PN:RG390E/LS	MOS	08-Sep-23	6 (+1m)		08-Mar-24	08-Apr-24	128 d (+31)			
SN:41090586	HRS	8967								
WC#: 24.190	AFL	5775								
					PROC. REF: AMM 24-32-01-700-802					
24-32-01-710-801-01	OPERATIONAL TEST OF THE MAIN BATTERIES - BATTERY 1 (2P1)									Service ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-32-01-710-801					
24-32-01-710-801-02	OPERATIONAL TEST OF THE MAIN BATTERIES - BATTERY 2 (2P2)									Service ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-32-01-710-801					
24-32-01-900-801-01	REMOVAL / INSTALLATION OF THE MAIN BATTERIES - BATTERY 1 (2P1)									Component ATA:24
PN:RG390E/LS	MOS/MSC	28-Oct-20	O/C	TSN 0						
SN:41090581	HRS	8701		TSN 0						
WC#: 24.100	AFL	5598		TSN 0						
					PROC. REF: AMM 24-32-01-900-801					
24-32-01-900-801-02	REMOVAL / INSTALLATION OF THE MAIN BATTERIES - BATTERY 2 (2P2)									Component ATA:24
PN:RG390E/LS	MOS/MSC	28-Oct-20	O/C	TSN 0						
SN:41090586	HRS	8701		TSN 0						
WC#: 24.190	AFL	5598		TSN 0						
					PROC. REF: AMM 24-32-01-900-801					
24-32-01-960-801-01	DISCARD OF THE MAIN LEAD / ACID BATTERIES - BATTERY 1 (2P1)									Service ATA:24
PN:RG390E/LS	MOS	28-Oct-20	60		28-Oct-25		727 d	LIFE LIMIT		
SN:41090581	HRS	8701	5000		13701		4708.9			
WC#: 24.100	AFL	5598								
					PROC. REF: AMM 24-32-01-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-32-01-960-801-02	DISCARD OF THE MAIN LEAD / ACID BATTERIES - BATTERY 2 (2P2)									Service ATA:24
PN:RG390E/LS	MOS	28-Oct-20	60		28-Oct-25		727 d	LIFE LIMIT		
SN:41090586	HRS	8701	5000		13701		4708.9			
WC#: 24.190	AFL	5598								
					PROC. REF: AMM 24-32-01-960-801					
24-32-05-710-801-01	OPERATIONAL TEST OF THE BATTERY FAN - BATTERY FAN (55P)									Service ATA:24
PN:VA0906XXA	MOS/MSC	16-Aug-96	C/C							
SN:10860	HRS	2146								
WC#: 24.170	AFL	1506								
					PROC. REF: AMM 24-32-05-710-801					
24-32-09-610-801-02	SERVICING NO. 1 IRS EMERGENCY POWER SUPPLY (NICKEL-CADMIUM BATTERY ONLY)									Service ATA:24
PN:100-0202-01	MOS/MSC	08-Sep-23	N/A							
SN:1093	HRS	8967								
WC#: 34.890	AFL	5775								
					PROC. REF: AMM 24-32-09-610-801, AMM 24-32-09-610-801, AMM 24-32-09-610-801, AMM 24-32-09-610-801					
24-32-09-610-801-03	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 2 STAND-BY BATTERY (295NP)									Service ATA:24
PN:100-0202-01	MOS/MSC	08-Sep-23	O/C							
SN:1783	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 24-32-09-610-801					
24-32-09-610-801-04	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 3 STAND-BY BATTERY (95NP)									Service ATA:24
PN:100-0202-01	MOS/MSC	08-Sep-23	O/C							
SN:1813	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 24-32-09-610-801					
24-32-09-610-801-05	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - AUXILIARY BATTERY (710PE)									Service ATA:24
PN:PN	MOS/MSC		N/A							
SN:NOT INSTALLED	HRS									
WC#: 23.100	AFL									
					PROC. REF: AMM 24-32-09-610-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-32-09-610-801-06	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (85RC)								Service	ATA:24
PN:PN	MOS/MSC		O/C							
SN:NOT INSTALLED	HRS									
	AFL									
					PROC. REF: AMM 24-32-09-610-801					
24-32-09-610-801-07	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - VHF 1 STAND-BY BATTERY (17RC)								Service	ATA:24
PN:PN	MOS/MSC		O/C							
SN:NOT INSTALLED	HRS									
	AFL									
					PROC. REF: AMM 24-32-09-610-801					
24-32-09-610-802-01	SERVICING OF "J.E.T." LEAD / ACID STAND-BY BATTERIES - VOLTAGE TEST OF THE BATTERY (5F)								Service	ATA:24
PN:501-1228-04	MOS	08-Sep-23	6		08-Mar-24		128 d			
SN:2900	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 24-32-09-610-802					
24-32-09-610-802-02	SERVICING OF "J.E.T." LEAD / ACID STAND-BY BATTERIES - CAPACITY TEST OF THE BATTERY (5F)								Service	ATA:24
PN:501-1228-04	MOS	08-Sep-23	12 (+3%)		08-Sep-24	18-Sep-24	312 d (+10)			
SN:2900	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 24-32-09-610-802					
24-32-09-710-802-02	OPERATIONAL TEST OF "SECURAPLANE" XL246-A TYPE STAND-BY BATTERIES - IRS 1 STAND-BY BATTERY (295NP)								Service	ATA:24
PN:100-0202-01	MOS	08-Sep-23	12 (+3%)		08-Sep-24	18-Sep-24	312 d (+10)			
SN:1093	HRS	8967								
WC#: 34.950	AFL	5775								
					PROC. REF: AMM 24-32-09-710-802					
24-32-09-710-802-03	OPERATIONAL TEST OF "SECURAPLANE" XL246-A TYPE STAND-BY BATTERIES - IRS 2 STAND-BY BATTERY (295NP)								Service	ATA:24
PN:100-0202-01	MOS	08-Sep-23	12 (+3%)		08-Sep-24	18-Sep-24	312 d (+10)			
SN:1783	HRS	8967								
WC#: 34.950	AFL	5775								
					PROC. REF: AMM 24-32-09-710-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-32-09-710-802-04	OPERATIONAL TEST OF "SECURAPLANE" XL246-A TYPE STAND-BY BATTERIES - IRS 3 STAND-BY BATTERY (295NP)								Service	ATA:24
PN:100-0202-01	MOS	08-Sep-23	12 (+3%)		08-Sep-24	18-Sep-24	312 d (+10)			
SN:1813	HRS	8967								
WC#: 34.950	AFL	5775								
					PROC. REF: AMM 24-32-09-710-802					
24-32-09-710-802-05	OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - AUXILIARY BATTERY (710PE)								Service	ATA:24
PN:PN	MOS/MSC		O/C							
SN:NOT INSTALLED	HRS									
	AFL									
					PROC. REF: AMM 24-32-09-710-802					
24-32-09-900-801-01	REMOVAL / INSTALLATION OF THE - STAND-BY HORIZON BATTERY (5F)								Component	ATA:24
PN:501-1228-04	MOS/MSC	27-May-21	O/C							
SN:2900	HRS	8754.4								
WC#: 34.380	AFL	5620								
					PROC. REF: AMM 24-32-09-900-801					
24-32-09-900-801-02	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 1 STAND-BY BATTERY (195NP)								Component	ATA:24
PN:100-0202-01	MOS/MSC	08-Sep-23	O/C	TSR 10						
SN:1093	HRS	8967		TSR 0						
WC#: 34.950	AFL	5775		TSR 0						
					PROC. REF: AMM 24-32-09-900-801					
24-32-09-900-801-03	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 2 STAND-BY BATTERY (295NP)								Component	ATA:24
PN:100-0202-01	MOS/MSC	08-Sep-23	O/C	TSR 7						
SN:1783	HRS	8967		TSR 0						
WC#: 34.950	AFL	5775		TSR 0						
					PROC. REF: AMM 24-32-09-900-801					
24-32-09-900-801-04	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 3 STAND-BY BATTERY (95NP)								Component	ATA:24
PN:100-0202-01	MOS/MSC	08-Sep-23	O/C	TSR 12						
SN:1813	HRS	8967		TSR 0						
WC#: 34.950	AFL	5775		TSR 0						
					PROC. REF: AMM 24-32-09-900-801					
24-32-09-900-801-05	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - AUXILIARY BATTERY (710PE)								Component	ATA:24
PN:PN	MOS/MSC		O/C							
SN:NOT INSTALLED	HRS									
	AFL									
					PROC. REF: AMM 24-32-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-32-09-900-801-06	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (85RC)								Component	ATA:24
PN:PN	MOS/MSC		O/C							
SN:NOT INSTALLED	HRS									
WC#: 23.100	AFL									
					PROC. REF: AMM 24-32-09-900-801					
24-32-09-900-801-07	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - VHF 1 STAND-BY BATTERY (17RC)								Component	ATA:24
PN:PN	MOS/MSC		O/C							
SN:NOT INSTALLED	HRS									
	AFL									
					PROC. REF: AMM 24-32-09-900-801					
24-32-09-960-801-01	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - STAND-BY HORIZON BATTERY (5F)								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-32-09-960-801					
24-32-09-960-801-02	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - IRS 1 STAND-BY BATTERY (195NP)								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-32-09-960-801					
24-32-09-960-801-03	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - IRS 2 STAND-BY BATTERY (295NP)								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-32-09-960-801					
24-32-09-960-801-04	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - IRS 3 STAND-BY BATTERY (95NP)								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-32-09-960-801					
24-32-09-960-801-05	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - AUXILIARY BATTERY (710PE)								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-32-09-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-32-09-960-801-06	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - VHF 3 STAND-BY BATTERY (85RC)									Service ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-32-09-960-801					
24-32-09-960-801-07	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - VHF 1 STAND-BY BATTERY (17RC)									Service ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-32-09-960-801					
24-32-09-960-802-02	DISCARD OF THE "SECURAPLANE" XL246-A TYPE STAND-BY BATTERY PACKS - IRS 1 STAND-BY BATTERY (195NP)									Service ATA:24
PN:100-0202-01	MOS	08-Sep-23	48	TAC 10	08-Nov-26		1103 d	LIFE LIMIT		
SN:1093	HRS	8967		TAC 0						
WC#: 34.950	AFL	5775		TAC 0						
					PROC. REF: AMM 24-32-09-960-802					
24-32-09-960-802-03	DISCARD OF THE "SECURAPLANE" XL246-A TYPE STAND-BY BATTERY PACKS - IRS 2 STAND-BY BATTERY (195NP)									Service ATA:24
PN:100-0202-01	MOS	08-Sep-23	48	TAC 7	08-Feb-27		1195 d	LIFE LIMIT		
SN:1783	HRS	8967		TAC 0						
WC#: 34.950	AFL	5775		TAC 0						
					PROC. REF: AMM 24-32-09-960-802					
24-32-09-960-802-04	DISCARD OF THE "SECURAPLANE" XL246-A TYPE STAND-BY BATTERY PACKS - IRS 3 STAND-BY BATTERY (195NP)									Service ATA:24
PN:100-0202-01	MOS	08-Sep-23	48	TAC 12	08-Sep-26		1042 d	LIFE LIMIT		
SN:1813	HRS	8967		TAC 0						
WC#: 34.950	AFL	5775		TAC 0						
					PROC. REF: AMM 24-32-09-960-802					
24-32-09-960-802-05	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - AUXILIARY BATTERY (710PE)									Service ATA:24
PN:PN	MOS/MSC		O/C							
SN:NOT INSTALLED	HRS									
	AFL									
					PROC. REF: AMM 24-32-09-960-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-33-01-900-801-01	REMOVAL / INSTALLATION OF THE APU STARTER-GENERATOR - APU STARTER-GENERATOR (103P) OR (21PA)								Component	ATA:24
PN:8060-360	MOS/MSC	25-Sep-15	H/T	TSO 0						
SN:1027	HRS	8249		TSO 0						
WC#: 24.210	AFL	5329		TSO 0						
	APH	4633.8	0	TSO 0						
					PROC. REF: AMM 24-33-01-900-801					
24-33-05-220-803-01	CHECK OF THE APU STARTER-GENERATOR BRUSHES - APU STARTER-GENERATOR (103P) OR (21PA)								Service	ATA:24
PN:8060-360	MOS	25-Sep-15								
SN:1027	HRS	8249								
	AFL	5329								
	APH	4633.8	T:600 (+60)		5233.8	5293.8	117.9 (+60)			
					PROC. REF: AMM 24-33-05-220-803, AMM 24-33-05-220-803, AMM 24-33-05-220-803, AMM 24-33-05-220-803					
24-40-00-720-801-01[S]	FUNCTIONAL TEST OF THE GROUND POWER RECEPTACLE OVERVOLTAGE PROTECTION PCB - GPU OVERVOLTAGE PROTECTION PCB (42P)								Service	ATA:24
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 24.250	AFL	5651								
					PROC. REF: AMM 24-40-00-720-801					PKG:21
24-41-00-720-801-01	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - GENERAL TEST OF THE CHARGING FUNCTION								Service	ATA:24
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-41-00-720-801					
24-41-00-720-801-02	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - TEST OF THE SAFETY DEVICES								Service	ATA:24
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-41-00-720-801					
24-63-13-710-801-01[S]	OPERATIONAL TEST OF THE DOME LIGHT PCB - DOME LIGHT PCB (415J)								Service	ATA:24
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 24.270	AFL	5651								
					PROC. REF: AMM 24-63-13-710-801					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
24-66-01-910-801-01	CONNECTIONS TO CIRCUIT BREAKER PANEL - CIRCUIT BREAKER PANEL								Service	ATA:24
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 24-66-01-910-801					
240011	PRINTED CIRCUIT BOARD								Component	ATA:24
PN:CI915	MOS/MSC	16-Dec-09	O/C							
SN:88	HRS	7169.2								
WC#: 39.020	AFL	4516								
					PROC. REF: GENERIC NO REF					
240016	PRINTED CIRCUIT BOARD								Component	ATA:24
PN:CI852A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 39.020	AFL	0								
					PROC. REF: GENERIC NO REF					
240021	PRINTED CIRCUIT BOARD								Component	ATA:24
PN:CI853B	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 39.020	AFL	0								
					PROC. REF: GENERIC NO REF					
240026	PRINTED CIRCUIT BOARD								Component	ATA:24
PN:CI854A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 39.030	AFL	0								
					PROC. REF: GENERIC NO REF					
240031	PRINTED CIRCUIT BOARD								Component	ATA:24
PN:CI855B	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 39.030	AFL	0								
					PROC. REF: GENERIC NO REF					
240036	PRINTED CIRCUIT BOARD								Component	ATA:24
PN:CI857	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 39.040	AFL	0								
					PROC. REF: GENERIC NO REF					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
240041		PRINTED CIRCUIT BOARD								Component ATA:24
PN:CI857	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 39.040	AFL	0								
					PROC. REF: GENERIC NO REF					
240046		PRINTED CIRCUIT BOARD								Component ATA:24
PN:CI955B	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 39.040	AFL	0								
					PROC. REF: GENERIC NO REF					
242101		ALTERNATING CURRENT VOLTMETER								Component ATA:24
PN:2396-213-0	MOS/MSC	24-Oct-91	O/C							
SN:708	HRS	0		TSN 0						
WC#: 24.010	AFL	0								
					PROC. REF: GENERIC NO REF					
242111		NO. 1 FREQUENCY MONITOR PRINTED CARD								Component ATA:24
PN:C1-818A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.020	AFL	0								
					PROC. REF: GENERIC NO REF					
242116		NO. 2 FREQUENCY MONITOR PRINTED CARD								Component ATA:24
PN:C1-818A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.020	AFL	0								
					PROC. REF: GENERIC NO REF					
243146		NO. 1 GENERATOR CONTROL UNIT (GCU)								Component ATA:24
PN:D22-011-1	MOS/MSC	07-Aug-20	O/C	TSO 0						
SN:D22-100	HRS	8690.7		TSO 0						
WC#: 24.070	AFL	5593		TSO 0						
					PROC. REF: AMM 24-31-09-900-801					
243151		NO. 2 GENERATOR CONTROL UNIT (GCU)								Component ATA:24
PN:D22-011-1	MOS/MSC	07-Mar-00	O/C							
SN:80444-15	HRS	3734								
WC#: 24.070	AFL	2405								
					PROC. REF: AMM 24-31-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
243156		NO. 3 GENERATOR CONTROL UNIT (GCU)								Component ATA:24
PN:D22-010	MOS/MSC	13-Aug-20	O/C							
SN:4450-188	HRS	8693.2								
WC#: 24.070	AFL	5594								
					PROC. REF: AMM 24-31-09-900-801					
243191		NO. 1 BATTERY (THERMISTOR) TEMPERATURE PROBE								Component ATA:24
PN:PN	MOS/MSC	08-Dec-06	O/C							
SN:REMOVED	HRS	5992.2								
WC#: 24.100	AFL	3650								
					PROC. REF: GENERIC NO REF					
243196		NO. 2 BATTERY (THERMISTOR) TEMPERATURE PROBE								Component ATA:24
PN:PN	MOS/MSC	08-Dec-06	O/C							
SN:REMOVED	HRS	5992.2								
WC#: 24.190	AFL	3650								
					PROC. REF: GENERIC NO REF					
243211		NO. 1 BATTERY CONNECTOR								Component ATA:24
PN:410	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.130	AFL	0								
					PROC. REF: GENERIC NO REF					
243213		NO. 1 BATTERY REVERSE CURRENT RELAY								Component ATA:24
PN:317GC0Y1AB	MOS/MSC	13-Oct-05	O/C	TSO 0						
SN:646	HRS	5630.9		TSO 0						
WC#: 24.140	AFL	3465		TSO 0						
					PROC. REF: GENERIC NO REF					
243216		NO. 2 BATTERY CONNECTOR								Component ATA:24
PN:410	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.130	AFL	0								
					PROC. REF: GENERIC NO REF					
243219		NO. 2 BATTERY REVERSE CURRENT RELAY								Component ATA:24
PN:317GC01Y1AB	MOS/MSC	08-Sep-23	O/C	TSO 0						
SN:568	HRS	8967		TSO 0						
WC#: 24.140	AFL	5775		TSO 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
243221		BATTERY FAN								Component ATA:24
PN:VA0906XXA	MOS/MSC	24-Oct-91	O/C							
SN:10860	HRS	0		TSN 0						
WC#: 24.170	AFL	0								
					PROC. REF: GENERIC NO REF					
243236		NO. 1 GENERATOR REVERSE CURRENT RELAY								Component ATA:24
PN:3510M0	MOS/MSC	24-Oct-91	O/C							
SN:3408	HRS	0		TSN 0						
WC#: 24.150	AFL	0								
					PROC. REF: GENERIC NO REF					
243238		NO. 1 STARTER/ RELAY								Component ATA:24
PN:2540M	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.160	AFL	0								
					PROC. REF: GENERIC NO REF					
243241		NO. 2 GENERATOR REVERSE CURRENT RELAY								Component ATA:24
PN:3510M0	MOS/MSC	24-Oct-91	O/C							
SN:3415	HRS	0		TSN 0						
WC#: 24.150	AFL	0								
					PROC. REF: GENERIC NO REF					
243243		NO. 2 STARTER/ RELAY								Component ATA:24
PN:2540M	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.160	AFL	0								
					PROC. REF: GENERIC NO REF					
243246		NO. 3 GENERATOR REVERSE CURRENT RELAY								Component ATA:24
PN:3510M0	MOS/MSC	24-Oct-91	O/C							
SN:3417	HRS	0		TSN 0						
WC#: 24.150	AFL	0								
					PROC. REF: GENERIC NO REF					
243248		NO. 3 STARTER/ RELAY								Component ATA:24
PN:2540M	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.160	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
243249		APU GENERATOR REVERSE CURRENT RELAY								Component ATA:24
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.280	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
243250		APU STARTER RELAY								Component ATA:24
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.290	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
243251		LH POWER SUPPLY DC VOLTMETER								Component ATA:24
PN:2396-118-0	MOS/MSC	24-Oct-91	O/C							
SN:1174	HRS	0		TSN 0						
WC#: 24.050	AFL	0								
					PROC. REF: GENERIC NO REF					
243261		RH POWER SUPPLY DC VOLTMETER								Component ATA:24
PN:2396-118-0	MOS/MSC	24-Oct-91	O/C							
SN:1279	HRS	0		TSN 0						
WC#: 24.050	AFL	0								
					PROC. REF: GENERIC NO REF					
243271		LH POWER SUPPLY DC AMMETER								Component ATA:24
PN:2396-323-0	MOS/MSC	24-Oct-91	O/C							
SN:862	HRS	0		TSN 0						
WC#: 24.060	AFL	0								
					PROC. REF: GENERIC NO REF					
243281		RH POWER SUPPLY DC AMMETER								Component ATA:24
PN:2396-323-0	MOS/MSC	25-Aug-06	O/C	TSN 0						
SN:1893	HRS	5991.5		TSN 0						
WC#: 24.060	AFL	3649		TSN 0						
					PROC. REF: GENERIC NO REF					
243291		BATTERY TEMPERATURE INDICATOR								Component ATA:24
PN:BTI600-3A	MOS/MSC	24-Oct-91	O/C							
SN:5972	HRS	0		TSN 0						
WC#: 24.200	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
243331		APU GENERATOR CONTROL UNIT (GCU)								Component ATA:24
PN:D22-011-1	MOS/MSC	04-Sep-20	O/C	TSR 0						
SN:80444-02	HRS	8695.7		TSR 0						
WC#: 24.300	AFL	5595		TSR 0						
					PROC. REF: AMM 24-31-09-900-801					
244401		GROUND POWER RECEPTACLE								Component ATA:24
PN:280B	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.180	AFL	0								
					PROC. REF: GENERIC NO REF					
ATA 25 - EQUIPMENT/FURNISHINGS										
25-00-00-100-801-01		CLEANING OF THE FLIGHT COMPARTMENT AND PASSENGER CABIN								Service ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-00-00-100-801					
25-00-01-200-801-01		INSPECTION OF THE ONBOARD KIT								Service ATA:25
	MOS/MSC	09-Mar-18	O/C							
	HRS	8497.6								
WC#: 25.220	AFL	5470								
					PROC. REF: AMM 25-00-01-200-801					
25-11-01-900-801-01		REMOVAL / INSTALLATION OF THE PILOT SEATS - LH PILOT SEAT (L2MG)								Component ATA:25
PN:394-14	MOS/MSC	24-Oct-91	O/C							
SN:279	HRS	0		TSN 0						
WC#: 25.010	AFL	0								
					PROC. REF: AMM 25-11-01-900-801					
25-11-01-900-801-02		REMOVAL / INSTALLATION OF THE PILOT SEATS - RH PILOT SEAT (R2MG)								Component ATA:25
PN:394-24	MOS/MSC	24-Oct-91	O/C							
SN:279	HRS	0		TSN 0						
WC#: 25.010	AFL	0								
					PROC. REF: AMM 25-11-01-900-801					
25-11-05-200-801-01		VISUAL INSPECTION OF BUCKLE SPRING OF ANJOU AERONAUTIQUE SAFETY BELTS AND RESTRAINT SYSTEM (TYPE 343 AND 343-1)								Service ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-11-05-200-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-11-05-200-801-01A	VISUAL INSPECTION OF BUCKLE SPRING OF ANJOU AERONAUTIQUE SAFETY BELTS AND RESTRAINT SYSTEM (TYPE 343 AMD 343-1)								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-11-05-200-801					
25-11-05-220-801-01[S]	DETAILED INSPECTION OF THE PILOT SEAT SAFETY BELT ASSEMBLY - LH PILOT SEAT (L2MG)								Service	ATA:25
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 25-11-05-220-801					PKG:31
25-11-05-220-801-02[S]	DETAILED INSPECTION OF THE PILOT SEAT SAFETY BELT ASSEMBLY - RH PILOT SEAT (R2MG)								Service	ATA:25
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 25-11-05-220-801					PKG:31
25-11-13-640-801-01[S]	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - LH PILOT SEAT (L2MG)								Service	ATA:25
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 25.010	AFL	5651								
					PROC. REF: AMM 25-11-13-640-801					PKG:21
25-11-13-640-801-02[S]	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - RH PILOT SEAT (R2MG)								Service	ATA:25
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 25.010	AFL	5651								
					PROC. REF: AMM 25-11-13-640-801					PKG:21
25-11-19-960-801-01[S]	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - LH PILOT SEAT (L2MG)								Service	ATA:25
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 25-11-19-960-801					PKG:31
25-11-19-960-801-02[S]	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - RH PILOT SEAT (R2MG)								Service	ATA:25
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 25-11-19-960-801					PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-13-05-910-801-01	INSTRUMENT PANEL BACKING UP									Service ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-13-05-910-801					
25-13-13-900-802-01	REMOVAL / INSTALLATION OF THE COCKPIT ROOF HEADLINER									Component ATA:25
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 25-13-13-900-802					
25-14-00-720-801-01	FUNCTIONAL TEST OF THE COCKPIT HEATING MATS									Service ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-14-00-720-801					
25-20-00-100-801-01	CLEANING OF THE EQUIPMENT AND FURNISHINGS									Service ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-20-00-100-801					
25-20-00-610-801-01	SERVICING OF THE EQUIPMENT AND FURNISHINGS									Service ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-20-00-610-801					
25-20-00-710-801-01	OPERATIONAL TEST OF THE CABIN OPTIONAL EQUIPMENT									Service ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-20-00-710-801					
25-33-00-710-801-01	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF COFFEE BREWER									Service ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-33-00-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-33-00-710-801-02	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF COFFEE MAKER								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-33-00-710-801					
25-33-00-710-801-03	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF CONVECTION OVEN								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-33-00-710-801					
25-33-00-710-801-04	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF ESPRESSO MACHINE								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-33-00-710-801					
25-33-00-710-801-05	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF HOT CUP								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-33-00-710-801					
25-33-00-710-801-06	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF MICROWAVE OVEN								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-33-00-710-801					
25-33-00-710-801-07	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF MICROWAVE OVEN BEHIND TAMBOUR DOOR								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-33-00-710-801					
25-33-00-710-801-08	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF WARMER								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-33-00-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-33-00-710-801-09	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF FORWARD WATER HEATER								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-33-00-710-801					
25-33-00-710-802-01	OPERATIONAL TEST OF THE AUXILIARY GALLEY OPTIONAL EQUIPMENT								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-33-00-710-802					
25-33-00-900-801-01	REMOVAL / INSTALLATION OF THE GALLEY & VANITY ELECTRICAL EQUIPMENT								Component	ATA:25
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 25-33-00-900-801					
25-40-00-710-801-01	OPERATIONAL TEST OF THE LAVATORY OPTIONAL EQUIPMENT								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-40-00-710-801					
25-40-25-100-801-01	CLEANING OF THE TRASH CANS								Service	ATA:25
	MOS	09-Mar-18								
	HRS	8497.6	1000		9497.6		505.5			
WC#: 25.060	AFL	5470								
					PROC. REF: AMM 25-40-25-100-801					
25-41-00-220-801-01	INSPECTION OF THE COMPARTMENT UNDER THE FRONT TOILET UNIT								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-41-00-220-801					
25-60-00-200-801-02[S]	INSPECTION OF THE SAFETY EQUIPMENT - SAFETY EQUIPMENT								Service	ATA:25
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 25.200	AFL	5775								
					PROC. REF: AMM 25-60-00-200-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-60-00-200-801-03	INSPECT FIRST AID KIT									Service ATA:25
	MOS	08-Sep-23	12		08-Sep-24		312 d			
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 25-60-00-200-801					
25-61-00-200-881-01	INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207)									Service ATA:25
	MOS	08-Sep-23	12		08-Sep-24		312 d	MANDATORY		
	HRS	8967								
	AFL	5775								
					PROC. REF: GENERIC NO REF, FAR 91.207					
25-61-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - SELF-TEST OF ELT 96/97									Service ATA:25
	MOS/MSC	09-Mar-16	O/C							
	HRS	8281.2								
WC#: 25.210	AFL	5349								
					PROC. REF: AMM 25-61-00-710-801					
25-61-00-710-801-02	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT 96/97 COCKPIT CONTROLS									Service ATA:25
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-61-00-710-801					
25-61-00-710-801-03	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - OPERATIONAL TEST OF ELT 90/91									Service ATA:25
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-61-00-710-801					
25-61-00-710-801-04	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT 96/97 UNIT CONTROLS									Service ATA:25
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-61-00-710-801					
25-61-01-710-801-01	OPERATIONAL TEST OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) G-SWITCH - ELT (32RB)									Service ATA:25
PN:453-5002-366	MOS/MSC	04-Sep-20	N/A							
SN:03074	HRS	8695.7								
	AFL	5595								
					PROC. REF: AMM 25-61-01-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-61-01-900-803-01	REMOVAL / INSTALLATION OF THE ELT AND REPLACEMENT OF THE ELT BATTERY PACKS (ELT 90 / 91 OR ELT 96 / 97) - ELT (32RB)								Component	ATA:25
PN:453-5002-366	MOS/MSC	04-Sep-20	O/C							
SN:03074	HRS	8695.7								
WC#: 25.210	AFL	5595								
					PROC. REF: AMM 25-61-01-900-803					
25-61-01-900-804-01	REMOVAL / INSTALLATION OF THE ELT AND REPLACEMENT OF THE ELT BATTERY PACK (JOLLIET JE2) - ELT (61RC)								Component	ATA:25
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 25-61-01-900-804					
25-61-13-200-801-01	VISUAL INSPECTION OF THE ELT BATTERY PACK (JOLLIET JE2) - ELT (61RC)								Service	ATA:25
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 25-61-13-200-801					
25-61-13-960-801-01	DISCARD OF THE ELT BATTERY PACKS - ELT (32RB) OR ELT (61RC)								Service	ATA:25
PN:453-5002-366	MOS/MSC	04-Sep-20	DUE		30-Jun-25 (M)		607 d	LIFE LIMIT		
SN:03074	HRS	8695.7								
	AFL	5595								
					PROC. REF: AMM 25-61-13-960-801					
25-61-21-900-801-01	REMOVAL / INSTALLATION OF THE ELT ANTENNA - ELT ANTENNA (33RB)								Component	ATA:25
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 25-61-21-900-801					
25-62-00-900-801-01	REMOVAL / INSTALLATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (10FZ1)								Component	ATA:25
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 25-62-00-900-801					
25-62-00-900-801-02	REMOVAL / INSTALLATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (130FZ1)								Component	ATA:25
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 25-62-00-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-62-01-720-801-01		FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (10FZ1)								Service ATA:25
PN:DK120/90	MOS	07-Sep-22	25		07-Oct-24		341 d			
SN:AT125863	HRS	8823								
WC#: 31.100	AFL	5651								
					PROC. REF: AMM 25-62-01-720-801					
25-62-01-720-801-02		FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (130FZ1)								Service ATA:25
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 31.110	AFL	0								
					PROC. REF: AMM 25-62-01-720-801					
25-62-05-960-801-01		RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - CVR UNDERWATER LOCATOR BEACON (10FZ1)								Service ATA:25
PN:DK120/90	MOS/MSC	10-Oct-19	DUE		01-Jan-26 (M)		792 d	LIFE LIMIT		
SN:AT125863	HRS	8674.4								
WC#: 31.100	AFL	5580								
					PROC. REF: AMM 25-62-05-960-801					
25-62-05-960-801-02		RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - FDR UNDERWATER LOCATOR BEACON (130FZ1)								Service ATA:25
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 31.110	AFL	0								
					PROC. REF: AMM 25-62-05-960-801					
25-64-17-200-802-01[U]		INSPECT ALL LIFE VEST YEARLY								Service ATA:25
PN:P01074-201W	MOS	08-Sep-23	12		08-Sep-24		312 d			
SN:22071330346	HRS	8967								
	AFL	5775								
25-64-17-350-802-01		RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - LH PILOT LIFE VEST (L10ME)								Service ATA:25
PN:P01074-201W	MOS	01-Mar-22	120		01-Mar-32		3043 d	OVERHAUL		
SN:22071330346	HRS									
WC#: 25.190	AFL									
					PROC. REF: AMM 25-64-17-350-802					
25-64-17-350-802-02		RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - RH PILOT LIFE VEST (R10ME)								Service ATA:25
PN:P01074-201W	MOS	01-Mar-22	120		01-Mar-32		3043 d	OVERHAUL		
SN:22071330329	HRS									
WC#: 25.190	AFL									
					PROC. REF: AMM 25-64-17-350-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-64-17-350-802-03	RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - THIRD CREW MEMBER LIFE VEST (M10ME)									Service ATA:25
PN:P01074-201W	MOS	01-Mar-22	120		01-Mar-32		3043 d	OVERHAUL		
SN:22071330164	HRS									
	AFL									
					PROC. REF: AMM 25-64-17-350-802					
25-64-17-350-803-01	RESTORATION NO. 1 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)									Service ATA:25
PN:P01074-201W	MOS	01-Mar-22	120		01-Mar-32		3043 d	OVERHAUL		
SN:22071330356	HRS									
WC#: 25.100	AFL									
					PROC. REF: AMM 25-64-17-350-803					
25-64-17-350-803-01	RESTORATION NO. 2 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)									Service ATA:25
PN:P01074-201W	MOS	07-Sep-22	120	TAC 6	07-Mar-32		3049 d	OVERHAUL		
SN:22071330185	HRS	8823		TAC 0						
WC#: 25.110	AFL	5651		TAC 0						
					PROC. REF: AMM 25-64-17-350-803					
25-64-17-350-803-01	RESTORATION NO. 3 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)									Service ATA:25
PN:P01074-201W	MOS	07-Sep-22	120	TAC 6	07-Mar-32		3049 d	OVERHAUL		
SN:22071330210	HRS	8823		TAC 0						
WC#: 25.120	AFL	5651		TAC 0						
					PROC. REF: AMM 25-64-17-350-803					
25-64-17-350-803-01	RESTORATION NO. 4 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)									Service ATA:25
PN:P01074-201W	MOS	07-Sep-22	120	TAC 6	07-Mar-32		3049 d	OVERHAUL		
SN:22071330112	HRS	8823		TAC 0						
WC#: 25.130	AFL	5651		TAC 0						
					PROC. REF: AMM 25-64-17-350-803					
25-64-17-350-803-01	RESTORATION NO. 5 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)									Service ATA:25
PN:P01074-201W	MOS	07-Sep-22	120	TAC 6	07-Mar-32		3049 d	OVERHAUL		
SN:22071330133	HRS	8823		TAC 0						
WC#: 25.140	AFL	5651		TAC 0						
					PROC. REF: AMM 25-64-17-350-803					
25-64-17-350-803-01	RESTORATION NO. 6 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)									Service ATA:25
PN:P01074-201W	MOS	07-Sep-22	120	TAC 6	07-Mar-32		3049 d	OVERHAUL		
SN:22071330128	HRS	8823		TAC 0						
WC#: 25.150	AFL	5651		TAC 0						
					PROC. REF: AMM 25-64-17-350-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
25-64-17-350-803-01		RESTORATION NO. 7 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								Service ATA:25
PN:P01074-201W	MOS	07-Sep-22	120	TAC 6	07-Mar-32		3049 d	OVERHAUL		
SN:22071330192	HRS	8823		TAC 0						
WC#: 25.160	AFL	5651		TAC 0						
					PROC. REF: AMM 25-64-17-350-803					
25-64-17-350-803-01		RESTORATION NO. 8 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								Service ATA:25
PN:P01074-201W	MOS	07-Sep-22	120	TAC 6	07-Mar-32		3049 d	OVERHAUL		
SN:22071330102	HRS	8823		TAC 0						
WC#: 25.170	AFL	5651		TAC 0						
					PROC. REF: AMM 25-64-17-350-803					
25-64-17-350-803-01		RESTORATION NO. 9 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								Service ATA:25
PN:P01074-201W	MOS	07-Sep-22	120	TAC 6	07-Mar-32		3049 d	OVERHAUL		
SN:22071330160	HRS	8823		TAC 0						
WC#: 25.180	AFL	5651		TAC 0						
					PROC. REF: AMM 25-64-17-350-803					
251121		PILOT SEAT BELT								Component ATA:25
PN:1101167-09	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 25.020	AFL	0								
					PROC. REF: GENERIC NO REF					
251126		COPILOT SEAT BELT								Component ATA:25
PN:1101166-13	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 25.020	AFL	0								
					PROC. REF: GENERIC NO REF					
251130		PILOT SHOULDER HARNESS								Component ATA:25
PN:2825A3X03	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 25.030	AFL	0								
					PROC. REF: GENERIC NO REF					
251135		COPILOT SHOULDER HARNESS								Component ATA:25
PN:2825A3X03	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 25.030	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
251141		PILOT HEATING CARPET								Component ATA:25
PN:592046	MOS/MSC	24-Oct-91	O/C							
SN:309	HRS	0		TSN 0						
WC#: 25.050	AFL	0								
					PROC. REF: GENERIC NO REF					
251146		COPILOT HEATING CARPET								Component ATA:25
PN:592045	MOS/MSC	24-Oct-91	O/C							
SN:306	HRS	0		TSN 0						
WC#: 25.050	AFL	0								
					PROC. REF: GENERIC NO REF					
251151		THIRD CREW MEMBER HEATING CARPET								Component ATA:25
PN:592044	MOS/MSC	24-Oct-91	O/C							
SN:319	HRS	0								
WC#: 25.050	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
253801[U]		COFFEE MAKER								Component ATA:25
PN:504-13-100	MOS/MSC	19-Jan-05	O/C	TSR 0						
SN:169	HRS	5407.1		TSR 0						
	AFL	3324		TSR 0						
256001		NO. 1 LIFE RAFT								Component ATA:25
PN:R1200-133	MOS/MSC	01-Jul-21	O/C	TSN 110, TSO 0						
SN:TAH4A002	HRS	8757		TSN 894.9, TSO 0						
WC#: 25.070	AFL	5621		TSN 527, TSO 0						
					PROC. REF: GENERIC NO REF					
256006		INSPECT/CHECK NO. 1 LIFE RAFT								Service ATA:25
PN:R1200-133	MOS	01-Jul-21	36		01-Jul-24		243 d			
SN:TAH4A002	HRS	8757								
WC#: 25.070	AFL	5621								
					PROC. REF: GENERIC NO REF					
256011		NO. 2 LIFE RAFT								Component ATA:25
PN:R1200-133	MOS/MSC	01-Jul-21	O/C	TSN 110, TSO 0						
SN:TAH4A003	HRS	8757		TSN 894.9, TSO 0						
WC#: 25.080	AFL	5621		TSN 527, TSO 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
256016		INSPECT/CHECK NO. 2 LIFE RAFT								Service ATA:25
PN:R1200-133	MOS	01-Jul-21	36		01-Jul-24		243 d			
SN:TAH4A003	HRS	8757								
WC#: 25.080	AFL	5621								
					PROC. REF: GENERIC NO REF					
256021		NO. 3 LIFE RAFT								Component ATA:25
PN:RAF1206-311T1	MOS/MSC	11-Oct-23	O/C	TSN 2						
SN:11230559591T2	HRS	8978.7		TSN 0						
WC#: 25.090	AFL	5790		TSN 0						
					PROC. REF: GENERIC NO REF					
256026		INSPECT/CHECK NO. 3 LIFE RAFT								Service ATA:25
PN:RAF1206-311T1	MOS	28-Aug-23	36		28-Aug-26		1031 d			
SN:11230559591T2	HRS									
WC#: 25.090	AFL									
					PROC. REF: GENERIC NO REF					
256031		NO. 1 PASSENGER LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	O/C	TSN 6						
SN:22071330356	HRS	8823		TSN 0						
WC#: 25.100	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
256041		NO. 2 PASSENGER LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	O/C	TSN 6						
SN:22071330185	HRS	8823		TSN 0						
WC#: 25.110	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
256051		NO. 3 PASSENGER LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	O/C	TSN 6						
SN:22071330210	HRS	8823		TSN 0						
WC#: 25.120	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
256061		NO. 4 PASSENGER LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	O/C	TSN 6						
SN:22071330112	HRS	8823		TSN 0						
WC#: 25.130	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
256071		NO. 5 PASSENGER LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	O/C	TSN 6						
SN:22071330133	HRS	8823		TSN 0						
WC#: 25.140	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
256081		NO. 6 PASSENGER LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	O/C	TSN 6						
SN:22071330128	HRS	8823		TSN 0						
WC#: 25.150	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
256091		NO. 7 PASSENGER LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	O/C	TSN 6						
SN:22071330192	HRS	8823		TSN 0						
WC#: 25.160	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
256101		NO. 8 PASSENGER LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	O/C	TSN 6						
SN:22071330102	HRS	8823		TSN 0						
WC#: 25.170	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
256111		NO. 9 PASSENGER LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	O/C	TSN 6						
SN:22071330160	HRS	8823		TSN 0						
WC#: 25.180	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
256121		PILOT LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	O/C	TSN 6						
SN:22071330346	HRS	8823		TSN 0						
WC#: 25.190	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
256131		COPILOT LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	O/C	TSN 6						
SN:22071330329	HRS	8823		TSN 0						
WC#: 25.190	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
256141		THIRD CREW MEMBER LIFE VEST								Component ATA:25
PN:P01074-201W	MOS/MSC	07-Sep-22	H/T	TSN 6						
SN:22071330164	HRS	8823		TSN 0						
	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
256849[U]		CDU,SECURITY SYSTEM								Component ATA:25
PN:IND3750-01	MOS/MSC	09-Apr-92	O/C							
SN:0131	HRS	26								
	AFL	13								
256870[U]		SECURITY S/S #1 MONITOR-								Component ATA:25
PN:BP-500-03	MOS/MSC	05-May-98	O/C							
SN:0049	HRS	2753								
	AFL	1927								
256883[U]		SECURITY SYST TRANSCEIVER								Component ATA:25
PN:RAD-02	MOS/MSC	09-Apr-92	O/C							
SN:0050	HRS	26								
	AFL	13								
ATA 26 - FIRE PROTECTION										
26-10-00-710-801-01		OPERATIONAL TEST OF THE FIRE DETECTION SYSTEM								Service ATA:26
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 26-10-00-710-801					
26-10-00-720-801-01		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 1 FIRE DETECTOR (L2W)								Service ATA:26
PN:30016190040013	MOS/MSC	11-Jun-08	E/C							
SN:84994	HRS	6744.9	5600		12344.9		3352.8			
WC#: 26.010	AFL	4197								
					PROC. REF: AMM 26-10-00-720-801					
26-10-00-720-801-01A		FUNCTIONAL TEST NO. 1 ENGINE FIRE DETECTOR (MANDATORY 5-40)								Service ATA:26
PN:30016190040013	MOS	11-Jun-08						MANDATORY 5-40		
SN:84994	HRS	6744.9	5600		12344.9		3352.8			
WC#: 26.010	AFL	4197								
					PROC. REF: AMM 26-10-00-720-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-10-00-720-801-02	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 2 FIRE DETECTOR (M2W)								Service	ATA:26
PN:3001619004001 3	MOS/MSC	11-Jun-08	E/C							
SN:85110	HRS	6698.5	5600		12298.5		3306.4			
WC#: 26.015	AFL	4197								
					PROC. REF: AMM 26-10-00-720-801					
26-10-00-720-801-02A	FUNCTIONAL TEST NO. 2 ENGINE FIRE DETECTOR (MANDATORY 5-40)								Service	ATA:26
PN:3001619004001 3	MOS	11-Jun-08						MANDATORY 5-40		
SN:85110	HRS	6698.5	5600		12298.5		3306.4			
WC#: 26.015	AFL	4197								
					PROC. REF: AMM 26-10-00-720-801					
26-10-00-720-801-03	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 3 FIRE DETECTOR (R2W)								Service	ATA:26
PN:3001619004001 3	MOS/MSC	15-Dec-11	E/C							
SN:69684	HRS	7712.7	5600		13312.7		4320.6			
WC#: 26.010	AFL	4979								
					PROC. REF: AMM 26-10-00-720-801					
26-10-00-720-801-03A	FUNCTIONAL TEST NO. 3 ENGINE FIRE DETECTOR (MANDATORY 5-40)								Service	ATA:26
PN:3001619004001 3	MOS	15-Dec-11						MANDATORY 5-40		
SN:69684	HRS	7712.7	5600		13312.7		4320.6			
WC#: 26.010	AFL	4979								
					PROC. REF: AMM 26-10-00-720-801					
26-10-00-720-801-04	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - APU FIRE DETECTOR (72W)								Service	ATA:26
PN:3001169004001 2	MOS	17-Dec-10								
SN:93044	HRS	7458.3	5600		13058.3		4066.2			
WC#: 26.050	AFL	4759								
					PROC. REF: AMM 26-10-00-720-801					
26-10-00-720-801-04A	FUNCTIONAL TEST APU FIRE DETECTOR (MANDATORY 5-40)								Service	ATA:26
PN:3001169004001 2	MOS	17-Dec-10						MANDATORY 5-40		
SN:93044	HRS	7458.3	5600		13058.3		4066.2			
WC#: 26.050	AFL	4759								
					PROC. REF: AMM 26-10-00-720-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-10-00-720-801-05	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - REAR COMPARTMENT FIRE DETECTOR (22W)									Service ATA:26
PN:3001198002703	MOS	03-Nov-03								
SN:70398	HRS	4936.4	5600		10536.4		1544.3			
WC#: 26.050	AFL	3064								
					PROC. REF: AMM 26-10-00-720-801					
26-10-00-720-801-05A	FUNCTIONAL TEST REAR COMPARTMENT FIRE DETECTOR (MANDATORY 5-40)									Service ATA:26
PN:3001198002703	MOS	03-Nov-03						MANDATORY 5-40		
SN:70398	HRS	4936.4	5600		10536.4		1544.3			
WC#: 26.050	AFL	3064								
					PROC. REF: AMM 26-10-00-720-801					
26-10-00-720-801-06	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - LH MLG BAY FIRE DETECTOR (29W1)									Service ATA:26
PN:30015160027012	MOS	03-Nov-03								
SN:70377	HRS	4936.4	5600		10536.4		1544.3			
WC#: 26.050	AFL	3064								
					PROC. REF: AMM 26-10-00-720-801					
26-10-00-720-801-06A	FUNCTIONAL TEST LH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR (MANDATORY 5-40)									Service ATA:26
PN:30015160027012	MOS	03-Nov-03						MANDATORY 5-40		
SN:70377	HRS	4936.4	5600		10536.4		1544.3			
WC#: 26.050	AFL	3064								
					PROC. REF: AMM 26-10-00-720-801					
26-10-00-720-801-07	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - RH MLG BAY FIRE DETECTOR (29W2)									Service ATA:26
PN:3001198002703	MOS	03-Nov-03								
SN:70399	HRS	4936.4	5600		10536.4		1544.3			
WC#: 26.050	AFL	3064								
					PROC. REF: AMM 26-10-00-720-801					
26-10-00-720-801-07A	FUNCTIONAL TEST RH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR (MANDATORY 5-40)									Service ATA:26
PN:3001198002703	MOS	03-Nov-03						MANDATORY 5-40		
SN:70399	HRS	4936.4	5600		10536.4		1544.3			
WC#: 26.050	AFL	3064								
					PROC. REF: AMM 26-10-00-720-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-10-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE PNEUMATIC FIRE DETECTORS - ENGINE 1 FIRE DETECTOR (L2W)								Component	ATA:26
PN:3001619004001 3	MOS/MSC	16-Dec-04	O/C	TSN 0						
SN:84994	HRS	5382.2		TSN 0						
WC#: 26.010	AFL	3315		TSN 0						
					PROC. REF: AMM 26-10-01-900-801, AMM 26-10-01-900-801					
26-10-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE PNEUMATIC FIRE DETECTORS - ENGINE 2 FIRE DETECTOR (M2W)								Component	ATA:26
PN:3001619004001 3	MOS/MSC	17-Dec-04	O/C	TSN 0						
SN:85110	HRS	5382.2		TSN 0						
WC#: 26.015	AFL	3315		TSN 0						
					PROC. REF: AMM 26-10-01-900-801, AMM 26-10-01-900-801					
26-10-01-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE PNEUMATIC FIRE DETECTORS - ENGINE 3 FIRE DETECTOR (R2W)								Component	ATA:26
PN:3001619004001 3	MOS/MSC	24-Oct-91	O/C							
SN:69684	HRS	0		TSN 0						
WC#: 26.010	AFL	0								
					PROC. REF: AMM 26-10-01-900-801, AMM 26-10-01-900-801					
26-10-21-710-801-01	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT SMOKE DETECTOR - SMOKE DETECTOR (27W)								Service	ATA:26
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 26-10-21-710-801					
26-10-21-900-801-01	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT SMOKE DETECTOR AND LAMP / LED REPLACEMENT - SMOKE DETECTOR (27W)								Component	ATA:26
PN:FR2210-2	MOS/MSC	24-Oct-91	O/C							
SN:433	HRS	0		TSN 0						
WC#: 26.030	AFL	0								
					PROC. REF: AMM 26-10-21-900-801					
26-10-21-900-801-02	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT SMOKE DETECTOR AND LAMP / LED REPLACEMENT - SMOKE DETECTOR LAMP/LED (27W1)								Component	ATA:26
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 26-10-21-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-01-760-801-01[S]	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 1" SELECTOR SWITCH (POSITION "1")								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 26-20-01-760-801					PKG:31
26-20-01-760-801-02[S]	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 1" SELECTOR SWITCH (POSITION "2")								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 26-20-01-760-801					PKG:31
26-20-01-760-801-03[S]	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 2" SELECTOR SWITCH (POSITION "1")								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 26-20-01-760-801					PKG:31
26-20-01-760-801-04[S]	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 2" SELECTOR SWITCH (POSITION "2")								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 26-20-01-760-801					PKG:31
26-20-01-760-801-05[S]	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 3" SELECTOR SWITCH (POSITION "1")								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 26-20-01-760-801					PKG:31
26-20-01-760-801-06[S]	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 3" SELECTOR SWITCH (POSITION "2")								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 26-20-01-760-801					PKG:31
26-20-01-760-801-07[S]	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "FIRE APU" SELECTOR SWITCH								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 26.170	AFL	5651								
					PROC. REF: AMM 26-20-01-760-801					PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-01-760-801-08[S]	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "FIRE BAG COMP" SELECTOR SWITCH								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 26.220	AFL	5651								
					PROC. REF: AMM 26-20-01-760-801					PKG:31
26-20-01-760-801-09[S]	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "FIRE AFT COMP" SELECTOR SWITCH								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 26.190	AFL	5651								
					PROC. REF: AMM 26-20-01-760-801					PKG:31
26-20-01-900-801-01	REMOVAL / INSTALLATION OF THE FIRE CONTROL PANEL - FIRE CONTROL PANEL (13W)								Component	ATA:26
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 26-20-01-900-801, AMM 26-20-01-900-801					
26-20-09-220-801-01	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (14W1)								Service	ATA:26
PN:860640	MOS	05-Sep-23	12		05-Sep-24		309 d			
SN:50567	HRS									
WC#: 26.060	AFL									
					PROC. REF: AMM 26-20-09-220-801					
26-20-09-220-801-02	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (14W2)								Service	ATA:26
PN:860640	MOS	05-Sep-23	12		05-Sep-24		309 d			
SN:54588	HRS									
WC#: 26.070	AFL									
					PROC. REF: AMM 26-20-09-220-801					
26-20-09-220-801-03	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (14W3)								Service	ATA:26
PN:860640	MOS	05-Sep-23	12		05-Sep-24		309 d			
SN:897	HRS									
WC#: 26.080	AFL									
					PROC. REF: AMM 26-20-09-220-801					
26-20-09-220-801-04	WEIGHING OF THE FIRE EXTINGUISHERS - APU FIRE EXTINGUISHER (73W)								Service	ATA:26
PN:30111102	MOS	05-Sep-23	12		05-Sep-24		309 d			
SN:05175A1	HRS									
WC#: 26.090	AFL									
					PROC. REF: AMM 26-20-09-220-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-09-220-801-05		WEIGHING OF THE FIRE EXTINGUISHERS - REAR COMPARTMENT FIRE EXTINGUISHER (23W1)							Service	ATA:26
PN:30702102-1	MOS	05-Sep-23	12		05-Sep-24		309 d			
SN:06307D2	HRS									
WC#: 26.210	AFL									
					PROC. REF: AMM 26-20-09-220-801					
26-20-09-220-801-06		WEIGHING OF THE FIRE EXTINGUISHERS - REAR/BAGGAGE COMPARTMENT FIRE EXTINGUISHER (23W2)							Service	ATA:26
PN:30702102-1	MOS	05-Sep-23	12		05-Sep-24		309 d			
SN:07421D1	HRS									
WC#: 26.180	AFL									
					PROC. REF: AMM 26-20-09-220-801					
26-20-09-350-801-01		RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (14W1)							Service	ATA:26
PN:860640	MOS	01-Mar-22	60		01-Mar-27		1216 d			
SN:50567	HRS									
	AFL									
					PROC. REF: AMM 26-20-09-350-801					
26-20-09-350-801-02		RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (14W2)							Service	ATA:26
PN:860640	MOS	01-Mar-22	60		01-Mar-27		1216 d			
SN:54588	HRS									
	AFL									
					PROC. REF: AMM 26-20-09-350-801					
26-20-09-350-801-03		RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (14W3)							Service	ATA:26
PN:860640	MOS	01-Aug-22	60		01-Aug-27		1369 d			
SN:897	HRS									
	AFL									
					PROC. REF: AMM 26-20-09-350-801					
26-20-09-350-801-04		RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - APU FIRE EXTINGUISHER (73W)							Service	ATA:26
PN:30111102	MOS	03-Dec-20	60		03-Dec-25		763 d	MANDATORY		
SN:05175A1	HRS									
WC#: 26.090	AFL									
					PROC. REF: AMM 26-20-09-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-09-350-801-05	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - REAR COMPARTMENT FIRE EXTINGUISHER (23W1)								Service	ATA:26
PN:30702102-1	MOS	15-Nov-19	60		15-Nov-24		380 d	MANDATORY		
SN:06307D2	HRS									
WC#: 26.210	AFL									
					PROC. REF: AMM 26-20-09-350-801					
26-20-09-350-801-06	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - REAR/BAGGAGE COMPARTMENT FIRE EXTINGUISHER (23W2)								Service	ATA:26
PN:30702102-1	MOS	15-Nov-19	60		15-Nov-24		380 d	MANDATORY		
SN:07421D1	HRS									
WC#: 26.180	AFL									
					PROC. REF: AMM 26-20-09-350-801					
26-20-09-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHERS - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (14W1)								Component	ATA:26
PN:860640	MOS/MSC	07-Sep-22	O/C	TSO 6						
SN:50567	HRS	8823		TSO 0						
WC#: 26.060	AFL	5651		TSO 0						
					PROC. REF: AMM 26-20-09-900-801					
26-20-09-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (14W2)								Component	ATA:26
PN:860640	MOS/MSC	07-Sep-22	O/C	TSO 6						
SN:54588	HRS	8823		TSO 0						
WC#: 26.070	AFL	5651		TSO 0						
					PROC. REF: AMM 26-20-09-900-801					
26-20-09-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHERS - ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (14W3)								Component	ATA:26
PN:860640	MOS/MSC	07-Sep-22	O/C	TSO 1						
SN:897	HRS	8823		TSO 0						
WC#: 26.080	AFL	5651		TSO 0						
					PROC. REF: AMM 26-20-09-900-801					
26-20-09-900-802-01	REMOVAL / INSTALLATION OF THE APU FIRE EXTINGUISHER - APU FIRE EXTINGUISHER (73W)								Component	ATA:26
PN:30111102	MOS/MSC	27-May-21	O/C	TSO 5						
SN:05175A1	HRS	8754.4		TSO 34.4						
WC#: 26.090	AFL	5620		TSO 14						
					PROC. REF: AMM 26-20-09-900-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-09-900-803-01	REMOVAL / INSTALLATION OF THE REAR / BAGGAGE COMPARTMENT (23W2) FIRE EXTINGUISHER - REAR/BAGGAGE COMPARTMENT FIRE EXTINGUISHER (23W2)								Component	ATA:26
PN:30702102-1	MOS/MSC	27-May-21	O/C	TSO 78						
SN:07421D1	HRS	8754.4		TSO 611						
WC#: 26.180	AFL	5620		TSO 347						
					PROC. REF: AMM 26-20-09-900-803					
26-20-09-900-804-01	REMOVAL / INSTALLATION OF THE REAR COMPARTMENT FIRE EXTINGUISHER - REAR COMPARTMENT FIRE EXTINGUISHER (23W1)								Component	ATA:26
PN:30702102-1	MOS/MSC	27-May-21	O/C	TSO 17						
SN:06307D2	HRS	8754.4		TSO 78						
WC#: 26.210	AFL	5620		TSO 38						
					PROC. REF: AMM 26-20-09-900-804					
26-20-11-700-801-01 S	CHECKING EXTINGUISHING LINES FOR CLOGGING - APU FIRE EXTINGUISHER (73W)								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 26.160	AFL	5651								
					PROC. REF: AMM 26-20-11-700-801					PKG:31
26-20-11-700-801-02 S	CHECKING EXTINGUISHING LINES FOR CLOGGING - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (14W1)								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 26.100	AFL	5651								
					PROC. REF: AMM 26-20-11-700-801					PKG:31
26-20-11-700-801-03 S	CHECKING EXTINGUISHING LINES FOR CLOGGING - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (14W2)								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 26.110	AFL	5651								
					PROC. REF: AMM 26-20-11-700-801					PKG:31
26-20-11-700-801-04 S	CHECKING EXTINGUISHING LINES FOR CLOGGING - ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (14W3)								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 26.120	AFL	5651								
					PROC. REF: AMM 26-20-11-700-801					PKG:31
26-20-11-700-801-05 S	CHECKING EXTINGUISHING LINES FOR CLOGGING - REAR/BAGGAGE COMPARTMENT FIRE EXTINGUISHER (23W2)								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 26.200	AFL	5651								
					PROC. REF: AMM 26-20-11-700-801					PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-11-700-801-06[S]	CHECKING EXTINGUISHING LINES FOR CLOGGING - REAR COMPARTMENT FIRE EXTINGUISHER (23W1)								Service	ATA:26
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 26.230	AFL	5651								
					PROC. REF: AMM 26-20-11-700-801					PKG:31
26-20-11-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER NOZZLES								Component	ATA:26
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 26-20-11-900-801					
26-20-13-760-801-01	INSULATION TEST OF THE ENGINE 1/2 FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (14W1)								Service	ATA:26
PN:860640	MOS/MSC	08-Sep-23	O/C							
SN:50567	HRS	8967								
WC#: 26.060	AFL	5775								
					PROC. REF: AMM 26-20-13-760-801					
26-20-13-760-802-01	INSULATION TEST OF THE ENGINE 2/3 FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (14W2)								Service	ATA:26
PN:860640	MOS/MSC	08-Sep-23	O/C							
SN:54588	HRS	8967								
WC#: 26.070	AFL	5775								
					PROC. REF: AMM 26-20-13-760-802					
26-20-13-760-803-01	INSULATION TEST OF THE ENGINE 3/1 FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (14W3)								Service	ATA:26
PN:860640	MOS/MSC	08-Sep-23	O/C							
SN:897	HRS	8967								
WC#: 26.080	AFL	5775								
					PROC. REF: AMM 26-20-13-760-803					
26-20-13-760-804-01	INSULATION TEST OF THE APU FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - APU FIRE EXTINGUISHER (73W)								Service	ATA:26
PN:30111102	MOS/MSC	08-Sep-23	O/C							
SN:05175A1	HRS	8967								
WC#: 26.090	AFL	5775								
					PROC. REF: AMM 26-20-13-760-804					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-13-760-805-01	INSULATION TEST OF THE REAR / BAGGAGE COMPARTMENT (23W2) FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - REAR/BAGGAGE COMPARTMENT FIRE EXTINGUISHER (23W2)								Service	ATA:26
PN:30702102-1	MOS/MSC	08-Sep-23	O/C							
SN:07421D1	HRS	8967								
WC#: 26.180	AFL	5775								
					PROC. REF: AMM 26-20-13-760-805					
26-20-13-760-806-01	INSULATION TEST OF THE REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - REAR COMPARTMENT FIRE EXTINGUISHER (23W1)								Service	ATA:26
PN:30702102-1	MOS/MSC	27-May-21	O/C							
SN:06307D2	HRS	8754.4								
WC#: 26.210	AFL	5620								
					PROC. REF: AMM 26-20-13-760-806					
26-20-13-900-802-01	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L14W)								Component	ATA:26
PN:M861385	MOS/MSC	31-Dec-19	H/T	TSN 0						
SN:01031	HRS	8676.4		TSN 0						
	AFL	5582		TSN 0						
					PROC. REF: AMM 26-20-13-900-802					
26-20-13-900-802-02	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT PERCUSSION CARTRIDGE (M14W)								Component	ATA:26
PN:861375	MOS/MSC	31-Dec-20	H/T							
SN:UNKNOWN	HRS	8720								
	AFL	5606								
					PROC. REF: AMM 26-20-13-900-802					
26-20-13-900-802-03	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 FIRST-SHOOT PERCUSSION CARTRIDGE (R14W)								Component	ATA:26
PN:86137	MOS/MSC	07-Sep-22	H/T	TSN 4						
SN:NA	HRS	8823		TSN 0						
	AFL	5651		TSN 0						
					PROC. REF: AMM 26-20-13-900-802					
26-20-13-900-802-04	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (L15W)								Component	ATA:26
PN:861385	MOS/MSC	07-Sep-22	H/T	TSN 3						
SN:NA	HRS	8823		TSN 0						
	AFL	5651		TSN 0						
					PROC. REF: AMM 26-20-13-900-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-13-900-802-05	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT PERCUSSION CARTRIDGE (M15W)								Component	ATA:26
PN:M861375	MOS/MSC	07-Sep-22	H/T	TSN 10						
SN:01710	HRS	8823		TSN 0						
	AFL	5651		TSN 0						
					PROC. REF: AMM 26-20-13-900-802					
26-20-13-900-802-06	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R15W)								Component	ATA:26
PN:861385	MOS/MSC	07-Sep-22	H/T	TSN 3						
SN:NA	HRS	8823		TSN 0						
	AFL	5651		TSN 0						
					PROC. REF: AMM 26-20-13-900-802					
26-20-13-900-805-01	REMOVAL / INSTALLATION OF THE APU FIRE EXTINGUISHER PERCUSSION CARTRIDGE - APU PERCUSSION CARTRIDGE (28W)								Component	ATA:26
PN:M13083-5	MOS/MSC	07-Sep-22	H/T	TSN 5						
SN:47276	HRS	8823		TSN 0						
	AFL	5651		TSN 0						
					PROC. REF: AMM 26-20-13-900-805					
26-20-13-900-806-01	REMOVAL / INSTALLATION OF THE RH REAR COMPARTMENT AND BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION CARTRIDGES - RH REAR COMPARTMENT PERCUSSION CARTRIDGE (24W)								Component	ATA:26
PN:M13083-5	MOS/MSC	07-Sep-22	H/T	TSN 5						
SN:47275	HRS	8823		TSN 0						
	AFL	5651		TSN 0						
					PROC. REF: AMM 26-20-13-900-806					
26-20-13-900-806-02	REMOVAL / INSTALLATION OF THE RH REAR COMPARTMENT AND BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION CARTRIDGES - BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (23W)								Component	ATA:26
PN:M13083-5	MOS/MSC	07-Sep-22	H/T	TSN 5						
SN:47199	HRS	8823		TSN 0						
	AFL	5651		TSN 0						
					PROC. REF: AMM 26-20-13-900-806					
26-20-13-900-807-01	REMOVAL / INSTALLATION OF THE LH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION CARTRIDGE - LH REAR COMPARTMENT PERCUSSION CARTRIDGE (25W)								Component	ATA:26
PN:M13083-5	MOS/MSC	01-May-18	H/T	TSN 0						
SN:38898	HRS	8515.3		TSN 0						
	AFL	5480		TSN 0						
					PROC. REF: AMM 26-20-13-900-807					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-13-960-801-01	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L14W)								Service	ATA:26
PN:M861385	MOS	31-Dec-19	144		31-Dec-31		2982 d	SCRAP		
SN:01031	HRS									
WC#: 26.060	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-01M	DISCARD ENGINE 1 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (L14W) CARTRIDGE (LIFE LIMIT)								Service	ATA:26
PN:M861385	MOS	01-Nov-18	180		01-Nov-33		3653 d	LIFE LIMIT		
SN:01031	HRS									
WC#: 26.060	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-02	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT PERCUSSION CARTRIDGE (M14W)								Service	ATA:26
PN:861375	MOS	31-Dec-20	60		31-Dec-25		791 d	SCRAP		
SN:UNKNOWN	HRS	8720								
WC#: 26.070	AFL	5606								
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-02M	DISCARD ENGINE 2 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (M14W) CARTRIDGE (LIFE LIMIT)								Service	ATA:26
PN:861375	MOS	31-Aug-17	84		31-Aug-24		304 d	LIFE LIMIT		
SN:UNKNOWN	HRS									
WC#: 26.070	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-03	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 FIRST-SHOOT PERCUSSION CARTRIDGE (R14W)								Service	ATA:26
PN:86137	MOS	07-Sep-22	144		30-Sep-34		3986 d	SERVICE LIFE LIMIT		
SN:NA	HRS									
WC#: 26.080	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-03M	DISCARD ENGINE 3 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (R14W) CARTRIDGE (LIFE LIMIT)								Service	ATA:26
PN:86137	MOS	01-May-22	180		31-May-37		4960 d	LIFE LIMIT		
SN:NA	HRS									
WC#: 26.080	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-04	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (L15W)								Service	ATA:26
PN:861385	MOS	07-Sep-22	144		07-Sep-34		3963 d	SCRAP		
SN:NA	HRS									
WC#: 26.080	AFL									
					PROC. REF: AMM 26-20-13-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-13-960-801-04M	DISCARD ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (L15W) CARTRIDGE (LIFE LIMIT)									Service ATA:26
PN:861385	MOS	01-Jun-22	180		30-Jun-37		4990 d	LIFE LIMIT		
SN:NA	HRS									
WC#: 26.080	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-05	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT PERCUSSION CARTRIDGE (M15W)									Service ATA:26
PN:M861375	MOS	07-Sep-22	144		30-Sep-34		3986 d	SERVICE LIFE LIMIT		
SN:01710	HRS									
WC#: 26.060	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-05M	DISCARD ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (M15W) CARTRIDGE (LIFE LIMIT)									Service ATA:26
PN:M861375	MOS	01-Nov-21	84		01-Nov-28		1827 d	LIFE LIMIT		
SN:01710	HRS									
WC#: 26.060	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-06	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R15W)									Service ATA:26
PN:861385	MOS	07-Sep-22	60		07-Sep-27		1406 d	SCRAP		
SN:NA	HRS									
WC#: 26.070	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-06M	DISCARD ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (R15W) CARTRIDGE (LIFE LIMIT)									Service ATA:26
PN:861385	MOS	01-Jun-22	84		01-Jun-29		2039 d	LIFE LIMIT		
SN:NA	HRS									
WC#: 26.070	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-07	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (23W)									Service ATA:26
PN:M13083-5	MOS	07-Sep-22	72		07-Sep-28		1772 d	SCRAP		
SN:47199	HRS									
WC#: 26.180	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-07M	DISCARD BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION (23W) CARTRIDGE (LIFE LIMIT)									Service ATA:26
PN:M13083-5	MOS	01-Apr-22	108		01-Apr-31		2708 d	LIFE LIMIT		
SN:47199	HRS									
WC#: 26.180	AFL									
					PROC. REF: AMM 26-20-13-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-13-960-801-08	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - RH REAR COMPARTMENT PERCUSSION CARTRIDGE (24W)								Service	ATA:26
PN:M13083-5	MOS	07-Sep-22	72		07-Sep-28		1772 d	SCRAP		
SN:47275	HRS									
WC#: 26.180	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-08M	DISCARD RH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION (24W) CARTRIDGE (LIFE LIMIT)								Service	ATA:26
PN:M13083-5	MOS	01-Apr-22	108		01-Apr-31		2708 d	LIFE LIMIT		
SN:47275	HRS									
WC#: 26.180	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-09	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - LH REAR COMPARTMENT PERCUSSION CARTRIDGE (25W)								Service	ATA:26
PN:M13083-5	MOS	01-May-18	72		01-May-24		182 d	SCRAP		
SN:38898	HRS									
WC#: 26.210	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-09M	DISCARD LH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION (25W) CARTRIDGE (LIFE LIMIT)								Service	ATA:26
PN:M13083-5	MOS	19-Feb-18	108		19-Feb-27		1206 d	LIFE LIMIT		
SN:38898	HRS									
WC#: 26.210	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-10	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - APU PERCUSSION CARTRIDGE (28W)								Service	ATA:26
PN:M13083-5	MOS/MSC	07-Sep-22	N/A							
SN:47276	HRS	8823								
WC#: 26.090	AFL	5651								
					PROC. REF: AMM 26-20-13-960-801					
26-20-13-960-801-10M	DISCARD APU FIRE EXTINGUISHER PERCUSSION (28W) CARTRIDGE (LIFE LIMIT)								Service	ATA:26
PN:M13083-5	MOS	01-Apr-22	120		01-Apr-32		3074 d	LIFE LIMIT		
SN:47276	HRS									
WC#: 26.090	AFL									
					PROC. REF: AMM 26-20-13-960-801					
26-20-15-350-802-02	RESTORATION OF THE PORTABLE EXTINGUISHERS (OVERHAUL) - CABIN PORTABLE FIRE EXTINGUISHER (501WB)								Service	ATA:26
PN:C352	MOS/MSC		O/C							
SN:H-00624889	HRS									
	AFL									
					PROC. REF: AMM 26-20-15-350-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-15-350-802-03	RESTORATION OF THE PORTABLE EXTINGUISHERS (OVERHAUL) - SECOND CABIN PORTABLE FIRE EXTINGUISHER (502WB)								Service	ATA:26
PN:A384	MOS/MSC		O/C							
SN:H-20653179	HRS									
	AFL									
					PROC. REF: AMM 26-20-15-350-802					
26-20-15-720-801-01	WEIGHING COCKPIT PORTABLE FIRE EXTINGUISHER								Service	ATA:26
PN:C352	MOS	05-Sep-23	12		05-Sep-24		309 d			
SN:H-00624904	HRS									
	AFL									
					PROC. REF: AMM 26-20-15-720-801, AMM 26-20-15-720-801					
26-20-15-720-801-02	WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN PORTABLE FIRE EXTINGUISHER (501WB)								Service	ATA:26
PN:C352	MOS	05-Sep-23	12		05-Sep-24		309 d			
SN:H-00624889	HRS									
	AFL									
					PROC. REF: AMM 26-20-15-720-801, AMM 26-20-15-720-801					
26-20-15-720-801-03	WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - SECOND CABIN PORTABLE FIRE EXTINGUISHER (502WB)								Service	ATA:26
PN:A384	MOS	08-Sep-23	12		08-Sep-24		312 d			
SN:H-20653179	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 26-20-15-720-801, AMM 26-20-15-720-801					
26-20-15-790-801-01	HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)								Service	ATA:26
PN:C352	MOS	31-Dec-21	144 (+3%)		31-Dec-33	09-May-34	3713 d (+129)			
SN:H-00624904	HRS									
	AFL									
					PROC. REF: AMM 26-20-15-790-801					
26-20-15-790-801-02	HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN PORTABLE FIRE EXTINGUISHER (501WB)								Service	ATA:26
PN:C352	MOS	31-Dec-21	144 (+3%)		31-Dec-33	09-May-34	3713 d (+129)			
SN:H-00624889	HRS									
	AFL									
					PROC. REF: AMM 26-20-15-790-801					
26-20-15-790-801-03	HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - SECOND CABIN PORTABLE FIRE EXTINGUISHER (502WB)								Service	ATA:26
PN:A384	MOS/MSC	07-Sep-22	N/A		01-Dec-34 (M)		4048 d			
SN:H-20653179	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 26-20-15-790-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
26-20-15-900-801-01		COCKPIT PORTABLE FIRE EXTINGUISHER								Component ATA:26
PN:C352	MOS/MSC	07-Sep-22	O/C	TSN 9						
SN:H-00624904	HRS	8823		TSN 0						
	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
26-20-15-900-801-02		NO. 1 CABIN PORTABLE FIRE EXTINGUISHER								Component ATA:26
PN:C352	MOS/MSC	07-Sep-22	O/C	TSN 9						
SN:H-00624889	HRS	8823		TSN 0						
	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
26-20-15-900-801-03		NO. 2 CABIN PORTABLE FIRE EXTINGUISHER								Component ATA:26
PN:A384	MOS/MSC	07-Sep-22	O/C	TSN 0						
SN:H-20653179	HRS	8823		TSN 0						
	AFL	5651		TSN 0						
					PROC. REF: GENERIC NO REF					
261155		LH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR								Component ATA:26
PN:3001516002701 2	MOS/MSC	24-Oct-91	O/C							
SN:70377	HRS	0		TSN 0						
WC#: 26.020	AFL	0								
					PROC. REF: GENERIC NO REF					
261160		RH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR								Component ATA:26
PN:300119800270- 3	MOS/MSC	24-Oct-91	O/C							
SN:70399	HRS	0		TSN 0						
WC#: 26.020	AFL	0								
					PROC. REF: GENERIC NO REF					
261165		APU FIRE DETECTOR								Component ATA:26
PN:3001169004001 2	MOS/MSC	15-Dec-10	O/C	TSN 0						
SN:93044	HRS	7458.3		TSN 0						
WC#: 26.040	AFL	4759		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
261170		REAR COMPARTMENT FIRE DETECTOR								Component ATA:26
PN:300119800270-3	MOS/MSC	24-Oct-91	O/C							
SN:70398	HRS	0		TSN 0						
WC#: 26.030	AFL	0								
					PROC. REF: GENERIC NO REF					
261801		FIRE DETECTION PANEL								Component ATA:26
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 26.270	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
262186		NO. 1 ENGINE DUAL CHECK VALVE								Component ATA:26
PN:860655	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 26.260	AFL	0								
					PROC. REF: GENERIC NO REF					
262196		NO. 2 ENGINE DUAL CHECK VALVE								Component ATA:26
PN:860655	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 26.260	AFL	0								
					PROC. REF: GENERIC NO REF					
262206		NO. 3 ENGINE DUAL CHECK VALVE								Component ATA:26
PN:860655	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 26.260	AFL	0								
					PROC. REF: GENERIC NO REF					
ATA 27 - FLIGHT CONTROLS										
27-00-00-640-803-01[S]		PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA - ROLL								Service ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.050	AFL	5347								
					PROC. REF: AMM 27-00-00-640-803					PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-00-00-640-803-02[S]	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA - YAW								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.050	AFL	5347								
					PROC. REF: AMM 27-00-00-640-803					PKG:32
27-00-00-640-803-03[S]	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA - PITCH								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.050	AFL	5347								
					PROC. REF: AMM 27-00-00-640-803					PKG:32
27-00-00-640-804-01[S]	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA - ROLL								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.040	AFL	5347								
					PROC. REF: AMM 27-00-00-640-804					PKG:32
27-00-00-640-804-02[S]	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA - YAW								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.040	AFL	5347								
					PROC. REF: AMM 27-00-00-640-804					PKG:32
27-00-00-640-804-03[S]	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA - PITCH								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.040	AFL	5347								
					PROC. REF: AMM 27-00-00-640-804					PKG:32
27-00-00-640-806-01[S]	VISUAL INSPECTION AND GREASING OF YAW AND PITCH CONTROL SEALED BOXES								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
	AFL	5347								
					PROC. REF: AMM 27-00-00-640-806					PKG:32
27-00-00-710-801-01[S]	OPERATIONAL TEST OF THE FLIGHT CONTROLS - HYDRAULIC SYSTEM 1								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 27-00-00-710-801					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-00-00-710-801-02[S]	OPERATIONAL TEST OF THE FLIGHT CONTROLS - HYDRAULIC SYSTEM 2									Service ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 27-00-00-710-801					PKG:21
27-00-00-710-802-01[S]	OPERATIONAL TEST OF THE TRIM SYSTEMS - ROLL									Service ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.200	AFL	5651								
					PROC. REF: AMM 27-00-00-710-802					PKG:31
27-00-00-710-802-02[S]	OPERATIONAL TEST OF THE TRIM SYSTEMS - YAW									Service ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.200	AFL	5651								
					PROC. REF: AMM 27-00-00-710-802					PKG:31
27-00-00-720-803-01[S]	FUNCTIONAL TEST OF ROLL AND PITCH AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - LH ROLL AAFU (L960CC)									Service ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-00-00-720-803					PKG:31
27-00-00-720-803-02[S]	FUNCTIONAL TEST OF ROLL AND PITCH AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - RH ROLL AAFU (R960CC)									Service ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-00-00-720-803					PKG:31
27-00-00-720-803-03[S]	FUNCTIONAL TEST OF ROLL AND PITCH AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - PITCH AAFU (924CW)									Service ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.190	AFL	5651								
					PROC. REF: AMM 27-00-00-720-803					PKG:31
27-00-00-720-806-01	BRIEF CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - ROLL									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-720-806					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-00-00-720-806-02	BRIEF CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - YAW									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 27.600	AFL	0								
					PROC. REF: AMM 27-00-00-720-806					
27-00-00-720-806-03	BRIEF CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - PITCH									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 27.600	AFL	0								
					PROC. REF: AMM 27-00-00-720-806					
27-00-00-790-801-01	LEAK CHECK OF THE FLIGHT CONTROL HYDRAULIC COMPONENTS									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-790-801					
27-00-00-820-801-01	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - FLAP POSITION MICROSWITCH (4C)									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-02	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - LH INBOARD AIRBRAKE POSITION MICROSWITCH (23C1)									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-03	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - RH INBOARD AIRBRAKE POSITION MICROSWITCH (23C2)									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-00-00-820-801-04	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - LH CENTER AIRBRAKE POSITION MICROSWITCH (24C1)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-05	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - RH CENTER AIRBRAKE POSITION MICROSWITCH (24C2)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-06	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - LH OUTBOARD AIRBRAKE POSITION MICROSWITCH (25C1)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-07	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - RH OUTBOARD AIRBRAKE POSITION MICROSWITCH (25C2)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-08	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - LH INBOARD SLAT RETRACTED MICROSWITCH (53D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-09	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - RH INBOARD SLAT RETRACTED MICROSWITCH (54D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-00-00-820-801-10	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - LH OUTBOARD SLAT RETRACTED MICROSWITCH (55D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-11	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - RH OUTBOARD SLAT RETRACTED MICROSWITCH (56D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-12	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - LH INBOARD SLAT EXTENDED MICROSWITCH (57D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-13	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - RH INBOARD SLAT EXTENDED MICROSWITCH (58D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-14	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - LH OUTBOARD SLAT EXTENDED MICROSWITCH (59D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					
27-00-00-820-801-15	ADJUSTMENT OF THE SLAT, FLAP AND AIRBRAKE INDICATING MICROSWITCHES - RH OUTBOARD SLAT EXTENDED MICROSWITCH (60D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-00-00-820-802-01	ADJUSTMENT OF THE MONITORING CIRCUITS OF THE ARTHUR VARIABLE BELLCRANKS (ROLL AND PITCH) - ROLL ARTHUR VARIABLE BELLCRANK (43C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-802					
27-00-00-820-802-02	ADJUSTMENT OF THE MONITORING CIRCUITS OF THE ARTHUR VARIABLE BELLCRANKS (ROLL AND PITCH) - PITCH ARTHUR VARIABLE BELLCRANK (42C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-820-802					
27-00-00-900-806-01	REMOVAL / INSTALLATION OF THE AIRBRAKE / TAILPLANE / TRIM CONTROL BOX - AIRBRAKE/TAILPLANE/TRIM CONTROL BOX (53C)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-00-00-900-806					
27-00-00-910-801-01	FLIGHT CONTROL SYSTEM MAINTENANCE AND SAFETY PRECAUTIONS								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-801					
27-00-00-910-802-01	PRECAUTIONS TO BE TAKEN WHEN REPLACING FLIGHT CONTROL SYSTEM COMPONENTS								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-802					
27-00-00-910-803-01	SETTING THE FLIGHT CONTROL TRIMS TO THE NEUTRAL POSITION - ROLL TRIM ACTUATOR (112C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-803					
27-00-00-910-803-02	SETTING THE FLIGHT CONTROL TRIMS TO THE NEUTRAL POSITION - ROLL EMERGENCY TRIM ACTUATOR (103C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-00-00-910-803-03	SETTING THE FLIGHT CONTROL TRIMS TO THE NEUTRAL POSITION - YAW TRIM ACTUATOR (92C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-803					
27-00-00-910-803-04	SETTING THE FLIGHT CONTROL TRIMS TO THE NEUTRAL POSITION - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (54C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-803					
27-00-00-910-804-01	USE OF THE FLIGHT CONTROL SURFACE DEFLECTION MEASURING FIXTURES - AILERON								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-804					
27-00-00-910-804-02	USE OF THE FLIGHT CONTROL SURFACE DEFLECTION MEASURING FIXTURES - RUDDER								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-804					
27-00-00-910-804-03	USE OF THE FLIGHT CONTROL SURFACE DEFLECTION MEASURING FIXTURES - ELEVATOR								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-804					
27-00-00-910-804-04	USE OF THE FLIGHT CONTROL SURFACE DEFLECTION MEASURING FIXTURES - HORIZONTAL STABILIZER								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-804					
27-00-00-910-805-01	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL RIGGING PINS - ROLL CONTROL LINKAGE								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-805					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-00-00-910-805-02	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL RIGGING PINS - YAW CONTROL LINKAGE									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-805					
27-00-00-910-805-03	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL RIGGING PINS - PITCH CONTROL LINKAGE									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-805					
27-00-00-910-806-01	FLIGHT CONTROL RODS: ACCEPTANCE CRITERIA									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-910-806					
27-00-00-960-802-01	REPLACEMENT OF THE SEALS ON THE SWIVEL COUPLINGS OF THE ROLL AND PITCH ARTHUR VARIABLE BELLCRANKS - ROLL ARTHUR VARIABLE BELLCRANK (43C)									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-960-802					
27-00-00-960-802-02	REPLACEMENT OF THE SEALS ON THE SWIVEL COUPLINGS OF THE ROLL AND PITCH ARTHUR VARIABLE BELLCRANKS - PITCH ARTHUR VARIABLE BELLCRANK (42C)									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-00-00-960-802					
27-10-00-720-801-01	FUNCTIONAL TEST OF THE AILERON CONTROL SURFACE DEFLECTION									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-10-00-720-801					
27-10-00-720-802-01	DETAILED CHECK OF THE ROLL CONTROL FORCE PATTERNS									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-10-00-720-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-10-00-820-801-01	ADJUSTMENT / TEST OF THE ROLL CONTROL								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-10-00-820-801					
27-12-01-640-801-01 S	PRESSURE GREASING OF THE AILERON SERVO-ACTUATOR BEARINGS - LH AILERON SERVO-ACTUATOR (L950CC)								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.070	AFL	5347								
					PROC. REF: AMM 27-12-01-640-801					PKG:32
27-12-01-640-801-02 S	PRESSURE GREASING OF THE AILERON SERVO-ACTUATOR BEARINGS - RH AILERON SERVO-ACTUATOR (R950CC)								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.070	AFL	5347								
					PROC. REF: AMM 27-12-01-640-801					PKG:32
27-12-01-790-802-01 S	CHECK FOR INTERNAL LEAKS ON THE AILERON SERVO-ACTUATORS - LH AILERON SERVO-ACTUATOR (L950CC)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.070	AFL	5651								
					PROC. REF: AMM 27-12-01-790-802					PKG:31
27-12-01-790-802-02 S	CHECK FOR INTERNAL LEAKS ON THE AILERON SERVO-ACTUATORS - RH AILERON SERVO-ACTUATOR (R950CC)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.070	AFL	5651								
					PROC. REF: AMM 27-12-01-790-802					PKG:31
27-12-01-900-801-01	REMOVAL / INSTALLATION OF THE AILERON SERVO-ACTUATORS - LH AILERON SERVO-ACTUATOR (L950CC)								Component	ATA:27
PN:103117-01	MOS/MSC	16-Mar-06	O/C	TSR 0						
SN:655	HRS	5810.6		TSR 0						
WC#: 27.070	AFL	3552		TSR 0						
					PROC. REF: AMM 27-12-01-900-801					
27-12-01-900-801-02	REMOVAL / INSTALLATION OF THE AILERON SERVO-ACTUATORS - RH AILERON SERVO-ACTUATOR (R950CC)								Component	ATA:27
PN:103117-02	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:747	HRS	0								
WC#: 27.070	AFL	0								
					PROC. REF: AMM 27-12-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-13-01-640-806-01[S]	LUBRICATION OF THE ROLL CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.170	AFL	5651								
					PROC. REF: AMM 27-13-01-640-806					PKG:31
27-13-01-640-808-01[S]	GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA								Service	ATA:27
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-13-01-640-808					PKG:16 ,15
27-13-01-900-801-01	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL EMERGENCY TRIM ACTUATOR (103C)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-02	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L900CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-03	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R900CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-04	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L901CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-05	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R901CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-13-01-900-801-06	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (902CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-07	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (903CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-08	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (904CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-09	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (905CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-10	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (906CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-11	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (907CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-12	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (908CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-13-01-900-801-13	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (909CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-14	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (910CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-15	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (911CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-16	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (912CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-17	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (913CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-18	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L914CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-19	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R914CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-13-01-900-801-20	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L915CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-21	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R915CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-22	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L916CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-23	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R916CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-24	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L917CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-25	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R917CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-26	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L918CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-13-01-900-801-27	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R918CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-28	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L919CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-29	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R919CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-30	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L920CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-31	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R920CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-32	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (921CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-33	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - LH SERVO-ACTUATOR DRIVE ROD (L922CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-13-01-900-801-34	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - RH SERVO-ACTUATOR DRIVE ROD (R922CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-35	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - LH ROLL AAFU LINK ROD (L923CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-36	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - RH ROLL AAFU LINK ROD (R923CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-37	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - LH AILERON DRIVE ROD (L924CC1)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-38	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - RH AILERON DRIVE ROD (R924CC1)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-39	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - LH AILERON DRIVE ROD (L924CC2)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					
27-13-01-900-801-40	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - RH AILERON DRIVE ROD (R924CC2)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-13-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-13-05-640-801-01[S]	VISUAL INSPECTION AND GREASING OF ROLL CONTROL SEALED BOXES									Service ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
	AFL	5347								
					PROC. REF: AMM 27-13-05-640-801					PKG:32
27-13-07-350-801-01	RESTORATION OF "AMEDEE" VARIABLE BELLCRANK (FUNCTIONAL TEST AND SERVICING) - VARIABLE BELLCRANK (AMEDEE) (930CC)									Service ATA:27
PN:028008-28	MOS	29-Jan-16	144 (+5m)		29-Jan-28	29-Jun-28	1550 d (+152)			
SN:2507	HRS									
WC#: 27.150	AFL									
					PROC. REF: AMM 27-13-07-350-801					
27-14-01-350-801-01	RESTORATION OF THE ROLL TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL TRIM ACTUATOR (112C)									Service ATA:27
PN:021057-26	MOS	07-Sep-22	144 (+5m)		07-Sep-34	07-Feb-35	3963 d (+153)			
SN:4411	HRS	8823								
WC#: 27.100	AFL	5651								
					PROC. REF: AMM 27-14-01-350-801					
27-14-03-350-801-01	RESTORATION OF THE ROLL EMERGENCY TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL EMERGENCY TRIM ACTUATOR (103C)									Service ATA:27
PN:021127	MOS	07-Aug-20	144 (+5m)		07-Aug-32	07-Jan-33	3202 d (+153)			
SN:350	HRS	8690.7								
WC#: 27.140	AFL	5593								
					PROC. REF: AMM 27-14-03-350-801					
27-14-03-720-802-01[S]	FUNCTIONAL TEST OF THE ROLL EMERGENCY TRIM ACTUATOR - ROLL EMERGENCY TRIM ACTUATOR (103C)									Service ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.140	AFL	5651								
					PROC. REF: AMM 27-14-03-720-802					PKG:21
27-14-05-720-801-01[S]	FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAYS - ROLL TRIM UNIT (119C)									Service ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.110	AFL	5347								
					PROC. REF: AMM 27-14-05-720-801					PKG:32
27-15-00-720-801-01[S]	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK MONITORING SYSTEM									Service ATA:27
	MOS	07-Mar-16								
	HRS	8278.1	3000 (+30)							
WC#: 27.080	AFL	5347								
					PROC. REF: AMM 27-15-00-720-801, AMM 27-15-00-720-801					PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-15-01-640-801-01[S]	PRESSURE GREASING OF THE ROLL ARTHUR VARIABLE BELLCRANK BEARINGS - ROLL ARTHUR VARIABLE BELLCRANK (43C)								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.080	AFL	5347								
					PROC. REF: AMM 27-15-01-640-801					PKG:32
27-15-01-720-801-01[S]	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK - ROLL ARTHUR VARIABLE BELLCRANK (43C)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.080	AFL	5651								
					PROC. REF: AMM 27-15-01-720-801					PKG:31
27-15-01-900-801-01	REMOVAL / INSTALLATION OF THE ROLL ARTHUR VARIABLE BELLCRANK - ROLL ARTHUR VARIABLE BELLCRANK (43C)								Component	ATA:27
PN:106043-20	MOS/MSC	07-Mar-16	O/C	TSR 11						
SN:1868	HRS	8278.1		TSR 0						
WC#: 27.080	AFL	5347		TSR 0						
					PROC. REF: AMM 27-15-01-900-801					
27-15-05-350-801-01	RESTORATION OF THE ROLL MAIN AFU (INSPECTION, SERVICING AND FUNCTIONAL TEST) - ROLL MAIN AFU (940CC)								Service	ATA:27
PN:105044-07	MOS	14-Jan-16	144 (+5m)		14-Jan-28	14-Jun-28	1535 d (+152)			
SN:1061	HRS									
	AFL									
					PROC. REF: AMM 27-15-05-350-801					
27-15-05-900-801-01	REMOVAL / INSTALLATION OF THE ROLL MAIN AFU - ROLL MAIN AFU (940CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-15-05-900-801					
27-15-07-640-801-01[S]	PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - LH ROLL AAFU (L960CC)								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.130	AFL	5347								
					PROC. REF: AMM 27-15-07-640-801					PKG:32
27-15-07-640-801-02[S]	PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - RH ROLL AAFU (R960CC)								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.130	AFL	5347								
					PROC. REF: AMM 27-15-07-640-801					PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-20-00-720-801-01	FUNCTIONAL TEST OF THE RUDDER CONTROL SURFACE DEFLECTION									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-20-00-720-801					
27-20-00-720-802-01	DETAILED CHECK OF THE YAW CONTROL FORCE PATTERNS									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-20-00-720-802					
27-20-00-820-801-01	ADJUSTMENT / TEST OF THE YAW CONTROL									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-20-00-820-801					
27-22-01-350-801-01	RESTORATION OF THE RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST OF VALVES AND CHECK OF DAMPER) - RUDDER SERVO-ACTUATOR (571CC)									Service ATA:27
PN:103103-13	MOS/MSC	11-May-07	N/A							
SN:347	HRS	6203								
	AFL	3806								
					PROC. REF: AMM 27-22-01-350-801					
27-22-01-350-802-01	RESTORATION OF THE RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST) - RUDDER SERVO-ACTUATOR (571CC)									Service ATA:27
PN:103103-13	MOS	11-May-07								
SN:347	HRS	6203	10000		16203		7210.9			
	AFL	3806								
					PROC. REF: AMM 27-22-01-350-802					
27-22-01-350-802-01A	RESTORATION RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST) (MANDATORY 5-40)									Service ATA:27
PN:103103-13	MOS	11-May-07						MANDATORY 5-40		
SN:347	HRS	6203	10000		16203		7210.9			
WC#: 27.220	AFL	3806								
					PROC. REF: AMM 27-22-01-350-802					
27-22-01-640-801-01[S]	PRESSURE GREASING OF THE RUDDER SERVO-ACTUATOR BEARINGS - RUDDER SERVO-ACTUATOR (571CC)									Service ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.220	AFL	5347								
					PROC. REF: AMM 27-22-01-640-801					PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-22-01-790-802-01[S]	CHECK FOR INTERNAL LEAKS ON THE RUDDER SERVO-ACTUATOR - RUDDER SERVO-ACTUATOR (571CC)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.220	AFL	5651								
					PROC. REF: AMM 27-22-01-790-802					PKG:31
27-22-01-900-801-01	REMOVAL / INSTALLATION OF THE RUDDER SERVO-ACTUATOR - RUDDER SERVO-ACTUATOR (571CC)								Component	ATA:27
PN:103103-13	MOS/MSC	11-May-07	O/C	TSR 0						
SN:347	HRS	6203		TSR 0						
WC#: 27.220	AFL	3806		TSR 0						
					PROC. REF: AMM 27-22-01-900-801					
27-23-01-640-806-01[S]	LUBRICATION OF THE YAW CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.300	AFL	5651								
					PROC. REF: AMM 27-23-01-640-806					PKG:31
27-23-01-640-807-01[S]	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-23-01-640-807					PKG:31
27-23-01-640-808-01[S]	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA								Service	ATA:27
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 27.290	AFL	5775								
					PROC. REF: AMM 27-23-01-640-808					PKG:16 ,15
27-23-01-900-801-01	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (548CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-02	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (551CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-23-01-900-801-03	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (552CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-04	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (553CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-05	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (554CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-06	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (555CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-07	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (556CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-08	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (557CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-09	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (558CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-23-01-900-801-10	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (559CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-11	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (560CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-12	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (561CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-13	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (561CC1)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-14	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (561CC2)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-15	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (562CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-16	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (563CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-23-01-900-801-17	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (564CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-18	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (565CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-19	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (566CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-20	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (567CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-21	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (568CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-22	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (569CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-23-01-900-801-23	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - YAW CONTROL ROD (569CC1)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-23-01-900-801-24	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS - RUDDER SERVO-ACTUATOR DRIVE ROD (570CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-23-01-900-801					
27-24-01-350-801-01	RESTORATION OF THE YAW TRIM ACTUATOR (FUNCTIONAL TEST) - YAW TRIM ACTUATOR (92C)								Service	ATA:27
PN:021057-28	MOS	22-Jan-16	144 (+5m)		22-Jan-28	22-Jun-28	1543 d (+152)			
SN:8193	HRS									
WC#: 27.250	AFL									
					PROC. REF: AMM 27-24-01-350-801					
27-24-01-900-801-01	REMOVAL / INSTALLATION OF THE YAW MAIN AFU / YAW TRIM ACTUATOR ASSEMBLY - YAW TRIM ACTUATOR (92C)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-24-01-900-801					
27-24-01-900-801-02	REMOVAL / INSTALLATION OF THE YAW MAIN AFU / YAW TRIM ACTUATOR ASSEMBLY - YAW MAIN AFU (573CC)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-24-01-900-801					
27-24-05-720-802-01 S	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS - YAW TRIM SAFETY RELAY (93C)								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
	AFL	5347								
					PROC. REF: AMM 27-24-05-720-802					PKG:32
27-24-05-720-802-02 S	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS - YAW TRIM SAFETY RELAY (94C)								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
	AFL	5347								
					PROC. REF: AMM 27-24-05-720-802					PKG:32
27-25-05-350-801-01	RESTORATION OF THE YAW MAIN AFU (INSPECTION, SERVICING AND FUNCTIONAL TEST) - YAW MAIN AFU (573CC)								Service	ATA:27
PN:105043-07	MOS	14-Jan-16	144 (+5m)		14-Jan-28	14-Jun-28	1535 d (+152)			
SN:1083	HRS									
	AFL									
					PROC. REF: AMM 27-25-05-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-25-07-220-801-01	INSPECTION AND SERVICING OF THE YAW AUXILIARY AFU - YAW AAFU (572CC)									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-25-07-220-801					
27-25-07-350-801-01	RESTORATION OF THE YAW AUXILIARY AFU (INSPECTION, SERVICING AND FUNCTIONAL TEST) - YAW AAFU (572CC)									Service ATA:27
PN:105070-04	MOS	13-Jan-16	144 (+5m)		13-Jan-28	13-Jun-28	1534 d (+152)			
SN:847	HRS									
	AFL									
					PROC. REF: AMM 27-25-07-350-801					
27-25-07-720-801-01	ADJUSTMENT / TESTS OF THE YAW AUXILARY AFU									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-25-07-720-801					
27-25-07-820-801-01	CHECK / ADJUSTMENT OF THE YAW AUXILIARY AFU - YAW AAFU (572CC)									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-25-07-820-801					
27-25-07-900-801-01	REMOVAL / INSTALLATION OF THE YAW AUXILIARY AFU - YAW AAFU (572CC)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-25-07-900-801					
27-30-00-720-801-01	FUNCTIONAL TEST OF THE ELEVATOR CONTROL SURFACE DEFLECTION									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-30-00-720-801					
27-30-00-720-802-01	DETAILED CHECK OF THE PITCH CONTROL FORCE PATTERNS									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-30-00-720-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-30-00-820-801-01		ADJUSTMENT / TEST OF THE PITCH CONTROL SYSTEM							Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-30-00-820-801					
27-31-01-640-801-01[S]		GREASING OF THE CONTROL COLUMNS - PILOT CONTROL COLUMN/WHEEL (L8TB)							Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.060	AFL	5347								
					PROC. REF: AMM 27-31-01-640-801					PKG:32
27-31-01-640-801-02[S]		GREASING OF THE CONTROL COLUMNS - COPILOT CONTROL COLUMN/WHEEL (R8TB)							Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.060	AFL	5347								
					PROC. REF: AMM 27-31-01-640-801					PKG:32
27-31-01-900-801-01		REMOVAL / INSTALLATION OF THE CONTROL COLUMNS - PILOT CONTROL COLUMN/WHEEL (L8TB)							Component	ATA:27
PN:F50-11696-501-701	MOS/MSC	08-Dec-06	O/C							
SN:224	HRS	5992.2								
WC#: 27.060	AFL	3650								
					PROC. REF: AMM 27-31-01-900-801					
27-31-01-900-801-02		REMOVAL / INSTALLATION OF THE CONTROL COLUMNS - COPILOT CONTROL COLUMN/WHEEL (R8TB)							Component	ATA:27
PN:F50-11696-501-703	MOS/MSC	08-Dec-06	O/C							
SN:224	HRS	5992.2								
WC#: 27.060	AFL	3650								
					PROC. REF: AMM 27-31-01-900-801					
27-32-01-350-801-01		RESTORATION OF THE ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST) - ELEVATOR SERVO-ACTUATOR (925CW)							Service	ATA:27
PN:103062-36	MOS	16-Dec-09								
SN:3108	HRS	7169.2	10000		17169.2		8177.1			
WC#: 27.320	AFL	4516								
					PROC. REF: AMM 27-32-01-350-801					
27-32-01-350-801-01A		RESTORATION ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST)(MANDATORY 5-40)							Service	ATA:27
PN:103062-36	MOS	16-Dec-09						MANDATORY 5-40		
SN:3108	HRS	7169.2	10000		17169.2		8177.1			
	AFL	4516								
					PROC. REF: AMM 27-32-01-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-32-01-640-801-01[S]	PRESSURE GREASING OF THE ELEVATOR SERVO-ACTUATOR BEARINGS - ELEVATOR SERVO-ACTUATOR (925CW)								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.320	AFL	5347								
					PROC. REF: AMM 27-32-01-640-801					PKG:32
27-32-01-790-802-01[S]	CHECK FOR INTERNAL LEAKS ON THE ELEVATOR SERVO-ACTUATOR - ELEVATOR SERVO-ACTUATOR (925CW)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.320	AFL	5651								
					PROC. REF: AMM 27-32-01-790-802					PKG:31
27-32-01-900-801-01	REMOVAL / INSTALLATION OF THE ELEVATOR SERVO-ACTUATOR - ELEVATOR SERVO-ACTUATOR (925CW)								Component	ATA:27
PN:103062-36	MOS/MSC	16-Dec-09	O/C	TSR 0						
SN:3108	HRS	7169.2		TSN 7169.2, TSR 0						
WC#: 27.320	AFL	4516		TSR 0						
					PROC. REF: AMM 27-32-01-900-801					
27-32-03-350-801-01	RESTORATION OF THE GUST DAMPING VALVE (FUNCTIONAL TEST) - GUST DAMPING VALVE (31F)								Service	ATA:27
PN:104086-13	MOS	24-Oct-91								
SN:3794	HRS	0	10000		10000		1007.9			
	AFL	0								
					PROC. REF: AMM 27-32-03-350-801					
27-32-03-350-801-01A	RESTORATION PITCH GUST VALVE (FUNCTIONAL TEST) (MANDATORY 5-40)								Service	ATA:27
PN:104086-13	MOS	24-Oct-91						MANDATORY 5-40		
SN:3794	HRS	0	10000		10000		1007.9			
WC#: 27.960	AFL	0								
					PROC. REF: AMM 27-32-03-350-801					
27-33-01-640-806-01[S]	LUBRICATION OF THE PITCH CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.400	AFL	5651								
					PROC. REF: AMM 27-33-01-640-806					PKG:31
27-33-01-640-807-01[S]	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-33-01-640-807					PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-33-01-900-801-01	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (L900CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-02	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (R900CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-03	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (901CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-04	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (902CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-05	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (903CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-06	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (904CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-07	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (905CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-33-01-900-801-08	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (906CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-09	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (907CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-10	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (908CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-11	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (909CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-12	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (910CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-13	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (911CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-14	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (912CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-33-01-900-801-15	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (913CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-16	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (914CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-17	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (915CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-18	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (916CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-19	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (917CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-20	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (918CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-21	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (919CW)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-33-01-900-801-22	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - PITCH CONTROL ROD (920CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-23	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - SERVO-ACTUATOR DRIVE CONTROL ROD (921CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-24	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - AUXILIARY AFU LINK ROD (922CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-25	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - ELEVATOR DRIVE ROD (L923CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-33-01-900-801-26	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS - ELEVATOR DRIVE ROD (R923CW)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-33-01-900-801					
27-35-00-720-801-01[S]	FUNCTIONAL TEST OF THE PITCH ARTHUR CONTROL SYSTEM								Service	ATA:27
	MOS	17-Dec-10								
	HRS	7458.3	3000 (+30)							
WC#: 27.360	AFL	4759								
					PROC. REF: AMM 27-35-00-720-801, AMM 27-35-00-720-801					PKG:22
27-35-01-640-801-01[S]	PRESSURE GREASING OF THE PITCH ARTHUR VARIABLE BELLCRANK BEARINGS - PITCH ARTHUR VARIABLE BELLCRANK (42C)								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.360	AFL	5347								
					PROC. REF: AMM 27-35-01-640-801					PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-35-01-720-801-01[S]	FUNCTIONAL TEST OF THE PITCH ARTHUR VARIABLE BELLCRANK - PITCH ARTHUR VARIABLE BELLCRANK (42C)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.360	AFL	5651								
					PROC. REF: AMM 27-35-01-720-801					PKG:31
27-35-01-900-801-01	REMOVAL / INSTALLATION OF THE PITCH ARTHUR VARIABLE BELLCRANK - PITCH ARTHUR VARIABLE BELLCRANK (42C)								Component	ATA:27
PN:106043-19	MOS/MSC	12-Feb-10	O/C	TSR 0						
SN:2334	HRS	7199.5		TSR 0						
WC#: 27.360	AFL	4547		TSR 0						
					PROC. REF: AMM 27-35-01-900-801					
27-35-05-350-801-01	RESTORATION OF THE PITCH MAIN AFU (INSPECTION, SERVICING AND FUNCTIONAL TEST) - PITCH MAIN AFU (524C)								Service	ATA:27
PN:105034-07	MOS	07-Aug-20	144 (+5m)		07-Aug-32	07-Jan-33	3202 d (+153)			
SN:1118	HRS	8690.7								
	AFL	5593								
					PROC. REF: AMM 27-35-05-350-801					
27-35-05-900-801-01	REMOVAL / INSTALLATION OF THE PITCH MAIN AFU - PITCH MAIN AFU (524C)								Component	ATA:27
PN:105034-07	MOS/MSC	07-Aug-20	O/C							
SN:1118	HRS	8690.7								
WC#: 27.340	AFL	5593								
					PROC. REF: AMM 27-35-05-900-801					
27-35-07-640-801-01[S]	PRESSURE GREASING OF THE PITCH AUXILIARY AFU BEARINGS - PITCH AAFU (924CW)								Service	ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 27.350	AFL	5347								
					PROC. REF: AMM 27-35-07-640-801					PKG:32
27-40-00-720-801-01[S]	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER CONTROL AND INDICATING SYSTEM								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.460	AFL	5651								
					PROC. REF: AMM 27-40-00-720-801					PKG:21
27-40-01-210-802-01	VISUAL INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (54C)								Service	ATA:27
PN:021121-11	MOS	07-Sep-22	72 (+3%)	TAC 3	07-Jun-28	11-Aug-28	1680 d (+65)			
SN:368	HRS	8823		TAC 0						
WC#: 27.420	AFL	5651	3750	TAC 0	9401		3605			
					PROC. REF: AMM 27-40-01-210-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-40-01-350-801-01	RESTORATION OF THE HORIZONTAL STABILIZER ACTUATOR (FULL DISASSEMBLY, INSPECTION/CHECK AND NDT) - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (54C)								Service	ATA:27
PN:021121-11	MOS	07-Sep-22	144 (+3%)	TAC 3	07-Jun-34	16-Oct-34	3871 d (+131)			
SN:368	HRS	8823		TAC 0						
WC#: 27.420	AFL	5651	7500 (+3%)	TAC 0	13151	13376	7355 (+225)			
					PROC. REF: AMM 27-40-01-350-801					
27-40-01-640-802-01[S]	GREASING OF THE HORIZONTAL STABILIZER ACTUATOR HINGES AND JACK SCREW - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (54C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 27.450	AFL	5775								
					PROC. REF: AMM 27-40-01-640-802					PKG:15
27-40-01-720-801-01[S]	MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP - NORMAL ELECTRIC MOTOR (954CA)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.470	AFL	5651								
					PROC. REF: AMM 27-40-01-720-801					PKG:21
27-40-01-720-801-02[S]	MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP - EMERGENCY ELECTRIC MOTOR (954CB)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.470	AFL	5651								
					PROC. REF: AMM 27-40-01-720-801					PKG:21
27-40-01-900-801-01	REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (54C)								Component	ATA:27
PN:021121-11	MOS/MSC	07-Sep-22	O/C	TSR 3						
SN:368	HRS	8823		TSR 0						
WC#: 27.420	AFL	5651		TSR 0						
					PROC. REF: AMM 27-40-01-900-801					
27-40-03-100-801-01	CHECK / CLEANING OF THE ELECTROMAGNETIC BRAKE OF THE HORIZONTAL STABILIZER ACTUATOR MOTORS - NORMAL ELECTRIC MOTOR (954CA)								Service	ATA:27
PN:PN	MOS/MSC		N/A							
SN:UNKNOWN	HRS									
WC#: 27.500	AFL									
					PROC. REF: AMM 27-40-03-100-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-40-03-100-801-02		CHECK / CLEANING OF THE ELECTROMAGNETIC BRAKE OF THE HORIZONTAL STABILIZER ACTUATOR MOTORS - EMERGENCY ELECTRIC MOTOR (954CB)						Service		ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-40-03-100-801					
27-40-03-760-801-01		MEASUREMENT OF THE DROP-OUT CURRENT OF THE ELECTROMAGNETIC BRAKE OF HS ACTUATOR NORMAL MOTOR - NORMAL ELECTRIC MOTOR (954CA)						Service		ATA:27
PN:PN	MOS/MSC		N/A							
SN:UNKNOWN	HRS									
WC#: 27.500	AFL									
					PROC. REF: AMM 27-40-03-760-801					
27-40-03-900-801-01		REMOVAL / INSTALLATION OF THE NORMAL MOTOR OF THE HORIZONTAL STABILIZER ACTUATOR - NORMAL ELECTRIC MOTOR (954CA)						Component		ATA:27
PN:1234-2	MOS/MSC	07-Sep-22	O/C							
SN:3224	HRS	8823								
WC#: 27.500	AFL	5651								
					PROC. REF: AMM 27-40-03-900-801					
27-40-05-900-801-01		REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER POSITION REPEATER BOX - HORIZONTAL STABILIZER POSITION REPEATER BOX (69C)						Component		ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-40-05-900-801					
27-40-07-220-801-01		REMOVAL / INSTALLATION, INSPECTION AND GREASING OF HS REPEATER MICROMETRIC ROD - HS REPEATER MICROMETRIC ROD (70C)						Service		ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-40-07-220-801					
27-40-15-710-801-01[S]		OPERATIONAL TEST OF THE HS EMERGENCY TRIM CONTROL RELAY						Service		ATA:27
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
	AFL	5347								
					PROC. REF: AMM 27-40-15-710-801					PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-40-17-720-801-01[S]	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX - HS RELAY BOX (80C)									Service ATA:27
	MOS	17-Dec-10								
	HRS	7458.3	4500 (+30)							
WC#: 27.490	AFL	4759								
					PROC. REF: AMM 27-40-17-720-801, AMM 27-40-17-720-801					PKG:23
27-40-17-720-801-01A	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX (MANDATORY 5-40)									Service ATA:27
	MOS	17-Dec-10						MANDATORY 5-40		
	HRS	7458.3	5000		12458.3		3466.2			
WC#: 27.490	AFL	4759								
					PROC. REF: AMM 27-40-17-720-801, AMM 27-40-17-720-801					
27-50-00-640-801-01[S]	GREASING / LUBRICATION OF FLAP MECHANISMS									Service ATA:27
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 27.071	AFL	5775								
					PROC. REF: AMM 27-50-00-640-801					PKG:16 ,15
27-50-00-720-801-01[S]	FUNCTIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM									Service ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.620	AFL	5651								
					PROC. REF: AMM 27-50-00-720-801					PKG:21
27-50-00-720-802-01[S]	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM									Service ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.630	AFL	5651								
					PROC. REF: AMM 27-50-00-720-802					PKG:21
27-50-00-720-803-01	CHECK OF THE GEAR BACKLASH OF FLAP LINKAGE									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-50-00-720-803					
27-50-00-720-804-01[S]	MEASUREMENT OF OVERALL LINKAGE PLAY OF FLAP LINKAGE - LH WING									Service ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.640	AFL	5651								
					PROC. REF: AMM 27-50-00-720-804					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-50-00-720-804-02[S]	MEASUREMENT OF OVERALL LINKAGE PLAY OF FLAP LINKAGE - RH WING								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.640	AFL	5651								
					PROC. REF: AMM 27-50-00-720-804					PKG:21
27-50-00-820-801-01	ADJUSTMENT OF THE FLAP ELECTRO-MECHANICAL CONTROL								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-50-00-820-801					
27-50-00-860-802-01	EXTENSION / RETRACTION OF THE SLATS / FLAPS FOR MAINTENANCE								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-50-00-860-802					
27-51-01-900-801-01	REMOVAL / INSTALLATION OF THE SLATS / FLAPS CONTROL BOX - SLATS/FLAPS CONTROL BOX (2C)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-51-01-900-801					
27-51-09-820-801-01	ADJUSTMENT OF THE FLAP POSITION POTENTIOMETERS - LH FLAP POSITION TRANSMITTER (44D1)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-51-09-820-801					
27-51-09-820-801-02	ADJUSTMENT OF THE FLAP POSITION POTENTIOMETERS - RH FLAP POSITION TRANSMITTER (44D2)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-51-09-820-801					
27-52-01-720-801-01	CHECK OF THE GEAR BACKLASH OF THE FLAP POWER DRIVE UNIT - FLAP POWER DRIVE UNIT (3C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-52-01-720-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-52-01-900-801-01	REMOVAL / INSTALLATION OF THE FLAP POWER DRIVE UNIT - FLAP POWER DRIVE UNIT (3C)								Component	ATA:27
PN:021138-02	MOS/MSC	18-Oct-99	O/C							
SN:371	HRS	3549		TSN 3549						
WC#: 27.530	AFL	2324		TSN 2324						
					PROC. REF: AMM 27-52-01-900-801					
27-52-05-720-801-01	CHECK OF THE GEAR BACKLASH OF THE SINGLE AND DOUBLE GEARBOXES - LH FLAP INTERMEDIATE TRANSFER GEARBOX (L504C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-52-05-720-801					
27-52-05-720-801-02	CHECK OF THE GEAR BACKLASH OF THE SINGLE AND DOUBLE GEARBOXES - RH FLAP INTERMEDIATE TRANSFER GEARBOX (R504C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-52-05-720-801					
27-52-05-720-801-03	CHECK OF THE GEAR BACKLASH OF THE SINGLE AND DOUBLE GEARBOXES - LH FLAP DUAL TRANSFER GEARBOX (L503C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-52-05-720-801					
27-52-05-720-801-04	CHECK OF THE GEAR BACKLASH OF THE SINGLE AND DOUBLE GEARBOXES - RH FLAP DUAL TRANSFER GEARBOX (R503C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-52-05-720-801					
27-52-13-200-801-01[S]	CHECK / GREASING OF FLAP CONTROL ROD SPLINES - LH WING								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.650	AFL	5651								
					PROC. REF: AMM 27-52-13-200-801					PKG:31
27-52-13-200-801-02[S]	CHECK / GREASING OF FLAP CONTROL ROD SPLINES - RH WING								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 27.650	AFL	5651								
					PROC. REF: AMM 27-52-13-200-801					PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-52-13-220-801-01	INSPECTION OF THE FLAP ACTUATOR CONTROL ROD SPLINES IN CASE OF ACTUATOR LOCKING								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-52-13-220-801					
27-52-13-900-804-01	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (507C)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					
27-52-13-900-804-02	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (L508C)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					
27-52-13-900-804-03	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (R508C)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					
27-52-13-900-804-04	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (L509C)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					
27-52-13-900-804-05	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (R509C)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					
27-52-13-900-804-06	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (L510C)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-52-13-900-804-07	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (R510C)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					
27-52-13-900-804-08	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (L511C)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					
27-52-13-900-804-09	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (R511C)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					
27-52-13-900-804-10	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (L512C)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					
27-52-13-900-804-11	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (R512C)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					
27-52-13-900-804-12	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (L513C)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					
27-52-13-900-804-13	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - FLAP ROTATING ROD (R513C)									Component ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-52-13-900-804					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-53-01-220-801-01[S]	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH OUTBOARD FLAP SCREW JACK (L502C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-220-801					PKG:15
27-53-01-220-801-02[S]	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP LATERAL SCREW JACK (L501C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-220-801					PKG:15
27-53-01-220-801-03[S]	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP CENTER SCREW JACK (L500C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-220-801					PKG:15
27-53-01-220-801-04[S]	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP CENTER SCREW JACK (R500C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-220-801					PKG:15
27-53-01-220-801-05[S]	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP LATERAL SCREW JACK (R501C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-220-801					PKG:15
27-53-01-220-801-06[S]	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH OUTBOARD FLAP SCREW JACK (R502C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-220-801					PKG:15
27-53-01-350-801-01	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH OUTBOARD FLAP SCREW JACK (L502C)								Service	ATA:27
PN:021137-21	MOS/MSC	07-Mar-16	O/C							
SN:2932	HRS	8278.1								
WC#: 27.560	AFL	5347								
					PROC. REF: AMM 27-53-01-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-53-01-350-801-02	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH INBOARD FLAP LATERAL SCREW JACK (L501C)								Service	ATA:27
PN:021137-19	MOS/MSC	07-Mar-16	O/C							
SN:453	HRS	8278.1								
WC#: 27.540	AFL	5347								
					PROC. REF: AMM 27-53-01-350-801					
27-53-01-350-801-03	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH INBOARD FLAP CENTER SCREW JACK (L500C)								Service	ATA:27
PN:021137-19	MOS/MSC	24-Oct-91	O/C							
SN:2152	HRS	0		TAC 0						
WC#: 27.540	AFL	0								
					PROC. REF: AMM 27-53-01-350-801					
27-53-01-350-801-04	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH INBOARD FLAP CENTER SCREW JACK (R500C)								Service	ATA:27
PN:021137-19	MOS/MSC	24-Oct-91	O/C							
SN:2154	HRS	0		TAC 0						
WC#: 27.550	AFL	0								
					PROC. REF: AMM 27-53-01-350-801					
27-53-01-350-801-05	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH INBOARD FLAP LATERAL SCREW JACK (R501C)								Service	ATA:27
PN:021137-19	MOS/MSC	07-Mar-16	O/C							
SN:1968	HRS	8278.1								
WC#: 27.550	AFL	5347								
					PROC. REF: AMM 27-53-01-350-801					
27-53-01-350-801-06	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH OUTBOARD FLAP SCREW JACK (R502C)								Service	ATA:27
PN:021137-20	MOS/MSC	07-Mar-16	O/C							
SN:2811	HRS	8278.1								
WC#: 27.560	AFL	5347								
					PROC. REF: AMM 27-53-01-350-801					
27-53-01-640-802-01[S]	GREASING OF FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-640-802					PKG:15
27-53-01-640-802-02[S]	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-640-802					PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-53-01-640-802-03[S]	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-640-802					PKG:15
27-53-01-640-802-04[S]	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-640-802					PKG:15
27-53-01-640-802-05[S]	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-640-802					PKG:15
27-53-01-640-802-06[S]	GREASING OF FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-53-01-640-802					PKG:15
27-53-01-720-804-01[S]	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502C)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.560	AFL	5651								
					PROC. REF: AMM 27-53-01-720-804					PKG:21
27-53-01-720-804-02[S]	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501C)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.540	AFL	5651								
					PROC. REF: AMM 27-53-01-720-804					PKG:21
27-53-01-720-804-03[S]	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500C)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.540	AFL	5651								
					PROC. REF: AMM 27-53-01-720-804					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-53-01-720-804-04[S]	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500C)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.550	AFL	5651								
					PROC. REF: AMM 27-53-01-720-804					PKG:21
27-53-01-720-804-05[S]	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501C)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.550	AFL	5651								
					PROC. REF: AMM 27-53-01-720-804					PKG:21
27-53-01-720-804-06[S]	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502C)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.560	AFL	5651								
					PROC. REF: AMM 27-53-01-720-804					PKG:21
27-53-01-900-803-01	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502C)								Component	ATA:27
PN:021137-21	MOS/MSC	07-Mar-16	O/C	TSR 34						
SN:2932	HRS	8278.1		TSR 0						
WC#: 27.560	AFL	5347		TSR 0						
					PROC. REF: AMM 27-53-01-900-803					
27-53-01-900-803-02	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501C)								Component	ATA:27
PN:021137-19	MOS/MSC	07-Mar-16	O/C	TSR 4						
SN:453	HRS	8278.1		TSR 0						
WC#: 27.540	AFL	5347		TSR 0						
					PROC. REF: AMM 27-53-01-900-803					
27-53-01-900-803-03	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500C)								Component	ATA:27
PN:021137-19	MOS/MSC	24-Oct-91	O/C							
SN:2152	HRS	0		TSN 0						
WC#: 27.540	AFL	0								
					PROC. REF: AMM 27-53-01-900-803					
27-53-01-900-803-04	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500C)								Component	ATA:27
PN:021137-19	MOS/MSC	24-Oct-91	O/C							
SN:2154	HRS	0		TSN 0						
WC#: 27.550	AFL	0								
					PROC. REF: AMM 27-53-01-900-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-53-01-900-803-05	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501C)								Component	ATA:27
PN:021137-19	MOS/MSC	07-Mar-16	O/C	TSR 2						
SN:1968	HRS	8278.1								
WC#: 27.550	AFL	5347		TSR 0						
					PROC. REF: AMM 27-53-01-900-803					
27-53-01-900-803-06	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502C)								Component	ATA:27
PN:021137-20	MOS/MSC	07-Mar-16	O/C	TSR 2						
SN:2811	HRS	8278.1		TSR 0						
WC#: 27.560	AFL	5347		TSR 0						
					PROC. REF: AMM 27-53-01-900-803					
27-60-00-720-802-01S	FUNCTIONAL TEST OF THE AIRBRAKE SYSTEM								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 27.760	AFL	5651								
					PROC. REF: AMM 27-60-00-720-802					PKG:21
27-60-00-720-802-01A	FUNCTIONAL TEST OF THE AIRBRAKE SYSTEM (MANDATORY 5-40)								Service	ATA:27
	MOS	07-Sep-22						MANDATORY 5-40		
	HRS	8823	10000		18823		9830.9			
WC#: 27.760	AFL	5651								
					PROC. REF: AMM 27-60-00-720-802					
27-60-00-860-801-01	EXTENSION / RETRACTION OF THE AIRBRAKES FOR MAINTENANCE								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-60-00-860-801					
27-60-00-870-801-01	BLEEDING OF THE AIRBRAKE HYDRAULIC SYSTEM								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-60-00-870-801					
27-61-01-720-801-01S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH OUTBOARD AIRBRAKE POSITION MICROSWITCH (25C1)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 27-61-01-720-801					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-61-01-720-801-02[S]	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH CENTER AIRBRAKE POSITION MICROSWITCH (24C1)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 27-61-01-720-801					PKG:21
27-61-01-720-801-03[S]	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH INBOARD AIRBRAKE POSITION MICROSWITCH (23C1)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 27-61-01-720-801					PKG:21
27-61-01-720-801-04[S]	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH INBOARD AIRBRAKE POSITION MICROSWITCH (23C2)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 27-61-01-720-801					PKG:21
27-61-01-720-801-05[S]	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH CENTER AIRBRAKE POSITION MICROSWITCH (24C2)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 27-61-01-720-801					PKG:21
27-61-01-720-801-06[S]	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH OUTBOARD AIRBRAKE POSITION MICROSWITCH (25C2)								Service	ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 27-61-01-720-801					PKG:21
27-61-01-960-801-01	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - LH OUTBOARD AIRBRAKE POSITION MICROSWITCH (25C1)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-61-01-960-801					
27-61-01-960-801-02	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - LH CENTER AIRBRAKE POSITION MICROSWITCH (24C1)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-61-01-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-61-01-960-801-03	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - LH INBOARD AIRBRAKE POSITION MICROSWITCH (23C1)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-61-01-960-801					
27-61-01-960-801-04	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - RH INBOARD AIRBRAKE POSITION MICROSWITCH (23C2)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-61-01-960-801					
27-61-01-960-801-05	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - RH CENTER AIRBRAKE POSITION MICROSWITCH (24C2)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-61-01-960-801					
27-61-01-960-801-06	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - RH OUTBOARD AIRBRAKE POSITION MICROSWITCH (25C2)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-61-01-960-801					
27-62-01-640-801-01[S]	GREASING OF THE AIRBRAKE ACTUATORS - LH OUTBOARD AIRBRAKE ACTUATOR (L30C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-62-01-640-801					PKG:15
27-62-01-640-801-02	GREASING OF THE AIRBRAKE ACTUATORS - LH MIDDLE AIRBRAKE ACTUATOR (L29C)								Service	ATA:27
	MOS/MSC	15-Dec-11	O/C							
	HRS	7712.7								
	AFL	4979								
					PROC. REF: AMM 27-62-01-640-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-62-01-640-801-03	GREASING OF THE AIRBRAKE ACTUATORS - LH INBOARD AIRBRAKE ACTUATOR (L28C)								Service	ATA:27
	MOS/MSC	15-Dec-11	O/C							
	HRS	7712.7								
	AFL	4979								
					PROC. REF: AMM 27-62-01-640-801					
27-62-01-640-801-04	GREASING OF THE AIRBRAKE ACTUATORS - RH INBOARD AIRBRAKE ACTUATOR (R28C)								Service	ATA:27
	MOS/MSC	15-Dec-11	O/C							
	HRS	7712.7								
	AFL	4979								
					PROC. REF: AMM 27-62-01-640-801					
27-62-01-640-801-05	GREASING OF THE AIRBRAKE ACTUATORS - RH MIDDLE AIRBRAKE ACTUATOR (R29C)								Service	ATA:27
	MOS/MSC	15-Dec-11	O/C							
	HRS	7712.7								
	AFL	4979								
					PROC. REF: AMM 27-62-01-640-801					
27-62-01-640-801-06[S]	GREASING OF THE AIRBRAKE ACTUATORS - RH OUTBOARD AIRBRAKE ACTUATOR (R30C)								Service	ATA:27
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 27-62-01-640-801					PKG:15
27-62-01-900-801-01	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH OUTBOARD AIRBRAKE ACTUATOR (L30C)								Component	ATA:27
PN:106091-04	MOS/MSC	19-Dec-00	O/C							
SN:2604	HRS	4127		TSN 4127, TSO 417						
WC#: 27.670	AFL	2568		TSN 2568						
					PROC. REF: AMM 27-62-01-900-801					
27-62-01-900-801-02	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH MIDDLE AIRBRAKE ACTUATOR (L29C)								Component	ATA:27
PN:106091-08	MOS/MSC	05-Feb-04	O/C	TSR 0						
SN:3126	HRS	4997.7		TSN 4997.7, TSR 0						
WC#: 27.670	AFL	3092		TSN 3092, TSR 0						
					PROC. REF: AMM 27-62-01-900-801					
27-62-01-900-801-03	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH INBOARD AIRBRAKE ACTUATOR (L28C)								Component	ATA:27
PN:106091-09	MOS/MSC	05-Feb-04	O/C	TSR 0						
SN:3130	HRS	4997.7		TSN 4997.7, TSR 0						
WC#: 27.670	AFL	3092		TSN 3092, TSR 0						
					PROC. REF: AMM 27-62-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-62-01-900-801-04	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH INBOARD AIRBRAKE ACTUATOR (R28C)								Component	ATA:27
PN:106091-09	MOS/MSC	24-Oct-91	O/C							
SN:3129	HRS	0		TSN 0						
WC#: 27.680	AFL	0								
					PROC. REF: AMM 27-62-01-900-801					
27-62-01-900-801-05	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH MIDDLE AIRBRAKE ACTUATOR (R29C)								Component	ATA:27
PN:106091-08	MOS/MSC	05-Feb-04	O/C	TSR 0						
SN:3125	HRS	4997.7		TSN 4997.7, TSR 0						
WC#: 27.680	AFL	3092		TSN 3092, TSR 0						
					PROC. REF: AMM 27-62-01-900-801					
27-62-01-900-801-06	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH OUTBOARD AIRBRAKE ACTUATOR (R30C)								Component	ATA:27
PN:106091-04	MOS/MSC	27-Jan-00	O/C							
SN:3039	HRS	3704		TSN 4030						
WC#: 27.680	AFL	2389								
					PROC. REF: AMM 27-62-01-900-801					
27-62-07-820-801-01	ADJUSTMENT OF THE AIRBRAKE CIRCUIT RESTRICTOR VALVES - LH OUTBOARD AIRBRAKE RESTRICTOR (L508CD)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-820-801					
27-62-07-820-801-02	ADJUSTMENT OF THE AIRBRAKE CIRCUIT RESTRICTOR VALVES - LH MIDDLE AIRBRAKE RESTRICTOR (L507CD)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-820-801					
27-62-07-820-801-03	ADJUSTMENT OF THE AIRBRAKE CIRCUIT RESTRICTOR VALVES - LH INBOARD AIRBRAKE RESTRICTOR (L506CD)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-820-801					
27-62-07-820-801-04	ADJUSTMENT OF THE AIRBRAKE CIRCUIT RESTRICTOR VALVES - RH INBOARD AIRBRAKE RESTRICTOR (R506CD)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-820-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-62-07-820-801-05	ADJUSTMENT OF THE AIRBRAKE CIRCUIT RESTRICTOR VALVES - RH MIDDLE AIRBRAKE RESTRICTOR (R507CD)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-820-801					
27-62-07-820-801-06	ADJUSTMENT OF THE AIRBRAKE CIRCUIT RESTRICTOR VALVES - RH OUTBOARD AIRBRAKE RESTRICTOR (R508CD)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-820-801					
27-62-07-910-801-01	ASSEMBLY PRECAUTIONS ON AIRBRAKE CIRCUIT RESTRICTOR VALVES - LH OUTBOARD AIRBRAKE RESTRICTOR (L508CD)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-910-801					
27-62-07-910-801-02	ASSEMBLY PRECAUTIONS ON AIRBRAKE CIRCUIT RESTRICTOR VALVES - LH MIDDLE AIRBRAKE RESTRICTOR (L507CD)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-910-801					
27-62-07-910-801-03	ASSEMBLY PRECAUTIONS ON AIRBRAKE CIRCUIT RESTRICTOR VALVES - LH INBOARD AIRBRAKE RESTRICTOR (L506CD)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-910-801					
27-62-07-910-801-04	ASSEMBLY PRECAUTIONS ON AIRBRAKE CIRCUIT RESTRICTOR VALVES - RH INBOARD AIRBRAKE RESTRICTOR (R506CD)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-910-801					
27-62-07-910-801-05	ASSEMBLY PRECAUTIONS ON AIRBRAKE CIRCUIT RESTRICTOR VALVES - RH MIDDLE AIRBRAKE RESTRICTOR (R507CD)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-910-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-62-07-910-801-06	ASSEMBLY PRECAUTIONS ON AIRBRAKE CIRCUIT RESTRICTOR VALVES - RH OUTBOARD AIRBRAKE RESTRICTOR (R508CD)									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-62-07-910-801					
27-80-00-710-803-01	OPERATIONAL TEST OF SLAT AUTO-EXTENSION									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-00-710-803					
27-80-00-710-806-01	OPERATIONAL TEST OF THE GROUND / FLIGHT RELAYS AND ANGLE-OF-ATTACK SENSOR CONTACTS									Service ATA:27
	MOS	09-Mar-18								
	HRS	8497.6	1000 (+30)		9497.6	9527.6	505.5 (+30)			
WC#: 27.950	AFL	5470								
					PROC. REF: AMM 27-80-00-710-806					
27-80-00-720-801-01 S	FUNCTIONAL TEST OF THE SLATS - NORMAL MODE									Service ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 27-80-00-720-801					PKG:21
27-80-00-720-801-02 S	FUNCTIONAL TEST OF THE SLATS - AUTOMATIC MODE									Service ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 27-80-00-720-801					PKG:21
27-80-00-720-801-03 S	FUNCTIONAL TEST OF THE SLATS - EMERGENCY MODE									Service ATA:27
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 27-80-00-720-801					PKG:21
27-80-00-870-801-01	BLEEDING OF THE SLAT HYDRAULIC SYSTEM									Service ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-00-870-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-80-01-350-802-01	RESTORATION OF THE SLAT SUPPLY DISTRIBUTOR (FUNCTIONAL TEST) - SLAT SUPPLY DISTRIBUTOR (508D)									Service ATA:27
PN:108103-05	MOS	19-Feb-16	144 (+5m)		19-Feb-28	19-Jul-28	1571 d (+151)			
SN:600	HRS									
WC#: 27.810	AFL									
					PROC. REF: AMM 27-80-01-350-802					
27-80-05-900-801-01	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH INBOARD SLAT ACTUATOR (L500D)									Component ATA:27
PN:106107-15	MOS/MSC	21-Mar-05	O/C	TSR 0						
SN:2943	HRS	5466		TSR 0						
WC#: 27.820	AFL	3348		TSR 0						
					PROC. REF: AMM 27-80-05-900-801					
27-80-05-900-801-02	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH INBOARD SLAT ACTUATOR (R500D)									Component ATA:27
PN:106107-15	MOS/MSC	14-Jul-04	O/C	TSR 0						
SN:2942	HRS	5219.5		TSR 0						
WC#: 27.830	AFL	3192		TSR 0						
					PROC. REF: AMM 27-80-05-900-801					
27-80-05-900-801-03	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT INBOARD ACTUATOR (L501D)									Component ATA:27
PN:106107-12	MOS/MSC	17-Nov-99	O/C							
SN:2967	HRS	3605								
WC#: 27.820	AFL	2347								
					PROC. REF: AMM 27-80-05-900-801					
27-80-05-900-801-04	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT INBOARD ACTUATOR (R501D)									Component ATA:27
PN:106107-12	MOS/MSC	26-Jul-99	O/C							
SN:2966	HRS	3338								
WC#: 27.830	AFL	2227								
					PROC. REF: AMM 27-80-05-900-801					
27-80-05-900-801-05	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT EMERGENCY ACTUATOR (L502D)									Component ATA:27
PN:106107-17	MOS/MSC	07-Mar-16	O/C	TSR 2						
SN:2899	HRS	8278.1		TSN 8278.1, TSR 0						
WC#: 27.840	AFL	5347		TSR 0						
					PROC. REF: AMM 27-80-05-900-801					
27-80-05-900-801-06	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT EMERGENCY ACTUATOR (R502D)									Component ATA:27
PN:106107-17	MOS/MSC	08-Oct-99	O/C							
SN:2898	HRS	3525								
WC#: 27.840	AFL	2310								
					PROC. REF: AMM 27-80-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-80-05-900-801-07	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT OUTBOARD ACTUATOR (L503D)								Component	ATA:27
PN:106107-13	MOS/MSC	02-Feb-00	O/C							
SN:2973	HRS	3710		TSN 3710						
WC#: 27.820	AFL	2391		TSN 2391						
					PROC. REF: AMM 27-80-05-900-801					
27-80-05-900-801-08	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT OUTBOARD ACTUATOR (R503D)								Component	ATA:27
PN:106107-13	MOS/MSC	17-Nov-99	O/C							
SN:2855	HRS	3605		TSN 4842						
WC#: 27.830	AFL	2347								
					PROC. REF: AMM 27-80-05-900-801					
27-80-17-720-801-01[S]	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - LH INBOARD SLAT RETRACTED MICROSWITCH (53D)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-80-17-720-801					PKG:31
27-80-17-720-801-02[S]	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - RH INBOARD SLAT RETRACTED MICROSWITCH (54D)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-80-17-720-801					PKG:31
27-80-17-720-801-03[S]	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - LH OUTBOARD SLAT RETRACTED MICROSWITCH (55D)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-80-17-720-801					PKG:31
27-80-17-720-801-04[S]	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - RH OUTBOARD SLAT RETRACTED MICROSWITCH (56D)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-80-17-720-801					PKG:31
27-80-17-720-801-05[S]	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - LH INBOARD SLAT EXTENDED MICROSWITCH (57D)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-80-17-720-801					PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-80-17-720-801-06[S]	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - RH INBOARD SLAT EXTENDED MICROSWITCH (58D)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-80-17-720-801					PKG:31
27-80-17-720-801-07[S]	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - LH OUTBOARD SLAT EXTENDED MICROSWITCH (59D)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-80-17-720-801					PKG:31
27-80-17-720-801-08[S]	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - RH OUTBOARD SLAT EXTENDED MICROSWITCH (60D)								Service	ATA:27
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 27-80-17-720-801					PKG:31
27-80-17-960-801-01	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - LH INBOARD SLAT RETRACTED MICROSWITCH (53D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-17-960-801					
27-80-17-960-801-02	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - RH INBOARD SLAT RETRACTED MICROSWITCH (54D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-17-960-801					
27-80-17-960-801-03	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - LH OUTBOARD SLAT RETRACTED MICROSWITCH (55D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-17-960-801					
27-80-17-960-801-04	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - RH OUTBOARD SLAT RETRACTED MICROSWITCH (56D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-17-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-80-17-960-801-05	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - LH INBOARD SLAT EXTENDED MICROSWITCH (57D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-17-960-801					
27-80-17-960-801-06	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - RH INBOARD SLAT EXTENDED MICROSWITCH (58D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-17-960-801					
27-80-17-960-801-07	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - LH OUTBOARD SLAT EXTENDED MICROSWITCH (59D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-17-960-801					
27-80-17-960-801-08	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - RH OUTBOARD SLAT EXTENDED MICROSWITCH (60D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-17-960-801					
27-80-17-960-803-01	REPLACEMENT / ADJUSTMENT OF THE FLAP POSITION MICROSWITCH - FLAP POSITION MICROSWITCH (4C)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-17-960-803					
27-80-25-910-801-01	PRECAUTIONS AT INSTALLATION OF SLAT RETRACTION FLOW RESTRICTORS								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-25-910-801					
27-80-31-640-801-01[S]	SERVICING OF THE SLAT CONTROL CABLE - SLAT CONTROL CABLE (509D)								Service	ATA:27
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 27.920	AFL	5775								
					PROC. REF: AMM 27-80-31-640-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
27-80-31-720-801-01	MEASUREMENT OF THE SLAT CONTROL CABLE SLIDING FORCES - SLAT CONTROL CABLE (509D)								Service	ATA:27
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 27-80-31-720-801					
27-80-31-900-801-01	REMOVAL / INSTALLATION OF THE SLAT CONTROL CABLE - SLAT CONTROL CABLE (509D)								Component	ATA:27
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 27-80-31-900-801					
270021	AILERON CONTROL PRESSURE SEAL BOX								Component	ATA:27
PN:F50B271100	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.020	AFL	0								
					PROC. REF: GENERIC NO REF					
270041	RUDDER/ELEVATOR CONTROL PRESSURE SEAL BOX								Component	ATA:27
PN:F50B270100	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.025	AFL	0								
					PROC. REF: GENERIC NO REF					
271160	ELEVATOR/AILERON ARTHUR Q-UNIT MONITORING-PRINTED CIRCUIT								Component	ATA:27
PN:CI816B	MOS/MSC	30-Nov-10	O/C	TSR 0						
SN:161	HRS	7454		TSR 0						
WC#: 27.090	AFL	4756		TSR 0						
					PROC. REF: GENERIC NO REF					
271161	(NORMAL) NORMAL AILERON TRIM ACTUATOR								Component	ATA:27
PN:021057-26	MOS/MSC	07-Sep-22	O/C	TSO 0						
SN:4411	HRS	8823		TSO 0						
WC#: 27.100	AFL	5651		TSO 0						
					PROC. REF: GENERIC NO REF					
271171	AILERON ARTIFICIAL FEEL UNIT								Component	ATA:27
PN:105044-07	MOS/MSC	07-Mar-16	O/C	TSR 2						
SN:1061	HRS	8278.1		TSN 8278.1, TSR 0						
WC#: 27.120	AFL	5347		TSR 0						
					PROC. REF: AMM 27-15-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
271181		LH AILERON NEUTRAL RETURN UNIT								Component ATA:27
PN:105045-06	MOS/MSC	24-Oct-91	O/C							
SN:3446	HRS	0		TSN 0						
WC#: 27.130	AFL	0								
					PROC. REF: GENERIC NO REF					
271191		RH AILERON NEUTRAL RETURN UNIT								Component ATA:27
PN:105045-06	MOS/MSC	24-Oct-91	O/C							
SN:3434	HRS	0		TSN 0						
WC#: 27.130	AFL	0								
					PROC. REF: GENERIC NO REF					
271201		AILERON EMERGENCY ACTUATOR								Component ATA:27
PN:021127	MOS/MSC	07-Aug-20	O/C	TSR 185						
SN:350	HRS	8690.7		TSR 3224.7						
WC#: 27.140	AFL	5593		TSR 2245						
					PROC. REF: GENERIC NO REF					
271211		VARIABLE RATIO (AMEDEE) BELLCRANK								Component ATA:27
PN:028008-28	MOS/MSC	07-Mar-16	O/C	TSR 2						
SN:2507	HRS	8278.1		TSN 8278.1, TSR 0						
WC#: 27.150	AFL	5347		TSR 0						
					PROC. REF: GENERIC NO REF					
272121		RUDDER ARTIFICIAL FEEL UNIT								Component ATA:27
PN:105043-07	MOS/MSC	07-Mar-16	O/C	TSR 2						
SN:1083	HRS	8278.1		TSN 8278.1, TSR 0						
WC#: 27.230	AFL	5347		TSR 0						
					PROC. REF: AMM 27-24-01-900-801					
272131		RUDDER AUXILIARY ARTIFICIAL FEEL UNIT								Component ATA:27
PN:105070-04	MOS/MSC	07-Mar-16	O/C	TSR 2						
SN:847	HRS	8278.1		TSN 8278.1, TSR 0						
WC#: 27.240	AFL	5347		TSR 0						
					PROC. REF: AMM 27-25-07-900-801					
272141		RUDDER TRIM ACTUATOR								Component ATA:27
PN:021057-28	MOS/MSC	07-Mar-16	O/C							
SN:8193	HRS	8278.1		TSN 8278.1						
WC#: 27.250	AFL	5347								
					PROC. REF: AMM 27-24-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
272161		AILERON-RUDDER-ELEVATOR TRIM TRIPLE INDICATOR								Component ATA:27
PN:4863-52-8	MOS/MSC	24-Oct-91	O/C							
SN:374	HRS	0		TSN 0						
WC#: 27.270	AFL	0								
					PROC. REF: GENERIC NO REF					
273126		HORIZONTAL STABILIZER POSITION PICK-OFF TRANSMITTER								Component ATA:27
PN:016082-02	MOS/MSC	24-Oct-91	O/C							
SN:253	HRS	0		TSN 0						
WC#: 27.330	AFL	0								
					PROC. REF: GENERIC NO REF					
273141		ELEVATOR NEUTRAL RETURN UNIT								Component ATA:27
PN:105045	MOS/MSC	24-Oct-91	O/C							
SN:3439	HRS	0		TSN 0						
WC#: 27.350	AFL	0								
					PROC. REF: GENERIC NO REF					
274171		HORIZONTAL STABILIZER AIRBRAKES-TRIM CONTROL BOX								Component ATA:27
PN:013015-14	MOS/MSC	24-Oct-91	O/C							
SN:1309	HRS	0		TSN 0						
WC#: 27.520	AFL	0								
					PROC. REF: GENERIC NO REF					
274186		HORIZONTAL STABILIZER ACTUATOR EMERGENCY ELECTRIC MOTOR								Component ATA:27
PN:1234-2	MOS/MSC	07-Sep-22	O/C							
SN:882	HRS	8823								
WC#: 27.510	AFL	5651								
					PROC. REF: GENERIC NO REF					
275136		LH DOUBLE ANGLE GEARBOX								Component ATA:27
PN:021068-06	MOS/MSC	24-Oct-91	O/C							
SN:1796	HRS	0		TSN 0						
WC#: 27.570	AFL	0								
					PROC. REF: GENERIC NO REF					
275141		RH DOUBLE ANGLE GEARBOX								Component ATA:27
PN:021068-07	MOS/MSC	24-Oct-91	O/C							
SN:1799	HRS	0		TSN 0						
WC#: 27.570	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
275146		LH FLAP SINGLE GEARBOX								Component ATA:27
PN:021063-01	MOS/MSC	24-Oct-91	O/C							
SN:1788	HRS	0		TSN 0						
WC#: 27.580	AFL	0								
					PROC. REF: GENERIC NO REF					
275151		RH FLAP SINGLE GEARBOX								Component ATA:27
PN:021063-01	MOS/MSC	24-Oct-91	O/C							
SN:1789	HRS	0		TSN 0						
WC#: 27.580	AFL	0								
					PROC. REF: GENERIC NO REF					
275156		FLAP FLAP POSITION INDICATOR								Component ATA:27
PN:4203-30-8	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.590	AFL	0								
					PROC. REF: GENERIC NO REF					
275161		LH FLAP POSITION TRANSMITTER								Component ATA:27
PN:1-4414-2	MOS/MSC	24-Oct-91	O/C							
SN:511	HRS	0		TSN 0						
WC#: 27.590	AFL	0								
					PROC. REF: GENERIC NO REF					
275166		RH FLAP POSITION TRANSMITTER								Component ATA:27
PN:2-4415-2	MOS/MSC	24-Oct-91	O/C							
SN:329	HRS	0		TSN 0						
WC#: 27.590	AFL	0								
					PROC. REF: GENERIC NO REF					
276131		INBOARD/OUTBOARD AIRBRAKE ELECTRO- DISTRIBUTOR								Component ATA:27
PN:65670-1	MOS/MSC	24-Oct-91	O/C							
SN:1431	HRS	0		TSN 0						
WC#: 27.690	AFL	0								
					PROC. REF: GENERIC NO REF					
276136		MIDDLE AIRBRAKE ELECTRO- DISTRIBUTOR								Component ATA:27
PN:65670-1	MOS/MSC	24-Oct-91	O/C							
SN:1415	HRS	0		TSN 0						
WC#: 27.690	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
276141		LH AIRBRAKE CHECK VALVE								Component ATA:27
PN:C24539000	MOS/MSC	24-Oct-91	O/C							
SN:U37	HRS	0		TSN 0						
WC#: 27.700	AFL	0								
					PROC. REF: GENERIC NO REF					
276146		RH AIRBRAKE CHECK VALVE								Component ATA:27
PN:A24524	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.700	AFL	0								
					PROC. REF: GENERIC NO REF					
276151		MIDDLE AIRBRAKE CIRCUIT PRESSURE RELIEF VALVE								Component ATA:27
PN:A24519001	MOS/MSC	24-Oct-91	O/C							
SN:FM1053	HRS	0		TSN 0						
WC#: 27.710	AFL	0								
					PROC. REF: GENERIC NO REF					
276156		INBOARD/OUTBOARD AIRBRAKE CIRCUIT PRESSURE RELIEF VALVE								Component ATA:27
PN:A24519	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.710	AFL	0								
					PROC. REF: GENERIC NO REF					
276161		CENTER AIRBRAKE ACTUATOR SUPPLY CHECK VALVE								Component ATA:27
PN:C24541000	MOS/MSC	24-Oct-91	O/C							
SN:U51	HRS	0		TSN 0						
WC#: 27.720	AFL	0								
					PROC. REF: GENERIC NO REF					
276166		INBOARD/OUTBOARD AIRBRAKE ACTUATOR CIRCUIT NONRETURN VALVE								Component ATA:27
PN:A24515	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.720	AFL	0								
					PROC. REF: GENERIC NO REF					
276171		LH INBOARD AIRBRAKE RESTRICTOR								Component ATA:27
PN:C24370-202	MOS/MSC	24-Oct-91	O/C							
SN:B3334	HRS	0		TSN 0						
WC#: 27.730	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
276176		RH INBOARD AIRBRAKE RESTRICTOR								Component ATA:27
PN:C24370-202	MOS/MSC	24-Oct-91	O/C							
SN:B3375	HRS	0		TSN 0						
WC#: 27.740	AFL	0								
					PROC. REF: GENERIC NO REF					
276181		LH MIDDLE AIRBRAKE RESTRICTOR								Component ATA:27
PN:C24370-302	MOS/MSC	24-Oct-91	O/C							
SN:B3305	HRS	0		TSN 0						
WC#: 27.730	AFL	0								
					PROC. REF: GENERIC NO REF					
276186		RH MIDDLE AIRBRAKE RESTRICTOR								Component ATA:27
PN:C24370-302	MOS/MSC	24-Oct-91	O/C							
SN:B3341	HRS	0		TSN 0						
WC#: 27.740	AFL	0								
					PROC. REF: GENERIC NO REF					
276191		LH OUTBOARD AIRBRAKE RESTRICTOR								Component ATA:27
PN:C24370-402	MOS/MSC	24-Oct-91	O/C							
SN:B3364	HRS	0		TSN 0						
WC#: 27.730	AFL	0								
					PROC. REF: GENERIC NO REF					
276196		RH OUTBOARD AIRBRAKE RESTRICTOR								Component ATA:27
PN:C24370-402	MOS/MSC	24-Oct-91	O/C							
SN:B3400	HRS	0		TSN 0						
WC#: 27.740	AFL	0								
					PROC. REF: GENERIC NO REF					
278001[U]		ANGLE OF ATTACK PROBE								Component ATA:27
PN:SLZ-9164	MOS/MSC	09-Apr-92	O/C							
SN:AB18026	HRS	26								
	AFL	13								
278006[U]		ANGLE ATCK INTERFACE UNIT								Component ATA:27
PN:SLZ-9926	MOS/MSC	09-Apr-92	O/C							
SN:HM1145A	HRS	26								
	AFL	13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
278009[U]		ANGLE OF ATTACK INDICATOR								Component ATA:27
PN:SLZ-9927	MOS/MSC	30-Apr-03	O/C	TSO 0						
SN:HP1132	HRS	4704.9		TSO 0						
	AFL	2964		TSO 0						
278111		LH INTERMEDIATE BEARING								Component ATA:27
PN:021063-01	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.780	AFL	0								
					PROC. REF: GENERIC NO REF					
278116		RH INTERMEDIATE BEARING								Component ATA:27
PN:021063-01	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.780	AFL	0								
					PROC. REF: GENERIC NO REF					
278121		FLAP/SLAT FLAP/SLAT CONTROL BOX								Component ATA:27
PN:7016	MOS/MSC	24-Oct-91	O/C							
SN:356	HRS	0		TSN 0						
WC#: 27.790	AFL	0								
					PROC. REF: AMM 27-51-01-900-801					
278126		SLAT CONTROL DISTRIBUTOR								Component ATA:27
PN:108092-03	MOS/MSC	15-Dec-12	O/C	TSR 3						
SN:253	HRS	7936		TSR 0						
WC#: 27.800	AFL	5150		TSR 0						
					PROC. REF: GENERIC NO REF					
278131		SLAT SUPPLY DISTRIBUTOR								Component ATA:27
PN:108103-05	MOS/MSC	07-Mar-16	O/C	TSR 1						
SN:600	HRS	8278.1		TSN 8278.1, TSR 0						
WC#: 27.810	AFL	5347		TSR 0						
					PROC. REF: GENERIC NO REF					
278136		SLAT STAND-BY DISTRIBUTOR								Component ATA:27
PN:65670-1	MOS/MSC	24-Oct-91	O/C							
SN:1402	HRS	0		TSN 0						
WC#: 27.800	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
278181		LH SLATS EMERGENCY CIRCUIT ADJUSTABLE DIAPHRAGM								Component ATA:27
PN:JETX0504650AC	MOS/MSC	24-Oct-91	O/C							
SN:MA4	HRS	0		TSN 0						
WC#: 27.850	AFL	0								
					PROC. REF: GENERIC NO REF					
278186		RH SLATS EMERGENCY CIRCUIT ADJUSTABLE DIAPHRAGM								Component ATA:27
PN:JETX0504650AC	MOS/MSC	24-Oct-91	O/C							
SN:MA6	HRS	0		TSN 0						
WC#: 27.850	AFL	0								
					PROC. REF: GENERIC NO REF					
278191		SLAT SUPPLY CIRCUIT CHECK VALVE								Component ATA:27
PN:A24515	MOS/MSC	24-Oct-91	O/C							
SN:FM1939	HRS	0		TSN 0						
WC#: 27.860	AFL	0								
					PROC. REF: GENERIC NO REF					
278196		OUTBOARD SLAT RETRACTION FLOW RESTRICTOR								Component ATA:27
PN:C24346-302	MOS/MSC	24-Oct-91	O/C							
SN:B480	HRS	0		TSN 0						
WC#: 27.870	AFL	0								
					PROC. REF: GENERIC NO REF					
278201		LH INBOARD SLAT RETRACTION RESTRICTOR								Component ATA:27
PN:C24346-102	MOS/MSC	24-Oct-91	O/C							
SN:B1472	HRS	0		TSN 0						
WC#: 27.880	AFL	0								
					PROC. REF: GENERIC NO REF					
278206		RH INBOARD SLAT RETRACTION RESTRICTOR								Component ATA:27
PN:C24346-102	MOS/MSC	24-Oct-91	O/C							
SN:B1467	HRS	0		TSN 0						
WC#: 27.880	AFL	0								
					PROC. REF: GENERIC NO REF					
278211		LH NORMAL SLAT CIRCUIT ADJUSTABLE RESTRICTOR								Component ATA:27
PN:C24370-102	MOS/MSC	24-Oct-91	O/C							
SN:B3374	HRS	0		TSN 0						
WC#: 27.890	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
278216		RH NORMAL SLAT CIRCUIT ADJUSTABLE RESTRICTOR								Component ATA:27
PN:C24370-102	MOS/MSC	24-Oct-91	O/C							
SN:B3373	HRS	0		TSN 0						
WC#: 27.890	AFL	0								
					PROC. REF: GENERIC NO REF					
278235		LEADING EDGE SELECTOR VALVE CONTROL CABLE								Component ATA:27
PN:F50B773001	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.920	AFL	0								
					PROC. REF: GENERIC NO REF					
278286		PITCH GUST VALVE								Component ATA:27
PN:104086-13	MOS/MSC	24-Oct-91	O/C							
SN:3794	HRS	0		TSN 0						
WC#: 27.960	AFL	0								
					PROC. REF: GENERIC NO REF					
278311		SLAT AIRSPEED SWITCH								Component ATA:27
PN:4219F010301	MOS/MSC	24-Oct-91	O/C							
SN:1702	HRS	0		TSN 0						
WC#: 27.900	AFL	0								
					PROC. REF: GENERIC NO REF					
ATA 28 - FUEL										
28-00-00-280-801-01 S		FUEL CONTAMINATION DETECTION TEST								Service ATA:28
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 28.820	AFL	5775								
					PROC. REF: AMM 28-00-00-280-801					PKG:15
28-00-00-290-801-01		BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH FEEDER TANK								Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-290-801					
28-00-00-290-801-02		BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH FEEDER TANK								Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-290-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-00-00-290-801-03	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE CTR FEEDER TANK								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-290-801					
28-00-00-290-801-04	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE CENTER-WING TANK								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-290-801					
28-00-00-290-801-05	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH WING TANK								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-290-801					
28-00-00-290-801-06	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH WING TANK								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-290-801					
28-00-00-910-801-01	FUEL SYSTEM MAINTENANCE AND SAFETY PRECAUTIONS								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-910-801					
28-00-00-910-802-01	ACCEPTANCE CRITERIA FOR FUEL LEAKS								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-910-802					
28-00-00-910-803-01	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - FUEL INJECTION METHOD								Service	ATA:28
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-910-803, AMM 28-00-00-910-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-00-00-910-803-02	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - GRAVITY POURING METHOD									Service ATA:28
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-910-803, AMM 28-00-00-910-803					
28-00-00-910-803-03	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - FUEL INJECTION METHOD									Service ATA:28
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-910-803, AMM 28-00-00-910-803					
28-00-00-910-803-04	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - GRAVITY POURING METHOD									Service ATA:28
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-910-803, AMM 28-00-00-910-803					
28-00-00-910-803-06	DECONTAMINATION OF THE FUEL SYSTEMS - CLEANING / REPLACEMENT OF FILTERS									Service ATA:28
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-910-803, AMM 28-00-00-910-803					
28-00-00-910-804-01	MEASURES TO BE TAKEN AFTER MAINTENANCE OPERATIONS IN THE FUEL TANKS									Service ATA:28
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-910-804					
28-00-00-960-802-01	DISCARD OF FEEDER TANK FUEL HOSES - LH FEEDER TANK SOL./TRANSF. VALVE HOSE (L903QD)									Service ATA:28
PN:71029-380A	MOS	07-Mar-16	144 (+20%/-20%) TAC 20		07-Jul-26	01-Dec-28	979 d (+878)	LIFE LIMIT		
SN:78525	HRS	8278.1								
WC#: 28.470	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-02	DISCARD OF FEEDER TANK FUEL HOSES - CENTER FEEDER TANK SOL./TRANSF. VALVE HOSE (M903QD)									Service ATA:28
PN:71029-420A	MOS	07-Mar-16	144 (+20%/-20%) TAC 14		07-Jan-27	31-May-29	1163 d (+875)	LIFE LIMIT		
SN:80314	HRS	8278.1								
WC#: 28.475	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-00-00-960-802-03	DISCARD OF FEEDER TANK FUEL HOSES - RH FEEDER TANK SOL./TRANSF. VALVE HOSE (R903QD)									Service ATA:28
PN:71029-380A	MOS	07-Mar-16	144 (+20%/-20%) TAC 20		07-Jul-26	01-Dec-28	979 d (+878)	LIFE LIMIT		
SN:78533	HRS	8278.1								
WC#: 28.470	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-04	DISCARD OF FEEDER TANK FUEL HOSES - LH FEEDER TANK REG. VALVE SUPPLY HOSE (L904QD)									Service ATA:28
PN:71029-1020A	MOS	07-Mar-16	144 (+20%/-20%) TAC 20		07-Jul-26	01-Dec-28	979 d (+878)	LIFE LIMIT		
SN:78355	HRS	8278.1								
WC#: 28.480	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-05	DISCARD OF FEEDER TANK FUEL HOSES - CENTER FEEDER TANK REG. VALVE SUPPLY HOSE (M904QD)									Service ATA:28
PN:71029-560A	MOS	07-Mar-16	144 (+20%/-20%) TAC 20		07-Jul-26	01-Dec-28	979 d (+878)	LIFE LIMIT		
SN:78213	HRS	8278.1								
WC#: 28.485	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-06	DISCARD OF FEEDER TANK FUEL HOSES - RH FEEDER TANK REG. VALVE SUPPLY HOSE (R904QD)									Service ATA:28
PN:71029-450A	MOS	07-Mar-16	144 (+20%/-20%) TAC 15		07-Dec-26	01-May-29	1132 d (+876)	LIFE LIMIT		
SN:79521	HRS	8278.1								
WC#: 28.480	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-07	DISCARD OF FEEDER TANK FUEL HOSES - CENTER FEEDER TANK REG./TRANSF. VALVE SUPPLY HOSE (M905QD)									Service ATA:28
PN:71029-1020A	MOS	07-Mar-16	144 (+20%/-20%) TAC 20		07-Jul-26	01-Dec-28	979 d (+878)	LIFE LIMIT		
SN:78356	HRS	8278.1								
WC#: 28.490	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-08	DISCARD OF FEEDER TANK FUEL HOSES - LH FEEDER TANK HIGH LEVEL/SOL. VALVE HOSE (L906QD)									Service ATA:28
PN:71028-610A	MOS	07-Mar-16	144 (+20%/-20%) TAC 20		07-Jul-26	01-Dec-28	979 d (+878)	LIFE LIMIT		
SN:78446	HRS	8278.1								
WC#: 28.500	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-09	DISCARD OF FEEDER TANK FUEL HOSES - RH FEEDER TANK HIGH LEVEL/SOL. VALVE HOSE (R906QD)									Service ATA:28
PN:71028-610A	MOS	07-Mar-16	144 (+20%/-20%) TAC 20		07-Jul-26	01-Dec-28	979 d (+878)	LIFE LIMIT		
SN:78449	HRS	8278.1								
WC#: 28.500	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-00-00-960-802-10	DISCARD OF FEEDER TANK FUEL HOSES - LH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (L907QD)									Service ATA:28
PN:71028-1290A	MOS	07-Mar-16	144 (+20%/-20%) TAC 19		07-Aug-26	31-Dec-28	1010 d (+877)	LIFE LIMIT		
SN:78686	HRS	8278.1								
WC#: 28.510	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-11	DISCARD OF FEEDER TANK FUEL HOSES - CENTER FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (M907QD)									Service ATA:28
PN:71028-2460A	MOS	07-Mar-16	144 (+20%/-20%) TAC 12		07-Mar-27	31-Jul-29	1222 d (+877)	LIFE LIMIT		
SN:78716	HRS	8278.1								
WC#: 28.515	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-12	DISCARD OF FEEDER TANK FUEL HOSES - RH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (R907QD)									Service ATA:28
PN:71028-1290A	MOS	07-Mar-16	144 (+20%/-20%) TAC 19		07-Aug-26	31-Dec-28	1010 d (+877)	LIFE LIMIT		
SN:78685	HRS	8278.1								
WC#: 28.510	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-13	DISCARD OF FEEDER TANK FUEL HOSES - LH FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (L908QD)									Service ATA:28
PN:71030-496A	MOS	07-Mar-16	144 (+20%/-20%) TAC 18		07-Sep-26	31-Jan-29	1041 d (+877)	LIFE LIMIT		
SN:78595	HRS	8278.1								
WC#: 28.520	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-14	DISCARD OF FEEDER TANK FUEL HOSES - CENTER FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (M908QD)									Service ATA:28
PN:71030-676A	MOS	07-Mar-16	144 (+20%/-20%) TAC 15		07-Dec-26	01-May-29	1132 d (+876)	LIFE LIMIT		
SN:79133	HRS	8278.1								
WC#: 28.525	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-960-802-15	DISCARD OF FEEDER TANK FUEL HOSES - RH FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (R908QD)									Service ATA:28
PN:71030-496A	MOS	07-Mar-16	144 (+20%/-20%) TAC 18		07-Sep-26	31-Jan-29	1041 d (+877)	LIFE LIMIT		
SN:78596	HRS	8278.1								
WC#: 28.520	AFL	5347								
					PROC. REF: AMM 28-00-00-960-802					
28-00-00-990-802-01	TABLE FOR RECORDING THE REPLACEMENT OF FEEDER TANK FUEL HOSES									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-00-00-990-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-20-00-710-802-01[S]	OPERATIONAL TEST OF THE TRANSFER VALVES AND ISOLATION VALVES - TRANSFER MANIFOLD TRANSFER VALVES (17Q1) AND (17Q2)								Service	ATA:28
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 28-20-00-710-802					PKG:21
28-20-00-710-802-02[S]	OPERATIONAL TEST OF THE TRANSFER VALVES AND ISOLATION VALVES - TRANSFER VALVE (13Q1) AND (13Q2)								Service	ATA:28
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 28-20-00-710-802					PKG:21
28-20-00-710-802-03[S]	OPERATIONAL TEST OF THE TRANSFER VALVES AND ISOLATION VALVES - ISOLATION VALVES (L17QD) , (M17QD) AND (R17QD)								Service	ATA:28
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 28-20-00-710-802					PKG:21
28-20-00-900-801-01	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - LH FEEDER TANK SOL./TRANSF. VALVE HOSE (L903QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-02	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - CENTER FEEDER TANK SOL./TRANSF. VALVE HOSE (M903QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-03	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - RH FEEDER TANK SOL./TRANSF. VALVE HOSE (R903QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-04	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - LH FEEDER TANK REG. VALVE SUPPLY HOSE (L904QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-20-00-900-801-05	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - CENTER FEEDER TANK REG. VALVE SUPPLY HOSE (M904QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-06	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - RH FEEDER TANK REG. VALVE SUPPLY HOSE (R904QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-07	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - CENTER FEEDER TANK REG./TRANSF. VALVE SUPPLY HOSE (M905QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-08	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - LH FEEDER TANK HIGH LEVEL/SOL. VALVE HOSE (L906QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-09	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - RH FEEDER TANK HIGH LEVEL/SOL. VALVE HOSE (R906QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-10	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - LH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (L907QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-11	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - CENTER FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (M907QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-20-00-900-801-12	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - RH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (R907QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-13	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - LH FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (L908QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-14	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - CENTER FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (M908QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-20-00-900-801-15	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - RH FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (R908QD)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
28-21-01-350-801-01	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF MOTOR BRUSHES) - BOOSTER PUMP 1 (3Q1)								Service	ATA:28
PN:226075-51	MOS/MSC	25-Feb-98	O/C							
SN:288	HRS	2691								
WC#: 28.600	AFL	1893								
					PROC. REF: AMM 28-21-01-350-801					
28-21-01-350-801-02	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF MOTOR BRUSHES) - BOOSTER PUMP 2 (3Q2)								Service	ATA:28
PN:226075-51	MOS/MSC	30-Jun-97	O/C							
SN:268	HRS	2457								
WC#: 28.610	AFL	1722								
					PROC. REF: AMM 28-21-01-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty

ATA 28 - FUEL

28-21-01-350-801-03	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF MOTOR BRUSHES) - BOOSTER PUMP 3 (3Q3)								Service	ATA:28
PN:226075-51	MOS/MSC	11-Mar-97	O/C							
SN:103	HRS	2325								
WC#: 28.620	AFL	1628								
					PROC. REF: AMM 28-21-01-350-801					
28-21-01-350-802-01	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF BEARINGS) - BOOSTER PUMP 1 (3Q1)								Service	ATA:28
PN:226075-51	MOS/MSC	25-Feb-98	O/C							
SN:288	HRS	2691								
WC#: 28.600	AFL	1893								
					PROC. REF: AMM 28-21-01-350-802					
28-21-01-350-802-02	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF BEARINGS) - BOOSTER PUMP 2 (3Q2)								Service	ATA:28
PN:226075-51	MOS/MSC	30-Jun-97	O/C							
SN:268	HRS	2457								
WC#: 28.610	AFL	1722								
					PROC. REF: AMM 28-21-01-350-802					
28-21-01-350-802-03	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF BEARINGS) - BOOSTER PUMP 3 (3Q3)								Service	ATA:28
PN:226075-51	MOS/MSC	11-Mar-97	O/C							
SN:103	HRS	2325								
WC#: 28.620	AFL	1628								
					PROC. REF: AMM 28-21-01-350-802					
28-21-01-900-801-01	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 1 (3Q1)								Component	ATA:28
PN:226075-51	MOS/MSC	25-Feb-98	O/C							
SN:288	HRS	2691		TSO 0						
WC#: 28.600	AFL	1893		TSO 0						
					PROC. REF: AMM 28-21-01-900-801					
28-21-01-900-801-02	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 2 (3Q2)								Component	ATA:28
PN:226075-51	MOS/MSC	30-Jun-97	O/C							
SN:268	HRS	2457		TSN 847, TSO 5						
WC#: 28.610	AFL	1722								
					PROC. REF: AMM 28-21-01-900-801					
28-21-01-900-801-03	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 3 (3Q3)								Component	ATA:28
PN:226075-51	MOS/MSC	11-Mar-97	O/C							
SN:103	HRS	2325		TSN 1562, TSO 0						
WC#: 28.620	AFL	1628								
					PROC. REF: AMM 28-21-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-21-05-200-802-01	CHECK OF LOW PRESSURE CROSSFEED DRAINING AND SHUT-OFF VALVE SEALS OF THE BP MANIFOLD - BP 1 MANIFOLD (L14QD)								Service	ATA:28
PN:L88A19-208	MOS	24-Oct-91								
SN:20547	HRS	0	10000 (+3%)		10000	10300	1007.9 (+300)			
WC#: 28.550	AFL	0								
					PROC. REF: AMM 28-21-05-200-802					
28-21-05-200-802-02	CHECK OF LOW PRESSURE CROSSFEED DRAINING AND SHUT-OFF VALVE SEALS OF THE BP MANIFOLD - BP 3 MANIFOLD (R14QD)								Service	ATA:28
PN:L88A19-209	MOS	24-Oct-91								
SN:20557	HRS	0	10000 (+3%)		10000	10300	1007.9 (+300)			
WC#: 28.550	AFL	0								
					PROC. REF: AMM 28-21-05-200-802					
28-21-05-900-801-01	REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 1 MANIFOLD (L14QD)								Component	ATA:28
PN:L88A19-208	MOS/MSC	24-Oct-91	O/C							
SN:20547	HRS	0		TSN 0						
WC#: 28.550	AFL	0								
					PROC. REF: AMM 28-21-05-900-801					
28-21-05-900-801-02	REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 2 MANIFOLD (M14QD)								Component	ATA:28
PN:L88A25-203	MOS/MSC	24-Oct-91	O/C							
SN:20244	HRS	0		TSN 0						
WC#: 28.560	AFL	0								
					PROC. REF: AMM 28-21-05-900-801					
28-21-05-900-801-03	REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 3 MANIFOLD (R14QD)								Component	ATA:28
PN:L88A19-209	MOS/MSC	24-Oct-91	O/C							
SN:20557	HRS	0		TSN 0						
WC#: 28.550	AFL	0								
					PROC. REF: AMM 28-21-05-900-801					
28-21-07-100-801-01 S	CLEANING OF THE JET PUMP FILTERS - LH JET PUMP FILTER (L40QD)								Service	ATA:28
	MOS	18-Nov-22	72 (+2m)							
	HRS	8850.4								
WC#: 28.150	AFL	5691								
					PROC. REF: AMM 28-21-07-100-801					PKG:31
28-21-07-100-801-02 S	CLEANING OF THE JET PUMP FILTERS - RH JET PUMP FILTER (R40QD)								Service	ATA:28
	MOS	18-Nov-22	72 (+2m)							
	HRS	8850.4								
	AFL	5691								
					PROC. REF: AMM 28-21-07-100-801					PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-21-13-790-801-01	LEAK TEST OF THE FUEL SHUT-OFF VALVES - ENGINE 1 SHUT-OFF VALVE INTEGRATED IN BP 1 MANIFOLD (L14QD)									Service ATA:28
PN:PN	MOS/MSC	13-Dec-13	E/C							
SN:UNKNOWN	HRS	8092.4	1530		9622.4		630.3			
WC#: 28.570	AFL	5236								
					PROC. REF: AMM 28-21-13-790-801					
28-21-13-790-801-01A	LEAK TEST LH FUEL FIRE SHUT-OFF VALVE (MANDATORY 5-40)									Service ATA:28
PN:PN	MOS	13-Dec-13						MANDATORY 5-40		
SN:UNKNOWN	HRS	8092.4	1530		9622.4		630.3			
WC#: 28.570	AFL	5236								
					PROC. REF: AMM 28-21-13-790-801					
28-21-13-790-801-02	LEAK TEST OF THE FUEL SHUT-OFF VALVES - ENGINE 2 SHUT-OFF VALVE INTEGRATED IN BP 2 MANIFOLD (M14QD)									Service ATA:28
PN:PN	MOS/MSC	13-Feb-14	E/C							
SN:UNKNOWN	HRS	8106.6	1530		9636.6		644.5			
WC#: 28.580	AFL	5246								
					PROC. REF: AMM 28-21-13-790-801					
28-21-13-790-801-02A	LEAK TEST MIDDLE FUEL FIRE SHUT-OFF VALVE (MANDATORY 5-40)									Service ATA:28
PN:PN	MOS	13-Feb-14						MANDATORY 5-40		
SN:UNKNOWN	HRS	8106.6	1530		9636.6		644.5			
WC#: 28.580	AFL	5246								
					PROC. REF: AMM 28-21-13-790-801					
28-21-13-790-801-03	LEAK TEST OF THE FUEL SHUT-OFF VALVES - ENGINE 3 SHUT-OFF VALVE INTEGRATED IN BP 3 MANIFOLD (R14QD)									Service ATA:28
PN:PN	MOS/MSC	14-Nov-14	E/C							
SN:UNKNOWN	HRS	8143.4	1530		9673.4		681.3			
WC#: 28.590	AFL	5273								
					PROC. REF: AMM 28-21-13-790-801					
28-21-13-790-801-03A	LEAK TEST RH FUEL FIRE SHUT-OFF VALVE (MANDATORY 5-40)									Service ATA:28
PN:PN	MOS	14-Nov-14						MANDATORY 5-40		
SN:UNKNOWN	HRS	8143.4	1530		9673.4		681.3			
WC#: 28.590	AFL	5273								
					PROC. REF: AMM 28-21-13-790-801					
28-21-14-720-801-01	FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 1 MANIFOLD (L14QD)									Service ATA:28
PN:L88A19-208	MOS	24-Oct-91								
SN:20547	HRS	0	10000 (+3%)		10000	10300	1007.9 (+300)			
WC#: 28.550	AFL	0								
					PROC. REF: AMM 28-21-14-720-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-21-14-720-801-02		FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 3 MANIFOLD (R14QD)							Service	ATA:28
PN:L88A19-209	MOS	24-Oct-91								
SN:20557	HRS	0	10000 (+3%)		10000	10300	1007.9 (+300)			
WC#: 28.550	AFL	0								
					PROC. REF: AMM 28-21-14-720-801					
28-21-16-610-801-01		SERVICING OF THE FUEL SHUT-OFF VALVES CONTROL CABLES - SERVICING OF THE CONTROL CABLES AND CHECKING OF THE SHUT-OFF VALVES OPENING/CLOSING							Service	ATA:28
	MOS	08-Sep-23	12 (+1m)		08-Sep-24	08-Oct-24	312 d (+30)			
	HRS	8967	1000 (+30)		9967	9997	974.9 (+30)			
	AFL	5775								
					PROC. REF: AMM 28-21-16-610-801					PKG:15
28-21-16-610-801-01A		SERVICING OF THE FUEL SHUT-OFF VALVE CONTROL CABLES AND CHECKING OF THE SHUT-OFF VALVES OPENING/CLOSING (MANDATORY 5-40)							Service	ATA:28
	MOS	08-Sep-23	13		08-Oct-24		342 d	MANDATORY 5-40		
	HRS	8967	1000		9967		974.9			
	AFL	5775								
					PROC. REF: AMM 28-21-16-610-801					
28-21-16-610-801-02[S]		SERVICING OF THE FUEL SHUT-OFF VALVES CONTROL CABLES - MEASUREMENT OF CONTROL CABLE SLIDING FORCES							Service	ATA:28
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 28-21-16-610-801					PKG:15
28-21-16-900-801-01		REMOVAL / INSTALLATION OF THE FUEL SHUT-OFF VALVES CONTROL CABLES - LH SHUT-OFF VALVE FLEXIBLE CONTROL CABLE (L15QD)							Component	ATA:28
PN:F50B795001110 A3	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.650	AFL	0								
					PROC. REF: AMM 28-21-16-900-801					
28-21-16-900-801-02		REMOVAL / INSTALLATION OF THE FUEL SHUT-OFF VALVES CONTROL CABLES - CENTER SHUT-OFF VALVE FLEXIBLE CONTROL CABLE (M15QD)							Component	ATA:28
PN:F50B795002110 A3	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.660	AFL	0								
					PROC. REF: AMM 28-21-16-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-21-16-900-801-03	REMOVAL / INSTALLATION OF THE FUEL SHUT-OFF VALVES CONTROL CABLES - RH SHUT-OFF VALVE FLEXIBLE CONTROL CABLE (R15QD)								Component	ATA:28
PN:F50B795001110A3	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.670	AFL	0								
					PROC. REF: AMM 28-21-16-900-801					
28-21-17-900-801-01	REMOVAL / INSTALLATION OF THE APU FUEL SHUT-OFF VALVE - APU FUEL SHUT-OFF VALVE (195H)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-21-17-900-801					
28-21-33-870-802-01	BLEEDING OF THE ENGINE FUEL SUPPLY LINES - ENGINE 1 (L4EZ)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-21-33-870-802					
28-21-33-870-802-02	BLEEDING OF THE ENGINE FUEL SUPPLY LINES - ENGINE 2 (M4EZ)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-21-33-870-802					
28-21-33-870-802-03	BLEEDING OF THE ENGINE FUEL SUPPLY LINES - ENGINE 3 (R4EZ)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-21-33-870-802					
28-21-33-870-803-01	BLEEDING OF THE APU FUEL SUPPLY LINES								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-21-33-870-803					
28-21-33-900-801-01	NO. 1 ENGINE FUEL SUPPLY HOSE								Component	ATA:28
PN:663106882001	MOS/MSC	10-Dec-03	O/C	TSN 0						
SN:DF 09 2003	HRS	4936.4								
WC#: 28.530	AFL	3069								
					PROC. REF: AMM 28-21-33-900-802, AMM 28-21-33-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-21-33-900-801-01	NO. 2 ENGINE FUEL SUPPLY HOSE									Component ATA:28
PN:665054EE2004	MOS/MSC	10-Dec-03	O/C	TSN 0						
SN:MF-50	HRS	4936.4								
WC#: 28.535	AFL	3069								
					PROC. REF: AMM 28-21-33-900-802, AMM 28-21-33-900-801					
28-21-33-900-801-01	NO. 3 ENGINE FUEL SUPPLY HOSE									Component ATA:28
PN:665106882001	MOS/MSC	10-Dec-03	O/C	TSN 0						
SN:MF-50	HRS	4936.4								
WC#: 28.530	AFL	3069								
					PROC. REF: AMM 28-21-33-900-802, AMM 28-21-33-900-801					
28-21-33-900-802-01	REMOVAL / INSTALLATION OF THE ENGINE FUEL SUPPLY HOSES - ENGINE 1 FUEL SUPPLY HOSE (L901QD)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-21-33-900-802					
28-21-33-900-802-02	REMOVAL / INSTALLATION OF THE ENGINE FUEL SUPPLY HOSES - ENGINE 2 FUEL SUPPLY HOSE (M901QD)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-21-33-900-802					
28-21-33-900-802-03	REMOVAL / INSTALLATION OF THE ENGINE FUEL SUPPLY HOSES - ENGINE 3 FUEL SUPPLY HOSE (R901QD)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-21-33-900-802					
28-21-33-900-803-01	REMOVAL / INSTALLATION OF THE APU FUEL SUPPLY HOSE - APU FUEL SUPPLY HOSE (902QD)									Component ATA:28
PN:601002-6D0125	MOS/MSC	10-Dec-03	O/C	TSN 0						
SN:UNKNOWN	HRS	4936.4								
WC#: 28.540	AFL	3069								
					PROC. REF: AMM 28-21-33-900-803					
28-21-33-960-801-01	DISCARD OF THE FUEL SUPPLY HOSES - APU FUEL SUPPLY HOSE (902QD)									Service ATA:28
PN:601002-6D0125	MOS/MSC	10-Dec-03	O/C	TAC 0						
SN:UNKNOWN	HRS	4936.4								
WC#: 28.540	AFL	3069								
					PROC. REF: AMM 28-21-33-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-21-33-960-801-02	DISCARD OF THE FUEL SUPPLY HOSES - ENGINE 1 FUEL SUPPLY HOSE (L901QD)								Service	ATA:28
PN:663106882001	MOS/MSC	10-Dec-03	O/C	TAC 0						
SN:DF 09 2003	HRS	4936.4								
WC#: 28.530	AFL	3069								
					PROC. REF: AMM 28-21-33-960-801					
28-21-33-960-801-03	DISCARD OF THE FUEL SUPPLY HOSES - ENGINE 2 FUEL SUPPLY HOSE (M901QD)								Service	ATA:28
PN:665054EE2004	MOS/MSC	10-Dec-03	O/C	TAC 0						
SN:MF-50	HRS	4936.4								
WC#: 28.535	AFL	3069								
					PROC. REF: AMM 28-21-33-960-801					
28-21-33-960-801-04	DISCARD OF THE FUEL SUPPLY HOSES - ENGINE 3 FUEL SUPPLY HOSE (R901QD)								Service	ATA:28
PN:665106882001	MOS/MSC	10-Dec-03	O/C	TAC 0						
SN:MF-50	HRS	4936.4								
WC#: 28.530	AFL	3069								
					PROC. REF: AMM 28-21-33-960-801					
28-21-41-900-801-01	REMOVAL / INSTALLATION OF THE LP INTERCONNECTION VALVE ACTUATOR - BP 1 MANIFOLD TRANSFER VALVE ACTUATOR (13Q1)								Component	ATA:28
PN:D97C00-215	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.310	AFL	0								
					PROC. REF: AMM 28-21-41-900-801					
28-21-41-900-801-02	REMOVAL / INSTALLATION OF THE LP INTERCONNECTION VALVE ACTUATOR - BP 3 MANIFOLD TRANSFER VALVE ACTUATOR (13Q2)								Component	ATA:28
PN:D97C00-215	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.310	AFL	0								
					PROC. REF: AMM 28-21-41-900-801					
28-21-49-900-801-01	REMOVAL / INSTALLATION OF THE UPPER SUPPORT OF BOOSTER PUMP CANISTER								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-21-49-900-801					
28-22-00-650-801-01	QUICK TRANSFER OF FUEL BETWEEN TANK GROUPS								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-22-00-650-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-22-00-700-801-01	CHECK OF THE TRANSFER REGULATING LEVEL IN FEEDER TANKS									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-22-00-700-801					
28-22-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY FUEL TRANSFER CONTROL									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-22-00-710-801, AMM 28-22-00-710-801					
28-22-05-350-801-01	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF MOTOR BRUSHES) - LH TRANSFER PUMP (23Q1)									Service ATA:28
PN:2060A12	MOS	02-Mar-23								
SN:1817	HRS	8929.3	2000 (+3%)		10929.3	10989.3	1937.2 (+60)			
WC#: 28.270	AFL	5742								
					PROC. REF: AMM 28-22-05-350-801					
28-22-05-350-801-02	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF MOTOR BRUSHES) - CENTER TRANSFER PUMP (23Q2)									Service ATA:28
PN:2060A01	MOS	14-Jul-15								
SN:1580	HRS	8226.6	2000 (+3%)		10226.6	10286.6	1234.5 (+60)			
WC#: 28.280	AFL	5321								
					PROC. REF: AMM 28-22-05-350-801					
28-22-05-350-801-03	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF MOTOR BRUSHES) - RH TRANSFER PUMP (23Q3)									Service ATA:28
PN:2060A01	MOS	14-Jul-15								
SN:734	HRS	8226.6	2000 (+3%)		10226.6	10286.6	1234.5 (+60)			
WC#: 28.290	AFL	5321								
					PROC. REF: AMM 28-22-05-350-801					
28-22-05-350-802-01	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF BEARINGS) - LH TRANSFER PUMP (23Q1)									Service ATA:28
PN:2060A12	MOS	02-Mar-23								
SN:1817	HRS	8929.3	2000 (+3%)		10929.3	10989.3	1937.2 (+60)			
WC#: 28.270	AFL	5742								
					PROC. REF: AMM 28-22-05-350-802					
28-22-05-350-802-02	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF BEARINGS) - CENTER TRANSFER PUMP (23Q2)									Service ATA:28
PN:2060A01	MOS	14-Jul-15								
SN:1580	HRS	8226.6	2000 (+3%)		10226.6	10286.6	1234.5 (+60)			
WC#: 28.280	AFL	5321								
					PROC. REF: AMM 28-22-05-350-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-22-05-350-802-03	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF BEARINGS) - RH TRANSFER PUMP (23Q3)									Service ATA:28
PN:2060A01	MOS	14-Jul-15								
SN:734	HRS	8226.6	2000 (+3%)		10226.6	10286.6	1234.5 (+60)			
WC#: 28.290	AFL	5321								
					PROC. REF: AMM 28-22-05-350-802					
28-22-05-900-801-01	REMOVAL / INSTALLATION OF THE TRANSFER PUMPS - LH TRANSFER PUMP (23Q1)									Component ATA:28
PN:2060A12	MOS/MSC	02-Mar-23	O/C	TSO 0						
SN:1817	HRS	8929.3		TSO 0						
WC#: 28.270	AFL	5742		TSO 0						
					PROC. REF: AMM 28-22-05-900-801					
28-22-05-900-801-02	REMOVAL / INSTALLATION OF THE TRANSFER PUMPS - CENTER TRANSFER PUMP (23Q2)									Component ATA:28
PN:2060A01	MOS/MSC	14-Jul-15	O/C	TSO 0						
SN:1580	HRS	8226.6		TSO 0						
WC#: 28.280	AFL	5321		TSO 0						
					PROC. REF: AMM 28-22-05-900-801					
28-22-05-900-801-03	REMOVAL / INSTALLATION OF THE TRANSFER PUMPS - RH TRANSFER PUMP (23Q3)									Component ATA:28
PN:2060A01	MOS/MSC	14-Jul-15	O/C	TSO 0						
SN:734	HRS	8226.6		TSO 0						
WC#: 28.290	AFL	5321		TSO 0						
					PROC. REF: AMM 28-22-05-900-801					
28-22-13-220-801-01 S	INSPECTION FOR CORROSION OF THE TRANSFER VALVE BASES AND LINES FITTED WITH DRAINAGE SLEEVES									Service ATA:28
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 28.330	AFL	5651								
					PROC. REF: AMM 28-22-13-220-801					PKG:31
28-22-13-350-801-01	CORROSION REMOVAL AND RECONDITIONING OF THE TRANSFER VALVE BASES AND LINES FITTED WITH DRAINAGE SLEEVES									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-22-13-350-801					
28-22-15-350-801-01	RESTORATION OF THE TRANSFER VALVES (OVERHAUL) - LH TRANSFER VALVE (L615QS)									Service ATA:28
PN:2504-3	MOS	11-Apr-19	108 (+3%)		11-Apr-28	18-Jul-28	1623 d (+98)	OVERHAUL		
SN:1055	HRS	8648.2	4800 (+3%)		13448.2	13592.2	4456.1 (+144)			
WC#: 28.240	AFL	5560								
					PROC. REF: AMM 28-22-15-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-22-15-350-801-02	RESTORATION OF THE TRANSFER VALVES (OVERHAUL) - CENTER TRANSFER VALVE (M615QS)								Service	ATA:28
PN:2504-3	MOS	11-Apr-19	108 (+3%)		11-Apr-28	18-Jul-28	1623 d (+98)	OVERHAUL		
SN:1885	HRS	8648.2	4800 (+3%)		13448.2	13592.2	4456.1 (+144)			
WC#: 28.240	AFL	5560								
					PROC. REF: AMM 28-22-15-350-801					
28-22-15-350-801-03	RESTORATION OF THE TRANSFER VALVES (OVERHAUL) - RH TRANSFER VALVE (R615QS)								Service	ATA:28
PN:2504-3	MOS	11-Apr-19	108 (+3%)		11-Apr-28	18-Jul-28	1623 d (+98)	OVERHAUL		
SN:2033	HRS	8648.2	4800 (+3%)		13448.2	13592.2	4456.1 (+144)			
WC#: 28.240	AFL	5560								
					PROC. REF: AMM 28-22-15-350-801					
28-22-15-900-801-01	REMOVAL / INSTALLATION OF THE TRANSFER VALVES - LH TRANSFER VALVE (L615QS)								Component	ATA:28
PN:2504-3	MOS/MSC	09-Aug-22	H/T	TSO 45						
SN:1055	HRS	8823		TSO 174.8						
WC#: 28.240	AFL	5651		TSO 91						
					PROC. REF: AMM 28-22-15-900-801					
28-22-15-900-801-02	REMOVAL / INSTALLATION OF THE TRANSFER VALVES - CENTER TRANSFER VALVE (M615QS)								Component	ATA:28
PN:2504-3	MOS/MSC	11-Apr-19	H/T	TSO 3						
SN:1885	HRS	8648.2		TSO 0						
WC#: 28.240	AFL	5560		TSO 0						
					PROC. REF: AMM 28-22-15-900-801					
28-22-15-900-801-03	REMOVAL / INSTALLATION OF THE TRANSFER VALVES - RH TRANSFER VALVE (R615QS)								Component	ATA:28
PN:2504-3	MOS/MSC	09-Aug-22	H/T	TSO 42						
SN:2033	HRS	8823		TSO 174.8						
WC#: 28.240	AFL	5651		TSO 91						
					PROC. REF: AMM 28-22-15-900-801					
28-22-17-900-801-01	REMOVAL / INSTALLATION OF THE CENTER FEEDER TANK LOW LEVEL FLOAT VALVE								Component	ATA:28
PN:C21KL0014	MOS/MSC	17-Jun-10	O/C	TSN 0						
SN:2678	HRS	7336.3		TSN 0						
WC#: 28.355	AFL	4659		TSN 0						
					PROC. REF: AMM 28-22-17-900-801					
28-22-21-900-801-01	REMOVAL / INSTALLATION OF THE ISOLATION VALVES - LH ISOLATION VALVE (L17QD)								Component	ATA:28
PN:B97M31-201	MOS/MSC	24-Oct-91	O/C							
SN:20316	HRS	0		TSN 0						
WC#: 28.160	AFL	0								
					PROC. REF: AMM 28-22-21-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-22-21-900-801-02	REMOVAL / INSTALLATION OF THE ISOLATION VALVES - CENTER ISOLATION VALVE (M17QD)									Component ATA:28
PN:B97M31-201	MOS/MSC	24-Oct-91	O/C							
SN:20318	HRS	0		TSN 0						
WC#: 28.160	AFL	0								
					PROC. REF: AMM 28-22-21-900-801					
28-22-21-900-801-03	REMOVAL / INSTALLATION OF THE ISOLATION VALVES - RH ISOLATION VALVE (R17QD)									Component ATA:28
PN:B97M31-201	MOS/MSC	24-Oct-91	O/C							
SN:20319	HRS	0		TSN 0						
WC#: 28.160	AFL	0								
					PROC. REF: AMM 28-22-21-900-801					
28-22-29-900-801-01	REMOVAL / INSTALLATION OF THE TRANSFER INTERCONNECTION VALVE ACTUATOR									Component ATA:28
PN:D97C00-202	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.320	AFL	0								
					PROC. REF: AMM 28-22-29-900-801					
28-22-29-900-801-02	RIGHT TRANSFER INTERCONNECTION VALVE ACTUATOR									Component ATA:28
PN:D97C00-202	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.320	AFL	0								
					PROC. REF: AMM 28-22-29-900-801					
28-22-31-900-801-01	REMOVAL/INSTALLATION OF THE HI/LO VALVES - LH HI/LO VALVE (64Q1)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-22-31-900-801					
28-22-31-900-801-02	REMOVAL/INSTALLATION OF THE HI/LO VALVES - CENTER HI/LO VALVE (65Q)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-22-31-900-801					
28-22-31-900-801-03	REMOVAL/INSTALLATION OF THE HI/LO VALVES - RH HI/LO VALVE (64Q2)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-22-31-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-30-00-650-801-01	SUCTION DEFUELING									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-00-650-801					
28-30-00-680-801-01	GRAVITY DEFUELING									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-00-680-801					
28-30-00-680-802-01	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE LH TANK GROUP									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-00-680-802					
28-30-00-680-802-02	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE CENTER TANK GROUP									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-00-680-802					
28-30-00-680-802-03	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE RH TANK GROUP									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-00-680-802					
28-30-00-680-802-05	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - LEAK CHECK OF THE DRY BAY									Service ATA:28
	MOS	08-Sep-23	2 (+5d)		08-Nov-23	13-Nov-23	7 d (+5)			
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 28-30-00-680-802					
28-30-00-680-802-06	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - FUEL SAMPLING									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-00-680-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-30-00-680-804-01	DRAINING WATER FROM THE FUEL TANKS									Service ATA:28
	MOS	08-Sep-23	2 (+5d)		08-Nov-23	13-Nov-23	7 d (+5)			
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 28-30-00-680-804					
28-30-11-900-801-01	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - LH WING TANK SUMP DRAIN VALVE (L10QV)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					
28-30-11-900-801-02	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH WING TANK SUMP DRAIN VALVE (R10QV)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					
28-30-11-900-801-03	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - CENTER-WING TANK FRONT SUMP DRAIN VALVE (M10QV)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					
28-30-11-900-801-04	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - CENTER-WING TANK MIDDLE SUMP DRAIN VALVE (M12QV)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					
28-30-11-900-801-05	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - CENTER-WING TANK REAR SUMP DRAIN VALVE (M14QV)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					
28-30-11-900-801-06	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - LH FEEDER TANK DOOR SUMP DRAIN VALVE (L20QV)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-30-11-900-801-07	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH FEEDER TANK DOOR SUMP DRAIN VALVE (R20QV)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					
28-30-11-900-801-08	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - LH FEEDER TANK SUMP DRAIN VALVE (L30QV)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					
28-30-11-900-801-09	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - CENTER FEEDER TANK SUMP DRAIN VALVE (M30QV)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					
28-30-11-900-801-10	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH FEEDER TANK SUMP DRAIN VALVE (R30QV)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					
28-30-11-960-801-01	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - LH WING TANK SUMP DRAIN VALVE (L10QV)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-11-960-801					
28-30-11-960-801-02	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - RH WING TANK SUMP DRAIN VALVE (R10QV)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-11-960-801					
28-30-11-960-801-03	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - CENTER-WING TANK FRONT SUMP DRAIN VALVE (M10QV)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-11-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-30-11-960-801-04	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - CENTER-WING TANK MIDDLE SUMP DRAIN VALVE (M12QV)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-11-960-801					
28-30-11-960-801-05	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - CENTER-WING TANK REAR SUMP DRAIN VALVE (M14QV)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-11-960-801					
28-30-11-960-801-06	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - LH FEEDER TANK DOOR SUMP DRAIN VALVE (L20QV)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-11-960-801					
28-30-11-960-801-07	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - RH FEEDER TANK DOOR SUMP DRAIN VALVE (R20QV)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-11-960-801					
28-30-11-960-801-08	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - LH FEEDER TANK SUMP DRAIN VALVE (L30QV)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-11-960-801					
28-30-11-960-801-09	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - CENTER FEEDER TANK SUMP DRAIN VALVE (M30QV)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-11-960-801					
28-30-11-960-801-10	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - RH FEEDER TANK SUMP DRAIN VALVE (R30QV)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-11-960-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-30-11-960-802-01	DISCARD OF THE FUEL DRAIN CAPS									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-30-11-960-802					
28-41-00-700-801-01	CHECK / ADJUSTMENT OF THE FUEL QUANTITY INDICATING SYSTEM									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-41-00-700-801					
28-41-00-700-802-01	CHECK / ADJUSTMENT OF THE FUEL QUANTITY INDICATING SYSTEM USING TEST SET - LH TANK GROUP									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-41-00-700-802					
28-41-00-700-802-02	CHECK / ADJUSTMENT OF THE FUEL QUANTITY INDICATING SYSTEM USING TEST SET - CENTER TANK GROUP									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-41-00-700-802					
28-41-00-700-802-03	CHECK / ADJUSTMENT OF THE FUEL QUANTITY INDICATING SYSTEM USING TEST SET - RH TANK GROUP									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-41-00-700-802					
28-41-00-720-802-01[S]	FUNCTIONAL TEST OF THE FEEDER TANK LOW LEVEL INDICATING SYSTEM									Service ATA:28
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 28.810	AFL	5775								
					PROC. REF: AMM 28-41-00-720-802					PKG:15
28-41-05-900-801-01	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - LH FEEDER TANK GAUGE (47E1)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-41-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-41-05-900-801-02	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - RH FEEDER TANK GAUGE (47E2)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-41-05-900-801					
28-41-05-900-801-03	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - CENTER WING TANK FRONT GAUGE (64E)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-41-05-900-801					
28-41-05-900-801-04	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - CENTER WING TANK REAR GAUGE (65E)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-41-05-900-801					
28-41-05-900-801-05	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - CENTER FEEDER TANK GAUGE (66E)									Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-41-05-900-801					
28-41-09-900-801-01	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING INBOARD TANK GAUGE (44E1)									Component ATA:28
PN:792-366-1	MOS/MSC	24-Oct-91	O/C							
SN:799	HRS	0		TSN 0						
WC#: 28.710	AFL	0								
					PROC. REF: AMM 28-41-09-900-801					
28-41-09-900-801-02	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING INBOARD TANK GAUGE (44E2)									Component ATA:28
PN:792-366-1	MOS/MSC	24-Oct-91	O/C							
SN:808	HRS	0		TSN 0						
WC#: 28.720	AFL	0								
					PROC. REF: AMM 28-41-09-900-801					
28-41-09-900-801-03	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING CENTER TANK GAUGE (45E1)									Component ATA:28
PN:792-367-2	MOS/MSC	24-Oct-91	O/C							
SN:895	HRS	0		TSN 0						
WC#: 28.710	AFL	0								
					PROC. REF: AMM 28-41-09-900-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-41-09-900-801-04	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING CENTER TANK GAUGE (45E2)									Component ATA:28
PN:792-367-2	MOS/MSC	24-Oct-91	O/C							
SN:884	HRS	0		TSN 0						
WC#: 28.720	AFL	0								
					PROC. REF: AMM 28-41-09-900-801					
28-41-09-900-801-05	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING OUTBOARD TANK GAUGE (46E1)									Component ATA:28
PN:792-368-2	MOS/MSC	24-Oct-91	O/C							
SN:870	HRS	0		TSN 0						
WC#: 28.710	AFL	0								
					PROC. REF: AMM 28-41-09-900-801					
28-41-09-900-801-06	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING OUTBOARD TANK GAUGE (46E2)									Component ATA:28
PN:792-368-2	MOS/MSC	24-Oct-91	O/C							
SN:879	HRS	0		TSN 0						
WC#: 28.720	AFL	0								
					PROC. REF: AMM 28-41-09-900-801					
28-41-13-900-801-01	REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - LH TANK GROUP FUEL QUANTITY INDICATOR (43E1)									Component ATA:28
PN:716686	MOS/MSC	24-Oct-91	O/C							
SN:680	HRS	0		TSN 0						
WC#: 28.750	AFL	0								
					PROC. REF: AMM 28-41-13-900-801					
28-41-13-900-801-02	REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - CENTER TANK GROUP FUEL QUANTITY INDICATOR (63E)									Component ATA:28
PN:716687	MOS/MSC	07-Dec-98	O/C							
SN:UNKNOWN	HRS	2995								
WC#: 28.750	AFL	2071								
					PROC. REF: AMM 28-41-13-900-801					
28-41-13-900-801-03	REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - RH TANK GROUP FUEL QUANTITY INDICATOR (43E2)									Component ATA:28
PN:716686	MOS/MSC	24-Oct-91	O/C							
SN:465	HRS	0		TSN 0						
WC#: 28.750	AFL	0								
					PROC. REF: AMM 28-41-13-900-801					
28-43-01-720-801-01	FUNCTIONAL TEST OF THE FUEL TEMPERATURE SENSOR - FUEL TEMPERATURE PROBE (51E)									Service ATA:28
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 28.840	AFL	0								
					PROC. REF: AMM 28-43-01-720-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-43-05-900-801-01	REMOVAL/INSTALLATION OF FUEL TEMPERATURE INDICATOR - FUEL TEMPERATURE INDICATOR (52E)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.800	AFL	0		TSN 0						
					PROC. REF: AMM 28-43-05-900-801					
28-50-00-650-801-01	PRESSURE REFUELING								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-50-00-650-801					
28-50-00-650-802-01	GRAVITY REFUELING								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-50-00-650-802					
28-50-00-700-801-01	INTEGRITY AND LEAK CHECK OF REFUELING CONNECTOR SEALING VALVE AND LEAK CHECK OF ISOLATION CHECK VALVES - INTEGRITY / LEAK CHECK OF REFUELING CONNECTOR TIGHTNESS VALVE								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-50-00-700-801					
28-50-00-700-801-02[S]	INTEGRITY AND LEAK CHECK OF REFUELING CONNECTOR SEALING VALVE AND LEAK CHECK OF ISOLATION CHECK VALVES - TIGHTNESS CHECK OF REFUELING SYSTEM/TRANSFER SYSTEM ISOLATION CHECK VALVES								Service	ATA:28
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 28.465	AFL	5347								
					PROC. REF: AMM 28-50-00-700-801					PKG:32
28-50-27-900-801-01	REMOVAL / INSTALLATION OF THE FUEL TEST VALVE PROXIMITY SENSOR - TEST VALVE PROXIMITY SWITCH (67Q)								Component	ATA:28
PN:8-240-02	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.790	AFL	0								
					PROC. REF: AMM 28-50-27-900-801					
28-70-00-720-801-01[S]	FUNCTIONAL TEST OF THE PRESSURIZATION SYSTEM								Service	ATA:28
	MOS	10-Dec-03								
	HRS	4936.4	6000 (+30)							
WC#: 28.450	AFL	3069								
					PROC. REF: AMM 28-70-00-720-801					PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-70-00-860-801-01	DE-PRESSURIZATION / PRESSURIZATION OF THE FUEL TANKS									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-70-00-860-801					
28-70-09-350-801-01	RESTORATION OF THE VALVE BOXES (OVERHAUL) - LH VALVE BOX (L200QP)									Service ATA:28
PN:2415-1010	MOS	07-Sep-22	72 (+3%)	TAC 3	07-Jun-28	11-Aug-28	1680 d (+65)	OVERHAUL		
SN:1449	HRS	8823	1600 (+3%)	TAC 0	10423	10471	1430.9 (+48)			
WC#: 28.440	AFL	5651		TAC 0						
					PROC. REF: AMM 28-70-09-350-801					
28-70-09-350-801-02	RESTORATION OF THE VALVE BOXES (OVERHAUL) - RH VALVE BOX (R200QP)									Service ATA:28
PN:2415-1010	MOS	07-Sep-22	72 (+3%)	TAC 3	07-Jun-28	11-Aug-28	1680 d (+65)	OVERHAUL		
SN:1522	HRS	8823	1600 (+3%)	TAC 0	10423	10471	1430.9 (+48)			
WC#: 28.440	AFL	5651		TAC 0						
					PROC. REF: AMM 28-70-09-350-801					
28-70-09-710-801-01	OPERATIONAL TEST OF THE VALVE BOX PRESSURE RELIEF VALVE - LH VALVE BOX (L200QP)									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-70-09-710-801					
28-70-09-710-801-02	OPERATIONAL TEST OF THE VALVE BOX PRESSURE RELIEF VALVE - RH VALVE BOX (R200QP)									Service ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-70-09-710-801					
28-70-13-350-801-01	RESTORATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST) - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L100QP)									Service ATA:28
PN:B06GA1051	MOS/MSC		O/C							
SN:881	HRS	EFF								
	AFL									
					PROC. REF: AMM 28-70-13-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-70-13-350-801-02	RESTORATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST) - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R100QP)								Service	ATA:28
PN:B06GA1050	MOS/MSC		O/C							
SN:789	HRS	EFF								
	AFL									
					PROC. REF: AMM 28-70-13-350-801					
28-70-13-720-802-01	FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L100QP)								Service	ATA:28
PN:B06GA1051	MOS	18-Jul-03								
SN:881	HRS	4798	5000 (+3%)		9798	9948	805.9 (+150)			
	AFL	3007								
					PROC. REF: AMM 28-70-13-720-802					
28-70-13-720-802-02	FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R100QP)								Service	ATA:28
PN:B06GA1050	MOS	18-Jul-03								
SN:789	HRS	4798	5000 (+3%)		9798	9948	805.9 (+150)			
	AFL	3007								
					PROC. REF: AMM 28-70-13-720-802					
28-70-13-900-801-01	REMOVAL / INSTALLATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L100QP)								Component	ATA:28
PN:B06GA1051	MOS/MSC	18-Jul-03	O/C	TSR 0						
SN:881	HRS	4798		TSR 0						
WC#: 28.420	AFL	3007		TSR 0						
					PROC. REF: AMM 28-70-13-900-801					
28-70-13-900-801-02	REMOVAL / INSTALLATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R100QP)								Component	ATA:28
PN:B06GA1050	MOS/MSC	24-Oct-91	O/C							
SN:789	HRS	0		TSN 0						
WC#: 28.420	AFL	0								
					PROC. REF: AMM 28-70-13-900-801					
28-70-17-130-801-01[S]	CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS - ENGINE 1 PRESSURIZATION AIR FILTER (L206QP)								Service	ATA:28
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 28.680	AFL	5651								
					PROC. REF: AMM 28-70-17-130-801					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-70-17-130-801-02[S]	CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS - ENGINE 2 PRESSURIZATION AIR FILTER (R206QP)								Service	ATA:28
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 28.680	AFL	5651								
					PROC. REF: AMM 28-70-17-130-801					PKG:21
28-70-21-860-801-01	OPENING / CLOSING OF THE VENT VALVES - LH WING/CENTER TANKS VENT VALVE (53Q1)								Service	ATA:28
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 28-70-21-860-801					
28-70-21-900-801-01	REMOVAL / INSTALLATION OF THE VENT VALVES - LH WING/CENTER TANKS VENT VALVE (53Q1)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-70-21-900-801					
28-70-22-900-801-01	REMOVAL / INSTALLATION OF THE VENT VALVE ELECTRIC ACTUATORS - LH WING/CENTER TANKS VENT VALVE ACTUATOR (53Q11)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-70-22-900-801					
28-70-22-900-801-02	REMOVAL / INSTALLATION OF THE VENT VALVE ELECTRIC ACTUATORS - RH WING/CENTER TANKS VENT VALVE ACTUATOR (53Q21)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-70-22-900-801					
28-70-22-900-801-03	REMOVAL / INSTALLATION OF THE VENT VALVE ELECTRIC ACTUATORS - FEEDER TANKS VENT VALVE ACTUATOR (54Q1)								Component	ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 28-70-22-900-801					
28-70-41-710-801-01[S]	OPERATIONAL TEST OF THE FEEDER TANK PRESSURE RELIEF VALVES - LH FEEDER TANK PRESSURE RELIEF VALVE (L300QP)								Service	ATA:28
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 28.410	AFL	5651								
					PROC. REF: AMM 28-70-41-710-801					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-70-41-710-801-02[S]	OPERATIONAL TEST OF THE FEEDER TANK PRESSURE RELIEF VALVES - RH FEEDER TANK PRESSURE RELIEF VALVE (R300QP)								Service	ATA:28
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 28.410	AFL	5651								
					PROC. REF: AMM 28-70-41-710-801					PKG:21
28-70-41-900-801-01	REMOVAL / INSTALLATION OF THE FEEDER TANK PRESSURE-RELIEF VALVES - LH FEEDER TANK PRESSURE RELIEF VALVE (L300QP)								Component	ATA:28
PN:1551-1000	MOS/MSC	24-Oct-91	O/C							
SN:2168	HRS	0		TSN 0						
WC#: 28.410	AFL	0								
					PROC. REF: AMM 28-70-41-900-801					
28-70-41-900-801-02	REMOVAL / INSTALLATION OF THE FEEDER TANK PRESSURE-RELIEF VALVES - RH FEEDER TANK PRESSURE RELIEF VALVE (R300QP)								Component	ATA:28
PN:1551-1000	MOS/MSC	24-Oct-91	O/C							
SN:2182	HRS	0		TSN 0						
WC#: 28.410	AFL	0								
					PROC. REF: AMM 28-70-41-900-801					
280111	LH WING DRAIN VALVE								Component	ATA:28
PN:142D12-1	MOS/MSC	25-Aug-06	O/C							
SN:B79296	HRS	5991.5								
WC#: 28.020	AFL	3649								
					PROC. REF: AMM 28-30-11-900-801					
280116	RH WING DRAIN VALVE								Component	ATA:28
PN:142D12-11	MOS/MSC	24-Oct-91	O/C							
SN:1026	HRS	0		TSN 0						
WC#: 28.020	AFL	0								
					PROC. REF: AMM 28-30-11-900-801					
280121	FORWARD CENTER WING DRAIN VALVE								Component	ATA:28
PN:142G12-42	MOS/MSC	25-Aug-06	O/C							
SN:C07439	HRS	5991.5								
WC#: 28.030	AFL	3649								
					PROC. REF: AMM 28-30-11-900-801					
280126	MIDDLE CENTER WING DRAIN VALVE								Component	ATA:28
PN:142G12-42	MOS/MSC	23-Aug-23	O/C	TSN 0						
SN:M78439	HRS	8966.7		TSN 0						
WC#: 28.030	AFL	5774		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
280131		REAR CENTER WING DRAIN VALVE								Component ATA:28
PN:142G12-42	MOS/MSC	07-Mar-16	O/C							
SN:H20879	HRS	8278.1								
WC#: 28.030	AFL	5347								
					PROC. REF: AMM 28-30-11-900-801					
280136		LH FEEDER TANK DRAIN VALVE								Component ATA:28
PN:142G12-43	MOS/MSC	24-Oct-91	O/C							
SN:1441	HRS	0		TSN 0						
WC#: 28.040	AFL	0								
					PROC. REF: AMM 28-30-11-900-801					
280141		CENTER FEEDER TANK DRAIN VALVE								Component ATA:28
PN:142G12-43	MOS/MSC	14-Jun-97	O/C	TSN 0						
SN:1776	HRS	2441		TSN 0						
WC#: 28.040	AFL	1708		TSN 0						
					PROC. REF: AMM 28-30-11-900-801					
280146		RH FEEDER TANK DRAIN VALVE								Component ATA:28
PN:142G12-43	MOS/MSC	24-Oct-91	O/C							
SN:1442	HRS	0		TSN 0						
WC#: 28.040	AFL	0								
					PROC. REF: AMM 28-30-11-900-801					
280156		LH DOOR FEEDER TANK DRAIN VALVE								Component ATA:28
PN:142G12-43	MOS/MSC	24-Oct-91	O/C							
SN:1443	HRS	0								
WC#: 28.045	AFL	0								
					PROC. REF: GENERIC NO REF					
280161		RH DOOR FEEDER TANK DRAIN VALVE								Component ATA:28
PN:142G12-43	MOS/MSC	24-Oct-91	O/C							
SN:1444	HRS	0								
WC#: 28.045	AFL	0								
					PROC. REF: GENERIC NO REF					
281101		LH FILLER PLUG								Component ATA:28
PN:431-1251	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.060	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281103		CENTER TRANSFER PUMP PRIMING CHECK VALVE								Component ATA:28
PN:L85Z13-201	MOS/MSC	24-Oct-91	O/C							
SN:20951	HRS	0		TSN 0						
WC#: 28.110	AFL	0								
					PROC. REF: GENERIC NO REF					
281106		RH FILLER PLUG								Component ATA:28
PN:431-1251	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.060	AFL	0								
					PROC. REF: GENERIC NO REF					
281108		RH TEST SYSTEM CHECK VALVE								Component ATA:28
PN:L85Z13-201	MOS/MSC	24-Oct-91	O/C							
SN:20954	HRS	0		TSN 0						
WC#: 28.120	AFL	0								
					PROC. REF: GENERIC NO REF					
281111		LH STRAINER								Component ATA:28
PN:431-51-2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.100	AFL	0								
					PROC. REF: GENERIC NO REF					
281113		NO. 1 SYSTEM CENTER FEEDER TANK TEST CHECK VALVE								Component ATA:28
PN:L85Z13-201	MOS/MSC	24-Oct-91	O/C							
SN:20952	HRS	0		TSN 0						
WC#: 28.130	AFL	0								
					PROC. REF: GENERIC NO REF					
281116		RIGHT STRAINER								Component ATA:28
PN:431-51-2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.100	AFL	0								
					PROC. REF: GENERIC NO REF					
281118		NO. 2 SYSTEM CENTER FEEDER TANK TEST CHECK VALVE								Component ATA:28
PN:L85Z13-201	MOS/MSC	24-Oct-91	O/C							
SN:20948	HRS	0		TSN 0						
WC#: 28.130	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281121		LH JET PUMP BOOSTER SYSTEM CHECK VALVE								Component ATA:28
PN:L96Z19-203	MOS/MSC	24-Oct-91	O/C							
SN:20486	HRS	0		TSN 0						
WC#: 28.140	AFL	0								
					PROC. REF: GENERIC NO REF					
281126		RH JET PUMP BOOSTER SYSTEM CHECK VALVE								Component ATA:28
PN:L96Z19-203	MOS/MSC	24-Oct-91	O/C							
SN:20493	HRS	0		TSN 0						
WC#: 28.140	AFL	0								
					PROC. REF: GENERIC NO REF					
281131		LH TRANSFER JET PUMP FILTER								Component ATA:28
PN:30819-1	MOS/MSC	24-Oct-91	O/C							
SN:1350	HRS	0		TSN 0						
WC#: 28.150	AFL	0								
					PROC. REF: GENERIC NO REF					
281141		RH TRANSFER JET PUMP FILTER								Component ATA:28
PN:30819-1	MOS/MSC	24-Oct-91	O/C							
SN:1387	HRS	0		TSN 0						
WC#: 28.150	AFL	0								
					PROC. REF: GENERIC NO REF					
281166		PRESSURE REFUELING UNIT								Component ATA:28
PN:K97-63-206	MOS/MSC	24-Oct-91	O/C							
SN:20438	HRS	0		TSN 0						
WC#: 28.080	AFL	0								
					PROC. REF: GENERIC NO REF					
281176		NO. 1 FILLER VALVE								Component ATA:28
PN:L94Z31-201	MOS/MSC	24-Oct-91	O/C							
SN:21148	HRS	0		TSN 0						
WC#: 28.070	AFL	0								
					PROC. REF: GENERIC NO REF					
281181		NO. 2 FILLER VALVE								Component ATA:28
PN:L94Z31-201	MOS/MSC	24-Oct-91	O/C							
SN:21150	HRS	0		TSN 0						
WC#: 28.070	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281186		NO. 3 FILLER VALVE								Component ATA:28
PN:L94Z31-201	MOS/MSC	07-Mar-16	O/C	TSR 7						
SN:21481	HRS	8278.1		TSR 0						
WC#: 28.070	AFL	5347		TSR 0						
					PROC. REF: GENERIC NO REF					
281191		LH TRANSFER PUMP CHECK VALVE								Component ATA:28
PN:L96Z31-201	MOS/MSC	24-Oct-91	O/C							
SN:21355	HRS	0		TSN 0						
WC#: 28.170	AFL	0								
					PROC. REF: GENERIC NO REF					
281196		MIDDLE TRANSFER PUMP CHECK VALVE								Component ATA:28
PN:L96Z31-201	MOS/MSC	24-Oct-91	O/C							
SN:21370	HRS	0		TSN 0						
WC#: 28.170	AFL	0								
					PROC. REF: GENERIC NO REF					
281201		RH TRANSFER PUMP CHECK VALVE								Component ATA:28
PN:L96Z31-201	MOS/MSC	24-Oct-91	O/C							
SN:21371	HRS	0		TSN 0						
WC#: 28.170	AFL	0								
					PROC. REF: GENERIC NO REF					
281206		FILLING CIRCUIT TRANSFER CHECK VALVE								Component ATA:28
PN:L96Z31-201	MOS/MSC	24-Oct-91	O/C							
SN:21372	HRS	0		TSN 0						
WC#: 28.180	AFL	0								
					PROC. REF: GENERIC NO REF					
281211		FILLER BLOCK								Component ATA:28
PN:K99Z31-001	MOS/MSC	24-Oct-91	O/C							
SN:20234	HRS	0		TSN 0						
WC#: 28.090	AFL	0								
					PROC. REF: GENERIC NO REF					
281216		FEEDER TANK AIR VENT VALVE								Component ATA:28
PN:B97J38-251	MOS/MSC	24-Oct-91	O/C							
SN:20109	HRS	0		TSN 0						
WC#: 28.190	AFL	0								
					PROC. REF: AMM 28-70-21-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281221		LH CENTER SECTION AIR VENT DRAINING BALL VALVE								Component ATA:28
PN:L87D06-001	MOS/MSC	24-Oct-91	O/C							
SN:20494	HRS	0		TSN 0						
WC#: 28.200	AFL	0								
					PROC. REF: GENERIC NO REF					
281226		RH CENTER SECTION AIR VENT DRAINING BALL VALVE								Component ATA:28
PN:L87D06-001	MOS/MSC	24-Oct-91	O/C							
SN:20495	HRS	0		TSN 0						
WC#: 28.200	AFL	0								
					PROC. REF: GENERIC NO REF					
281231		LH WING AIR VENT VALVE								Component ATA:28
PN:B97L38-251	MOS/MSC	24-Oct-91	O/C							
SN:20088	HRS	0		TSN 0						
WC#: 28.190	AFL	0								
					PROC. REF: GENERIC NO REF					
281236		RH WING AIR VENT VALVE								Component ATA:28
PN:B97L38-252	MOS/MSC	24-Oct-91	O/C							
SN:20114	HRS	0		TSN 0						
WC#: 28.190	AFL	0								
					PROC. REF: GENERIC NO REF					
281241		LH WING FUELLING FLOAT SWITCH								Component ATA:28
PN:005-906-001	MOS/MSC	24-Oct-91	O/C							
SN:1395	HRS	0		TSN 0						
WC#: 28.210	AFL	0								
					PROC. REF: GENERIC NO REF					
281246		RH WING FUELLING FLOAT SWITCH								Component ATA:28
PN:005-906-001	MOS/MSC	24-Oct-91	O/C							
SN:1397	HRS	0		TSN 0						
WC#: 28.220	AFL	0								
					PROC. REF: GENERIC NO REF					
281251		LH CENTER SECTION OVERFULL FLOAT SWITCH								Component ATA:28
PN:005-906-001	MOS/MSC	24-Oct-91	O/C							
SN:1407	HRS	0		TSN 0						
WC#: 28.210	AFL	0								
					PROC. REF: GENERIC NO REF					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281256		RH CENTER SECTION OVERFULL FLOAT SWITCH								Component ATA:28
PN:005-906-001	MOS/MSC	24-Oct-91	O/C							
SN:1374	HRS	0		TSN 0						
WC#: 28.220	AFL	0								
					PROC. REF: GENERIC NO REF					
281261		FEEDER TANK OVERFULL FLOAT SWITCH								Component ATA:28
PN:005-906-001	MOS/MSC	24-Oct-91	O/C							
SN:1388	HRS	0		TSN 0						
WC#: 28.230	AFL	0								
					PROC. REF: GENERIC NO REF					
281266		LH CENTER SECTION FUELLING FLOAT SWITCH								Component ATA:28
PN:005-909-001	MOS/MSC	24-Oct-91	O/C							
SN:01259	HRS	0		TSN 0						
WC#: 28.210	AFL	0								
					PROC. REF: GENERIC NO REF					
281271		RH CENTER SECTION FUELLING FLOAT SWITCH								Component ATA:28
PN:005-909-001	MOS/MSC	24-Oct-91	O/C							
SN:1267	HRS	0		TSN 0						
WC#: 28.220	AFL	0								
					PROC. REF: GENERIC NO REF					
281273		LATERAL TANK LOADING PRINTED CARD								Component ATA:28
PN:CI822A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.250	AFL	0								
					PROC. REF: GENERIC NO REF					
281275		CENTER TANK LOADING PRINTED CARD								Component ATA:28
PN:CI845A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.250	AFL	0								
					PROC. REF: GENERIC NO REF					
281276		TRANSFER UNIT								Component ATA:28
PN:L88A31-205	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.260	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281353		TRANSFER MANIFOLD REFUELING VALVE								Component ATA:28
PN:B97-31-251	MOS/MSC	24-Oct-91	O/C							
SN:20086	HRS	0		TSN 0						
WC#: 28.300	AFL	0								
					PROC. REF: GENERIC NO REF					
281391		LH TANK LEVEL SOLENOID VALVE								Component ATA:28
PN:C41BP0042	MOS/MSC	24-Oct-91	O/C							
SN:834	HRS	0		TSN 0						
WC#: 28.340	AFL	0								
					PROC. REF: GENERIC NO REF					
281396		MIDDLE TANK LEVEL SOLENOID VALVE								Component ATA:28
PN:C41BP0042	MOS/MSC	24-Oct-91	O/C							
SN:835	HRS	0		TSN 0						
WC#: 28.340	AFL	0								
					PROC. REF: GENERIC NO REF					
281401		RH TANK LEVEL SOLENOID VALVE								Component ATA:28
PN:C41BP0042	MOS/MSC	24-Oct-91	O/C							
SN:837	HRS	0		TSN 0						
WC#: 28.340	AFL	0								
					PROC. REF: GENERIC NO REF					
281406		LH TANK HIGH LEVEL FLOAT VALVE								Component ATA:28
PN:C21KL0014	MOS/MSC	24-Oct-91	O/C							
SN:1895	HRS	0		TSN 0						
WC#: 28.350	AFL	0								
					PROC. REF: GENERIC NO REF					
281411		LH TANK LOW LEVEL FLOAT VALVE								Component ATA:28
PN:C21KL0014	MOS/MSC	24-Oct-91	O/C							
SN:1842	HRS	0		TSN 0						
WC#: 28.360	AFL	0								
					PROC. REF: GENERIC NO REF					
281416		MIDDLE TANK HIGH LEVEL FLOAT VALVE								Component ATA:28
PN:C21KL0014	MOS/MSC	24-Oct-91	O/C							
SN:1847	HRS	0		TSN 0						
WC#: 28.350	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281426		RH TANK HIGH LEVEL FLOAT VALVE								Component ATA:28
PN:C21KL0014	MOS/MSC	24-Oct-91	O/C							
SN:1886	HRS	0		TSN 0						
WC#: 28.350	AFL	0								
					PROC. REF: GENERIC NO REF					
281431		RH TANK LOW LEVEL FLOAT VALVE								Component ATA:28
PN:C21KL0014	MOS/MSC	24-Oct-91	O/C							
SN:1891	HRS	0		TSN 0						
WC#: 28.360	AFL	0								
					PROC. REF: GENERIC NO REF					
281436		LH FEEDER TANK TRANSFER JET-PUMP								Component ATA:28
PN:C17AS0051	MOS/MSC	24-Oct-91	O/C							
SN:230	HRS	0		TSN 0						
WC#: 28.370	AFL	0								
					PROC. REF: GENERIC NO REF					
281441		RH FEEDER TANK TRANSFER JET-PUMP								Component ATA:28
PN:C17AS0061	MOS/MSC	24-Oct-91	O/C							
SN:229	HRS	0		TSN 0						
WC#: 28.370	AFL	0								
					PROC. REF: GENERIC NO REF					
281466		WING TANK PRESSURIZATION REAR NON RETURN VALVE								Component ATA:28
PN:L96Z19-003	MOS/MSC	24-Oct-91	O/C							
SN:21724	HRS	0		TSN 0						
WC#: 28.380	AFL	0								
					PROC. REF: GENERIC NO REF					
281471		FEEDER TANK PRESSURIZATION FORWARD NON RETURN VALVE								Component ATA:28
PN:L96Z19-003	MOS/MSC	24-Oct-91	O/C							
SN:21754	HRS	0		TSN 0						
WC#: 28.380	AFL	0								
					PROC. REF: GENERIC NO REF					
281476		WING TANK REAR PRESSURE REDUCER VALVE								Component ATA:28
PN:B14DE2041	MOS/MSC	24-Oct-91	O/C							
SN:396	HRS	0		TSN 0						
WC#: 28.390	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281481		FEEDER TANK FORWARD PRESSURE REDUCER VALVE								Component ATA:28
PN:B14DE2031	MOS/MSC	24-Oct-91	O/C							
SN:399	HRS	0		TSN 0						
WC#: 28.390	AFL	0								
					PROC. REF: GENERIC NO REF					
281486		TANK PRESSURIZATION AUTOMATIC DRAIN								Component ATA:28
PN:P177-526	MOS/MSC	30-Nov-98	O/C	TSN 0						
SN:UNKNOWN	HRS	2995		TSN 0						
WC#: 28.400	AFL	2071		TSN 0						
					PROC. REF: GENERIC NO REF					
281491		WING TANK PRESSURIZATION AUTOMATIC DRAIN								Component ATA:28
PN:P177-526	MOS/MSC	30-Nov-98	O/C	TSN 0						
SN:UNKNOWN	HRS	2995		TSN 0						
WC#: 28.400	AFL	2071		TSN 0						
					PROC. REF: GENERIC NO REF					
281526		LH FEEDER TANK VACUUM PRESSURE RELIEF VALVE								Component ATA:28
PN:B42LA1040	MOS/MSC	24-Oct-91	O/C							
SN:564	HRS	0		TSN 0						
WC#: 28.430	AFL	0								
					PROC. REF: AMM 28-70-41-900-801					
281531		RH FEEDER TANK VACUUM PRESSURE RELIEF VALVE								Component ATA:28
PN:B42LA1040	MOS/MSC	24-Oct-91	O/C							
SN:568	HRS	0		TSN 0						
WC#: 28.430	AFL	0								
					PROC. REF: AMM 28-70-41-900-801					
281536		LH VALVE BOX								Component ATA:28
PN:2415-1010	MOS/MSC	07-Sep-22	H/T	TSO 3						
SN:1449	HRS	8823		TSO 0						
WC#: 28.440	AFL	5651		TSO 0						
					PROC. REF: GENERIC NO REF					
281541		RH VALVE BOX								Component ATA:28
PN:2415-1010	MOS/MSC	07-Sep-22	H/T	TSO 3						
SN:1522	HRS	8823		TSO 0						
WC#: 28.440	AFL	5651		TSO 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281601		LH FEEDER TANK SOLENOID/TRANSFER VALVE HOSE								Component ATA:28
PN:71029-380A	MOS/MSC	07-Mar-16	H/T	TSN 39						
SN:78525	HRS	8278.1		TSN 0						
WC#: 28.470	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
281606		CENTER FEEDER TANK SOLENOID/TRANSFER VALVE HOSE								Component ATA:28
PN:71029-420A	MOS/MSC	07-Mar-16	H/T	TSN 27						
SN:80314	HRS	8278.1		TSN 0						
WC#: 28.475	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
281611		RH FEEDER TANK SOLENOID/TRANSFER VALVE HOSE								Component ATA:28
PN:71029-380A	MOS/MSC	07-Mar-16	H/T	TSN 39						
SN:78533	HRS	8278.1		TSN 0						
WC#: 28.470	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
281616		LH FEEDER TANK REGULATION VALVE SUPPLY HOSE								Component ATA:28
PN:71029-1020A	MOS/MSC	07-Mar-16	H/T	TSN 39						
SN:78355	HRS	8278.1		TSN 0						
WC#: 28.480	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
281621		CENTER FEEDER TANK REGULATION/TRANSFER VALVE SPLY HOSE								Component ATA:28
PN:71029-1020A	MOS/MSC	07-Mar-16	H/T	TSN 39						
SN:78356	HRS	8278.1		TSN 0						
WC#: 28.490	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
281626		CENTER FEEDER TANK REGULATION VALVE SUPPLY HOSE								Component ATA:28
PN:71029-560A	MOS/MSC	07-Mar-16	H/T	TSN 39						
SN:78213	HRS	8278.1		TSN 0						
WC#: 28.485	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
281631		RH FEEDER TANK REGULATION VALVE SUPPLY HOSE								Component ATA:28
PN:71029-450A	MOS/MSC	07-Mar-16	H/T	TSN 30						
SN:79521	HRS	8278.1		TSN 0						
WC#: 28.480	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
281636		LH FEEDER TANK HIGH LEVEL/SOLENOID VALVE HOSE								Component ATA:28
PN:71028-610A	MOS/MSC	07-Mar-16	H/T	TSN 39						
SN:78446	HRS	8278.1		TSN 0						
WC#: 28.500	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
281641		RH FEEDER TANK HIGH LEVEL/SOLENOID VALVE HOSE								Component ATA:28
PN:71028-610A	MOS/MSC	07-Mar-16	H/T	TSN 39						
SN:78449	HRS	8278.1		TSN 0						
WC#: 28.500	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
281646		LH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE								Component ATA:28
PN:71028-1290A	MOS/MSC	07-Mar-16	H/T	TSN 38						
SN:78686	HRS	8278.1		TSN 0						
WC#: 28.510	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
281651		CENTER FEEDER TANK LEVEL/VALVE SUPPLY HOSE								Component ATA:28
PN:71028-2460A	MOS/MSC	07-Mar-16	H/T	TSN 24						
SN:78716	HRS	8278.1		TSN 0						
WC#: 28.515	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
281656		RH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE								Component ATA:28
PN:71028-1290A	MOS/MSC	07-Mar-16	H/T	TSN 38						
SN:78685	HRS	8278.1		TSN 0						
WC#: 28.510	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
282011		LH FUEL FIRE SHUT-OFF VALVE								Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.570	AFL	0								
					PROC. REF: GENERIC NO REF					
282031		MIDDLE FUEL FIRE SHUT-OFF VALVE								Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.580	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282051		RH FUEL FIRE SHUT-OFF VALVE								Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.590	AFL	0								
					PROC. REF: GENERIC NO REF					
282191		LH LOW PRESSURE PUMP BELL HOUSING								Component ATA:28
PN:2061J	MOS/MSC	24-Oct-91	O/C							
SN:807	HRS	0		TSN 0						
WC#: 28.630	AFL	0								
					PROC. REF: GENERIC NO REF					
282201		CENTRAL LOW PRESSURE PUMP BELL HOUSING								Component ATA:28
PN:2061J	MOS/MSC	24-Oct-91	O/C							
SN:812	HRS	0		TSN 0						
WC#: 28.630	AFL	0								
					PROC. REF: GENERIC NO REF					
282211		RH LOW PRESSURE PUMP BELL HOUSING								Component ATA:28
PN:2061J	MOS/MSC	24-Oct-91	O/C							
SN:814	HRS	0		TSN 0						
WC#: 28.630	AFL	0								
					PROC. REF: GENERIC NO REF					
282221		NO. 1 FIRE SHUT-OFF HANDLE								Component ATA:28
PN:4161174	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.640	AFL	0								
					PROC. REF: GENERIC NO REF					
282226		NO. 2 FIRE SHUT-OFF HANDLE								Component ATA:28
PN:4161181	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.640	AFL	0								
					PROC. REF: GENERIC NO REF					
282231		NO. 3 FIRE SHUT-OFF HANDLE								Component ATA:28
PN:4161197	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.640	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
282311		NO. 1 ENGINE PRESSURIZATION AIR FILTER								Component ATA:28
PN:018500AA000NF0A	MOS/MSC	24-Oct-91	O/C							
SN:422890027	HRS	0		TSN 0						
WC#: 28.680	AFL	0								
					PROC. REF: GENERIC NO REF					
282321		NO. 2 ENGINE PRESSURIZATION AIR FILTER								Component ATA:28
PN:018500AA000NF0A	MOS/MSC	24-Oct-91	O/C							
SN:558250003	HRS	0		TSN 0						
WC#: 28.680	AFL	0								
					PROC. REF: GENERIC NO REF					
282601		LH FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE								Component ATA:28
PN:71030-496A	MOS/MSC	07-Mar-16	H/T	TSN 36						
SN:78595	HRS	8278.1		TSN 0						
WC#: 28.520	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
282606		CENTER FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE								Component ATA:28
PN:71030-676A	MOS/MSC	07-Mar-16	H/T	TSN 30						
SN:79133	HRS	8278.1		TSN 0						
WC#: 28.525	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
282611		RH FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE								Component ATA:28
PN:71030-496A	MOS/MSC	07-Mar-16	H/T	TSN 36						
SN:78596	HRS	8278.1		TSN 0						
WC#: 28.520	AFL	5347		TSN 0						
					PROC. REF: AMM 28-20-00-900-801					
284101		LH LOW TRANSFER PRESSURE SWITCH								Component ATA:28
PN:1G344	MOS/MSC	07-Aug-20	O/C							
SN:100	HRS	8690.7								
WC#: 28.690	AFL	5593								
					PROC. REF: GENERIC NO REF					
284106		CENTER LOW TRANSFER PRESSURE SWITCH								Component ATA:28
PN:1G344-1	MOS/MSC	05-May-98	O/C	TSN 0						
SN:671	HRS	2753		TSN 0						
WC#: 28.690	AFL	1927		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284111		RH LOW TRANSFER PRESSURE SWITCH								Component ATA:28
PN:1G344-1	MOS/MSC	30-Jun-06	O/C	TSN 0						
SN:1261	HRS	5950.2		TSN 0						
WC#: 28.690	AFL	3630		TSN 0						
					PROC. REF: GENERIC NO REF					
284116		LH LOW PRESSURE SWITCH								Component ATA:28
PN:8G1256-1	MOS/MSC	24-Oct-91	O/C							
SN:949	HRS	0		TSN 0						
WC#: 28.700	AFL	0								
					PROC. REF: GENERIC NO REF					
284121		CENTER LOW PRESSURE SWITCH								Component ATA:28
PN:8G1256-1	MOS/MSC	24-Oct-91	O/C							
SN:263	HRS	0		TSN 0						
WC#: 28.700	AFL	0								
					PROC. REF: GENERIC NO REF					
284126		RH LOW PRESSURE SWITCH								Component ATA:28
PN:8G1256-1	MOS/MSC	24-Oct-91	O/C							
SN:917	HRS	0		TSN 0						
WC#: 28.700	AFL	0								
					PROC. REF: GENERIC NO REF					
284161		CENTER WING FORWARD QUANTITY GAUGE								Component ATA:28
PN:792-370-1	MOS/MSC	24-Oct-91	O/C							
SN:376	HRS	0		TSN 0						
WC#: 28.730	AFL	0								
					PROC. REF: GENERIC NO REF					
284166		CENTER WING REAR QUANTITY GAUGE								Component ATA:28
PN:792-371-1	MOS/MSC	09-Aug-22	O/C							
SN:369	HRS	8823		TSN 8823						
WC#: 28.730	AFL	5651								
					PROC. REF: GENERIC NO REF					
284171		CENTER FEEDER TANK QUANTITY GAUGE								Component ATA:28
PN:792-795-1	MOS/MSC	24-Jun-94	O/C							
SN:378	HRS	1200								
WC#: 28.740	AFL	845								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284176		LH FEEDER TANK QUANTITY GAUGE								Component ATA:28
PN:792-794-2	MOS/MSC	24-Oct-91	O/C							
SN:658	HRS	0		TSN 0						
WC#: 28.740	AFL	0								
					PROC. REF: GENERIC NO REF					
284178		RH FEEDER TANK QUANTITY GAUGE								Component ATA:28
PN:792-794-3	MOS/MSC	09-Aug-22	O/C							
SN:1261	HRS	8823								
WC#: 28.740	AFL	5651								
					PROC. REF: GENERIC NO REF					
284196		LH QUANTITY INDICATOR SYSTEM AMPLIFIER								Component ATA:28
PN:706-719-1	MOS/MSC	07-Aug-08	O/C	TSO 0						08/07/2010
SN:749	HRS	6784.5		TSO 0						
WC#: 28.760	AFL	4219		TSO 0						
					PROC. REF: GENERIC NO REF					
284201		CENTER QUANTITY INDICATOR SYSTEM AMPLIFIER								Component ATA:28
PN:706-720-1	MOS/MSC	24-Oct-91	O/C							
SN:400	HRS	0		TSN 0						
WC#: 28.760	AFL	0								
					PROC. REF: GENERIC NO REF					
284206		RH QUANTITY INDICATOR SYSTEM AMPLIFIER								Component ATA:28
PN:706-719-1	MOS/MSC	25-Aug-06	O/C	TSR 0						
SN:495	HRS	5991.5		TSR 0						
WC#: 28.760	AFL	3649		TSR 0						
					PROC. REF: GENERIC NO REF					
284211		FUEL TANK LOW LEVEL PRINTED CIRCUIT CARD								Component ATA:28
PN:CI815A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.770	AFL	0								
					PROC. REF: GENERIC NO REF					
284221		FUEL TEST VALVE								Component ATA:28
PN:B97M13-201	MOS/MSC	24-Oct-91	O/C							
SN:20138	HRS	0		TSN 0						
WC#: 28.780	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284231		FUEL TEMPERATURE PROBE								Component ATA:28
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.850	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
284291[U]		FUEL USED INDICATOR								Component ATA:28
PN:9-138-01	MOS/MSC	16-Sep-99	O/C							
SN:101	HRS	3469		TSN 5968						
	AFL	2286								
ATA 29 - HYDRAULIC POWER										
29-00-00-280-801-01		SAMPLING OF THE HYDRAULIC FLUID								Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-280-801					
29-00-00-610-801-01		REPLACEMENT OF THE HYDRAULIC FLUID IN CASE OF CONTAMINATION								Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-610-801					
29-00-00-610-802-01		REPLACEMENT OF THE HYDRAULIC FLUID AFTER FAILURE OF A HYDRAULIC POWER SYSTEM COMPONENT								Service ATA:29
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 29.380	AFL	0								
					PROC. REF: AMM 29-00-00-610-802					
29-00-00-790-801-01		LEAK CHECK OF THE HYDRAULIC SYSTEMS								Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-790-801					
29-00-00-860-801-01		PRESSURIZATION / DE-PRESSURIZATION OF THE HYDRAULIC SYSTEMS - WITH STANDBY PUMP								Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-860-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-00-00-860-801-02	PRESSURIZATION / DE-PRESSURIZATION OF THE HYDRAULIC SYSTEMS - WITH HYDRAULIC GROUND POWER UNIT									Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-860-801					
29-00-00-860-801-03	PRESSURIZATION / DE-PRESSURIZATION OF THE HYDRAULIC SYSTEMS - WITH THE ENGINES									Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-860-801					
29-00-00-870-801-01	BLEEDING OF THE HYDRAULIC SYSTEMS									Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-870-801					
29-00-00-870-802-01	DEGASSING OF THE HYDRAULIC SYSTEMS									Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-870-802					
29-00-00-910-802-01	PRECAUTIONS TO TAKE AFTER HYDRAULIC PUMP FAILURE									Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-910-802					
29-00-00-910-804-01	PRECAUTIONS TO TAKE AFTER SIGNIFICANT LOSS OF HYDRAULIC FLUID									Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-910-804					
29-00-00-910-805-01	SAFETY PRECAUTIONS FOR INSTALLATION OF CHECK VALVES									Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-910-805					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-00-00-910-806-01	PRECAUTIONS TO TAKE AFTER INTERVENTION ON HYDRAULIC COMPONENTS FITTED "ONE-WAY" WITHIN THE SYSTEM									Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-00-00-910-806					
29-10-00-720-801-01[S]	FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEMS - SYSTEM 1									Service ATA:29
	MOS	10-Dec-03								
	HRS	4936.4	6000 (+30)							
	AFL	3069								
					PROC. REF: AMM 29-10-00-720-801					PKG:24
29-10-00-720-801-02[S]	FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEMS - SYSTEM 2									Service ATA:29
	MOS	10-Dec-03								
	HRS	4936.4	6000 (+30)							
	AFL	3069								
					PROC. REF: AMM 29-10-00-720-801					PKG:24
29-11-01-350-801-01	RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 1 (L500ML)									Service ATA:29
PN:PVB-022-2	MOS	07-Mar-13						OVERHAUL		
SN:MX-514734G	HRS	7960.6	4000 (+3%)		11960.6	12080.6	2968.5 (+120)			
WC#: 29.030	AFL	5171								
					PROC. REF: AMM 29-11-01-350-801					
29-11-01-350-801-02	RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 2 (M500ML)									Service ATA:29
PN:PVB-022-2	MOS	07-Mar-13						OVERHAUL		
SN:MX-519262G	HRS	7960.6	4000 (+3%)		11960.6	12080.6	2968.5 (+120)			
WC#: 29.040	AFL	5171								
					PROC. REF: AMM 29-11-01-350-801					
29-11-01-350-801-03	RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 3 (R500ML)									Service ATA:29
PN:PVB-022-2	MOS	18-May-12						OVERHAUL		
SN:MX-364174G	HRS	7862.1	4000 (+3%)		11862.1	11982.1	2870 (+120)			
WC#: 29.050	AFL	5094								
					PROC. REF: AMM 29-11-01-350-801					
29-11-01-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 1 (L500ML)									Component ATA:29
PN:PVB-022-2	MOS/MSC	07-Mar-13	H/T	TSO 0						
SN:MX-514734G	HRS	7960.6		TSO 0						
WC#: 29.030	AFL	5171		TSO 0						
					PROC. REF: AMM 29-11-01-900-801, AMM 29-11-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-11-01-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 2 (M500ML)								Component	ATA:29
PN:PVB-022-2	MOS/MSC	07-Mar-13	H/T	TSO 150						
SN:MX-519262G	HRS	7960.6		TSO 3989.6						
WC#: 29.040	AFL	5171		TSO 2635						
					PROC. REF: AMM 29-11-01-900-801, AMM 29-11-01-900-801					
29-11-01-900-801-03	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 3 (R500ML)								Component	ATA:29
PN:PVB-022-2	MOS/MSC	18-May-12	H/T	TSO 17						
SN:MX-364174G	HRS	7862.1		TSO 0						
WC#: 29.050	AFL	5094		TSO 0						
					PROC. REF: AMM 29-11-01-900-801, AMM 29-11-01-900-801					
29-11-07-870-801-01	BLEEDING OF THE HYDRAULIC PUMP SUCTION LINES								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-11-07-870-801					
29-11-07-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE HYDRAULIC PUMP LINES								Component	ATA:29
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 29-11-07-900-801					
29-11-21-230-801-01	SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 1 PRESSURE RELIEF VALVE (L100ML)								Service	ATA:29
PN:A24518001	MOS/MSC	04-Jan-11	O/C							
SN:FM690	HRS	7460								
WC#: 29.250	AFL	4760								
					PROC. REF: AMM 29-11-21-230-801					
29-11-21-230-801-02	SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 2 PRESSURE RELIEF VALVE (M100ML)								Service	ATA:29
PN:A24518001	MOS/MSC	04-Jan-11	O/C							
SN:FM748	HRS	7460								
WC#: 29.250	AFL	4760								
					PROC. REF: AMM 29-11-21-230-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-11-21-230-801-03	SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 3 PRESSURE RELIEF VALVE (R100ML)								Service	ATA:29
PN:A24518001	MOS/MSC	04-Jan-11	O/C							
SN:FM691	HRS	7460								
WC#: 29.260	AFL	4760								
					PROC. REF: AMM 29-11-21-230-801					
29-11-21-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 1 PRESSURE RELIEF VALVE (L100ML)								Component	ATA:29
PN:A24518001	MOS/MSC	04-Jan-11	O/C	TSO 0						
SN:FM690	HRS	7460		TSO 0						
WC#: 29.250	AFL	4760		TSO 0						
					PROC. REF: AMM 29-11-21-900-801					
29-11-21-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 2 PRESSURE RELIEF VALVE (M100ML)								Component	ATA:29
PN:A24518001	MOS/MSC	04-Jan-11	O/C	TSO 0						
SN:FM748	HRS	7460		TSO 0						
WC#: 29.250	AFL	4760		TSO 0						
					PROC. REF: AMM 29-11-21-900-801					
29-11-21-900-801-03	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 3 PRESSURE RELIEF VALVE (R100ML)								Component	ATA:29
PN:A24518001	MOS/MSC	04-Jan-11	O/C	TSO 0						
SN:FM691	HRS	7460		TSO 0						
WC#: 29.260	AFL	4760		TSO 0						
					PROC. REF: AMM 29-11-21-900-801					
29-11-25-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE SWITCHES - HYDRAULIC PUMP 1 PRESSURE SWITCH (11D1)								Component	ATA:29
PN:90G229	MOS/MSC	18-Nov-05	O/C							
SN:1815	HRS	5701.3								
WC#: 29.360	AFL	3490								
					PROC. REF: AMM 29-11-25-900-801					
29-11-25-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE SWITCHES - HYDRAULIC PUMP 2 PRESSURE SWITCH (11D2)								Component	ATA:29
PN:90G229	MOS/MSC	18-Nov-05	O/C	TSN 0						
SN:1817	HRS	5701.3		TSN 0						
WC#: 29.360	AFL	3490		TSN 0						
					PROC. REF: AMM 29-11-25-900-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-11-25-900-801-03	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE SWITCHES - HYDRAULIC PUMP 3 PRESSURE SWITCH (11D3)								Component	ATA:29
PN:90G229	MOS/MSC	27-May-21	O/C	TSN 0, TSO 0, TSR 0						
SN:1601	HRS	8751.8		TSN 0, TSO 0, TSR 0						
WC#: 29.360	AFL	5619		TSN 0, TSO 0, TSR 0						
					PROC. REF: AMM 29-11-25-900-801					
29-11-25-900-801-04	NO. 1 HYDRAULIC SYSTEM STANDBY PUMP PRESSURE SWITCH								Component	ATA:29
PN:90G196-2	MOS/MSC	18-Nov-05	O/C	TSN 0						
SN:2706	HRS	5701.3		TSN 0						
WC#: 29.320	AFL	3490		TSN 0						
					PROC. REF: AMM 29-11-25-900-801					
29-11-25-900-801-05	NO. 2 HYDRAULIC SYSTEM STANDBY PUMP PRESSURE SWITCH								Component	ATA:29
PN:90G196-2	MOS/MSC	20-Oct-04	O/C	TSN 0						
SN:2574	HRS	5330.4		TSN 0						
WC#: 29.320	AFL	3287		TSN 0						
					PROC. REF: AMM 29-11-25-900-801					
29-11-25-960-801-01	DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 1 PRESSURE SWITCH (11D1)								Service	ATA:29
PN:90G229	MOS/MSC	18-Nov-05	O/C							
SN:1815	HRS	5701.3								
WC#: 29.360	AFL	3490								
					PROC. REF: AMM 29-11-25-960-801					
29-11-25-960-801-02	DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 2 PRESSURE SWITCH (11D2)								Service	ATA:29
PN:90G229	MOS/MSC	18-Nov-05	O/C	TAC 0						
SN:1817	HRS	5701.3		TAC 0						
WC#: 29.360	AFL	3490		TAC 0						
					PROC. REF: AMM 29-11-25-960-801					
29-11-25-960-801-03	DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 3 PRESSURE SWITCH (11D3)								Service	ATA:29
PN:90G229	MOS/MSC	18-Nov-05	O/C	TAC 0						
SN:1601	HRS	5701.3		TAC 0						
WC#: 29.360	AFL	3490		TAC 0						
					PROC. REF: AMM 29-11-25-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-13-09-100-801-01	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 1 RETURN FILTER (L200ML)								Service	ATA:29
PN:CG8104013446 N00	MOS	09-Mar-18								
SN:UNKNOWN	HRS	8497.6	1200 (+30)		9697.6	9727.6	705.5 (+30)			
WC#: 29.070	AFL	5470								
					PROC. REF: AMM 29-13-09-100-801					
29-13-09-100-801-02	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 2 RETURN FILTER (M200ML)								Service	ATA:29
PN:CG8104013446 N00	MOS	09-Mar-18								
SN:UNKNOWN	HRS	8497.6	1200 (+30)		9697.6	9727.6	705.5 (+30)			
WC#: 29.070	AFL	5470								
					PROC. REF: AMM 29-13-09-100-801					
29-13-09-100-801-03	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 3 RETURN FILTER (R200ML)								Service	ATA:29
PN:CG8104013446 N00	MOS	09-Mar-18								
SN:UNKNOWN	HRS	8497.6	1200 (+30)		9697.6	9727.6	705.5 (+30)			
WC#: 29.080	AFL	5470								
					PROC. REF: AMM 29-13-09-100-801					
29-13-09-100-801-04	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 1 DELIVERY FILTER (L350ML)								Service	ATA:29
PN:CH0378103392 B00	MOS	09-Mar-18								
SN:UNKNOWN	HRS	8497.6	1200 (+30)		9697.6	9727.6	705.5 (+30)			
WC#: 29.140	AFL	5470								
					PROC. REF: AMM 29-13-09-100-801					
29-13-09-100-801-05	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 2 DELIVERY FILTER (M350ML)								Service	ATA:29
PN:CH0378103392 B00	MOS	09-Mar-18								
SN:UNKNOWN	HRS	8497.6	1200 (+30)		9697.6	9727.6	705.5 (+30)			
WC#: 29.150	AFL	5470								
					PROC. REF: AMM 29-13-09-100-801					
29-13-09-100-801-06	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 3 DELIVERY FILTER (R350ML)								Service	ATA:29
PN:CH0378103392 B00	MOS	09-Mar-18								
SN:UNKNOWN	HRS	8497.6	1200 (+30)		9697.6	9727.6	705.5 (+30)			
WC#: 29.160	AFL	5470								
					PROC. REF: AMM 29-13-09-100-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-13-09-100-801-07	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - STANDBY PUMP FILTER (14ML)								Service	ATA:29
PN:CG8106013356 N00	MOS	09-Mar-18								
SN:41798A	HRS	8497.6	1200 (+30)		9697.6	9727.6	705.5 (+30)			
WC#: 29.330	AFL	5470								
					PROC. REF: AMM 29-13-09-100-801					
29-14-01-220-801-01	DETAILED INSPECTION OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)								Service	ATA:29
PN:C24304002	MOS/MSC	09-Mar-18	O/C							
SN:U15	HRS	8497.6								
WC#: 29.060	AFL	5470								
					PROC. REF: AMM 29-14-01-220-801					
29-14-01-220-801-02	DETAILED INSPECTION OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)								Service	ATA:29
PN:C24304002	MOS/MSC	09-Mar-18	O/C							
SN:U48	HRS	8497.6								
WC#: 29.060	AFL	5470								
					PROC. REF: AMM 29-14-01-220-801					
29-14-01-610-801-01	FILLING AND REPLENISHING OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-14-01-610-801					
29-14-01-610-801-02	FILLING AND REPLENISHING OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-14-01-610-801					
29-14-01-680-801-01	DRAINING OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-14-01-680-801					
29-14-01-680-801-02	DRAINING OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-14-01-680-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-14-01-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)								Component	ATA:29
PN:C24304002	MOS/MSC	24-Oct-91	O/C							
SN:U15	HRS	0		TSN 0						
WC#: 29.060	AFL	0								
					PROC. REF: AMM 29-14-01-900-801					
29-14-01-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)								Component	ATA:29
PN:C24304002	MOS/MSC	24-Oct-91	O/C							
SN:U48	HRS	0		TSN 0						
WC#: 29.060	AFL	0								
					PROC. REF: AMM 29-14-01-900-801					
29-14-11-610-801-01	CHARGING OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 1 ACCUMULATOR (L515ML)								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-14-11-610-801					
29-14-11-610-801-02	CHARGING OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 2 ACCUMULATOR (R515ML)								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-14-11-610-801					
29-14-11-710-801-01	OPERATIONAL TEST OF THE HYDRAULIC SYSTEM ACCUMULATOR - SYSTEM 1 ACCUMULATOR (L515ML)								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-14-11-710-801					
29-14-11-710-801-02	OPERATIONAL TEST OF THE HYDRAULIC SYSTEM ACCUMULATOR - SYSTEM 2 ACCUMULATOR (R515ML)								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-14-11-710-801					
29-14-11-780-802-01	CHECK OF THE HYDRAULIC SYSTEM ACCUMULATOR PRESSURE - SYSTEM 1 ACCUMULATOR (L515ML)								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-14-11-780-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-14-11-780-802-02	CHECK OF THE HYDRAULIC SYSTEM ACCUMULATOR PRESSURE - SYSTEM 2 ACCUMULATOR (R515ML)									Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-14-11-780-802					
29-14-11-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 1 ACCUMULATOR (L515ML)									Component ATA:29
PN:60833-2	MOS/MSC	24-Oct-91	O/C							
SN:783	HRS	0		TSN 0						
WC#: 29.190	AFL	0								
					PROC. REF: AMM 29-14-11-900-801					
29-14-11-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 2 ACCUMULATOR (R515ML)									Component ATA:29
PN:60833-2	MOS/MSC	24-Oct-91	O/C							
SN:780	HRS	0		TSN 0						
WC#: 29.190	AFL	0								
					PROC. REF: AMM 29-14-11-900-801					
29-14-33-960-801-01	REPLACEMENT OF THE HYDRAULIC RESERVOIR FILTERING ELEMENTS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)									Service ATA:29
PN:C24304002	MOS	09-Mar-18								
SN:U15	HRS	8497.6	1200 (+30)		9697.6	9727.6	705.5 (+30)			
WC#: 29.060	AFL	5470								
					PROC. REF: AMM 29-14-33-960-801					
29-14-33-960-801-02	REPLACEMENT OF THE HYDRAULIC RESERVOIR FILTERING ELEMENTS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)									Service ATA:29
PN:C24304002	MOS	09-Mar-18								
SN:U48	HRS	8497.6	1200 (+30)		9697.6	9727.6	705.5 (+30)			
WC#: 29.060	AFL	5470								
					PROC. REF: AMM 29-14-33-960-801					
29-14-33-960-802-01	REPLACEMENT OF THE CHLORINE RETAINING ELEMENT - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)									Service ATA:29
	MOS/MSC	09-Apr-92	N/A							
	HRS	26								
WC#: 29.010	AFL	13								
					PROC. REF: AMM 29-14-33-960-802					
29-14-33-960-802-02	REPLACEMENT OF THE CHLORINE RETAINING ELEMENT - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)									Service ATA:29
	MOS/MSC	09-Apr-92	N/A							
	HRS	26								
WC#: 29.010	AFL	13								
					PROC. REF: AMM 29-14-33-960-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-15-00-720-801-01 S	FUNCTIONAL TEST OF THE HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM - HYDRAULIC SYSTEM 1								Service	ATA:29
	MOS	10-Dec-03								
	HRS	4936.4	6000 (+30)							
WC#: 29.060	AFL	3069								
				PROC. REF: AMM 29-15-00-720-801						PKG:24
29-15-00-720-801-02 S	FUNCTIONAL TEST OF THE HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM - HYDRAULIC SYSTEM 2								Service	ATA:29
	MOS	10-Dec-03								
	HRS	4936.4	6000 (+30)							
WC#: 29.060	AFL	3069								
				PROC. REF: AMM 29-15-00-720-801						PKG:24
29-15-05-100-801-01	CLEANING OF THE HYDRAULIC RESERVOIR PRESSURE REDUCER FILTERS - HYDRAULIC RESERVOIR PRESSURE REDUCER (10ML)								Service	ATA:29
PN:2407ZR4EQ10	MOS	07-Aug-20	48		07-Aug-24		280 d			
SN:1616	HRS	8690.7								
WC#: 29.090	AFL	5593								
				PROC. REF: AMM 29-15-05-100-801						
29-15-05-350-801-01	RESTORATION OF THE HYDRAULIC RESERVOIR PRESSURE REDUCER (FUNCTIONAL TEST AND DIAPHRAGM REPLACEMENT) - HYDRAULIC RESERVOIR PRESSURE REDUCER (10ML)								Service	ATA:29
PN:2407ZR4EQ10	MOS	07-Aug-20	72		07-Aug-26		1010 d			
SN:1616	HRS	8690.7								
	AFL	5593								
				PROC. REF: AMM 29-15-05-350-801						
29-15-05-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIR PRESSURE REDUCER - HYDRAULIC RESERVOIR PRESSURE REDUCER (10ML)								Component	ATA:29
PN:2407ZR4EQ10	MOS/MSC	07-Aug-20	O/C	TSO 101						
SN:1616	HRS	8690.7		TSO 896.4						
WC#: 29.090	AFL	5593		TSO 551						
				PROC. REF: AMM 29-15-05-900-801						
29-20-00-720-801-01	FUNCTIONAL TEST OF THE AUXILIARY HYDRAULIC SYSTEM - TEST ON HYDRAULIC SYSTEM 2								Service	ATA:29
	MOS	17-Dec-10								
	HRS	7458.3	4800 (+30)		12258.3	12288.3	3266.2 (+30)			
WC#: 29.300	AFL	4759								
				PROC. REF: AMM 29-20-00-720-801						
29-20-00-720-801-02	FUNCTIONAL TEST OF THE AUXILIARY HYDRAULIC SYSTEM - TEST ON HYDRAULIC SYSTEM 1								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
				PROC. REF: AMM 29-20-00-720-801						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-20-01-900-801-01	REMOVAL / INSTALLATION OF THE STAND-BY ELECTRIC PUMP - STANDBY ELECTRIC PUMP (15M)									Component ATA:29
PN:EP1600-12	MOS/MSC	17-Dec-10	O/C	TSN 230, TSR 0						
SN:378	HRS	7458.3		TSN 7458.3, TSR 0						
WC#: 29.300	AFL	4759		TSN 4759, TSR 0						
					PROC. REF: AMM 29-20-01-900-801					
29-20-03-220-801-01	CHECK OF THE STANDBY ELECTRIC PUMP MOTOR BRUSHES - STANDBY ELECTRIC PUMP (15M)									Service ATA:29
PN:1153-1	MOS	17-Dec-10								
SN:2147	HRS	7458.3	4800 (+3%)		12258.3	12402.3	3266.2 (+144)			
WC#: 29.300	AFL	4759								
					PROC. REF: AMM 29-20-03-220-801					
29-20-03-720-801-01	FUNCTIONAL TEST OF THE STANDBY ELECTRIC PUMP MOTOR - STANDBY ELECTRIC PUMP (15M)									Service ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-20-03-720-801					
29-20-05-900-801-01	REMOVAL / INSTALLATION OF THE STANDBY PUMP SELECTOR VALVE - STANDBY PUMP SELECTOR VALVE (17D)									Component ATA:29
PN:B94A13-205	MOS/MSC	24-Oct-91	O/C							
SN:20283	HRS	0		TSN 0						
WC#: 29.310	AFL	0								
					PROC. REF: AMM 29-20-05-900-801					
29-20-07-900-801-01	REMOVAL / INSTALLATION OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 1 STANDBY PUMP PRESSURE SWITCH (16M1)									Component ATA:29
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 29-20-07-900-801					
29-20-07-900-801-02	REMOVAL / INSTALLATION OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 2 STANDBY PUMP PRESSURE SWITCH (16M2)									Component ATA:29
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 29-20-07-900-801					
29-20-07-960-801-01	DISCARD OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 1 STANDBY PUMP PRESSURE SWITCH (16M1)									Service ATA:29
PN:90G196-2	MOS/MSC	18-Nov-05	O/C	TAC 0						
SN:2706	HRS	5701.3		TAC 0						
WC#: 29.320	AFL	3490		TAC 0						
					PROC. REF: AMM 29-20-07-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
29-20-07-960-801-02	DISCARD OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 2 STANDBY PUMP PRESSURE SWITCH (16M2)								Service	ATA:29
PN:90G196-2	MOS/MSC	20-Oct-04	O/C	TAC 0						
SN:2574	HRS	5330.4		TAC 0						
WC#: 29.320	AFL	3287		TAC 0						
					PROC. REF: AMM 29-20-07-960-801					
29-30-00-710-801-01	OPERATIONAL TEST OF THE HYDRAULIC RESERVOIR GAUGING SYSTEM								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-30-00-710-801, AMM 29-30-00-710-801					
29-30-09-960-801-01	REPLACEMENT OF THE HYDRAULIC RESERVOIR GAUGE TRANSMITTERS - SYSTEM 1 HYDRAULIC RESERVOIR GAUGE (4D1)								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-30-09-960-801					
29-30-09-960-801-02	REPLACEMENT OF THE HYDRAULIC RESERVOIR GAUGE TRANSMITTERS - SYSTEM 2 HYDRAULIC RESERVOIR GAUGE (4D2)								Service	ATA:29
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 29-30-09-960-801					
291161	HYDRAULIC PRESSURIZATION VALVE ASSEMBLY								Component	ATA:29
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
291166	NO. 1 CIRCUIT NO.1 RETURN REGULATION FILTER								Component	ATA:29
PN:CG8104013446 N00	MOS/MSC	16-Dec-09	O/C	TSR 0						
SN:UNKNOWN	HRS	7169.2		TSR 0						
WC#: 29.070	AFL	4516		TSR 0						
					PROC. REF: GENERIC NO REF					
291176	NO. 1 CIRCUIT NO.2 RETURN REGULATION FILTER								Component	ATA:29
PN:CG8104013446 N00	MOS/MSC	16-Dec-09	O/C	TSR 0						
SN:UNKNOWN	HRS	7169.2		TSR 0						
WC#: 29.070	AFL	4516		TSR 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291186		NO. 2 CIRCUIT NO.3 RETURN REGULATION FILTER								Component ATA:29
PN:CG8104013446 N00	MOS/MSC	16-Dec-09	O/C							
SN:UNKNOWN	HRS	7169.2								
WC#: 29.080	AFL	4516								
					PROC. REF: GENERIC NO REF					
291226		NO. 1 PUMP RETURN CHECK VALVE								Component ATA:29
PN:A24515-1	MOS/MSC	24-Oct-91	O/C							
SN:FM1088	HRS	0		TSN 0						
WC#: 29.100	AFL	0								
					PROC. REF: GENERIC NO REF					
291231		NO. 2 PUMP RETURN CHECK VALVE								Component ATA:29
PN:A24515-1	MOS/MSC	24-Oct-91	O/C							
SN:FM1093	HRS	0		TSN 0						
WC#: 29.100	AFL	0								
					PROC. REF: GENERIC NO REF					
291236		NO. 3 PUMP RETURN CHECK VALVE								Component ATA:29
PN:A24515-1	MOS/MSC	24-Oct-91	O/C							
SN:FM1090	HRS	0		TSN 0						
WC#: 29.100	AFL	0								
					PROC. REF: GENERIC NO REF					
291241		NO. 1 PUMP SUCTION FIXED-HALF QUICK DISCONNECT COUPLING								Component ATA:29
PN:405-20402-13300	MOS/MSC	24-Oct-91	O/C							
SN:1079	HRS	0		TSN 0						
WC#: 29.110	AFL	0								
					PROC. REF: GENERIC NO REF					
291246		NO. 2 PUMP SUCTION FIXED-HALF QUICK DISCONNECT COUPLING								Component ATA:29
PN:405-20402-13300	MOS/MSC	24-Oct-91	O/C							
SN:1080	HRS	0		TSN 0						
WC#: 29.110	AFL	0								
					PROC. REF: GENERIC NO REF					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291251		NO. 3 PUMP SUCTION FIXED-HALF QUICK DISCONNECT COUPLING							Component	ATA:29
PN:405-20402-13300	MOS/MSC	24-Oct-91	O/C							
SN:1078	HRS	0		TSN 0						
WC#: 29.110	AFL	0								
					PROC. REF: GENERIC NO REF					
291256		NO. 1 PUMP SUCTION COUPLER QUICK DISCONNECT COUPLING							Component	ATA:29
PN:405-20403-13200	MOS/MSC	24-Oct-91	O/C							
SN:1142	HRS	0		TSN 0						
WC#: 29.120	AFL	0								
					PROC. REF: GENERIC NO REF					
291261		NO. 2 PUMP SUCTION COUPLER QUICK DISCONNECT COUPLING							Component	ATA:29
PN:405-20403-13200	MOS/MSC	24-Oct-91	O/C							
SN:1143	HRS	0		TSN 0						
WC#: 29.120	AFL	0								
					PROC. REF: GENERIC NO REF					
291266		NO. 3 PUMP SUCTION COUPLER QUICK DISCONNECT COUPLING							Component	ATA:29
PN:405-20403-13200	MOS/MSC	24-Oct-91	O/C							
SN:1136	HRS	0		TSN 0						
WC#: 29.120	AFL	0								
					PROC. REF: GENERIC NO REF					
291271		NO. 1 PUMP DISCHARGE QUICK DISCONNECT VALVE							Component	ATA:29
PN:AE99113H	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 29.130	AFL	0								
					PROC. REF: GENERIC NO REF					
291276		NO. 2 PUMP DISCHARGE QUICK DISCONNECT VALVE							Component	ATA:29
PN:AE99113H	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 29.130	AFL	0								
					PROC. REF: GENERIC NO REF					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291281		NO. 3 PUMP DISCHARGE QUICK DISCONNECT VALVE								Component ATA:29
PN:AE99113H	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 29.130	AFL	0								
					PROC. REF: GENERIC NO REF					
291286		NO. 1 HP HYDRAULIC FILTER								Component ATA:29
PN:CH0378103392 B00	MOS/MSC	16-Dec-09	O/C							
SN:UNKNOWN	HRS	7169.2								
WC#: 29.140	AFL	4516								
					PROC. REF: GENERIC NO REF					
291296		NO. 2 HP HYDRAULIC FILTER								Component ATA:29
PN:CH0378103392 B00	MOS/MSC	16-Dec-09	O/C							
SN:UNKNOWN	HRS	7169.2								
WC#: 29.150	AFL	4516								
					PROC. REF: GENERIC NO REF					
291306		NO. 3 HP HYDRAULIC FILTER								Component ATA:29
PN:CH0378103392 B00	MOS/MSC	16-Dec-09	O/C							
SN:UNKNOWN	HRS	7169.2								
WC#: 29.160	AFL	4516								
					PROC. REF: GENERIC NO REF					
291316		NO. 1 HYDRAULIC SYSTEM LEFT GROUND RETURN CONNECTION								Component ATA:29
PN:B3005S4-12D	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 29.170	AFL	0								
					PROC. REF: GENERIC NO REF					
291321		NO. 2 HYDRAULIC SYSTEM RIGHT GROUND RETURN CONNECTION								Component ATA:29
PN:B3005S4-12D	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 29.170	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291326		NO. 1 HYDRAULIC SYSTEM LEFT GROUND PRESSURE CONNECTION								Component ATA:29
PN:TB3005S4-8D	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 29.180	AFL	0								
					PROC. REF: GENERIC NO REF					
291331		NO. 2 HYDRAULIC SYSTEM RIGHT GROUND PRESSURE CONNECTION								Component ATA:29
PN:TB3005S4-8D	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 29.180	AFL	0								
					PROC. REF: GENERIC NO REF					
291356		NO. 1 PRESSURE INDICATOR								Component ATA:29
PN:18040100	MOS/MSC	24-Oct-91	O/C							
SN:29657C	HRS	0		TSN 0						
WC#: 29.200	AFL	0								
					PROC. REF: GENERIC NO REF					
291366		NO. 2 PRESSURE INDICATOR								Component ATA:29
PN:18040100	MOS/MSC	24-Oct-91	O/C							
SN:29649C	HRS	0		TSN 0						
WC#: 29.200	AFL	0								
					PROC. REF: GENERIC NO REF					
291376		NO. 1 HYDRAULIC SYSTEM ACCUMULATOR FILLER VALVE								Component ATA:29
PN:MS28889-2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 29.210	AFL	0								
					PROC. REF: GENERIC NO REF					
291381		NO. 2 HYDRAULIC SYSTEM ACCUMULATOR FILLER VALVE								Component ATA:29
PN:MS28889-2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 29.210	AFL	0								
					PROC. REF: GENERIC NO REF					
291386		PARKING BRAKE ACCUMULATOR FILLER VALVE								Component ATA:29
PN:MS28889-2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 29.220	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291391		THRUST REVERSER ACCUMULATOR FILLER VALVE								Component ATA:29
PN:MS28889-2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 29.220	AFL	0								
					PROC. REF: GENERIC NO REF					
291396		NO. 1 PUMP SUCTION CHECK VALVE								Component ATA:29
PN:A24517	MOS/MSC	24-Oct-91	O/C							
SN:FM3295	HRS	0		TSN 0						
WC#: 29.230	AFL	0								
					PROC. REF: GENERIC NO REF					
291401		NO. 2 PUMP SUCTION CHECK VALVE								Component ATA:29
PN:A24517	MOS/MSC	24-Oct-91	O/C							
SN:FM3298	HRS	0		TSN 0						
WC#: 29.230	AFL	0								
					PROC. REF: GENERIC NO REF					
291406		NO. 3 PUMP SUCTION CHECK VALVE								Component ATA:29
PN:A24517	MOS/MSC	24-Oct-91	O/C							
SN:FM3296	HRS	0		TSN 0						
WC#: 29.230	AFL	0								
					PROC. REF: GENERIC NO REF					
291411		NO. 1 SYSTEM SUCTION CHECK VALVE GROUND CONNECTION								Component ATA:29
PN:A24517	MOS/MSC	24-Oct-91	O/C							
SN:FM3297	HRS	0		TSN 0						
WC#: 29.240	AFL	0								
					PROC. REF: GENERIC NO REF					
291416		NO. 2 SYSTEM SUCTION CHECK VALVE GROUND CONNECTION								Component ATA:29
PN:A24517	MOS/MSC	24-Oct-91	O/C							
SN:FM3300	HRS	0		TSN 0						
WC#: 29.240	AFL	0								
					PROC. REF: GENERIC NO REF					
291436		NO. 1 SYSTEM ELECTRO PUMP DISTRIBUTOR CHECK VALVE								Component ATA:29
PN:A24516	MOS/MSC	24-Oct-91	O/C							
SN:FM2791	HRS	0		TSN 0						
WC#: 29.270	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291441		NO. 2 SYSTEM ELECTRO PUMP DISTRIBUTOR CHECK VALVE								Component ATA:29
PN:A24516	MOS/MSC	24-Oct-91	O/C							
SN:FM2794	HRS	0		TSN 0						
WC#: 29.270	AFL	0								
					PROC. REF: GENERIC NO REF					
291446		HYDRAULIC PRESSURIZATION CHECK VALVE								Component ATA:29
PN:2504CD01	MOS/MSC	24-Oct-91	O/C							
SN:719	HRS	0		TSN 0						
WC#: 29.280	AFL	0								
					PROC. REF: GENERIC NO REF					
291806[U]		NO. 2 HYDRAULIC RESERVOIR PRESSURIZATION VALVE								Component ATA:29
PN:C24265	MOS/MSC	25-Aug-06	O/C	TSO 0						
SN:M071	HRS	5991.5		TSO 0						
	AFL	3649		TSO 0						
292121		HYDRAULIC ELECTRO- PUMP-MOTOR								Component ATA:29
PN:1153-1	MOS/MSC	24-Oct-91	O/C							
SN:2147	HRS	0		TSN 0						
WC#: 29.300	AFL	0								
					PROC. REF: GENERIC NO REF					
292156		AUXILIARY HYDRAULIC SYSTEM FILTER								Component ATA:29
PN:CG8106013356 N00	MOS/MSC	16-Dec-09	O/C							
SN:41798A	HRS	7169.2								
WC#: 29.330	AFL	4516								
					PROC. REF: GENERIC NO REF					
293101		NO. 1 CIRCUIT PRESSURE TRANSMITTER								Component ATA:29
PN:8107-134-00-12	MOS/MSC	24-Oct-91	O/C							
SN:190	HRS	0		TSN 0						
WC#: 29.340	AFL	0								
					PROC. REF: GENERIC NO REF					
293106		NO. 2 CIRCUIT PRESSURE TRANSMITTER								Component ATA:29
PN:8107-134-00-12	MOS/MSC	24-Oct-91	O/C							
SN:189	HRS	0		TSN 0						
WC#: 29.340	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
293111		NO. 1 CIRCUIT DUAL INDICATOR PRESSURE LEVEL								Component ATA:29
PN:5502-382-80-12	MOS/MSC	05-Jul-94	O/C	TSN 0, TSO 0						
SN:282	HRS	1205		TSN 600, TSO 600						
WC#: 29.350	AFL	850		TSN 0, TSO 0						
					PROC. REF: GENERIC NO REF					
293116		NO. 2 CIRCUIT DUAL INDICATOR PRESSURE LEVEL								Component ATA:29
PN:5502-382-80-12	MOS/MSC	25-Oct-99	O/C	TSO 0						
SN:255	HRS	3550		TSO 0						
WC#: 29.350	AFL	2325		TSO 0						
					PROC. REF: GENERIC NO REF					
293141		NO. 1 HYDRAULIC RESERVOIR PRESSURIZATION LOW PRESSURE SWITCH								Component ATA:29
PN:8A1206-1	MOS/MSC	24-Oct-91	O/C							
SN:181	HRS	0		TSN 0						
WC#: 29.370	AFL	0								
					PROC. REF: GENERIC NO REF					
293146		NO. 2 HYDRAULIC RESERVOIR PRESSURIZATION LOW PRESSURE SWITCH								Component ATA:29
PN:8A1206-1	MOS/MSC	14-Nov-02	O/C	TSN 0						
SN:1118	HRS	4554.5		TSN 0						
WC#: 29.370	AFL	2887		TSN 0						
					PROC. REF: GENERIC NO REF					
293806[U]		HYDR LVL NO.1 TRANSMITTER								Component ATA:29
PN:64754-001-3	MOS/MSC	19-Mar-94	O/C							
SN:4780	HRS	1062								
	AFL	732								
293817[U]		HYD EMERGENCY ACTUATOR								Component ATA:29
PN:D97E00-201	MOS/MSC	21-Dec-99	O/C							
SN:20667	HRS	3652		TSN 327						
	AFL	2368								
ATA 30 - ICE AND RAIN PROTECTION										
30-00-00.1		ICE AND RAIN PROTECTION (A/C WITH ENGINES TFE 731-3)								Service ATA:30
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-00-00.1					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-00-00.2	ICE AND RAIN PROTECTION (A/C WITH ENGINES TFE 731-40)								Service	ATA:30
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-00-00.2					
30-10-00-710-801-01	OPERATIONAL TEST OF THE WING ANTI-ICING SYSTEM								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-10-00-710-801, AMM 30-10-00-710-801					
30-10-00-790-801-01	LEAK CHECK OF THE WING ANTI-ICING SYSTEM								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-10-00-790-801, AMM 30-10-00-790-801					
30-10-00-790-801.1	LEAK CHECK OF THE WING ANTI-ICING SYSTEM (A/C WITH ENGINES TFE 731-3)								Service	ATA:30
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-10-00-790-801					
30-10-00-790-801.2	LEAK CHECK OF THE WING ANTI-ICING SYSTEM (A/C WITH ENGINES TFE 731-40)								Service	ATA:30
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-10-00-790-801					
30-11-00-350-801-01	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - LH INBOARD SLAT TELESCOPIC DUCT (L537H1)								Service	ATA:30
PN:5041-200	MOS/MSC	10-Aug-11	O/C	TAC 0						
SN:416	HRS	7615.9		TAC 0						
WC#: 30.030	AFL	4881		TAC 0						
					PROC. REF: AMM 30-11-00-350-801					
30-11-00-350-801-02	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - RH INBOARD SLAT TELESCOPIC DUCT (R537H1)								Service	ATA:30
PN:5041-300	MOS/MSC	24-Apr-03	O/C	TAC 0						
SN:611	HRS	4704.9		TAC 0						
WC#: 30.030	AFL	2964		TAC 0						
					PROC. REF: AMM 30-11-00-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-11-00-350-801-03	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - LH OUTBOARD SLAT TELESCOPIC DUCT (L537H2)								Service	ATA:30
PN:5040-000	MOS/MSC	24-Apr-03	O/C	TAC 0						
SN:514	HRS	4704.9		TAC 0						
WC#: 30.020	AFL	2964		TAC 0						
					PROC. REF: AMM 30-11-00-350-801					
30-11-00-350-801-04	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - RH OUTBOARD SLAT TELESCOPIC DUCT (R537H2)								Service	ATA:30
PN:5040-300	MOS/MSC	24-Apr-03	O/C	TAC 0						
SN:019	HRS	4704.9		TAC 0						
WC#: 30.020	AFL	2964		TAC 0						
					PROC. REF: AMM 30-11-00-350-801					
30-11-00-720-801-01	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - LH INBOARD SLAT TELESCOPIC DUCT (L537H1)								Service	ATA:30
PN:5041-200	MOS	10-Aug-11								
SN:416	HRS	7615.9	2500 (+3%)		10115.9	10190.9	1123.8 (+75)			
WC#: 30.030	AFL	4881	2000 (+3%)		6881	6941	1085 (+60)			
					PROC. REF: AMM 30-11-00-720-801					
30-11-00-720-801-02	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - RH INBOARD SLAT TELESCOPIC DUCT (R537H1)								Service	ATA:30
PN:5041-300	MOS	07-Sep-22								
SN:611	HRS	8823	1250 (+3%)		10073	10110.5	1080.9 (+37.5)			
WC#: 30.030	AFL	5651	1000 (+3%)		6651	6681	855 (+30)			
					PROC. REF: AMM 30-11-00-720-801					
30-11-00-720-801-03	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - LH OUTBOARD SLAT TELESCOPIC DUCT (L537H2)								Service	ATA:30
PN:5040-000	MOS	24-Sep-12		Adj -45d						
SN:514	HRS	7931	1250 (+3%)		9181	9218.5	188.9 (+37.5)			
WC#: 30.020	AFL	5144	1000 (+3%)		6144	6174	348 (+30)			
					PROC. REF: AMM 30-11-00-720-801					
30-11-00-720-801-04	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - RH OUTBOARD SLAT TELESCOPIC DUCT (R537H2)								Service	ATA:30
PN:5040-300	MOS	24-Sep-12		Adj -45d						
SN:019	HRS	7931	1250 (+3%)		9181	9218.5	188.9 (+37.5)			
WC#: 30.020	AFL	5144	1000 (+3%)		6144	6174	348 (+30)			
					PROC. REF: AMM 30-11-00-720-801					
30-11-00-900-801-01	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - LH INBOARD TELESCOPIC DUCT (L537H1)								Component	ATA:30
PN:5040-000	MOS/MSC	24-Apr-03	O/C	TSR 0						
SN:514	HRS	4704.9		TSR 0						
WC#: 30.020	AFL	2964		TSR 0						
					PROC. REF: AMM 30-11-00-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-11-00-900-801-02	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - RH INBOARD TELESCOPIC DUCT (R537H1)								Component	ATA:30
PN:5041-200	MOS/MSC	10-Aug-11	O/C	TSO 0						
SN:416	HRS	7615.9		TSO 0						
WC#: 30.030	AFL	4881		TSO 0						
					PROC. REF: AMM 30-11-00-900-801					
30-11-00-900-801-03	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - LH OUTBOARD TELESCOPIC DUCT (L537H2)								Component	ATA:30
PN:5041-300	MOS/MSC	24-Apr-03	O/C	TSO 0						
SN:611	HRS	4704.9		TSO 0						
WC#: 30.030	AFL	2964		TSO 0						
					PROC. REF: AMM 30-11-00-900-801					
30-11-00-900-801-04	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - RH OUTBOARD TELESCOPIC DUCT (R537H2)								Component	ATA:30
PN:5040-300	MOS/MSC	24-Apr-03	O/C	TSN 0						
SN:019	HRS	4704.9		TSN 0						
WC#: 30.020	AFL	2964		TSN 0						
					PROC. REF: AMM 30-11-00-900-801					
30-11-11-280-801	SPECIAL DETAILED INSPECTION OF THE PICCOLO TUBES								Service	ATA:30
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-11-11-280-801					
30-11-11-280-801-01	SPECIAL DETAILED INSPECTION OF THE PICCOLO TUBES - LH OUTBOARD SLAT PICCOLO TUBE								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-11-11-280-801					
30-11-11-280-801-02	SPECIAL DETAILED INSPECTION OF THE PICCOLO TUBES - RH OUTBOARD SLAT PICCOLO TUBE								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-11-11-280-801					
30-11-11-960-801	PICCOLO TUBES								Component	ATA:30
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 30-11-11-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-11-11-960-801-01	REPLACEMENT OF THE PICCOLO TUBES - LH OUTBOARD SLAT PICCOLO TUBE								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-11-11-960-801					
30-11-11-960-801-02	REPLACEMENT OF THE PICCOLO TUBES - LH INBOARD SLAT PICCOLO TUBE								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-11-11-960-801					
30-11-11-960-801-03	REPLACEMENT OF THE PICCOLO TUBES - RH INBOARD SLAT PICCOLO TUBE								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-11-11-960-801					
30-11-11-960-801-04	REPLACEMENT OF THE PICCOLO TUBES - RH OUTBOARD SLAT PICCOLO TUBE								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-11-11-960-801					
30-12-01-720-801-01	FUNCTIONAL TEST OF THE WING ANTI-ICING VALVES - WING ANTI-ICING VALVE (113H)								Service	ATA:30
PN:BYLB51994	MOS/MSC	13-Dec-07	O/C							
SN:334	HRS	6537.4								
WC#: 30.010	AFL	4056								
					PROC. REF: AMM 30-12-01-720-801					
30-12-01-720-801-02	FUNCTIONAL TEST OF THE WING ANTI-ICING VALVES - WING STAND-BY ANTI-ICING VALVE (97H)								Service	ATA:30
PN:NOT INSTALLED	MOS/MSC	24-Oct-91	O/C							
SN:REMOVED	HRS	0								
WC#: 30.010	AFL	0								
					PROC. REF: AMM 30-12-01-720-801					
30-12-01-720-803	IN-FLIGHT CHECK OF THE NORMAL AND EMERGENCY WING ANTI-ICING VALVES								Service	ATA:30
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-12-01-720-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-12-01-720-803-01	IN-FLIGHT CHECK OF THE NORMAL AND EMERGENCY WING ANTI-ICING VALVES								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-12-01-720-803					
30-12-05-900-801-01	REMOVAL / INSTALLATION OF THE WING ANTI-ICING PRESSURE SENSOR - PV - P'V PRESSURE PROBE (510H)								Component	ATA:30
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 30-12-05-900-801					
30-12-05-900-801-02	REMOVAL / INSTALLATION OF THE WING ANTI-ICING PRESSURE SENSOR - PRESSURE PROBE PM - P'M (512H)								Component	ATA:30
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 30-12-05-900-801					
30-12-13-900-801-01	REMOVAL / INSTALLATION OF THE WING ANTI-ICING PRESSURE SWITCHES - LH WING PRESSURE SWITCH (115H1)								Component	ATA:30
PN:8G1199-2	MOS/MSC	24-Oct-91	O/C							
SN:1307	HRS	0		TSN 0						
WC#: 30.040	AFL	0								
					PROC. REF: AMM 30-12-13-900-801					
30-12-13-900-801-02	REMOVAL / INSTALLATION OF THE WING ANTI-ICING PRESSURE SWITCHES - RH WING PRESSURE SWITCH (115H2)								Component	ATA:30
PN:8G1199-2	MOS/MSC	24-Oct-91	O/C							
SN:1309	HRS	0		TSN 0						
WC#: 30.040	AFL	0								
					PROC. REF: AMM 30-12-13-900-801					
30-20-00-710-801-01	OPERATIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM - ENGINE 1								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-20-00-710-801, AMM 30-20-00-710-801					
30-20-00-710-801-02	OPERATIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM - ENGINE 2								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-20-00-710-801, AMM 30-20-00-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-20-00-710-801-03	OPERATIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM - ENGINE 3								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-20-00-710-801, AMM 30-20-00-710-801					
30-20-01-100-801-01	CLEANING OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 1 AIR INTAKE ANTI-ICING VALVE (L103H)								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-20-01-100-801					
30-20-01-100-801-02	CLEANING OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 2 AIR INTAKE ANTI-ICING VALVE (M103H)								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-20-01-100-801					
30-20-01-100-801-03	CLEANING OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 3 AIR INTAKE ANTI-ICING VALVE (R103H)								Service	ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-20-01-100-801					
30-20-01-700-801-01	FUNCTIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 1 AIR INTAKE ANTI-ICING VALVE (L103H)								Service	ATA:30
PN:1780-00-1	MOS	07-Mar-13								
SN:969	HRS	7960.6	4000		11960.6		2968.5			
WC#: 30.070	AFL	5171								
					PROC. REF: AMM 30-20-01-700-801					
30-20-01-700-801-02	FUNCTIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 2 AIR INTAKE ANTI-ICING VALVE (M103H)								Service	ATA:30
PN:1780-00-1	MOS	07-Mar-13								
SN:0610	HRS	7960.6	4000		11960.6		2968.5			
WC#: 30.060	AFL	5171								
					PROC. REF: AMM 30-20-01-700-801					
30-20-01-700-801-03	FUNCTIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 3 AIR INTAKE ANTI-ICING VALVE (R103H)								Service	ATA:30
PN:1780-00-1	MOS	02-Apr-04								
SN:0532	HRS	5090.8	4000		9090.8		98.7			
WC#: 30.070	AFL	3124								
					PROC. REF: AMM 30-20-01-700-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-20-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 1 AIR INTAKE ANTI-ICING VALVE (L103H)								Component	ATA:30
PN:1780-00-1	MOS/MSC	07-Mar-13	O/C	TSO 0						
SN:969	HRS	7960.6		TSO 0						
WC#: 30.070	AFL	5171		TSO 0						
					PROC. REF: AMM 30-20-01-900-801, AMM 30-20-01-900-801					
30-20-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 2 AIR INTAKE ANTI-ICING VALVE (M103H)								Component	ATA:30
PN:1780-00-1	MOS/MSC	07-Mar-13	O/C	TSO 0						
SN:0610	HRS	7960.6		TSO 0						
WC#: 30.060	AFL	5171		TSO 0						
					PROC. REF: AMM 30-20-01-900-801, AMM 30-20-01-900-801					
30-20-01-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 3 AIR INTAKE ANTI-ICING VALVE (R103H)								Component	ATA:30
PN:1780-00-1	MOS/MSC	02-Apr-04	O/C	TSN 0, TSR 0						04/02/2005
SN:0532	HRS	5090.8		TSN 0, TSR 0						
WC#: 30.070	AFL	3124		TSN 0, TSR 0						
					PROC. REF: AMM 30-20-01-900-801, AMM 30-20-01-900-801					
30-20-09-900-801-01	NO. 1 ENGINE AIR INTAKE ANTI-ICING PRESSURE SWITCH								Component	ATA:30
PN:8G1199-2	MOS/MSC	24-Oct-91	O/C							
SN:1442	HRS	0		TSN 0						
WC#: 30.080	AFL	0								
					PROC. REF: AMM 30-20-09-900-801, AMM 30-20-09-900-801					
30-20-09-900-801-02	NO. 2 ENGINE AIR INTAKE ANTI-ICING PRESSURE SWITCH								Component	ATA:30
PN:8G1199-2	MOS/MSC	24-Oct-91	O/C							
SN:1092	HRS	0		TSN 0						
WC#: 30.090	AFL	0								
					PROC. REF: AMM 30-20-09-900-801, AMM 30-20-09-900-801					
30-20-09-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING PRESSURE INDICATING SWITCHES - ENGINE AIR INTAKE ANTI-ICING PRESSURE SWITCH (R107H)								Component	ATA:30
PN:8G1199-2	MOS/MSC	24-Oct-91	O/C							
SN:1281	HRS	0		TSN 0						
WC#: 30.080	AFL	0								
					PROC. REF: AMM 30-20-09-900-801					
30-20-09-900-801-04	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING PRESSURE INDICATING SWITCHES - S-DUCT ANTI-ICING PRESSURE SWITCH (109H)								Component	ATA:30
PN:8G1199-2	MOS/MSC	24-Oct-91	O/C							
SN:974	HRS	0		TSN 0						
WC#: 30.090	AFL	0								
					PROC. REF: AMM 30-20-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-20-15-900-801-01	REMOVAL / INSTALLATION OF THE SIDE ENGINE AIR INTAKE ANTI-ICING PIPES - EGINE 1 AIR INTAKE ANTI-ICING PIPES								Component	ATA:30
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 30-20-15-900-801					
30-20-15-900-801-02	REMOVAL / INSTALLATION OF THE SIDE ENGINE AIR INTAKE ANTI-ICING PIPES - EGINE 3 AIR INTAKE ANTI-ICING PIPES								Component	ATA:30
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 30-20-15-900-801					
30-20-15-900-802-01	REMOVAL / INSTALLATION OF THE CENTER ENGINE AIR INTAKE ANTI-ICING PIPES - ENGINE 2 AIR INTAKE ANTI-ICING PIPES								Component	ATA:30
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 30-20-15-900-802					
30-30-00-710-801-01 S	OPERATIONAL TEST OF THE AIR DATA PROBE ANTI-ICING SYSTEM								Service	ATA:30
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 30.300	AFL	5651								
					PROC. REF: AMM 30-30-00-710-801					PKG:21
30-41-00-710-801-01 S	OPERATIONAL TEST OF THE WINDSHIELD DE-ICING SYSTEM								Service	ATA:30
	MOS	10-Dec-03								
	HRS	4936.4	6000 (+30)							
	AFL	3069								
					PROC. REF: AMM 30-41-00-710-801					PKG:24
30-42-00-200-801-01	INSPECTION OF THE DESICCANT OF COCKPIT AFT SIDE WINDOW DEMISTING - LH REAR WINDOW (146H1)								Service	ATA:30
	MOS/MSC	03-Jun-09	O/C							
	HRS	7032.8								
WC#: 30.190	AFL	4415								
					PROC. REF: AMM 30-42-00-200-801					
30-42-00-200-801-02	INSPECTION OF THE DESICCANT OF COCKPIT AFT SIDE WINDOW DEMISTING - RH REAR WINDOW (146H2)								Service	ATA:30
	MOS/MSC	03-Jun-09	O/C							
	HRS	7032.8								
WC#: 30.190	AFL	4415								
					PROC. REF: AMM 30-42-00-200-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
30-43-00-720-801-01	FUNCTIONAL TEST OF THE WINDSHIELD WIPERS									Service ATA:30
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 30-43-00-720-801					
30-43-09-220-801-01	CHECK OF THE WINDSHIELD WIPER MOTOR BRUSHES - LH WINDSHIELD WIPER MOTOR (3M1)									Service ATA:30
PN:XW23827G1	MOS	24-Oct-91								
SN:00014	HRS	0	10000		10000		1007.9			
	AFL	0								
					PROC. REF: AMM 30-43-09-220-801					
30-43-09-220-801-02	CHECK OF THE WINDSHIELD WIPER MOTOR BRUSHES - RH WINDSHIELD WIPER MOTOR (3M2)									Service ATA:30
PN:XW23827G1	MOS	24-Oct-91								
SN:00015	HRS	0	10000		10000		1007.9			
	AFL	0								
					PROC. REF: AMM 30-43-09-220-801					
30-60-01-720-801-01	FUNCTIONAL TEST OF THE S-DUCT ANTI-ICING VALVE - S-DUCT ANTI-ICING VALVE (104H)									Service ATA:30
PN:3137-100	MOS	16-Feb-06								
SN:123	HRS	5789	4000		9789		796.9			
WC#: 30.060	AFL	3538								
					PROC. REF: AMM 30-60-01-720-801					
301050	AIRFOIL ANTI-ICING VALVE									Component ATA:30
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.210	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
301091	AIRFRAME NORMAL ANTI-ICING VALVE									Component ATA:30
PN:BYLB51994	MOS/MSC	13-Dec-07	O/C	TSR 0						
SN:334	HRS	6537.4		TSR 0						
WC#: 30.010	AFL	4056		TSR 0						
					PROC. REF: GENERIC NO REF					
301101	AIRFRAME EMERGENCY ANTI-ICING VALVE									Component ATA:30
PN:NOT INSTALLED	MOS/MSC	06-Sep-00	O/C							
SN:REMOVED	HRS	3962								
WC#: 30.010	AFL	2529								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
302111		S-DUCT ANTI-ICING VALVE								Component ATA:30
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.220	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
302116		TC-T'C DUAL TEMPERATURE PROBE (38H1)								Component ATA:30
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.230	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
302126		TV-T'V DUAL TEMPERATURE PROBE (38H3)								Component ATA:30
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.240	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
302131		NO. 2 ENGINE S-DUCT ANTI-ICING VALVE								Component ATA:30
PN:3137-100	MOS/MSC	16-Feb-06	O/C	TSR 0						
SN:123	HRS	5789		TSR 0						
WC#: 30.060	AFL	3538		TSR 0						
					PROC. REF: GENERIC NO REF					
303001		LH PITOT HEAT INDICATOR PRINTED CIRCUIT BOARD								Component ATA:30
PN:24-250	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.100	AFL	0								
					PROC. REF: GENERIC NO REF					
303106		RH PITOT HEAT INDICATOR PRINTED CIRCUIT BOARD								Component ATA:30
PN:24-250	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.100	AFL	0								
					PROC. REF: GENERIC NO REF					
304101		PILOT WINDSHIELD WIPER MOTOR								Component ATA:30
PN:XW23827G1	MOS/MSC	24-Oct-91	O/C							
SN:00014	HRS	0		TSN 0						
WC#: 30.110	AFL	0								
					PROC. REF: AMM 56-10-01-900-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
304111		COPILOT WINDSHIELD WIPER MOTOR								Component ATA:30
PN:XW23827G1	MOS/MSC	24-Oct-91	O/C							
SN:00015	HRS	0		TSN 0						
WC#: 30.110	AFL	0								
					PROC. REF: AMM 56-10-01-900-801					
304121		PILOT WINDSHIELD WIPER CONVERTER								Component ATA:30
PN:XW203453421082L	MOS/MSC	24-Oct-91	O/C							
SN:00011	HRS	0		TSN 0						
WC#: 30.120	AFL	0								
					PROC. REF: GENERIC NO REF					
304126		COPILOT WINDSHIELD WIPER CONVERTER								Component ATA:30
PN:XW203453421082R	MOS/MSC	24-Oct-91	O/C							
SN:00010	HRS	0		TSN 0						
WC#: 30.130	AFL	0								
					PROC. REF: GENERIC NO REF					
304131		PILOT WINDSHIELD FLEXIBLE DRIVE								Component ATA:30
PN:4172396	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.120	AFL	0								
					PROC. REF: AMM 56-10-01-900-801					
304136		COPILOT WINDSHIELD FLEXIBLE DRIVE								Component ATA:30
PN:4172396	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.130	AFL	0								
					PROC. REF: AMM 56-10-01-900-801					
304141		PILOT WINDSHIELD WIPER ARM								Component ATA:30
PN:4011316	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.120	AFL	0								
					PROC. REF: GENERIC NO REF					
304146		COPILOT WINDSHIELD WIPER ARM								Component ATA:30
PN:4011323	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.130	AFL	0								
					PROC. REF: GENERIC NO REF					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
304156		PILOT FRONT WINDSHIELD HEATER REGULATOR								Component ATA:30
PN:HYLZ50426-1	MOS/MSC	24-Oct-91	O/C							
SN:852D	HRS	0		TSN 0						
WC#: 30.140	AFL	0								
					PROC. REF: GENERIC NO REF					
304161		COPILOT FRONT WINDSHIELD HEATER REGULATOR								Component ATA:30
PN:HYLZ50426-1	MOS/MSC	24-Oct-91	O/C							
SN:853D	HRS	0		TSN 0						
WC#: 30.140	AFL	0								
					PROC. REF: GENERIC NO REF					
304166		PILOT SIDE WINDSHIELD HEATER REGULATOR								Component ATA:30
PN:HYLZ50422	MOS/MSC	24-Oct-91	O/C							
SN:1065D	HRS	0		TSN 0						
WC#: 30.150	AFL	0								
					PROC. REF: GENERIC NO REF					
304171		COPILOT SIDE WINDSHIELD HEATER REGULATOR								Component ATA:30
PN:HYLZ50422	MOS/MSC	24-Oct-91	O/C							
SN:1066D	HRS	0		TSN 0						
WC#: 30.150	AFL	0								
					PROC. REF: GENERIC NO REF					
304181		LH WIPER PARKING POSITION RESISTOR								Component ATA:30
PN:24-450	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.170	AFL	0								
					PROC. REF: GENERIC NO REF					
304186		WINDSHIELD DE-MIST BLOWER								Component ATA:30
PN:125XS01-62-001	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.170	AFL	0								
					PROC. REF: GENERIC NO REF					
304191		DE-MIST CIRCUIT THERMAL FUSE								Component ATA:30
PN:4257A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.170	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
304196		DE-MIST CIRCUIT RESISTOR								Component ATA:30
PN:505-0087	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.180	AFL	0								
					PROC. REF: GENERIC NO REF					
304201		DE-MIST CIRCUIT THERMOSTAT								Component ATA:30
PN:M1-140-120-182	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.180	AFL	0								
					PROC. REF: GENERIC NO REF					
304209		DE-MIST CIRCUIT SPEED SELECTOR								Component ATA:30
PN:319-100-01	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.180	AFL	0								
					PROC. REF: GENERIC NO REF					
304211		LH DESSICANT BOTTLE								Component ATA:30
PN:210-90-17-68601	MOS/MSC		O/C							
SN:SN-UNK	HRS									
WC#: 30.190	AFL									
					PROC. REF: GENERIC NO REF					
304221		RH DESSICANT BOTTLE								Component ATA:30
PN:210-90-17-68601	MOS/MSC	24-Oct-91	O/C							
SN:SN-UNK	HRS	0		TSN 0						
WC#: 30.190	AFL	0								
					PROC. REF: GENERIC NO REF					
304241		OUTSIDE AIR TEMPERATURE PROBE								Component ATA:30
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.200	AFL	0								
					PROC. REF: GENERIC NO REF					
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-11-47-960-801-01		REPLACEMENT OF THE OVERHEAD PANEL MAGNETIC SWITCHES - "BAT 1" MAGNETIC SWITCH (29P1)								Service ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
	AFL	0								
					PROC. REF: AMM 31-11-47-960-801					
31-11-47-960-801-02	REPLACEMENT OF THE OVERHEAD PANEL MAGNETIC SWITCHES - "BAT 2" MAGNETIC SWITCH (29P2)									Service ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-11-47-960-801					
31-11-47-960-801-03	REPLACEMENT OF THE OVERHEAD PANEL MAGNETIC SWITCHES - "GEN 1" MAGNETIC SWITCH (16P1)									Service ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-11-47-960-801					
31-11-47-960-801-04	REPLACEMENT OF THE OVERHEAD PANEL MAGNETIC SWITCHES - "GEN 2" MAGNETIC SWITCH (16P2)									Service ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-11-47-960-801					
31-11-47-960-801-05	REPLACEMENT OF THE OVERHEAD PANEL MAGNETIC SWITCHES - "GEN 3" MAGNETIC SWITCH (16P3)									Service ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-11-47-960-801					
31-21-05-960-801-01	REPLACEMENT OF THE PILOT CLOCK BATTERIES - LH PILOT CLOCK (93D) BATTERY									Service ATA:31
PN:811-BATT-1	MOS	29-Apr-22	25		29-May-24		210 d	SCRAP		
SN:UNKNOWN	HRS	8810.8								
WC#: 31.010	AFL	5644								
					PROC. REF: AMM 31-21-05-960-801					
31-21-05-960-801-02	REPLACEMENT OF THE PILOT CLOCK BATTERIES - RH PILOT CLOCK (103D) BATTERY									Service ATA:31
PN:811-BATT-1	MOS	29-Apr-22	25		29-May-24		210 d	SCRAP		
SN:UNKNOWN	HRS	8810.8								
WC#: 31.010	AFL	5644								
					PROC. REF: AMM 31-21-05-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-31-00-710-802-01[S]		OPERATIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) SYSTEM								Service ATA:31
PN:PN	MOS	07-Sep-22	36 (+1m)							
SN:UNKNOWN	HRS	8823								
WC#: 31.090	AFL	5651								
					PROC. REF: AMM 31-31-00-710-802					PKG:207
31-31-00-720-803-01		FUNCTIONAL TEST OF THE 32-PARAMETER FDR - FDR (2FZ)								Service ATA:31
PN:PN	MOS/MSC	24-Oct-91	N/A							
SN:UNKNOWN	HRS	0								
WC#: 31.090	AFL	0								
					PROC. REF: AMM 31-31-00-720-803					
31-31-00-970-801-01		DOWNLOAD OF THE FLIGHT DATA RECORDER (FDR) - FDR (2FZ) / FDR (130FZ)								Service ATA:31
PN:PN	MOS/MSC	24-Oct-91	A/R							
SN:UNKNOWN	HRS	0								
WC#: 31.190	AFL	0								
					PROC. REF: AMM 31-31-00-970-801					
31-31-09-710-801-01		OPERATIONAL TEST COCKPIT VOICE RECORDER ACCELERATION CONTACT								Service ATA:31
PN:400-10B	MOS	11-May-09	240 (+3%)		11-May-29	17-Dec-29	2018 d (+220)			
SN:5000	HRS	7018.9								
WC#: 31.120	AFL	4408								
					PROC. REF: AMM 31-31-09-710-801					
31-31-09-710-801-01		OPERATIONAL TEST DIGITAL FLIGHT DATA RECORDER (FDR) ACCELERATION CONTACT								Service ATA:31
	MOS/MSC	24-Oct-91	O/C					NOT INSTALLED		
	HRS	0								
WC#: 31.130	AFL	0								
					PROC. REF: AMM 31-31-09-710-801					
31-31-09-900-801-01		COCKPIT VOICE RECORDER ACCELERATION CONTACT								Component ATA:31
PN:400-10B	MOS/MSC	11-May-09	O/C	TSN 0						
SN:5000	HRS	7018.9		TSN 0						
WC#: 31.120	AFL	4408		TSN 0						
					PROC. REF: AMM 31-31-09-900-801					
31-31-09-900-801-01		DIGITAL FLIGHT DATA RECORDER (FDR) ACCELERATION CONTACT								Component ATA:31
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 31.130	AFL	0		TSN 0						
					PROC. REF: AMM 31-31-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-31-37-820-801-01	ADJUSTMENT OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - PITCH POTENTIOMETER (10FZ)								Service	ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-31-37-820-801					
31-31-37-820-801-02	ADJUSTMENT OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - YAW POTENTIOMETER (12FZ)								Service	ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-31-37-820-801					
31-31-37-820-801-03	ADJUSTMENT OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - ROLL POTENTIOMETER (11FZ)								Service	ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-31-37-820-801					
31-31-38-900-801-01	REMOVAL / INSTALLATION OF THE FDR ACCELEROMETER - FDR ACCELEROMETER (5FZ)								Component	ATA:31
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 31-31-38-900-801					
31-31-50-710-801-01[S]	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR) SYSTEM - CVR (2RK)								Service	ATA:31
	MOS	07-Sep-22	36 (+1m)							
	HRS	8823								
WC#: 31.080	AFL	5651								
					PROC. REF: AMM 31-31-50-710-801					PKG:207
31-31-50-970-801-01	DOWNLOAD OF THE COCKPIT VOICE RECORDER (CVR) - CVR (2RK)								Service	ATA:31
PN:93-A100-83	MOS/MSC	24-Oct-91	O/C							
SN:57772	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-31-50-970-801					
31-32-01-900-801-01	QUICK ACCESS (QAR) RECORDER								Component	ATA:31
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 31.140	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-32-05-960-801-01	REPLACEMENT QUICK ACCESS (QAR) RECORDER BATTERY								Service	ATA:31
PN:PN	MOS/MSC	24-Oct-91	N/A							
SN:UNKNOWN	HRS	0								
WC#: 31.140	AFL	0								
					PROC. REF: GENERIC NO REF					
31-52-00-710-801-01	OPERATIONAL TEST OF THE WARNING PANEL DUAL POWER SUPPLY - WARNING PANEL (32W)								Service	ATA:31
	MOS	09-Mar-18								
	HRS	8497.6	2400 (+30)		10897.6	10927.6	1905.5 (+30)			
	AFL	5470								
					PROC. REF: AMM 31-52-00-710-801					
31-54-00-720-801-01	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: ALARM TEST								Service	ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-54-00-720-801					
31-54-00-720-802-01[S]	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: LOGIC TEST - ALARM TEST								Service	ATA:31
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 31.040	AFL	5651								
					PROC. REF: AMM 31-54-00-720-802					PKG:21
31-54-00-720-802-02[S]	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: LOGIC TEST - TEST OF INDICATION LOGIC								Service	ATA:31
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 31-54-00-720-802					PKG:21
31-55-00-720-801-01[S]	FUNCTIONAL TEST OF THE LANDING SAFETIES								Service	ATA:31
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 31.050	AFL	5651								
					PROC. REF: AMM 31-55-00-720-801					PKG:21
31-56-00-720-801-01	FUNCTIONAL TEST OF THE AUDIO WARNING SYSTEM								Service	ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-56-00-720-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-56-00-820-801-01		ADJUSTMENT OF THE GAIN OF THE AUDIO WARNING SYSTEM DURING RUNUP							Service	ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-56-00-820-801					
31-60-00-710-801-01[S]		OPERATIONAL TEST OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED)							Service	ATA:31
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 31.180	AFL	5651								
					PROC. REF: AMM 31-60-00-710-801					PKG:21
31-60-00-710-801-01A		OPERATIONAL TEST OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED) (MANDATORY 5-40)							Service	ATA:31
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 31.180	AFL	0								
					PROC. REF: AMM 31-60-00-710-801					
31-60-51-900-801-01		REMOVAL / INSTALLATION OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED) - EIED 1 (10EA)							Component	ATA:31
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 31.170	AFL	0		TSN 0						
					PROC. REF: AMM 31-60-51-900-801					
31-60-51-900-801-02		REMOVAL / INSTALLATION OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED) - EIED 2 (20EA)							Component	ATA:31
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 31.170	AFL	0		TSN 0						
					PROC. REF: AMM 31-60-51-900-801					
31-60-51-900-801-03		REMOVAL / INSTALLATION OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED) - EIED 3 (30EA)							Component	ATA:31
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 31.170	AFL	0		TSN 0						
					PROC. REF: AMM 31-60-51-900-801					
31-60-53-960-801-01		REPLACEMENT OF THE EIED LIGHTING TUBES - EIED 1 (10EA)							Service	ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-60-53-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
31-60-53-960-801-02	REPLACEMENT OF THE EIED LIGHTING TUBES - EIED 2 (20EA)								Service	ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-60-53-960-801					
31-60-53-960-801-03	REPLACEMENT OF THE EIED LIGHTING TUBES - EIED 3 (30EA)								Service	ATA:31
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 31-60-53-960-801					
310001	WARNING PANEL								Component	ATA:31
PN:90050-3	MOS/MSC	13-Jul-11	O/C	TSN 218						
SN:158	HRS	7602.5		TSN 8651.9						
WC#: 39.010	AFL	4867		TSN 6728						
					PROC. REF: GENERIC NO REF					
310006	ELECTRONIC PANEL								Component	ATA:31
PN:203TS04Y011	MOS/MSC	08-May-12	O/C	TSR 0						
SN:128	HRS	7853.4		TSR 0						
WC#: 39.010	AFL	5085		TSR 0						
					PROC. REF: GENERIC NO REF					
310009	HYDRAULIC PANEL								Component	ATA:31
PN:694TS03Y01	MOS/MSC	24-Jan-00	O/C							
SN:348	HRS	3704								
WC#: 39.010	AFL									
					PROC. REF: GENERIC NO REF					
312001	PILOT CLOCK BATTERY								Component	ATA:31
PN:811-BATT-1	MOS/MSC	29-Apr-22	H/T	TSN 0						
SN:UNKNOWN	HRS	8810.8		TSN 0						
WC#: 31.010	AFL	5644		TSN 0						
					PROC. REF: GENERIC NO REF					
312006	COPILOT CLOCK BATTERY								Component	ATA:31
PN:811-BATT-1	MOS/MSC	29-Apr-22	H/T	TSN 0						
SN:UNKNOWN	HRS	8810.8		TSN 0						
WC#: 31.010	AFL	5644		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
312011		GROUND PROXIMITY WARNING SYSTEM COMPUTER								Component ATA:31
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 31.150	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
312016		GROUND PROXIMITY WARNING SYSTEM INVERTER								Component ATA:31
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 31.160	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
312801[U]		PILOT CLOCK								Component ATA:31
PN:811B-FTR-24HR	MOS/MSC	09-Apr-92	O/C							
SN:27570	HRS	26								
	AFL	13								
312803[U]		COPILOT CLOCK								Component ATA:31
PN:811B-FTR-24HR	MOS/MSC	09-Apr-92	O/C							
SN:27571	HRS	26								
	AFL	13								
313146[U]		CVR MICROPHONE								Component ATA:31
PN:93-A055-40	MOS/MSC	09-Apr-92	O/C							
SN:46331	HRS	26								
	AFL	13								
313149[U]		INERT CVR SWITCH								Component ATA:31
PN:6UO-114	MOS/MSC	09-Apr-92	O/C							
SN:59119	HRS	26								
	AFL	13								
315101		AUDIO WARNING UNIT								Component ATA:31
PN:164ZS01Y01	MOS/MSC	24-Oct-91	O/C							
SN:482	HRS	0		TSN 0						
WC#: 31.020	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
315111		TAKE OFF WARNING PRINTED CARD								Component ATA:31
PN:CI820A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 31.030	AFL	0								
					PROC. REF: GENERIC NO REF					
316001		COCKPIT VOICE RECORDER								Component ATA:31
PN:93-A100-83	MOS/MSC	08-Dec-06	O/C							
SN:57772	HRS	5992.2								
WC#: 31.080	AFL	3650								
					PROC. REF: GENERIC NO REF					
316008		COCKPIT VOICE RECORDER CONTROL								Component ATA:31
PN:93-A151-2001	MOS/MSC	09-Apr-92	O/C							
SN:74009	HRS	26								
WC#: 31.070	AFL	13								
					PROC. REF: GENERIC NO REF					
316021		COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON								Component ATA:31
PN:DK120/90	MOS/MSC	10-Oct-19	O/C	TSN 0						
SN:AT125863	HRS	8674.4		TSN 0						
WC#: 31.100	AFL	5580		TSN 0						
					PROC. REF: AMM 25-62-00-900-801					
316051		FLIGHT DATA RECORDER								Component ATA:31
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 31.090	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
316071		FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON								Component ATA:31
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 31.110	AFL	0		TSN 0						
					PROC. REF: AMM 25-62-00-900-801					
ATA 32 - LANDING GEAR										
32-00-00-220-801-01		CHECK OF THE MINIMUM HEIGHT OF MLG AND NLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L2GF5)								Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-00-00-220-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-00-00-220-801-02	CHECK OF THE MINIMUM HEIGHT OF MLG AND NLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R2GF5)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-00-00-220-801					
32-00-00-220-801-03	CHECK OF THE MINIMUM HEIGHT OF MLG AND NLG SHOCK ABSORBERS - NLG SHOCK ABSORBER (3GF5)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-00-00-220-801					
32-00-00-700-801-01[S]	CHECK OF THE MLG AND NLG UPLOCK BOXES - NLG UPLOCK BOX (13G)								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.940	AFL	5651								
					PROC. REF: AMM 32-00-00-700-801					PKG:21
32-00-00-700-801-02[S]	CHECK OF THE MLG AND NLG UPLOCK BOXES - LH MLG UPLOCK BOX (7G1)								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.940	AFL	5651								
					PROC. REF: AMM 32-00-00-700-801					PKG:21
32-00-00-700-801-03[S]	CHECK OF THE MLG AND NLG UPLOCK BOXES - RH MLG UPLOCK BOX (7G2)								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.940	AFL	5651								
					PROC. REF: AMM 32-00-00-700-801					PKG:21
32-00-00-780-801-01	CHECK OF LANDING GEAR AND L/G DOOR OPERATING PRESSURES								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-00-00-780-801					
32-00-00-820-801-01	REDUCTION OF TORQUE LINK END PLAY ON MAIN AND NOSE LANDING GEARS - LH MLG LEG (L2GF)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-00-00-820-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-00-00-820-801-02	REDUCTION OF TORQUE LINK END PLAY ON MAIN AND NOSE LANDING GEARS - RH MLG LEG (R2GF)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-00-00-820-801					
32-00-00-820-801-03	REDUCTION OF TORQUE LINK END PLAY ON MAIN AND NOSE LANDING GEARS - NLG LEG (3GF)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-00-00-820-801					
32-00-05-900-801-01	REMOVAL / INSTALLATION OF THE NLG AND MLG SHOCK ABSORBER CHARGING VALVES - LH MLG SHOCK ABSORBER (L2GF5)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 32-00-05-900-801					
32-00-05-900-801-02	REMOVAL / INSTALLATION OF THE NLG AND MLG SHOCK ABSORBER CHARGING VALVES - RH MLG SHOCK ABSORBER (R2GF5)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 32-00-05-900-801					
32-00-05-900-801-03	REMOVAL / INSTALLATION OF THE NLG AND MLG SHOCK ABSORBER CHARGING VALVES - NLG SHOCK ABSORBER (3GF5)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 32-00-05-900-801					
32-10-00-640-801-01	LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - LH MLG AND MLG DOORS								Service	ATA:32
	MOS	08-Sep-23	6 (+1m)	Adj -6d	31-Mar-24	02-Apr-24	151 d (+2)			
	HRS	8967								
	AFL	5775	400		6175		379			
					PROC. REF: AMM 32-10-00-640-801					
32-10-00-640-801-02	LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - RH MLG AND MLG DOORS								Service	ATA:32
	MOS	08-Sep-23	6 (+1m)	Adj -6d	31-Mar-24	02-Apr-24	151 d (+2)			
	HRS	8967								
	AFL	5775	400		6175		379			
					PROC. REF: AMM 32-10-00-640-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-10-00-700-801-01	CHECK / ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - CHECK OF CAMBER ANGLE								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-10-00-700-801					
32-10-00-700-801-02	CHECK / ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - CHECK OF L/G LOCKING IN UP POSITION								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-10-00-700-801					
32-10-00-700-801-03	CHECK / ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - CHECK OF L/G MAIN DOOR UPLOCKING								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-10-00-700-801					
32-10-00-700-802-01	GEOMETRICAL CHECK OF THE MAIN LANDING GEARS (MLG) - LH MLG LEG (L2GF)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-10-00-700-802					
32-10-00-700-802-02	GEOMETRICAL CHECK OF THE MAIN LANDING GEARS (MLG) - RH MLG LEG (R2GF)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-10-00-700-802					
32-10-00-860-801-01	MANUAL OPENING / CLOSING OF THE MLG DOORS								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-10-00-860-801					
32-11-00-220-801-01	DETAILED INSPECTION OF THE MLG LEGS - LH MLG LEG (L2GF)								Service	ATA:32
PN:C23791-1010-/-1012	MOS	07-Sep-22	72 (+8m)		07-Sep-28	07-May-29	1772 d (+242)			
SN:U208	HRS	8823								
WC#: 32.930	AFL	5651								
					PROC. REF: AMM 32-11-00-220-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-11-00-220-801-01C	DETAILED INSPECTION OF THE MLG LEGS - LH MLG LEG (L2GF) (CPCP)									Service ATA:32
	MOS	07-Sep-22	80		07-May-29		2014 d	CPCP		
	HRS	8823								
WC#: 32.015	AFL	5651								
					PROC. REF: AMM 32-11-00-220-801					
32-11-00-220-801-02	DETAILED INSPECTION OF THE MLG LEGS - RH MLG LEG (R2GF)									Service ATA:32
PN:C23792-1010-/-1012	MOS	07-Sep-22	72 (+8m)		07-Sep-28	07-May-29	1772 d (+242)			
SN:U207	HRS	8823								
WC#: 32.930	AFL	5651								
					PROC. REF: AMM 32-11-00-220-801					
32-11-00-220-801-02C	DETAILED INSPECTION OF THE MLG LEGS - RH MLG LEG (R2GF) (CPCP)									Service ATA:32
	MOS	07-Sep-22	80		07-May-29		2014 d	CPCP		
	HRS	8823								
WC#: 32.015	AFL	5651								
					PROC. REF: AMM 32-11-00-220-801					
32-11-00-350-801-01	RESTORATION OF THE MLG LEGS (OVERHAUL) - LH MLG LEG (L2GF)									Service ATA:32
PN:C23791-1010-/-1012	MOS	07-Mar-16	144 (+5m)		07-Mar-28	07-Aug-28	1588 d (+153)	OVERHAUL		
SN:U208	HRS	8278.1								
	AFL	5347	6000		11347		5551			
					PROC. REF: AMM 32-11-00-350-801					
32-11-00-350-801-02	RESTORATION OF THE MLG LEGS (OVERHAUL) - RH MLG LEG (R2GF)									Service ATA:32
PN:C23792-1010-/-1012	MOS	07-Mar-16	144 (+5m)		07-Mar-28	07-Aug-28	1588 d (+153)	OVERHAUL		
SN:U207	HRS	8278.1								
	AFL	5347	6000		11347		5551			
					PROC. REF: AMM 32-11-00-350-801					
32-11-00-700-801-01	CHECK OF THE MLG LEG GRAVITY OSCILLATIONS - LH MLG LEG (L2GF)									Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 32.130	AFL	0								
					PROC. REF: AMM 32-11-00-700-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-11-00-700-801-02	CHECK OF THE MLG LEG GRAVITY OSCILLATIONS - RH MLG LEG (R2GF)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 32.130	AFL	0								
					PROC. REF: AMM 32-11-00-700-801					
32-11-00-900-801-01	REMOVAL / INSTALLATION OF THE MLG LEGS - LH MLG LEG (L2GF)								Component	ATA:32
PN:C23791-1010-/-1012	MOS/MSC	07-Mar-16	H/T	TSO 1						
SN:U208	HRS	8278.1		TSN 8278.1, TSO 0						
WC#: 32.010	AFL	5347		TSN 5347, TSO 0						
					PROC. REF: AMM 32-11-00-900-801					
32-11-00-900-801-02	REMOVAL / INSTALLATION OF THE MLG LEGS - RH MLG LEG (R2GF)								Component	ATA:32
PN:C23792-1010-/-1012	MOS/MSC	07-Mar-16	H/T	TSO 1						
SN:U207	HRS	8278.1		TSN 8278.1, TSO 0						
WC#: 32.010	AFL	5347		TSN 5347, TSO 0						
					PROC. REF: AMM 32-11-00-900-801					
32-11-00-960-801-01	REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - LH MLG LEG (L2GF)								Service	ATA:32
PN:C23791-1010-/-1012	MOS	07-Mar-16						LIFE LIMIT		
SN:U208	HRS	8278.1								
WC#: 32.010	AFL	5347	20000	TAC 5347	20000		14204			
					PROC. REF: AMM 32-11-00-960-801					
32-11-00-960-801-01A	REPLACEMENT LH MAIN LANDING GEAR (MLG) LEG (DISCARD OF LIFE LIMITED PARTS)(MANDATORY 5-40)								Service	ATA:32
PN:C23791-1010-/-1012	MOS	07-Mar-16						MANDATORY 5-40		
SN:U208	HRS	8278.1								
	AFL	5347	20000	TAC 5347	20000		14204			
					PROC. REF: AMM 32-11-00-960-801					
32-11-00-960-801-02	REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - RH MLG LEG (R2GF)								Service	ATA:32
PN:C23792-1010-/-1012	MOS	07-Mar-16						LIFE LIMIT		
SN:U207	HRS	8278.1								
WC#: 32.010	AFL	5347	20000	TAC 5347	20000		14204			
					PROC. REF: AMM 32-11-00-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-11-00-960-801-02A	REPLACEMENT RH MAIN LANDING GEAR (MLG) LEG (DISCARD OF LIFE LIMITED PARTS)(MANDATORY 5-40)									Service ATA:32
PN:C23792-1010-/-1012	MOS	07-Mar-16						MANDATORY 5-40		
SN:U207	HRS	8278.1								
	AFL	5347	20000	TAC 5347	20000		14204			
					PROC. REF: AMM 32-11-00-960-801					
32-11-03-960-801-01	DISCARD OF THE MLG PINTLE PIN - LH MLG PINTLE PIN (L2GF7)									Service ATA:32
PN:D52554-1	MOS	24-Oct-91						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 32.060	AFL	0	18670		18670		12874			
					PROC. REF: AMM 32-11-03-960-801					
32-11-03-960-801-01A	DISCARD LH REAR MAIN LANDING GEAR (MLG) PINTLE PIN (MANDATORY 5-40)									Service ATA:32
PN:D52554-1	MOS	24-Oct-91						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
	AFL	0	18670		18670		12874			
					PROC. REF: AMM 32-11-03-960-801					
32-11-03-960-801-02	DISCARD OF THE MLG PINTLE PIN - RH MLG PINTLE PIN (R2GF7)									Service ATA:32
PN:D52554-1	MOS	24-Oct-91						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 32.060	AFL	0	18670		18670		12874			
					PROC. REF: AMM 32-11-03-960-801					
32-11-03-960-801-02A	DISCARD RH REAR MAIN LANDING GEAR (MLG) PINTLE PIN (MANDATORY 5-40)									Service ATA:32
PN:D52554-1	MOS	24-Oct-91						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
	AFL	0	18670		18670		12874			
					PROC. REF: AMM 32-11-03-960-801					
32-11-05-350-801-01	RESTORATION OF THE MLG SHOCK ABSORBER (DISCARD OF END-FITTING) - LH MLG SHOCK ABSORBER (L2GF5)									Service ATA:32
PN:D50493	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936								
	AFL	3069								
					PROC. REF: AMM 32-11-05-350-801					
32-11-05-350-801-01A	RESTORATION LH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING (DISCARD) (MANDATORY 5-40)									Service ATA:32
PN:D50493	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936								
WC#: 32.020	AFL	3069								
					PROC. REF: AMM 32-11-05-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-11-05-350-801-02	RESTORATION OF THE MLG SHOCK ABSORBER (DISCARD OF END-FITTING) - RH MLG SHOCK ABSORBER (R2GF5)								Service	ATA:32
PN:D50493	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936								
	AFL	3069								
					PROC. REF: AMM 32-11-05-350-801					
32-11-05-350-801-02A	RESTORATION RH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING (DISCARD) (MANDATORY 5-40)								Service	ATA:32
PN:D50493	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936								
WC#: 32.030	AFL	3069								
					PROC. REF: AMM 32-11-05-350-801					
32-11-05-610-801-01	SERVICING OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L2GF5)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-11-05-610-801					
32-11-05-610-801-02	SERVICING OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R2GF5)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-11-05-610-801					
32-11-05-610-802-01	CHARGING OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L2GF5)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-11-05-610-802					
32-11-05-610-802-02	CHARGING OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R2GF5)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-11-05-610-802					
32-11-05-780-801-01[S]	CHECK OF THE CHARGING PRESSURE OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L2GF5)								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.020	AFL	5651								
					PROC. REF: AMM 32-11-05-780-801					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-11-05-780-801-02[S]	CHECK OF THE CHARGING PRESSURE OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R2GF5)								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.030	AFL	5651								
					PROC. REF: AMM 32-11-05-780-801					PKG:21
32-11-05-900-801-01	REMOVAL / INSTALLATION OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L2GF5)								Component	ATA:32
PN:C23795-1004	MOS/MSC	10-Dec-03	O/C	TSN 146, TSO 0						
SN:UNKNOWN	HRS	4936.4								
WC#: 32.020	AFL	3069		TSN 3069, TSO 0						
					PROC. REF: AMM 32-11-05-900-801					
32-11-05-900-801-02	REMOVAL / INSTALLATION OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R2GF5)								Component	ATA:32
PN:C23796-1007	MOS/MSC	10-Dec-03	O/C	TSO 0						
SN:U215	HRS	4936		TSO 0						
WC#: 32.030	AFL	3069		TSO 0						
					PROC. REF: AMM 32-11-05-900-801					
32-11-05-900-802-01	REMOVAL / INSTALLATION OF THE SHOCK ABSORBER FILLING AND CHARGING TOOLS								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 32-11-05-900-802					
32-11-21-350-801-01	RESTORATION OF THE MLG BRACE ACTUATOR (DISCARD OF DASH-POT FITTING) - LH MLG BRACE STRUT ACTUATOR (12G1)								Service	ATA:32
PN:D52369	MOS/MSC	24-Oct-91	N/A							
SN:UNKNOWN	HRS	0								
WC#: 32.040	AFL	0								
					PROC. REF: AMM 32-11-21-350-801					
32-11-21-350-801-01A	RESTORATION LH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE (DISCARD)(MANDATORY 5-40)								Service	ATA:32
PN:D52369	MOS/MSC	24-Oct-91	N/A							
SN:UNKNOWN	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-11-21-350-801					
32-11-21-350-801-02	RESTORATION OF THE MLG BRACE ACTUATOR (DISCARD OF DASH-POT FITTING) - RH MLG BRACE STRUT ACTUATOR (12G2)								Service	ATA:32
PN:D52369	MOS/MSC	24-Oct-91	N/A							
SN:UNKNOWN	HRS	0								
WC#: 32.050	AFL	0								
					PROC. REF: AMM 32-11-21-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-11-21-350-801-02A	RESTORATION RH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE (DISCARD)(MANDATORY 5-40)								Service	ATA:32
PN:D52369	MOS/MSC	24-Oct-91	N/A							
SN:UNKNOWN	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-11-21-350-801					
32-11-21-900-801-01	REMOVAL / INSTALLATION OF THE MLG BRACE STRUT ACTUATORS - LH MLG BRACE STRUT ACTUATOR (12G1)								Component	ATA:32
PN:C23925-1103	MOS/MSC	24-Oct-91	O/C							
SN:B33	HRS	0		TSN 0						
WC#: 32.040	AFL	0								
					PROC. REF: AMM 32-11-21-900-801					
32-11-21-900-801-02	REMOVAL / INSTALLATION OF THE MLG BRACE STRUT ACTUATORS - RH MLG BRACE STRUT ACTUATOR (12G2)								Component	ATA:32
PN:C23926-1104	MOS/MSC	25-Aug-06	O/C	TSR 0						
SN:U133	HRS	5991.5		TSR 0						
WC#: 32.050	AFL	3649		TSR 0						
					PROC. REF: AMM 32-11-21-900-801					
32-11-25-220-801-01	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA)								Service	ATA:32
	MOS	24-Oct-91	72 (+8m)		07-Mar-28 (M)	07-Nov-28	1588 d (+245)			
	HRS	0								
	AFL	0			11347 (M)		5551			
					PROC. REF: AMM 32-11-25-220-801					
32-11-25-220-801-02	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA)								Service	ATA:32
	MOS	24-Oct-91	72 (+8m)		07-Mar-28 (M)	07-Nov-28	1588 d (+245)			
	HRS	0								
	AFL	0			11347 (M)		5551			
					PROC. REF: AMM 32-11-25-220-801					
32-11-25-220-801-03	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA)								Service	ATA:32
	MOS	24-Oct-91	72 (+8m)		07-Mar-28 (M)	07-Nov-28	1588 d (+245)			
	HRS	0								
	AFL	0			11347 (M)		5551			
					PROC. REF: AMM 32-11-25-220-801					
32-11-25-220-801-04	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA)								Service	ATA:32
	MOS	24-Oct-91	72 (+8m)		07-Mar-28 (M)	07-Nov-28	1588 d (+245)			
	HRS	0								
	AFL	0			11347 (M)		5551			
					PROC. REF: AMM 32-11-25-220-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-11-25-900-801-01	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - LH MLG FRONT BALL-JOINT BEARING (L90GA)									Component ATA:32
PN:BRS50RTGSP6	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.120	AFL	0								
					PROC. REF: AMM 32-11-25-900-801					
32-11-25-900-801-02	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - LH MLG REAR BALL-JOINT BEARING (L100GA)									Component ATA:32
PN:BRS55TAGSP2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.060	AFL	0								
					PROC. REF: AMM 32-11-25-900-801					
32-11-25-900-801-03	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - RH MLG FRONT BALL-JOINT BEARING (R90GA)									Component ATA:32
PN:BRS50RTGSP7	MOS/MSC	05-May-98	O/C	TSN 0						
SN:NSN	HRS	2753		TSN 0						
WC#: 32.120	AFL	1927		TSN 0						
					PROC. REF: AMM 32-11-25-900-801					
32-11-25-900-801-04	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - RH MLG REAR BALL-JOINT BEARING (R100GA)									Component ATA:32
PN:BRS55TAGSP2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.070	AFL	0								
					PROC. REF: AMM 32-11-25-900-801					
32-12-00-220-802-01	DETAILED INSPECTION OF THE MLG FAIRING DOOR HINGE PINS AND KNUCKLES									Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-12-00-220-802					
32-12-00-640-801-01	LUBRICATION OF THE MLG FAIRING DOOR HINGE PINS									Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-12-00-640-801					
32-12-00-640-801-02	LUBRICATION OF THE MLG FAIRING DOOR HINGE PINS									Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-12-00-640-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-12-17-900-801-01	REMOVAL / INSTALLATION OF THE MLG UPLOCK BOXES - LH MLG UPLOCK BOX (7G1)									Component ATA:32
PN:C24244-0-1	MOS/MSC	24-Oct-91	O/C							
SN:U342	HRS	0		TSN 0						
WC#: 32.310	AFL	0								
					PROC. REF: AMM 32-12-17-900-801					
32-12-17-900-801-02	REMOVAL / INSTALLATION OF THE MLG UPLOCK BOXES - RH MLG UPLOCK BOX (7G2)									Component ATA:32
PN:C24245-0-1	MOS/MSC	03-May-20	O/C							
SN:U13	HRS	8678.2								
WC#: 32.310	AFL									
					PROC. REF: AMM 32-12-17-900-801					
32-12-25-900-801-01	REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATORS - LH MLG MAIN DOOR ACTUATOR (6G1)									Component ATA:32
PN:C23735-1101	MOS/MSC	15-Dec-12	O/C							
SN:B49	HRS	7936								
WC#: 32.090	AFL	5150								
					PROC. REF: AMM 32-12-25-900-801					
32-12-25-900-801-02	REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATORS - RH MLG MAIN DOOR ACTUATOR (6G2)									Component ATA:32
PN:C23736-1101	MOS/MSC	22-Jul-04	O/C	TSR 0						
SN:U243	HRS	5219		TSR 0						
WC#: 32.090	AFL	3192		TSR 0						
					PROC. REF: AMM 32-12-25-900-801					
32-12-29-900-801-01	REMOVAL / INSTALLATION OF THE MLG DOOR UPLOCK BOXES - LH MLG MAIN DOOR UPLOCK BOX (14G1)									Component ATA:32
PN:C24257-1-3	MOS/MSC	01-Mar-12	O/C	TSO 0						
SN:U192	HRS	7780.1		TSO 0						
WC#: 32.320	AFL	5029		TSO 0						
					PROC. REF: AMM 32-12-29-900-801					
32-12-29-900-801-02	REMOVAL / INSTALLATION OF THE MLG DOOR UPLOCK BOXES - RH MLG MAIN DOOR UPLOCK BOX (14G2)									Component ATA:32
PN:C24257-1-4	MOS/MSC	07-Mar-16	O/C							
SN:H1414	HRS	8278.1								
WC#: 32.320	AFL	5347								
					PROC. REF: AMM 32-12-29-900-801					
32-20-00-640-801-01	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - NLG AND NLG DOORS									Service ATA:32
	MOS	08-Sep-23	6 (+1m)	Adj -6d	31-Mar-24	02-Apr-24	151 d (+2)			
	HRS	8967								
WC#: 32.290	AFL	5775	400		6175		379			
					PROC. REF: AMM 32-20-00-640-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-20-00-640-801-02	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - NLG SLIDING ROD LOWER BEARING								Service	ATA:32
	MOS/MSC	29-Mar-93	N/A							
	HRS	544								
WC#: 32.300	AFL	353								
					PROC. REF: AMM 32-20-00-640-801					
32-20-00-700-801-01	CHECK OF ADJUSTMENT OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - CHECK OF CASTER ANGLE								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-20-00-700-801					
32-20-00-700-801-02	CHECK OF ADJUSTMENT OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - CHECK OF NOSE GEAR UPLOCKING								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-20-00-700-801					
32-20-00-700-801-03	CHECK OF ADJUSTMENT OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - CHECK OF DOOR ADJUSTMENT								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-20-00-700-801					
32-20-00-700-802-01	GEOMETRICAL CHECK OF THE NOSE LANDING GEAR (NLG) - NLG LEG (3GF)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-20-00-700-802					
32-21-00-220-801-01	DETAILED INSPECTION OF THE NLG LEG - NLG LEG (3GF)								Service	ATA:32
PN:C23787-1007-/-/-1010	MOS	07-Sep-22	72 (+8m)	Adj -184d	07-Mar-28	07-Nov-28	1588 d (+245)			
SN:U234	HRS	8823								
WC#: 32.920	AFL	5651								
					PROC. REF: AMM 32-21-00-220-801					
32-21-00-220-801-01C	DETAILED INSPECTION OF THE NLG LEG - NLG LEG (3GF) (CPCP)								Service	ATA:32
	MOS	07-Sep-22	80		07-May-29		2014 d	CPCP		
	HRS	8823								
WC#: 32.025	AFL	5651								
					PROC. REF: AMM 32-21-00-220-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-21-00-350-801-01	RESTORATION OF THE NLG LEG (OVERHAUL) - NLG LEG (3GF)									Service ATA:32
PN:C23787-1007-/-/-1010	MOS	07-Mar-16	144 (+5m)	TAC 1	07-Feb-28	07-Jul-28	1559 d (+151)	OVERHAUL		
SN:U234	HRS	8278.1								
	AFL	5347	6000		11347		5551			
					PROC. REF: AMM 32-21-00-350-801					
32-21-00-700-801-01	CHECK OF THE NLG LEG GRAVITY OSCILLATIONS - NLG LEG (3GF)									Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 32.270	AFL	0								
					PROC. REF: AMM 32-21-00-700-801					
32-21-00-900-801-01	REMOVAL / INSTALLATION OF THE NLG LEG - NLG LEG (3GF)									Component ATA:32
PN:C23787-1007-/-/-1010	MOS/MSC	07-Mar-16	H/T	TSO 1						
SN:U234	HRS	8278.1		TSN 8278.1, TSO 0						
WC#: 32.180	AFL	5347		TSN 5347, TSO 0						
					PROC. REF: AMM 32-21-00-900-801					
32-21-00-960-801-01	REPLACEMENT OF THE NLG LEG (DISCARD OF LIFE LIMITED PARTS) - NLG LEG (3GF)									Service ATA:32
PN:C23787-1007-/-/-1010	MOS	07-Mar-16						LIFE LIMIT		
SN:U234	HRS	8278.1								
WC#: 32.180	AFL	5347	20000	TAC 5347	20000		14204			
					PROC. REF: AMM 32-21-00-960-801					
32-21-00-960-801-01A	REPLACEMENT NOSE LANDING GEAR (NLG) LEG (DISCARD OF LIFE LIMITED PARTS)(MANDATORY 5-40)									Service ATA:32
PN:C23787-1007-/-/-1010	MOS	07-Mar-16						MANDATORY 5-40		
SN:U234	HRS	8278.1								
	AFL	5347	20000	TAC 5347	20000		14204			
					PROC. REF: AMM 32-21-00-960-801					
32-21-01-610-801-01	SERVICING OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (3GF5)									Service ATA:32
PN:C23789-1003	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-21-01-610-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-21-01-610-802-01	CHARGING OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (3GF5)								Service	ATA:32
PN:C23789-1003	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-21-01-610-802					
32-21-01-780-801-01[S]	CHECK OF THE CHARGING PRESSURE OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (3GF5)								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.190	AFL	5651								
					PROC. REF: AMM 32-21-01-780-801					PKG:21
32-21-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (3GF5)								Component	ATA:32
PN:C23789-1003	MOS/MSC	10-Dec-03	O/C	TSO 0						
SN:UNKNOWN	HRS	4936.4		TSN 4936.4, TSO 0						
WC#: 32.190	AFL	3069		TSN 3069, TSO 0						
					PROC. REF: AMM 32-21-01-900-801					
32-21-09-220-801-01	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG DRAG BRACE BALL-JOINT BEARING								Service	ATA:32
	MOS	07-Sep-22	72 (+8m)		07-Sep-28	07-May-29	1772 d (+242)			
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 32-21-09-220-801					
32-21-09-220-801-02	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG DRAG BRACE BALL-JOINT BEARING								Service	ATA:32
	MOS	07-Sep-22	72 (+8m)		07-Sep-28	07-May-29	1772 d (+242)			
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 32-21-09-220-801					
32-21-09-220-801-03	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG LEG BALL-JOINT BEARING								Service	ATA:32
	MOS	07-Sep-22	72 (+8m)		07-Sep-28	07-May-29	1772 d (+242)			
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 32-21-09-220-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-21-09-220-801-04	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG LEG BALL-JOINT BEARING								Service	ATA:32
	MOS	07-Sep-22	72 (+8m)		07-Sep-28	07-May-29	1772 d (+242)			
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 32-21-09-220-801					
32-21-09-900-801-01	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - LH NLG DRAG BRACE BALL-JOINT BEARING								Component	ATA:32
PN:BRS35TAGSP5	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.250	AFL	0								
					PROC. REF: AMM 32-21-09-900-801					
32-21-09-900-801-02	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - RH NLG DRAG BRACE BALL-JOINT BEARING								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 32-21-09-900-801					
32-21-09-900-801-03	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - LH NLG LEG BALL-JOINT BEARING								Component	ATA:32
PN:BRS40TAGSP2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.240	AFL	0								
					PROC. REF: AMM 32-21-09-900-801					
32-21-09-900-801-04	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - RH NLG LEG BALL-JOINT BEARING								Component	ATA:32
PN:BRS40TAGSP2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.240	AFL	0								
					PROC. REF: AMM 32-21-09-900-801					
32-22-01-350-801-01	RESTORATION OF THE NLG DRAG BRACE YOKE ASSY (OVERHAUL) - NLG DRAG BRACE (11G)								Service	ATA:32
PN:GA58346	MOS	07-Mar-16	144 (+5m)		07-Mar-28	07-Aug-28	1588 d (+153)	OVERHAUL		
SN:U049	HRS	8278.1								
WC#: 32.210	AFL	5347	6000		11347		5551			
					PROC. REF: AMM 32-22-01-350-801					
32-22-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG DRAG BRACE - NLG DRAG BRACE (11G)								Component	ATA:32
PN:C23811-11	MOS/MSC	07-Mar-16	O/C							
SN:B4	HRS	8278.1		TSN 8278.1						
WC#: 32.210	AFL	5347		TSO 2278						
					PROC. REF: AMM 32-22-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-22-13-900-801-01	REMOVAL / INSTALLATION OF THE NLG ACTUATOR - NLG LEG ACTUATOR (500GA)								Component	ATA:32
PN:C23810-10-1	MOS/MSC	25-Sep-01	O/C							
SN:B19	HRS	4035								
WC#: 32.200	AFL	2584								
					PROC. REF: AMM 32-22-13-900-801					
32-22-17-900-801-01	REMOVAL / INSTALLATION OF THE NLG UPLOCK BOX - NLG UPLOCK BOX (13G)								Component	ATA:32
PN:C24245-4-1	MOS/MSC	24-Oct-91	O/C							
SN:U694	HRS	0		TSN 0						
WC#: 32.310	AFL	0								
					PROC. REF: AMM 32-22-17-900-801					
32-30-00-720-801-01[S]	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - NORMAL OPERATION								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 32-30-00-720-801					PKG:21
32-30-00-720-801-02[S]	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - HYDRAULIC EMERGENCY OPERATION								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 32-30-00-720-801					PKG:21
32-30-00-720-801-03[S]	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - MECHANICAL EMERGENCY OPERATION								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 32-30-00-720-801					PKG:21
32-30-13-900-801-01	REMOVAL / INSTALLATION OF THE NORMAL / EMERGENCY SELECTOR VALVE - L/G NORMAL/EMERGENCY SELECTOR VALVE (3G)								Component	ATA:32
PN:B94B09-202-1	MOS/MSC	24-Oct-91	O/C							
SN:20177	HRS	0		TSN 0						
WC#: 32.370	AFL	0								
					PROC. REF: AMM 32-30-13-900-801					
32-31-00-700-801-01[S]	CHECK OF THE LANDING GEAR RETRACTION INHIBITION ON THE GROUND								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.450	AFL	5651								
					PROC. REF: AMM 32-31-00-700-801					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-31-00-860-801-01	RETRACTION / EXTENSION OF THE LANDING GEARS									Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-31-00-860-801					
32-31-01-900-801-01	REMOVAL / INSTALLATION OF THE LANDING GEAR CONTROL LEVER - L/G CONTROL LEVER (2G)									Component ATA:32
PN:12-337-32	MOS/MSC	24-Oct-91	O/C							
SN:445	HRS	0		TSN 0						
WC#: 32.360	AFL	0								
					PROC. REF: AMM 32-31-01-900-801					
32-31-13-790-801-01S	INTERNAL LEAK CHECK OF THE LANDING GEAR SOLENOID SELECTOR VALVE - L/G SOLENOID SELECTOR VALVE (9G)									Service ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.910	AFL	5651								
					PROC. REF: AMM 32-31-13-790-801					PKG:21
32-32-00-640-801-01S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE NLG CONTROL									Service ATA:32
PN:PN	MOS	08-Sep-23	24 (+1m)							
SN:UNKNOWN	HRS	8967								
WC#: 32.430	AFL	5775								
					PROC. REF: AMM 32-32-00-640-801					PKG:16 ,15
32-32-00-640-801-02S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE NLG CONTROL ACTUATION FORCE									Service ATA:32
PN:PN	MOS	08-Sep-23	24 (+1m)							
SN:UNKNOWN	HRS	8967								
WC#: 32.430	AFL	5775								
					PROC. REF: AMM 32-32-00-640-801					PKG:16 ,15
32-32-00-640-801-03S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE MLG CONTROLS									Service ATA:32
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 32.420	AFL	5775								
					PROC. REF: AMM 32-32-00-640-801					PKG:16 ,15
32-32-00-640-801-04S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE MLG CONTROL ACTUATION FORCE									Service ATA:32
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 32.420	AFL	5775								
					PROC. REF: AMM 32-32-00-640-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-32-00-700-801-01		CHECK AFTER LANDING GEAR EMERGENCY EXTENSION							Service	ATA:32
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 32.160	AFL	0								
					PROC. REF: AMM 32-32-00-700-801					
32-32-00-820-801-01		ADJUSTMENT OF THE MECHANICAL EMERGENCY RELEASE CONTROL							Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-32-00-820-801					
32-32-05-900-801-01		REMOVAL / INSTALLATION OF THE MLG MECHANICAL EMERGENCY RELEASE CONTROL CABLES - LH MLG MECHANICAL EMERGENCY EXTENSION CONTROL CABLE (L515GA)							Component	ATA:32
PN:F50B796001110 A3	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.420	AFL	0								
					PROC. REF: AMM 32-32-05-900-801					
32-32-05-900-801-02		REMOVAL / INSTALLATION OF THE MLG MECHANICAL EMERGENCY RELEASE CONTROL CABLES - RH MLG MECHANICAL EMERGENCY EXTENSION CONTROL CABLE (R515GA)							Component	ATA:32
PN:F50B796001110 A3	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.420	AFL	0								
					PROC. REF: AMM 32-32-05-900-801					
32-32-17-640-801-01 S		SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - LUBRICATION OF THE L/G HYDRAULIC EMERGENCY EXTENTION CONTROL							Service	ATA:32
PN:F50B793001110 A3	MOS	08-Sep-23	24 (+1m)							
SN:UNKNOWN	HRS	8967								
WC#: 32.350	AFL	5775								
					PROC. REF: AMM 32-32-17-640-801					PKG:16 ,15
32-32-17-640-801-02 S		SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - CHECK OF CONTROL ACTUATION LOADS							Service	ATA:32
PN:F50B793001110 A3	MOS	08-Sep-23	24 (+1m)							
SN:UNKNOWN	HRS	8967								
WC#: 32.350	AFL	5775								
					PROC. REF: AMM 32-32-17-640-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-32-17-820-801-01		ADJUSTMENT OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE - L/G HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE (504GA)							Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-32-17-820-801					
32-32-17-900-801-01		REMOVAL / INSTALLATION OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE - L/G HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE (504GA)							Component	ATA:32
PN:F50B793001110 A3	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.350	AFL	0								
					PROC. REF: AMM 32-32-17-900-801					
32-40-00-780-801-01[S]		CHECK OF BRAKING PRESSURES - NORMAL BRAKING SYSTEM							Service	ATA:32
	MOS	17-Dec-10								
	HRS	7458.3	3000 (+30)							
WC#: 32.710	AFL	4759								
					PROC. REF: AMM 32-40-00-780-801					PKG:22
32-40-00-780-801-02[S]		CHECK OF BRAKING PRESSURES - EMERGENCY BRAKING SYSTEM							Service	ATA:32
	MOS	17-Dec-10								
	HRS	7458.3	3000 (+30)							
WC#: 32.710	AFL	4759								
					PROC. REF: AMM 32-40-00-780-801					PKG:22
32-40-00-870-801-01		BLEEDING OF THE BRAKE HYDRAULIC SYSTEM - NORMAL BRAKE SYSTEM LH BLEEDING							Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-40-00-870-801					
32-40-00-870-801-02		BLEEDING OF THE BRAKE HYDRAULIC SYSTEM - NORMAL BRAKE SYSTEM RH BLEEDING							Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-40-00-870-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-40-00-870-801-03	BLEEDING OF THE BRAKE HYDRAULIC SYSTEM - EMERGENCY BRAKE SYSTEM LH BLEEDING								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-40-00-870-801					
32-40-00-870-801-04	BLEEDING OF THE BRAKE HYDRAULIC SYSTEM - EMERGENCY BRAKE SYSTEM RH BLEEDING								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-40-00-870-801					
32-40-00-870-801-05	BLEEDING OF THE BRAKE HYDRAULIC SYSTEM - PARKING BRAKE SYSTEM BLEEDING								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-40-00-870-801					
32-41-00-710-801-01	OPERATIONAL TEST OF THE ANTI-SKID SYSTEM								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-41-00-710-801					
32-41-00-720-802-01[S]	FUNCTIONAL TEST OF THE ANTI-SKID SYSTEM								Service	ATA:32
	MOS	17-Dec-10								
	HRS	7458.3	4500 (+30)							
WC#: 32.730	AFL	4759								
					PROC. REF: AMM 32-41-00-720-802					PKG:23
32-41-00-820-801-01	ADJUSTMENT / TEST OF THE NORMAL AND EMERGENCY MODE BRAKE CONTROL								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-41-00-820-801					
32-41-23-900-801-01	REMOVAL / INSTALLATION OF THE NORMAL / EMERGENCY BRAKE SELECTOR VALVE - NORMAL/EMERGENCY BRAKE SELECTOR VALVE (501GC)								Component	ATA:32
PN:57530-2	MOS/MSC	07-Mar-16	O/C	TSR 0						
SN:239AB	HRS	8278.1		TSR 0						
WC#: 32.490	AFL	5347		TSR 0						
					PROC. REF: AMM 32-41-23-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-41-37-960-801-01[S]	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - LH MLG BRAKE FILTER (L580GC)								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.670	AFL	5651								
					PROC. REF: AMM 32-41-37-960-801					PKG:21
32-41-37-960-801-02[S]	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - RH MLG BRAKE FILTER (R580GC)								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.670	AFL	5651								
					PROC. REF: AMM 32-41-37-960-801					PKG:21
32-41-45-900-801-01	REMOVAL / INSTALLATION OF THE ANTI-SKID CONTROL UNIT - ANTI-SKID CONTROL UNIT (52G)								Component	ATA:32
PN:6002614-3	MOS/MSC	24-Oct-91	O/C							
SN:NOV89-0491	HRS	0		TSN 0						
WC#: 32.620	AFL	0								
					PROC. REF: AMM 32-41-45-900-801					
32-41-49-900-801-01	REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - LH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (53G)								Component	ATA:32
PN:9542653-1	MOS/MSC	24-Oct-91	O/C							
SN:FEB91-2883	HRS	0		TSN 0						
WC#: 32.630	AFL	0								
					PROC. REF: AMM 32-41-49-900-801					
32-41-49-900-801-02	REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - LH MLG INBOARD WHEEL TACHOMETER GENERATOR (55G)								Component	ATA:32
PN:9542653-1	MOS/MSC	24-Oct-91	O/C							
SN:FEB91-2887	HRS	0		TSN 0						
WC#: 32.630	AFL	0								
					PROC. REF: AMM 32-41-49-900-801					
32-41-49-900-801-03	REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - RH MLG INBOARD WHEEL TACHOMETER GENERATOR (56G)								Component	ATA:32
PN:9542653-1	MOS/MSC	24-Oct-91	O/C							
SN:FEB91-2889	HRS	0		TSN 0						
WC#: 32.640	AFL	0								
					PROC. REF: AMM 32-41-49-900-801					
32-41-49-900-801-04	REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - RH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (54G)								Component	ATA:32
PN:9542653-1	MOS/MSC	24-Oct-91	O/C							
SN:FEB91-2895	HRS	0		TSN 0						
WC#: 32.640	AFL	0								
					PROC. REF: AMM 32-41-49-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-41-57-350-801-01		RESTORATION OF THE BRAKE SERVOVALVES (OVERHAUL) - LH MLG BRAKE SERVOVALVE (57G1)							Service	ATA:32
PN:9542732-2	MOS	09-Apr-07	300 (+3%)		09-Apr-32	09-Jan-33	3082 d (+275)	OVERHAUL		
SN:MAY74-912D	HRS	6170.8		TAC 0						
WC#: 32.600	AFL	3779		TAC 0						
					PROC. REF: AMM 32-41-57-350-801					
32-41-57-350-801-02		RESTORATION OF THE BRAKE SERVOVALVES (OVERHAUL) - RH MLG BRAKE SERVOVALVE (57G2)							Service	ATA:32
PN:9542732-2	MOS	21-Jan-09	300 (+3%)		21-Jan-34	21-Oct-34	3734 d (+273)	OVERHAUL		
SN:JAN65-419D	HRS	6918.5		TAC 0						
WC#: 32.600	AFL	4322		TAC 0						
					PROC. REF: AMM 32-41-57-350-801					
32-41-57-900-801-01		REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - LH MLG BRAKE SERVOVALVE (57G1)							Component	ATA:32
PN:9542732-2	MOS/MSC	09-Apr-07	H/T	TSO 0						
SN:MAY74-912D	HRS	6170.8		TSO 0						
WC#: 32.600	AFL	3779		TSO 0						
					PROC. REF: AMM 32-41-57-900-801					
32-41-57-900-801-02		REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - RH MLG BRAKE SERVOVALVE (57G2)							Component	ATA:32
PN:9542732-2	MOS/MSC	21-Jan-09	H/T	TSO 0						
SN:JAN65-419D	HRS	6918.5		TSO 0						
WC#: 32.600	AFL	4322		TSO 0						
					PROC. REF: AMM 32-41-57-900-801					
32-41-57-960-801-01[S]		REPLACEMENT OF THE FILTER AND SEAL OF THE BRAKE SERVOVALVES - LH MLG BRAKE SERVOVALVE (57G1)							Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.600	AFL	5651								
					PROC. REF: AMM 32-41-57-960-801					PKG:21
32-41-57-960-801-02[S]		REPLACEMENT OF THE FILTER AND SEAL OF THE BRAKE SERVOVALVES - RH MLG BRAKE SERVOVALVE (57G2)							Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.600	AFL	5651								
					PROC. REF: AMM 32-41-57-960-801					PKG:21
32-42-00-610-801-01		SERVICING OF THE PARK BRAKE CONTROL							Service	ATA:32
PN:F50B794001A1	MOS/MSC	09-Mar-18	O/C							
SN:UNKNOWN	HRS	8497.6								
WC#: 32.590	AFL	5470								
					PROC. REF: AMM 32-42-00-610-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-42-00-720-801-01 S	FUNCTIONAL TEST OF THE PARK BRAKE SYSTEM - PARK BRAKE SYSTEM									Service ATA:32
	MOS	27-May-21								
	HRS	8754.4	3000							
	AFL	5620								
					PROC. REF: AMM 32-42-00-720-801					PKG:22
32-42-01-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE SELECTOR VALVE - PARK BRAKE SELECTOR VALVE (30GC)									Component ATA:32
PN:A24522-1	MOS/MSC	24-Oct-91	O/C							
SN:FM314	HRS	0		TSN 0						
WC#: 32.480	AFL	0								
					PROC. REF: AMM 32-42-01-900-801					
32-42-05-610-801-01	CHARGING OF THE PARK BRAKE ACCUMULATOR - PARK BRAKE ACCUMULATOR (520GC)									Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-42-05-610-801					
32-42-05-720-801-01	FUNCTIONAL TEST OF THE PARK BRAKE ACCUMULATOR CAPACITY - PARK BRAKE ACCUMULATOR (520GC)									Service ATA:32
	MOS/MSC	27-May-21	O/C							
	HRS	8754.4								
WC#: 32.720	AFL	5620								
					PROC. REF: AMM 32-42-00-720-801					
32-42-05-780-801-02	CHECK OF THE PARK BRAKE SYSTEM ACCUMULATOR PRESSURE - PARK BRAKE ACCUMULATOR (520GC)									Service ATA:32
	MOS	08-Sep-23	24 (+1m)		08-Sep-25	08-Oct-25	677 d (+30)			
	HRS	8967	2000		10967		1974.9			
	AFL	5775								
					PROC. REF: AMM 32-42-05-780-801					PKG:16 ,15
32-42-05-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE SYSTEM ACCUMULATOR - PARK BRAKE ACCUMULATOR (520GC)									Component ATA:32
PN:60833-2	MOS/MSC	24-Oct-91	O/C							
SN:779	HRS	0		TSN 0						
WC#: 32.530	AFL	0								
					PROC. REF: AMM 32-42-05-900-801					
32-42-13-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE FLEXIBLE CONTROL - PARK BRAKE CONTROL CABLE (511GC)									Component ATA:32
PN:F50B794001A1	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.590	AFL	0								
					PROC. REF: AMM 32-42-13-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-42-17-900-801-01	REMOVAL/INSTALLATION OF PARK BRAKE PRESSURE SWITCH - PARK BRAKE PRESSURE SWITCH (82G)								Component	ATA:32
PN:90G198-1	MOS/MSC	24-Oct-91	O/C							
SN:317	HRS	0		TSN 0						
WC#: 32.540	AFL	0								
					PROC. REF: AMM 32-42-17-900-801					
32-44-00-220-801-01	DETAILED INSPECTION OF THE MLG AND NLG WHEEL TIRES								Service	ATA:32
	MOS/MSC	27-May-21	O/C							
	HRS	8754.4								
WC#: 32.260	AFL	5620								
					PROC. REF: AMM 32-44-00-220-801					
32-44-00-640-801-01	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - LH MLG OUTBOARD WHEEL (L540GC)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-44-00-640-801					
32-44-00-640-801-02	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - LH MLG INBOARD WHEEL (L535GC)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-44-00-640-801					
32-44-00-640-801-03	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - RH MLG INBOARD WHEEL (R535GC)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-44-00-640-801					
32-44-00-640-801-04	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - RH MLG OUTBOARD WHEEL (R540GC)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-44-00-640-801					
32-44-00-640-801-05	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - LH NLG WHEEL (L565GC)								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-44-00-640-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-44-00-640-801-06	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - RH NLG WHEEL (R565GC)									Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-44-00-640-801					
32-44-00-780-801-01	PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES									Service ATA:32
	MOS	08-Sep-23	2 (+5d)		08-Nov-23	13-Nov-23	7 d (+5)			
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 32-44-00-780-801					
32-44-01-280-801-01	SPECIAL DETAILED INSPECTION OF THE NLG WHEELS - LH NLG WHEEL (L565GC)									Service ATA:32
PN:9543426	MOS	28-Jun-20								
SN:DEC79-1545	HRS	8685.7								
WC#: 32.560	AFL	5591	500 (+3%)		6091	6106	295 (+15)			
					PROC. REF: AMM 32-44-01-280-801					
32-44-01-280-801-02	SPECIAL DETAILED INSPECTION OF THE NLG WHEELS - RH NLG WHEEL (R565GC)									Service ATA:32
PN:9543426	MOS	28-Jun-20								
SN:OCT83-2571	HRS	8685.7								
WC#: 32.565	AFL	5591	500 (+3%)		6091	6106	295 (+15)			
					PROC. REF: AMM 32-44-01-280-801					
32-44-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG WHEELS - LH NLG WHEEL (L565GC)									Component ATA:32
PN:9543426	MOS/MSC	28-Jun-20	O/C	TSO 90						
SN:DEC79-1545	HRS	8685.7		TSO 749.7						
WC#: 32.560	AFL	5591		TSO 441						
					PROC. REF: AMM 32-44-01-900-801					
32-44-01-900-801-02	REMOVAL / INSTALLATION OF THE NLG WHEELS - RH NLG WHEEL (R565GC)									Component ATA:32
PN:9543426	MOS/MSC	28-Jun-20	O/C	TSO 0						
SN:OCT83-2571	HRS	8685.7		TSO 0						
WC#: 32.565	AFL	5591		TSO 0						
					PROC. REF: AMM 32-44-01-900-801					
32-44-05-900-801-01	REMOVAL / INSTALLATION OF THE NLG WHEEL TIRES - LH NLG TIRE (L570GC)									Component ATA:32
PN:M08301	MOS/MSC	07-Sep-22	O/C	TSN 0						
SN:2034T164	HRS	8823		TSN 0						
WC#: 32.560	AFL	5651		TSN 0						
					PROC. REF: AMM 32-44-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-44-05-900-801-02	REMOVAL / INSTALLATION OF THE NLG WHEEL TIRES - RH NLG TIRE (R570GC)									Component ATA:32
PN:M08301	MOS/MSC	07-Sep-22	O/C	TSN 0						
SN:203T145	HRS	8823		TSN 0						
WC#: 32.565	AFL	5651		TSN 0						
					PROC. REF: AMM 32-44-05-900-801					
32-44-09-280-801-01	SPECIAL DETAILED INSPECTION OF THE MLG WHEELS - LH MLG OUTBOARD WHEEL (L540GC)									Service ATA:32
PN:5003279-3	MOS	19-Mar-19								
SN:MAR82-160	HRS	8641.9								
	AFL	5555	400 (+3%)		5955	5967	159 (+12)			
					PROC. REF: AMM 32-44-09-280-801					
32-44-09-280-801-02	SPECIAL DETAILED INSPECTION OF THE MLG WHEELS - LH MLG INBOARD WHEEL (L535GC)									Service ATA:32
PN:5003279-3	MOS	19-Mar-19								
SN:APR85-939	HRS	8641.9								
	AFL	5555	400 (+3%)		5955	5967	159 (+12)			
					PROC. REF: AMM 32-44-09-280-801					
32-44-09-280-801-03	SPECIAL DETAILED INSPECTION OF THE MLG WHEELS - RH MLG INBOARD WHEEL (R535GC)									Service ATA:32
PN:5003279-3	MOS	19-Mar-19								
SN:APR89-1367	HRS	8641.9								
	AFL	5555	400 (+3%)		5955	5967	159 (+12)			
					PROC. REF: AMM 32-44-09-280-801					
32-44-09-280-801-04	SPECIAL DETAILED INSPECTION OF THE MLG WHEELS - RH MLG OUTBOARD WHEEL (R540GC)									Service ATA:32
PN:5003279-3	MOS	19-Mar-19								
SN:APR85-948	HRS	8641.9								
	AFL	5555	400 (+3%)		5955	5967	159 (+12)			
					PROC. REF: AMM 32-44-09-280-801					
32-44-09-900-801-01	REMOVAL / INSTALLATION OF THE MLG WHEELS - LH MLG OUTBOARD WHEEL (L540GC)									Component ATA:32
PN:5003279-3	MOS/MSC	19-Mar-19	O/C	TSO 0						
SN:MAR82-160	HRS	8641.9		TSO 0						
WC#: 32.570	AFL	5555		TSO 0						
					PROC. REF: AMM 32-44-09-900-801					
32-44-09-900-801-02	REMOVAL / INSTALLATION OF THE MLG WHEELS - LH MLG INBOARD WHEEL (L535GC)									Component ATA:32
PN:5003279-3	MOS/MSC	19-Mar-19	O/C	TSO 0						
SN:APR85-939	HRS	8641.9		TSO 0						
WC#: 32.575	AFL	5555		TSO 0						
					PROC. REF: AMM 32-44-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-44-09-900-801-03	REMOVAL / INSTALLATION OF THE MLG WHEELS - RH MLG INBOARD WHEEL (R535GC)									Component ATA:32
PN:5003279-3	MOS/MSC	19-Mar-19	O/C							
SN:APR89-1367	HRS	8641.9								
WC#: 32.580	AFL	5555								
					PROC. REF: AMM 32-44-09-900-801					
32-44-09-900-801-04	REMOVAL / INSTALLATION OF THE MLG WHEELS - RH MLG OUTBOARD WHEEL (R540GC)									Component ATA:32
PN:5003279-3	MOS/MSC	19-Mar-19	O/C							
SN:APR85-948	HRS	8641.9								
WC#: 32.585	AFL	5555								
					PROC. REF: AMM 32-44-09-900-801					
32-44-13-900-801-01	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - LH MLG OUTBOARD TIRE (L550GC)									Component ATA:32
PN:M08401	MOS/MSC	07-Sep-22	O/C	TSN 0						
SN:1331T270	HRS	8823		TSN 0						
WC#: 32.570	AFL	5651		TSN 0						
					PROC. REF: AMM 32-44-13-900-801					
32-44-13-900-801-02	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - LH MLG INBOARD TIRE (L545GC)									Component ATA:32
PN:M08401	MOS/MSC	07-Sep-22	O/C	TSN 0						
SN:1336T264	HRS	8823		TSN 0						
WC#: 32.575	AFL	5651		TSN 0						
					PROC. REF: AMM 32-44-13-900-801					
32-44-13-900-801-03	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - RH MLG INBOARD TIRE (R545GC)									Component ATA:32
PN:M08401	MOS/MSC	07-Sep-22	O/C	TSN 0						
SN:1333T246	HRS	8823		TSN 0						
WC#: 32.580	AFL	5651		TSN 0						
					PROC. REF: AMM 32-44-13-900-801					
32-44-13-900-801-04	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - RH MLG OUTBOARD TIRE (R550GC)									Component ATA:32
PN:M08401	MOS/MSC	07-Sep-22	O/C	TSN 0						
SN:1333T257	HRS	8823		TSN 0						
WC#: 32.585	AFL	5651		TSN 0						
					PROC. REF: AMM 32-44-13-900-801					
32-44-17-900-801-01	REMOVAL / INSTALLATION OF THE BRAKES - LH MLG OUTBOARD BRAKE (L530GC)									Component ATA:32
PN:5003280-5	MOS/MSC	04-Jun-20	O/C	TSO 0						
SN:SEP82-774	HRS	8679.95		TSO 0						
WC#: 32.460	AFL	5588		TSO 0						
					PROC. REF: AMM 32-44-17-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-44-17-900-801-02	REMOVAL / INSTALLATION OF THE BRAKES - LH MLG INBOARD BRAKE (L525GC)								Component	ATA:32
PN:5003280-5	MOS/MSC	04-Jun-20	O/C	TSO 0						
SN:MAR82-686	HRS	8679.95		TSO 0						
WC#: 32.460	AFL	5588		TSO 0						
					PROC. REF: AMM 32-44-17-900-801					
32-44-17-900-801-03	REMOVAL / INSTALLATION OF THE BRAKES - RH MLG INBOARD BRAKE (R525GC)								Component	ATA:32
PN:5003280-5	MOS/MSC	04-Jun-20	O/C	TSO 0						
SN:MAY81-400	HRS	8679.95		TSO 0						
WC#: 32.470	AFL	5588		TSO 0						
					PROC. REF: AMM 32-44-17-900-801					
32-44-17-900-801-04	REMOVAL / INSTALLATION OF THE BRAKES - RH MLG OUTBOARD BRAKE (R530GC)								Component	ATA:32
PN:5003280-5	MOS/MSC	04-Jun-20	O/C	TSO 0						
SN:JUN81-454	HRS	8679.95		TSO 0						
WC#: 32.470	AFL	5588		TSO 0						
					PROC. REF: AMM 32-44-17-900-801					
32-44-21-820-801-01	CHECK / ADJUSTMENT OF THE BRAKE SWIVEL COUPLING ALIGNMENT - CHECK OF BRAKE SWIVEL COUPLING ALIGNMENT								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-44-21-820-801					
32-44-21-820-801-02	CHECK / ADJUSTMENT OF THE BRAKE SWIVEL COUPLING ALIGNMENT - ADJUSTMENT OF BRAKE SWIVEL COUPLING ALIGNMENT								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-44-21-820-801					
32-44-21-900-801-01	REMOVAL / INSTALLATION OF THE BRAKE SWIVEL COUPLINGS - UPPER SWIVEL COUPLING (L100GC) / (R100GC) / (L101GC) / (R101GC)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 32-44-21-900-801					
32-44-21-900-801-02	REMOVAL / INSTALLATION OF THE BRAKE SWIVEL COUPLINGS - LOWER SWIVEL COUPLING (L102GC) / (R102GC) / (L103GC) / (R103GC)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 32-44-21-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-50-00-720-801-01	FUNCTIONAL TEST OF THE STEERING CONTROL SYSTEM								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-50-00-720-801					
32-50-00-720-802-01	FUNCTIONAL TEST OF THE CENTERING SYSTEM AND ANTI-SHIMMY SYSTEM								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-50-00-720-802					
32-50-00-820-801-01	ADJUSTMENT OF THE STEERING CONTROL SYSTEM								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-50-00-820-801					
32-50-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG WHEEL STEERING REPEATER BOX - STEERING REPEATER BOX (66G)								Component	ATA:32
PN:C24166-1	MOS/MSC	24-Oct-91	O/C							
SN:U437	HRS	0		TSN 0						
WC#: 32.740	AFL	0								
					PROC. REF: AMM 32-50-01-900-801					
32-50-05-900-801-01	REMOVAL / INSTALLATION OF THE STEERING HYDRAULIC UNIT - STEERING HYDRAULIC UNIT (67G)								Component	ATA:32
PN:C24248-1	MOS/MSC	24-Oct-91	O/C							
SN:U367	HRS	0		TSN 0						
WC#: 32.780	AFL	0								
					PROC. REF: AMM 32-50-05-900-801					
32-50-13-900-801-01	REMOVAL / INSTALLATION OF THE STEERING SERVOVALVE - STEERING SERVOVALVE (65G)								Component	ATA:32
PN:A25455	MOS/MSC	24-Oct-91	O/C							
SN:006	HRS	0		TSN 0						
WC#: 32.790	AFL	0								
					PROC. REF: AMM 32-50-13-900-801					
32-50-17-960-801-01[S]	REPLACEMENT OF THE STEERING SYSTEM FILTERING ELEMENT - STEERING SYSTEM FILTER (511GH)								Service	ATA:32
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 32.760	AFL	5651								
					PROC. REF: AMM 32-50-17-960-801					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-60-00-910-801-01	USE OF THE GROUND / FLIGHT BOX									Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-60-00-910-801					
32-60-00-910-802-01	USE OF THE TARGETS FOR FLIGHT SIMULATION									Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-60-00-910-802					
32-61-01-900-801-01	REMOVAL / INSTALLATION OF THE MLG HARNESSES - LH MLG ELECTRICAL HARNESS (90G1)									Component ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 32-61-01-900-801					
32-61-01-900-801-02	REMOVAL / INSTALLATION OF THE MLG HARNESSES - RH MLG ELECTRICAL HARNESS (90G2)									Component ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 32-61-01-900-801					
32-61-37-820-801-01	ADJUSTMENT / TEST OF THE MLG PROXIMITY SWITCHES									Service ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-61-37-820-801					
32-61-37-900-801-01	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - LH MLG PROXIMITY SWITCH UNIT (41G)									Component ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.850	AFL	0								
					PROC. REF: AMM 32-61-37-900-801					
32-61-37-900-801-02	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - RH MLG PROXIMITY SWITCH UNIT (42G)									Component ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.850	AFL	0								
					PROC. REF: AMM 32-61-37-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-61-37-900-801-03	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - LH MLG BRACE STRUT ACTUATOR (12G1)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.860	AFL	0								
					PROC. REF: AMM 32-61-37-900-801					
32-61-37-900-801-04	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - RH MLG BRACE STRUT ACTUATOR (12G2)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.860	AFL	0								
					PROC. REF: AMM 32-61-37-900-801					
32-61-37-900-801-05	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - LH MLG UPLOCK BOX (7G1)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.870	AFL	0								
					PROC. REF: AMM 32-61-37-900-801					
32-61-37-900-801-06	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - RH MLG UPLOCK BOX (7G2)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.870	AFL	0								
					PROC. REF: AMM 32-61-37-900-801					
32-61-37-900-801-07	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - LH MLG MAIN DOOR UPLOCK BOX (14G1)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.880	AFL	0								
					PROC. REF: AMM 32-61-37-900-801					
32-61-37-900-801-08	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - RH MLG MAIN DOOR UPLOCK BOX (14G2)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.890	AFL	0								
					PROC. REF: AMM 32-61-37-900-801					
32-61-37-900-801-09	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - LH MLG MAIN DOOR ACTUATOR (6G1)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.880	AFL	0								
					PROC. REF: AMM 32-61-37-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
32-61-37-900-801-10	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - RH MLG MAIN DOOR ACTUATOR (6G2)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.890	AFL	0								
					PROC. REF: AMM 32-61-37-900-801					
32-61-41-820-801-01	ADJUSTMENT / TEST OF THE NLG PROXIMITY SWITCHES								Service	ATA:32
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 32-61-41-820-801					
32-61-41-900-801-01	REMOVAL / INSTALLATION OF THE NLG PROXIMITY SWITCHES - NLG UPLOCK BOX (13G)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.820	AFL	0								
					PROC. REF: AMM 32-61-41-900-801					
32-61-41-900-801-02	REMOVAL / INSTALLATION OF THE NLG PROXIMITY SWITCHES - NLG PROXIMITY SWITCH UNIT (44G)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.820	AFL	0								
					PROC. REF: AMM 32-61-41-900-801					
32-61-41-900-801-03	REMOVAL / INSTALLATION OF THE NLG PROXIMITY SWITCHES - NLG DRAG BRACE (11G)								Component	ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.830	AFL	0								
					PROC. REF: AMM 32-61-41-900-801					
321102	LH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING								Component	ATA:32
PN:D50493	MOS/MSC	10-Dec-03	O/C	TSO 0						
SN:UNKNOWN	HRS	4936		TSO 0						
WC#: 32.020	AFL	3069		TSO 0						
					PROC. REF: GENERIC NO REF					
321104	LH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE								Component	ATA:32
PN:D52369	MOS/MSC	24-Oct-91	H/T							
SN:UNKNOWN	HRS	0								
WC#: 32.040	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321107		RH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING								Component ATA:32
PN:D50493	MOS/MSC	10-Dec-03	O/C	TSO 0						
SN:UNKNOWN	HRS	4936		TSO 0						
WC#: 32.030	AFL	3069		TSO 0						
					PROC. REF: GENERIC NO REF					
321109		RH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE								Component ATA:32
PN:D52369	MOS/MSC	24-Oct-91	H/T							
SN:UNKNOWN	HRS	0								
WC#: 32.050	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
321117		LH REAR MAIN LANDING GEAR (MLG) PINTLE PIN								Component ATA:32
PN:D52554-1	MOS/MSC	24-Oct-91	H/T							
SN:UNKNOWN	HRS	0								
WC#: 32.060	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
321118		RH REAR MAIN LANDING GEAR (MLG) PINTLE PIN								Component ATA:32
PN:D52554-1	MOS/MSC	24-Oct-91	H/T							
SN:UNKNOWN	HRS	0								
WC#: 32.070	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
321119		LH MAIN LANDING GEAR (MLG) BARREL								Component ATA:32
PN:C23793-10	MOS/MSC	10-Dec-03	O/C	TSO 0						
SN:UNKNOWN	HRS	4936.4								
WC#: 32.020	AFL	3069		TSO 0						
					PROC. REF: GENERIC NO REF					
321120		RH MAIN LANDING GEAR (MLG) BARREL								Component ATA:32
PN:C23794-1005	MOS/MSC	10-Dec-03	O/C	TSO 0						
SN:U207	HRS	4936		TSO 0						
WC#: 32.030	AFL	3069		TSO 0						
					PROC. REF: GENERIC NO REF					
321121		LH MAIN LANDING GEAR (MLG) BRAKE RESTRICTOR VALVE								Component ATA:32
PN:A24506-5200	MOS/MSC	24-Oct-91	O/C							
SN:U136	HRS	0		TSN 0						
WC#: 32.080	AFL	0								
					PROC. REF: GENERIC NO REF					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321126		RH MAIN LANDING GEAR (MLG) BRAKE RESTRICTOR VALVE								Component ATA:32
PN:A24506-5200	MOS/MSC	24-Oct-91	O/C							
SN:U140	HRS	0		TSN 0						
WC#: 32.080	AFL	0								
					PROC. REF: GENERIC NO REF					
321141		LH MAIN LANDING GEAR (MLG) (ACTUATOR SIDE) SHAFT								Component ATA:32
PN:C23929-0-1	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.100	AFL	0								
					PROC. REF: GENERIC NO REF					
321146		RH MAIN LANDING GEAR (MLG) (ACTUATOR SIDE) SHAFT								Component ATA:32
PN:C23929-0-1	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.100	AFL	0								
					PROC. REF: GENERIC NO REF					
321151		LH MAIN LANDING GEAR (MLG) (STRUCTURE SIDE) SHAFT								Component ATA:32
PN:C23321	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.110	AFL	0								
					PROC. REF: GENERIC NO REF					
321156		RH MAIN LANDING GEAR (MLG) (STRUCTURE SIDE) SHAFT								Component ATA:32
PN:C23321	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.110	AFL	0								
					PROC. REF: GENERIC NO REF					
322104		NOSE LANDING GEAR BARREL								Component ATA:32
PN:C23788-10	MOS/MSC	10-Dec-03	O/C	TSN 146, TSO 0						
SN:UNKNOWN	HRS	4936.4								
WC#: 32.190	AFL	3069		TSN 3069, TSO 0						
					PROC. REF: GENERIC NO REF					
322112		NOSE LANDING GEAR TELESCOPIC STRUT YOKE ASSEMBLY								Component ATA:32
PN:GA58346	MOS/MSC	07-Mar-16	H/T	TSO 0						
SN:U049	HRS	8278.1		TSO 0						
WC#: 32.210	AFL	5347		TSO 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
322131		NOSE LANDING GEAR RETRACTION STRUT RIGHT BALL-JOINT BEARING								Component ATA:32
PN:BRS35TAGSP5	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.250	AFL	0								
					PROC. REF: GENERIC NO REF					
322136		NOSE LANDING GEAR RETRACTION STRUT (STRUCTURE SIDE) SHAFT								Component ATA:32
PN:C23807	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.220	AFL	0								
					PROC. REF: GENERIC NO REF					
322141		NOSE LANDING GEAR SWIVEL COUPLING								Component ATA:32
PN:C24266-1	MOS/MSC	22-Apr-05	O/C	TSR 0						
SN:U14	HRS	5487.1		TSR 0						
WC#: 32.230	AFL	3357		TSR 0						
					PROC. REF: GENERIC NO REF					
323106		NOSE LANDING GEAR "UP" RESTRICTOR VALVE								Component ATA:32
PN:A24508-5150	MOS/MSC	24-Oct-91	O/C							
SN:U958	HRS	0		TSN 0						
WC#: 32.340	AFL	0								
					PROC. REF: GENERIC NO REF					
323111		NOSE LANDING GEAR RESTRICTOR VALVE								Component ATA:32
PN:A5060-24508	MOS/MSC	24-Oct-91	O/C							
SN:U883	HRS	0		TSN 0						
WC#: 32.080	AFL	0								
					PROC. REF: GENERIC NO REF					
323121		LANDING GEAR CIRCUIT SHUTTLE VALVE								Component ATA:32
PN:A25493-1	MOS/MSC	24-Oct-91	O/C							
SN:623	HRS	0		TSN 0						
WC#: 32.360	AFL	0								
					PROC. REF: GENERIC NO REF					
323126		LANDING GEAR DOORS CIRCUIT SHUTTLE VALVE								Component ATA:32
PN:A25493-1	MOS/MSC	24-Oct-91	O/C							
SN:599	HRS	0		TSN 0						
WC#: 32.360	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
323146		LANDING GEAR SOLENOID DIRECTIONAL VALVE								Component ATA:32
PN:A24520-1	MOS/MSC	24-Oct-91	O/C							
SN:FM288	HRS	0		TSN 0						
WC#: 32.380	AFL	0								
					PROC. REF: GENERIC NO REF					
323151		LANDING GEAR DOORS SOLENOID DIRECTIONAL VALVE								Component ATA:32
PN:A24521-102	MOS/MSC	24-Oct-91	O/C							
SN:FM967	HRS	0		TSN 0						
WC#: 32.380	AFL	0								
					PROC. REF: GENERIC NO REF					
323158		LH MAIN LANDING GEAR (MLG) DOOR MANUAL UNLOCKING CONTROL PIN								Component ATA:32
PN:F50B793600180	MOS/MSC	24-Oct-91	O/C					LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.330	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
323163		RH MAIN LANDING GEAR (MLG) DOOR MANUAL UNLOCKING CONTROL PIN								Component ATA:32
PN:F50B793600180	MOS/MSC	24-Oct-91	O/C					LIFE LIMIT		
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.330	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
323166		LH MAIN LANDING GEAR (MLG) DOOR RESTRICTOR VALVE								Component ATA:32
PN:A5150-24506	MOS/MSC	24-Oct-91	O/C							
SN:U161	HRS	0		TSN 0						
WC#: 32.390	AFL	0								
					PROC. REF: GENERIC NO REF					
323171		RH MAIN LANDING GEAR (MLG) DOOR RESTRICTOR VALVE								Component ATA:32
PN:A5150-24506	MOS/MSC	24-Oct-91	O/C							
SN:U163	HRS	0		TSN 0						
WC#: 32.400	AFL	0								
					PROC. REF: GENERIC NO REF					
323176		LH MAIN LANDING GEAR (MLG) DOWN RESTRICTOR VALVE								Component ATA:32
PN:A24508-5180	MOS/MSC	24-Oct-91	O/C							
SN:U906	HRS	0		TSN 0						
WC#: 32.390	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
323181		RH MAIN LANDING GEAR (MLG) DOWN RESTRICTOR VALVE								Component ATA:32
PN:A24508-5180	MOS/MSC	24-Oct-91	O/C							
SN:U905	HRS	0		TSN 0						
WC#: 32.400	AFL	0								
					PROC. REF: GENERIC NO REF					
323186		LH MAIN LANDING GEAR (MLG) UP RESTRICTOR VALVE								Component ATA:32
PN:A24510-5220	MOS/MSC	24-Oct-91	O/C							
SN:U47	HRS	0		TSN 0						
WC#: 32.390	AFL	0								
					PROC. REF: GENERIC NO REF					
323191		RH MAIN LANDING GEAR (MLG) UP RESTRICTOR VALVE								Component ATA:32
PN:A24510-5220	MOS/MSC	24-Oct-91	O/C							
SN:U46	HRS	0		TSN 0						
WC#: 32.400	AFL	0								
					PROC. REF: GENERIC NO REF					
323196		MAIN LANDING GEAR SUPPLY CHECK VALVE								Component ATA:32
PN:A24516	MOS/MSC	24-Oct-91	O/C							
SN:FM2824	HRS	0		TSN 0						
WC#: 32.410	AFL	0								
					PROC. REF: GENERIC NO REF					
323201		MAIN LANDING GEAR RETURN CHECK VALVE								Component ATA:32
PN:A24516	MOS/MSC	24-Oct-91	O/C							
SN:FM2820	HRS	0		TSN 0						
WC#: 32.410	AFL	0								
					PROC. REF: GENERIC NO REF					
323206		GEAR DOOR ELECTRO DISTRIBUTOR CIRCUIT RESTRICTOR VALVE								Component ATA:32
PN:A5040-24510	MOS/MSC	24-Oct-91	O/C							
SN:U69	HRS	0		TSN 0						
WC#: 32.410	AFL	0								
					PROC. REF: GENERIC NO REF					
323221		NOSE LANDING GEAR/DOOR MANUAL/EMERGENCY CONTROL CABLE								Component ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.430	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324141		NORMAL/EMERGENCY BRAKE DISTRIBUTOR								Component ATA:32
PN:57530-2	MOS/MSC	24-Oct-91	O/C							
SN:239	HRS	0		TSN 0						
WC#: 32.480	AFL	0								
					PROC. REF: GENERIC NO REF					
324151		NORMAL/BRAKE DISTRIBUTOR VALVE								Component ATA:32
PN:65660	MOS/MSC	24-Oct-91	O/C							
SN:292	HRS	0		TSN 0						
WC#: 32.490	AFL	0								
					PROC. REF: GENERIC NO REF					
324161		LH BRAKE CIRCUIT SHUTTLE VALVE								Component ATA:32
PN:CN100	MOS/MSC	24-Oct-91	O/C							
SN:232	HRS	0		TSN 0						
WC#: 32.500	AFL	0								
					PROC. REF: GENERIC NO REF					
324166		RH BRAKE CIRCUIT SHUTTLE VALVE								Component ATA:32
PN:CN100	MOS/MSC	24-Oct-91	O/C							
SN:213	HRS	0		TSN 0						
WC#: 32.500	AFL	0								
					PROC. REF: GENERIC NO REF					
324171		CENTER PARKING BRAKE CIRCUIT OVERPRESSURE VALVE								Component ATA:32
PN:A24519001	MOS/MSC	24-Oct-91	O/C							
SN:FM1052	HRS	0		TSN 0						
WC#: 32.520	AFL	0								
					PROC. REF: GENERIC NO REF					
324176		PARKING BRAKE ACCUMULATOR SUPPLY CHECK VALVE								Component ATA:32
PN:A24515	MOS/MSC	24-Oct-91	O/C							
SN:FM1942	HRS	0		TSN 0						
WC#: 32.520	AFL	0								
					PROC. REF: GENERIC NO REF					
324181		EMERGENCY BRAKE DISTRIBUTOR CHECK VALVE								Component ATA:32
PN:A24515	MOS/MSC	24-Oct-91	O/C							
SN:FM1938	HRS	0		TSN 0						
WC#: 32.510	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324186		LH BRAKE CIRCUIT SWIVEL CONNECTOR								Component ATA:32
PN:A100-24660	MOS/MSC	24-Oct-91	O/C							
SN:U11	HRS	0		TSN 0						
WC#: 32.515	AFL	0								
					PROC. REF: GENERIC NO REF					
324191		RH BRAKE CIRCUIT SWIVEL CONNECTOR								Component ATA:32
PN:A101-24660	MOS/MSC	24-Oct-91	O/C							
SN:U105	HRS	0		TSN 0						
WC#: 32.515	AFL	0								
					PROC. REF: GENERIC NO REF					
324201		PARKING BRAKE ACCUMULATOR GAUGE								Component ATA:32
PN:18040100	MOS/MSC	24-Oct-91	O/C							
SN:29638C	HRS	0		TSN 0						
WC#: 32.530	AFL	0								
					PROC. REF: GENERIC NO REF					
324211		PARKING BRAKE ACCUMULATOR FILLER VALVE								Component ATA:32
PN:MS28889-2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.530	AFL	0								
					PROC. REF: GENERIC NO REF					
324216		LH PARKING BRAKE PRESSURE SWITCH								Component ATA:32
PN:7G663-1	MOS/MSC	24-Oct-91	O/C							
SN:1067	HRS	0		TSN 0						
WC#: 32.540	AFL	0								
					PROC. REF: AMM 32-42-17-900-801					
324221		RH PARKING BRAKE PRESSURE SWITCH								Component ATA:32
PN:7G663-1	MOS/MSC	24-Oct-91	O/C							
SN:1068	HRS	0		TSN 0						
WC#: 32.540	AFL	0								
					PROC. REF: AMM 32-42-17-900-801					
324231		NORMAL BRAKING DISTRIBUTOR RETURN CIRCUIT CHECK VALVE								Component ATA:32
PN:A24516	MOS/MSC	24-Oct-91	O/C							
SN:FM2821	HRS	0		TSN 0						
WC#: 32.510	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324236		PARKING BRAKE CONTROL HANDLE								Component ATA:32
PN:4183907	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.550	AFL	0								
					PROC. REF: GENERIC NO REF					
324341		NO. 1 DRIVING CAP								Component ATA:32
PN:6002597	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.650	AFL	0								
					PROC. REF: GENERIC NO REF					
324346		NO. 2 DRIVING CAP								Component ATA:32
PN:6002597	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.650	AFL	0								
					PROC. REF: GENERIC NO REF					
324351		NO. 3 DRIVING CAP								Component ATA:32
PN:6002597	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.660	AFL	0								
					PROC. REF: GENERIC NO REF					
324356		NO. 4 DRIVING CAP								Component ATA:32
PN:6002597	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.660	AFL	0								
					PROC. REF: GENERIC NO REF					
324361		LH ANTI-SKID PRESSURE SWITCH								Component ATA:32
PN:7G612-1	MOS/MSC	20-Apr-04	O/C	TSN 0						
SN:1672	HRS	5120.9		TSN 0						
WC#: 32.610	AFL	3134		TSN 0						
					PROC. REF: GENERIC NO REF					
324366		RH ANTI-SKID PRESSURE SWITCH								Component ATA:32
PN:9542732-2	MOS/MSC	24-Oct-91	O/C							
SN:2257D	HRS	0		TSN 0						
WC#: 32.610	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324371		LH BRAKE CIRCUIT FILTER								Component ATA:32
PN:CG8104013356 N00	MOS/MSC	17-Dec-10	O/C	TSR 0						
SN:UNKNOWN	HRS	7458.3		TSR 0						
WC#: 32.670	AFL	4759		TSR 0						
					PROC. REF: GENERIC NO REF					
324381		RH BRAKE CIRCUIT FILTER								Component ATA:32
PN:285697	MOS/MSC	24-Oct-91	O/C							
SN:U2037	HRS	0		TSN 0						
WC#: 32.670	AFL	0								
					PROC. REF: GENERIC NO REF					
324391		LH BRAKE SERVO VALVE RETURN CIRCUIT CHECK VALVE								Component ATA:32
PN:A24516	MOS/MSC	24-Oct-91	O/C							
SN:FM2701	HRS	0		TSN 0						
WC#: 32.680	AFL	0								
					PROC. REF: GENERIC NO REF					
324396		RH BRAKE SERVO VALVE RETURN CIRCUIT CHECK VALVE								Component ATA:32
PN:A24516	MOS/MSC	24-Oct-91	O/C							
SN:FM2702	HRS	0		TSN 0						
WC#: 32.680	AFL	0								
					PROC. REF: GENERIC NO REF					
324401		LH BRAKE SERVO VALVE SUPPLY CIRCUIT CHECK VALVE								Component ATA:32
PN:A5140-24508	MOS/MSC	24-Oct-91	O/C							
SN:U1018	HRS	0		TSN 0						
WC#: 32.690	AFL	0								
					PROC. REF: GENERIC NO REF					
324406		RH BRAKE SERVO VALVE SUPPLY CIRCUIT CHECK VALVE								Component ATA:32
PN:A5140-24508	MOS/MSC	24-Oct-91	O/C							
SN:U1019	HRS	0		TSN 0						
WC#: 32.690	AFL	0								
					PROC. REF: GENERIC NO REF					
325106		STEERING DIRECTIONAL VALVE								Component ATA:32
PN:65670-1	MOS/MSC	24-Oct-91	O/C							
SN:1430	HRS	0		TSN 0						
WC#: 32.750	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
325111		STEERING CONTROL UNIT								Component ATA:32
PN:287837-1	MOS/MSC	08-Dec-06	O/C							
SN:U785	HRS	5992.2								
WC#: 32.750	AFL	3650								
					PROC. REF: GENERIC NO REF					
325116		STEERING FILTER								Component ATA:32
PN:CG8104013356 N00	MOS/MSC	17-Dec-10	O/C	TSO 0						
SN:UNKNOWN	HRS	7458.3		TSO 0						
WC#: 32.760	AFL	4759		TSO 0						
					PROC. REF: GENERIC NO REF					
325126		STEERING AMPLIFIER								Component ATA:32
PN:C24242	MOS/MSC	24-Oct-91	O/C							
SN:U153	HRS	0		TSN 0						
WC#: 32.770	AFL	0								
					PROC. REF: GENERIC NO REF					
326006		L/G CONTROL PRINTED CIRCUIT BOARD								Component ATA:32
PN:CI823A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.800	AFL	0								
					PROC. REF: GENERIC NO REF					
326011		NA-BLANK PRINTED CIRCUIT								Component ATA:32
PN:CI846A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.800	AFL	0								
					PROC. REF: GENERIC NO REF					
326026		LH MAIN LANDING GEAR (MLG) LEG DUAL PROXIMITY SWITCH								Component ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.840	AFL	0								
					PROC. REF: GENERIC NO REF					
326031		RH MAIN LANDING GEAR (MLG) LEG DUAL PROXIMITY SWITCH								Component ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.840	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
326076		NOSE GEAR LEG DUAL PROXIMITY SWITCH								Component ATA:32
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.830	AFL	0								
					PROC. REF: GENERIC NO REF					
326101		LANDING GEAR UP IAS INDICATOR SWITCH								Component ATA:32
PN:4219G010201	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.810	AFL	0								
					PROC. REF: GENERIC NO REF					
A 32-11-10		MLG TORQUE LINK – DAMAGE DATA								Service ATA:32
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 32-11-10					
R 32-11-25		CHAMFERING THE ANGLES OF THE MLG BALL-JOINT BEARING CAGES								Service ATA:32
	MOS/MSC	07-Sep-22	A/R							
	HRS	8823								
	AFL	5651								
					PROC. REF: SRM 32-11-25					
ATA 33 - LIGHTS										
33-10-00-710-802-01		OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF PILOT DOME LIGHT (74L1) AND COPILOT DOME LIGHT (74L2)								Service ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-00-710-802-02		OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF LH CIRCUIT BREAKER PANEL SPOTLIGHT (55L1) AND RH CIRCUIT BREAKER PANEL SPOTLIGHT (55L2)								Service ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-10-00-710-802-03	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF PILOT WINDSHIELD ICE DETECTION SPOT LIGHT (27L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-00-710-802-04	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF PILOT READING LIGHT (53L1)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-00-710-802-05	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF COPILOT READING LIGHT (53L2)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-00-710-802-06	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF LIGHTS CONTROLLED THROUGH THE WARNING PANEL (32W) ?TEST? SWITCH								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-00-710-802-07	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF LIGHTS CONTROLLED THROUGH THE LH "INSTRUMENTS" POTENTIOMETER (92L1)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-00-710-802-08	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF LIGHTS CONTROLLED THROUGH THE RH "INSTRUMENTS" POTENTIOMETER (92L2)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-00-710-802-09	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF LIGHTS CONTROLLED THROUGH THE "SHIELD" POTENTIOMETER (42L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-10-00-710-802-10	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF LIGHTS CONTROLLED THROUGH THE "OVERHEAD" POTENTIOMETER (63L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-00-710-802-11	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF LIGHTS CONTROLLED THROUGH THE LH "SIDE/CENTER" POTENTIOMETER (82L1)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-00-710-802-12	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF LIGHTS CONTROLLED THROUGH THE RH "SIDE/CENTER" POTENTIOMETER (82L2)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-00-710-802-13	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF LIGHTS CONTROLLED THROUGH THE LH "DIGITS" POTENTIOMETER (223L1)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-00-710-802-14	OPERATIONAL TEST OF COCKPIT LIGHTS - TEST OF LIGHTS CONTROLLED THROUGH THE RH "DIGITS" POTENTIOMETER (223L2)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-00-710-802					
33-10-07-900-801-01	REMOVAL/INSTALLATION OF THE COCKPIT DOME LIGHTS - PILOT DOME LIGHT (74L1)								Component	ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-10-07-900-801					
33-10-07-900-801-02	REMOVAL/INSTALLATION OF THE COCKPIT DOME LIGHTS - COPILOT DOME LIGHT (74L2)								Component	ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-10-07-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-10-09-960-801-01	REPLACEMENT OF THE GLARESHIELD LIGHTS - PILOT GLARESHIELD STRIP LIGHT (44L1)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-09-960-801					
33-10-09-960-801-02	REPLACEMENT OF THE GLARESHIELD LIGHTS - COPILOT GLARESHIELD STRIP LIGHT (44L2)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-10-09-960-801					
33-20-00-200-802-01	CHECK OF THE CONNECTION OF "SELA" LIGHTING TUBES								Service	ATA:33
	MOS/MSC	10-Dec-03	N/A							
	HRS	4936.4								
WC#: 33.240	AFL	3069								
					PROC. REF: AMM 33-20-00-200-802					
33-30-01-710-801-01	OPERATIONAL TEST OF THE NOSE CONE, BAGGAGE AND REAR COMPARTMENT LIGHTING - LH DOME LIGHT (77L1)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-30-01-710-801					
33-30-01-710-801-02	OPERATIONAL TEST OF THE NOSE CONE, BAGGAGE AND REAR COMPARTMENT LIGHTING - RH DOME LIGHT (77L2)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-30-01-710-801					
33-30-01-710-801-03	OPERATIONAL TEST OF THE NOSE CONE, BAGGAGE AND REAR COMPARTMENT LIGHTING - DOME LIGHT (75L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-30-01-710-801					
33-30-01-710-801-04	OPERATIONAL TEST OF THE NOSE CONE, BAGGAGE AND REAR COMPARTMENT LIGHTING - INSPECTION HAND-LIGHT (78L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-30-01-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-30-01-710-801-05	OPERATIONAL TEST OF THE NOSE CONE, BAGGAGE AND REAR COMPARTMENT LIGHTING - BAGGAGE COMPARTMENT DOOR LIGHT (88L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-30-01-710-801					
33-30-01-710-801-06	OPERATIONAL TEST OF THE NOSE CONE, BAGGAGE AND REAR COMPARTMENT LIGHTING - REFUELING AREA LIGHT (95L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-30-01-710-801					
33-40-00-710-801-01	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH RED NAVIGATION LIGHT (23L) OR (23L) / (28L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-00-710-801-02	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH GREEN NAVIGATION LIGHT (24L) OR (24L) / (29L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-00-710-801-03	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - REAR WHITE NAVIGATION/ANTI-COLLISION LIGHT (25L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-00-710-801-04	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH WING WHITE ANTI-COLLISION LIGHT (133L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-00-710-801-05	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH WING WHITE ANTI-COLLISION LIGHT (134L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-40-00-710-801-06	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - UPPER ANTI-COLLISION LIGHT (17L)									Service ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-00-710-801-07	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - BELLY ANTI-COLLISION LIGHT (15L)									Service ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-00-710-801-08	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH LANDING LIGHT (3L1)									Service ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-00-710-801-09	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH LANDING LIGHT (3L2)									Service ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-00-710-801-10	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - TAXI LIGHT (9L)									Service ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-00-710-801-11	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH ICE DETECTION LIGHT (143L1)									Service ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-00-710-801-12	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH ICE DETECTION LIGHT (143L2)									Service ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-40-00-710-801-13	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH LOGO LIGHT (294L1)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-00-710-801-14	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH LOGO LIGHT (294L2)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-00-710-801					
33-40-01-900-801-01	REMOVAL / INSTALLATION OF THE WING NAVIGATION LIGHTS - LH WING TIP NAVIGATION LIGHT LAMPS								Component	ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-40-01-900-801					
33-40-01-900-801-02	REMOVAL / INSTALLATION OF THE WING NAVIGATION LIGHTS - RH WING TIP NAVIGATION LIGHT LAMPS								Component	ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-40-01-900-801					
33-40-07-900-801-01	REMOVAL / INSTALLATION OF THE WHITE REAR NAVIGATION LIGHT - WHITE REAR NAVIGATION LIGHT (25L) .								Component	ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-40-07-900-801					
33-40-07-900-802-01	REMOVAL / INSTALLATION OF THE WHITE REAR NAVIGATION / ANTI-COLLISION LIGHT - WHITE REAR NAVIGATION/ANTI-COLLISION LIGHT (25L) .								Component	ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-40-07-900-802					
33-40-07-960-801-01	REPLACEMENT OF THE WHITE REAR NAVIGATION / ANTI-COLLISION LIGHT FLASH TUBE - WHITE REAR NAVIGATION/ANTI-COLLISION LIGHT (25L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-07-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-40-07-960-802-01	REPLACEMENT OF THE WHITE REAR NAVIGATION/ANTI-COLLISION LIGHT BULBS - WHITE REAR NAVIGATION/ANTI-COLLISION LIGHT (25L) BULBS							Service		ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-07-960-802					
33-40-09-900-802-01	REMOVAL / INSTALLATION OF UPPER ANTI-COLLISION LIGHT - UPPER ANTI-COLLISION LIGHT (17L)							Component		ATA:33
PN:30-1136-9	MOS/MSC	24-Oct-91	O/C							
SN:2759	HRS	0		TSN 0						
WC#: 33.140	AFL	0								
					PROC. REF: AMM 33-40-09-900-802					
33-40-09-960-804-01	REPLACEMENT OF UPPER AND LOWER ANTI-COLLISION LIGHT BULBS (WHELEN) - UPPER ANTI-COLLISION LIGHT (17L) OR (4LX)							Service		ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-09-960-804					
33-40-09-960-804-02	REPLACEMENT OF UPPER AND LOWER ANTI-COLLISION LIGHT BULBS (WHELEN) - BELLY ANTI-COLLISION LIGHT (15L)							Service		ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-09-960-804					
33-40-09-960-805-01	REPLACEMENT OF UPPER AND LOWER ANTI-COLLISION LIGHT FLASH TUBES (GRIMES) - UPPER ANTI-COLLISION LIGHT (17L) OR (4LX)							Service		ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-09-960-805					
33-40-09-960-805-02	REPLACEMENT OF UPPER AND LOWER ANTI-COLLISION LIGHT FLASH TUBES (GRIMES) - BELLY ANTI-COLLISION LIGHT (15L)							Service		ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-09-960-805					
33-40-31-960-801-01	REPLACEMENT OF THE FLASH TUBE OF THE WING WHITE ANTI-COLLISION LIGHT - LH WING WHITE ANTI-COLLISION LIGHT (133L)							Service		ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-31-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-40-31-960-801-02	REPLACEMENT OF THE FLASH TUBE OF THE WING WHITE ANTI-COLLISION LIGHT - RH WING WHITE ANTI-COLLISION LIGHT (134L)							Service		ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-31-960-801					
33-40-31-960-802-01	REPLACEMENT OF THE WING WHITE ANTI-COLLISION LIGHTS - LH WING WHITE ANTI-COLLISION LIGHT (133L)							Service		ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-31-960-802					
33-40-31-960-802-02	REPLACEMENT OF THE WING WHITE ANTI-COLLISION LIGHTS - RH WING WHITE ANTI-COLLISION LIGHT (134L)							Service		ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-31-960-802					
33-40-33-900-801-01	REMOVAL / INSTALLATION OF THE LOGO LIGHTS - LH UPPER LOGO LIGHT (294L1)							Component		ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-40-33-900-801					
33-40-33-900-801-02	REMOVAL / INSTALLATION OF THE LOGO LIGHTS - RH UPPER LOGO LIGHT (294L2)							Component		ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-40-33-900-801					
33-40-33-900-802-01	LH UPPER LOGO LIGHT							Component		ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-40-33-900-801					
33-40-33-900-802-02	RH UPPER LOGO LIGHT							Component		ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-40-33-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-40-33-900-802-03	LH LOWER LOGO LIGHT									Component ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-40-33-900-801					
33-40-33-900-802-04	RH LOWER LOGO LIGHT									Component ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-40-33-900-801					
33-40-33-960-801-01	REPLACEMENT OF THE LOGO LIGHT BULB - LH UPPER LOGO LIGHT (294L1) BULB									Service ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-33-960-801					
33-40-33-960-801-02	REPLACEMENT OF THE LOGO LIGHT BULB - RH UPPER LOGO LIGHT (294L2) BULB									Service ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-33-960-801					
33-40-37-200-801-01	CHECK OF THE LANDING LIGHTS - LH LANDING LIGHT (3L1)									Service ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-37-200-801					
33-40-37-200-801-02	CHECK OF THE LANDING LIGHTS - RH LANDING LIGHT (3L2)									Service ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-37-200-801					
33-40-37-900-801-01	REMOVAL / INSTALLATION OF THE LANDING LIGHTS - LH LANDING LIGHT (3L1)									Component ATA:33
PN:751-1002-001	MOS/MSC	07-Mar-16	O/C	TSN 0						
SN:HPL-000202	HRS	8278.1		TSN 0						
WC#: 33.150	AFL	5347		TSN 0						
					PROC. REF: AMM 33-40-37-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-40-37-900-801-02	REMOVAL / INSTALLATION OF THE LANDING LIGHTS - RH LANDING LIGHT (3L2)								Component	ATA:33
PN:751-1002-001	MOS/MSC	07-Mar-16	O/C	TSN 0						
SN:HPL-792	HRS	8278.1		TSN 0						
WC#: 33.150	AFL	5347		TSN 0						
					PROC. REF: AMM 33-40-37-900-801					
33-40-37-960-801-01	REPLACEMENT OF THE LANDING LIGHT OPTICAL UNITS								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-37-960-801					
33-40-41-820-801-01	ADJUSTMENT OF THE TAXI LIGHT - TAXI LIGHT (9L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-41-820-801					
33-40-41-900-801-01	REMOVAL / INSTALLATION OF THE TAXI LIGHT - TAXI LIGHT (9L)								Component	ATA:33
PN:4060622	MOS/MSC	24-Oct-91	O/C							
SN:57932	HRS	0		TSN 0						
WC#: 33.160	AFL	0								
					PROC. REF: AMM 33-40-41-900-801					
33-40-41-900-802-01	REMOVAL / INSTALLATION OF THE TAXI LIGHT CIRCUIT PROXIMITY SENSOR - PROXIMITY SWITCH (20L)								Component	ATA:33
PN:8-240-02	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.170	AFL	0								
					PROC. REF: AMM 33-40-41-900-802					
33-40-41-960-801-01	REPLACEMENT OF THE TAXI LIGHT BULB - TAXI LIGHT (9L) BULB								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-41-960-801					
33-40-53-960-801-01	REPLACEMENT OF THE WHITE REAR ANTI-COLLISION LIGHT POWER SUPPLY BOX - WHITE REAR ANTI-COLLISION LIGHT POWER SUPPLY BOX (137L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-53-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-40-65-960-801-01	REPLACEMENT OF THE WING ANTI-COLLISION LIGHT POWER SUPPLY BOXES - POWER SUPPLY UNIT (135L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-65-960-801					
33-40-65-960-801-02	REPLACEMENT OF THE WING ANTI-COLLISION LIGHT POWER SUPPLY BOXES - POWER SUPPLY UNIT (136L)								Service	ATA:33
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 33-40-65-960-801					
33-50-00-710-804-01[S]	OPERATIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM								Service	ATA:33
	MOS	24-Oct-91								
	HRS	0	4500							
	AFL	0								
					PROC. REF: AMM 33-50-00-710-804					PKG:23
33-50-00-720-801-01	FUNCTIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM - EPS 1 (113L)								Service	ATA:33
PN:D734-02-001	MOS/MSC	07-Sep-22	O/C							
SN:2091/06-2003	HRS	8823								
WC#: 33.100	AFL	5651								
33-50-00-720-801-02	FUNCTIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM - EPS 2 (114L1)								Service	ATA:33
PN:D734-02-001	MOS/MSC	29-Apr-22	O/C							
SN:3291074	HRS	8810.8								
WC#: 33.110	AFL	5644								
					PROC. REF: AMM 33-50-00-720-801					
33-50-00-720-801-03	FUNCTIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM - EPS 3 (114L2)								Service	ATA:33
PN:D734-02-001	MOS/MSC	07-Sep-22	O/C							
SN:319	HRS	8823								
WC#: 33.120	AFL	5651								
					PROC. REF: AMM 33-50-00-720-801					
33-50-33-610-801-01	SERVICING NO. 1 (113L) EMERGENCY (EPS 1) POWER SUPPLY								Service	ATA:33
PN:D734-02-001	MOS/MSC	07-Sep-22	O/C							
SN:2091/06-2003	HRS	8823								
WC#: 33.100	AFL	5651								
					PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-50-33-610-801-02	SERVICING NO. 2 (114L1) EMERGENCY (EPS 2) POWER SUPPLY								Service	ATA:33
PN:D734-02-001	MOS/MSC	29-Apr-22	O/C							
SN:3291074	HRS	8810.8								
WC#: 33.110	AFL	5644								
					PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801					
33-50-33-610-801-03	SERVICING NO. 3 (114L2) EMERGENCY (EPS 3) POWER SUPPLY								Service	ATA:33
PN:D734-02-001	MOS/MSC	07-Sep-22	O/C							
SN:319	HRS	8823								
WC#: 33.120	AFL	5651								
					PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801					
33-50-33-900-801-01	REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 1 (113L)								Component	ATA:33
PN:D734-02-001	MOS/MSC	19-Jul-21	O/C	TSO 0						
SN:2091/06-2003	HRS	8762		TSO 0						
WC#: 33.100	AFL	5623		TSO 0						
					PROC. REF: AMM 33-50-33-900-801					
33-50-33-900-801-02	REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 2 (114L1)								Component	ATA:33
PN:D734-02-001	MOS/MSC	29-Apr-22	O/C	TSO 0						
SN:3291074	HRS	8810.8		TSO 0						
WC#: 33.110	AFL	5644		TSO 0						
					PROC. REF: AMM 33-50-33-900-801					
33-50-33-900-801-03	REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 3 (114L2)								Component	ATA:33
PN:D734-02-001	MOS/MSC	09-Dec-20	O/C	TSO 87						
SN:319	HRS	8676.4		TSO 608.7						
WC#: 33.120	AFL	5582		TSO 358						
					PROC. REF: AMM 33-50-33-900-801					
33-50-37-900-801-01	REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 1 (113L) BATTERY PACK								Component	ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-50-37-900-801					
33-50-37-900-801-02	REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 2 (114L1) BATTERY PACK								Component	ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-50-37-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
33-50-37-900-801-03	REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 3 (114L2) BATTERY PACK									Component ATA:33
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 33-50-37-900-801					
33-50-37-960-802-01	DISCARD OF THE EPS BATTERY PACKS - EPS 1 (113L) BATTERY PACK									Service ATA:33
PN:D734-02-001	MOS	07-Sep-22	24		07-Sep-24		311 d	LIFE LIMIT		
SN:2091/06-2003	HRS	8823								
WC#: 33.100	AFL	5651								
					PROC. REF: AMM 33-50-37-960-802					
33-50-37-960-802-02	DISCARD OF THE EPS BATTERY PACKS - EPS 2 (114L1) BATTERY PACK									Service ATA:33
PN:D734-02-001	MOS	29-Apr-22	24		29-Apr-24		180 d	LIFE LIMIT		
SN:3291074	HRS	8810.8								
WC#: 33.110	AFL	5644								
					PROC. REF: AMM 33-50-37-960-802					
33-50-37-960-802-03	DISCARD OF THE EPS BATTERY PACKS - EPS 3 (114L2) BATTERY PACK									Service ATA:33
PN:D734-02-001	MOS	07-Sep-22	24		07-Sep-24		311 d	LIFE LIMIT		
SN:319	HRS	8823								
WC#: 33.120	AFL	5651								
					PROC. REF: AMM 33-50-37-960-802					
331101	FLIGHT COMPARTMENT LEFT READING LIGHT									Component ATA:33
PN:10-0027-1	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.010	AFL	0								
					PROC. REF: GENERIC NO REF					
331106	FLIGHT COMPARTMENT RIGHT READING LIGHT									Component ATA:33
PN:10-0027-1	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.020	AFL	0								
					PROC. REF: GENERIC NO REF					
331111	LH SPOT LIGHT									Component ATA:33
PN:4X650	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.010	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
331113		LOWER LIGHT ASSEMBLY								Component ATA:33
PN:10-50B	MOS/MSC	01-Oct-02	O/C	TSR 0						
SN:075	HRS	4494.2		TSR 0						
WC#: 33.010	AFL	2855		TSR 0						
					PROC. REF: GENERIC NO REF					
331116		RH SPOT LIGHT								Component ATA:33
PN:4X650	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.020	AFL	0								
					PROC. REF: GENERIC NO REF					
331118		UPPER LIGHT ASSEMBLY								Component ATA:33
PN:10-50T	MOS/MSC	01-Oct-02	O/C	TSR 0						
SN:01004	HRS	4494.2		TSR 0						
WC#: 33.020	AFL	2855		TSR 0						
					PROC. REF: GENERIC NO REF					
331121		GLARE SHIELD LIGHTING POWER SUPPLY								Component ATA:33
PN:17-3019-1	MOS/MSC	24-Oct-91	O/C							
SN:1206	HRS	0		TSN 0						
WC#: 33.030	AFL	0								
					PROC. REF: GENERIC NO REF					
331126		PILOT LIGHTING UNIT POWER SUPPLY								Component ATA:33
PN:24-54	MOS/MSC	24-Oct-91	O/C							
SN:848	HRS	0		TSN 0						
WC#: 33.040	AFL	0								
					PROC. REF: GENERIC NO REF					
331131		COPILOT LIGHTING UNIT POWER SUPPLY								Component ATA:33
PN:24-54	MOS/MSC	02-Aug-18	O/C							
SN:09	HRS	8543.6								
WC#: 33.040	AFL	5498								
					PROC. REF: GENERIC NO REF					
331136		LH CONSOLE UNIT POWER SUPPLY								Component ATA:33
PN:24-54	MOS/MSC	24-Oct-91	O/C							
SN:1031	HRS	0		TSN 0						
WC#: 33.050	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
331141		RH CONSOLE UNIT POWER SUPPLY								Component ATA:33
PN:24-54	MOS/MSC	24-Oct-91	O/C							
SN:1048	HRS	0		TSN 0						
WC#: 33.050	AFL	0								
					PROC. REF: GENERIC NO REF					
331146		OVERHEAD PANEL POWER SUPPLY								Component ATA:33
PN:24-014	MOS/MSC	24-Mar-06	O/C	TSR 0						
SN:330	HRS	5817		TSR 0						
WC#: 33.030	AFL	3556		TSR 0						
					PROC. REF: GENERIC NO REF					
331151		LH SEGMENTS UNIT POWER SUPPLY								Component ATA:33
PN:24-52-4	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.060	AFL	0								
					PROC. REF: GENERIC NO REF					
331156		RH SEGMENTS UNIT POWER SUPPLY								Component ATA:33
PN:24-52-4	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.060	AFL	0								
					PROC. REF: GENERIC NO REF					
332101		LH EMERGENCY EXIT LIGHT								Component ATA:33
PN:30-1358-17	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.080	AFL	0								
					PROC. REF: GENERIC NO REF					
332106		RH EMERGENCY EXIT LIGHT								Component ATA:33
PN:30-1358-17	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.080	AFL	0								
					PROC. REF: GENERIC NO REF					
332825[U]		FWD OVERHEAD CABIN LIGHTING INVERTER								Component ATA:33
PN:AL-5114	MOS/MSC	21-Jun-04	O/C	TSR 0						
SN:5903	HRS	5197.9		TSR 0						
	AFL	3177		TSR 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
333827[U]		523LP POWER SUPPLY								Component ATA:33
PN:AL-5118	MOS/MSC	21-Jan-99	O/C	TSO 0						
SN:380	HRS	3003		TSO 0						
	AFL	2083		TSO 0						
334106		LOWER ANTI-COLLISION LIGHT								Component ATA:33
PN:30-1136-11	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.140	AFL	0								
					PROC. REF: GENERIC NO REF					
334116		UPPER ANTI-COLLISION LIGHTS UNIT POWER SUPPLY								Component ATA:33
PN:60-2667-3	MOS/MSC	24-Oct-91	O/C							
SN:2619	HRS	0		TSN 0						
WC#: 33.070	AFL	0								
					PROC. REF: AMM 33-40-65-960-801					
334121		LOWER ANTI-COLLISION LIGHTS UNIT POWER SUPPLY								Component ATA:33
PN:60-2667-3	MOS/MSC	10-May-10	O/C	TSO 0						
SN:567	HRS	7309.3		TSO 0						
WC#: 33.070	AFL	4638		TSO 0						
					PROC. REF: AMM 33-40-65-960-801					
334146		LH WING STROBE LIGHT								Component ATA:33
PN:39-28-21	MOS/MSC	15-May-23	O/C							
SN:NSN	HRS	8954.2								
WC#: 33.180	AFL	5760								
					PROC. REF: GENERIC NO REF					
334151		RIGHT WING STROBE LIGHT								Component ATA:33
PN:39-28-21	MOS/MSC	24-Oct-91	O/C							
SN:539	HRS	0		TSN 0						
WC#: 33.180	AFL	0								
					PROC. REF: GENERIC NO REF					
334156		LH WING STROBE UNIT POWER SUPPLY								Component ATA:33
PN:6480702	MOS/MSC	15-May-23	O/C							
SN:661	HRS	8954.2								
WC#: 33.190	AFL	5760								
					PROC. REF: GENERIC NO REF					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
334161		RH WING STROBE UNIT POWER SUPPLY								Component ATA:33
PN:39-42-1	MOS/MSC	28-Oct-20	O/C	TSO 0						
SN:528	HRS	8701		TSO 0						
WC#: 33.190	AFL	5598		TSO 0						
					PROC. REF: GENERIC NO REF					
334171		TAIL NAVIGATION LIGHT								Component ATA:33
PN:03-9302-4002	MOS/MSC	07-Mar-16	O/C	TSN 0						
SN:287300012	HRS	8278.1		TSN 0						
WC#: 33.200	AFL	5347		TSN 0						
					PROC. REF: GENERIC NO REF					
334851[U]		PULSELITE CONTROL								Component ATA:33
PN:24000-25-4-4	MOS/MSC	09-Apr-92	O/C							
SN:K00540	HRS	26								
	AFL	13								
334873[U]		ORDINANCE L/H AFT LIGHT								Component ATA:33
PN:WS4101RL	MOS/MSC	25-Jun-99	O/C	TSN 0						
SN:990510013	HRS	3266		TSN 0						
	AFL	2203		TSN 0						
334874[U]		LEFT HAND FORWARD ORDINANCE LIGHT								Component ATA:33
PN:WS4101RL	MOS/MSC	22-Mar-02	O/C	TSN 0						
SN:0000901008	HRS	4208		TSN 0						
	AFL	2704		TSN 0						
335121		LH EVACUATION LIGHT								Component ATA:33
PN:30-0424-9	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.090	AFL	0								
					PROC. REF: GENERIC NO REF					
335126		RH EVACUATION LIGHT								Component ATA:33
PN:30-0424-9	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.090	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
336096[U]		NO. 3 ANTI-ICE WARNING LIGHT							Component	ATA:33
PN:588VR01E1N72-20	MOS/MSC	26-Apr-04	O/C	TSN 0						
SN:040331046	HRS	5126.2		TSN 0						
	AFL	3136		TSN 0						
ATA 34 - NAVIGATION										
34-00-00-700-801-01		CHECK OF THE COLLINS EQUIPMENT INTERNAL BATTERY - COLLINS FLIGHT MANAGEMENT COMPUTER 1 BATTERY							Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-00-00-700-801					
34-00-00-700-801-02		CHECK OF THE COLLINS EQUIPMENT INTERNAL BATTERY - COLLINS FLIGHT MANAGEMENT COMPUTER 2 BATTERY							Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-00-00-700-801					
34-00-00-700-801-03		CHECK OF THE COLLINS EQUIPMENT INTERNAL BATTERY - COLLINS FLIGHT MANAGEMENT COMPUTER 3 BATTERY (A/C WITH THIRD FMS)							Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-00-00-700-801					
34-00-00-700-801-04		CHECK OF THE COLLINS EQUIPMENT INTERNAL BATTERY - MDC BATTERY							Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-00-00-700-801					
34-00-00-700-801-05		CHECK OF THE COLLINS EQUIPMENT INTERNAL BATTERY - ADC 1 BATTERY							Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-00-00-700-801					
34-00-00-700-801-06		CHECK OF THE COLLINS EQUIPMENT INTERNAL BATTERY - ADC 2 BATTERY							Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-00-00-700-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-00-00-760-801-01	CHECK OF THE RADIO-NAVIGATION ANTENNA ELECTRICAL BONDING								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-00-00-760-801					
34-00-00-910-802-01	PRECAUTIONS TO BE TAKEN WHEN REMOVING SPERRY GYROSCOPES AND INDICATORS FROM STORAGE								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-00-00-910-802					
34-01-00-720-801-01	FUNCTIONAL TEST OF THE EFIS SYSTEM								Service	ATA:34
	MOS/MSC	24-Aug-18	N/A							
	HRS									
WC#: 34.640	AFL									
					PROC. REF: AMM 34-01-00-720-801, AMM 34-01-00-720-801, AMM 34-01-00-720-801					
34-01-13-900-801-01	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - PFD 1 (L360NH)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.230	AFL	0		TSN 0						
					PROC. REF: AMM 34-01-13-900-801					
34-01-13-900-801-02	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - PFD 2 (R360NH)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.230	AFL	0		TSN 0						
					PROC. REF: AMM 34-01-13-900-801					
34-01-13-900-801-03	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - MFD 1 (L361NH)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.240	AFL	0		TSN 0						
					PROC. REF: AMM 34-01-13-900-801					
34-01-13-900-801-04	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - MFD 2 (R361NH)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.240	AFL	0		TSN 0						
					PROC. REF: AMM 34-01-13-900-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-01-25-710-801-07[S]		OPERATIONAL TEST OF THE EFIS FANS - EFIS FANS								Service ATA:34
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 34.630	AFL	5651								
					PROC. REF: AMM 34-01-25-710-801, AMM 34-01-25-710-801, AMM 34-01-25-710-801					PKG:21
34-02-01-710-801-01		OPERATIONAL TEST OF THE ATTITUDE DIRECTOR INDICATORS (ADI)								Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-02-01-710-801					
34-10-00-700-801-01		OPERATIONS TO BE PERFORMED AFTER REMOVAL / INSTALLATION OF THE AIR DATA SYSTEM PNEUMATIC COMPONENTS - AIR DATA SYSTEM PNEUMATIC COMPONENTS								Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-10-00-700-801					
34-10-00-700-881-01		TEST PILOT AIR DATA (ADC) COMPUTER (FAR 91.411)								Service ATA:34
PN:622-8329-646	MOS	01-Feb-22	24		01-Feb-24		92 d	MANDATORY		
SN:659	HRS									
WC#: 34.510	AFL									
					PROC. REF: GENERIC NO REF, FAR 91.411					
34-10-00-700-881-02		TEST COPILOT AIR DATA (ADC) COMPUTER (FAR 91.411)								Service ATA:34
PN:622-8329-100	MOS	01-Feb-22	24		01-Feb-24		92 d	MANDATORY		
SN:656	HRS									
WC#: 34.520	AFL									
					PROC. REF: GENERIC NO REF, FAR 91.411					
34-10-00-700-881-03		TEST STAND BY ALTIMETER (FAR 91.411)								Service ATA:34
PN:8047/10	MOS	01-Feb-22	24		01-Feb-24		92 d	MANDATORY		
SN:8653	HRS									
WC#: 34.530	AFL									
					PROC. REF: GENERIC NO REF, FAR 91.411					
34-10-00-720-801-01[S]		FUNCTIONAL TEST OF THE AIR DATA SYSTEM								Service ATA:34
	MOS	08-Sep-23	24 (+1m)					RVSM		
	HRS	8967								
WC#: 34.105	AFL	5775								
					PROC. REF: AMM 34-10-00-720-801, AMM 34-10-00-720-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-10-00-720-802-01		FUNCTIONAL TEST PILOT AIR DATA (ADC) COMPUTER								Service ATA:34
PN:622-8329-646	MOS	07-Sep-22	24 (+3%)		07-Sep-24	28-Sep-24	311 d (+21)			
SN:659	HRS	8823								
WC#: 34.510	AFL	5651								
					PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802					
34-10-00-720-802-02		FUNCTIONAL TEST COPILOT AIR DATA (ADC) COMPUTER								Service ATA:34
PN:622-8329-100	MOS	07-Sep-22	24 (+3%)		07-Sep-24	28-Sep-24	311 d (+21)			
SN:656	HRS	8823								
WC#: 34.520	AFL	5651								
					PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802					
34-10-00-720-802-03		FUNCTIONAL TEST STAND BY ALTIMETER								Service ATA:34
PN:8047/10	MOS/MSC	01-Feb-22	O/C							
SN:8653	HRS	8793.2								
WC#: 34.530	AFL	5636								
					PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802					
34-10-00-720-802-04		FUNCTIONAL TEST STANDBY MACH-AIRSPEED INDICATOR								Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 34.535	AFL	0								
					PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802					
34-10-00-720-802-05		FUNCTIONAL TEST STANDBY AIR DATA UNIT								Service ATA:34
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 34.560	AFL	0								
					PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802					
34-10-00-860-801-01		PREPARATION AND USE OF THE AIR DATA BENCH								Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-10-00-860-801					
34-10-01-700-881-01		TEST STANDBY AIR DATA UNIT (FAR 91.411)								Service ATA:34
	MOS/MSC		N/A							
	HRS									
WC#: 34.560	AFL									
					PROC. REF: GENERIC NO REF, FAR 91.413					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-10-01-900-801-01	REMOVAL / INSTALLATION OF THE OUTSIDE AIR TEMPERATURE PROBE - OUTSIDE AIR TEMPERATURE PROBE (185F)									Component ATA:34
PN:102AU1CK	MOS/MSC	24-Oct-91	O/C							
SN:89433	HRS	0		TSN 0						
WC#: 34.100	AFL	0								
					PROC. REF: AMM 34-10-01-900-801					
34-10-02-700-881-01	TEST PILOT ALTIMETER (FAR 91.411)									Service ATA:34
PN:622-3975-005	MOS	01-Feb-22	24		01-Feb-24		92 d	MANDATORY		
SN:576	HRS									
WC#: 34.040	AFL									
					PROC. REF: GENERIC NO REF, FAR 91.411					
34-10-02-700-881-02	TEST COPILOT ALTIMETER (FAR 91.411)									Service ATA:34
PN:622-3975-005	MOS	01-Feb-22	24		01-Feb-24		92 d	MANDATORY		
SN:7156	HRS									
WC#: 34.040	AFL									
					PROC. REF: GENERIC NO REF, FAR 91.411					
34-10-11-720-801-01[S]	CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - LH AOA SENSOR (52F1)									Service ATA:34
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 34-10-11-720-801					PKG:31
34-10-11-720-801-02[S]	CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - RH AOA SENSOR (52F2)									Service ATA:34
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 34-10-11-720-801					PKG:31
34-10-11-720-802-01	RESISTANCE CHECK OF THE AOA SENSOR POTENTIOMETERS									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-10-11-720-802					
34-10-11-900-801-01	REMOVAL / INSTALLATION OF THE ANGLE-OF-ATTACK SENSOR - LH AOA SENSOR (52F1)									Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.200	AFL	0								
					PROC. REF: AMM 34-10-11-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-10-11-900-801-02	REMOVAL / INSTALLATION OF THE ANGLE-OF-ATTACK SENSOR - RH AOA SENSOR (52F2)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.200	AFL	0								
					PROC. REF: AMM 34-10-11-900-801					
34-11-00-200-801-01	CHECK OF THE TOTAL / STATIC PRESSURE SYSTEM FOR CLOGGING								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-11-00-200-801					
34-11-00-680-801-01[S]	DRAINING OF THE TOTAL / STATIC PRESSURE SYSTEM								Service	ATA:34
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 34.110	AFL	5775								
					PROC. REF: AMM 34-11-00-680-801					PKG:16 ,15
34-11-00-790-801-01	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - PILOT STATIC AIR PRESSURE SYSTEM								Service	ATA:34
	MOS/MSC	02-Mar-18	O/C							
	HRS	8497.6								
WC#: 34.120	AFL	5470								
					PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801					
34-11-00-790-801-02	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - PILOT TOTAL AIR PRESSURE SYSTEM								Service	ATA:34
	MOS/MSC	02-Mar-18	O/C							
	HRS	8497.6								
	AFL	5470								
					PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801					
34-11-00-790-801-03	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - COPILOT STATIC AIR PRESSURE SYSTEM								Service	ATA:34
	MOS/MSC	02-Mar-18	O/C							
	HRS	8497.6								
	AFL	5470								
					PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801					
34-11-00-790-801-04	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - COPILOT TOTAL AIR PRESSURE SYSTEM								Service	ATA:34
	MOS/MSC	02-Mar-18	O/C							
	HRS	8497.6								
	AFL	5470								
					PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-00-790-801-05	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - STAND-BY STATIC AIR PRESSURE SYSTEM								Service	ATA:34
	MOS/MSC	29-Apr-19	O/C							
	HRS									
	AFL									
					PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801					
34-11-01-100-801-01	INSPECTION AND CLEANING OF THE TOTAL PRESSURE PROBES								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-11-01-100-801					
34-11-01-200-801-01	CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - LH TOTAL PRESSURE PROBE (14F1)								Service	ATA:34
	MOS	08-Sep-23	12 (+1m)	Adj -1d	07-Sep-24	07-Oct-24	311 d (+30)			
	HRS	8967	300 (+30)		9267	9297	274.9 (+30)			
	AFL	5775								
					PROC. REF: AMM 34-11-01-200-801					
34-11-01-200-801-02	CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - RH TOTAL PRESSURE PROBE (14F2)								Service	ATA:34
	MOS	08-Sep-23	12 (+1m)	Adj -1d	07-Sep-24	07-Oct-24	311 d (+30)			
	HRS	8967	300 (+30)		9267	9297	274.9 (+30)			
	AFL	5775								
					PROC. REF: AMM 34-11-01-200-801					
34-11-01-900-801-01	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - LH TOTAL PRESSURE PROBE (14F1)								Component	ATA:34
PN:50520	MOS/MSC	08-Aug-05	O/C							
SN:3525	HRS	5566.9								
WC#: 34.080	AFL	3419								
					PROC. REF: AMM 34-11-01-900-801					
34-11-01-900-801-02	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - RH TOTAL PRESSURE PROBE (14F2)								Component	ATA:34
PN:50520	MOS/MSC	30-Nov-98	O/C							11/30/1999
SN:UNKNOWN	HRS	2995								
WC#: 34.080	AFL	2071								
					PROC. REF: AMM 34-11-01-900-801					
34-11-05-900-801-01	REMOVAL / INSTALLATION OF THE STATIC PRESSURE PROBES - LH STATIC PRESSURE PROBE (16F1)								Component	ATA:34
PN:44320	MOS/MSC	24-Oct-91	O/C							
SN:607	HRS	0		TSN 0						
WC#: 34.090	AFL	0								
					PROC. REF: AMM 34-11-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-05-900-801-02	REMOVAL / INSTALLATION OF THE STATIC PRESSURE PROBES - RH STATIC PRESSURE PROBE (16F2)									Component ATA:34
PN:44320	MOS/MSC	24-Oct-91	O/C							
SN:608	HRS	0		TSN 0						
WC#: 34.090	AFL	0								
					PROC. REF: AMM 34-11-05-900-801					
34-11-07-900-801-01	PILOT RATE OF CLIMB INDICATOR HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C	TSN 0				NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.150	AFL									
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-02	COPILOT RATE OF CLIMB INDICATOR HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C	TSN 0				NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.150	AFL									
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-03	LH PILOT AIRSPEED MACHMETER INDICATOR HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C	TSN 0				NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.160	AFL									
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-04	LH COPILOT AIRSPEED MACHMETER INDICATOR HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C	TSN 0				NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.170	AFL									
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-05	RH PILOT AIRSPEED MACHMETER INDICATOR HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C	TSN 0				NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.160	AFL									
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-06	RH COPILOT AIRSPEED MACHMETER INDICATOR HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C	TSN 0				NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.170	AFL									
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-07-900-801-07	EMERGENCY ALTIMETER HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C	TSN 0				NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.180	AFL									
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-08	COPILOT ALTIMETER HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C	TSN 0				NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.180	AFL									
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-09	CABIN TRIPLE INDICATOR HOSE									Component ATA:34
PN:19645L0500	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.190	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-10	NOSE CONE ACTUATOR HOSE									Component ATA:34
PN:6780060005	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.190	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-11	PILOT PITOT HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C							
SN:UNKNOWN	HRS									
WC#: 34.200	AFL									
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-12	COPILOT PITOT HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C	TSN 0				NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.200	AFL									
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-13	PILOT LOWER STATIC HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C	TSN 0				NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.210	AFL									
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-07-900-801-14	COPILOT LOWER STATIC HOSE									Component ATA:34
PN:6780060013	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.220	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-15	PILOT UPPER STATIC HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C					NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.210	AFL									
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-16	COPILOT UPPER STATIC HOSE									Component ATA:34
PN:6780060013	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.220	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-17	PILOT SOLENOID VALVE LOWER HOSE									Component ATA:34
PN:6780060016	MOS/MSC	06-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.230	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-18	COPILOT SOLENOID VALVE FRONT HOSE									Component ATA:34
PN:6780060009	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.240	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-19	PILOT SOLENOID VALVE CENTER HOSE									Component ATA:34
PN:6780060011	MOS/MSC	06-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.235	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-20	COPILOT SOLENOID VALVE CENTER HOSE									Component ATA:34
PN:19644L0225	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.245	AFL	3069								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-07-900-801-21	PILOT SOLENOID VALVE UPPER HOSE									Component ATA:34
PN:6780060034	MOS/MSC	06-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.230	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-22	COPILOT SOLENOID VALVE REAR HOSE									Component ATA:34
PN:6780060010	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.240	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-23	AIR DATA COMPUTER PITOT HOSE									Component ATA:34
PN:6780060003	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.250	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-24	COPILOT AIR DATA COMPUTER PITOT HOSE									Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0								
WC#: 34.270	AFL	0								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-25	RH MANIFOLD BLOCK/COP. S/V HOSE									Component ATA:34
PN:19644L0415	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.260	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-26	AIR DATA COMPUTER STATIC HOSE									Component ATA:34
PN:6780060011	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.250	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-27	COPILOT AIR DATA COMPUTER STATIC HOSE									Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0								
WC#: 34.270	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-07-900-801-28	L/G IAS SWITCH PITOT HOSE									Component ATA:34
PN:07034L0660	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0								
WC#: 34.280	AFL	0								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-29	AILERON ARTHUR PITOT HOSE									Component ATA:34
PN:19644L0350	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.290	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-30	L/G IAS SWITCH STATIC HOSE									Component ATA:34
PN:07035L0600	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0								
WC#: 34.280	AFL	0								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-31	AILERON ARTHUR STATIC HOSE									Component ATA:34
PN:6780060015	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.290	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-32	SLATS IAS SWITCH PITOT HOSE									Component ATA:34
PN:1964460225	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.300	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-33	ELEVATOR ARTHUR PITOT HOSE									Component ATA:34
PN:19644L0310	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.310	AFL	3064								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-34	SLATS IAS SWITCH STATIC HOSE									Component ATA:34
PN:6780060032	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.300	AFL	3069								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-07-900-801-35	ELEVATOR ARTHUR STATIC HOSE									Component ATA:34
PN:6780060014	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.310	AFL	3064								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-36	PRESSURE TRANSMITTER HOSE									Component ATA:34
PN:PN	MOS/MSC		O/C	TSN 0				NOT INSTALLED		
SN:UNKNOWN	HRS									
WC#: 34.320	AFL									
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-37	NO. 1 ENGINE FUEL COMPUTER PT2 HOSE									Component ATA:34
PN:19644L0385	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.330	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-38	NO. 2 ENGINE FUEL COMPUTER PT2 HOSE									Component ATA:34
PN:19644L0310	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.335	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-900-801-39	NO. 3 ENGINE FUEL COMPUTER PT2 HOSE									Component ATA:34
PN:19644L0385	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.330	AFL	3069								
					PROC. REF: GENERIC NO REF					
34-11-07-960-801-01	DISCARD OF THE ELASTOMER HOSES INSTALLED ON TOTAL AND STATIC PRESSURE LINES									Service ATA:34
	MOS/MSC		O/C	TAC 0						
	HRS									
WC#: 34.150	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-02	DISCARD COPILOT RATE OF CLIMB INDICATOR HOSE									Service ATA:34
	MOS/MSC		O/C	TAC 0						
	HRS									
WC#: 34.150	AFL									
					PROC. REF: AMM 34-11-07-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-07-960-801-03	DISCARD LH PILOT AIRSPEED MACHMETER INDICATOR HOSE									Service ATA:34
	MOS/MSC		O/C	TAC 0						
	HRS									
WC#: 34.160	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-04	DISCARD LH COPILOT AIRSPEED MACHMETER INDICATOR HOSE									Service ATA:34
	MOS/MSC		O/C	TAC 0						
	HRS									
WC#: 34.170	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-05	DISCARD RH PILOT AIRSPEED MACHMETER INDICATOR HOSE									Service ATA:34
	MOS/MSC		O/C	TAC 0						
	HRS									
WC#: 34.160	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-06	DISCARD RH COPILOT AIRSPEED MACHMETER INDICATOR HOSE									Service ATA:34
	MOS/MSC		O/C	TAC 0						
	HRS									
WC#: 34.170	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-07	DISCARD EMERGENCY ALTIMETER HOSE									Service ATA:34
	MOS/MSC		O/C	TAC 0						
	HRS									
WC#: 34.180	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-08	DISCARD COPILOT ALTIMETER HOSE									Service ATA:34
	MOS/MSC		O/C	TAC 0						
	HRS									
WC#: 34.180	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-09	DISCARD CABIN TRIPLE INDICATOR HOSE									Service ATA:34
PN:19645L0500	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.190	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-07-960-801-10	DISCARD NOSE CONE ACTUATOR HOSE									Service ATA:34
PN:6780060005	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.190	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-11	DISCARD PILOT PITOT HOSE									Service ATA:34
	MOS/MSC		O/C							
	HRS									
WC#: 34.200	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-12	DISCARD COPILOT PITOT HOSE									Service ATA:34
	MOS/MSC		O/C	TAC 0						
	HRS									
WC#: 34.200	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-13	DISCARD PILOT LOWER STATIC HOSE									Service ATA:34
	MOS/MSC		O/C	TAC 0						
	HRS									
WC#: 34.210	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-14	DISCARD COPILOT LOWER STATIC HOSE									Service ATA:34
PN:6780060013	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.220	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-15	DISCARD PILOT UPPER STATIC HOSE									Service ATA:34
	MOS/MSC		O/C							
	HRS									
WC#: 34.210	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-16	DISCARD COPILOT UPPER STATIC HOSE									Service ATA:34
PN:6780060013	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.220	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty

ATA 34 - NAVIGATION

34-11-07-960-801-17	DISCARD PILOT SOLENOID VALVE LOWER HOSE									Service ATA:34
PN:6780060016	MOS/MSC	06-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.230	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-18	DISCARD COPILOT SOLENOID VALVE FRONT HOSE									Service ATA:34
PN:6780060009	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.240	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-19	DISCARD PILOT SOLENOID VALVE CENTER HOSE									Service ATA:34
PN:6780060011	MOS/MSC	06-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.235	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-20	DISCARD COPILOT SOLENOID VALVE CENTER HOSE									Service ATA:34
PN:19644L0225	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.245	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-21	DISCARD PILOT SOLENOID VALVE UPPER HOSE									Service ATA:34
PN:6780060034	MOS/MSC	06-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.230	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-22	DISCARD COPILOT SOLENOID VALVE REAR HOSE									Service ATA:34
PN:6780060010	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.240	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-23	DISCARD AIR DATA COMPUTER PITOT HOSE									Service ATA:34
PN:6780060003	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.250	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-07-960-801-24	DISCARD COPILOT AIR DATA COMPUTER PITOT HOSE								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C	TAC 0						
	HRS	0								
WC#: 34.270	AFL	0								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-25	DISCARD RH MANIFOLD BLOCK/COP. S/V HOSE								Service	ATA:34
PN:19644L0415	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.260	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-26	DISCARD AIR DATA COMPUTER STATIC HOSE								Service	ATA:34
PN:6780060011	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.250	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-27	DISCARD COPILOT AIR DATA COMPUTER STATIC HOSE								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C	TAC 0						
	HRS	0								
WC#: 34.270	AFL	0								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-28	DISCARD L/G IAS SWITCH PITOT HOSE								Service	ATA:34
PN:07034L0660	MOS/MSC	24-Oct-91	O/C	TAC 0						
SN:UNKNOWN	HRS	0								
WC#: 34.260	AFL	0								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-29	DISCARD AILERON ARTHUR PITOT HOSE								Service	ATA:34
PN:19644L0350	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.270	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-30	DISCARD L/G IAS SWITCH STATIC HOSE								Service	ATA:34
PN:07035L0600	MOS/MSC	24-Oct-91	O/C	TAC 0						
SN:UNKNOWN	HRS	0								
WC#: 34.280	AFL	0								
					PROC. REF: AMM 34-11-07-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-07-960-801-31	DISCARD AILERON ARTHUR STATIC HOSE									Service ATA:34
PN:6780060015	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.290	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-32	DISCARD SLATS IAS SWITCH PITOT HOSE									Service ATA:34
PN:1964460225	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.300	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-33	DISCARD ELEVATOR ARTHUR PITOT HOSE									Service ATA:34
PN:19644L0310	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.310	AFL	3064								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-34	DISCARD SLATS IAS SWITCH STATIC HOSE									Service ATA:34
PN:6780060032	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.300	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-35	DISCARD ELEVATOR ARTHUR STATIC HOSE									Service ATA:34
PN:6780060014	MOS/MSC	07-Nov-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.310	AFL	3064								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-36	DISCARD PRESSURE TRANSMITTER HOSE									Service ATA:34
	MOS/MSC		O/C	TAC 0						
	HRS									
WC#: 34.320	AFL									
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-37	DISCARD NO. 1 ENGINE FUEL COMPUTER PT2 HOSE									Service ATA:34
PN:19644L0385	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.330	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-11-07-960-801-38	DISCARD NO. 2 ENGINE FUEL COMPUTER PT2 HOSE									Service ATA:34
PN:19644L0310	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.335	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-960-801-39	DISCARD NO. 3 ENGINE FUEL COMPUTER PT2 HOSE									Service ATA:34
PN:19644L0385	MOS/MSC	10-Dec-03	O/C							
SN:UNKNOWN	HRS	4936.4								
WC#: 34.330	AFL	3069								
					PROC. REF: AMM 34-11-07-960-801					
34-11-07-990-801-01	TABLE FOR RECORDING THE REPLACEMENT OF TOTAL AND STATIC PRESSURE ELASTOMER HOSES									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-11-07-990-801					
34-13-00-720-801-01	FUNCTIONAL TEST OF THE ANGLE-OF-ATTACK INDICATING SYSTEM									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-13-00-720-801					
34-14-01-710-802-01	OPERATIONAL TEST PILOT AIR DATA (ADC) COMPUTER									Service ATA:34
PN:622-8329-646	MOS/MSC	01-Feb-22	O/C							
SN:659	HRS	8793.2								
WC#: 34.510	AFL	5636								
					PROC. REF: AMM 34-14-01-710-802, AMM 34-14-01-710-802					
34-14-01-710-803-01	OPERATIONAL TEST COPILOT AIR DATA (ADC) COMPUTER									Service ATA:34
PN:622-8329-100	MOS/MSC	01-Feb-22	O/C							
SN:656	HRS	8793.2								
WC#: 34.520	AFL	5636								
					PROC. REF: AMM 34-14-01-710-803, AMM 34-14-01-710-803					
34-14-01-900-801-01	REMOVAL / INSTALLATION OF THE AIR DATA COMPUTERS (ADC) - ADC 1 (1FX) OR (10FX) OR (L320FE)									Component ATA:34
PN:622-8329-646	MOS/MSC	27-Apr-16	O/C	TSO 0						
SN:659	HRS			TSO 0						
WC#: 34.510	AFL			TSO 0						
					PROC. REF: AMM 34-14-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-14-01-900-801-02	REMOVAL / INSTALLATION OF THE AIR DATA COMPUTERS (ADC) - ADC 2 (81FX) OR (20FX) OR (R320FE)								Component	ATA:34
PN:622-8329-100	MOS/MSC	17-Feb-20	O/C	TSO 0						
SN:656	HRS	8676.4		TSO 0						
WC#: 34.520	AFL	5582		TSO 0						
					PROC. REF: AMM 34-14-01-900-801					
34-15-00-720-801-01	FUNCTIONAL TEST OF THE ALTITUDE ALERTER SYSTEM - ALTITUDE ALERTER SYSTEM								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-15-00-720-801					
34-16-05-710-801-01	OPERATIONAL TEST OF THE ALTIMETERS - PILOT ALTIMETER (11FX) OR (2FX)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-16-05-710-801					
34-16-05-710-801-02	OPERATIONAL TEST OF THE ALTIMETERS - COPILOT ALTIMETER (21FX) OR (82FX) .								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-16-05-710-801					
34-16-09-900-801-01	STAND BY ALTIMETER								Component	ATA:34
PN:8047/10	MOS/MSC	17-Feb-20	O/C	TSO 0						
SN:8653	HRS	8676.4		TSO 0						
WC#: 34.530	AFL	5582		TSO 0						
					PROC. REF: AMM 34-16-09-900-801, AMM 34-16-09-900-801					
34-16-13-710-801-01	OPERATIONAL TEST OF THE METRIC ALTIMETER REPETITOR								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-16-13-710-801					
34-16-14-710-801-01	OPERATIONAL TEST OF METRIC SELECTED ALTITUDE REPETITOR								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-16-14-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-21-00-710-801-01	OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 1 (151NP)									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-21-00-710-801, AMM 34-21-00-710-801					
34-21-00-710-801-02	OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 2 (250NP)									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-21-00-710-801, AMM 34-21-00-710-801					
34-21-00-710-801-03	OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 3 (50NP) (OPTION M2102 OR M2411)									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-21-00-710-801, AMM 34-21-00-710-801					
34-21-00-710-801-04	OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - AHC (740NP) (OPTION M1969)									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-21-00-710-801, AMM 34-21-00-710-801					
34-21-00-820-801-01	IRS ALIGNMENT - IRU 1 (150NP)									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-21-00-820-801					
34-21-00-820-801-02	IRS ALIGNMENT - IRU 2 (250NP)									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-21-00-820-801					
34-21-00-820-801-03	IRS ALIGNMENT - IRU 3 (50NP)									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-21-00-820-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-21-01-900-801-01		NO. 1 INERTIAL REFERENCE (IRU 1) UNIT								Component ATA:34
PN:HG1075AB0506	MOS/MSC	09-Apr-92	O/C							
SN:619	HRS	26								
WC#: 34.900	AFL	13								
					PROC. REF: AMM 34-21-01-900-801, AMM 34-21-01-900-801					
34-21-01-900-801-02		NO. 2 INERTIAL REFERENCE (IRU2) UNIT								Component ATA:34
PN:HG1075AB05	MOS/MSC	09-Apr-92	O/C							
SN:620	HRS	26								
WC#: 34.900	AFL	13								
					PROC. REF: AMM 34-21-01-900-801, AMM 34-21-01-900-801					
34-21-01-900-801-03		NO. 3 INERTIAL REFERENCE (IRU 3) UNIT								Component ATA:34
PN:HG1075AB05	MOS/MSC	28-Jan-03	O/C	TSO 0						
SN:650	HRS	4602.6		TSO 0						
WC#: 34.900	AFL	2905		TSO 0						
					PROC. REF: AMM 34-21-01-900-801, AMM 34-21-01-900-801					
34-21-13-100-801-01[S]		CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 1 FAN FILTER								Service ATA:34
	MOS	24-Oct-91								
	HRS	0	3000							
WC#: 34.975	AFL	0								
					PROC. REF: AMM 34-21-13-100-801					PKG:22
34-21-13-100-801-02[S]		CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 2 FAN FILTER								Service ATA:34
	MOS	24-Oct-91								
	HRS	0	3000							
WC#: 34.975	AFL	0								
					PROC. REF: AMM 34-21-13-100-801					PKG:22
34-21-13-100-801-03[S]		CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 3 FAN FILTER								Service ATA:34
	MOS	24-Oct-91								
	HRS	0	3000							
WC#: 34.975	AFL	0								
					PROC. REF: AMM 34-21-13-100-801					PKG:22
34-22-00-710-801-01		OPERATIONAL TEST OF THE ATTITUDE AND HEADING REFERENCE SYSTEM (AHRS)								Service ATA:34
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 34.980	AFL	0								
					PROC. REF: AMM 34-22-00-710-801, AMM 34-22-00-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-22-00-710-801-02	OPERATIONAL TEST OF THE ATTITUDE AND HEADING REFERENCE SYSTEM (AHRS) - MHRS 2 (23FF)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-22-00-710-801, AMM 34-22-00-710-801					
34-22-01-900-801-01	REMOVAL / INSTALLATION OF THE ATTITUDE AND HEADING COMPUTER (AHC) - AHC (740NP)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 34-22-01-900-801					
34-22-17-820-801-01	CHECK / ADJUSTMENT OF THE AHRS INTERNAL COMPENSATION UNIT (ICU) - AHRS 1 (13AH) (A/C WITHOUT PROLINE 4 AVIONICS) OR AHC (740NP) (A/C WITH PROLINE 4 AVIONICS (M1924))								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-22-17-820-801					
34-22-17-820-801-02	CHECK / ADJUSTMENT OF THE AHRS INTERNAL COMPENSATION UNIT (ICU) - AHRS 2 (23AH)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-22-17-820-801					
34-23-00-710-802-01	OPERATIONAL TEST OF THE STAND-BY HORIZON - STAND-BY HORIZON (4F) OR (24F)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-23-00-710-802					
34-23-00-900-801-01	REMOVAL / INSTALLATION OF THE STAND-BY HORIZON - STAND-BY HORIZON (4F)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 34-23-00-900-801, AMM 34-23-00-900-801					
34-25-00-820-801-01	COMPENSATION OF STAND-BY COMPASS - STAND-BY COMPASS (46F)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-25-00-820-801, AMM 34-25-00-820-801, AMM 34-25-00-820-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-26-00-710-801-01	OPERATIONAL TEST OF THE HEADING REFERENCE SYSTEM - HRS 1 SYSTEM								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-26-00-710-801					
34-26-00-710-801-02	OPERATIONAL TEST OF THE HEADING REFERENCE SYSTEM - HRS 2 SYSTEM								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-26-00-710-801					
34-26-01-710-801-01	OPERATIONAL TEST OF THE HEADING REFERENCE SYSTEM FLUX VALVES - HDG 1 FLUX VALVE (11FF)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 34.390	AFL	0								
					PROC. REF: AMM 34-26-01-710-801					
34-26-01-710-801-02	OPERATIONAL TEST OF THE HEADING REFERENCE SYSTEM FLUX VALVES - HDG 2 FLUX VALVE (21FF)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 34.390	AFL	0								
					PROC. REF: AMM 34-26-01-710-801					
34-26-05-900-801-01	REMOVAL / INSTALLATION OF THE DIRECTIONAL GYROS - DIRECTIONAL GYRO 1 (12FF)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.350	AFL	0		TSN 0						
					PROC. REF: AMM 34-26-05-900-801					
34-26-05-900-801-02	REMOVAL / INSTALLATION OF THE DIRECTIONAL GYROS - DIRECTIONAL GYRO 2 (22FF)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.350	AFL	0		TSN 0						
					PROC. REF: AMM 34-26-05-900-801					
34-27-00-710-801-01	OPERATIONAL TEST OF THE ATTITUDE REFERENCE SYSTEM - ARS 1								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-27-00-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-27-00-710-801-02	OPERATIONAL TEST OF THE ATTITUDE REFERENCE SYSTEM - ARS 2								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-27-00-710-801					
34-27-01-900-801-01	REMOVAL / INSTALLATION OF THE VERTICAL GYROS - VERTICAL GYRO 1 (13FV)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.460	AFL	0		TSN 0						
					PROC. REF: AMM 34-27-01-900-801					
34-27-01-900-801-02	REMOVAL / INSTALLATION OF THE VERTICAL GYROS - VERTICAL GYRO 2 (23FV)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.460	AFL	0		TSN 0						
					PROC. REF: AMM 34-27-01-900-801					
34-41-00-710-801-01	OPERATIONAL TEST OF THE WEATHER RADAR SYSTEM								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-41-00-710-801, AMM 34-41-00-710-801, AMM 34-41-00-710-801					
34-41-01-900-801-01	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.380	AFL	0		TSN 0						
					PROC. REF: AMM 34-41-01-900-801, AMM 34-41-01-900-801					
34-41-05-900-801-01	REMOVAL / INSTALLATION OF THE WEATHER RADAR ANTENNA - WEATHER RADAR ANTENNA (3SQ)								Component	ATA:34
PN:622-2504-001	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.750	AFL	0								
					PROC. REF: AMM 34-41-05-900-801					
34-41-09-820-801-01	ADJUSTMENT / TEST OF THE WEATHER RADAR ANTENNA STABILIZATION								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-41-09-820-801, AMM 34-41-09-820-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-42-00-710-801-01	OPERATIONAL TEST OF THE RADIO ALTIMETER SYSTEM - RADIO ALTIMETER 1 SYSTEM								Service	ATA:34
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-42-00-710-801, AMM 34-42-00-710-801					
34-42-00-710-801-02	OPERATIONAL TEST OF THE RADIO ALTIMETER SYSTEM - RADIO ALTIMETER 2 SYSTEM								Service	ATA:34
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-42-00-710-801, AMM 34-42-00-710-801					
34-42-01-900-801-01	NO. 1 RADIO ALTIMETER RECEIVER/TRANSMITTER								Component	ATA:34
PN:622-2855-001	MOS/MSC	05-May-98	O/C							
SN:8010	HRS	2753								
WC#: 34.010	AFL	1927								
					PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801					
34-42-01-900-801-02	NO. 2 RADIO ALTIMETER RECEIVER/TRANSMITTER								Component	ATA:34
PN:622-2855-001	MOS/MSC	29-Apr-19	O/C	TSO 5						
SN:11342	HRS			TSO 0						
WC#: 34.015	AFL			TSO 0						
					PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801					
34-42-01-900-801-03	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER AND ADAPTER - RADIO ALTIMETER 1 ADAPTER (21NL)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801					
34-42-01-900-801-04	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER AND ADAPTER - RADIO ALTIMETER 2 ADAPTER (51NL)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801					
34-42-09-900-801-01	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 1 TRANSMITTER ANTENNA (10NL)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 34-42-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-42-09-900-801-02	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 1 RECEIVER ANTENNA (11NL)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 34-42-09-900-801					
34-42-09-900-801-03	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 2 TRANSMITTER ANTENNA (40NL)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 34-42-09-900-801					
34-42-09-900-801-04	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 2 RECEIVER ANTENNA (41NL)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 34-42-09-900-801					
34-44-00-710-801-01	OPERATIONAL TEST OF THE TRAFFIC / COLLISION AVOIDANCE SYSTEM (TCAS)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-44-00-710-801					
34-44-00-720-801-01	FUNCTIONAL TEST OF THE TRAFFIC / COLLISION AVOIDANCE SYSTEM (TCAS)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-44-00-720-801					
34-44-01-900-801-01	REMOVAL / INSTALLATION OF THE TCAS TRANSCEIVER - TCAS TRANSCEIVER (350NP)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.400	AFL	0		TSN 0						
					PROC. REF: AMM 34-44-01-900-801					
34-44-05-900-801-01	REMOVAL / INSTALLATION OF THE TCAS ANTENNAS - LOWER TCAS ANTENNA (356NP)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 34-44-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-44-05-900-801-02	REMOVAL / INSTALLATION OF THE TCAS ANTENNAS - UPPER TCAS ANTENNA (354NP)								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 34-44-05-900-801					
34-45-00-710-801-01	OPERATIONAL TEST OF THE ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-45-00-710-801					
34-45-00-720-802-01	FUNCTIONAL TEST OF THE GROUND PROXIMITY WARNING SYSTEM (GPWS)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-45-00-720-802					
34-51-01-820-801-01	CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 1 RECEIVER (L210NR) / (12RS)								Service	ATA:34
PN:622-6137-201	MOS/MSC	24-Oct-91	O/C							
SN:16042	HRS	0								
WC#: 34.700	AFL	0								
					PROC. REF: AMM 34-51-01-820-801					
34-51-01-820-801-02	CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 2 RECEIVER (R210NR) / (22RS)								Service	ATA:34
PN:622-6137-201	MOS/MSC	24-Oct-91	O/C							
SN:12068	HRS	0								
WC#: 34.700	AFL	0								
					PROC. REF: AMM 34-51-01-820-801					
34-51-05-900-801-01	REMOVAL / INSTALLATION OF THE VOR / LOC ANTENNAS - LH VOR/LOC ANTENNA (L230NR)								Component	ATA:34
PN:DMN4-15-3D	MOS/MSC	31-Mar-00	O/C	TSO 0						
SN:9256	HRS	3776		TSO 0						
WC#: 34.720	AFL	2419		TSO 0						
					PROC. REF: AMM 34-51-05-900-801					
34-51-05-900-801-02	REMOVAL / INSTALLATION OF THE VOR / LOC ANTENNAS - RH VOR/LOC ANTENNA (R230NR)								Component	ATA:34
PN:DMN4-15-3D	MOS/MSC	31-Mar-00	O/C	TSO 0						
SN:9250	HRS	3776		TSO 0						
WC#: 34.720	AFL	2419		TSO 0						
					PROC. REF: AMM 34-51-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-51-10-710-801-01	OPERATIONAL TEST OF THE VOR NAVIGATION SYSTEM - VOR 1 SYSTEM									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-51-10-710-801, AMM 34-51-10-710-801, AMM 34-51-10-710-801, AMM 34-51-10-710-801					
34-51-10-710-801-02	OPERATIONAL TEST OF THE VOR NAVIGATION SYSTEM - VOR 2 SYSTEM									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-51-10-710-801, AMM 34-51-10-710-801, AMM 34-51-10-710-801, AMM 34-51-10-710-801					
34-51-20-710-801-01	OPERATIONAL TEST OF THE INSTRUMENT LANDING SYSTEM (ILS) - ILS 1 SYSTEM									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-51-20-710-801, AMM 34-51-20-710-801, AMM 34-51-20-710-801					
34-51-20-710-801-02	OPERATIONAL TEST OF THE INSTRUMENT LANDING SYSTEM (ILS) - ILS 2 SYSTEM									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-51-20-710-801, AMM 34-51-20-710-801, AMM 34-51-20-710-801					
34-51-40-710-801-01	OPERATIONAL TEST OF THE MARKER SYSTEM - MARKER 1 SYSTEM									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-51-40-710-801, AMM 34-51-40-710-801, AMM 34-51-40-710-801, AMM 34-51-40-710-801					
34-51-40-710-801-02	OPERATIONAL TEST OF THE MARKER SYSTEM - MARKER 2 SYSTEM									Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-51-40-710-801, AMM 34-51-40-710-801, AMM 34-51-40-710-801, AMM 34-51-40-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-51-60-710-801-01	OPERATIONAL TEST OF THE GLOBAL POSITIONING SYSTEM (GPS)								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-51-60-710-801					
34-52-00-710-801-01	OPERATIONAL TEST OF THE DISTANCE MEASURING EQUIPMENT (DME) SYSTEM - DME 1 SYSTEM								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-52-00-710-801, AMM 34-52-00-710-801					
34-52-00-710-801-02	OPERATIONAL TEST OF THE DISTANCE MEASURING EQUIPMENT (DME) SYSTEM - DME 2 SYSTEM								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-52-00-710-801, AMM 34-52-00-710-801					
34-52-05-900-801-01	REMOVAL / INSTALLATION OF THE DME ANTENNAS - DME 1 ANTENNA (13RV) OR (L330NR)								Component	ATA:34
PN:DMN150-2	MOS/MSC	24-Oct-91	O/C							
SN:46368	HRS	0		TSN 0						
	AFL	0								
					PROC. REF: AMM 34-52-05-900-801					
34-52-05-900-801-02	REMOVAL / INSTALLATION OF THE DME ANTENNAS - DME 2 ANTENNA (23RV) OR (R330NR)								Component	ATA:34
PN:DMN150-2	MOS/MSC	24-Oct-91	O/C							
SN:46914	HRS	0		TSN 0						
	AFL	0								
					PROC. REF: AMM 34-52-05-900-801					
34-53-00-710-801-01	OPERATIONAL TEST OF THE AUTOMATIC DIRECTION FINDER (ADF) SYSTEM - ADF 1 SYSTEM								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-53-00-710-801, AMM 34-53-00-710-801, AMM 34-53-00-710-801					
34-53-00-710-801-02	OPERATIONAL TEST OF THE AUTOMATIC DIRECTION FINDER (ADF) SYSTEM - ADF 2 SYSTEM								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-53-00-710-801, AMM 34-53-00-710-801, AMM 34-53-00-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-54-00-700-881-01		TEST NO. 1 ATC TRANSPONDER (FAR 91.413)								Service ATA:34
PN:622-9210-501	MOS	01-Feb-22	24		01-Feb-24		92 d	MANDATORY		
SN:4J3V	HRS									
WC#: 34.820	AFL									
					PROC. REF: GENERIC NO REF, FAR 91.413					
34-54-00-700-881-02		TEST NO. 2 ATC TRANSPONDER (FAR 91.413)								Service ATA:34
PN:622-9210-501	MOS	01-Feb-22	24		01-Feb-24		92 d	MANDATORY		
SN:1GH6P	HRS									
WC#: 34.820	AFL									
					PROC. REF: GENERIC NO REF, FAR 91.413					
34-54-00-710-801-01		OPERATIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM								Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-54-00-710-801, AMM 34-54-00-710-801					
34-54-00-710-801-02		OPERATIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM								Service ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-54-00-710-801, AMM 34-54-00-710-801					
34-54-00-720-802-01		FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM PERIODIC TESTS								Service ATA:34
PN:622-9210-501	MOS	01-Feb-22	24 (+3%)		01-Feb-24	21-Feb-24	92 d (+20)			
SN:4J3V	HRS	8793.2								
WC#: 34.820	AFL	5636								
					PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802					
34-54-00-720-802-02		FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM PERIODIC TESTS								Service ATA:34
PN:622-9210-501	MOS	01-Feb-22	24 (+3%)		01-Feb-24	21-Feb-24	92 d (+20)			
SN:1GH6P	HRS	8793.2								
WC#: 34.820	AFL	5636								
					PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-54-00-720-802-03	FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM COMPLEMENTARY TESTS								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802					
34-54-00-720-802-04	FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM COMPLEMENTARY TESTS								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802					
34-58-01-710-881-01	CHECK VOR EQUIPMENT FOR IFR OPERATIONS (FAR 91.171)								Service	ATA:34
	DAYS/MSC	09-Dec-22	A/R							
	HRS	8862.1								
WC#: 34.725	AFL	5701								
					PROC. REF: GENERIC NO REF, FAR 91.171					
34-61-00-710-802-01	OPERATIONAL TEST OF FLIGHT MANAGEMENT SYSTEM (UNS) - FMS 1								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-61-00-710-802					
34-61-00-710-802-02	OPERATIONAL TEST OF FLIGHT MANAGEMENT SYSTEM (UNS) - FMS 2								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-61-00-710-802					
34-61-00-710-803-01	OPERATIONAL TEST OF FLIGHT MANAGEMENT SYSTEM (GNSX) WITH GPS - FMS 1								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-61-00-710-803					
34-61-00-710-803-02	OPERATIONAL TEST OF FLIGHT MANAGEMENT SYSTEM (GNSX) WITH GPS - FMS 2								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-61-00-710-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-61-01-470-801-01	FMS DATABASE LOADING / COPYING (COLLINS) - FMS 1 DATABASE LOADING								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-61-01-470-801					
34-61-01-470-801-02	FMS DATABASE LOADING / COPYING (COLLINS) - FMS 2 DATABASE LOADING								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-61-01-470-801					
34-61-01-470-801-03	FMS DATABASE LOADING / COPYING (COLLINS) - FMS 3 DATABASE LOADING								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-61-01-470-801					
34-61-01-900-801-01	REMOVAL / INSTALLATION OF THE FMS COMPUTER (COLLINS) - FMC 1 (L110NG)								Component	ATA:34
PN:2192-00-111102	MOS/MSC	17-Jun-11	O/C	TSO 24, TSR 0						
SN:238	HRS	7591.3		TSO 559.7, TSR 0						
WC#: 34.960	AFL	4859		TSO 446, TSR 0						
					PROC. REF: AMM 34-61-01-900-801					
34-61-01-900-801-02	REMOVAL / INSTALLATION OF THE FMS COMPUTER (COLLINS) - FMC 2 (R110NG)								Component	ATA:34
PN:2192-00-111102	MOS/MSC	18-May-12	O/C	TSO 49						
SN:604	HRS	7862.1		TSO 1178.3						
WC#: 34.960	AFL	5094		TSO 943						
					PROC. REF: AMM 34-61-01-900-801					
34-61-01-900-801-03	REMOVAL / INSTALLATION OF THE FMS COMPUTER (COLLINS) - FMC 3								Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 34-61-01-900-801					
34-66-00-710-801-01	OPERATIONAL TEST OF THE INERTIAL NAVIGATION SYSTEM (INS) - INS								Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 34-66-00-710-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
34-66-01-900-801-01		REMOVAL / INSTALLATION OF THE INERTIAL NAVIGATION UNITS (INU) - INU 1 (1FP)								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.860	AFL	0		TSN 0						
					PROC. REF: AMM 34-66-01-900-801					
341008		NO.1 ANALOGIC/DIGITAL CONVERTER								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.990	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
341009		NO.2 ANALOGIC/DIGITAL CONVERTER								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.020	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
341011		NO. 1 RADIO ALTIMETER INDICATOR								Component ATA:34
PN:622-2937-008	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.020	AFL	0								
					PROC. REF: GENERIC NO REF					
341014		NO. 2 RADIO ALTIMETER INDICATOR								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.951	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
341015		NO.1 RADIO ALTIMETER RECEIVER ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.030	AFL	0		TSN 0						
					PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801					
341016		NO.2 RADIO ALTIMETER RECEIVER ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.030	AFL	0		TSN 0						
					PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
341017		NO.1 RADIO ALTIMETER TRANSMITTER ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.040	AFL	0		TSN 0						
					PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801					
341018		NO.2 RADIO ALTIMETER TRANSMITTER ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.040	AFL	0		TSN 0						
					PROC. REF: AMM 34-42-09-900-801					
341021		RADIO ALTIMETER ANTENNA								Component ATA:34
PN:522-4140-001	MOS/MSC	07-Jun-06	O/C	TSN 0						
SN:16931K	HRS	5909.3		TSN 0						
WC#: 34.020	AFL	3602		TSN 0						
					PROC. REF: AMM 34-42-09-900-801					
341029[U]		RADIO ALT NO.2 ANTENNA								Component ATA:34
PN:522-4140-001	MOS/MSC	07-Jun-06	O/C	TSN 0						
SN:16931H	HRS	5909.3		TSN 0						
	AFL	3602		TSN 0						
341032[U]		RADIO ALT NO.3 ANTENNA								Component ATA:34
PN:622-6793-001	MOS/MSC	09-Apr-92	O/C							
SN:1366	HRS	26								
	AFL	13								
341033		STANDBY AIR DATA UNIT								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.560	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
341041		STANDBY MACH-AIRSPEED INDICATOR								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.535	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
341101		PILOT AIRSPEED/MACH INDICATOR								Component ATA:34
PN:622-6785-015	MOS/MSC	27-Apr-16	O/C	TSO 4						
SN:664	HRS			TSO 0						
WC#: 34.030	AFL			TSO 0						
					PROC. REF: GENERIC NO REF					
341111		COPILOT AIRSPEED/MACH INDICATOR								Component ATA:34
PN:622-6785-015	MOS/MSC	08-Dec-06	O/C	TSR 0						
SN:680	HRS	5992.2		TSR 0						
WC#: 34.030	AFL	3650		TSR 0						
					PROC. REF: GENERIC NO REF					
341121		PILOT ALTIMETER								Component ATA:34
PN:622-3975-005	MOS/MSC	03-May-20	O/C	TSO 2						
SN:576	HRS	8678.2		TSO 0						
WC#: 34.040	AFL			TSO 0						
					PROC. REF: GENERIC NO REF					
341126		COPILOT ALTIMETER								Component ATA:34
PN:622-3975-005	MOS/MSC	17-Feb-20	O/C	TSO 0						
SN:7156	HRS	8676.4		TSO 0						
WC#: 34.040	AFL	5582		TSO 0						
					PROC. REF: GENERIC NO REF					
341131		PILOT RATE OF CLIMB INDICATOR								Component ATA:34
PN:622-9728-322	MOS/MSC	18-Apr-23	O/C							
SN:687	HRS	8950.5								
WC#: 34.060	AFL	5756								
					PROC. REF: GENERIC NO REF					
341141		COPILOT RATE OF CLIMB INDICATOR								Component ATA:34
PN:TV1920D	MOS/MSC	07-May-92	O/C							
SN:481	HRS	67		TSN 0						
WC#: 34.060	AFL	35								
					PROC. REF: GENERIC NO REF					
341151		TOTAL TEMPERATURE INDICATOR								Component ATA:34
PN:622-3234-004	MOS/MSC	15-Dec-10	O/C	TSN 206, TSR 0						
SN:2125	HRS	7458.3		TSN 8453.1, TSR 0						
WC#: 34.070	AFL	4759		TSN 6583, TSR 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
341191		STATIC PRESSURE SELECTOR VALVE								Component ATA:34
PN:919ZEQ4	MOS/MSC	24-Oct-91	O/C							
SN:1104	HRS	0		TSN 0						
WC#: 34.130	AFL	0								
					PROC. REF: GENERIC NO REF					
341193		DUAL CUT-OFF VALVE								Component ATA:34
PN:914A01	MOS/MSC	24-Oct-91	O/C							
SN:669	HRS	0		TSN 0						
WC#: 34.140	AFL	0								
					PROC. REF: GENERIC NO REF					
341196		ALTITUDE ALERTER								Component ATA:34
PN:622-9426-005	MOS/MSC	07-Mar-05	O/C	TSR 0						
SN:1193	HRS			TSR 0						
WC#: 34.050	AFL			TSR 0						
					PROC. REF: GENERIC NO REF					
341236		PILOT AIR DATA COMPUTER REFERENCE PANEL								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.050	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
341241		COPILOT AIR DATA COMPUTER REFERENCE PANEL								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.050	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
341351		REMOVAL/INSTALLATION OF STATIC PRESSURE PROBES								Service ATA:34
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
WC#: 34.945	AFL	0								
					PROC. REF: AMM 34-11-05-900-801					
341835[U]		RADIO ALT NO.4 ANTENNA								Component ATA:34
PN:622-6793-001	MOS/MSC	09-Apr-92	O/C							
SN:1365	HRS	26								
	AFL	13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342001		STAND-BY COMPASS								Component ATA:34
PN:KCA0105W	MOS/MSC	24-Oct-91	O/C							
SN:AD613	HRS	0		TSN 0						
WC#: 34.340	AFL	0								
					PROC. REF: GENERIC NO REF					
342037		STAND-BY HORIZON								Component ATA:34
PN:501-1197-05	MOS/MSC	20-Oct-10	O/C	TSO 0						
SN:4380	HRS	7418.8		TSO 0						
WC#: 34.370	AFL	4726		TSO 0						
					PROC. REF: AMM 34-23-00-900-801, AMM 34-23-00-900-801					
342041		NO. 1 HEADING REFERENCE SYSTEM (HDG 1) FLUX VALVE								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.390	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342051		NO. 2 HEADING REFERENCE SYSTEM (HDG 2) FLUX VALVE								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.390	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342061		LH COMPASS COUPLER								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.360	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342066		RH COMPASS COUPLER								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.360	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342071		PILOT FLIGHT DIRECTOR MODE SELECTOR								Component ATA:34
PN:622-6209-010	MOS/MSC	20-Apr-16	O/C	TSO 4						
SN:525F	HRS			TSO 0						
WC#: 34.400	AFL			TSO 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342072		REPLACEMENT MAINTENANCE DIAGNOSTIC COMPUTER (MDC) MODULE BATTERY							Service	ATA:34
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 34.946	AFL	0								
					PROC. REF: GENERIC NO REF					
342081		COPILOT FLIGHT DIRECTOR MODE SELECTOR							Component	ATA:34
PN:622-6209-010	MOS/MSC	20-Apr-16	O/C	TSO 4						
SN:1136	HRS			TSO 0						
WC#: 34.400	AFL			TSO 0						
					PROC. REF: GENERIC NO REF					
342091		PILOT RMI INDICATOR							Component	ATA:34
PN:3137L-B-2-1C	MOS/MSC	09-Apr-92	O/C							
SN:11393	HRS	26								
WC#: 34.420	AFL	13								
					PROC. REF: GENERIC NO REF					
342101		COPILOT RMI INDICATOR							Component	ATA:34
PN:3137L-B-2-1C	MOS/MSC	09-Apr-92	O/C							
SN:10395	HRS	26								
WC#: 34.420	AFL	13								
					PROC. REF: GENERIC NO REF					
342111		PILOT FLIGHT DIRECTOR INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.430	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342121		COPILOT FLIGHT DIRECTOR INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.430	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342131		PILOT COMPASS HEADING CONTROL BOX							Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.450	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342141		COPILOT COMPASS HEADING CONTROL BOX								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.450	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342151		PILOT FLIGHT DIRECTOR COMPUTER								Component ATA:34
PN:622-5224-001	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.410	AFL	0								
					PROC. REF: GENERIC NO REF					
342161		COPILOT FLIGHT DIRECTOR COMPUTER								Component ATA:34
PN:622-5224-001	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.410	AFL	0								
					PROC. REF: GENERIC NO REF					
342191		PILOT ACCELEROMETER								Component ATA:34
PN:229-0324-010	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.470	AFL	0								
					PROC. REF: AMM 31-31-38-900-801					
342197		COPILOT ACCELEROMETER								Component ATA:34
PN:229-0324-010	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.470	AFL	0								
					PROC. REF: AMM 31-31-38-900-801					
342226		COURSE SELECTOR								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.500	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342231		RATE OF TURN GYRO								Component ATA:34
PN:622-0181-001	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.480	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty

ATA 34 - NAVIGATION

342260		REPLACEMENT PILOT AIR DATA (ADC) COMPUTER BATTERY							Service	ATA:34
PN:622-8329-646	MOS/MSC	27-Apr-16	O/C							
SN:659	HRS									
WC#: 34.948	AFL									
					PROC. REF: GENERIC NO REF					
342266		PILOT HORIZONTAL SITUATION (HSI) INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.440	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342276		COPILOT HORIZONTAL SITUATION (HSI) INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.440	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342296		REPLACEMENT COPILOT AIR DATA (ADC) COMPUTER BATTERY							Service	ATA:34
PN:622-8329-100	MOS/MSC	17-Feb-20	O/C							
SN:656	HRS	8676.4								
WC#: 34.948	AFL	5582								
					PROC. REF: GENERIC NO REF					
342301		PILOT UPPER ELECTRONIC ATITUDE DIRECTOR INDICATOR (EADI) DISPLAY							Component	ATA:34
PN:622-6342-024	MOS/MSC	10-Jan-05	O/C	TSO 0						
SN:4558	HRS	5395.8		TSO 0						
WC#: 34.540	AFL	3320		TSO 0						
					PROC. REF: GENERIC NO REF					
342311		PILOT LOWER ELECTRONIC HORIZONTAL SITUATION INDICATOR (EHSI) DISPLAY							Component	ATA:34
PN:622-6342-024	MOS/MSC	09-Apr-92	O/C							
SN:3754	HRS	26								
WC#: 34.540	AFL	13								
					PROC. REF: GENERIC NO REF					
342321		PILOT DISPLAY (DPU) PROCESSOR UNIT							Component	ATA:34
PN:622-9009-004	MOS/MSC	10-Jan-05	O/C	TSO 0						
SN:3097	HRS	5395.8		TSO 0						
WC#: 34.560	AFL	3320		TSO 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342331		PILOT DISPLAY (DCP) CONTROL								Component ATA:34
PN:622-9165-002	MOS/MSC	09-Apr-92	O/C							
SN:262	HRS	26								
WC#: 34.570	AFL	13								
					PROC. REF: GENERIC NO REF					
342341		COPILOT UPPER ELECTRONIC ATITUDE DIRECTOR INDICATOR (EADI) DISPLAY								Component ATA:34
PN:622-6342-024	MOS/MSC	09-Apr-92	O/C							
SN:3751	HRS	26								
WC#: 34.550	AFL	13								
					PROC. REF: GENERIC NO REF					
342351		COPILOT LOWER ELECTRONIC HORIZONTAL SITUATION INDICATOR (EHSI) DISPLAY								Component ATA:34
PN:622-6342-024	MOS/MSC	09-Apr-92	O/C							
SN:3755	HRS	26								
WC#: 34.550	AFL	13								
					PROC. REF: GENERIC NO REF					
342361		COPILOT DISPLAY PROCESSOR (DPU) UNIT								Component ATA:34
PN:622-9009-004	MOS/MSC	09-Jun-04	O/C	TSO 0						
SN:4953	HRS	5186.5		TSO 0						
WC#: 34.560	AFL	3166		TSO 0						
					PROC. REF: GENERIC NO REF					
342371		COPILOT DISPLAY CONTROL (DCP) PANEL								Component ATA:34
PN:622-9165-002	MOS/MSC	09-Apr-92	O/C							
SN:318	HRS	26								
WC#: 34.570	AFL	13								
					PROC. REF: GENERIC NO REF					
342381		MULTIFUNCTION CATHODE RAY TUBE (MFD) DISPLAY								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.590	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342391		MULTIFUNCTION PROCESSOR (MPU) UNIT								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.610	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342401		COURSE HEADING PANEL								Component ATA:34
PN:622-6404-002	MOS/MSC	09-Apr-92	O/C							
SN:396	HRS	26								
WC#: 34.620	AFL	13								
					PROC. REF: GENERIC NO REF					
342411		WEATHER RADAR CONTROL (WXP) PANEL								Component ATA:34
PN:622-8393-004	MOS/MSC	09-Apr-92	O/C							
SN:519	HRS	26		TSN 0						
WC#: 34.600	AFL	13								
					PROC. REF: GENERIC NO REF					
342451		PILOT REVERSION SWITCH (RSP) PANEL								Component ATA:34
PN:622-6383-002	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.580	AFL	0								
					PROC. REF: GENERIC NO REF					
342461		COPILOT REVERSION SWITCH (RSP) PANEL								Component ATA:34
PN:622-6383-002	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.580	AFL	0								
					PROC. REF: GENERIC NO REF					
342501		PILOT F/D INDIC./SITUATION INDIC. (EADI/EHSI) BLOWER								Component ATA:34
PN:030002	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.670	AFL	0								
					PROC. REF: GENERIC NO REF					
342506		COPILOT F/D INDIC./SITUATION INDIC. (EADI/EHSI) BLOWER								Component ATA:34
PN:030002	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.670	AFL	0								
					PROC. REF: GENERIC NO REF					
342511		MULTIFUNCTION CATHODE RAY TUBE DISPLAY (MFB) BLOWER								Component ATA:34
PN:030002	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.690	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342516		PILOT DISPLAY PROCESSOR UNIT (DPU) BLOWER								Component ATA:34
PN:026955	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.680	AFL	0								
					PROC. REF: GENERIC NO REF					
342521		COPILOT DISPLAY PROCESSOR UNIT (DPU) BLOWER								Component ATA:34
PN:026955	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.680	AFL	0								
					PROC. REF: GENERIC NO REF					
342526		MULTIFUNCTION DISPLAY PROCESSOR UNIT (MPU) BLOWER								Component ATA:34
PN:026949	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0								
WC#: 34.690	AFL	0								
					PROC. REF: GENERIC NO REF					
342601		LONGITUDINAL ACCELEROMETER								Component ATA:34
PN:229-0324-020	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.490	AFL	0								
					PROC. REF: GENERIC NO REF					
342901		LH CONFIGURATION (CSU) MODULE								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.170	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342902		RH CONFIGURATION (CSU) MODULE								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.170	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342905		INTERGRATED AVIONICS SYSTEM PROCESSOR								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.180	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342911		LH UPPER INPUT/OUTPUT CONCENTRATOR								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.190	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342912		LH LOWER INPUT/OUTPUT CONCENTRATOR								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.190	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342913		RH UPPER INPUT/OUTPUT CONCENTRATOR								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.200	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342914		RH LOWER INPUT/OUTPUT CONCENTRATOR								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.200	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342921		EFIS INPUT/OUTPUT CONCENTRATOR								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.210	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342935		SECONDARY FLIGHT DISPLAY								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.570	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342945		PILOT REVERSIONARY CONTROL								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.250	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342946		COPILOT REVERSIONARY CONTROL								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.250	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342947		PILOT DISPLAY CONTROL								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.260	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
342948		COPILOT DISPLAY CONTROL								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.260	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
343001		NO. 1 VOR/ILS/MKR RECEIVER								Component ATA:34
PN:622-6137-201	MOS/MSC	05-Nov-02	O/C	TSO 0						
SN:16042	HRS	4545.6		TSO 0						
WC#: 34.700	AFL	2885		TSO 0						
					PROC. REF: GENERIC NO REF					
343011		NO. 2 VOR/ILS/MKR RECEIVER								Component ATA:34
PN:622-6137-201	MOS/MSC	05-May-98	O/C							
SN:12068	HRS	2753								
WC#: 34.700	AFL	1927								
					PROC. REF: GENERIC NO REF					
343021		VOR/ILS/MKR1/DME1/VHF1 CONTROL								Component ATA:34
PN:G6286	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.710	AFL	0								
					PROC. REF: GENERIC NO REF					
343023		VOR/ILS/MKR2/DME2/ATC1/ATC2 CONTROL								Component ATA:34
PN:G-4876A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.710	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
343041		MARKER ANTENNA								Component ATA:34
PN:DMN27-1A	MOS/MSC	24-Oct-91	O/C							
SN:3105	HRS	0		TSN 0						
WC#: 34.730	AFL	0								
					PROC. REF: GENERIC NO REF					
343051		GLIDESLOPE ANTENNA								Component ATA:34
PN:DMN25-2	MOS/MSC	24-Oct-91	O/C							
SN:2945	HRS	0		TSN 0						
WC#: 34.730	AFL	0								
					PROC. REF: GENERIC NO REF					
344001		RADAR TRANSCEIVER								Component ATA:34
PN:622-4022-001	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.740	AFL	0								
					PROC. REF: GENERIC NO REF					
344003		WEATHER RADAR CONTROL								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.390	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
344011		RADAR INDICATOR								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.760	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
344080[U]		EGPWS COMPUTER								Component ATA:34
PN:965-0976-040-218-218	MOS/MSC	07-Aug-20	O/C	TSO 188						
SN:14417	HRS	8690.7		TSO 3305.2						
	AFL	5593		TSO 2276						
344086		NO.1 ATC UPPER ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.430	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
344087		NO.2 ATC UPPER ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.430	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
344088		NO.1 ATC LOWER ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.440	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
344089		NO.2 ATC LOWER ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.440	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
345001		NO. 1 VLF/OMEGA RECEIVER/ COMPUTER								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.770	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
345011		NO. 2 VLF/OMEGA RECEIVER/ COMPUTER								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.780	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
345021		NO. 1 OMEGA CONTROL AND DISPLAY UNIT								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.770	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
345031		NO. 2 OMEGA CONTROL AND DISPLAY UNIT								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.780	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345041		NO. 1 VLF/OMEGA ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.790	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
345051		NO. 2 VLF/OMEGA ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.790	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
345061		NO. 1 OMEGA OPTIONAL EQUIPMENT UNIT								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.770	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
345071		NO. 2 OMEGA OPTIONAL EQUIPMENT UNIT								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.780	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
345086		NO. 1 ADF RECEIVER								Component ATA:34
PN:622-2362-001	MOS/MSC	16-Oct-02	O/C							
SN:23153	HRS	4505.1								
WC#: 34.800	AFL	2367								
					PROC. REF: GENERIC NO REF					
345096		NO. 2 ADF RECEIVER								Component ATA:34
PN:622-2362-001	MOS/MSC	05-Nov-02	O/C	TSR 0						
SN:23132	HRS	4545.6		TSR 0						
WC#: 34.800	AFL	2885		TSR 0						
					PROC. REF: GENERIC NO REF					
345106		ADF1/ADF2 CONTROL UNIT								Component ATA:34
PN:G6862-01	MOS/MSC		O/C							
SN:REMOVED	HRS									
WC#: 34.810	AFL									
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345126		NO. 1 ADF ANTENNA								Component ATA:34
PN:622-2363-001	MOS/MSC	24-Oct-91	O/C							
SN:27007	HRS	0								
WC#: 34.810	AFL	0								
					PROC. REF: GENERIC NO REF					
345136		NO. 2 ADF ANTENNA								Component ATA:34
PN:622-2363-001	MOS/MSC	24-Oct-91	O/C							
SN:27008	HRS	0								
WC#: 34.810	AFL	0								
					PROC. REF: GENERIC NO REF					
345181		NO. 1 ATC TRANSPONDER								Component ATA:34
PN:622-9210-501	MOS/MSC	07-Mar-16	O/C							
SN:4J3V	HRS	8278.1								
WC#: 34.820	AFL	5347								
					PROC. REF: GENERIC NO REF					
345196		NO. 1 ATC ANTENNA								Component ATA:34
PN:DMN150-2	MOS/MSC	09-Apr-92	O/C							
SN:48524	HRS	26								
WC#: 34.830	AFL	13								
					PROC. REF: GENERIC NO REF					
345206		NO. 2 ATC TRANSPONDER								Component ATA:34
PN:622-9210-501	MOS/MSC	07-Mar-16	O/C							
SN:1GH6P	HRS	8278.1								
WC#: 34.820	AFL	5347								
					PROC. REF: GENERIC NO REF					
345221		NO. 2 ATC ANTENNA								Component ATA:34
PN:DMN150-2	MOS/MSC	09-Apr-92	O/C							
SN:48489	HRS	26								
WC#: 34.830	AFL	13								
					PROC. REF: GENERIC NO REF					
345231		NO. 1 DME TRANSCEIVER								Component ATA:34
PN:622-6263-003	MOS/MSC	09-Apr-92	O/C							
SN:11153	HRS	26								
WC#: 34.840	AFL	13								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345241		NO. 2 DME TRANSCEIVER								Component ATA:34
PN:622-6263-003	MOS/MSC	09-Apr-92	O/C							
SN:11154	HRS	26								
WC#: 34.840	AFL	13								
					PROC. REF: GENERIC NO REF					
345801[U]		DME NO.1 INDICATOR								Component ATA:34
PN:622-7318-001	MOS/MSC	09-Apr-92	O/C							
SN:2705	HRS	26								
	AFL	13								
345803[U]		DME NO.2 INDICATOR								Component ATA:34
PN:622-7318-001	MOS/MSC	16-Dec-09	O/C	TSO 0						
SN:2706	HRS	7169.2		TSO 0						
	AFL	4516		TSO 0						
345809[U]		ADF NO.1 INVERTER								Component ATA:34
PN:622-6590-001	MOS/MSC	09-Apr-92	O/C							
SN:9904	HRS	26								
	AFL	13								
345810[U]		ADF NO.2 INVERTER								Component ATA:34
PN:622-6590-001	MOS/MSC	09-Apr-92	O/C							
SN:9927	HRS	26								
	AFL	13								
346006		MODE SELECTOR (MSU) UNIT								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.870	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
346011		CONTROL DISPLAY (CDU) UNIT								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.870	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
346016		INS BATTERY								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.890	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
346026		INS BLOWER								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.880	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
346036		INS CARD READER								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.880	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
346045		DATA TRANSFER UNIT								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.510	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
346050		NAV DATA INTERFACE								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.650	AFL	0								
					PROC. REF: GENERIC NO REF					
346053		NAV DATA MEMORY MODULE								Component ATA:34
PN:22150-1	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.650	AFL	0								
					PROC. REF: GENERIC NO REF					
346066[U]		AIRSHOW INTERFACE UNIT								Component ATA:34
PN:910020-379	MOS/MSC	09-Apr-92	O/C							
SN:1214	HRS	26								
	AFL	13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
346106		NO. 1 IRS MODE SELECTOR (MSU 1) UNIT								Component ATA:34
PN:CG1042AB03	MOS/MSC	09-Apr-92	O/C							
SN:1151	HRS	26								
WC#: 34.910	AFL	13								
					PROC. REF: GENERIC NO REF					
346116		NO. 2 IRS MODE SELECTOR (MSU 2) UNIT								Component ATA:34
PN:CG1042AB03	MOS/MSC	09-Apr-92	O/C							
SN:1152	HRS	26								
WC#: 34.910	AFL	13								
					PROC. REF: GENERIC NO REF					
346126		NO. 3 IRS MODE SELECTOR (MSU 3) UNIT								Component ATA:34
PN:CG1042AB03	MOS/MSC	09-Apr-92	O/C							
SN:1187	HRS	26		TSN 0						
WC#: 34.910	AFL	13								
					PROC. REF: GENERIC NO REF					
346131		IRS CONTROL DISPLAY (ISDU) PANEL								Component ATA:34
PN:NA	MOS/MSC	28-Oct-20	O/C							
SN:NA	HRS	8701								
WC#: 34.920	AFL	5598								
					PROC. REF: GENERIC NO REF					
346151		NO. 1 IRS BLOWER								Component ATA:34
PN:10089782-103	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.930	AFL	0								
					PROC. REF: GENERIC NO REF					
346156		NO. 1 IRS BLOWER FILTER								Component ATA:34
PN:10090306-101	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.940	AFL	0								
					PROC. REF: GENERIC NO REF					
346166		NO. 2 IRS BLOWER								Component ATA:34
PN:10089782-103	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.930	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
346171		NO. 2 IRS BLOWER FILTER								Component ATA:34
PN:10090306-101	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.940	AFL	0								
					PROC. REF: GENERIC NO REF					
346181		NO. 3 IRS BLOWER								Component ATA:34
PN:10089782-103	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.930	AFL	0								
					PROC. REF: GENERIC NO REF					
346186		NO. 3 IRS BLOWER FILTER								Component ATA:34
PN:10090306-101	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.940	AFL	0								
					PROC. REF: GENERIC NO REF					
346241		NO.1 GLOBAL POSISTIONING SENSING ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.530	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
346246		NO.2 GLOBAL POSISTIONING SENSING ANTENNA								Component ATA:34
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.530	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
346303		REPLACEMENT FMC 1 (FLIGHT MANAGEMENT COMPUTER) BATTERY								Service ATA:34
	MOS/MSC	17-Jun-11	O/C							
	HRS	7591.3								
WC#: 34.949	AFL	4859								
					PROC. REF: GENERIC NO REF					
346306		NO. 1 FMS CONTROL DISPLAY UNIT								Component ATA:34
PN:1018-2-113	MOS/MSC		O/C	TSN 0						
SN:1617	HRS			TSN 0						
WC#: 34.970	AFL			TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
346313		REPLACEMENT FMC 2 (FLIGHT MANAGEMENT COMPUTER) BATTERY							Service	ATA:34
	MOS/MSC	18-May-12	O/C							
	HRS	7862.1								
WC#: 34.949	AFL	5094								
					PROC. REF: GENERIC NO REF					
346316		NO. 2 FMS CONTROL DISPLAY UNIT							Component	ATA:34
PN:1018-2-113	MOS/MSC		O/C	TSN 0						
SN:1619	HRS			TSN 0						
WC#: 34.970	AFL			TSN 0						
					PROC. REF: GENERIC NO REF					
346809[U]		UNIVERSAL DATA #2 TRANSFER UNIT							Component	ATA:34
PN:DTU-100	MOS/MSC	13-May-06	O/C	TSO 0						
SN:3146	HRS	5866		TSO 0						
	AFL	3581		TSO 0						
346863[U]		AFIS DATA MANAGEMENT UNIT							Component	ATA:34
PN:400-045500-0003	MOS/MSC		O/C	TSR 0						
SN:2486	HRS			TSR 0						
	AFL			TSR 0						
346865[U]		AFIS DATA TRANSFER UNIT							Component	ATA:34
PN:400-045500-0003	MOS/MSC	24-Sep-04	O/C	TSR 0						
SN:X2486	HRS	5312		TSR 0						
	AFL	3277		TSR 0						
346867[U]		SAT/AFIS ANTENNA							Component	ATA:34
PN:121-017537-01	MOS/MSC	27-Jan-03	O/C	TSN 0						
SN:608	HRS	4602		TSN 0						
	AFL	2905		TSN 0						
346869[U]		CONFIGURATION AFIS MODULE							Component	ATA:34
PN:31990-1	MOS/MSC	09-Apr-92	O/C							
SN:2971	HRS	26								
	AFL	13								
347824[U]		SAT/AFIS COM UNIT TRANSCEIVER							Component	ATA:34
PN:153-017311-01	MOS/MSC	27-Jan-02	O/C	TSN 0						
SN:963	HRS	4602		TSN 0						
	AFL	2905		TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
347828[U]		CONFIG GNSX NMU #1 MODULE								Component ATA:34
PN:31990-1	MOS/MSC	09-Apr-92	O/C							
SN:2962	HRS	26								
	AFL	13								
347829[U]		CONFIG GNSX NMU #2 MODULE								Component ATA:34
PN:31990-1	MOS/MSC	09-Apr-92	O/C							
SN:3062	HRS	26								
	AFL	13								
347830[U]		SAT/AFIS AMPLIFIER								Component ATA:34
PN:153-017310-01	MOS/MSC	27-Jan-03	O/C	TSN 0						
SN:945	HRS	4602		TSN 0						
	AFL	2905		TSN 0						
347832[U]		GPS #1 ANTENNA								Component ATA:34
PN:567-1575-39	MOS/MSC		O/C	TSN 0						
SN:12119	HRS			TSN 0						
	AFL			TSN 0						
347834[U]		DOWN CONVERTER,GPS-GNSX								Component ATA:34
PN:400-014135-01	MOS/MSC	09-Apr-92	O/C							
SN:735	HRS	26								
	AFL	13								
347851[U]		WEATHER RADAR DISPLAY								Component ATA:34
PN:622-7876-012	MOS/MSC	03-Nov-16	O/C	TSO 10						
SN:1743	HRS			TSO 0						
	AFL			TSO 0						
347855[U]		WEATHER RADAR PROCESSOR								Component ATA:34
PN:622-9010-004	MOS/MSC	24-Aug-18	O/C	TSO 7						
SN:3304	HRS			TSO 0						
	AFL			TSO 0						
347859[U]		DATA PROGRMMR,WEATH RADAR								Component ATA:34
PN:622-5110-001	MOS/MSC	09-Apr-92	O/C							
SN:2638	HRS	26								
	AFL	13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
347863[U]		XCEIVER/ANTNA,WEATH RADAR								Component ATA:34
PN:622-8441-003	MOS/MSC	10-May-11	O/C	TSO 0						
SN:888	HRS	7550.5		TSO 0						
	AFL	4837		TSO 0						
347873[U]		TCAS #1 ANTENNA								Component ATA:34
PN:622-8973-001	MOS/MSC	09-Apr-92	O/C							
SN:2073	HRS	26								
	AFL	13								
347881[U]		TCAS TRANSCEIVER								Component ATA:34
PN:622-8971-122	MOS/MSC	29-Oct-09	O/C	TSR 0						
SN:6117	HRS	7150.6		TSR 0						
	AFL	4496		TSR 0						
347883[U]		TCAS CONTROL								Component ATA:34
PN:822-0078-00301	MOS/MSC	09-Apr-92	O/C							
SN:70	HRS	26								
	AFL	13								
347885[U]		TCAS #1 CONVERTER								Component ATA:34
PN:622-7209-002	MOS/MSC	09-Apr-92	O/C							
SN:395	HRS	26								
	AFL	13								
347887[U]		TCAS #2 CONVERTER								Component ATA:34
PN:622-7209-002	MOS/MSC	09-Apr-92	O/C							
SN:253	HRS	26								
	AFL	13								
348873[U]		AUDIO CHECKLIST CONTROL								Component ATA:34
PN:CMS400-1-G5	MOS/MSC	27-Jan-03	O/C	TSN 0						
SN:C400-003562	HRS	4602		TSN 0						
	AFL	2905		TSN 0						
ATA 35 - OXYGEN										
35-00-00-360-801-01		LOCALIZATION AND REPAIR OF LEAKS ON THE OXYGEN SYSTEM								Service ATA:35
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 35-00-00-360-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-00-00-790-801-01	LEAK CHECK OF THE OXYGEN SYSTEM									Service ATA:35
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 35-00-00-790-801					
35-00-00-910-801-01	OXYGEN SYSTEM MAINTENANCE AND SAFETY PRECAUTIONS									Service ATA:35
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 35-00-00-910-801					
35-10-00-790-801-01	LEAK CHECK OF THE CREW OXYGEN SYSTEM									Service ATA:35
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 35-10-00-790-801					
35-10-05-100-801-01	CLEANING OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH)									Service ATA:35
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 35-10-05-100-801					
35-10-05-100-801-02	CLEANING OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH)									Service ATA:35
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 35-10-05-100-801					
35-10-05-100-801-03	CLEANING OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)									Service ATA:35
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 35-10-05-100-801					
35-10-05-350-801-01	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - LH PILOT OXYGEN MASK (L502WH)									Service ATA:35
PN:MA10-12-00	MOS	07-Sep-22	72 (+3%)	TAC 2	31-Jul-28	11-Sep-28	1734 d (+42)	OVERHAUL		
SN:4879	HRS	8823		TAC 0						
WC#: 35.080	AFL	5651		TAC 0						
					PROC. REF: AMM 35-10-05-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-10-05-350-801-02	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - RH PILOT OXYGEN MASK (R502WH)								Service	ATA:35
PN:MA10-12-00	MOS	27-May-21	72 (+3%)		27-May-27	31-Jul-27	1303 d (+65)	OVERHAUL		
SN:5660	HRS	8751.8								
WC#: 35.080	AFL	5619								
					PROC. REF: AMM 35-10-05-350-801					
35-10-05-350-801-03	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - THIRD CREW MEMBER OXYGEN MASK (524WH)								Service	ATA:35
PN:289-601-228	MOS/MSC	17-Dec-10	O/C	TAC 0						
SN:N/A	HRS	7458.3		TAC 0						
WC#: 35.180	AFL	4759		TAC 0						
					PROC. REF: AMM 35-10-05-350-801					
35-10-05-710-801-01[S]	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH)								Service	ATA:35
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 35.080	AFL	5775								
					PROC. REF: AMM 35-10-05-710-801					PKG:15
35-10-05-710-801-02[S]	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH)								Service	ATA:35
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 35.080	AFL	5775								
					PROC. REF: AMM 35-10-05-710-801					PKG:15
35-10-05-710-801-03	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)								Service	ATA:35
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 35.180	AFL	0								
					PROC. REF: AMM 35-10-05-710-801					
35-10-05-900-801-01	REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH)								Component	ATA:35
PN:MA10-12-00	MOS/MSC	07-Sep-22	H/T	TSO 2						
SN:4879	HRS	8823		TSO 0						
WC#: 35.080	AFL	5651		TSO 0						
					PROC. REF: AMM 35-10-05-900-801					
35-10-05-900-801-02	REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH)								Component	ATA:35
PN:MA10-12-00	MOS/MSC	27-May-21	H/T	TSO 0						
SN:5660	HRS	8751.8		TSO 0						
WC#: 35.080	AFL	5619		TSO 0						
					PROC. REF: AMM 35-10-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-10-05-900-801-03	REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)								Component	ATA:35
PN:289-601-228	MOS/MSC	17-Dec-10	O/C	TSN 0						
SN:N/A	HRS	7458.3		TSN 0						
WC#: 35.180	AFL	4759		TSN 0						
					PROC. REF: AMM 35-10-05-900-801					
35-20-00-210-801-01[S]	GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS - PASSENGER OXYGEN MASK (9510WJ)								Service	ATA:35
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 35.205	AFL	5775								
					PROC. REF: AMM 35-20-00-210-801					PKG:16 ,15
35-20-00-720-801-01[S]	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM								Service	ATA:35
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 35.010	AFL	5651								
					PROC. REF: AMM 35-20-00-720-801					PKG:21
35-20-01-350-801-01	RESTORATION OF THE PASSENGER OXYGEN CONTROLLER (OVERHAUL) - PASSENGER OXYGEN CONTROLLER (1WH)								Service	ATA:35
PN:RCA70	MOS	10-Aug-21	72 (+3%)		10-Aug-27	14-Oct-27	1378 d (+65)	OVERHAUL		
SN:186	HRS	8767.1								
WC#: 35.100	AFL	5625								
					PROC. REF: AMM 35-20-01-350-801					
35-20-01-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER OXYGEN CONTROLLER								Component	ATA:35
PN:RCA70	MOS/MSC	10-Aug-21	H/T	TSO 0						
SN:186	HRS	8767.1		TSO 0						
WC#: 35.100	AFL	5625		TSO 0						
					PROC. REF: AMM 35-20-01-900-801					
35-20-09-860-801-01	PACKING OF THE PASSENGER OXYGEN MASKS								Service	ATA:35
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 35-20-09-860-801					
35-20-09-900-801-01	NO. 1 PASSENGER OXYGEN MASK								Component	ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.110	AFL									
					PROC. REF: AMM 35-20-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-20-09-900-801-01	NO. 10 PASSENGER OXYGEN MASK									Component ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.140	AFL									
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-900-801-01	NO. 11 PASSENGER OXYGEN MASK									Component ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.140	AFL									
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-900-801-01	NO. 12 PASSENGER OXYGEN MASK									Component ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.140	AFL									
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-900-801-01	NO. 2 PASSENGER OXYGEN MASK									Component ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.110	AFL									
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-900-801-01	NO. 3 PASSENGER OXYGEN MASK									Component ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.110	AFL									
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-900-801-01	NO. 4 PASSENGER OXYGEN MASK									Component ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.120	AFL									
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-900-801-01	NO. 5 PASSENGER OXYGEN MASK									Component ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.120	AFL									
					PROC. REF: AMM 35-20-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-20-09-900-801-01		NO. 6 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.120	AFL									
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-900-801-01		NO. 7 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.130	AFL									
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-900-801-01		NO. 8 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.130	AFL									
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-900-801-01		NO. 9 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-205	MOS/MSC	03-May-20	O/C							
SN:NSN	HRS	8678.2								
WC#: 35.130	AFL									
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-900-801-01		THERAPEUTIC OXYGEN MASK								Component ATA:35
PN:MW3511	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 35.150	AFL	0								
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-900-801-01		TOILET OXYGEN MASK								Component ATA:35
PN:289-601-205	MOS/MSC	15-Dec-12	O/C							
SN:UNKNOWN	HRS	7936								
WC#: 35.150	AFL	5150								
					PROC. REF: AMM 35-20-09-900-801					
35-20-09-960-802-01		REPLACEMENT OF THE FLEXIBLE TUBE SLEEVE ON PASSENGER OXYGEN MASKS								Service ATA:35
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 35-20-09-960-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-30-01-960-801-01	DISCARD OF THE SMOKE HOOD - SMOKE HOOD (508WH)									Service ATA:35
PN:PN	MOS/MSC		O/C							
SN:NOT INSTALLED	HRS									
WC#: 35.190	AFL									
					PROC. REF: AMM 35-30-01-960-801					
35-30-05-210-801-01	GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)									Service ATA:35
PN:5500-894-20330	MOS	08-Sep-23	12 (+3%)		08-Sep-24	18-Sep-24	312 d (+10)			
SN:747280	HRS	8967								
WC#: 35.170	AFL	5775								
					PROC. REF: AMM 35-30-05-210-801					
35-30-05-350-801-01	RESTORATION OF THE PORTABLE OXYGEN BOTTLE (OVERHAUL) - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)									Service ATA:35
PN:5500-894-20330	MOS	28-Oct-20	60 (+3%)		28-Oct-25	22-Dec-25	727 d (+55)	OVERHAUL		
SN:747280	HRS	8701								
	AFL	5598								
					PROC. REF: AMM 35-30-05-350-801					
35-30-05-610-801-01	REFILLING OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)									Service ATA:35
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 35-30-05-610-801, AMM 35-30-05-610-801					
35-30-05-960-801-01	DISCARD OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)									Service ATA:35
PN:5500-894-20330	MOS/MSC	09-Dec-10	O/C							
SN:747280	HRS	7458.3								
WC#: 35.030	AFL	4759								
					PROC. REF: AMM 35-30-05-960-801					
35-30-09-100-801-01	CLEANING OF THE PORTABLE OXYGEN MASKS - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)									Service ATA:35
PN:5500-894-20330	MOS	08-Sep-23	12 (+3%)		08-Sep-24	18-Sep-24	312 d (+10)			
SN:747280	HRS	8967								
WC#: 35.030	AFL	5775								
					PROC. REF: AMM 35-30-09-100-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
35-40-01-610-801-01	REFILLING OF THE OXYGEN CYLINDER									Service ATA:35
	MOS/MSC	23-Nov-22	O/C							
	HRS	8850.4								
	AFL	5691								
					PROC. REF: AMM 35-40-01-610-801					
35-40-01-790-801-01	HYDROSTATIC TEST OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)									Service ATA:35
PN:GST2151	MOS	20-Jul-22	36		31-Jul-25		638 d	MANDATORY		
SN:AB07369	HRS									
WC#: 35.020	AFL									
					PROC. REF: AMM 35-40-01-790-801					
35-40-01-900-801-01	REMOVAL / INSTALLATION OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)									Component ATA:35
PN:GST2151	MOS/MSC	07-Sep-22	H/T	TSO 71, TSR 0						
SN:AB07369	HRS	8823		TSR 0						
WC#: 35.020	AFL	5651		TSR 0						
					PROC. REF: AMM 35-40-01-900-801					
35-40-01-960-801-01	DISCARD OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)									Service ATA:35
PN:GST2151	MOS	01-Feb-05	288		01-Feb-29		1919 d	LIFE LIMIT		
SN:AB07369	HRS									
WC#: 35.020	AFL									
					PROC. REF: AMM 35-40-01-960-801					
35-40-05-350-801-01	RESTORATION OF THE OXYGEN CYLINDER PRESSURE REDUCING VALVE (OVERHAUL) - OXYGEN CYLINDER PRESSURE REDUCING VALVE (50WY)									Service ATA:35
PN:RDN1000	MOS	03-May-20	72 (+3%)		03-May-26	07-Jul-26	914 d (+65)	OVERHAUL		
SN:192	HRS									
WC#: 35.060	AFL									
					PROC. REF: AMM 35-40-05-350-801					
35-40-05-900-801-01	REMOVAL/INSTALLATION OF THE OXYGEN CYLINDER PRESSURE REDUCING VALVE - OXYGEN CYLINDER PRESSURE REDUCING VALVE (50WY)									Component ATA:35
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 35-40-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
350116		FILLER VALVE								Component ATA:35
PN:DKR130	MOS/MSC	30-Nov-98	O/C							
SN:UNKNOWN	HRS	2995								
WC#: 35.050	AFL	2071								
					PROC. REF: GENERIC NO REF					
350121		OXYGEN PRESSURE REDUCING VALVE								Component ATA:35
PN:RDN1000	MOS/MSC	03-May-20	H/T							
SN:192	HRS	8678.2								
WC#: 35.060	AFL									
					PROC. REF: GENERIC NO REF					
350131		OXYGEN BOTTLE HP INDICATOR								Component ATA:35
PN:CMT150	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 35.070	AFL	0								
					PROC. REF: GENERIC NO REF					
350141		COPILOT OXYGEN HP INDICATOR								Component ATA:35
PN:CMT10-1	MOS/MSC	24-Oct-91	O/C							
SN:1288	HRS	0		TSN 0						
WC#: 35.070	AFL	0								
					PROC. REF: GENERIC NO REF					
351111		PILOT OXYGEN CONNECTOR								Component ATA:35
PN:DPB179	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 35.090	AFL	0								
					PROC. REF: GENERIC NO REF					
351131		COPILOT OXYGEN CONNECTOR								Component ATA:35
PN:DPB179	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 35.090	AFL	0								
					PROC. REF: GENERIC NO REF					
353111		PORTABLE OXYGEN BOTTLE								Component ATA:35
PN:5500-894-20330	MOS/MSC	20-Nov-15	O/C							
SN:747280	HRS	8257.2								
WC#: 35.030	AFL	5333								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
353121		SMOKE HOOD								Component ATA:35
PN:PN	MOS/MSC		H/T							
SN:NOT INSTALLED	HRS									
WC#: 35.190	AFL									
					PROC. REF: GENERIC NO REF					
ATA 36 - PNEUMATIC										
36-00-01-710-801-01		OPERATIONAL TEST OF THE BLEED AIR SUPPLY COMPUTER (BASC) - BASC (40H)								Service ATA:36
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 36-00-01-710-801					
36-10-00-790-801-01 S		LEAK CHECK OF THE BLEED AIR SYSTEM - CHECK FOR LEAKS AT APU								Service ATA:36
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 36-10-00-790-801					PKG:21
36-10-00-790-801-02 S		LEAK CHECK OF THE BLEED AIR SYSTEM - CHECK FOR LEAKS AT ENGINE 1								Service ATA:36
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 36-10-00-790-801					PKG:21
36-10-00-790-801-03 S		LEAK CHECK OF THE BLEED AIR SYSTEM - CHECK FOR LEAKS AT ENGINE 2								Service ATA:36
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 36-10-00-790-801					PKG:21
36-10-00-790-801-04 S		LEAK CHECK OF THE BLEED AIR SYSTEM - CHECK FOR LEAKS AT ENGINE 3								Service ATA:36
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
	AFL	5651								
					PROC. REF: AMM 36-10-00-790-801					PKG:21

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-10-02-710-801		OPERATIONAL TEST OF THE ENGINE HP BLEED AIR VALVES							Service	ATA:36
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 36-10-02-710-801					
36-10-02-710-801-01		OPERATIONAL TEST OF THE ENGINE HP BLEED AIR VALVES - ENGINE 1 HP BLEED AIR VALVE (23H1)							Service	ATA:36
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 36-10-02-710-801					
36-10-02-710-801-02		OPERATIONAL TEST OF THE ENGINE HP BLEED AIR VALVES - ENGINE 2 HP BLEED AIR VALVE (23H2)							Service	ATA:36
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 36-10-02-710-801					
36-10-02-710-801-03		OPERATIONAL TEST OF THE ENGINE HP BLEED AIR VALVES - ENGINE 3 HP BLEED AIR VALVE (23H3)							Service	ATA:36
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 36-10-02-710-801					
36-10-02-720-801-01		FUNCTIONAL TEST OF THE ENGINE HP BLEED AIR VALVES - ENGINE 1 HP BLEED AIR VALVE (23H1)							Service	ATA:36
PN:1780-00-1	MOS	07-Mar-13								
SN:0386	HRS	7960.6	4000		11960.6		2968.5			
WC#: 36.030	AFL	5171								
					PROC. REF: AMM 36-10-02-720-801					
36-10-02-720-801-02		FUNCTIONAL TEST OF THE ENGINE HP BLEED AIR VALVES - ENGINE 2 HP BLEED AIR VALVE (23H2)							Service	ATA:36
PN:1780-00-1	MOS	07-Mar-13								
SN:1582	HRS	7960.6	4000		11960.6		2968.5			
WC#: 36.040	AFL	5171								
					PROC. REF: AMM 36-10-02-720-801					
36-10-02-720-801-03		FUNCTIONAL TEST OF THE ENGINE HP BLEED AIR VALVES - ENGINE 3 HP BLEED AIR VALVE (23H3)							Service	ATA:36
PN:1780-00-1	MOS	07-Mar-13								
SN:0460	HRS	7960.6	4000		11960.6		2968.5			
WC#: 36.050	AFL	5171								
					PROC. REF: AMM 36-10-02-720-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-10-02-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE HP BLEED AIR VALVES - ENGINE 1 HP BLEED AIR VALVE (23H1)								Component	ATA:36
PN:1780-00-1	MOS/MSC	07-Mar-13	O/C	TSO 0						
SN:0386	HRS	7960.6		TSO 0						
WC#: 36.030	AFL	5171		TSO 0						
					PROC. REF: AMM 36-10-02-900-801					
36-10-02-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE HP BLEED AIR VALVES - ENGINE 2 HP BLEED AIR VALVE (23H2)								Component	ATA:36
PN:1780-00-1	MOS/MSC	07-Mar-13	O/C	TSO 0						
SN:1582	HRS	7960.6		TSO 0						
WC#: 36.040	AFL	5171		TSO 0						
					PROC. REF: AMM 36-10-02-900-801					
36-10-02-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE HP BLEED AIR VALVES - ENGINE 3 HP BLEED AIR VALVE (23H3)								Component	ATA:36
PN:1780-00-1	MOS/MSC	07-Mar-13	O/C	TSO 0						
SN:0460	HRS	7960.6		TSO 0						
WC#: 36.050	AFL	5171		TSO 0						
					PROC. REF: AMM 36-10-02-900-801					
36-10-02-910-901	TROUBLESHOOTING OF THE HP BLEED AIR VALVES								Service	ATA:36
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: GENERIC NO REF					
36-10-03-720-801-01	FUNCTIONAL TEST OF THE ENGINE 2 HP PRESSURE REGULATING VALVE - ENGINE 2 HP PRESSURE REGULATING VALVE (29H)								Service	ATA:36
PN:3213902-2	MOS	07-Aug-20								
SN:406	HRS	8690.7	4000		12690.7		3698.6			
WC#: 36.060	AFL	5593								
					PROC. REF: AMM 36-10-03-720-801					
36-10-03-900-803-01	REMOVAL / INSTALLATION OF THE ENGINE 2 HP PRESSURE REGULATING VALVE								Component	ATA:36
PN:3213902-2	MOS/MSC	07-Aug-20	O/C	TSR 158						
SN:406	HRS	8690.7		TSR 3390.5						
WC#: 36.060	AFL	5593		TSR 2615						
					PROC. REF: AMM 36-10-03-900-803					
36-10-05-200-801-01	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 1 LP BLEED AIR CHECK VALVE (L515H)								Service	ATA:36
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 36.080	AFL	0								
					PROC. REF: AMM 36-10-05-200-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-10-05-200-801-02	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 2 LP BLEED AIR CHECK VALVE (M515H)								Service	ATA:36
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 36.090	AFL	0								
					PROC. REF: AMM 36-10-05-200-801					
36-10-05-200-801-03	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 3 LP BLEED AIR CHECK VALVE (R515H)								Service	ATA:36
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 36.100	AFL	0								
					PROC. REF: AMM 36-10-05-200-801					
36-10-05-200-801-04	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 1 HP/LP BLEED AIR CHECK VALVE (L516H)								Service	ATA:36
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 36.080	AFL	0								
					PROC. REF: AMM 36-10-05-200-801					
36-10-05-200-801-05	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 2 HP/LP BLEED AIR CHECK VALVE (M516H)								Service	ATA:36
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 36.090	AFL	0								
					PROC. REF: AMM 36-10-05-200-801					
36-10-05-200-801-06	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 3 HP/LP BLEED AIR CHECK VALVE (R516H)								Service	ATA:36
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 36.100	AFL	0								
					PROC. REF: AMM 36-10-05-200-801					
36-10-05-200-801-07	INSPECTION OF THE BLEED AIR CHECK VALVES - APU BLEED AIR CHECK VALVE (599H)								Service	ATA:36
	MOS/MSC	10-Dec-03	N/A							
	HRS	4936.4								
WC#: 36.140	AFL	3069								
					PROC. REF: AMM 36-10-05-200-801					
36-10-05-900-801-01	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 1 LP BLEED AIR CHECK VALVE (L515H)								Component	ATA:36
PN:CYLB50419-1H	MOS/MSC	24-Oct-91	O/C							
SN:1449	HRS	0		TSN 0						
WC#: 36.080	AFL	0								
					PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-10-05-900-801-02	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 2 LP BLEED AIR CHECK VALVE (M515H)									Component ATA:36
PN:CYLB50419-1H	MOS/MSC	24-Oct-91	O/C							
SN:1468	HRS	0		TSN 0						
WC#: 36.090	AFL	0								
					PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801					
36-10-05-900-801-03	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 3 LP BLEED AIR CHECK VALVE (R515H)									Component ATA:36
PN:CYLB50419-1H	MOS/MSC	24-Oct-91	O/C							
SN:1448	HRS	0		TSN 0						
WC#: 36.100	AFL	0								
					PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801					
36-10-05-900-801-04	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 1 HP/LP BLEED AIR CHECK VALVE (L516H)									Component ATA:36
PN:CYLB50419-1H	MOS/MSC	24-Oct-91	O/C							
SN:1453	HRS	0		TSN 0						
WC#: 36.080	AFL	0								
					PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801					
36-10-05-900-801-05	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 2 HP/LP BLEED AIR CHECK VALVE (M516H)									Component ATA:36
PN:CYLB50419-1H	MOS/MSC	24-Oct-91	O/C							
SN:1467	HRS	0		TSN 0						
WC#: 36.090	AFL	0								
					PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801					
36-10-05-900-801-06	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 3 HP/LP BLEED AIR CHECK VALVE (R516H)									Component ATA:36
PN:CYLB50419-1H	MOS/MSC	24-Oct-91	O/C							
SN:1501	HRS	0		TSN 0						
WC#: 36.100	AFL	0								
					PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801					
36-10-05-900-801-07	CABIN HP BLEED AIR CHECK VALVE									Component ATA:36
PN:CYLB50414	MOS/MSC	24-Oct-91	O/C							
SN:1651	HRS	0		TSN 0						
WC#: 36.110	AFL	0								
					PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801					
36-10-05-900-801-08	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - COCKPIT HP BLEED AIR CHECK VALVE (546H)									Component ATA:36
PN:CYLB50414	MOS/MSC	24-Oct-91	O/C							
SN:1653	HRS	0		TSN 0						
WC#: 36.110	AFL	0								
					PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-10-05-900-801-09	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - CABIN LP BLEED AIR CHECK VALVE (547H)								Component	ATA:36
PN:CYLB50414	MOS/MSC	24-Oct-91	O/C							
SN:1657	HRS	0		TSN 0						
WC#: 36.120	AFL	0								
					PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801					
36-10-05-900-801-10	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - COCKPIT LP BLEED AIR CHECK VALVE (548H)								Component	ATA:36
PN:CYLB50414	MOS/MSC	24-Oct-91	O/C							
SN:1659	HRS	0		TSN 0						
WC#: 36.120	AFL	0								
					PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801					
36-10-05-900-801-11	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - APU BLEED AIR CHECK VALVE (599H)								Component	ATA:36
PN:CYLB50419-1	MOS/MSC	24-Oct-91	O/C							
SN:1542	HRS	0		TSN 0						
WC#: 36.140	AFL	0								
					PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801					
36-10-21-710-801-01 S	OPERATIONAL TEST OF THE BLEED AIR ISOLATION VALVE - BLEED AIR ISOLATION VALVE (43H)								Service	ATA:36
	MOS	17-Dec-10								
	HRS	7458.3	4500 (+30)							
WC#: 36.070	AFL	4759								
					PROC. REF: AMM 36-10-21-710-801					PKG:23
36-10-29-900-801-01	REMOVAL / INSTALLATION OF THE HP BLEED AIR PIPES - ENGINE 1 HP BLEED AIR PIPES								Component	ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 36-10-29-900-801					
36-10-29-900-801-02	REMOVAL / INSTALLATION OF THE HP BLEED AIR PIPES - ENGINE 2 HP BLEED AIR PIPES								Component	ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 36-10-29-900-801					
36-10-29-900-801-03	REMOVAL / INSTALLATION OF THE HP BLEED AIR PIPES - ENGINE 3 HP BLEED AIR PIPES								Component	ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 36-10-29-900-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-10-29-900-802-01	REMOVAL / INSTALLATION OF ENGINE 2 HP BLEED AIR PIPE									Component ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 36-10-29-900-802, AMM 36-10-29-900-802					
36-10-31-900-801-01	REMOVAL / INSTALLATION OF THE LP BLEED AIR PIPES - ENGINE 1 LP BLEED AIR PIPES									Component ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 36-10-31-900-801					
36-10-31-900-801-02	REMOVAL / INSTALLATION OF THE LP BLEED AIR PIPES - ENGINE 2 LP BLEED AIR PIPES									Component ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 36-10-31-900-801					
36-10-31-900-801-03	REMOVAL / INSTALLATION OF THE LP BLEED AIR PIPES - ENGINE 3 LP BLEED AIR PIPES									Component ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 36-10-31-900-801					
36-10-33-350-801-01	RESTORATION OF THE BLEED AIR ARTICULATED PIPES (LEAK TEST AND DISCARD OF PISTON RING) - ENGINE 1 ARTICULATED PIPE (L510HU)									Service ATA:36
PN:B45CB1042	MOS	13-Dec-13								
SN:00939	HRS	8092.4	4000		12092.4		3100.3			
	AFL	5236								
					PROC. REF: AMM 36-10-33-350-801					
36-10-33-350-801-02	RESTORATION OF THE BLEED AIR ARTICULATED PIPES (LEAK TEST AND DISCARD OF PISTON RING) - ENGINE 2 ARTICULATED PIPE (M510HU)									Service ATA:36
PN:B45CB1072	MOS	13-Feb-14								
SN:T189	HRS	8106.6	4000		12106.6		3114.5			
	AFL	5246								
					PROC. REF: AMM 36-10-33-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
36-10-33-350-801-03		RESTORATION OF THE BLEED AIR ARTICULATED PIPES (LEAK TEST AND DISCARD OF PISTON RING) - ENGINE 3 ARTICULATED PIPE (R510HU)							Service	ATA:36
PN:B45CB1042	MOS	13-Dec-13								
SN:00878	HRS	8092.4	4000		12092.4		3100.3			
	AFL	5236								
					PROC. REF: AMM 36-10-33-350-801					
361101		NO. 1 ENGINE EXPANSION PIPE							Component	ATA:36
PN:B45CB1042	MOS/MSC	13-Dec-13	O/C	TSO 71						
SN:00939	HRS	8092.4		TSO 0						
WC#: 36.010	AFL	5236		TSO 0						
					PROC. REF: GENERIC NO REF					
361106		NO. 2 ENGINE EXPANSION PIPE							Component	ATA:36
PN:B45CB1072	MOS/MSC	13-Feb-14	O/C	TSO 66						
SN:T189	HRS	8106.6		TSO 0						
WC#: 36.020	AFL	5246		TSO 0						
					PROC. REF: GENERIC NO REF					
361111		NO. 3 ENGINE EXPANSION PIPE							Component	ATA:36
PN:B45CB1042	MOS/MSC	13-Dec-13	O/C	TSO 71						
SN:00878	HRS	8092.4		TSO 0						
WC#: 36.010	AFL	5236		TSO 0						
					PROC. REF: GENERIC NO REF					
361201		BLEED AIR SHUTOFF VALVE							Component	ATA:36
PN:BYLB50423-1	MOS/MSC	24-Oct-91	O/C							
SN:828	HRS	0		TSN 0						
WC#: 36.070	AFL	0								
					PROC. REF: GENERIC NO REF					
361206		NO. 1 ENGINE BLEED VENTURI CHECK VALVE							Component	ATA:36
PN:AR88-020-003	MOS/MSC	24-Oct-91	O/C							
SN:3670990	HRS	0		TSN 0						
WC#: 36.130	AFL	0								
					PROC. REF: GENERIC NO REF					
361211		NO. 2 ENGINE BLEED VENTURI CHECK VALVE							Component	ATA:36
PN:AR88-020-003	MOS/MSC	24-Oct-91	O/C							
SN:3730990	HRS	0		TSN 0						
WC#: 36.130	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 36 - PNEUMATIC										
361251		APU BLEED VENTURI CHECK VALVE								Component ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 36.130	AFL	0								
					PROC. REF: GENERIC NO REF					
362101		NO. 1 ENGINE BLEED AIR THERMOSTAT								Component ATA:36
PN:150T321-1	MOS/MSC	24-Oct-91	O/C							
SN:1451	HRS	0		TSN 0						
WC#: 36.160	AFL	0								
					PROC. REF: GENERIC NO REF					
362106		NO. 1 ENGINE BLEED AIR (THERMOSTAT 25H1) TEMPERATURE PROBE								Component ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 36.190	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
362111		NO. 2 ENGINE BLEED AIR THERMOSTAT								Component ATA:36
PN:150T378	MOS/MSC	01-Feb-04	O/C	TSN 0						
SN:1434	HRS	4997.7		TSN 0						
WC#: 36.160	AFL	3092		TSN 0						
					PROC. REF: GENERIC NO REF					
362116		NO. 2 ENGINE BLEED AIR (THERMOSTAT 25H2) TEMPERATURE PROBE								Component ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 36.200	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
362121		NO. 3 ENGINE BLEED AIR THERMOSTAT								Component ATA:36
PN:150T321-1	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 36.160	AFL	0								
					PROC. REF: GENERIC NO REF					
362126		NO. 3 ENGINE BLEED AIR (THERMOSTAT 25H3) TEMPERATURE PROBE								Component ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 36.210	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty

ATA 36 - PNEUMATIC

362131		CABIN AIR CONDITIONING THERMOSTAT								Component ATA:36
PN:150T321-1	MOS/MSC	02-Mar-02	O/C	TSN 0						
SN:1893	HRS	4186		TSN 0						
WC#: 36.170	AFL	2690		TSN 0						
					PROC. REF: GENERIC NO REF					
362136		BLEED AIR SYSTEM COMPUTER								Component ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 36.220	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
362141		COCKPIT AIR CONDITIONING THERMOSTAT								Component ATA:36
PN:150T321-1	MOS/MSC	02-Mar-02	O/C	TSN 0						
SN:1892	HRS	4186		TSN 0						
WC#: 36.170	AFL	2690		TSN 0						
					PROC. REF: GENERIC NO REF					
362144		NO.1 AND NO.3 ENGINE PRESSURE TRANSDUCER								Component ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 36.170	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
362146		NO. 2 ENGINE PRESSURE TRANSDUCER								Component ATA:36
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 36.230	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
362151		AIR BLEED INDICATOR PRINTED CIRCUIT								Component ATA:36
PN:CI999A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 36.180	AFL	0								
					PROC. REF: GENERIC NO REF					
362156		AIR BLEED INDICATOR PRINTED CIRCUIT								Component ATA:36
PN:CI999A	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 36.180	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 38 - WATER/WASTE										
38-00-00-610-801-01[S]	SERVICING OF THE WATER SYSTEM									Service ATA:38
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 38.030	AFL	5775								
					PROC. REF: AMM 38-00-00-610-801					PKG:16 ,15
38-10-00-610-803-01	GRAVITY REFILLING OF THE FWD LAVATORY HOT WATER RESERVOIR - HOT WATER RESERVOIR (284H)									Service ATA:38
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 38-10-00-610-803					
38-10-00-670-801-01	STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION									Service ATA:38
	MOS	08-Sep-23	6 (+1m)	Adj -6d	02-Mar-24	02-Apr-24	122 d (+31)			
	HRS	8967								
WC#: 38.020	AFL	5775								
					PROC. REF: AMM 38-10-00-670-801					
38-10-00-670-801-02	STERILIZATION OF THE POTABLE WATER SYSTEM - SHOCK TREATMENT									Service ATA:38
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 38-10-00-670-801					
38-13-01-960-801-01	REPLACEMENT OF THE MAIN FILTER CARTRIDGE									Service ATA:38
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 38-13-01-960-801					
38-30-00-710-801-01	OPERATIONAL TEST OF THE DRAIN MAST ANTI-ICING SYSTEMS									Service ATA:38
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 38-30-00-710-801					
38-34-00-600-801-01	DRAINING AND FILLING OF THE TOILETS									Service ATA:38
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 38-34-00-600-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 38 - WATER/WASTE										
381826[U]		HEATED DRAIN MAST							Component	ATA:38
PN:115677-101	MOS/MSC	23-Jan-03	O/C							
SN:194	HRS	4604								
	AFL									
ATA 44 - CABIN SYSTEMS										
44-34-00-710-801-01		OPERATIONAL TEST OF THE RADIO TELEPHONE SYSTEM							Service	ATA:44
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 44-34-00-710-801, AMM 44-34-00-710-801					
ATA 45 - CENTRAL MAINT SYSTEM										
45-10-02-900-801-01		REMOVAL / INSTALLATION OF THE MAINTENANCE DIAGNOSTIC COMPUTER (MDC) MODULE - MDC (355NH)							Component	ATA:45
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 34.220	AFL	0		TSN 0						
					PROC. REF: AMM 45-10-02-900-801					
45-20-00-910-801-01		USE OF THE MAINTENANCE PC							Service	ATA:45
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 45-20-00-910-801					
ATA 49 - AIRBORNE AUXILIARY POWER										
49-50-01-900-801-01		REMOVAL / INSTALLATION / ADJUSTMENT OF THE APU AIR INLET DOOR ACTUATOR - AIR INTAKE DOOR ACTUATOR (333H)							Component	ATA:49
PN:MA11A1061B	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 49.123	AFL	0								
					PROC. REF: AMM 49-50-01-900-801					
49-60-00-710-801-01[S]		OPERATIONAL TEST OF THE APU FUEL SHUT-OFF ELECTRIC VALVE AND FIRE DETECTION CIRCUIT - APU SHUT-OFF VALVE (189H)							Service	ATA:49
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 49.110	AFL	5651								
					PROC. REF: AMM 49-60-00-710-801					PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
490010		APU - OPERATIONAL CHECK								Service ATA:49
	MOS/MSC	30-Jan-93	C/C							
	HRS	284		TAC 0						
	APUS	0								
					PROC. REF: MM 49-20-00					
490213		APU DOOR MOTOR								Component ATA:49
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 49.306	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
491010		APU - TURBINE ROTOR								Component ATA:49
PN:3615880-1	MOS	05-May-98						LIFE LIMIT		
SN:970134509282	HRS	2134	10000	TSN 0	12134		7018.1			
	APUS	0		TSN 0						
					PROC. REF: GENERIC NO REF					
491015		APU - ROTOR MARK								Component ATA:49
PN:PN	MOS/MSC	12-Feb-92	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
491020		APU - COMPRESSOR ROTOR								Component ATA:49
PN:3822101-1	MOS	12-Feb-92						LIFE LIMIT		
SN:0-03501-4749	HRS	0	100000	TSN 0	100000		94884.1			
	APUS	0		TSN 0						
					PROC. REF: GENERIC NO REF					
491030		APU - HOT SECTION INSPECTION								Service ATA:49
	MOS	16-Dec-10								
	HRS	4216.9	1500 (+45)		5716.9	5761.9	601 (+45)			
	APUS									
					PROC. REF: MM 49-20-00					
491080		APU - COMBUSTOR UNIT								Component ATA:49
PN:3830077-9	MOS/MSC	09-Mar-18	O/C	TSN 0						
SN:UNKNOWN	HRS	4798		TSN 0						
	APUS			TSN 0						
					PROC. REF: MM 49-20-04					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
491110		APU - INSPECT COMBUSTOR UNIT								Service ATA:49
PN:3830077-9	MOS	10-Jan-23								
SN:UNKNOWN	HRS	5049.7	300 (+10%)		5349.7	5379.7	233.8 (+30)			
	APUS									
					PROC. REF: MM 49-20-04					
491120		APU - VISUAL CHECK COMPRESSOR ROTOR								Service ATA:49
PN:3822101-1	MOS	16-Dec-10								
SN:0-03501-4749	HRS	4216.9	1500 (+45)		5716.9	5761.9	601 (+45)			
	APUS									
					PROC. REF: MM 49-20-00					
492001		APU - PRESERVATION OF APU								Service ATA:49
	MOS/MSC	12-Feb-92	O/C							
	HRS	0								
	APUS	0								
					PROC. REF: MM 49-20-00					
492002		APU - PERFORM APU PRESERVATION CHECK								Service ATA:49
	MOS/MSC	12-Feb-92	O/C							
	HRS	0								
	APUS	0								
					PROC. REF: MM 49-20-00					
492003		APU - DE-PRESERVATION OF APU								Service ATA:49
	MOS/MSC	12-Feb-92	O/C							
	HRS	0								
	APUS	0								
					PROC. REF: GENERIC NO REF					
492004		APU - PERFORM APU PRESERVATION – APU RUN								Service ATA:49
	MOS/MSC	12-Feb-92	A/R							
	HRS	0								
	APUS	0								
					PROC. REF: MM 49-20-00					
493010		APU - FUEL CONTROL								Component ATA:49
PN:3882600-5-1	MOS/MSC	12-Feb-92	O/C							
SN:A-1760	HRS	0		TSN 0						
	APUS	0								
					PROC. REF: MM 49-30-49					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
493020		APU - REMOVE AND REPLACE FUEL FILTER ELEMENT								Service ATA:49
	MOS	10-Jan-23								
	HRS	5049.7	300 (+10%)		5349.7	5379.7	233.8 (+30)			
	APUS									
					PROC. REF: MM 49-30-49					
493040		APU - FUEL SHUTOFF VALVE								Component ATA:49
PN:692545-6	MOS/MSC	12-Feb-92	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0								
					PROC. REF: MM 49-30-54					
493041		APU FUEL SHUT-OFF SOLENOID VALVE								Component ATA:49
PN:65690	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 49.110	AFL	0								
					PROC. REF: GENERIC NO REF					
493060		APU - CONTROLLER								Component ATA:49
PN:3410000-19	MOS/MSC	08-Dec-06	O/C							
SN:4892-295	HRS									
	APUS									
					PROC. REF: MM 49-60-42					
493070		APU - AIR LOAD CONTROL VALVE								Component ATA:49
PN:109776-3-2	MOS/MSC	12-Feb-92	O/C							
SN:398	HRS	0		TSN 0						
	APUS	0								
					PROC. REF: MM 49-50-31					
493110		APU - FUEL NOZZLE								Component ATA:49
PN:3830061-5	MOS/MSC	09-Mar-18	O/C	TSN 0						
SN:114	HRS	4798		TSN 0						
	APUS			TSN 0						
					PROC. REF: MM 49-30-51					
493120		APU - CLEAN FUEL NOZZLE								Service ATA:49
PN:3830061-5	MOS	10-Jan-23								
SN:114	HRS	5049.7	300 (+10%)		5349.7	5379.7	233.8 (+30)			
	APUS									
					PROC. REF: MM 49-30-51					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
493130		APU - COMBUSTOR DRAIN/ORIFICE FITTING VALVE								Component ATA:49
PN:968214-1	MOS/MSC	12-Feb-92	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0								
					PROC. REF: MM 49-30-24					
493140		APU - CLEAN/INSPECT COMBUSTOR DRAIN/ORIFICE FITTING VALVE								Service ATA:49
PN:968214-1	MOS	10-Jan-23								
SN:UNKNOWN	HRS	5049.7	300 (+10%)		5349.7	5379.7	233.8 (+30)			
	APUS									
					PROC. REF: MM 49-30-24					
494010		APU - IGNITION UNIT								Component ATA:49
PN:3888000-2	MOS/MSC	12-Feb-92	O/C							
SN:90514976	HRS	0		TSN 0						
	APUS	0								
					PROC. REF: MM 49-40-32					
494020		APU - IGNITER PLUG								Component ATA:49
PN:3888366-1	MOS/MSC	09-Mar-18	O/C	TSN 0						
SN:N/A	HRS	4798		TSN 0						
	APUS			TSN 0						
					PROC. REF: MM 49-40-33					
494030		APU - CLEAN/INSPECT IGNITER PLUG								Service ATA:49
PN:3888366-1	MOS	10-Jan-23								
SN:N/A	HRS	5049.7	300 (+10%)		5349.7	5379.7	233.8 (+30)			
	APUS									
					PROC. REF: MM 49-40-33					
495006[U]		APU SURGE (SHUTOFF) VALVE								Component ATA:49
PN:978668-3-1	MOS/MSC	12-Feb-92	O/C							
SN:3038	HRS	0		TSN 0						
	AFL									
	APS									
495206		APU - SURGE SHUTOFF VALVE								Component ATA:49
PN:PN	MOS/MSC	12-Feb-92	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0		TSN 0						
					PROC. REF: MM 49-50-32					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
497010		APU - MOTION PICK UP TRANSDUCER								Component ATA:49
PN:3876000-1	MOS/MSC	12-Feb-92	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0								
					PROC. REF: MM 49-60-43					
497020		APU - THERMOCOUPLE								Component ATA:49
PN:3876003-1	MOS/MSC	12-Feb-92	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0								
					PROC. REF: MM 49-60-45					
497030		APU - HOURMETER								Component ATA:49
PN:620NBH28VDC1500	MOS/MSC	12-Feb-92	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	APUS	0								
					PROC. REF: MM 49-70-40					
499030		APU - DRAIN AND REFILL OIL								Service ATA:49
	MOS/MSC	09-Mar-18	O/C							
	HRS	4798								
	APUS									
					PROC. REF: MM 49-20-00					
499040		APU - REMOVE/INSPECT/REPLACE OIL FILTER ELEMENT								Service ATA:49
	MOS	05-Nov-21								
	HRS	4982.9	500		5482.9		367			
	APUS	1117								
					PROC. REF: MM 49-90-14					
499070		APU - LOW PRESSURE SWITCH								Component ATA:49
PN:3876001-8	MOS/MSC	05-May-98	O/C							
SN:1818	HRS	2134		TSN 0						
	APUS	0		TSN 0						
					PROC. REF: MM 49-60-44					
499110		APU - SOAP CHECK OIL								Service ATA:49
	MOS	25-Jul-18								
	HRS	4822.4	500		5322.4		206.5			
	APUS	1117								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 49 - AIRBORNE AUXILIARY POWER										
49APU1		APU								Component ATA:49
PN:3800016-3-1	MOS/MSC		E/C							
SN:P-331	HRS									
	AFL									
					PROC. REF: AMM 49-10-01-900-802					
ATA 51 - STD PRACTICES AND STRUCT-GENRL										
51-00-00-210-801-01		GENERAL VISUAL INSPECTION OF THE CONTROL SURFACES AND EXPOSED AREAS OF THE AIRCRAFT SKIN								Service ATA:51
	MOS/MSC	09-Mar-18	O/C							
	HRS	8497.6								
WC#: 51.010	AFL	5470								
					PROC. REF: AMM 51-00-00-210-801					
51-00-00-220-801-01		AIRFRAME DIMENSIONAL CHECK								Service ATA:51
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 51-00-00-220-801					
A 51-71-06		DENTS - DAMAGE DATA								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-71-06					
A 51-71-10		REPAIR OF DENTS USING EDR PROCESS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-71-10					
A 51-80-01		BONDING MESH - DAMAGE DATA								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-80-01					
R 51-00-01		ILLUSTRATED OVERVIEW OF ADD AND RPI								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-00-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 51 - STD PRACTICES AND STRUCT-GENRL										
R 51-00-02		LIST OF PRINCIPAL STRUCTURE ELEMENTS (PSE)								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-00-02					
R 51-00-03		REPAIR GENERAL INFORMATION								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-00-03					
R 51-00-04		DAMAGE IDENTIFICATION								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-00-04					
R 51-00-05		DAMAGE TREATMENT PROCESS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-00-05					
R 51-00-06		DAMAGE REPORT AND MAPPING								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-00-06					
R 51-00-12		CRITICAL PARTS WITH LOW SAFETY MARGINS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-00-12					
R 51-10-01		AERODYNAMIC CRITERIA								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-10-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 51 - STD PRACTICES AND STRUCT-GENRL										
R 51-40-01		DIMPLING								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-40-01					
R 51-40-02		CLAMPING								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-40-02					
R 51-40-03		DRILLING								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-40-03					
R 51-40-04		RIVETING								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-40-04					
R 51-40-05		INSTALLATION OF BLIND AND THRU INSERTS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-40-05					
R 51-40-06		COUNTERSINKING								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-40-06					
R 51-40-07		SEALING REPAIRS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-40-07					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 51 - STD PRACTICES AND STRUCT-GENRL										
R 51-71-01		REPAIR OF SKIN PANELS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-71-01					
R 51-71-02		REPAIRS OF FRAMEWORK COMPONENTS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-71-02					
R 51-71-03		JOGGLING OF SHEET METAL								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-71-03					
R 51-71-04		SMOOTHING AND BLENDING								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-71-04					
R 51-71-05		REPLACEMENT OF INTERFERENCE-FIT BUSHINGS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-71-05					
R 51-71-06		STANDARD REPAIRS OF DENTS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-71-06					
R 51-71-09		WELDING								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-71-09					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 51 - STD PRACTICES AND STRUCT-GENRL										
R 51-72-02		SAFETY PRECAUTIONS FOR REPAIRS ON COMPOSITE COMPONENTS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-72-02					
R 51-72-03		USE OF RESINS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-72-03					
R 51-72-04		CURING OF RESINS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-72-04					
R 51-72-05		NON-STRUCTURAL REPAIR OF PAINT ETCHING ON COMPOSITE PANELS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-72-05					
R 51-72-08		WORKING OF COMPOSITE COMPONENTS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-72-08					
R 51-73-01		REPAIR OF MONOLITHIC STRUCTURES BY INJECTION OF RESIN IN THE CURRENT AREA								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-01					
R 51-73-05		STRUCTURAL REPAIR OF FASTENER HOLES IN MONOLITHIC AREAS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-05					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 51 - STD PRACTICES AND STRUCT-GENRL										
R 51-73-09		ECE1 TYPE COSMETIC REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-09					
R 51-73-10		ECE2 TYPE COSMETIC REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-10					
R 51-73-11		ECE3 TYPE COSMETIC REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-11					
R 51-73-12		SCE4 TYPE STRUCTURAL REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-12					
R 51-73-13		SCE5 TYPE STRUCTURAL REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-13					
R 51-73-14		EKE1 TYPE COSMETIC REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-14					
R 51-73-15		EKE2 TYPE COSMETIC REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-15					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 51 - STD PRACTICES AND STRUCT-GENRL										
R 51-73-16		EKE3 TYPE COSMETIC REPAIR (MONOLITHIC EDGING)								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-16					
R 51-73-17		EKE5 TYPE COSMETIC REPAIR (MONOLITHIC STRUCTURE)								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-17					
R 51-73-18		REPAIR OF GLASS FIBER SOLID LAMINATED COMPONENTS								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-73-18					
R 51-77-15		SCE1 TYPE STRUCTURAL REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-77-15					
R 51-77-16		SCE2 TYPE STRUCTURAL REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-77-16					
R 51-77-17		SCE3 TYPE STRUCTURAL REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-77-17					
R 51-77-18		SCE2 SPECIAL TYPE STRUCTURAL REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-77-18					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 51 - STD PRACTICES AND STRUCT-GENRL										
R 51-77-19		SCE3 SPECIAL TYPE STRUCTURAL REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-77-19					
R 51-77-20		SKE1 TYPE STRUCTURAL REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-77-20					
R 51-77-21		SKE2 TYPE STRUCTURAL REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-77-21					
R 51-77-22		SKE3 TYPE STRUCTURAL REPAIR								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-77-22					
R 51-77-23		EKE4 TYPE COSMETIC REPAIR (SANDWICH STRUCTURE)								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-77-23					
R 51-80-01		REPAIR OF THE BONDING MESH								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-80-01					
R 51-80-02		REPAIR OF A TEDLAR PLY								Service ATA:51
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 51-80-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-00-00-640-802-01[S]	LUBRICATION OF THE VISIBLE DOOR HINGES									Service ATA:52
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 52.010	AFL	5775								
					PROC. REF: AMM 52-00-00-640-802					PKG:15
52-10-00-200-803-01[S]	INSPECTION CHECK AND SERVICING OF THE PASSENGER DOOR - PASSENGER DOOR (900MA)									Service ATA:52
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 52-10-00-200-803					PKG:31
52-10-00-610-801-01	SERVICING OF THE PASSENGER DOOR - CHECK OF STRUCTURE AND LATCHES									Service ATA:52
	MOS	08-Sep-23	24 (+1m)		08-Sep-25	08-Oct-25	677 d (+30)			
	HRS	8967	800		9767		774.9			
	AFL	5775								
					PROC. REF: AMM 52-10-00-610-801					
52-10-00-610-801-01A	SERVICING OF THE PASSENGER DOOR - CHECK OF STRUCTURE AND LATCHES (MANDATORY 5-40)									Service ATA:52
	MOS	08-Sep-23	24		08-Sep-25		677 d	ALI		
	HRS	8967	800		9767		774.9			
	AFL	5775								
					PROC. REF: AMM 52-10-00-610-801					
52-10-00-610-801-02	SERVICING OF THE PASSENGER DOOR - CHECK OF OPENING AND CLOSING MECHANISM									Service ATA:52
	MOS	07-Sep-22	24	Adj -127d	03-May-24		184 d			
	HRS	8823	800		9623		630.9			
	AFL	5651								
					PROC. REF: AMM 52-10-00-610-801					
52-10-00-610-801-02A	SERVICING OF THE PASSENGER DOOR - CHECK OF OPENING AND CLOSING MECHANISM (MANDATORY 5-40)									Service ATA:52
	MOS	07-Sep-22	24		07-Sep-24		311 d	ALI		
	HRS	8823	800		9623		630.9			
	AFL	5651								
					PROC. REF: AMM 52-10-00-610-801					
52-10-00-610-801-03	SERVICING OF THE PASSENGER DOOR - GREASING / LUBRICATION									Service ATA:52
	MOS	07-Sep-22	24	Adj -127d	03-May-24		184 d			
	HRS	8823	800		9623		630.9			
	AFL	5651								
					PROC. REF: AMM 52-10-00-610-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-10-00-610-801-03A	SERVICING OF THE PASSENGER DOOR - GREASING / LUBRICATION (MANDATORY 5-40)									Service ATA:52
	MOS	07-Sep-22	24		07-Sep-24		311 d	ALI		
	HRS	8823	800		9623		630.9			
	AFL	5651								
					PROC. REF: AMM 52-10-00-610-801					
52-10-00-610-801-04	SERVICING OF THE PASSENGER DOOR - CHECK OF THE DOOR COUNTERBALANCING SYSTEM									Service ATA:52
	MOS	07-Sep-22	24	Adj -127d	03-May-24		184 d			
	HRS	8823	800		9623		630.9			
	AFL	5651								
					PROC. REF: AMM 52-10-00-610-801					
52-10-00-610-801-04A	SERVICING OF THE PASSENGER DOOR - CHECK OF THE DOOR COUNTERBALANCING SYSTEM (MANDATORY 5-40)									Service ATA:52
	MOS	07-Sep-22	24		07-Sep-24		311 d	ALI		
	HRS	8823	800		9623		630.9			
	AFL	5651								
					PROC. REF: AMM 52-10-00-610-801					
52-10-00-610-801-05	SERVICING OF THE PASSENGER DOOR - CHECK OF DOOR LOCKED INDICATION									Service ATA:52
	MOS	08-Sep-23	6 (+1m)	Adj -6d	31-Mar-24	02-Apr-24	151 d (+2)			
	HRS	8967	800		9767		774.9			
WC#: 52.020	AFL	5775								
					PROC. REF: AMM 52-10-00-610-801					
52-10-00-610-801-05A	SERVICING OF THE PASSENGER DOOR - CHECK OF THE DOOR LOCKED INDICATION (MANDATORY 5-40)									Service ATA:52
	MOS	08-Sep-23	24		08-Sep-25		677 d	ALI		
	HRS	8967	800		9767		774.9			
	AFL	5775								
					PROC. REF: AMM 52-10-00-610-801					
52-10-00-820-801-01	ADJUSTMENT OF THE PASSENGER DOOR									Service ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-10-00-820-801					
52-10-01-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR									Component ATA:52
PN:F50B295A2	MOS/MSC	24-Oct-91	O/C							
SN:S0-228	HRS	0		TSN 0						
WC#: 52.020	AFL	0								
					PROC. REF: AMM 52-10-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-10-03-610-801-01	PRESSURIZATION OF THE PASSENGER DOOR PNEUMATIC ACTUATOR								Service	ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-10-03-610-801					
52-10-03-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR PNEUMATIC ACTUATOR - PASSENGER DOOR PNEUMATIC ACTUATOR (902MC)								Component	ATA:52
PN:107-15-0	MOS/MSC	13-Jan-09	O/C	TSO 0						01/13/2010
SN:446	HRS	6902.3		TSO 0						
WC#: 52.030	AFL	4314		TSO 0						
					PROC. REF: AMM 52-10-03-900-801					
52-10-07-220-801-01	DETAILED INSPECTION OF THE PASSENGER DOOR LOCKING HOOKS								Service	ATA:52
	MOS	24-Oct-91								
	HRS	0								
WC#: 53.160	AFL	0	T:11435		11435		5639			
					PROC. REF: AMM 52-10-07-220-801					
52-10-07-220-801-01A	DETAILED INSPECTION OF THE PASSENGER DOOR LOCKING HOOKS (MANDATORY 5-40)								Service	ATA:52
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.290	AFL	0	T:11435		11435		5639			
					PROC. REF: AMM 52-10-07-220-801					
52-10-13-960-801-01	REPLACEMENT OF THE PASSENGER DOOR SEAL								Service	ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-10-13-960-801					
52-20-00-610-801-01[S]	SERVICING OF THE EMERGENCY EXIT DOOR - SERVICING OF THE LH EMERGENCY EXIT DOOR								Service	ATA:52
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 52.040	AFL	5775								
					PROC. REF: AMM 52-20-00-610-801					PKG:16 ,15
52-20-00-610-801-02[S]	SERVICING OF THE EMERGENCY EXIT DOOR - SERVICING OF THE RH EMERGENCY EXIT DOOR								Service	ATA:52
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 52.040	AFL	5775								
					PROC. REF: AMM 52-20-00-610-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-20-00-610-801-03[S]	SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE LH EMERGENCY EXIT DOOR								Service	ATA:52
	MOS	08-Sep-23	24							
	HRS	8967								
WC#: 52.040	AFL	5775								
					PROC. REF: AMM 52-20-00-610-801					PKG:16 ,15
52-20-00-610-801-03A	SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE LH EMERGENCY EXIT DOOR (MANDATORY 5-40)								Service	ATA:52
	MOS	08-Sep-23	24		08-Sep-25		677 d	MANDATORY 5-40		
	HRS	8967								
WC#: 52.040	AFL	5775								
					PROC. REF: AMM 52-20-00-610-801					
52-20-00-610-801-04[S]	SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE RH EMERGENCY EXIT DOOR								Service	ATA:52
	MOS	08-Sep-23	24							
	HRS	8967								
WC#: 52.040	AFL	5775								
					PROC. REF: AMM 52-20-00-610-801					PKG:16 ,15
52-20-00-610-801-04A	SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE RH EMERGENCY EXIT DOOR (MANDATORY 5-40)								Service	ATA:52
	MOS	08-Sep-23	24		08-Sep-25		677 d	MANDATORY 5-40		
	HRS	8967								
WC#: 52.040	AFL	5775								
					PROC. REF: AMM 52-20-00-610-801					
52-20-00-710-801-03[S]	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM OUTSIDE - UNLOCKING TEST FROM OUTSIDE OF LH EXIT								Service	ATA:52
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 52.040	AFL	5651								
					PROC. REF: AMM 52-20-00-710-801					PKG:21
52-20-00-710-801-04[S]	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM OUTSIDE - UNLOCKING TEST FROM OUTSIDE OF RH EXIT								Service	ATA:52
	MOS	07-Sep-22								
	HRS	8823	1500 (+30)							
WC#: 52.040	AFL	5651								
					PROC. REF: AMM 52-20-00-710-801					PKG:21
52-20-00-720-801-01	FUNCTIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING LOADS								Service	ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-20-00-720-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-20-01-960-801-01	DISCARD OF THE EMERGENCY EXIT DOORS - LH EMERGENCY EXIT DOOR (900MB1)									Service ATA:52
PN:F50B296001A2	MOS	24-Oct-91						LIFE LIMIT		
SN:463	HRS	0		TAC 0						
WC#: 52.040	AFL	0	26718		26718		20922			
					PROC. REF: AMM 52-20-01-960-801					
52-20-01-960-801-01A	DISCARD LH EMERGENCY EXIT (MANDATORY 5-40)									Service ATA:52
PN:F50B296001A2	MOS	24-Oct-91						MANDATORY 5-40		
SN:463	HRS	0								
	AFL	0	26718		26718		20922			
					PROC. REF: AMM 52-20-01-960-801					
52-20-01-960-801-02	DISCARD OF THE EMERGENCY EXIT DOORS - RH EMERGENCY EXIT DOOR (900MB2)									Service ATA:52
PN:F50B296001A2	MOS	24-Oct-91						LIFE LIMIT		
SN:462	HRS	0		TAC 0						
WC#: 52.040	AFL	0	26718		26718		20922			
					PROC. REF: AMM 52-20-01-960-801					
52-20-01-960-801-02A	DISCARD RH EMERGENCY EXIT (MANDATORY 5-40)									Service ATA:52
PN:F50B296001A2	MOS	24-Oct-91						MANDATORY 5-40		
SN:462	HRS	0								
	AFL	0	26718		26718		20922			
					PROC. REF: AMM 52-20-01-960-801					
52-20-05-960-801-01	REPLACEMENT OF THE EMERGENCY EXIT DOOR SEAL									Service ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-20-05-960-801					
52-20-11-960-801-01	REPLACEMENT OF THE EMERGENCY EXIT DOOR ELECTRICAL CONNECTORS									Service ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-20-11-960-801					
52-20-13-960-801-01	REPLACEMENT / ADJUSTMENT OF THE EMERGENCY EXIT DOOR STOPS									Service ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-20-13-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-20-17-640-801-01	LUBRICATION OF THE EMERGENCY EXIT DOOR MECHANISM									Service ATA:52
	MOS/MSC	15-Dec-12	O/C							
	HRS	7936								
WC#: 52.040	AFL	5150								
					PROC. REF: AMM 52-20-17-640-801					
52-20-17-640-801-02	LUBRICATION OF THE EMERGENCY EXIT DOOR MECHANISM									Service ATA:52
	MOS/MSC	15-Dec-11	O/C							
	HRS	7712.7								
WC#: 52.040	AFL	4979								
					PROC. REF: AMM 52-20-17-640-801					
52-30-00-200-801-01	VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT DOOR									Service ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-30-00-200-801					
52-30-00-200-801-01A	VISUAL INSPECTION BAGGAGE COMPARTMENT DOOR (MANDATORY 5-40)									Service ATA:52
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.370	AFL	0	T:26299		26299		20503			
					PROC. REF: AMM 52-30-00-200-801					
52-30-00-200-802-01	INSPECTION OF THE BAGGAGE COMPARTMENT DOOR FORWARD SIDE FOLD									Service ATA:52
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.150	AFL	0								
					PROC. REF: AMM 52-30-00-200-802					
52-30-00-200-802-01A	INSPECTION OF THE BAGGAGE COMPARTMENT DOOR FORWARD SIDE FOLD (MANDATORY 5-40)									Service ATA:52
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.285	AFL	0								
					PROC. REF: AMM 52-30-00-200-802					
52-30-00-610-801-01[S]	SERVICING OF THE BAGGAGE COMPARTMENT DOOR									Service ATA:52
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 52-30-00-610-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-30-01-900-801-01		REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT DOOR								Component ATA:52
PN:F50B299B1	MOS/MSC	24-Oct-91	O/C							
SN:SFA-226	HRS	0		TSN 0						
WC#: 52.050	AFL	0								
					PROC. REF: AMM 52-30-01-900-801					
52-30-20-900-802-01		REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT DOOR RETAINING CABLE, COUNTERBALANCING CABLE AND BUNGEE CORDS								Component ATA:52
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 52-30-20-900-802					
52-40-00-210-801-01 S		GENERAL VISUAL INSPECTION OF THE SERVICE DOORS								Service ATA:52
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 52.070	AFL	5775								
					PROC. REF: AMM 52-40-00-210-801					PKG:16 ,15
52-40-00-720-801-01		FUNCTIONAL TEST OF THE LATCH CONTACT OF THE REAR LAVATORY DRAIN DOOR AND THE REFUELING DOOR								Service ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-40-00-720-801					
52-50-00-710-801-01 S		INSPECTION / TEST OF THE BLOWOUT DOORS / PANELS								Service ATA:52
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 52-50-00-710-801					PKG:31
52-52-01-220-801-01		DETAILED INSPECTION OF THE DOOR AT FRAME 00								Service ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-52-01-220-801					
52-55-00-610-801-01		SERVICING OF THE S-DUCT DOOR								Service ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-55-00-610-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-55-05-960-801-01	REPLACEMENT OF THE S-DUCT DOOR SEAL								Service	ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-55-05-960-801					
52-60-09-610-801-03[S]	SERVICING OF THE REAR COMPARTMENT DOOR								Service	ATA:52
	MOS	07-Sep-22	36 (+1m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 52-60-09-610-801					PKG:207
52-60-09-900-801-01	REMOVAL / INSTALLATION OF THE REAR COMPARTMENT DOOR								Component	ATA:52
PN:F50B297A4	MOS/MSC	24-Oct-91	O/C							
SN:234	HRS	0		TSN 0						
WC#: 52.060	AFL	0								
					PROC. REF: AMM 52-60-09-900-801					
52-70-01-900-801-01	REMOVAL / INSTALLATION OF THE REFUELING DOOR MICROSWITCH - REFUELING DOOR MICROSWITCH (42Q)								Component	ATA:52
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 52-70-01-900-801					
52-70-05-960-801-01	REPLACEMENT OF THE PASSENGER DOOR POSITION INDICATING MICROSWITCH (31M1) - MICROSWITCH (31M1)								Service	ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-70-05-960-801					
52-70-05-960-802-01	REPLACEMENT OF THE PASSENGER DOOR POSITION INDICATING MICROSWITCH (31M2) - MICROSWITCH (31M2)								Service	ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-70-05-960-802					
52-70-05-960-803-01	REPLACEMENT OF THE PASSENGER DOOR POSITION INDICATING MICROSWITCH (34M) - MICROSWITCH (34M)								Service	ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-70-05-960-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
52-70-07-960-801-01	REPLACEMENT OF THE BAGGAGE COMPARTMENT DOOR POSITION INDICATING MICROSWITCH (32M) - MICROSWITCH (32M)								Service	ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-70-07-960-801					
52-70-11-710-801-01[S]	OPERATIONAL TEST OF THE S-DUCT DOOR POSITION INDICATING MICROSWITCH								Service	ATA:52
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 52.080	AFL	5775								
					PROC. REF: AMM 52-70-11-710-801					PKG:16 ,15
52-70-11-710-801-01A	OPERATIONAL TEST OF THE S-DUCT DOOR POSITION INDICATING MICROSWITCH (MANDATORY 5-40)								Service	ATA:52
	MOS	08-Sep-23						MANDATORY 5-40		
	HRS	8967	10000		18967		9974.9			
WC#: 52.080	AFL	5775								
					PROC. REF: AMM 52-70-11-710-801					
52-70-21-960-801-01	REPLACEMENT OF THE REAR COMPARTMENT DOOR POSITION INDICATING MICROSWITCH (33M) - MICROSWITCH (33M)								Service	ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-70-21-960-801					
52-80-13-960-801-01	REPLACEMENT OF THE SEAL BETWEEN THE NLG DOOR AND THE WHEEL WELL								Service	ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-80-13-960-801					
52-80-17-960-801-01	REPLACEMENT OF THE SEALS AND GAP-SEALING BRUSHES ON MLG WHEEL WELL								Service	ATA:52
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 52-80-17-960-801					
522101	LH EMERGENCY EXIT								Component	ATA:52
PN:F50B296001A2	MOS/MSC	24-Oct-91	H/T							
SN:463	HRS	0		TSN 0						
WC#: 52.040	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
522121		RH EMERGENCY EXIT								Component ATA:52
PN:F50B296001A2	MOS/MSC	24-Oct-91	H/T							
SN:462	HRS	0		TSN 0						
WC#: 52.040	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
R 52-00-01		REPLACEMENT OF DOORS AND REMOVABLE PANELS								Service ATA:52
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 52-00-01					
R 52-30-06		REPAIR OF CRACKS ON BAGGAGE COMPARTMENT DOOR WEB								Service ATA:52
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 52-30-06					
R 52-30-07		REPAIR OF CRACKS ON BAGGAGE COMPARTMENT DOOR INTERNAL WEB								Service ATA:52
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 52-30-07					
R 52-60-02		REPAIR OF CRACKS ON SERVICING COMPARTMENT DOOR SKIN AT LATCH CONTROL								Service ATA:52
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 52-60-02					
R 52-80-09		REPAIR OF KLEGECELL BLOCK ON NLG MAIN SHIELD DOOR								Service ATA:52
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 52-80-09					
ATA 53 - FUSELAGE										
53-00-00-200-801-01[S]		INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION								Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 53.025	AFL	5775								
					PROC. REF: AMM 53-00-00-200-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-00-00-200-801-01C		INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION (CPCP)								Service ATA:53
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 53.035	AFL	5775								
					PROC. REF: AMM 53-00-00-200-801					
53-00-00-200-802-01		VISUAL INSPECTION OF THE SKIN PANELS - FRAME 7 TO FRAME 31								Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-00-00-200-802					
53-00-00-200-802-01A		VISUAL INSPECTION OF THE SKIN PANELS - FRAME 7 TO FRAME 31 (MANDATORY 5-40)								Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.310	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-00-00-200-802					
53-00-00-220-801-01		DETAILED INSPECTION OF THE FUSELAGE FRAMES IN PRESSURIZED AREA								Service ATA:53
	MOS	24-Oct-91								
	HRS	0								
WC#: 53.250	AFL	0	10000		10000		4204			
					PROC. REF: AMM 53-00-00-220-801					
53-00-00-250-801-01		EDDY-CURRENT INSPECTION FOR CORROSION AT INTERFACES BETWEEN SPOT-WELDED SKIN PANELS AND STRINGERS BETWEEN FRAMES 0 AND 19								Service ATA:53
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.350	AFL	0								
					PROC. REF: AMM 53-00-00-250-801					
53-00-00-250-801-01C		EDDY-CURRENT INSPECTION FOR CORROSION AT INTERFACES BETWEEN SPOT-WELDED SKIN PANELS AND STRINGERS BETWEEN FRAMES 0 AND 19 (CPCP)								Service ATA:53
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.045	AFL	0								
					PROC. REF: AMM 53-00-00-250-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-00-00-250-802-01	EDDY-CURRENT INSPECTION OF THE FUSELAGE FRAMEWORK AROUND THE WINDOWS IN T2 AND T3 SECTIONS									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-00-00-250-802					
53-00-00-250-802-01A	NON DESTRUCTIVE TEST OF THE FUSELAGE FRAMEWORK AROUND THE WINDOWS IN T2 AND T3 SECTIONS (LONGITUDINAL CRACKS) (MANDATORY 5-40)									Service ATA:53
	MOS							MANDATORY 5-40		
	HRS									
WC#: 53.330	AFL		T:31250		31250		25454			
					PROC. REF: AMM 53-00-00-250-802					
53-04-01-220-801-01	DETAILED INSPECTION OF THE FLOOR PANEL OMEGAS AT FRAMES 18-19									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-04-01-220-801					
53-04-01-220-801-01A	VISUAL INSPECTION FLOOR OMEGAS AT FRAMES 18-19 (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.145	AFL	0	T:27500		27500		21704			
					PROC. REF: AMM 53-04-01-220-801					
53-04-01-900-802-02	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (121AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-03	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (123AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-04	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (124AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-04-01-900-802-05	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (131AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-06	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (133AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-07	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (133BZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-08	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (134AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-09	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (141AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-10	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (141BZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-11	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (143AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-04-01-900-802-12	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (143BZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-13	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (144AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-14	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (144BZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-15	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (151AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-16	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (151BZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-17	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (153AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-18	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (153BZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-04-01-900-802-19	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (154AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-20	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (154BZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-21	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (161AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-22	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (161BZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-23	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (161CZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-24	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (165AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-25	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (165BZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-04-01-900-802-26	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (166AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-27	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (166BZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-01-900-802-28	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (167AZ)									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-01-900-802					
53-04-03-900-801-01	REMOVAL / INSTALLATION OF THE COCKPIT FLOOR PANELS									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-04-03-900-801					
53-04-05-250-801-01	EDDY-CURRENT INSPECTION OF FLOOR PANEL STIFFENERS BETWEEN FRAMES 31 AND 35									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-04-05-250-801					
53-04-05-250-801-01A	EDDY CURRENT INSPECTION OF FLOOR PANEL STIFFENERS BETWEEN FRAMES 31 AND 35 (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.195	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-04-05-250-801					
53-10-00-200-808-01[S]	INSPECTION OF THE NLG BAY									Service ATA:53
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 32.2801	AFL	5775								
					PROC. REF: AMM 53-10-00-200-808					PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-10-00-200-808-01C		INSPECTION OF THE NLG BAY (CPCP)								Service ATA:53
	MOS	08-Sep-23	13 (+1m)		08-Oct-24	08-Nov-24	342 d (+31)	CPCP		
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 53-10-00-200-808					
53-10-00-210-802-01S		GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT								Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 53.0401	AFL	5775								
					PROC. REF: AMM 53-10-00-210-802					PKG:16 ,15
53-10-00-220-801-01S		DETAILED INSPECTION OF THE STATIC PRESSURE PROBE AND OF THE FUSELAGE SKIN IN PROBE AREA								Service ATA:53
	MOS	08-Sep-23	24 (+1m)					RVSM		
	HRS	8967								
WC#: 53.030	AFL	5775								
					PROC. REF: AMM 53-10-00-220-801					PKG:16 ,15
53-10-00-220-802-01S		DETAILED INSPECTION OF THE FLIGHT COMPARTMENT								Service ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 53.0402	AFL	5651								
					PROC. REF: AMM 53-10-00-220-802					PKG:31
53-10-00-220-802-01C		DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)								Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 53.055	AFL	5651								
					PROC. REF: AMM 53-10-00-220-802					
53-10-00-220-803-01S		DETAILED INSPECTION OF THE NLG BAY								Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 32.2802	AFL	5775								
					PROC. REF: AMM 53-10-00-220-803					PKG:16 ,15
53-10-00-220-803-01C		DETAILED INSPECTION OF THE NLG BAY (CPCP)								Service ATA:53
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 53.065	AFL	5775								
					PROC. REF: AMM 53-10-00-220-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-10-00-220-804-01	DIMENSIONAL CHECK OF NLG BALL-JOINT BEARING BORES									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-10-00-220-804					
53-10-03-250-802-01	EDDY-CURRENT INSPECTION OF THE PASSENGER DOOR FRAME CORNERS									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-10-03-250-802					
53-10-03-250-802-01A	EDDY CURRENT INSPECTION OF THE PASSENGER DOOR FRAME CORNERS (MANDATORY 5-40)									Service ATA:53
	MOS							MANDATORY 5-40		
	HRS									
WC#: 53.320	AFL		T:31250		31250		25454			
					PROC. REF: AMM 53-10-03-250-802					
53-10-05-250-801-01	EDDY-CURRENT INSPECTION OF FRAME 12 AROUND PAX DOOR TELESCOPIC ROD FITTING									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-10-05-250-801					
53-10-05-250-801-01A	EDDY CURRENT INSPECTION OF FRAME 12 AROUND PAX DOOR TELESCOPIC ROD FITTING (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.215	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-10-05-250-801					
53-10-31-220-801-01	DETAILED INSPECTION OF COCKPIT UPPER SKIN JUNCTION WITH WINDSHIELD AND WINDOW FRAMES									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-10-31-220-801					
53-10-31-220-801-01A	DETAILED INSPECTION OF COCKPIT UPPER SKIN JUNCTION WITH WINDSHIELD AND WINDOW FRAMES (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.152	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-10-31-220-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-10-39-220-801-01[S]	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES									Service ATA:53
PN:PN	MOS	07-Sep-22	72 (+2m)							
SN:UNKNOWN	HRS	8823								
WC#: 53.210	AFL	5651								
					PROC. REF: AMM 53-10-39-220-801					PKG:31
53-10-39-220-801-01A	INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD/WINDOW FRAMES (MANDATORY 5-40)									Service ATA:53
	MOS	07-Sep-22						MANDATORY 5-40		
	HRS	8823								
WC#: 53.210	AFL	5651	3750		9401		3605			
					PROC. REF: AMM 53-10-39-220-801					
53-10-39-220-801-01C	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 53.075	AFL	5651								
					PROC. REF: AMM 53-10-39-220-801					
53-10-39-220-803-01	DETAILED INSPECTION OF THE SCREWS ATTACHING THE WINDSHIELD FRAMES TO FRAME 0									Service ATA:53
	MOS	24-Oct-91								
	HRS	0								
WC#: 53.090	AFL	0	T:10525		10525		4729			
					PROC. REF: AMM 53-10-39-220-803					
53-10-39-220-803-01A	DETAILED INSPECTION OF THE ATTACHING SCREW OF COCKPIT WINDSHIELD FRAMES TO FRAME 0 (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.235	AFL	0	T:10525		10525		4729			
					PROC. REF: AMM 53-10-39-220-803					
53-10-39-220-804-01	DETAILED INSPECTION OF THE FRAME OF THE LH AND RH REAR COCKPIT WINDOWS - LH SIDE REAR WINDOW									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 53.140	AFL	0								
					PROC. REF: AMM 53-10-39-220-804					
53-10-39-220-804-01A	DETAILED INSPECTION OF THE FRAME OF THE LH SIDE REAR COCKPIT WINDOWS (MANDATORY 5-40)									Service ATA:53
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.265	AFL	0								
					PROC. REF: AMM 53-10-39-220-804					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-10-39-220-804-02	DETAILED INSPECTION OF THE FRAME OF THE LH AND RH REAR COCKPIT WINDOWS - RH SIDE REAR WINDOW									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 53.140	AFL	0								
					PROC. REF: AMM 53-10-39-220-804					
53-10-39-220-804-02A	INSPECTION RIGHT REAR WINDOW FRAME (MADATORY 5-40)									Service ATA:53
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.275	AFL	0								
					PROC. REF: AMM 53-10-39-220-804					
53-10-39-220-805-01	DETAILED INSPECTION OF THE FRAME OF THE RH COCKPIT LATERAL WINDOW									Service ATA:53
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.110	AFL	0								
					PROC. REF: AMM 53-10-39-220-805					
53-10-39-220-805-01A	DETAILED INSPECTION OF THE FRAME OF THE RH COCKPIT LATERAL WINDOW (MANDATORY 5-40)									Service ATA:53
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.110	AFL	0								
					PROC. REF: AMM 53-10-39-220-805					
53-10-39-250-801-01[S]	EDDY CURRENT INSPECTION OF THE LOWER RECESSES OF THE COCKPIT WINDSHIELD / WINDOW FRAMES									Service ATA:53
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 53.420	AFL	5347								
					PROC. REF: AMM 53-10-39-250-801					PKG:32
53-10-39-250-801-01C	EDDY CURRENT INSPECTION OF THE LOWER RECESSES OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)									Service ATA:53
	MOS	07-Mar-16	148		07-Jul-28		1710 d	CPCP		
	HRS	8278.1								
WC#: 53.095	AFL	5347								
					PROC. REF: AMM 53-10-39-250-801					
53-10-39-250-802-01	EDDY-CURRENT INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-10-39-250-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-10-39-250-802-01A	EDDY CURRENT INSPECTION OF THE COCKPIT WINDSHIELD/WINDOW FRAMES (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.300	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-10-39-250-802					
53-10-39-270-801-01 S	ULTRASONIC CHECK OF THE LOWER PART OF THE FRAMES OF THE COCKPIT WINDSHIELDS AND WINDOWS									Service ATA:53
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 53.420	AFL	5347								
					PROC. REF: AMM 53-10-39-270-801					PKG:32
53-10-39-270-801-01C	ULTRASONIC CHECK OF THE LOWER PART OF THE FRAMES OF THE COCKPIT WINDSHIELDS AND WINDOWS (CPCP)									Service ATA:53
	MOS	07-Mar-16	148		07-Jul-28		1710 d	CPCP		
	HRS	8278.1								
WC#: 53.115	AFL	5347								
					PROC. REF: AMM 53-10-39-270-801					
53-10-39-270-802-01 S	ULTRASONIC CHECK OF THE VERTICAL POSTS OF THE COCKPIT WINDSHIELDS AND WINDOWS									Service ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 53-10-39-270-802					PKG:31
53-10-39-270-802-01A	ULTRASONIC CHECK OF THE VERTICAL POSTS OF THE COCKPIT WINDSHIELDS AND WINDOWS (MANDATORY 5-40)									Service ATA:53
	MOS	07-Sep-22						MANDATORY 5-40		
	HRS	8823								
WC#: 53.270	AFL	5651	3750		9401		3605			
					PROC. REF: AMM 53-10-39-270-802					
53-10-39-270-802-01C	ULTRASONIC CHECK OF THE VERTICAL POSTS OF THE COCKPIT WINDSHIELDS AND WINDOWS (CPCP)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 53.120	AFL	5651								
					PROC. REF: AMM 53-10-39-270-802					
53-10-39-290-801-01C	ENDOSCOPE INSPECTION OF THE LOWER RECESSES OF COCKPIT WINDSHIELD/WINDOW FRAMES (CPCP)									Service ATA:53
	MOS/MSC	24-Oct-91	O/C					CPCP		
	HRS	0								
WC#: 53.125	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-10-41-220-801-01	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR									Service ATA:53
	MOS	24-Oct-91								
	HRS	0								
WC#: 53.228	AFL	0	T:10000		10000		4204			
					PROC. REF: AMM 53-10-41-220-801					
53-10-41-220-801-01A	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.228	AFL	0	T:10000		10000		4204			
					PROC. REF: AMM 53-10-41-220-801					
53-10-45-250-801-01	EDDY-CURRENT INSPECTION OF THE NLG BAY SKIN PANEL AND DOOR FRAME AT FRAME 7									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-10-45-250-801					
53-10-45-250-801-01A	EDDY CURRENT INSPECTION OF THE NLG BAY SKIN PANEL AND DOOR FRAME AT FRAME 7 (MANDATORY 5-40)									Service ATA:53
	MOS							MANDATORY 5-40		
	HRS									
WC#: 53.340	AFL		T:31250		31250		25454			
					PROC. REF: AMM 53-10-45-250-801					
53-11-00-210-801-02[S]	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA									Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 53.0301	AFL	5775								
					PROC. REF: AMM 53-11-00-210-801					PKG:16 ,15
53-11-00-210-801-02C	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA (CPCP)									Service ATA:53
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 53.130	AFL	5775								
					PROC. REF: AMM 53-11-00-210-801					
53-11-00-220-801-01[S]	DETAILED INSPECTION OF THE NOSE CONE AREA									Service ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 53.0302	AFL	5651								
					PROC. REF: AMM 53-11-00-220-801					PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-11-00-220-801-01C	DETAILED INSPECTION OF THE NOSE CONE AREA (CPCP)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 53.135	AFL	5651								
					PROC. REF: AMM 53-11-00-220-801					
53-11-00-760-801-01 S	CHECK OF THE NOSE CONE ELECTRICAL BONDING									Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 53.380	AFL	5775								
					PROC. REF: AMM 53-11-00-760-801					PKG:16 ,15
53-11-01-900-801-01	REMOVAL / INSTALLATION OF THE NOSE CONE									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-11-01-900-801					
53-11-09-900-801-01	REMOVAL / INSTALLATION OF THE RADOME									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-11-09-900-801					
53-11-33-960-801-01	REPLACEMENT / REPAIR OF THE LIGHTNING ARRESTER STRIPS									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-11-33-960-801					
53-11-33-960-802-01	REPLACEMENT OF THE ARGEPOX LIGHTNING STRIPS WITH DAYTON GRANGER LIGHTNING STRIPS									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-11-33-960-802					
53-30-00-210-802-01 S	GENERAL VISUAL INSPECTION OF THE PASSENGER CABIN									Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 53.0501	AFL	5775								
					PROC. REF: AMM 53-30-00-210-802					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-30-00-220-801-01[S]	DETAILED INSPECTION OF THE PASSENGER CABIN									Service ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 53.0502	AFL	5651								
					PROC. REF: AMM 53-30-00-220-801					PKG:31
53-30-00-220-801-01C	DETAILED INSPECTION OF THE PASSENGER CABIN (CPCP)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 53.230	AFL	5651								
					PROC. REF: AMM 53-30-00-220-801					
53-30-00-220-802-01	INSPECTION OF THE CENTER FLOOR ANGLE PIECE, RH SIDE BETWEEN FRAME 19 AND FRAME 26									Service ATA:53
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.170	AFL	0								
					PROC. REF: AMM 53-30-00-220-802					
53-30-00-220-802-01A	INSPECTION OF THE CENTER FLOOR ANGLE PIECE, RH SIDE BETWEEN FRAME 19 AND FRAME 26 (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91								
	HRS	0								
WC#: 53.302	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-30-00-220-802					
53-30-00-220-803-01	DETAILED INSPECTION OF THE FLOOR PICK-UP ANGLE AT FRAME 27 AND OF THE FLOOR PANEL BETWEEN FRAME 26 AND FRAME 29									Service ATA:53
	MOS	24-Oct-91								
	HRS	0								
WC#: 53.305	AFL	0	T:10000		10000		4204			
					PROC. REF: AMM 53-30-00-220-803					
53-30-00-220-803-01A	DETAILED INSPECTION OF THE FLOOR PICKUP ANGLE AT FRAME 27 AND OF THE FLOOR PANEL BETWEEN FRAME 26 AND FRAME 29 (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.360	AFL	0	T:10000		10000		4204			
					PROC. REF: AMM 53-30-00-220-803					
53-30-00-220-805-01	DETAILED INSPECTION OF FUSELAGE SKIN IN SPLICE AREA AT STRINGER 13 BETWEEN FRAME 13 AND 18									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-30-00-220-805					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-30-00-220-805-01A	DETAILED INSPECTION OF FUSELAGE SKIN IN SPLICE AREA AT STRINGER 13 BETWEEN FRAME 13 AND 18 (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
	AFL	0	T:30000		30000		24204			
					PROC. REF: AMM 53-30-00-220-805					
53-30-00-250-801-01	EDDY-CURRENT INSPECTION OF THE EMERGENCY EXIT DOOR FRAME ROUNDED ANGLES									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-30-00-250-801					
53-30-00-250-801-01A	EDDY CURRENT INSPECTION OF THE PASSENGER CABIN SKIN PANEL AROUND EMERGENCY EXIT DOOR ROUNDED ANGLES (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.175	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-30-00-250-801					
53-30-00-250-803-01	EDDY-CURRENT INSPECTION OF THE FINGER PLATE OF CIRCUMFERENTIAL SPLICE AT FRAMES 19 AND 26									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-30-00-250-803					
53-30-00-250-803-01A	EDDY CURRENT INSPECTION OF THE FINGER PLATE OF CIRCUMFERENTIAL SPLICE AT FRAMES 19 AND 26 (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.180	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-30-00-250-803					
53-30-01-220-801-01 S	DETAILED INSPECTION OF THE FEEDER TANKS									Service ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 53.010	AFL	5651								
					PROC. REF: AMM 53-30-01-220-801					PKG:31
53-30-01-220-801-01A	DETAILED INSPECTION OF THE FEEDER TANKS (MANDATORY 5-40)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	MANDATORY 5-40		
	HRS	8823								
WC#: 53.225	AFL	5651								
					PROC. REF: AMM 53-30-01-220-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-30-01-220-801-01C	DETAILED INSPECTION OF THE FEEDER TANKS (CPCP)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 53.240	AFL	5651								
					PROC. REF: AMM 53-30-01-220-801					
53-30-01-790-801-01	LEAK TEST OF THE FEEDER TANK									Service ATA:53
	MOS/MSC	17-Dec-10	N/A							
	HRS	7458.3								
WC#: 53.260	AFL	4759								
					PROC. REF: AMM 53-30-01-790-801					
53-30-01-790-801-01A	LEAK TEST OF THE FEEDER TANK (MANDATORY 5-40)									Service ATA:53
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.280	AFL	0								
					PROC. REF: AMM 53-30-01-790-801					
53-30-01-900-801-01	REMOVAL / INSTALLATION OF THE DOUBLE SKIN AT FRAME 28									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-30-01-900-801					
53-30-01-900-802-01	REMOVAL / INSTALLATION OF THE DOUBLE SKIN AT FRAME 31									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-30-01-900-802					
53-30-01-900-803-01	RESTORATION OF FEEDER TANK SEALING									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-30-01-900-803					
53-30-03-960-801-01	REPLACEMENT OF THE ALUMINUM LIGHTNING DIVERTER STRIPS ON REAR TANK									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 53.430	AFL	0								
					PROC. REF: AMM 53-30-03-960-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-30-05-960-801-01	REPLACEMENT REPAIR OF THE LIGHTNING PROTECTION SEALANT PATCHES INSIDE REAR FUSELAGE FEEDER TANKS									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-30-05-960-801					
53-40-00-200-804-01[S]	INSPECTION OF THE MLG BAYS - LH MLG BAY									Service ATA:53
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 32.1401	AFL	5775								
					PROC. REF: AMM 53-40-00-200-804					PKG:15
53-40-00-200-804-01C	INSPECTION OF THE MLG BAYS - LH MLG BAY (CPCP)									Service ATA:53
	MOS	08-Sep-23	13 (+1m)		08-Oct-24	08-Nov-24	342 d (+31)	CPCP		
	HRS	8967								
WC#: 53.245	AFL	5775								
					PROC. REF: AMM 53-40-00-200-804					
53-40-00-200-804-02[S]	INSPECTION OF THE MLG BAYS - RH MLG BAY									Service ATA:53
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 32.1401	AFL	5775								
					PROC. REF: AMM 53-40-00-200-804					PKG:15
53-40-00-200-804-02C	INSPECTION OF THE MLG BAYS - RH MLG BAY (CPCP)									Service ATA:53
	MOS	08-Sep-23	13 (+1m)		08-Oct-24	08-Nov-24	342 d (+31)	CPCP		
	HRS	8967								
WC#: 53.245	AFL	5775								
					PROC. REF: AMM 53-40-00-200-804					
53-40-00-210-803-02[S]	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE THE FEEDER TANKS									Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 53.0601	AFL	5775								
					PROC. REF: AMM 53-40-00-210-803					PKG:16 ,15
53-40-00-210-803-02C	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE THE FEEDER TANKS (CPCP)									Service ATA:53
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 53.255	AFL	5775								
					PROC. REF: AMM 53-40-00-210-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-40-00-220-802-01[S]	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS									Service ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 53.450	AFL	5651								
					PROC. REF: AMM 53-40-00-220-802					PKG:31
53-40-00-220-802-01A	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (MANDATORY 5-40)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	MANDATORY 5-40		
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 53-40-00-220-802					
53-40-00-220-802-01C	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 53-40-00-220-802					
53-40-00-220-803-01[S]	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE THE FEEDER TANKS									Service ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 53.0602	AFL	5651								
					PROC. REF: AMM 53-40-00-220-803					PKG:31
53-40-00-220-803-01C	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE THE FEEDER TANKS (CPCP)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 53.295	AFL	5651								
					PROC. REF: AMM 53-40-00-220-803					
53-40-00-220-804-01[S]	DETAILED INSPECTION OF THE MLG BAYS - LH MLG BAY									Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 32.1402	AFL	5775								
					PROC. REF: AMM 53-40-00-220-804					PKG:16 ,15
53-40-00-220-804-01C	DETAILED INSPECTION OF THE MLG BAYS - LH MLG BAY (CPCP)									Service ATA:53
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 53.315	AFL	5775								
					PROC. REF: AMM 53-40-00-220-804					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-40-00-220-804-02[S]	DETAILED INSPECTION OF THE MLG BAYS - RH MLG BAY									Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 32.1402	AFL	5775								
					PROC. REF: AMM 53-40-00-220-804					PKG:16 ,15
53-40-00-220-804-02C	DETAILED INSPECTION OF THE MLG BAYS - RH MLG BAY (CPCP)									Service ATA:53
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 53.315	AFL	5775								
					PROC. REF: AMM 53-40-00-220-804					
53-40-07-220-801-01	DETAILED INSPECTION OF THE CENTERWING TANK LOWER PANELS									Service ATA:53
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-40-07-220-801					
53-40-07-220-801-01A	DETAILED INSPECTION OF THE CENTERWING TANK LOWER PANELS (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.165	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-40-07-220-801					
53-40-07-250-801-01	EDDY-CURRENT INSPECTION OF CENTERWING TANK LOWER PANEL SPLICE									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-40-07-250-801					
53-40-07-250-801-01A	EDDY CURRENT INSPECTION OF CENTERWING TANK LOWER PANEL SPLICE (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.172	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-40-07-250-801					
53-40-07-280-801-01[S]	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF CENTERWING TANK LOWER PANELS AND MAPPING OF REWORKED AREAS									Service ATA:53
	MOS	07-Sep-22	144 (+2m)							
	HRS	8823								
WC#: 53.400	AFL	5651								
					PROC. REF: AMM 53-40-07-280-801					PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-40-07-280-801-01A	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF CENTERWING TANK LOWER PANELS AND MAPPING OF REWORKED AREAS (MANDATORY 5-40)								Service	ATA:53
	MOS	07-Sep-22						MANDATORY 5-40		
	HRS	8823								
WC#: 53.155	AFL	5651	7500		13151		7355			
					PROC. REF: AMM 53-40-07-280-801					
53-40-07-280-801-01C	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF CENTERWING TANK LOWER PANELS AND MAPPING OF REWORKED AREAS (CPCP)								Service	ATA:53
	MOS	07-Sep-22	151		07-Apr-35		4175 d	CPCP		
	HRS	8823								
WC#: 53.325	AFL	5651								
					PROC. REF: AMM 53-40-07-280-801					
53-40-07-900-801-01	REMOVAL / INSTALLATION OF THE CENTERWING TANK REMOVABLE PANEL								Component	ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-40-07-900-801					
53-40-07-960-801-01	DISCARD OF THE CENTERWING TANK LOWER PANELS								Service	ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-40-07-960-801					
53-40-07-960-801-01A	DISCARD CENTRAL WING SECTION OF THE CENTERWING TANK LOWER PANELS (MANDATORY 5-40)								Service	ATA:53
	MOS/MSC	24-Oct-91	O/C					LIFE LIMIT		
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-40-07-960-801					
53-41-00-220-801-01[S]	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - LH WING								Service	ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801					PKG:31
53-41-00-220-801-01C	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - LH WING (CPCP)								Service	ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 53.335	AFL	5651								
					PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-41-00-220-801-02[S]	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - RH WING									Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801					PKG:16 ,15
53-41-00-220-801-02C	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - RH WING (CPCP)									Service ATA:53
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 53.335	AFL	5775								
					PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801					
53-41-00-620-802-01[S]	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - LH WING UPPER BOLT RECESSES									Service ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.170	AFL	5651								
					PROC. REF: AMM 53-41-00-620-802					PKG:31
53-41-00-620-802-01C	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - LH WING UPPER BOLT RECESSES (CPCP)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 53.345	AFL	5651								
					PROC. REF: AMM 53-41-00-620-802					
53-41-00-620-802-02[S]	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - RH WING UPPER BOLT RECESSES									Service ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.180	AFL	5651								
					PROC. REF: AMM 53-41-00-620-802					PKG:31
53-41-00-620-802-02C	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - RH WING UPPER BOLT RECESSES (CPCP)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 53.345	AFL	5651								
					PROC. REF: AMM 53-41-00-620-802					
53-41-00-620-802-03[S]	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - LH WING LOWER BOLT RECESSES									Service ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.170	AFL	5651								
					PROC. REF: AMM 53-41-00-620-802					PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-41-00-620-802-03C	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - LH WING LOWER BOLT RECESSES (CPCP)								Service	ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 53-41-00-620-802					
53-41-00-620-802-04[S]	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - RH WING LOWER BOLT RECESSES								Service	ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.180	AFL	5651								
					PROC. REF: AMM 53-41-00-620-802					PKG:31
53-41-00-620-802-04C	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - RH WING LOWER BOLT RECESSES (CPCP)								Service	ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 53-41-00-620-802					
53-41-01-640-801-01[S]	LUBRICATION OF THE WING TO FUSELAGE CONNECTING ROD - LH LINK ROD								Service	ATA:53
PN:PN	MOS	07-Sep-22	72 (+2m)							
SN:UNKNOWN	HRS	8823								
WC#: 57.040	AFL	5651								
					PROC. REF: AMM 53-41-01-640-801					PKG:31
53-41-01-640-801-02[S]	LUBRICATION OF THE WING TO FUSELAGE CONNECTING ROD - RH LINK ROD								Service	ATA:53
PN:PN	MOS	07-Sep-22	72 (+2m)							
SN:UNKNOWN	HRS	8823								
WC#: 57.040	AFL	5651								
					PROC. REF: AMM 53-41-01-640-801					PKG:31
53-41-01-900-801-01	REMOVAL / INSTALLATION OF THE WING TO FUSELAGE CONNECTING ROD AT FRAME 29								Component	ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 57.040	AFL	0								
					PROC. REF: AMM 53-41-01-900-801					
53-41-01-900-801-02	RH WING TO FUSELAGE CONNECTING AT FRAME 29 ROD								Component	ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 57.040	AFL	0								
					PROC. REF: AMM 53-41-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-50-00-210-804-02[S]	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT									Service ATA:53
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 53.0801	AFL	5775								
					PROC. REF: AMM 53-50-00-210-804					PKG:15
53-50-00-210-804-02C	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT (CPCP)									Service ATA:53
	MOS	08-Sep-23	13 (+1m)		08-Oct-24	08-Nov-24	342 d (+31)	CPCP		
	HRS	8967								
WC#: 53.350	AFL	5775								
					PROC. REF: AMM 53-50-00-210-804					
53-50-00-210-806-02[S]	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT									Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 53.0701	AFL	5775								
					PROC. REF: AMM 53-50-00-210-806					PKG:16 ,15
53-50-00-210-806-02C	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)									Service ATA:53
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 53.355	AFL	5775								
					PROC. REF: AMM 53-50-00-210-806					
53-50-00-210-807-02[S]	GENERAL VISUAL INSPECTION OF THE APU AREA									Service ATA:53
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 49.124	AFL	5775								
					PROC. REF: AMM 53-50-00-210-807					PKG:15
53-50-00-220-803-02[S]	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT									Service ATA:53
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 53.0702	AFL	5651								
					PROC. REF: AMM 53-50-00-220-803					PKG:31
53-50-00-220-803-02C	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)									Service ATA:53
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 53.375	AFL	5651								
					PROC. REF: AMM 53-50-00-220-803					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-50-00-220-805-01[S]	DETAILED INSPECTION OF THE REAR COMPARTMENT									Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 53.0802	AFL	5775								
					PROC. REF: AMM 53-50-00-220-805					PKG:16 ,15
53-50-00-220-805-01C	DETAILED INSPECTION OF THE REAR COMPARTMENT (CPCP)									Service ATA:53
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 53.385	AFL	5775								
					PROC. REF: AMM 53-50-00-220-805					
53-50-07-900-801-01	REMOVAL / INSTALLATION OF THE FIN STUB REAR CONE									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-50-07-900-801					
53-50-34-220-801-01	DETAILED INSPECTION OF THE FRAME 34 UPPER AND LOWER SECTIONS									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-50-34-220-801					
53-50-34-220-801-01A	DETAILED INSPECTION OF THE FRAME 34 UPPER AND LOWER SECTIONS (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.142	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-50-34-220-801					
53-50-35-220-801-01	DETAILED INSPECTION OF THE FRAME 35 LOWER SECTION									Service ATA:53
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.100	AFL	0		TAC 0						
					PROC. REF: AMM 53-50-35-220-801					
53-50-35-220-802-01	DETAILED INSPECTION OF THE FRAME 35 UPPER AND LOWER SECTIONS									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-50-35-220-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-50-35-220-802-01A	DETAILED INSPECTION OF THE FRAME 35 UPPER AND LOWER SECTIONS (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-50-35-220-802					
53-50-35-250-801-01	EDDY-CURRENT INSPECTION OF THE FRAME 35 VERTICAL BEAMS									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-50-35-250-801					
53-50-35-250-801-01A	EDDY CURRENT INSPECTION OF THE FRAME 35 VERTICAL BEAMS (MANDATORY 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.185	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-50-35-250-801					
53-50-40-220-802-01	DETAILED INSPECTION OF THE STUB-FUSELAGE ASSEMBLY SCREWS AT FRAMES 41 AND 42									Service ATA:53
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 53.220	AFL	0								
					PROC. REF: AMM 53-50-40-220-802					
53-50-44-220-801-01	DETAILED INSPECTION OF THE FIN STUB FRONT SPAR									Service ATA:53
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 53-50-44-220-801					
53-50-44-220-801-01A	DETAILED INSPECTION OF THE FIN STUB FRONT SPAR (MANDATORY REF 5-40)									Service ATA:53
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.205	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 53-50-44-220-801					
53-60-01-900-801-01	REMOVAL / INSTALLATION OF THE FUSELAGE FAIRINGS									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 53-60-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
53-80-00-200-801-01 S	CHECK OF THE CONDENSATION AND STREAM WATER DRAINS									Service ATA:53
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 51.040	AFL	5775								
					PROC. REF: AMM 53-80-00-200-801					PKG:16 ,15
53-80-09-710-801-01	OPERATIONAL TEST OF THE "CIRCLE SEAL" AUTOMATIC DRAINS									Service ATA:53
	MOS	09-Mar-18	72 (+2m)		09-Mar-24	09-May-24	129 d (+61)			
	HRS	8497.6								
WC#: 51.050	AFL	5470								
					PROC. REF: AMM 53-80-09-710-801					
530321	FLIGHT COMPARTMENT REMOVABLE WINDOW FAIRING									Component ATA:53
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 53.210	AFL	0								
					PROC. REF: GENERIC NO REF					
A 53-10-02	ACCEPTANCE CRITERIA FOR BORES OF NLG BALL-JOINT BEARINGS - CORROSION TREATMENT									Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-10-02					
A 53-10-08	ACCEPTANCE CRITERIA FOR BORES OF NLG BALL-JOINT BEARINGS - DIMENSIONAL CHECK									Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-10-08					
A 53-10-39	ACCEPTANCE CRITERIA FOR CRACKS ON THE WINDSHIELD AND COCKPIT WINDOW LOWER FRAME RECESSES									Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-10-39					
A 53-30-09	CORROSION ON LH FUSELAGE AT LADDER ANCHORING POINTS AT FRAME 27-28 - DAMAGE DATA									Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-30-09					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
A 53-40-15		CENTER WING JUNCTION PIPE - DAMAGE DATA								Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-40-15					
R 53-00-12		ADJUSTMENT OF THE CLEARANCE BETWEEN THE FAIRING STIFFENERS AND THE FUSELAGE SKIN								Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-00-12					
R 53-00-22		REPAIR OF CORROSION ON FUSELAGE SKIN AROUND APU EXHAUST								Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-00-22					
R 53-10-02		REPAIR OF CORROSION ON BORES OF NLG BALL-JOINT BEARINGS								Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-10-02					
R 53-10-18		REPAIR OF WINDSHIELD TRIMMING								Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-10-18					
R 53-10-20		REPAIR OF THE SLIDING WINDOW RACK SYSTEM								Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-10-20					
R 53-40-01		REPAIR OF BEAD SEALANT AT JUNCTION PLATE								Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-40-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
R 53-40-15		REPAIR OF CENTER WING JUNCTION PIPE								Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-40-15					
R 53-60-09		REPAIR OF FAIRING AT STIFFENER WELDING POINTS								Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-60-09					
R 53-60-11		REPAIR OF LANDING LIGHT FAIRING								Service ATA:53
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 53-60-11					
ATA 54 - NACELLES/PYLONS										
54-00-00-210-810-03		GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1								Service ATA:54
	MOS	07-Sep-22	19		07-Apr-24		158 d			
	HRS	8823	800		9623		630.9			
WC#: 54.0101	AFL	5651								
					PROC. REF: AMM 54-00-00-210-810					
54-00-00-210-810-03C		GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (CPCP)								Service ATA:54
	MOS	07-Sep-22	19		07-Apr-24		158 d	CPCP		
	HRS	8823	800		9623		630.9			
WC#: 54.085	AFL	5651								
					PROC. REF: AMM 54-00-00-210-810					
54-00-00-210-810-04		GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3								Service ATA:54
	MOS	07-Sep-22	19		07-Apr-24		158 d			
	HRS	8823	800		9623		630.9			
WC#: 54.0101	AFL	5651								
					PROC. REF: AMM 54-00-00-210-810					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-00-00-210-810-04C	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (CPCP)									Service ATA:54
	MOS	07-Sep-22	19		07-Apr-24		158 d	CPCP		
	HRS	8823	800		9623		630.9			
WC#: 54.055	AFL	5651								
					PROC. REF: AMM 54-00-00-210-810					
54-00-00-210-811-02	GENERAL VISUAL INSPECTION OF THE ENGINE 2 NACELLE									Service ATA:54
	MOS	07-Sep-22	19		07-Apr-24		158 d			
	HRS	8823	800		9623		630.9			
WC#: 54.0201	AFL	5651								
					PROC. REF: AMM 54-00-00-210-811					
54-00-00-210-811-02C	GENERAL VISUAL INSPECTION OF THE ENGINE 2 NACELLE (CPCP)									Service ATA:54
	MOS	07-Sep-22	19		07-Apr-24		158 d	CPCP		
	HRS	8823	800		9623		630.9			
WC#: 54.065	AFL	5651								
					PROC. REF: AMM 54-00-00-210-811					
54-00-00-220-802-01[S]	DETAILED INSPECTION OF THE ENGINE 2 NACELLE									Service ATA:54
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 54.0202	AFL	5347								
					PROC. REF: AMM 54-00-00-220-802					PKG:32
54-00-00-220-802-01C	DETAILED INSPECTION OF THE ENGINE 2 NACELLE (CPCP)									Service ATA:54
	MOS	07-Mar-16	148		07-Jul-28		1710 d	CPCP		
	HRS	8278.1								
WC#: 54.095	AFL	5347								
					PROC. REF: AMM 54-00-00-220-802					
54-10-01-960-801-01	REPLACEMENT OF THE PADS AND SEALS OF THE ENGINE FAN INTERNAL COWLINGS									Service ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-10-01-960-801					
54-10-05-900-801-01	REMOVAL / INSTALLATION OF THE EXHAUST NOZZLE ATTACHING CLAMPS									Component ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-10-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-10-13-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE AFTERBODY AND CORE COWL ASSEMBLY ACCESS PANELS								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-10-13-900-801					
54-11-00-210-801-01	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 COWLINGS - ENGINE 1 COWLINGS								Service	ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-11-00-210-801					
54-11-00-210-801-02	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 COWLINGS - ENGINE 3 COWLINGS								Service	ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-11-00-210-801					
54-11-00-610-801-01 S	SERVICING OF THE ENGINE COWLINGS - ENGINE 1 COWLINGS								Service	ATA:54
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 54.030	AFL	5775								
					PROC. REF: AMM 54-11-00-610-801					PKG:16 ,15
54-11-00-610-801-02 S	SERVICING OF THE ENGINE COWLINGS - ENGINE 2 COWLINGS								Service	ATA:54
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 54.030	AFL	5775								
					PROC. REF: AMM 54-11-00-610-801					PKG:16 ,15
54-11-00-610-801-03 S	SERVICING OF THE ENGINE COWLINGS - ENGINE 3 COWLINGS								Service	ATA:54
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 54.030	AFL	5775								
					PROC. REF: AMM 54-11-00-610-801					PKG:16 ,15
54-11-00-860-801-01	OPENING / CLOSING OF THE ENGINE 1 AND 3 COWLINGS - ENGINE 1								Service	ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-11-00-860-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-11-00-860-801-02	OPENING / CLOSING OF THE ENGINE 1 AND 3 COWLINGS - ENGINE 3								Service	ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-11-00-860-801					
54-11-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 UPPER COWLINGS - ENGINE 1 UPPER COWLING (414A)								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-01-900-801					
54-11-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 UPPER COWLINGS - ENGINE 3 UPPER COWLING (424A)								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-01-900-801					
54-11-01-900-802-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 UPPER AND LOWER COWLINGS - ENGINE 1 LOWER COWLING								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-01-900-802					
54-11-01-900-802-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 UPPER AND LOWER COWLINGS - ENGINE 3 LOWER COWLING								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-01-900-802					
54-11-01-900-802-03	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 UPPER AND LOWER COWLINGS - ENGINE 1 UPPER COWLING								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-01-900-802					
54-11-01-900-802-04	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 UPPER AND LOWER COWLINGS - ENGINE 3 UPPER COWLING								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-01-900-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-11-05-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 LOWER COWLINGS - ENGINE 1 LOWER COWLING (413A)								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-05-900-801					
54-11-05-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 LOWER COWLINGS - ENGINE 3 LOWER COWLING (423A)								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-05-900-801					
54-11-09-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 2 COWLINGS - LH ENGINE 2 COWLING								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-09-900-801					
54-11-09-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 2 COWLINGS - RH ENGINE 2 COWLING								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-09-900-801					
54-11-10-900-801-01	REMOVAL / INSTALLATION OF THE HOLD OPEN RODS OF THE ENGINE 1 AND 3 LOWER COWLINGS - ENGINE 1 LOWER COWLING (413A)								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-10-900-801					
54-11-10-900-801-02	REMOVAL / INSTALLATION OF THE HOLD OPEN RODS OF THE ENGINE 1 AND 3 LOWER COWLINGS - ENGINE 3 LOWER COWLING (423A)								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-11-10-900-801					
54-11-11-820-801-01	ADJUSTMENT OF THE ENGINE 1 AND 3 COWLING LATCHES - ENGINE 1								Service	ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-11-11-820-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-11-11-820-801-02	ADJUSTMENT OF THE ENGINE 1 AND 3 COWLING LATCHES - ENGINE 3									Service ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-11-11-820-801					
54-11-13-960-801-01	REPLACEMENT OF THE ENGINE 1 AND 3 COWLING SEALS - ENGINE 1									Service ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-11-13-960-801					
54-11-13-960-801-02	REPLACEMENT OF THE ENGINE 1 AND 3 COWLING SEALS - ENGINE 3									Service ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-11-13-960-801					
54-13-01-210-801-01	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 AFTERBODIES									Service ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-13-01-210-801					
54-13-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 AFTERBODIES - ENGINE 1 AFTERBODY									Component ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-13-01-900-801, AMM 54-13-01-900-801					
54-13-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 AFTERBODIES - ENGINE 3 AFTERBODY									Component ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-13-01-900-801, AMM 54-13-01-900-801					
54-14-00-210-801-01	GENERAL VISUAL INSPECTION OF THE ENGINE CORE COWL ASSEMBLIES - ENGINE 1									Service ATA:54
	MOS	07-Sep-22								
	HRS	8823	300		9123		130.9			
	AFL	5651								
					PROC. REF: AMM 54-14-00-210-801, AMM 54-14-00-210-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-14-00-210-801-02	GENERAL VISUAL INSPECTION OF THE ENGINE CORE COWL ASSEMBLIES - ENGINE 2									Service ATA:54
	MOS	07-Sep-22								
	HRS	8823	300		9123		130.9			
	AFL	5651								
					PROC. REF: AMM 54-14-00-210-801, AMM 54-14-00-210-801					
54-14-00-210-801-03	GENERAL VISUAL INSPECTION OF THE ENGINE CORE COWL ASSEMBLIES - ENGINE 3									Service ATA:54
	MOS	07-Sep-22								
	HRS	8823	300		9123		130.9			
	AFL	5651								
					PROC. REF: AMM 54-14-00-210-801, AMM 54-14-00-210-801					
54-14-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 CORE COWL ASSEMBLIES - ENGINE 1									Component ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-14-01-900-801					
54-14-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 CORE COWL ASSEMBLIES - ENGINE 3									Component ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-14-01-900-801					
54-14-05-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 2 CORE COWL ASSEMBLY - ENGINE 2									Component ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-14-05-900-801					
54-14-09-210-801-01	GENERAL VISUAL INSPECTION OF THE ENGINE EXHAUST DUCTS - ENGINE 1									Service ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-14-09-210-801					
54-14-09-210-801-02	GENERAL VISUAL INSPECTION OF THE ENGINE EXHAUST DUCTS - ENGINE 2									Service ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-14-09-210-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-14-09-210-801-03	GENERAL VISUAL INSPECTION OF THE ENGINE EXHAUST DUCTS - ENGINE 3								Service	ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-14-09-210-801					
54-14-09-220-801-01	DETAILED INSPECTION OF THE ENGINE EXHAUST DUCTS - ENGINE 1 (L4EZ)								Service	ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-14-09-220-801					
54-14-09-220-801-02	DETAILED INSPECTION OF THE ENGINE EXHAUST DUCTS - ENGINE 2 (M4EZ)								Service	ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-14-09-220-801					
54-14-09-220-801-03	DETAILED INSPECTION OF THE ENGINE EXHAUST DUCTS - ENGINE 3 (R4EZ)								Service	ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-14-09-220-801					
54-14-09-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE EXHAUST DUCTS - ENGINE 1								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-14-09-900-801					
54-14-09-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE EXHAUST DUCTS - ENGINE 2								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-14-09-900-801					
54-14-09-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE EXHAUST DUCTS - ENGINE 3								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-14-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-41-01-210-801-01	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 AIR INTAKES - AIR INTAKE COWL - INSPECTION/CHECK								Service	ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-41-01-210-801					
54-41-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 AIR INTAKES - ENGINE 1 AIR INTAKE								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-41-01-900-801, AMM 54-41-01-900-801					
54-41-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 AIR INTAKES - ENGINE 3 AIR INTAKE								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-41-01-900-801, AMM 54-41-01-900-801					
54-42-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 2 AIR INTAKE								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-42-01-900-801					
54-42-05-900-801-01	REMOVAL / INSTALLATION OF THE S-DUCT SECTION S1-S2								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-42-05-900-801					
54-42-09-900-801-01	REMOVAL / INSTALLATION OF THE S-DUCT SECTION S3-S5								Component	ATA:54
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 54-42-09-900-801					
54-42-17-200-801-01	CHECK FOR NON-LOOSENING OF SCREWS OF S-DUCT SECTIONS 2 AND 3 COUPLING FLANGES								Service	ATA:54
	MOS	09-Mar-18								
	HRS	8497.6	600 (+30)		9097.6	9127.6	105.5 (+30)			
WC#: 54.070	AFL	5470								
					PROC. REF: AMM 54-42-17-200-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
54-42-17-420-801-01	METHOD FOR TIGHTENING SCREWS OF S-DUCT SECTIONS 2 AND 3 COUPLING FLANGES									Service ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-42-17-420-801					
54-50-00-220-802-01	DETAILED INSPECTION OF PYLON UPPER FLANGE RIBS AT FRAME 32									Service ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-50-00-220-802					
54-50-00-220-802-01A	DETAILED INSPECTION OF PYLON UPPER FLANGE RIBS AT FRAME 32 (MANDATORY 5-40)									Service ATA:54
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 53.222	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 54-50-00-220-802					
54-50-00-820-801-01	REPOSITIONING OF HYDRAULIC LINES IN THE AREA OF ENGINE PYLONS									Service ATA:54
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 54-50-00-820-801					
540171	NO. 1 ENGINE REAR ATTACH FITTING									Component ATA:54
PN:F50B581106400	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0								
WC#: 54.040	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
540173	NO. 1 ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT									Component ATA:54
PN:PN	MOS/MSC	24-Oct-91	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 54.040	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
540176	NO. 1 ENGINE MAIN ATTACH FITTING									Component ATA:54
PN:F10A5B10555	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0								
WC#: 54.040	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
540181		NO. 2 ENGINE REAR ATTACH FITTING								Component ATA:54
PN:F50B25520	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0								
WC#: 54.050	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
540186		NO. 2 ENGINE REAR ATTACH LINK								Component ATA:54
PN:F50B255520110	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0								
WC#: 54.050	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
540191		NO. 3 ENGINE REAR ATTACH FITTING								Component ATA:54
PN:F50B581106400	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0								
WC#: 54.060	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
540193		NO. 3 ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT								Component ATA:54
PN:PN	MOS/MSC	24-Oct-91	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 54.060	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
540196		NO. 3 ENGINE MAIN ATTACH FITTING								Component ATA:54
PN:F10A5B10555	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0								
WC#: 54.060	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
545806[U]		AIR INTAKE,ENGINE NO.3								Component ATA:54
PN:F50B581301B3	MOS/MSC	21-Aug-00	O/C							
SN:241-AT-224	HRS	3957								
	AFL	2523								
R 54-14-01		REPAIR OF CORROSION ON ENGINE CORE COWL								Service ATA:54
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 54-14-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
R 54-14-04		REPAIR OF CRACKS ON CORE COWLS								Service ATA:54
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 54-14-04					
R 54-41-02		LATERAL ENGINE AIR INTAKES - REPLACEMENT OF RIVETS ON THE INNER PART OF THE LIP AND ON THE INNER SKIN								Service ATA:54
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 54-41-02					
R 54-41-03		LATERAL ENGINE AIR INTAKES - REPLACEMENT OF RIVETS SECURING THE LIP								Service ATA:54
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 54-41-03					
R 54-42-05		REPLACEMENT OF THE S-DUCT SECTION S1-S2								Service ATA:54
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 54-42-05					
R 54-42-09		REPLACEMENT OF THE S-DUCT SECTION S3-S5								Service ATA:54
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 54-42-09					
R 54-42-11		REPLACEMENT OF THE ENGINE 2 AIR INTAKE								Service ATA:54
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 54-42-11					
ATA 55 - STABILIZERS										
55-00-00-210-801-01[S]		GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT								Service ATA:55
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 55.0101	AFL	5775								
					PROC. REF: AMM 55-00-00-210-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)									Service ATA:55
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 55.025	AFL	5775								
					PROC. REF: AMM 55-00-00-210-801					
55-00-00-220-801-01[S]	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT									Service ATA:55
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 55.0102	AFL	5651								
					PROC. REF: AMM 55-00-00-220-801					PKG:31
55-00-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)									Service ATA:55
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 55.035	AFL	5651								
					PROC. REF: AMM 55-00-00-220-801					
55-00-00-250-801-01	EDDY-CURRENT INSPECTION OF HORIZONTAL AND VERTICAL STABILIZERS ATTACHMENT FITTINGS									Service ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-00-00-250-801					
55-00-00-270-801-01[S]	ULTRASONIC INSPECTION FOR STRESS CORROSION IN STABILIZER HINGES									Service ATA:55
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 55.070	AFL	5651								
					PROC. REF: AMM 55-00-00-270-801					PKG:31
55-00-00-270-801-01A	ULTRASONIC INSPECTION FOR STRESS CORROSION IN STABILIZER HINGES (MANDATORY 5-40)									Service ATA:55
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 55-00-00-270-801					
55-00-00-270-801-01C	ULTRASONIC INSPECTION FOR STRESS CORROSION IN STABILIZER HINGES (CPCP)									Service ATA:55
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 55.060	AFL	5651								
					PROC. REF: AMM 55-00-00-270-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-00-00-760-801-01[S]	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RUDDER									Service ATA:55
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 55.080	AFL	5775								
					PROC. REF: AMM 55-00-00-760-801					PKG:16 ,15
55-00-00-760-801-02[S]	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - LH ELEVATOR									Service ATA:55
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 55.080	AFL	5775								
					PROC. REF: AMM 55-00-00-760-801					PKG:16 ,15
55-00-00-760-801-03[S]	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RH ELEVATOR									Service ATA:55
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 55.080	AFL	5775								
					PROC. REF: AMM 55-00-00-760-801					PKG:16 ,15
55-00-01-400-801-01	INSTALLATION OF ANTI-EROSION STRIPS ON STABILIZER LEADING EDGES									Service ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-00-01-400-801					
55-10-00-220-801-01[S]	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE - DETAILED INSPECTION OF THE HS INTERNAL BOX STRUCTURE									Service ATA:55
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
	AFL	5347								
					PROC. REF: AMM 55-10-00-220-801					PKG:32
55-10-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE - DETAILED INSPECTION OF THE HS INTERNAL BOX STRUCTURE (CPCP)									Service ATA:55
	MOS	07-Mar-16	148		07-Jul-28		1710 d	CPCP		
	HRS	8278.1								
	AFL	5347								
					PROC. REF: AMM 55-10-00-220-801					
55-10-00-220-802-01[S]	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS									Service ATA:55
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
	AFL	5347								
					PROC. REF: AMM 55-10-00-220-802					PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-10-00-220-802-01C	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS (CPCP)								Service	ATA:55
	MOS	07-Mar-16	148		07-Jul-28		1710 d	CPCP		
	HRS	8278.1								
	AFL	5347								
					PROC. REF: AMM 55-10-00-220-802					
55-10-00-220-803-01	DETAILED INSPECTION OF HORIZONTAL STABILIZER UPPER PANELS BETWEEN ROOT AND RIB 2								Service	ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-10-00-220-803					
55-10-00-220-803-01A	DETAILED INSPECTION OF HORIZONTAL STABILIZER UPPER PANELS BETWEEN ROOT AND RIB2 (MANDATORY 5-40)								Service	ATA:55
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 55.045	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 55-10-00-220-803					
55-10-00-640-803-01 S	GREASING OF THE HORIZONTAL STABILIZER FRONT TORQUE LINK, ACTUATOR UPPER HINGE, AND ELEVATOR U-JOINTS - LINKAGE U-JOINTS AND ELEVATOR BEARINGS								Service	ATA:55
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 27.380	AFL	5775								
					PROC. REF: AMM 55-10-00-640-803					PKG:16 ,15
55-10-00-640-803-02 S	GREASING OF THE HORIZONTAL STABILIZER FRONT TORQUE LINK, ACTUATOR UPPER HINGE, AND ELEVATOR U-JOINTS - HORIZONTAL STABILIZER FRONT HINGE POINTS								Service	ATA:55
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 27.440	AFL	5775								
					PROC. REF: AMM 55-10-00-640-803					PKG:16 ,15
55-10-01-900-801-01	REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER								Component	ATA:55
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 55-10-01-900-801					
55-10-03-640-801-01 S	LUBRICATION OF THE SPRING-LOADED FAIRING MECHANISM								Service	ATA:55
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 27.440	AFL	5775								
					PROC. REF: AMM 55-10-03-640-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-10-03-820-801-01	ADJUSTMENT OF THE SPRING-LOADED FAIRINGS - LH SPRING LOADED FAIRINGS								Service	ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-10-03-820-801					
55-10-03-820-801-02	ADJUSTMENT OF THE SPRING-LOADED FAIRINGS - RH SPRING LOADED FAIRINGS								Service	ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-10-03-820-801					
55-10-03-900-801-01	REMOVAL / INSTALLATION OF THE SPRING-LOADED FAIRINGS - LH SPRING LOADED FAIRINGS								Component	ATA:55
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 55-10-03-900-801					
55-10-03-900-801-02	REMOVAL / INSTALLATION OF THE SPRING-LOADED FAIRINGS - RH SPRING LOADED FAIRINGS								Component	ATA:55
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 55-10-03-900-801					
55-10-05-960-802-01	REPLACEMENT OF THE SPRING-LOADED FAIRING FRICTION STRIPS								Service	ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-10-05-960-802					
55-10-29-900-801-01	REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER TORQUE LINK								Component	ATA:55
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 55-10-29-900-801					
55-10-31-220-801-01[S]	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS								Service	ATA:55
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 55.040	AFL	5651								
					PROC. REF: AMM 55-10-31-220-801					PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-10-31-220-801-01A	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS (MANDATORY 5-40)									Service ATA:55
	MOS	07-Sep-22						MANDATORY 5-40		
	HRS	8823								
WC#: 55.040	AFL	5651	3750		9401		3605			
					PROC. REF: AMM 55-10-31-220-801					
55-10-33-640-801-01	LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS									Service ATA:55
	MOS	08-Sep-23	12 (+1m)	Adj -1d	07-Sep-24	07-Oct-24	311 d (+30)			
	HRS	8967	600 (+30)		9567	9597	574.9 (+30)			
WC#: 27.430	AFL	5775								
					PROC. REF: AMM 55-10-33-640-801					
55-10-39-220-801-01	DETAILED INSPECTION OF HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS									Service ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-10-39-220-801					
55-10-39-220-801-01A	DETAILED INSPECTION OF HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS (MANDATORY 5-40)									Service ATA:55
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 55.065	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 55-10-39-220-801					
55-20-00-220-801-01	DETAILED INSPECTION OF THE ELEVATORS SKIN AND HINGE FITTINGS									Service ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-20-00-220-801					
55-20-00-220-801-01A	DETAILED INSPECTION OF THE ELEVATORS SKIN AND HINGE FITTINGS (MANDATORY 5-40)									Service ATA:55
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 55.050	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 55-20-00-220-801					
55-20-01-900-801-01	REMOVAL / INSTALLATION OF THE ELEVATORS - LH ELEVATOR									Component ATA:55
PN:FGFB341A1	MOS/MSC	05-May-98	O/C							
SN:1BZ/RECH	HRS	2753								
WC#: 55.020	AFL	1927								
					PROC. REF: AMM 55-20-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-20-01-900-801-02	REMOVAL / INSTALLATION OF THE ELEVATORS - RH ELEVATOR								Component	ATA:55
PN:FGFB342A1	MOS/MSC	24-Oct-91	O/C							
SN:HD164343	HRS	0		TSN 0						
WC#: 55.020	AFL	0								
					PROC. REF: AMM 55-20-01-900-801					
55-20-03-640-801-01[S]	LUBRICATION OF THE ELEVATOR BEARINGS - LH ELEVATOR								Service	ATA:55
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 55.020	AFL	5347								
					PROC. REF: AMM 55-20-03-640-801					PKG:32
55-20-03-640-801-02[S]	LUBRICATION OF THE ELEVATOR BEARINGS - RH ELEVATOR								Service	ATA:55
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 55.020	AFL	5347								
					PROC. REF: AMM 55-20-03-640-801					PKG:32
55-20-03-640-802-01[S]	LUBRICATION OF THE ELEVATOR CONTROL SURFACE HINGES								Service	ATA:55
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 27.370	AFL	5775								
					PROC. REF: AMM 55-20-03-640-802					PKG:15
55-20-03-820-801-01	ADJUSTMENT OF THE ELEVATOR BEARING 1								Service	ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-20-03-820-801					
55-20-05-220-801-01	DETAILED INSPECTION OF THE ELEVATOR UNIVERSAL JOINT TUBE INTERNAL PROTECTION								Service	ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-20-05-220-801					
55-20-05-220-801-02	DETAILED INSPECTION OF THE ELEVATOR UNIVERSAL JOINT TUBE INTERNAL PROTECTION								Service	ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-20-05-220-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-20-05-960-801-01	REPLACEMENT OF THE ELEVATOR INBOARD BEARING ROLLER BEARINGS									Service ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-20-05-960-801					
55-30-01-900-801-01	REMOVAL / INSTALLATION OF THE VERTICAL STABILIZER									Component ATA:55
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 55-30-01-900-801					
55-30-05-960-801-01	REPLACEMENT OF THE FIN TIP FAIRING LIGHTNING-ARRESTER STRIP									Service ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-30-05-960-801					
55-30-07-900-801-01	REMOVAL / INSTALLATION OF THE FIN TIP FAIRING									Component ATA:55
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 55-30-07-900-801					
55-30-70-900-801-01	FIN TIP FAIRING									Component ATA:55
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 55-30-07-900-801					
55-40-00-220-801-01	DETAILED INSPECTION OF THE RUDDER SKIN AND HINGE FITTINGS									Service ATA:55
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 55-40-00-220-801					
55-40-00-220-801-01A	DETAILED INSPECTION OF THE RUDDER SKIN AND HINGE FITTINGS (MANDATORY 5-40)									Service ATA:55
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 55.055	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 55-40-00-220-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
55-40-01-900-801-01		REMOVAL / INSTALLATION OF THE RUDDER								Component ATA:55
PN:F50B321	MOS/MSC	24-Oct-91	O/C							
SN:57RA224	HRS	0		TSN 0						
WC#: 55.030	AFL	0								
					PROC. REF: AMM 55-40-01-900-801					
55-40-05-640-801-01[S]		LUBRICATION OF THE RUDDER BEARINGS								Service ATA:55
	MOS	07-Mar-16	144 (+2m)							
	HRS	8278.1								
WC#: 55.030	AFL	5347								
					PROC. REF: AMM 55-40-05-640-801					PKG:32
55-40-05-640-802-01[S]		LUBRICATION OF THE RUDDER CONTROL SURFACE HINGES								Service ATA:55
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 27.280	AFL	5775								
					PROC. REF: AMM 55-40-05-640-802					PKG:15
A 55-10-01		HORIZONTAL STABILIZER LEADING EDGE - DAMAGE DATA								Service ATA:55
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 55-10-01					
A 55-20-02		MACHINED ELEVATOR SKINS - DAMAGE DATA								Service ATA:55
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 55-20-02					
R 55-10-05		REPAIR OF COMPOSITE HORIZONTAL STABILIZER								Service ATA:55
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 55-10-05					
R 55-10-09		REPLACEMENT OF HORIZONTAL STABILIZER TRAILING EDGE								Service ATA:55
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 55-10-09					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
R 55-20-01	REPAIR OF SHEET-METAL ELEVATOR TRAILING EDGES									Service ATA:55
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 55-20-01					
R 55-40-02	REPAIR OF CRACKS ON RUDDER									Service ATA:55
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 55-40-02					
ATA 56 - WINDOWS										
56-00-00-100-801-01	CLEANING OF WINDSHIELD, WINDOWS AND TRANSPARENT FAIRINGS - COCKPIT WINDSHIELDS/WINDOWS									Service ATA:56
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 56-00-00-100-801					
56-00-00-100-801-02	CLEANING OF WINDSHIELD, WINDOWS AND TRANSPARENT FAIRINGS - CABIN WINDOWS									Service ATA:56
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 56-00-00-100-801					
56-00-00-100-801-03	CLEANING OF WINDSHIELD, WINDOWS AND TRANSPARENT FAIRINGS - TRANSPARENT FAIRINGS									Service ATA:56
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 56-00-00-100-801					
56-00-00-350-801-01	SMOOTHING OF SCRATCHES ON WINDSHIELDS, WINDOWS AND TRANSPARENT FAIRINGS									Service ATA:56
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 56-00-00-350-801					
56-00-00-910-801-01	ACCEPTANCE CRITERIA FOR DAMAGE TO WINDSHIELDS, WINDOWS AND TRANSPARENT FAIRINGS									Service ATA:56
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 56-00-00-910-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
56-10-01-900-801-01	REMOVAL / INSTALLATION OF THE WINDSHIELDS - PILOT WINDSHIELD (126H1)								Component	ATA:56
PN:MY20267-10-8	MOS/MSC	24-Oct-91	O/C							
SN:2509	HRS	0		TSN 0						
WC#: 56.010	AFL	0								
					PROC. REF: AMM 56-10-01-900-801					
56-10-01-900-801-02	REMOVAL / INSTALLATION OF THE WINDSHIELDS - COPILOT WINDSHIELD (126H2)								Component	ATA:56
PN:MY20.268.10.9	MOS/MSC	26-Sep-06	O/C	TSR 0						
SN:1012	HRS	5992.2		TSR 0						
WC#: 56.010	AFL	3650		TSR 0						
					PROC. REF: AMM 56-10-01-900-801					
56-10-01-900-801-03	REMOVAL / INSTALLATION OF THE WINDSHIELDS - FRONT WINDSHIELD (127H)								Component	ATA:56
PN:MY20261-10-8	MOS/MSC	24-Oct-91	O/C							
SN:2600	HRS	0		TSN 0						
WC#: 56.010	AFL	0								
					PROC. REF: AMM 56-10-01-900-801					
56-10-07-900-801-01	REMOVAL / INSTALLATION OF THE RH LATERAL WINDOW - RH LATERAL WINDOW (145H2)								Component	ATA:56
PN:MY20263-10-5	MOS/MSC	24-Oct-91	O/C							
SN:3021	HRS	0		TSN 0						
WC#: 56.020	AFL	0								
					PROC. REF: AMM 56-10-07-900-801, AMM 56-10-07-900-801					
56-10-09-350-801-01	REPAIR OF WATER TIGHTNESS OF THE OPENING WINDOW								Service	ATA:56
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 56-10-09-350-801					
56-10-09-640-801-01[S]	LUBRICATION OF THE OPENING WINDOW MECHANISM - LH SLIDING WINDOW (145H1)								Service	ATA:56
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 56.040	AFL	5775								
					PROC. REF: AMM 56-10-09-640-801					PKG:16 ,15
56-10-09-820-801-01	ADJUSTMENT OF THE OPENING WINDOW ELECTRIC CONNECTOR								Service	ATA:56
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 56-10-09-820-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
56-10-09-900-801-01	REMOVAL / INSTALLATION OF THE OPENING WINDOW									Component ATA:56
PN:MY20264-10-4	MOS/MSC	24-Oct-91	O/C							
SN:3153	HRS	0		TSN 0						
WC#: 56.040	AFL	0								
					PROC. REF: AMM 56-10-09-900-801					
56-10-11-900-801-01	REMOVAL / INSTALLATION OF THE REAR WINDOWS - LH REAR WINDOW (146H1)									Component ATA:56
PN:F50B265001001 B3	MOS/MSC	24-Oct-91	O/C							
SN:527	HRS	0		TSN 0						
WC#: 56.030	AFL	0								
					PROC. REF: AMM 56-10-11-900-801, AMM 56-10-11-900-801					
56-10-11-900-801-02	REMOVAL / INSTALLATION OF THE REAR WINDOWS - RH REAR WINDOW (146H2)									Component ATA:56
PN:F50B266001001 B5	MOS/MSC	19-Nov-05	O/C	TSN 0						
SN:1332	HRS	5703		TSN 0						
WC#: 56.030	AFL	3491		TSN 0						
					PROC. REF: AMM 56-10-11-900-801, AMM 56-10-11-900-801					
56-20-00-350-801-01	DRYING OFF OF THE AIR GAP BETWEEN THE TWO PANELS OF CABIN WINDOWS									Service ATA:56
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 56-20-00-350-801					
56-20-05-900-801-01	NO. 1 LEFT PASSENGER CABIN WINDOW									Component ATA:56
PN:F50B228100A3	MOS/MSC	24-Oct-91	O/C							
SN:4849	HRS	0		TSN 0						
WC#: 56.060	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					
56-20-05-900-801-01	NO. 1 RIGHT PASSENGER CABIN WINDOW									Component ATA:56
PN:F50B228100A3	MOS/MSC	24-Oct-91	O/C							
SN:4856	HRS	0		TSN 0						
WC#: 56.060	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					
56-20-05-900-801-01	NO. 2 LEFT PASSENGER CABIN WINDOW									Component ATA:56
PN:F50B228100A3	MOS/MSC	24-Oct-91	O/C							
SN:4850	HRS	0		TSN 0						
WC#: 56.070	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
56-20-05-900-801-01	NO. 2 RIGHT PASSENGER CABIN WINDOW									Component ATA:56
PN:F50B228100A3	MOS/MSC	24-Oct-91	O/C							
SN:4857	HRS	0		TSN 0						
WC#: 56.070	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					
56-20-05-900-801-01	NO. 3 LEFT PASSENGER CABIN WINDOW									Component ATA:56
PN:F50B228100A3	MOS/MSC	09-Apr-92	O/C							
SN:4534	HRS	26		TSN 0						
WC#: 56.080	AFL	13								
					PROC. REF: AMM 56-20-05-900-801					
56-20-05-900-801-01	NO. 3 RIGHT PASSENGER CABIN WINDOW									Component ATA:56
PN:F50B228100A3	MOS/MSC	24-Oct-91	O/C							
SN:4858	HRS	0		TSN 0						
WC#: 56.080	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					
56-20-05-900-801-01	NO. 4 LEFT PASSENGER CABIN WINDOW									Component ATA:56
PN:F50B228100A3	MOS/MSC	24-Oct-91	O/C							
SN:4854	HRS	0		TSN 0						
WC#: 56.090	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					
56-20-05-900-801-01	NO. 4 RIGHT PASSENGER CABIN WINDOW									Component ATA:56
PN:F50B228100A3	MOS/MSC	24-Oct-91	O/C							
SN:4859	HRS	0		TSN 0						
WC#: 56.090	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					
56-20-05-900-801-01	NO. 5 LEFT PASSENGER CABIN WINDOW									Component ATA:56
PN:F50B228100A3	MOS/MSC	24-Oct-91	O/C							
SN:4853	HRS	0		TSN 0						
WC#: 56.100	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					
56-20-05-900-801-01	NO. 5 RIGHT PASSENGER CABIN WINDOW									Component ATA:56
PN:F50B228100A3	MOS/MSC	24-Oct-91	O/C							
SN:4860	HRS	0		TSN 0						
WC#: 56.100	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
56-20-05-900-801-01		NO. 6 LEFT PASSENGER CABIN WINDOW								Component ATA:56
PN:F50B228100A3	MOS/MSC	09-Apr-92	O/C							
SN:4525	HRS	26		TSN 0						
WC#: 56.110	AFL	13								
					PROC. REF: AMM 56-20-05-900-801					
56-20-05-900-801-01		NO. 6 RIGHT PASSENGER CABIN WINDOW								Component ATA:56
PN:F50B228100A3	MOS/MSC	24-Oct-91	O/C							
SN:4870	HRS	0		TSN 0						
WC#: 56.110	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					
56-20-05-900-801-01		NO. 7 LEFT PASSENGER CABIN WINDOW								Component ATA:56
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 56.120	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					
56-20-05-900-801-01		NO. 7 RIGHT PASSENGER CABIN WINDOW								Component ATA:56
PN:F50B228100A3	MOS/MSC	24-Oct-91	O/C							
SN:4873	HRS	0		TSN 0						
WC#: 56.120	AFL	0								
					PROC. REF: AMM 56-20-05-900-801					
561136		LH DEFOGGING VALVE								Component ATA:56
PN:L95-001	MOS/MSC	24-Oct-91	O/C							
SN:21289	HRS	0		TSN 0						
WC#: 56.050	AFL	0								
					PROC. REF: GENERIC NO REF					
561141		RH DEFOGGING VALVE								Component ATA:56
PN:L95-001	MOS/MSC	24-Oct-91	O/C							
SN:21295	HRS	0		TSN 0						
WC#: 56.050	AFL	0								
					PROC. REF: GENERIC NO REF					
ATA 57 - WINGS										
57-00-00-210-801-03[S]		GENERAL VISUAL INSPECTION OF THE WINGS - LH WING								Service ATA:57
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 57.0101	AFL	5775								
					PROC. REF: AMM 57-00-00-210-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-00-00-210-801-03C	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING (CPCP)									Service ATA:57
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 57.035	AFL	5775								
					PROC. REF: AMM 57-00-00-210-801					
57-00-00-210-801-04[S]	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING									Service ATA:57
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 57.0101	AFL	5775								
					PROC. REF: AMM 57-00-00-210-801					PKG:16 ,15
57-00-00-210-801-04C	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING (CPCP)									Service ATA:57
	MOS	08-Sep-23	25		08-Oct-25		707 d	CPCP		
	HRS	8967								
WC#: 57.035	AFL	5775								
					PROC. REF: AMM 57-00-00-210-801					
57-00-00-220-802-01[S]	DETAILED INSPECTION OF THE WINGS - LH WING									Service ATA:57
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.0102	AFL	5651								
					PROC. REF: AMM 57-00-00-220-802					PKG:31
57-00-00-220-802-01C	DETAILED INSPECTION OF THE WINGS - LH WING (CPCP)									Service ATA:57
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 57.045	AFL	5651								
					PROC. REF: AMM 57-00-00-220-802					
57-00-00-220-802-02[S]	DETAILED INSPECTION OF THE WINGS - RH WING									Service ATA:57
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.0102	AFL	5651								
					PROC. REF: AMM 57-00-00-220-802					PKG:31
57-00-00-220-802-02C	DETAILED INSPECTION OF THE WINGS - RH WING (CPCP)									Service ATA:57
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 57.045	AFL	5651								
					PROC. REF: AMM 57-00-00-220-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-00-00-760-801-01[S]	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH AILERON									Service ATA:57
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 57.240	AFL	5775								
					PROC. REF: AMM 57-00-00-760-801					PKG:16 ,15
57-00-00-760-801-02[S]	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH AILERON									Service ATA:57
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 57.240	AFL	5775								
					PROC. REF: AMM 57-00-00-760-801					PKG:16 ,15
57-00-00-760-801-03[S]	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH FLAPS									Service ATA:57
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 57.250	AFL	5775								
					PROC. REF: AMM 57-00-00-760-801					PKG:16 ,15
57-00-00-760-801-04[S]	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH FLAPS									Service ATA:57
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 57.250	AFL	5775								
					PROC. REF: AMM 57-00-00-760-801					PKG:16 ,15
57-00-00-760-801-05[S]	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH SLATS									Service ATA:57
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 57.260	AFL	5775								
					PROC. REF: AMM 57-00-00-760-801					PKG:16 ,15
57-00-00-760-801-06[S]	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH SLATS									Service ATA:57
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 57.260	AFL	5775								
					PROC. REF: AMM 57-00-00-760-801					PKG:16 ,15
57-00-00-760-801-07[S]	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH AIRBRAKES									Service ATA:57
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 57.270	AFL	5775								
					PROC. REF: AMM 57-00-00-760-801					PKG:16 ,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-00-00-760-801-08[S]	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH AIRBRAKES								Service	ATA:57
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 57.270	AFL	5775								
					PROC. REF: AMM 57-00-00-760-801					PKG:16 ,15
57-00-01-900-801-01	REMOVAL / INSTALLATION OF THE WINGS - LH WING								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-00-01-900-801					
57-00-01-900-801-02	REMOVAL / INSTALLATION OF THE WINGS - RH WING								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-00-01-900-801					
57-10-00-220-801-01	DETAILED INSPECTION OF THE MLG WHEEL WELL GAP SEALING BRUSHES - LH MLG BAY								Service	ATA:57
	MOS/MSC		O/C							
	HRS	0								
WC#: 57.150	AFL	0								
					PROC. REF: AMM 57-10-00-220-801					
57-10-00-220-801-02	DETAILED INSPECTION OF THE MLG WHEEL WELL GAP SEALING BRUSHES - RH MLG BAY								Service	ATA:57
	MOS/MSC		O/C							
	HRS	0								
WC#: 57.150	AFL	0								
					PROC. REF: AMM 57-10-00-220-801					
57-10-00-220-803-01	DIMENSIONAL CHECK OF MLG BALL-JOINT BEARING BORES								Service	ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-10-00-220-803					
57-10-00-290-801-01[S]	BORESCOPE INSPECTION OF THE WING TANKS								Service	ATA:57
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.030	AFL	5651								
					PROC. REF: AMM 57-10-00-290-801					PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-10-00-290-801-01A	BORESCOPE INSPECTION OF THE WING TANKS (MANDATORY 5-40)									Service ATA:57
	MOS	07-Sep-22	74		07-Nov-28		1833 d	MANDATORY 5-40		
	HRS	8823								
	AFL	5651								
					PROC. REF: AMM 57-10-00-290-801					
57-10-00-290-801-01C	BORESCOPE INSPECTION OF THE WING TANKS (CPCP)									Service ATA:57
	MOS	07-Sep-22	74		07-Nov-28		1833 d	CPCP		
	HRS	8823								
WC#: 57.057	AFL	5651								
					PROC. REF: AMM 57-10-00-290-801					
57-10-01-220-801-01	DETAILED INSPECTION OF LOWER WING PANELS									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-10-01-220-801					
57-10-01-220-801-01A	DETAILED INSPECTION OF LOWER WING PANELS (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 57.172	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 57-10-01-220-801					
57-10-01-270-801-01	ULTRASONIC INSPECTION OF THE WING LOWER SURFACE PANEL STIFFENERS BETWEEN RIBS 13 AND 17									Service ATA:57
	MOS	24-Oct-91								
	HRS	0								
WC#: 57.290	AFL	0	T:14200		14200		8404			
					PROC. REF: AMM 57-10-01-270-801					
57-10-01-270-801-01A	ULTRASONIC INSPECTION OF THE WING LOWER SURFACE PANEL STIFFENERS BETWEEN RIBS 13 AND 17 (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 57.295	AFL	0	T:14200		14200		8404			
					PROC. REF: AMM 57-10-01-270-801					
57-10-01-280-801-01[S]	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF LOWER WING PANELS AND MAPPING OF REWORKED AREAS									Service ATA:57
	MOS	07-Sep-22	144 (+2m)							
	HRS	8823								
WC#: 57.280	AFL	5651								
					PROC. REF: AMM 57-10-01-280-801					PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-10-01-280-801-01A	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF LOWER WING PANELS AND MAPPING OF REWORKED AREAS (MANDATORY 5-40)								Service	ATA:57
	MOS	07-Sep-22						MANDATORY 5-40		
	HRS	8823								
WC#: 57.165	AFL	5651	7500		13151		7355			
					PROC. REF: AMM 57-10-01-280-801					
57-10-01-280-801-01C	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF LOWER WING PANELS AND MAPPING OF REWORKED AREAS (CPCP)								Service	ATA:57
	MOS	07-Sep-22	151		07-Apr-35		4175 d	CPCP		
	HRS	8823								
WC#: 57.065	AFL	5651								
					PROC. REF: AMM 57-10-01-280-801					
57-10-01-900-801-01	REMOVAL / INSTALLATION OF THE WING STRUCTURAL FUEL TANK REMOVABLE PANELS - LH WING								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-10-01-900-801					
57-10-01-900-801-02	REMOVAL / INSTALLATION OF THE WING STRUCTURAL FUEL TANK REMOVABLE PANELS - RH WING								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-10-01-900-801					
57-10-11-900-801-01	REMOVAL / INSTALLATION OF THE WING TIP FAIRINGS - LH WING TIP FAIRING								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-10-11-900-801					
57-10-11-900-801-02	REMOVAL / INSTALLATION OF THE WING TIP FAIRINGS - RH WING TIP FAIRING								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-10-11-900-801					
57-10-14-200-801-01	INSPECTION OF WING FRONT SPAR FROM ROOT TO RIB 8 AND FROM RIB 9 TO RIB 17								Service	ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-10-14-200-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-10-14-200-801-01A	INSPECTION OF WING FRONT SPAR FROM ROOT TO RIB 8 AND FROM RIB 9 TO RIB 17 (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 57.175	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 57-10-14-200-801					
57-10-14-200-802-01	INSPECTION OF WING FRONT SPAR FROM RIB 8 TO RIB 9									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-10-14-200-802					
57-10-14-200-802-01A	INSPECTION OF WING FRONT SPAR FROM RIB 8 TO RIB 9 (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 57.182	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 57-10-14-200-802					
57-10-14-250-802-01A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR SPLICE AREA AT RIB7 - LH WING (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 57-10-14-250-802					
57-10-14-250-802-02A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR SPLICE AREA AT RIB7 - RH WING (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 57-10-14-250-802					
57-10-15-200-801-01	INSPECTION OF WING REAR SPAR 1 FROM ROOT TO RIB 3									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-10-15-200-801					
57-10-15-200-801-01A	INSPECTION OF WING REAR SPAR 1 FROM ROOT TO RIB 3 (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 57.192	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 57-10-15-200-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-10-15-200-802-01	INSPECTION OF WING REAR SPAR 2 FROM RIB 3 TO RIB 17									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-10-15-200-802					
57-10-15-200-802-01A	INSPECTION OF WING REAR SPAR 2 FROM RIB 3 TO RIB 17 (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 57.185	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 57-10-15-200-802					
57-10-15-250-801-01	EDDY-CURRENT INSPECTION OF WING REAR SPAR RIB 8 SPLICE									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-10-15-250-801					
57-10-15-250-801-01A	EDDY CURRENT INSPECTION OF WING REAR SPAR RIB 8 SPLICE (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 57.195	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 57-10-15-250-801					
57-10-19-900-801-01	REMOVAL / INSTALLATION OF THE FRONT WING HOISTING POINT FILLING PLUGS									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-10-19-900-801					
57-41-05-900-801-01	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCT CLOSING MECHANISMS - LH OUTBOARD SLAT TELESCOPIC DUCT (L537H2) CLOSING MECHANISM									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-41-05-900-801					
57-41-05-900-801-02	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCT CLOSING MECHANISMS - RH OUTBOARD SLAT TELESCOPIC DUCT (R537H2) CLOSING MECHANISM									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-41-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-41-13-640-801-01[S]	LUBRICATION OF THE SLAT ROLLERS									Service ATA:57
	MOS	08-Sep-23	24 (+1m)							
	HRS	8967								
WC#: 27.910	AFL	5775								
					PROC. REF: GENERIC NO REF					PKG:16 ,15
57-45-01-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD SLATS - LH INBOARD SLAT									Component ATA:57
PN:F50B133B2	MOS/MSC	24-Oct-91	O/C							
SN:360RA	HRS	0		TSN 0						
WC#: 57.110	AFL	0								
					PROC. REF: AMM 57-45-01-900-801					
57-45-01-900-801-02	REMOVAL / INSTALLATION OF THE INBOARD SLATS - RH INBOARD SLAT									Component ATA:57
PN:F50B143B2	MOS/MSC	24-Oct-91	O/C							
SN:358RA	HRS	0		TSN 0						
WC#: 57.110	AFL	0								
					PROC. REF: AMM 57-45-01-900-801					
57-45-01-960-801-01	REPLACEMENT OF THE INBOARD SLATS - LH INBOARD SLAT									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-45-01-960-801					
57-45-01-960-801-02	REPLACEMENT OF THE INBOARD SLATS - RH INBOARD SLAT									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-45-01-960-801					
57-45-13-900-801-01	REMOVAL / INSTALLATION OF THE OUTBOARD SLATS - LH OUTBOARD SLAT									Component ATA:57
PN:F50B134B2	MOS/MSC	30-Nov-98	O/C							
SN:UNKNOWN	HRS	2995								
WC#: 57.120	AFL	2071								
					PROC. REF: AMM 57-45-13-900-801					
57-45-13-900-801-02	REMOVAL / INSTALLATION OF THE OUTBOARD SLATS - RH OUTBOARD SLAT									Component ATA:57
PN:F50B144B2	MOS/MSC	01-Nov-02	O/C	TSR 0						
SN:5	HRS	4538.7		TSR 0						
WC#: 57.120	AFL	2880		TSR 0						
					PROC. REF: AMM 57-45-13-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-45-13-960-801-01	REPLACEMENT OF THE OUTBOARD SLATS - LH OUTBOARD SLAT								Service	ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-45-13-960-801					
57-45-13-960-801-02	REPLACEMENT OF THE OUTBOARD SLATS - RH OUTBOARD SLAT								Service	ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-45-13-960-801					
57-45-21-900-801-01	REMOVAL / INSTALLATION OF THE SLAT ANTI-VIBRATION SYSTEM - LH SIDE								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-45-21-900-801					
57-45-21-900-801-02	REMOVAL / INSTALLATION OF THE SLAT ANTI-VIBRATION SYSTEM - RH SIDE								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-45-21-900-801					
57-45-21-910-801-01	WEAR ACCEPTANCE CRITERIA OF THE SLAT ROLLER SLIDING CONTACTS								Service	ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-45-21-910-801					
57-45-23-900-801-01	REMOVAL / INSTALLATION OF THE SLAT SEALS - LH INBOARD SLAT SEAL								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-45-23-900-801					
57-45-23-900-801-02	REMOVAL / INSTALLATION OF THE SLAT SEALS - RH INBOARD SLAT SEAL								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-45-23-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-45-23-900-801-03	REMOVAL / INSTALLATION OF THE SLAT SEALS - LH OUTBOARD SLAT SEAL									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-45-23-900-801					
57-45-23-900-801-04	REMOVAL / INSTALLATION OF THE SLAT SEALS - RH OUTBOARD SLAT SEAL									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-45-23-900-801					
57-45-25-250-801-01	EDDY CURRENT INSPECTION OF SLAT TRACKS									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-45-25-250-801					
57-45-25-250-801-01A	EDDY CURRENT INSPECTION OF SLAT TRACKS (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 57.225	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 57-45-25-250-801					
57-55-00-700-801-01 S	CHECK OF THE FLAP LATERAL CLEARANCE - LH WING									Service ATA:57
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.235	AFL	5651								
					PROC. REF: AMM 57-55-00-700-801					PKG:31
57-55-00-700-801-02 S	CHECK OF THE FLAP LATERAL CLEARANCE - RH WING									Service ATA:57
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.235	AFL	5651								
					PROC. REF: AMM 57-55-00-700-801					PKG:31
57-55-01-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD FLAPS - LH INBOARD FLAP									Component ATA:57
PN:F50B153A1	MOS/MSC	24-Oct-91	O/C							
SN:167SE338	HRS	0		TSN 0						
WC#: 57.070	AFL	0								
					PROC. REF: AMM 57-55-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-55-01-900-801-02	REMOVAL / INSTALLATION OF THE INBOARD FLAPS - RH INBOARD FLAP								Component	ATA:57
PN:F50B154A1	MOS/MSC	24-Oct-91	O/C							
SN:170SE337	HRS	0		TSN 0						
WC#: 57.070	AFL	0								
					PROC. REF: AMM 57-55-01-900-801					
57-55-05-900-801-01	REMOVAL / INSTALLATION OF THE OUTBOARD FLAPS - LH OUTBOARD FLAP								Component	ATA:57
PN:F50B161B8	MOS/MSC	24-Oct-91	O/C							
SN:341F50225	HRS	0		TSN 0						
WC#: 57.080	AFL	0								
					PROC. REF: AMM 57-55-05-900-801					
57-55-05-900-801-02	REMOVAL / INSTALLATION OF THE OUTBOARD FLAPS - RH OUTBOARD FLAP								Component	ATA:57
PN:F50B162B8	MOS/MSC	24-Oct-91	O/C							
SN:343F50225	HRS	0		TSN 0						
WC#: 57.080	AFL	0								
					PROC. REF: AMM 57-55-05-900-801					
57-55-07-220-801-01 S	DETAILED INSPECTION OF THE PROTECTION ON INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS - LH WING								Service	ATA:57
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.130	AFL	5651								
					PROC. REF: AMM 57-55-07-220-801					PKG:31
57-55-07-220-801-02 S	DETAILED INSPECTION OF THE PROTECTION ON INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS - RH WING								Service	ATA:57
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.130	AFL	5651								
					PROC. REF: AMM 57-55-07-220-801					PKG:31
57-55-07-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD / OUTBOARD FLAP JUNCTION FAIRINGS - LH FLAP JUNCTION FAIRING								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 57.130	AFL	0								
					PROC. REF: AMM 57-55-07-900-801					
57-55-07-900-801-02	REMOVAL / INSTALLATION OF THE INBOARD / OUTBOARD FLAP JUNCTION FAIRINGS - RH FLAP JUNCTION FAIRING								Component	ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-07-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-55-09-900-801-01	REMOVAL / INSTALLATION OF THE FORE FLAPS - LH INBOARD FORE FLAP 1									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-09-900-801					
57-55-09-900-801-02	REMOVAL / INSTALLATION OF THE FORE FLAPS - LH INBOARD FORE FLAP 2									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-09-900-801					
57-55-09-900-801-03	REMOVAL / INSTALLATION OF THE FORE FLAPS - LH INBOARD FORE FLAP 3									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-09-900-801					
57-55-09-900-801-04	REMOVAL / INSTALLATION OF THE FORE FLAPS - LH OUTBOARD FORE FLAP 1									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-09-900-801					
57-55-09-900-801-05	REMOVAL / INSTALLATION OF THE FORE FLAPS - LH OUTBOARD FORE FLAP 2									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-09-900-801					
57-55-09-900-801-06	REMOVAL / INSTALLATION OF THE FORE FLAPS - RH INBOARD FORE FLAP 1									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-09-900-801					
57-55-09-900-801-07	REMOVAL / INSTALLATION OF THE FORE FLAPS - RH INBOARD FORE FLAP 2									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-09-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-55-09-900-801-08	REMOVAL / INSTALLATION OF THE FORE FLAPS - RH INBOARD FORE FLAP 3									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-09-900-801					
57-55-09-900-801-09	REMOVAL / INSTALLATION OF THE FORE FLAPS - RH OUTBOARD FORE FLAP 1									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-09-900-801					
57-55-09-900-801-10	REMOVAL / INSTALLATION OF THE FORE FLAPS - RH OUTBOARD FORE FLAP 2									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-09-900-801					
57-55-11-210-801-01[S]	GENERAL VISUAL INSPECTION OF THE FORE FLAP BRACKETS - LH WING									Service ATA:57
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.140	AFL	5651								
					PROC. REF: AMM 57-55-11-210-801					PKG:31
57-55-11-210-801-02[S]	GENERAL VISUAL INSPECTION OF THE FORE FLAP BRACKETS - RH WING									Service ATA:57
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.140	AFL	5651								
					PROC. REF: AMM 57-55-11-210-801					PKG:31
57-55-13-640-801-01	GREASING / LUBRICATION OF FLAP ROLLERS AND TRACKS - LH WING									Service ATA:57
	MOS	07-Sep-22	24 (+1m)	Adj -127d	03-May-24	03-Jun-24	184 d (+31)			
	HRS	8823	800 (+30)		9623	9653	630.9 (+30)			
	AFL	5651								
					PROC. REF: AMM 57-55-13-640-801					
57-55-13-640-801-02	GREASING / LUBRICATION OF FLAP ROLLERS AND TRACKS - RH WING									Service ATA:57
	MOS	07-Sep-22	24 (+1m)	Adj -127d	03-May-24	03-Jun-24	184 d (+31)			
	HRS	8823	800 (+30)		9623	9653	630.9 (+30)			
	AFL	5651								
					PROC. REF: AMM 57-55-13-640-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-55-13-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD / OUTBOARD FLAP ROLLERS									Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 57-55-13-900-801					
57-55-13-960-801-01	REPLACEMENT OF THE FLAP ROLLER SLIDING PEG									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-55-13-960-801					
57-55-21-250-801-01	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5									Service ATA:57
	MOS	24-Oct-91								
	HRS	0								
WC#: 57.310	AFL	0	T:7900		7900		2104			
					PROC. REF: AMM 57-55-21-250-801					
57-55-21-250-801-01A	EDDY CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5 (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
	AFL	0	T:7900		7900		2104			
					PROC. REF: AMM 57-55-21-250-801					
57-60-00-220-801-01	DETAILED INSPECTION OF THE AILERON SKIN AND HINGE FITTINGS									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-60-00-220-801					
57-60-00-220-801-01A	DETAILED INSPECTION OF THE AILERON SKIN AND HINGE FITTINGS (MANDATORY 5-40)									Service ATA:57
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 57.210	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 57-60-00-220-801					
57-60-00-820-801-01	ADJUSTMENT OF THE AILERONS									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-60-00-820-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-60-01-900-801-01	REMOVAL / INSTALLATION OF THE AILERONS - LH AILERON									Component ATA:57
PN:F50B101B5	MOS/MSC	24-Oct-91	O/C							
SN:49AT226342	HRS	0		TSN 0						
WC#: 57.020	AFL	0								
					PROC. REF: AMM 57-60-01-900-801					
57-60-01-900-801-02	REMOVAL / INSTALLATION OF THE AILERONS - RH AILERON									Component ATA:57
PN:F50B102B5	MOS/MSC	24-Oct-91	O/C							
SN:49AT226342	HRS	0		TSN 0						
WC#: 57.020	AFL	0								
					PROC. REF: AMM 57-60-01-900-801					
57-60-03-960-801-01	REPLACEMENT OF THE AILERON BRUSHES - LH AILERON									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-60-03-960-801					
57-60-03-960-801-02	REPLACEMENT OF THE AILERON BRUSHES - RH AILERON									Service ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 57-60-03-960-801					
57-60-05-640-801-01 S	PRESSURE LUBRICATION OF THE AILERON BEARINGS - LH AILERON BEARINGS									Service ATA:57
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.020	AFL	5651								
					PROC. REF: AMM 57-60-05-640-801					PKG:31
57-60-05-640-801-02 S	PRESSURE LUBRICATION OF THE AILERON BEARINGS - RH AILERON BEARINGS									Service ATA:57
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 57.020	AFL	5651								
					PROC. REF: AMM 57-60-05-640-801					PKG:31
57-60-05-640-802-01 S	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - LH AILERON									Service ATA:57
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 57-60-05-640-802					PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-60-05-640-802-02[S]	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - RH AILERON								Service	ATA:57
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 57-60-05-640-802					PKG:15
57-60-09-270-801-01	ULTRASONIC INSPECTION OF THE COMPOSITE MATERIAL AILERONS - LH AILERON F50B153A1								Service	ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 57.020	AFL	0								
					PROC. REF: AMM 57-60-09-270-801					
57-60-09-270-801-02	ULTRASONIC INSPECTION OF THE COMPOSITE MATERIAL AILERONS - RH AILERON F50B154A1								Service	ATA:57
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 57.020	AFL	0								
					PROC. REF: AMM 57-60-09-270-801					
57-70-01-900-801-01	REMOVAL / INSTALLATION OF THE AIRBRAKES - LH OUTBOARD AIRBRAKE								Component	ATA:57
PN:FGFB169	MOS/MSC	24-Oct-91	O/C							
SN:685FGEB158	HRS	0		TSN 0						
WC#: 57.090	AFL	0								
					PROC. REF: AMM 57-70-01-900-801					
57-70-01-900-801-02	REMOVAL / INSTALLATION OF THE AIRBRAKES - LH MIDDLE AIRBRAKE								Component	ATA:57
PN:FGFB167	MOS/MSC	24-Oct-91	O/C							
SN:341FGEB158	HRS	0		TSN 0						
WC#: 57.090	AFL	0								
					PROC. REF: AMM 57-70-01-900-801					
57-70-01-900-801-03	REMOVAL / INSTALLATION OF THE AIRBRAKES - LH INBOARD AIRBRAKE								Component	ATA:57
PN:F50B163B8	MOS/MSC	24-Oct-91	O/C							
SN:342F50225	HRS	0		TSN 0						
WC#: 57.090	AFL	0								
					PROC. REF: AMM 57-70-01-900-801					
57-70-01-900-801-04	REMOVAL / INSTALLATION OF THE AIRBRAKES - RH INBOARD AIRBRAKE								Component	ATA:57
PN:F50B164B8	MOS/MSC	24-Oct-91	O/C							
SN:343F50225	HRS	0		TSN 0						
WC#: 57.100	AFL	0								
					PROC. REF: AMM 57-70-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
57-70-01-900-801-05	REMOVAL / INSTALLATION OF THE AIRBRAKES - RH MIDDLE AIRBRAKE									Component ATA:57
PN:FGFB168	MOS/MSC	24-Oct-91	O/C							
SN:345FGEB158	HRS	0		TSN 0						
WC#: 57.100	AFL	0								
					PROC. REF: AMM 57-70-01-900-801					
57-70-01-900-801-06	REMOVAL / INSTALLATION OF THE AIRBRAKES - RH OUTBOARD AIRBRAKE									Component ATA:57
PN:FGFB169	MOS/MSC	24-Oct-91	O/C							
SN:686FGEB158	HRS	0		TSN 0						
WC#: 57.100	AFL	0								
					PROC. REF: AMM 57-70-01-900-801					
57-70-03-640-801-01S	LUBRICATION OF THE AIRBRAKE HINGES									Service ATA:57
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 57-70-03-640-801					PKG:15
57-70-03-960-801-01	DISCARD OF OUTBOARD AIRBRAKE CENTER HINGE - LH OUTBOARD AIRBRAKE CENTER HINGE (L901CD)									Service ATA:57
PN:F50B165003001	MOS	24-Oct-91		TAC 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TAC 0						
WC#: 57.230	AFL	0	20000		20000		14204			
					PROC. REF: AMM 57-70-03-960-801					
57-70-03-960-801-01A	DISCARD LH OUTBOARD AIRBRAKE CENTRAL HINGE (MANDATORY 5-40)									Service ATA:57
PN:F50B165003001	MOS	24-Oct-91						MANDATORY 5-40		
SN:UNKNOWN	HRS	0								
	AFL	0	20000		20000		14204			
					PROC. REF: AMM 57-70-03-960-801					
57-70-03-960-801-02	DISCARD OF OUTBOARD AIRBRAKE CENTER HINGE - RH OUTBOARD AIRBRAKE CENTER HINGE (R901CD)									Service ATA:57
PN:F50B165003001	MOS	24-Oct-91		TAC 0				LIFE LIMIT		
SN:UNKNOWN	HRS	0		TAC 0						
WC#: 57.230	AFL	0	20000		20000		14204			
					PROC. REF: AMM 57-70-03-960-801					
57-70-03-960-801-02A	DISCARD RH OUTBOARD AIRBRAKE CENTRAL HINGE (MANDATORY 5-40)									Service ATA:57
PN:F50B165003001	MOS	24-Oct-91						MANDATORY 5-40		
SN:UNKNOWN	HRS	0								
	AFL	0	20000		20000		14204			
					PROC. REF: AMM 57-70-03-960-801					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
570701		CENTRAL WING SECTION								Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 57.300	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
575151		LINKING FAIRING-INBOARD FLAP-LEFT OUTBOARD FLAP ASSEMBLY								Component ATA:57
PN:PN	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 57.130	AFL	0								
					PROC. REF: GENERIC NO REF					
575181		LH OUTBOARD AIRBRAKE CENTRAL HINGE								Component ATA:57
PN:F50B165003001	MOS/MSC	24-Oct-91	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 57.230	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
575186		RH OUTBOARD AIRBRAKE CENTRAL HINGE								Component ATA:57
PN:F50B165003001	MOS/MSC	24-Oct-91	H/T	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 57.230	AFL	0		TSN 0						
					PROC. REF: GENERIC NO REF					
A 57-10-02		MAIN LANDING GEAR BALL-JOINT BEARING BORES – DAMAGE DATA								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-10-02					
A 57-10-08		ACCEPTANCE CRITERIA FOR BORES OF MLG BALL-JOINT BEARINGS - DIMENSIONAL CHECK								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-10-08					
A 57-10-12		CORROSION ON WHEEL WELL RIB 1 AT BONDING FITTING - DAMAGE DATA								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-10-12					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
A 57-40-01		INBOARD SLATS - DAMAGE DATA								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-40-01					
A 57-40-03		OUTBOARD SLATS - DAMAGE DATA								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-40-03					
A 57-40-09		SLAT TRACKS - DAMAGE DATA								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-40-09					
A 57-50-09		FLAP TRACKS - DAMAGE DATA								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-50-09					
A 57-51-01		LOWER WING TRAILING EDGE PANEL - DAMAGE DATA								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-51-01					
A 57-55-01		INBOARD FLAPS - DAMAGE DATA								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-55-01, SRM 57-55-01					
A 57-55-04		OUTBOARD FLAPS - DAMAGE DATA								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-55-04					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
A 57-60-01		AILERONS - DAMAGE DATA								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-60-01					
R 57-00-15		RECONDITIONING AND REWORKING CRITERIA FOR WING-TO-FUSELAGE ATTACHMENT BOLT RECESSES								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-00-15					
R 57-00-17		JUNCTION PLATE CORROSION TYPICAL REPAIR								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: GENERIC NO REF					
R 57-10-02		REPAIR OF DAMAGE ON BORES OF MLG BALL-JOINT BEARINGS								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-10-02					
R 57-10-12		REPAIR OF CORROSION ON THE WHEEL WELL RIB 1 AT BONDING FITTING								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-10-12					
R 57-10-15		REPAIR OF CRACKS LOCATED ON THE WING FALSE SPAR								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-10-15					
R 57-10-16		REPAIR OF SEALANT AT MLG TRUNNION CASING								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-10-16					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
R 57-10-17		REPAIR OF FUEL LEAKS AT WING LOWER PANELS								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-10-17					
R 57-40-05		ADJUSTMENT OF CLEARANCES ON WING LEADING EDGES								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-40-05					
R 57-40-07		REPLACEMENT OF RILSAN SHIMS ON SLATS								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-40-07					
R 57-40-13		REPAIR OF BUMP ON WING LEADING EDGE AT OBTURATOR AREA								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-40-13					
R 57-50-01		REPAIR OF CORROSION ON THE FORE FLAPS								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-50-01					
R 57-60-02		REMOVAL / INSTALLATION OF THE CARBON FIBER AILERON STATIC DISCHARGERS								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-60-02					
R 57-70-02		ADJUSTMENT OF THE CLEARANCE BETWEEN MIDDLE AND OUTBOARD AIRBRAKES								Service ATA:57
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 57-70-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71-00-00-910-802-01	ENGINE INSPECTION RUN-UP - ENGINE 1 (L4EZ)									Service ATA:71
	MOS/MSC	24-Oct-91	C/C							
	HRS	0								
WC#: 71.010	AFL	0								
					PROC. REF: AMM 71-00-00-910-802, AMM 71-00-00-910-802					
71-00-00-910-802-02	ENGINE INSPECTION RUN-UP - ENGINE 2 (M4EZ)									Service ATA:71
	MOS/MSC	24-Oct-91	C/C							
	HRS	0								
WC#: 71.020	AFL	0								
					PROC. REF: AMM 71-00-00-910-802, AMM 71-00-00-910-802					
71-00-00-910-802-03	ENGINE INSPECTION RUN-UP - ENGINE 3 (R4EZ)									Service ATA:71
	MOS/MSC	24-Oct-91	C/C							
	HRS	0								
WC#: 71.030	AFL	0								
					PROC. REF: AMM 71-00-00-910-802, AMM 71-00-00-910-802					
71-20-01-220-801-01A	DETAILED INSPECTION OF ENGINE 1 AND 3 FRONT AND REAR MOUNTS (MANDATORY 5-40)									Service ATA:71
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 54.075	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 71-20-01-220-801					
71-20-02-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS AND FAIL SAFE ATTACHMENTS - ENGINE 1 FRONT MOUNT									Service ATA:71
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 71-20-02-250-801					
71-20-02-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS AND FAIL SAFE ATTACHMENTS - ENGINE 3 FRONT MOUNT									Service ATA:71
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 71-20-02-250-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71-20-02-250-801-03	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS AND FAIL SAFE ATTACHMENTS - ENGINE 1 FAIL SAFE ATTACHMENTS								Service	ATA:71
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 71-20-02-250-801					
71-20-02-250-801-04	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS AND FAIL SAFE ATTACHMENTS - ENGINE 3 FAIL SAFE ATTACHMENTS								Service	ATA:71
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
	AFL	0								
					PROC. REF: AMM 71-20-02-250-801					
71-20-05-350-801-01	RESTORATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 1 FRONT MOUNT UPPER VIBRATION ISOLATOR (L901EZ1)								Service	ATA:71
PN:3071070-2	MOS/MSC		N/A							
SN:UNKNOWN	HRS									
	AFL									
					PROC. REF: AMM 71-20-05-350-801					
71-20-05-350-801-02	RESTORATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 1 FRONT MOUNT LOWER VIBRATION ISOLATOR (L901EZ2)								Service	ATA:71
PN:3071070-2	MOS/MSC		N/A							
SN:UNKNOWN	HRS									
	AFL									
					PROC. REF: AMM 71-20-05-350-801					
71-20-05-350-801-03	RESTORATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 3 FRONT MOUNT UPPER VIBRATION ISOLATOR (R901EZ1)								Service	ATA:71
PN:3071070-2	MOS/MSC		N/A							
SN:UNKNOWN	HRS									
	AFL									
					PROC. REF: AMM 71-20-05-350-801					
71-20-05-350-801-04	RESTORATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 3 FRONT MOUNT LOWER VIBRATION ISOLATOR (R901EZ2)								Service	ATA:71
PN:3071070-2	MOS/MSC		N/A							
SN:UNKNOWN	HRS									
	AFL									
					PROC. REF: AMM 71-20-05-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71-20-05-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS - ENGINE 1 FRONT MOUNT UPPER VIBRATION ISOLATOR (L901EZ1)								Component	ATA:71
PN:3071070-2	MOS/MSC	13-Dec-13	O/C	TSR 66						
SN:UNKNOWN	HRS	8092.4		TSR 1347.5						
WC#: 71.050	AFL	5236		TSR 1039						
					PROC. REF: AMM 71-20-05-900-801					
71-20-05-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS - ENGINE 1 FRONT MOUNT LOWER VIBRATION ISOLATOR (L901EZ2)								Component	ATA:71
PN:3071070-2	MOS/MSC	13-Dec-13	O/C	TSR 66						
SN:UNKNOWN	HRS	8092.4		TSR 1347.5						
WC#: 71.050	AFL	5236		TSR 1039						
					PROC. REF: AMM 71-20-05-900-801					
71-20-05-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS - ENGINE 3 FRONT MOUNT UPPER VIBRATION ISOLATOR (R901EZ1)								Component	ATA:71
PN:3071070-2	MOS/MSC	19-Dec-11	O/C							
SN:UNKNOWN	HRS	7712.7								
WC#: 71.055	AFL	4979								
					PROC. REF: AMM 71-20-05-900-801					
71-20-05-900-801-04	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS - ENGINE 3 FRONT MOUNT LOWER VIBRATION ISOLATOR (R901EZ2)								Component	ATA:71
PN:3071070-2	MOS/MSC	19-Dec-11	O/C							
SN:UNKNOWN	HRS	7712.7								
WC#: 71.055	AFL	4979								
					PROC. REF: AMM 71-20-05-900-801					
71-20-07-250-801-01	SPECIAL DETAILED INSPECTION (NDT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 1 REAR MOUNT (L910EZ)								Service	ATA:71
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 54.100	AFL	0								
					PROC. REF: AMM 71-20-07-250-801					
71-20-07-250-801-02	SPECIAL DETAILED INSPECTION (NDT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 3 REAR MOUNT (R910EZ)								Service	ATA:71
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 54.100	AFL	0								
					PROC. REF: AMM 71-20-07-250-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71-20-07-960-801-01	DISCARD OF THE ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT - ENGINE 1									Service ATA:71
	MOS/MSC		O/C							
	HRS									
WC#: 54.040	AFL									
					PROC. REF: AMM 71-20-07-960-801					
71-20-07-960-801-01A	DISCARD OF THE ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT - ENGINE 1 (MANDATORY 5-40)									Service ATA:71
	MOS/MSC		O/C							
	HRS									
	AFL									
					PROC. REF: AMM 71-20-07-960-801					
71-20-07-960-801-02	DISCARD OF THE ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT - ENGINE 3									Service ATA:71
	MOS/MSC		O/C							
	HRS									
WC#: 54.060	AFL									
					PROC. REF: AMM 71-20-07-960-801					
71-20-07-960-801-02A	DISCARD OF THE ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT - ENGINE 3 (MANDATORY 5-40)									Service ATA:71
	MOS/MSC		O/C							
	HRS									
	AFL									
					PROC. REF: AMM 71-20-07-960-801					
71-20-09-350-801-01	RESTORATION OF THE ENGINE 1 AND 3 REAR MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 1 REAR MOUNT VIBRATION ISOLATOR (L911EZ)									Service ATA:71
	MOS/MSC		N/A							
	HRS									
	AFL									
					PROC. REF: AMM 71-20-09-350-801					
71-20-09-350-801-02	RESTORATION OF THE ENGINE 1 AND 3 REAR MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 3 REAR MOUNT VIBRATION ISOLATOR (R911EZ)									Service ATA:71
	MOS/MSC		N/A							
	HRS									
	AFL									
					PROC. REF: AMM 71-20-09-350-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71-20-09-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 REAR MOUNT VIBRATION ISOLATORS - ENGINE 1 REAR MOUNT VIBRATION ISOLATOR (L911EZ)									Component ATA:71
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 71.070	AFL	0		TSN 0						
					PROC. REF: AMM 71-20-09-900-801					
71-20-09-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 REAR MOUNT VIBRATION ISOLATORS - ENGINE 3 REAR MOUNT VIBRATION ISOLATOR (R911EZ)									Component ATA:71
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 71.080	AFL	0		TSN 0						
					PROC. REF: AMM 71-20-09-900-801					
71-20-11-220-801-01A	DETAILED INSPECTION OF ENGINE 2 HOISTING PLATE AND MOUNTS (MANDATORY 5-40)									Service ATA:71
	MOS	24-Oct-91						MANDATORY 5-40		
	HRS	0								
WC#: 54.082	AFL	0	T:20000		20000		14204			
					PROC. REF: AMM 71-20-11-220-801					
71-20-11-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 2 MOUNT COMPONENTS - ENGINE 2 LH FRONT MOUNT									Component ATA:71
PN:LM833-16	MOS/MSC	10-Dec-03	O/C	TSN 0						
SN:UNKNOWN	HRS	4936.4		TSN 0						
WC#: 71.045	AFL	3069		TSN 0						
					PROC. REF: AMM 71-20-11-900-801					
71-20-11-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 2 MOUNT COMPONENTS - ENGINE 2 RH FRONT MOUNT									Component ATA:71
PN:LM833SA9	MOS/MSC	27-Jan-01	O/C	TSN 0						
SN:001011030	HRS	4030		TSN 0						
WC#: 71.046	AFL	2570		TSN 0						
					PROC. REF: AMM 71-20-11-900-801					
71-20-11-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE 2 MOUNT COMPONENTS - ENGINE 2 AFT MOUNT									Component ATA:71
PN:LM833-16	MOS/MSC	10-Dec-03	O/C	TSN 0						
SN:001115056	HRS	4936.4		TSN 0						
WC#: 71.047	AFL	3069		TSN 0						
					PROC. REF: AMM 71-20-11-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71-20-17-230-801-01		SPECIAL DETAILED INSPECTION OF THE ENGINE 2 FRONT VIBRATION ISOLATORS / REPLACEMENT OF RUBBER CORES - ENGINE 2 LH FRONT VIBRATION ISOLATOR (M900EZ1)							Service	ATA:71
PN:LM833-16	MOS	10-Dec-03								
SN:UNKNOWN	HRS	4936.4	5000 (+150)		9936.4	10086.4	944.3 (+150)			
	AFL	3069								
					PROC. REF: AMM 71-20-17-230-801, AMM 71-20-17-230-801					
71-20-17-230-801-02		SPECIAL DETAILED INSPECTION OF THE ENGINE 2 FRONT VIBRATION ISOLATORS / REPLACEMENT OF RUBBER CORES - ENGINE 2 RH FRONT VIBRATION ISOLATOR (M900EZ2)							Service	ATA:71
PN:LM833SA9	MOS	11-Dec-03								
SN:001011030	HRS	4936.4	5000 (+150)		9936.4	10086.4	944.3 (+150)			
	AFL	3069								
					PROC. REF: AMM 71-20-17-230-801, AMM 71-20-17-230-801					
71-20-21-230-801-01		SPECIAL DETAILED INSPECTION OF THE ENGINE 2 REAR VIBRATION ISOLATOR / REPLACEMENT OF RUBBER CORES - ENGINE 2 REAR VIBRATION ISOLATOR (M910EZ)							Service	ATA:71
PN:LM833-16	MOS	10-Dec-03								
SN:001115056	HRS	4936.4	5000 (+150)		9936.4	10086.4	944.3 (+150)			
	AFL	3069								
					PROC. REF: AMM 71-20-21-230-801					
71-20-21-960-801-01		DISCARD OF THE ENGINE 2 REAR MOUNT VIBRATION ISOLATOR - ENGINE 2 REAR VIBRATION ISOLATOR (M910EZ)							Service	ATA:71
PN:LM833-16	MOS/MSC	24-Oct-91	O/C							
SN:001115056	HRS	0								
WC#: 71.065	AFL	0								
					PROC. REF: AMM 71-20-21-960-801					
71-20-23-900-801-01		REMOVAL / INSTALLATION OF THE ENGINE 2 HOISTING PLATE - ENGINE 2 HOISTING PLATE							Component	ATA:71
PN:4210-3	MOS/MSC	24-Oct-91	O/C							
SN:341	HRS	0		TSN 0						
WC#: 71.060	AFL	0								
					PROC. REF: AMM 71-20-23-900-801					
710120		NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)							Service	ATA:71
	MOS	19-Dec-11								
	HRS	7512.1	1400 (+100)		(8912.1) 9200.8	9012.1	208.7 (+100)			
WC#: 71.010	ENC	4826								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
710120		NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)								Service ATA:71
	MOS	24-Dec-13								
	HRS	7993.6	1400 (+100)		(9393.6) 9506.6	9493.6	514.5 (+100)			
WC#: 71.010	ENC	5148								
					PROC. REF: LMM 72-00-00					
710120		NO. 3 ENGINE - MAJOR PERIODIC INSPECTION (MPI)								Service ATA:71
	MOS	13-Dec-13								
	HRS	7961.7	1400 (+100)		(9361.7) 9492.4	9461.7	500.3 (+100)			
WC#: 71.010	ENC	5141								
					PROC. REF: LMM 72-00-00					
710130[S]		NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES								Service ATA:71
	MOS	07-Jul-23								
	HRS	8674.8	400							
WC#: 71.020	ENC	5769								
					PROC. REF: LMM 72-00-00					PKG:0
710130[S]		NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES								Service ATA:71
	MOS	10-Jan-23								
	HRS	8781.4	400							
WC#: 71.020	ENC	5622								
					PROC. REF: LMM 72-00-00					PKG:0
710130[S]		NO. 3 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES								Service ATA:71
	MOS	10-Jan-23								
	HRS	8763.7	400							
WC#: 71.020	ENC	5626								
					PROC. REF: LMM 72-00-00					PKG:0
710336		FLIGHT CHECK ENGINE								Service ATA:71
	MOS/MSC	24-Oct-91	E/C							
	HRS	0								
WC#: 71.040	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
714010[S]		NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS								Service ATA:71
	MOS	03-Dec-18								
	HRS	8308.8	800							
WC#: 71.040	ENC	5327								
					PROC. REF: LMM 72-00-00					PKG:0
714010[S]		NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS								Service ATA:71
	MOS	10-Jan-23								
	HRS	8781.4	800							
WC#: 71.040	ENC	5622								
					PROC. REF: LMM 72-00-00					PKG:0
714010[S]		NO. 3 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS								Service ATA:71
	MOS	10-Jan-23								
	HRS	8763.7	800							
WC#: 71.040	ENC	5626								
					PROC. REF: LMM 72-00-00					PKG:0
715010[S]		NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS								Service ATA:71
	MOS	03-Dec-18								
	HRS	8308.8	800							
WC#: 71.050	ENC	5327								
					PROC. REF: LMM 72-00-00					PKG:0
715010[S]		NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS								Service ATA:71
	MOS	10-Jan-23								
	HRS	8781.4	800							
WC#: 71.050	ENC	5622								
					PROC. REF: LMM 72-00-00					PKG:0
715010[S]		NO. 3 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS								Service ATA:71
	MOS	10-Jan-23								
	HRS	8763.7	800							
WC#: 71.050	ENC	5626								
					PROC. REF: LMM 72-00-00					PKG:0
71EN1		NO. 1 ENGINE								Component ATA:71
PN:3072800-5	MOS/MSC	14-Aug-15	E/C							
SN:P-76815	HRS	8241.2		TSN 7952.5						
	AFL	5325		TSN 5124						
	APH									
					PROC. REF: AMM 71-00-01-900-801, AMM 71-00-01-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
71EN2		NO. 2 ENGINE								Component ATA:71
PN:3072800-5	MOS/MSC	13-Feb-14	E/C							
SN:P-76813	HRS	8106.6		TSN 7993.6						
	AFL	5246								
					PROC. REF: AMM 71-00-05-900-801, AMM 71-00-05-900-801, AMM 71-00-05-900-801					
71EN3		NO. 3 ENGINE								Component ATA:71
PN:3072800-5	MOS/MSC	12-Jun-15	E/C							
SN:P-76814	HRS	8203.4		TSN 8072.7						
	AFL	5309								
					PROC. REF: AMM 71-00-01-900-801, AMM 71-00-01-900-801					
ATA 72 - ENGINE										
72-00-00.10		NO. 1 ENGINE - HUNG START (NO OR SLOW ACCELERATION)								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.10		NO. 2 ENGINE - HUNG START (NO OR SLOW ACCELERATION)								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.10		NO. 3 ENGINE - HUNG START (NO OR SLOW ACCELERATION)								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.11		NO. 1 ENGINE - HOT START								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.11		NO. 2 ENGINE - HOT START								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.11		NO. 3 ENGINE - HOT START								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.12		NO. 1 ENGINE - SURGE BLEED VALVE OPERATION CHECK								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.12		NO. 2 ENGINE - SURGE BLEED VALVE OPERATION CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.12		NO. 3 ENGINE - SURGE BLEED VALVE OPERATION CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.13_FUEL		NO. 1 ENGINE - [3A, 3B, 3C] FUEL PUMP MOTIVE FLOW PRESSURE REGULATOR ADJUSTMENT PROCEDURE								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.13_FUEL		NO. 2 ENGINE - [3A, 3B, 3C] FUEL PUMP MOTIVE FLOW PRESSURE REGULATOR ADJUSTMENT PROCEDURE								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.13_FUEL		NO. 3 ENGINE - [3A, 3B, 3C] FUEL PUMP MOTIVE FLOW PRESSURE REGULATOR ADJUSTMENT PROCEDURE								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.13_OIL		NO. 1 ENGINE - OIL AND FILTER ANALYSIS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.13_OIL		NO. 2 ENGINE - OIL AND FILTER ANALYSIS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.13_OIL		NO. 3 ENGINE - OIL AND FILTER ANALYSIS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.13_SBV		NO. 1 ENGINE - SURGE BLEED VALVE AND SOLENOID CONTROLLER CHECKS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.13_SBV		NO. 2 ENGINE - SURGE BLEED VALVE AND SOLENOID CONTROLLER CHECKS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.13_SBV		NO. 3 ENGINE - SURGE BLEED VALVE AND SOLENOID CONTROLLER CHECKS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.15		NO. 1 ENGINE - INTERSTAGE TURBINE TEMPERATURE (ITT) CIRCUITRY CHECKS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.15		NO. 2 ENGINE - INTERSTAGE TURBINE TEMPERATURE (ITT) CIRCUITRY CHECKS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.15		NO. 3 ENGINE - INTERSTAGE TURBINE TEMPERATURE (ITT) CIRCUITRY CHECKS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.16_BINDING		NO. 1 ENGINE - ENGINE INTERNAL BINDING CHECKS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.16_BINDING		NO. 2 ENGINE - ENGINE INTERNAL BINDING CHECKS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.16_BINDING		NO. 3 ENGINE - ENGINE INTERNAL BINDING CHECKS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.16_INS		NO. 1 ENGINE - OVERSPEED INSPECTION								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.16_INS		NO. 2 ENGINE - OVERSPEED INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.16_INS	NO. 3 ENGINE - OVERSPEED INSPECTION									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.16_STALL	NO. 1 ENGINE - COMPRESSOR STALL									Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.16_STALL	NO. 2 ENGINE - COMPRESSOR STALL									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.16_STALL	NO. 3 ENGINE - COMPRESSOR STALL									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.17_FUEL	NO. 1 ENGINE - FUEL PUMP FUNCTIONAL TEST									Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.17_FUEL	NO. 2 ENGINE - FUEL PUMP FUNCTIONAL TEST									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.17_FUEL	NO. 3 ENGINE - FUEL PUMP FUNCTIONAL TEST									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.17_HP		NO. 1 ENGINE - HP IMPELLER BORESCOPE INSPECTION								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.17_HP		NO. 2 ENGINE - HP IMPELLER BORESCOPE INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.17_HP		NO. 3 ENGINE - HP IMPELLER BORESCOPE INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.17_MEDRA		NO. 1 ENGINE - MEDRA								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.17_MEDRA		NO. 2 ENGINE - MEDRA								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.17_MEDRA		NO. 3 ENGINE - MEDRA								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.18		NO. 1 ENGINE - COMPRESSOR DISCHARGE PRESSURE (P3) LIMITER VALVE FUNCTIONAL TEST								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.18		NO. 2 ENGINE - COMPRESSOR DISCHARGE PRESSURE (P3) LIMITER VALVE FUNCTIONAL TEST								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.18		NO. 3 ENGINE - COMPRESSOR DISCHARGE PRESSURE (P3) LIMITER VALVE FUNCTIONAL TEST								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.19		NO. 1 ENGINE - [ALL EXCEPT 3-1J] ROUTINE PERIODIC INSPECTION								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.19		NO. 2 ENGINE - [ALL EXCEPT 3-1J] ROUTINE PERIODIC INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.19		NO. 3 ENGINE - [ALL EXCEPT 3-1J] ROUTINE PERIODIC INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.2		NO. 1 ENGINE - NO N2 INDICATION								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.2		NO. 2 ENGINE - NO N2 INDICATION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.2		NO. 3 ENGINE - NO N2 INDICATION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.20_FUEL		NO. 1 ENGINE - FUEL MANIFOLD ASSEMBLY PRESSURE CHECK								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.20_FUEL		NO. 2 ENGINE - FUEL MANIFOLD ASSEMBLY PRESSURE CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.20_FUEL		NO. 3 ENGINE - FUEL MANIFOLD ASSEMBLY PRESSURE CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.20_INSP		NO. 1 ENGINE - [3-1J] ROUTINE PERIODIC INSPECTION								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.20_INSP		NO. 2 ENGINE - [3-1J] ROUTINE PERIODIC INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.20_INSP		NO. 3 ENGINE - [3-1J] ROUTINE PERIODIC INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.21_P3		NO. 1 ENGINE - FUEL CONTROL P3 DRAIN LEAKAGE TEST								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.21_P3		NO. 2 ENGINE - FUEL CONTROL P3 DRAIN LEAKAGE TEST								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.21_P3		NO. 3 ENGINE - FUEL CONTROL P3 DRAIN LEAKAGE TEST								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.22_EEC		NO. 1 ENGINE - [EEC] PT2 SENSING SYSTEM CHECK								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.22_EEC		NO. 2 ENGINE - [EEC] PT2 SENSING SYSTEM CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.22_EEC		NO. 3 ENGINE - [EEC] PT2 SENSING SYSTEM CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.22_INSP		NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE PERIODIC INSPECTION								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.22_INSP	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE PERIODIC INSPECTION									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.22_INSP	NO. 3 ENGINE - COMBUSTION CHAMBER PLENUM CASE PERIODIC INSPECTION									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.23_CZI	NO. 1 ENGINE - COMPRESSOR ZONE PERIODIC INSPECTION									Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.23_CZI	NO. 2 ENGINE - COMPRESSOR ZONE PERIODIC INSPECTION									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.23_CZI	NO. 3 ENGINE - COMPRESSOR ZONE PERIODIC INSPECTION									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.23_INSP	NO. 1 ENGINE - COMBUSTION CHAMBER LINER BORESCOPE INSPECTION									Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.23_INSP	NO. 2 ENGINE - COMBUSTION CHAMBER LINER BORESCOPE INSPECTION									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.23_INSP	NO. 3 ENGINE - COMBUSTION CHAMBER LINER BORESCOPE INSPECTION									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.24	NO. 1 ENGINE - FUEL-IN-OIL CHECK									Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.24	NO. 2 ENGINE - FUEL-IN-OIL CHECK									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.24	NO. 3 ENGINE - FUEL-IN-OIL CHECK									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.25	NO. 1 ENGINE - FAN SUPPORT ASSEMBLY PERIODIC INSPECTION									Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.25	NO. 2 ENGINE - FAN SUPPORT ASSEMBLY PERIODIC INSPECTION									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.25	NO. 3 ENGINE - FAN SUPPORT ASSEMBLY PERIODIC INSPECTION									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.25_FUEL	NO. 1 ENGINE - IMPENDING FUEL FILTER BY-PASS INDICATION CHECK									Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.25_FUEL	NO. 2 ENGINE - IMPENDING FUEL FILTER BY-PASS INDICATION CHECK									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.25_FUEL	NO. 3 ENGINE - IMPENDING FUEL FILTER BY-PASS INDICATION CHECK									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.26	NO. 1 ENGINE - [3-1J] LP COMPRESSOR ROTOR ASSEMBLY DISCS (DE-BLADE) PERIODIC INSPECTION									Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.26	NO. 2 ENGINE - [3-1J] LP COMPRESSOR ROTOR ASSEMBLY DISCS (DE-BLADE) PERIODIC INSPECTION									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.26	NO. 3 ENGINE - [3-1J] LP COMPRESSOR ROTOR ASSEMBLY DISCS (DE-BLADE) PERIODIC INSPECTION									Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.27	NO. 1 ENGINE - FAN ROTOR ASSEMBLY BLADES INSPECTION									Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.27		NO. 2 ENGINE - FAN ROTOR ASSEMBLY BLADES INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.27		NO. 3 ENGINE - FAN ROTOR ASSEMBLY BLADES INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.28		NO. 1 ENGINE - FAN AREA INSPECTION								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.28		NO. 2 ENGINE - FAN AREA INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.28		NO. 3 ENGINE - FAN AREA INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.29		NO. 1 ENGINE - HOT SECTION INSPECTION								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.29		NO. 2 ENGINE - HOT SECTION INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.29		NO. 3 ENGINE - HOT SECTION INSPECTION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4B		NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) POWER CIRCUIT CHECK								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4B		NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) POWER CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4B		NO. 3 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) POWER CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4C		NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) CHECK								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4C		NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4C		NO. 3 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.4D		NO. 1 ENGINE - N1 TRANSDUCER CIRCUIT CHECK								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4D		NO. 2 ENGINE - N1 TRANSDUCER CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4D		NO. 3 ENGINE - N1 TRANSDUCER CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4E		NO. 1 ENGINE - N2 TRANSDUCER CIRCUIT CHECK								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4E		NO. 2 ENGINE - N2 TRANSDUCER CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4E		NO. 3 ENGINE - N2 TRANSDUCER CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4F		NO. 1 ENGINE - INLET TEMPERATURE (T2) SENSOR CIRCUIT CHECK								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.4F		NO. 2 ENGINE - INLET TEMPERATURE (T2) SENSOR CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4F		NO. 3 ENGINE - INLET TEMPERATURE (T2) SENSOR CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4J		NO. 1 ENGINE - SURGE CONTROL VALVE SOLENOID A CIRCUIT CHECK								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4J		NO. 2 ENGINE - SURGE CONTROL VALVE SOLENOID A CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4J		NO. 3 ENGINE - SURGE CONTROL VALVE SOLENOID A CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4K		NO. 1 ENGINE - SURGE CONTROL VALVE SOLENOID B CIRCUIT CHECK								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.4K		NO. 2 ENGINE - SURGE CONTROL VALVE SOLENOID B CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.4K		NO. 3 ENGINE - SURGE CONTROL VALVE SOLENOID B CIRCUIT CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.5		NO. 1 ENGINE - NO OR LOW FUEL FLOW								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.5		NO. 2 ENGINE - NO OR LOW FUEL FLOW								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.5		NO. 3 ENGINE - NO OR LOW FUEL FLOW								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.7		NO. 1 ENGINE - FUEL LEAKAGE CHECKS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.7		NO. 2 ENGINE - FUEL LEAKAGE CHECKS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.7		NO. 3 ENGINE - FUEL LEAKAGE CHECKS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.8		NO. 1 ENGINE - OIL LEAKAGE CHECKS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.8		NO. 2 ENGINE - OIL LEAKAGE CHECKS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.8		NO. 3 ENGINE - OIL LEAKAGE CHECKS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.9_EEC		NO. 1 ENGINE - [EEC] ELECTRONIC ENGINE CONTROL (EEC) ADJUSTMENT PROCEDURES								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.9_EEC		NO. 2 ENGINE - [EEC] ELECTRONIC ENGINE CONTROL (EEC) ADJUSTMENT PROCEDURES								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.9_EEC		NO. 3 ENGINE - [EEC] ELECTRONIC ENGINE CONTROL (EEC) ADJUSTMENT PROCEDURES								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.9_N1		NO. 1 ENGINE - NO N1 INDICATION								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-00-00.9_N1		NO. 2 ENGINE - NO N1 INDICATION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.9_N1		NO. 3 ENGINE - NO N1 INDICATION								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-20-01.1		NO. 1 ENGINE - FAN INLET HOUSING								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-20-01					
72-20-01.1		NO. 2 ENGINE - FAN INLET HOUSING								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-20-01					
72-20-01.1		NO. 3 ENGINE - FAN INLET HOUSING								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-20-01					
72-20-01.2		NO. 1 ENGINE - FAN INLET HOUSING CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-20-01					
72-20-01.2		NO. 2 ENGINE - FAN INLET HOUSING CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-20-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-20-01.2		NO. 3 ENGINE - FAN INLET HOUSING CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-20-01					
72-20-02.1		NO. 1 ENGINE - COMPRESSOR INLET STATOR								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-20-02					
72-20-02.1		NO. 2 ENGINE - COMPRESSOR INLET STATOR								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-20-02					
72-20-02.1		NO. 3 ENGINE - COMPRESSOR INLET STATOR								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-20-02					
72-20-02.2		NO. 1 ENGINE - COMPRESSOR INLET STATOR CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-20-02					
72-20-02.2		NO. 2 ENGINE - COMPRESSOR INLET STATOR CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-20-02					
72-20-02.2		NO. 3 ENGINE - COMPRESSOR INLET STATOR CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-20-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-30-01.1		NO. 1 ENGINE - LP COMPRESSOR BEARING AND NO. 3 SEAL								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-30-01					
72-30-01.1		NO. 2 ENGINE - LP COMPRESSOR BEARING AND NO. 3 SEAL								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-30-01					
72-30-01.1		NO. 3 ENGINE - LP COMPRESSOR BEARING AND NO. 3 SEAL								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-30-01					
72-30-01.2		NO. 1 ENGINE - LP COMPRESSOR BEARING AND NO. 3 SEAL CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-30-01					
72-30-01.2		NO. 2 ENGINE - LP COMPRESSOR BEARING AND NO. 3 SEAL CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-30-01					
72-30-01.2		NO. 3 ENGINE - LP COMPRESSOR BEARING AND NO. 3 SEAL CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-30-01					
72-30-03.1		NO. 1 ENGINE - BORESCOPE INSPECTION PLUG AND ENGINE MOUNT BUSHINGS								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-30-03					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-30-03.1		NO. 2 ENGINE - BORESCOPE INSPECTION PLUG AND ENGINE MOUNT BUSHINGS							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-30-03					
72-30-03.1		NO. 3 ENGINE - BORESCOPE INSPECTION PLUG AND ENGINE MOUNT BUSHINGS							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-30-03					
72-30-03.2		NO. 1 ENGINE - BORESCOPE INSPECTION PLUG AND ENGINE MOUNT BUSHINGS CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-30-03					
72-30-03.2		NO. 2 ENGINE - BORESCOPE INSPECTION PLUG AND ENGINE MOUNT BUSHINGS CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-30-03					
72-30-03.2		NO. 3 ENGINE - BORESCOPE INSPECTION PLUG AND ENGINE MOUNT BUSHINGS CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-30-03					
72-30-04.2		NO. 1 ENGINE - BORESCOPE INSPECTION LP FIRST STAGE COMPRESSOR ROTOR ASSEMBLY							Service	ATA:72
	MOS/MSC	11-Jul-22	A/R							
	HRS	8532.4								
	ENC	5648								
					PROC. REF: LMM 72-30-04					
72-30-04.2		NO. 2 ENGINE - BORESCOPE INSPECTION LP FIRST STAGE COMPRESSOR ROTOR ASSEMBLY							Service	ATA:72
	MOS/MSC	11-Jul-22	A/R							
	HRS	8708.1								
	ENC	5556								
					PROC. REF: LMM 72-30-04					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-30-04.2		NO. 3 ENGINE - BORESCOPE INSPECTION LP FIRST STAGE COMPRESSOR ROTOR ASSEMBLY							Service	ATA:72
	MOS/MSC	11-Jul-22	A/R							
	HRS	8690.4								
	ENC	5560								
					PROC. REF: LMM 72-30-04					
72-30-10.2		NO. 1 ENGINE - LP TIE ROD CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-30-10					
72-30-10.2		NO. 2 ENGINE - LP TIE ROD CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-30-10					
72-30-10.2		NO. 3 ENGINE - LP TIE ROD CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-30-10					
72-40-01.1		NO. 1 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER AND CAP							Component	ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-01					
72-40-01.1		NO. 2 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER AND CAP							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-01					
72-40-01.1		NO. 3 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER AND CAP							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-40-01.2		NO. 1 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER AND CAP CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-01					
72-40-01.2		NO. 2 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER AND CAP CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-01					
72-40-01.2		NO. 3 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER AND CAP CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-01					
72-40-02.1		NO. 1 ENGINE - [PRE SB TFE731-72-3536] COMBUSTION CHAMBER LINER							Component	ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-02					
72-40-02.1		NO. 2 ENGINE - [PRE SB TFE731-72-3536] COMBUSTION CHAMBER LINER							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-02					
72-40-02.1		NO. 3 ENGINE - [PRE SB TFE731-72-3536] COMBUSTION CHAMBER LINER							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-02					
72-40-02.2		NO. 1 ENGINE - [PRE SB TFE731-72-3536] COMBUSTION CHAMBER LINER CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-40-02.2		NO. 2 ENGINE - [PRE SB TFE731-72-3536] COMBUSTION CHAMBER LINER CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-02					
72-40-02.2		NO. 3 ENGINE - [PRE SB TFE731-72-3536] COMBUSTION CHAMBER LINER CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-02					
72-40-03.1		NO. 1 ENGINE - OUTER TRANSITION LINER							Component	ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-03					
72-40-03.1		NO. 2 ENGINE - OUTER TRANSITION LINER							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-03					
72-40-03.1		NO. 3 ENGINE - OUTER TRANSITION LINER							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-03					
72-40-03.2		NO. 1 ENGINE - OUTER TRANSITION LINER CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-03					
72-40-03.2		NO. 2 ENGINE - OUTER TRANSITION LINER CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-03					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-40-03.2		NO. 3 ENGINE - OUTER TRANSITION LINER CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-03					
72-40-04.2		NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE CHECK							Service	ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-04					
72-40-04.2		NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE CHECK							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-04					
72-40-04.2		NO. 3 ENGINE - COMBUSTION CHAMBER PLENUM CASE CHECK							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-04					
72-40-05.1		NO. 1 ENGINE - [POST SB TFE731-72-3536] COMBUSTION CHAMBER LINER (CONTROLLED FIT)							Component	ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-05					
72-40-05.1		NO. 2 ENGINE - [POST SB TFE731-72-3536] COMBUSTION CHAMBER LINER (CONTROLLED FIT)							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-05					
72-40-05.1		NO. 3 ENGINE - [POST SB TFE731-72-3536] COMBUSTION CHAMBER LINER (CONTROLLED FIT)							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-40-05					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-40-05.2		NO. 1 ENGINE - [POST SB TFE731-72-3536] COMBUSTION CHAMBER LINER (CONTROLLED FIT) CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-05					
72-40-05.2		NO. 2 ENGINE - [POST SB TFE731-72-3536] COMBUSTION CHAMBER LINER (CONTROLLED FIT) CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-05					
72-40-05.2		NO. 3 ENGINE - [POST SB TFE731-72-3536] COMBUSTION CHAMBER LINER (CONTROLLED FIT) CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-40-05					
72-50-01.1		NO. 1 ENGINE - LP TURBINE ROLLER BEARING							Component	ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-01					
72-50-01.1		NO. 2 ENGINE - LP TURBINE ROLLER BEARING							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-01					
72-50-01.1		NO. 3 ENGINE - LP TURBINE ROLLER BEARING							Component	ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-01					
72-50-01.2		NO. 1 ENGINE - LP TURBINE ROLLER BEARING CHECK AND REPAIRS							Service	ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-50-01.2		NO. 2 ENGINE - LP TURBINE ROLLER BEARING CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-01					
72-50-01.2		NO. 3 ENGINE - LP TURBINE ROLLER BEARING CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-01					
72-50-02.1		NO. 1 ENGINE - THRUST AND EXHAUST NOZZLE								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-02					
72-50-02.1		NO. 2 ENGINE - THRUST AND EXHAUST NOZZLE								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-02					
72-50-02.1		NO. 3 ENGINE - THRUST AND EXHAUST NOZZLE								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-02					
72-50-02.2		NO. 1 ENGINE - THRUST AND EXHAUST NOZZLE CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-02					
72-50-02.2		NO. 2 ENGINE - THRUST AND EXHAUST NOZZLE CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-50-02.2		NO. 3 ENGINE - THRUST AND EXHAUST NOZZLE CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-02					
72-50-03.1		NO. 1 ENGINE - THERMOCOUPLE HARNESS AND N1 TRANSDUCER MOUNTING BRACKETS								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-03					
72-50-03.1		NO. 2 ENGINE - THERMOCOUPLE HARNESS AND N1 TRANSDUCER MOUNTING BRACKETS								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-03					
72-50-03.1		NO. 3 ENGINE - THERMOCOUPLE HARNESS AND N1 TRANSDUCER MOUNTING BRACKETS								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-03					
72-50-03.2		NO. 1 ENGINE - THERMOCOUPLE HARNESS AND N1 TRANSDUCER MOUNTING BRACKETS CHECKS AND REPAIRS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-03					
72-50-03.2		NO. 2 ENGINE - THERMOCOUPLE HARNESS AND N1 TRANSDUCER MOUNTING BRACKETS CHECKS AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-03					
72-50-03.2		NO. 3 ENGINE - THERMOCOUPLE HARNESS AND N1 TRANSDUCER MOUNTING BRACKETS CHECKS AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-03					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-50-05.2		NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-05					
72-50-05.2		NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-05					
72-50-05.2		NO. 3 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-05					
72-50-06.2		NO. 1 ENGINE - HP TURBINE ROTOR ASSEMBLY CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-06					
72-50-06.2		NO. 2 ENGINE - HP TURBINE ROTOR ASSEMBLY CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-06					
72-50-06.2		NO. 3 ENGINE - HP TURBINE ROTOR ASSEMBLY CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-06					
72-50-07.1		NO. 1 ENGINE - HP TURBINE NOZZLE ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-07					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-50-07.1		NO. 2 ENGINE - HP TURBINE NOZZLE ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-07					
72-50-07.1		NO. 3 ENGINE - HP TURBINE NOZZLE ASSEMBLY								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-07					
72-50-07.2		NO. 1 ENGINE - HP TURBINE NOZZLE ASSEMBLY CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-07					
72-50-07.2		NO. 2 ENGINE - HP TURBINE NOZZLE ASSEMBLY CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-07					
72-50-07.2		NO. 3 ENGINE - HP TURBINE NOZZLE ASSEMBLY CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-07					
72-50-08.1		NO. 1 ENGINE - [3C] LP TURBINE MODULE								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-08					
72-50-08.1		NO. 2 ENGINE - [3C] LP TURBINE MODULE								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-08					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
72-50-08.1		NO. 3 ENGINE - [3C] LP TURBINE MODULE								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 72-50-08					
72-50-08.2		NO. 1 ENGINE - [3C] LP TURBINE MODULE CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-08					
72-50-08.2		NO. 2 ENGINE - [3C] LP TURBINE MODULE CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-08					
72-50-08.2		NO. 3 ENGINE - [3C] LP TURBINE MODULE CHECK AND REPAIRS								Service ATA:72
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-50-08					
720078		NO. 1 ENGINE - ENGINE HARNESS								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.320	ENC	0		TSN 0						
					PROC. REF: LMM 72-00-02					
720078		NO. 2 ENGINE - ENGINE HARNESS								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.320	ENC	0		TSN 0						
					PROC. REF: LMM 72-00-02					
720078		NO. 3 ENGINE - ENGINE HARNESS								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.320	ENC	0		TSN 0						
					PROC. REF: LMM 72-00-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720079		NO. 1 ENGINE - COMPUTER HARNESS								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.330	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
720079		NO. 2 ENGINE - COMPUTER HARNESS								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.330	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
720079		NO. 3 ENGINE - COMPUTER HARNESS								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.330	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
720080		NO. 1 ENGINE - T/C HARNESS								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.340	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
720080		NO. 2 ENGINE - T/C HARNESS								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.340	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
720080		NO. 3 ENGINE - T/C HARNESS								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.340	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
721001		NO. 1 ENGINE - PRESERVATION OF ENGINE								Service ATA:72
	MOS/MSC	29-Mar-91	O/C							
	HRS	0								
WC#: 72.350	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
721001		NO. 2 ENGINE - PRESERVATION OF ENGINE								Service ATA:72
	MOS/MSC	30-Mar-91	O/C							
	HRS	0								
WC#: 72.350	ENC	0								
					PROC. REF: LMM 72-00-00					
721001		NO. 3 ENGINE - PRESERVATION OF ENGINE								Service ATA:72
	MOS/MSC	30-Mar-91	O/C							
	HRS	0								
WC#: 72.350	ENC	0								
					PROC. REF: LMM 72-00-00					
721002		NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK								Service ATA:72
	MOS/MSC	29-Mar-91	O/C							
	HRS	0								
WC#: 72.360	ENC	0								
					PROC. REF: LMM 72-00-00					
721002		NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	O/C							
	HRS	0								
WC#: 72.360	ENC	0								
					PROC. REF: LMM 72-00-00					
721002		NO. 3 ENGINE - PERFORM ENGINE PRESERVATION CHECK								Service ATA:72
	MOS/MSC	30-Mar-91	O/C							
	HRS	0								
WC#: 72.360	ENC	0								
					PROC. REF: LMM 72-00-00					
721003		NO. 1 ENGINE - DEPRESERVATION OF ENGINE								Service ATA:72
	MOS/MSC	29-Mar-91	O/C							
	HRS	0								
WC#: 72.370	ENC	0								
					PROC. REF: LMM 72-00-00					
721003		NO. 2 ENGINE - DEPRESERVATION OF ENGINE								Service ATA:72
	MOS/MSC	30-Mar-91	O/C							
	HRS	0								
WC#: 72.370	ENC	0								
					PROC. REF: LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
721003		NO. 3 ENGINE - DEPRESERVATION OF ENGINE								Service ATA:72
	MOS/MSC	30-Mar-91	O/C							
	HRS	0								
WC#: 72.370	ENC	0								
					PROC. REF: LMM 72-00-00					
721010		NO. 1 ENGINE - LOW PRESSURE ROTOR THRUST BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
721010		NO. 2 ENGINE - LOW PRESSURE ROTOR THRUST BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
721010		NO. 3 ENGINE - LOW PRESSURE ROTOR THRUST BALL BEARING								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
723110		NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)								Service ATA:72
	MOS	17-Aug-07								
	HRS	6137.4	4200 (+200)		(10337.4) 10626.1	10537.4	1634 (+200)			
WC#: 72.010	ENC	3754								
					PROC. REF: GENERIC NO REF, LMM 72-00-00					
723110		NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)								Service ATA:72
	MOS	06-Feb-14								
	HRS	7993.6	4200 (+200)		(12193.6) 12306.6	12393.6	3314.5 (+200)			
WC#: 72.010	ENC	5148								
					PROC. REF: GENERIC NO REF, LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
723110		NO. 3 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)								Service ATA:72
	MOS	20-Jun-08								
	HRS	6666.6	4200 (+200)		(10866.6) 10997.3	11066.6	2005.2 (+200)			
WC#: 72.010	ENC	4141								
					PROC. REF: GENERIC NO REF, LMM 72-00-00					
724110		NO. 1 ENGINE - COMBUSTION PLENUM CASE								Component ATA:72
PN:3072443-4	MOS/MSC	27-Jul-07	O/C	TSO 0						
SN:2P-13314	HRS			TSO 0						
WC#: 72.020	ENC									
					PROC. REF: GENERIC NO REF					
724110		NO. 2 ENGINE - COMBUSTION PLENUM CASE								Component ATA:72
PN:3072443-4	MOS/MSC	27-Jan-01	O/C							
SN:0P24675	HRS	3986		TSN 5708						
WC#: 72.020	ENC	2513								
	(AFL)			TSN 4215						
					PROC. REF: GENERIC NO REF					
724110		NO. 3 ENGINE - COMBUSTION PLENUM CASE								Component ATA:72
PN:3072443-4	MOS/MSC	30-Mar-91	O/C							
SN:0P19331	HRS	0		TSN 0						
WC#: 72.020	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
724120		NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE								Service ATA:72
	MOS	19-Dec-11								
	HRS	7512.1	1400 (+100)		(8912.1) 9200.8	9012.1	208.7 (+100)			
WC#: 72.030	ENC	4826								
					PROC. REF: LMM 72-40-04					
724120		NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE								Service ATA:72
	MOS	06-Feb-14								
	HRS	7993.6	1400 (+100)		(9393.6) 9506.6	9493.6	514.5 (+100)			
WC#: 72.030	ENC	5148								
					PROC. REF: LMM 72-40-04					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
724120		NO. 3 ENGINE - INSPECT COMBUSTION PLENUM CASE								Service ATA:72
	MOS	13-Dec-13								
	HRS	7961.7	1400 (+100)		(9361.7) 9492.4	9461.7	500.3 (+100)			
WC#: 72.030	ENC	5141								
					PROC. REF: LMM 72-40-04					
725010		NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC								Component ATA:72
PN:3075831-1	MOS	13-Jun-07		TSN 0				LIFE LIMIT		
SN:060322905285	HRS	6137.4		TSN 0						
WC#: 72.040	ENC	3754	3000	TSN 0	(6754) 6754		958			
	(AFL)									
					PROC. REF: LMM 72-50-04					
725010		NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC								Component ATA:72
PN:3075830-1	MOS	20-Jun-08		TSN 0				LIFE LIMIT		
SN:08-03229-00963	HRS	6698.5		TSN 0						
WC#: 72.040	ENC	4134	3000	TSN 0	(7134) 7226		1430			
					PROC. REF: LMM 72-50-04					
725010		NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC								Component ATA:72
PN:3075830-1	MOS	16-Jun-08						LIFE LIMIT		
SN:08-03229-00975	HRS									
WC#: 72.040	ENC	4141	3000	TSN 0	(7141) 7229		1433			
					PROC. REF: LMM 72-50-04					
725020		NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC								Component ATA:72
PN:3072542-5	MOS	19-Dec-11		TSN 0				LIFE LIMIT		
SN:1118244902492	HRS	7512.1		TSN 0						
WC#: 72.050	ENC	4826	3000	TSN 0	(7826) 7826		2030			
					PROC. REF: LMM 72-50-04					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725020		NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC								Component ATA:72
PN:3072542-5	MOS	13-Dec-13		TSN 0				LIFE LIMIT		
SN:12-182449-06985	HRS	7993.6		TSN 0						
WC#: 72.050	ENC	5148	3000	TSN 0	(8148) 8240		2444			
					PROC. REF: LMM 72-50-04					
725020		NO. 3 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC								Component ATA:72
PN:3072542-5	MOS	06-Dec-13		TSN 0				LIFE LIMIT		
SN:12-182449-06989	HRS	7961.7		TSN 0						
WC#: 72.050	ENC	5141	3000	TSN 0	(8141) 8229		2433			
					PROC. REF: LMM 72-50-04					
725030		NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC								Component ATA:72
PN:3074096	MOS	02-Dec-00						LIFE LIMIT		
SN:975332201538	HRS			TSN 1196.2						
WC#: 72.060	ENC	2510	7000	TSN 579	(8931) 8931		3135			
	(AFL)									
					PROC. REF: LMM 72-50-04					
725030		NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC								Component ATA:72
PN:3074097-1	MOS	27-Jan-01						LIFE LIMIT		
SN:975332200375	HRS	3986		TSN 1275						
WC#: 72.060	ENC	2513	7000	TSN 621	(8892) 8984		3188			
	(AFL)									
					PROC. REF: LMM 72-50-04					
725030		NO. 3 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC								Component ATA:72
PN:3074096	MOS	21-Jun-98						LIFE LIMIT		
SN:975332201470	HRS	2753.2		TSN 0						
WC#: 72.060	ENC	1931	7000	TSN 0	(8931) 9019		3223			
					PROC. REF: LMM 72-50-04					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725040		NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC								Component ATA:72
PN:3072314-3	MOS	28-Jul-15		TSR 0				LIFE LIMIT		
SN:9-03229-5277	HRS	7952.5		TSN 7952.5, TSR 0						
WC#: 72.070	ENC	5124	7000	TSN 5124, TSR 0	(7000) 7000		1204			
					PROC. REF: LMM 72-50-06					
725040		NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC								Component ATA:72
PN:3072314-2	MOS	30-Mar-91						LIFE LIMIT		
SN:9-032295292	HRS	0		TSN 0						
WC#: 72.070	ENC	0	7000	TSN 0	(7000) 7092		1296			
					PROC. REF: LMM 72-50-06					
725040		NO. 3 ENGINE - HIGH PRESSURE TURBINE DISC								Component ATA:72
PN:3072316-2	MOS	30-Mar-91						LIFE LIMIT		
SN:9-03229-5282	HRS	0		TSN 0						
WC#: 72.070	ENC	0	7000	TSN 0	(7000) 7088		1292			
					PROC. REF: LMM 72-50-06					
725045		NO. 1 ENGINE - HIGH PRESSURE ROTOR STEPPED SEAL PLATE								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.080	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
725045		NO. 2 ENGINE - HIGH PRESSURE ROTOR STEPPED SEAL PLATE								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.080	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
725045		NO. 3 ENGINE - HIGH PRESSURE ROTOR STEPPED SEAL PLATE								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	N/A	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.080	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725050		NO. 1 ENGINE - FAN ROTOR DISC								Component ATA:72
PN:3073563-2	MOS	21-Jun-98						LIFE LIMIT		
SN:970322901832	HRS	2753.2		TSN 0						
WC#: 72.090	ENC	1931	10000	TSN 0	(11931) 11931		6135			
	(AFL)									
					PROC. REF: LMM 72-70-03					
725050		NO. 2 ENGINE - FAN ROTOR DISC								Component ATA:72
PN:3073570-4	MOS	27-Jan-01						LIFE LIMIT		
SN:970322902459	HRS	3986		TSN 1275						
WC#: 72.090	ENC	2513	10000	TSN 621	(11892) 11984		6188			
	(AFL)									
					PROC. REF: LMM 72-70-03					
725050		NO. 3 ENGINE - FAN ROTOR DISC								Component ATA:72
PN:3073563-2	MOS	21-Jun-98						LIFE LIMIT		
SN:960322905749	HRS	2753.2		TSN 0						
WC#: 72.090	ENC	1931	10000	TSN 0	(11931) 12019		6223			
					PROC. REF: LMM 72-70-03					
725060		NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3072395-2	MOS	29-Mar-91						LIFE LIMIT		
SN:0-03160-331	HRS	0		TSN 0						
WC#: 72.100	ENC	0	10000	TSN 0	(10000) 10000		4204			
					PROC. REF: LMM 72-30-04					
725060		NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3070440-10	MOS	27-Jan-01						LIFE LIMIT		
SN:000316002718	HRS	3986		TSN 0						
WC#: 72.100	ENC	2513	10000	TSN 0	(12513) 12605		6809			
					PROC. REF: LMM 72-30-04					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725060		NO. 3 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3072395-2	MOS	30-Mar-91						LIFE LIMIT		
SN:0-03160-287	HRS	0		TSN 0						
WC#: 72.100	ENC	0	10000	TSN 0	(10000) 10088		4292			
					PROC. REF: LMM 72-30-04					
725070		NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3072416-10	MOS	28-Jul-15		TSR 0				LIFE LIMIT		
SN:0-03160-747	HRS	7952.5		TSN 7952.5, TSR 0						
WC#: 72.110	ENC	5124	10000	TSN 5124, TSR 0	(10000) 10000		4204			
					PROC. REF: LMM 72-30-04					
725070		NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3072416-5	MOS	30-Mar-91						LIFE LIMIT		
SN:0-03160-792	HRS	0		TSN 0						
WC#: 72.110	ENC	0	10000	TSN 0	(10000) 10092		4296			
					PROC. REF: LMM 72-30-04					
725070		NO. 3 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3072396-3	MOS	21-Jun-08						LIFE LIMIT		
SN:0-03160-817	HRS	2700.7		TSN 2700.7						
WC#: 72.110	ENC	1890	10000	TSN 1890	(10000) 10088		4292			
					PROC. REF: LMM 72-30-04					
725071		NO. 1 ENGINE - COMBUSTION LINER								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.310	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
725071		NO. 2 ENGINE - COMBUSTION LINER								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.310	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725071		NO. 3 ENGINE - COMBUSTION LINER								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.310	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
725080		NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3072417-5	MOS	28-Jul-15		TSR 0				LIFE LIMIT		
SN:0-12112-904	HRS	7952.5		TSN 7952.5, TSR 0						
WC#: 72.120	ENC	5124	10000	TSN 5124, TSR 0	(10000) 10000		4204			
					PROC. REF: LMM 72-30-04					
725080		NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3072417-5	MOS	30-Mar-91						LIFE LIMIT		
SN:0-12112-229	HRS	0		TSN 0						
WC#: 72.120	ENC	0	10000	TSN 0	(10000) 10092		4296			
					PROC. REF: LMM 72-30-04					
725080		NO. 3 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3072397-3	MOS	30-Mar-91						LIFE LIMIT		
SN:0-12112-481	HRS	0		TSN 0						
WC#: 72.120	ENC	0	10000	TSN 0	(10000) 10088		4292			
	(AFL)			TSN 0						
					PROC. REF: LMM 72-30-04					
725090		NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3071652-12	MOS	28-Jul-15		TSR 0				LIFE LIMIT		
SN:9-03229-1605	HRS	7952.5		TSN 7952.5, TSR 0						
WC#: 72.130	ENC	5124	10000	TSN 5124, TSR 0	(10000) 10000		4204			
					PROC. REF: LMM 72-30-04					
725090		NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3071652-12	MOS	30-Mar-91						LIFE LIMIT		
SN:0-03229-1625	HRS	0		TSN 0						
WC#: 72.130	ENC	0	10000	TSN 0	(10000) 10092		4296			
					PROC. REF: LMM 72-30-04					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725090		NO. 3 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC								Component ATA:72
PN:3072398-2	MOS	30-Mar-91						LIFE LIMIT		
SN:0-03229-1655	HRS	0		TSN 0						
WC#: 72.130	ENC	0	10000	TSN 0	(10000) 10088		4292			
					PROC. REF: LMM 72-30-04					
725091		NO. 1 ENGINE - LOW PRESSURE TIE ROD								Component ATA:72
PN:3073049-1	MOS/MSC	29-Mar-91	O/C							
SN:0P24488	HRS	0		TSN 0						
WC#: 72.140	ENC	0		TSN 0						
					PROC. REF: LMM 72-30-10					
725091		NO. 2 ENGINE - LOW PRESSURE TIE ROD								Component ATA:72
PN:3073049-1	MOS/MSC	30-Mar-91	O/C							
SN:0P24493	HRS	0		TSN 0						
WC#: 72.140	ENC	0		TSN 0						
	(AFL)			TSN 0						
					PROC. REF: LMM 72-30-10					
725091		NO. 3 ENGINE - LOW PRESSURE TIE ROD								Component ATA:72
PN:3073049-1	MOS/MSC	30-Mar-91	O/C							
SN:0P24451	HRS	0		TSN 0						
WC#: 72.140	ENC	0		TSN 0						
					PROC. REF: LMM 72-30-10					
725110		NO. 1 ENGINE - HIGH PRESSURE IMPELLER								Component ATA:72
PN:3073398-2	MOS	29-Mar-91						LIFE LIMIT		
SN:0-23315-1013	HRS	0								
WC#: 72.150	ENC	0	10000	TSN 0	(10000) 10000		4204			
					PROC. REF: GENERIC NO REF					
725110		NO. 2 ENGINE - HIGH PRESSURE IMPELLER								Component ATA:72
PN:3073398-2	MOS	30-Mar-91						LIFE LIMIT		
SN:0-023315-988	HRS	0		TSN 0						
WC#: 72.150	ENC	0	10000	TSN 0	(10000) 10092		4296			
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725110		NO. 3 ENGINE - HIGH PRESSURE IMPELLER								Component ATA:72
PN:3073398-2	MOS	30-Mar-91						LIFE LIMIT		
SN:0-23315-1041	HRS	0		TSN 0						
WC#: 72.150	ENC	0	10000	TSN 0	(10000) 10088		4292			
					PROC. REF: GENERIC NO REF					
725120		NO. 1 ENGINE - ROTATING SEAL								Component ATA:72
PN:3072729-1	MOS/MSC	04-Jun-07	O/C	TSN 0						
SN:4-23151-1098	HRS			TSN 0						
WC#: 72.160	ENC									
					PROC. REF: GENERIC NO REF					
725120		NO. 2 ENGINE - ROTATING SEAL								Component ATA:72
PN:3072729-1	MOS/MSC	27-Jan-01	O/C							
SN:2-23151-513	HRS	3986		TSN 2870						
WC#: 72.160	ENC	2513		TSN 2588						
					PROC. REF: GENERIC NO REF					
725120		NO. 3 ENGINE - ROTATING SEAL								Component ATA:72
PN:3072729-1	MOS/MSC	21-Jun-98	O/C							
SN:3-23151-302	HRS	2753.2								
WC#: 72.160	ENC	1931								
					PROC. REF: GENERIC NO REF					
725130		NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT								Component ATA:72
PN:3072545-1	MOS	29-Mar-91						LIFE LIMIT		
SN:1P5432	HRS	0		TSN 0						
WC#: 72.170	ENC	0	12000	TSN 0	(12000) 12000		6204			
					PROC. REF: GENERIC NO REF					
725130		NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT								Component ATA:72
PN:3072545-1	MOS	30-Mar-91						LIFE LIMIT		
SN:1P5443	HRS	0		TSN 0						
WC#: 72.170	ENC	0	12000	TSN 0	(12000) 12092		6296			
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725130		NO. 3 ENGINE - HIGH PRESSURE SHOULDERED SHAFT								Component ATA:72
PN:3072545-1	MOS	30-Mar-91						LIFE LIMIT		
SN:0P22234	HRS	0		TSN 0						
WC#: 72.170	ENC	0	12000	TSN 0	(12000) 12088		6292			
					PROC. REF: GENERIC NO REF					
725140		NO. 1 ENGINE - HIGH PRESSURE ROTOR SEAL PLATE								Component ATA:72
PN:3072411-1	MOS	29-Mar-91						LIFE LIMIT		
SN:0-03160-1090	HRS	0		TSN 0						
WC#: 72.180	ENC	0	10000	TSN 0	(10000) 10000		4204			
					PROC. REF: GENERIC NO REF					
725140		NO. 2 ENGINE - HIGH PRESSURE ROTOR SEAL PLATE								Component ATA:72
PN:3072411-1	MOS	30-Mar-91						LIFE LIMIT		
SN:0-03160-1082	HRS	0		TSN 0						
WC#: 72.180	ENC	0	10000	TSN 0	(10000) 10092		4296			
					PROC. REF: GENERIC NO REF					
725140		NO. 3 ENGINE - HIGH PRESSURE ROTOR SEAL PLATE								Component ATA:72
PN:3072411-1	MOS	30-Mar-91						LIFE LIMIT		
SN:0-03160-1086	HRS	0		TSN 0						
WC#: 72.180	ENC	0	10000	TSN 0	(10000) 10088		4292			
					PROC. REF: GENERIC NO REF					
725150		NO. 1 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:3071955-3	MOS/MSC	29-Mar-91	O/C							
SN:1P4899	HRS	0		TSN 0						
WC#: 72.190	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
725150		NO. 2 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:3071607-10	MOS/MSC	30-Mar-91	O/C							
SN:1P-4885	HRS	0		TSN 0						
WC#: 72.190	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725150		NO. 3 ENGINE - FAN DRIVE SHAFT								Component ATA:72
PN:3071955-3	MOS/MSC	30-Mar-91	O/C							
SN:1P4898	HRS	0		TSN 0						
WC#: 72.190	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
725160		NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								Component ATA:72
PN:3072318	MOS/MSC	21-Jun-98	O/C							
SN:UNKNOWN	HRS	2753.2								
WC#: 72.200	ENC	1931								
					PROC. REF: LMM 72-50-05					
725160		NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								Component ATA:72
PN:3072318-5	MOS/MSC	27-Jan-01	O/C							
SN:00P05721	HRS	3986		TSN 0						
WC#: 72.200	ENC	2513		TSN 0						
					PROC. REF: LMM 72-50-05					
725160		NO. 3 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								Component ATA:72
PN:3072318	MOS/MSC	21-Jun-98	O/C							
SN:UNKNOWN	HRS	2753.2								
WC#: 72.200	ENC	1931								
					PROC. REF: LMM 72-50-05					
725170		NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE ROTATING SEAL PLATE								Component ATA:72
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.210	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
725170		NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE ROTATING SEAL PLATE								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.210	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
725170		NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE ROTATING SEAL PLATE								Component ATA:72
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 72.210	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725180		NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE								Component ATA:72
PN:3072319-11	MOS/MSC	26-Jul-07	O/C	TSN 0						
SN:07P06294	HRS			TSN 0						
WC#: 72.220	ENC									
					PROC. REF: GENERIC NO REF					
725180		NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE								Component ATA:72
PN:3072319-11	MOS/MSC	30-Mar-91	O/C							
SN:0-01344-727	HRS	0		TSN 0						
WC#: 72.220	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
725180		NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE								Component ATA:72
PN:3072319	MOS/MSC	21-Jun-98	O/C							
SN:UNKNOWN	HRS	2753.2								
WC#: 72.220	ENC	1931								
					PROC. REF: GENERIC NO REF					
725190		NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL								Component ATA:72
PN:3073765-5	MOS/MSC	09-Dec-11	O/C							
SN:03P02514	HRS	7512.1		TSN 115.8						
WC#: 72.230	ENC	4826		TSN 93						
					PROC. REF: GENERIC NO REF					
725190		NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL								Component ATA:72
PN:3073765-3	MOS/MSC	27-Jan-01	O/C							
SN:3-03405-925	HRS	3986		TSN 3440						
WC#: 72.230	ENC	2513		TSN 2152						
					PROC. REF: GENERIC NO REF					
725190		NO. 3 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL								Component ATA:72
PN:3073355	MOS/MSC	21-Jun-98	O/C							
SN:UNKNOWN	HRS	2753.2								
WC#: 72.230	ENC	1931								
					PROC. REF: GENERIC NO REF					
725191		NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT								Component ATA:72
PN:3073764-3	MOS/MSC	09-Dec-11	O/C							
SN:03P00585	HRS	7512.1		TSN 115.8						
WC#: 72.240	ENC	4826		TSN 93						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
725191		NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT								Component ATA:72
PN:3073764-3	MOS/MSC	27-Jan-01	O/C							
SN:3-03405-964	HRS	3986		TSN 3440						
WC#: 72.240	ENC	2513		TSN 2152						
					PROC. REF: GENERIC NO REF					
725191		NO. 3 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT								Component ATA:72
PN:3073355	MOS/MSC	21-Jun-98	O/C							
SN:UNKNOWN	HRS	2753.2								
WC#: 72.240	ENC	1931								
					PROC. REF: GENERIC NO REF					
726110		NO. 1 ENGINE - ACCESSORY GEARBOX								Component ATA:72
PN:3070003-11	MOS/MSC	29-Mar-91	O/C							
SN:P5813	HRS	0		TSN 0						
WC#: 72.250	ENC	0		TSN 0						
					PROC. REF: LMM 72-60-01					
726110		NO. 2 ENGINE - ACCESSORY GEARBOX								Component ATA:72
PN:3070003-26	MOS/MSC	30-Mar-91	O/C							
SN:P-5812	HRS	0		TSN 0						
WC#: 72.250	ENC	0		TSN 0						
					PROC. REF: LMM 72-60-01					
726110		NO. 3 ENGINE - ACCESSORY GEARBOX								Component ATA:72
PN:3070003-11	MOS/MSC	30-Mar-91	O/C							
SN:P5840	HRS	0		TSN 0						
WC#: 72.250	ENC	0		TSN 0						
					PROC. REF: LMM 72-60-01					
726120		NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX								Service ATA:72
PN:3070003-11	MOS	26-Jul-07								
SN:P5813	HRS	6137.4	4200 (+200)		(10337.4) 10626.1	10537.4	1634 (+200)			
WC#: 72.260	ENC	3754								
					PROC. REF: LMM 72-60-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
726120		NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX								Service ATA:72
PN:3070003-26	MOS	06-Feb-14								
SN:P-5812	HRS	7993.6	4200 (+200)		(12193.6) 12306.6	12393.6	3314.5 (+200)			
WC#: 72.260	ENC	5148								
					PROC. REF: LMM 72-60-02					
726120		NO. 3 ENGINE - INSPECT ACCESSORY GEARBOX								Service ATA:72
PN:3070003-11	MOS	21-Aug-08								
SN:P5840	HRS	6666.6	4200 (+200)		(10866.6) 10997.3	11066.6	2005.2 (+200)			
WC#: 72.260	ENC	4141								
					PROC. REF: LMM 72-60-02					
726130		NO. 1 ENGINE - TRANSFER GEARBOX								Component ATA:72
PN:3070093-4	MOS/MSC	29-Mar-91	O/C							
SN:P6981	HRS	0		TSN 0						
WC#: 72.270	ENC	0		TSN 0						
					PROC. REF: LMM 72-60-01					
726130		NO. 2 ENGINE - TRANSFER GEARBOX								Component ATA:72
PN:3070093-12	MOS/MSC	30-Mar-91	O/C							
SN:P6979	HRS	0		TSN 0						
WC#: 72.270	ENC	0		TSN 0						
					PROC. REF: LMM 72-60-01					
726130		NO. 3 ENGINE - TRANSFER GEARBOX								Component ATA:72
PN:3070093-4	MOS/MSC	30-Mar-91	O/C							
SN:P6980	HRS	0		TSN 0						
WC#: 72.270	ENC	0		TSN 0						
					PROC. REF: LMM 72-60-01					
726310		NO. 1 ENGINE - INSPECT STARTER/GENERATOR ACCESSORY DRIVE SPLINE								Service ATA:72
	MOS	19-Dec-11						PART OF MPI		
	HRS	7512.1	1400 (+100)		(8912.1) 9200.8	9012.1	208.7 (+100)			
WC#: 72.280	ENC	4826								
					PROC. REF: LMM 72-60-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
726310		NO. 2 ENGINE - INSPECT STARTER/GENERATOR ACCESSORY DRIVE SPLINE								Service ATA:72
	MOS	24-Dec-13						PART OF MPI		
	HRS	7993.6	1400 (+100)		(9393.6) 9506.6	9493.6	514.5 (+100)			
WC#: 72.280	ENC	5148								
					PROC. REF: LMM 72-60-01					
726310		NO. 3 ENGINE - INSPECT STARTER/GENERATOR ACCESSORY DRIVE SPLINE								Service ATA:72
	MOS	13-Dec-13						PART OF MPI		
	HRS	7961.7	1400 (+100)		(9361.7) 9492.4	9461.7	500.3 (+100)			
WC#: 72.280	ENC	5141								
					PROC. REF: LMM 72-60-01					
726320[S]		NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX ALTERNATOR ACCESSORY DRIVE SPLINE								Service ATA:72
PN:3070003-11	MOS	07-Jul-23								
SN:P5813	HRS	8674.8	200 (+50)							
WC#: 72.290	ENC	5769								
					PROC. REF: LMM 72-60-01					PKG:0
726320[S]		NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX ALTERNATOR ACCESSORY DRIVE SPLINE								Service ATA:72
PN:3070003-26	MOS	10-Jan-23								
SN:P-5812	HRS	8781.4	150 (+100)							
WC#: 72.290	ENC	5622								
					PROC. REF: LMM 72-60-01					PKG:0
726320[S]		NO. 3 ENGINE - INSPECT ACCESSORY GEARBOX ALTERNATOR ACCESSORY DRIVE SPLINE								Service ATA:72
PN:3070003-11	MOS	10-Jan-23								
SN:P5840	HRS	8763.7	150 (+100)							
WC#: 72.290	ENC	5626								
					PROC. REF: LMM 72-60-01					PKG:0
727110		NO. 1 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY								Service ATA:72
	MOS	13-Jun-07								
	HRS	6137.4	4200 (+200)		(10337.4) 10626.1	10537.4	1634 (+200)			
WC#: 72.300	ENC	3754								
					PROC. REF: LMM 72-70-06					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
727110		NO. 2 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY								Service ATA:72
	MOS	24-Dec-13								
	HRS	7993.6	4200 (+200)		(12193.6) 12306.6	12393.6	3314.5 (+200)			
WC#: 72.300	ENC	5148								
					PROC. REF: LMM 72-70-06					
727110		NO. 3 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY								Service ATA:72
	MOS	20-Jun-08								
	HRS	6666.6	4200 (+200)		(10866.6) 10997.3	11066.6	2005.2 (+200)			
WC#: 72.300	ENC	4141								
					PROC. REF: LMM 72-70-06					
ATA 73 - ENGINE FUEL AND CONTROL										
73-10-01.1		NO. 1 ENGINE - FUEL MANIFOLD								Component ATA:73
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-01					
73-10-01.1		NO. 2 ENGINE - FUEL MANIFOLD								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-01					
73-10-01.1		NO. 3 ENGINE - FUEL MANIFOLD								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-01					
73-10-01.2		NO. 1 ENGINE - FUEL MANIFOLD CHECK AND REPAIRS								Service ATA:73
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-10-01.2		NO. 2 ENGINE - FUEL MANIFOLD CHECK AND REPAIRS								Service ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-01					
73-10-01.2		NO. 3 ENGINE - FUEL MANIFOLD CHECK AND REPAIRS								Service ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-01					
73-10-02.1		NO. 1 ENGINE - FUEL AND P3 SENSING LINES								Component ATA:73
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-02					
73-10-02.1		NO. 2 ENGINE - FUEL AND P3 SENSING LINES								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-02					
73-10-02.1		NO. 3 ENGINE - FUEL AND P3 SENSING LINES								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-02					
73-10-03.1		NO. 1 ENGINE - SERVICE TUBES CLAMP AND TUBES								Component ATA:73
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-03					
73-10-03.1		NO. 2 ENGINE - SERVICE TUBES CLAMP AND TUBES								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-03					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-10-03.1		NO. 3 ENGINE - SERVICE TUBES CLAMP AND TUBES								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-03					
73-10-03.2		NO. 1 ENGINE - SERVICE TUBES CLAMP AND TUBES CHECK AND REPAIR								Service ATA:73
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-03					
73-10-03.2		NO. 2 ENGINE - SERVICE TUBES CLAMP AND TUBES CHECK AND REPAIR								Service ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-03					
73-10-03.2		NO. 3 ENGINE - SERVICE TUBES CLAMP AND TUBES CHECK AND REPAIR								Service ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-03					
73-10-04.2		NO. 1 ENGINE - FUEL HEATER CHECK AND REPAIR								Service ATA:73
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-04					
73-10-04.2		NO. 2 ENGINE - FUEL HEATER CHECK AND REPAIR								Service ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-04					
73-10-04.2		NO. 3 ENGINE - FUEL HEATER CHECK AND REPAIR								Service ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-04					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-10-05.1		NO. 1 ENGINE - CHECK VALVE								Component ATA:73
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-05					
73-10-05.1		NO. 2 ENGINE - CHECK VALVE								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-05					
73-10-05.1		NO. 3 ENGINE - CHECK VALVE								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-05					
73-10-05.2		NO. 1 ENGINE - CHECK VALVE CHECKS AND REPAIRS								Service ATA:73
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-05					
73-10-05.2		NO. 2 ENGINE - CHECK VALVE CHECKS AND REPAIRS								Service ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-05					
73-10-05.2		NO. 3 ENGINE - CHECK VALVE CHECKS AND REPAIRS								Service ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-10-05					
73-20-01-710-802-01		OPERATIONAL TEST OF THE ENGINE 1 DIGITAL ELECTRONIC COMPUTER (DEEC 1) DUAL POWER SUPPLY								Service ATA:73
	MOS/MSC	24-Oct-91	N/A							
	HRS	0								
WC#: 76.040	AFL	0								
					PROC. REF: AMM 73-20-01-710-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-20-01-710-802-01A	OPERATIONAL TEST OF THE ENGINE 1 DIGITAL ELECTRONIC COMPUTER (DEEC 1) DUAL POWER SUPPLY (MANDATORY 5-40)								Service	ATA:73
	MOS/MSC		N/A							
	HRS									
WC#: 76.040	AFL									
					PROC. REF: AMM 73-20-01-710-802					
73-20-01-900-801-01	NO. 1 ENGINE DIGITAL ELECTRONIC ENGINE CONTROL (DEEC 1) COMPUTER								Component	ATA:73
PN:2119020-1001	MOS/MSC	12-Apr-02	O/C							
SN:121-BJ0003	HRS	4249								
WC#: 73.070	AFL	2718								
					PROC. REF: AMM 73-20-01-900-801, AMM 73-20-01-900-801					
73-20-01-900-801-02	NO. 2 ENGINE DIGITAL ELECTRONIC ENGINE CONTROL (DEEC 2) COMPUTER								Component	ATA:73
PN:2119020-1001	MOS/MSC	12-Apr-02	O/C							
SN:50-AK0258	HRS	4249								
WC#: 73.070	AFL	2718								
					PROC. REF: AMM 73-20-01-900-801, AMM 73-20-01-900-801					
73-20-01-900-801-03	NO. 3 ENGINE DIGITAL ELECTRONIC ENGINE CONTROL (DEEC 3) COMPUTER								Component	ATA:73
PN:2119020-1001	MOS/MSC	12-Apr-02	O/C							
SN:121-BJ001	HRS	4249								
WC#: 73.070	AFL	2718								
					PROC. REF: AMM 73-20-01-900-801, AMM 73-20-01-900-801					
73-20-01.2	NO. 1 ENGINE - FUEL SYSTEM CHECK AND REPAIRS								Service	ATA:73
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-20-01					
73-20-01.2	NO. 2 ENGINE - FUEL SYSTEM CHECK AND REPAIRS								Service	ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-20-01					
73-20-01.2	NO. 3 ENGINE - FUEL SYSTEM CHECK AND REPAIRS								Service	ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-20-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-21-01.1		NO. 1 ENGINE - FUEL CONTROL COMPONENTS								Component ATA:73
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-21-01					
73-21-01.1		NO. 2 ENGINE - FUEL CONTROL COMPONENTS								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-21-01					
73-21-01.1		NO. 3 ENGINE - FUEL CONTROL COMPONENTS								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 73-21-01					
73-21-01.2		NO. 1 ENGINE - FUEL CONTROL CHECK AND REPAIRS								Service ATA:73
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-21-01					
73-21-01.2		NO. 2 ENGINE - FUEL CONTROL CHECK AND REPAIRS								Service ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-21-01					
73-21-01.2		NO. 3 ENGINE - FUEL CONTROL CHECK AND REPAIRS								Service ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-21-01					
73-21-02.2		NO. 1 ENGINE - FUEL PUMP CHECK AND REPAIRS								Service ATA:73
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-21-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-21-02.2		NO. 2 ENGINE - FUEL PUMP CHECK AND REPAIRS							Service	ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-21-02					
73-21-02.2		NO. 3 ENGINE - FUEL PUMP CHECK AND REPAIRS							Service	ATA:73
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 73-21-02					
73-30-09-900-801-01		REMOVAL / INSTALLATION OF THE FUEL FLOWMETERS - ENGINE 1 FUEL FLOWMETER (L103E)							Component	ATA:73
PN:9-127-27	MOS/MSC	02-Sep-04	O/C	TSR 0						
SN:2045	HRS	5279.1		TSR 0						
WC#: 73.090	AFL	3245		TSR 0						
					PROC. REF: AMM 73-30-09-900-801					
73-30-09-900-801-02		REMOVAL / INSTALLATION OF THE FUEL FLOWMETERS - ENGINE 2 FUEL FLOWMETER (M103E)							Component	ATA:73
PN:9-127-27	MOS/MSC	17-May-95	O/C							
SN:5857	HRS	1646		TSN 1602						
WC#: 73.090	AFL	1169		TSN 1142						
					PROC. REF: AMM 73-30-09-900-801					
73-30-09-900-801-03		REMOVAL / INSTALLATION OF THE FUEL FLOWMETERS - ENGINE 3 FUEL FLOWMETER (R103E)							Component	ATA:73
PN:9-127-27	MOS/MSC	02-Sep-04	O/C							
SN:5670	HRS	5279.1		TSN 5279.1						
WC#: 73.090	AFL	3245		TSN 3245						
					PROC. REF: AMM 73-30-09-900-801					
73-30-12-900-801-01		REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FUEL FLOW 1 INDICATOR METER (102E1)							Component	ATA:73
PN:9-328-01	MOS/MSC	24-Oct-91	O/C							
SN:2833	HRS	0		TSN 0						
WC#: 73.080	AFL	0								
					PROC. REF: AMM 73-30-12-900-801					
73-30-12-900-801-02		REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FUEL FLOW 2 INDICATOR METER (102E2)							Component	ATA:73
PN:9-328-01	MOS/MSC	24-Oct-91	O/C							
SN:2861	HRS	0		TSN 0						
WC#: 73.080	AFL	0								
					PROC. REF: AMM 73-30-12-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
73-30-12-900-801-03	REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FUEL FLOW 3 INDICATOR METER (102E3)									Component ATA:73
PN:9-328-01	MOS/MSC	24-Oct-91	O/C							
SN:2846	HRS	0		TSN 0						
WC#: 73.080	AFL	0								
					PROC. REF: AMM 73-30-12-900-801					
731020	NO. 1 ENGINE - FUEL MANIFOLD									Component ATA:73
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.130	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
731020	NO. 2 ENGINE - FUEL MANIFOLD									Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.130	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
731020	NO. 3 ENGINE - FUEL MANIFOLD									Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.130	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
731110	NO. 1 ENGINE - ENGINE FUEL PUMP									Component ATA:73
PN:3070850-28	MOS/MSC	21-Jun-98	O/C							
SN:MX16939	HRS	2753.2								
WC#: 73.010	ENC	1931								
					PROC. REF: LMM 73-21-02					
731110	NO. 2 ENGINE - ENGINE FUEL PUMP									Component ATA:73
PN:3070850-28	MOS/MSC	30-Mar-91	O/C							
SN:MX516940	HRS	0		TSN 0						
WC#: 73.010	ENC	0		TSN 0						
					PROC. REF: LMM 73-21-02					
731110	NO. 3 ENGINE - ENGINE FUEL PUMP									Component ATA:73
PN:3070850-28	MOS/MSC	30-Mar-91	O/C							
SN:MX516937	HRS	0		TSN 0						
WC#: 73.010	ENC	0		TSN 0						
					PROC. REF: LMM 73-21-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731120		NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT								Service ATA:73
	MOS	08-Sep-17								
	HRS	8153.7	600 (+50)		(8753.7) 9042.4	8803.7	50.3 (+50)			
WC#: 73.020	ENC	5242								
					PROC. REF: LMM 73-21-02					
731120		NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT								Service ATA:73
	MOS	10-Jan-23								
	HRS	8781.4	600 (+50)		(9381.4) 9494.4	9431.4	502.3 (+50)			
WC#: 73.020	ENC	5622								
					PROC. REF: LMM 73-21-02					
731120		NO. 3 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT								Service ATA:73
	MOS	10-Jan-23								
	HRS	8763.7	600 (+50)		(9363.7) 9494.4	9413.7	502.3 (+50)			
WC#: 73.020	ENC	5626								
					PROC. REF: LMM 73-21-02					
731130		NO. 1 ENGINE - FLOW DIVIDER/DRAIN VALVE								Component ATA:73
PN:394366-4	MOS/MSC	29-Mar-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.030	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
731130		NO. 2 ENGINE - FLOW DIVIDER/DRAIN VALVE								Component ATA:73
PN:394396-2-1	MOS/MSC	27-Jan-01	O/C							
SN:8145	HRS	3986								
WC#: 73.030	ENC	2513								
					PROC. REF: GENERIC NO REF					
731130		NO. 3 ENGINE - FLOW DIVIDER/DRAIN VALVE								Component ATA:73
PN:394366-4	MOS/MSC	30-Mar-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.030	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731140		NO. 1 ENGINE - FUEL HEATER								Component ATA:73
PN:158670-3	MOS/MSC	29-Mar-91	O/C							
SN:11-5654	HRS	0		TSN 0						
WC#: 73.040	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-04					
731140		NO. 2 ENGINE - FUEL HEATER								Component ATA:73
PN:158670-5	MOS/MSC	30-Mar-91	O/C							
SN:11-5662	HRS	0		TSN 0						
WC#: 73.040	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-04					
731140		NO. 3 ENGINE - FUEL HEATER								Component ATA:73
PN:158670-3	MOS/MSC	30-Mar-91	O/C							
SN:11-5655	HRS	0		TSN 0						
WC#: 73.040	ENC	0		TSN 0						
					PROC. REF: LMM 73-10-04					
731150		NO. 1 ENGINE - FUEL/OIL COOLER								Component ATA:73
PN:158610-8	MOS/MSC	29-Mar-91	O/C							
SN:49-7298	HRS	0		TSN 0						
WC#: 73.050	ENC	0		TSN 0						
					PROC. REF: LMM 79-20-07					
731150		NO. 2 ENGINE - FUEL/OIL COOLER								Component ATA:73
PN:158610-8	MOS/MSC	27-Jan-01	O/C							
SN:10-7487	HRS	3986								
WC#: 73.050	ENC	2513								
					PROC. REF: LMM 79-20-07					
731150		NO. 3 ENGINE - FUEL/OIL COOLER								Component ATA:73
PN:158610-8	MOS/MSC	30-Mar-91	O/C							
SN:49-7304	HRS	0		TSN 0						
WC#: 73.050	ENC	0		TSN 0						
					PROC. REF: LMM 79-20-07					
732110		NO. 1 ENGINE - FUEL CONTROL UNIT								Component ATA:73
PN:3070800-33	MOS/MSC	28-Jul-15	O/C	TSO 0						
SN:A8333C	HRS	7952.5		TSO 0						
WC#: 73.060	ENC	5124		TSO 0						
					PROC. REF: LMM 73-20-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
732110		NO. 2 ENGINE - FUEL CONTROL UNIT								Component ATA:73
PN:3070800-11	MOS/MSC	27-Jan-01	O/C							
SN:A10384	HRS	3986		TSN 4028						
WC#: 73.060	ENC	2513								
					PROC. REF: LMM 73-20-01					
732110		NO. 3 ENGINE - FUEL CONTROL UNIT								Component ATA:73
PN:3070800-33	MOS/MSC	29-Dec-16	O/C							
SN:15318	HRS	8252.6								
WC#: 73.060	ENC	5321								
					PROC. REF: LMM 73-20-01					
732120		NO. 1 ENGINE - PRESSURE LIMITER VALVE								Component ATA:73
PN:3070685-6	MOS/MSC	29-Mar-91	O/C							
SN:A10205	HRS	0		TSN 0						
WC#: 73.070	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
732120		NO. 2 ENGINE - PRESSURE LIMITER VALVE								Component ATA:73
PN:3070685-6	MOS/MSC	30-Mar-91	O/C							
SN:A10203	HRS	0		TSN 0						
WC#: 73.070	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
732120		NO. 3 ENGINE - PRESSURE LIMITER VALVE								Component ATA:73
PN:3070685-6	MOS/MSC	30-Mar-91	O/C							
SN:A10200	HRS	0		TSN 0						
WC#: 73.070	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
732130		NO. 1 ENGINE - SURGE BLEED VALVE								Component ATA:73
PN:978812-5-1	MOS/MSC	19-Dec-11	O/C	TSO 0						
SN:P-1265	HRS	7512.1		TSO 0						
WC#: 73.080	ENC	4826		TSO 0						
					PROC. REF: LMM 76-10-01					
732130		NO. 2 ENGINE - SURGE BLEED VALVE								Component ATA:73
PN:978812-5-1	MOS/MSC	13-Dec-04	O/C							
SN:8411	HRS	5335.8		TSO 0						
WC#: 73.080	ENC	3251		TSO 0						
					PROC. REF: LMM 76-10-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
732130		NO. 3 ENGINE - SURGE BLEED VALVE								Component ATA:73
PN:978812-5-1	MOS/MSC	10-Dec-04	O/C							
SN:9206	HRS	5303.9		TSO 0						
WC#: 73.080	ENC	3259								
					PROC. REF: LMM 76-10-01					
732140		NO. 1 ENGINE - SOLENOID CONTROL VALVE								Component ATA:73
PN:109696-4-1	MOS/MSC	05-Dec-20	O/C							
SN:7771	HRS	8421.5								
WC#: 73.090	ENC	5602								
					PROC. REF: LMM 76-10-01					
732140		NO. 2 ENGINE - SOLENOID CONTROL VALVE								Component ATA:73
PN:109696-4-1	MOS/MSC	30-Mar-91	O/C							
SN:7121	HRS	0		TSN 0						
WC#: 73.090	ENC	0		TSN 0						
					PROC. REF: LMM 76-10-01					
732140		NO. 3 ENGINE - SOLENOID CONTROL VALVE								Component ATA:73
PN:109696-4-1	MOS/MSC	30-Mar-91	O/C							
SN:7131	HRS	0		TSN 0						
WC#: 73.090	ENC	0		TSN 0						
					PROC. REF: LMM 76-10-01					
732150		NO. 1 ENGINE - FUEL CONTROL COMPUTER								Component ATA:73
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.100	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
732150		NO. 2 ENGINE - FUEL CONTROL COMPUTER								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.100	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
732150		NO. 3 ENGINE - FUEL CONTROL COMPUTER								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.100	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
732160		NO. 1 ENGINE - FUEL FLOW TRANSMITTER								Component ATA:73
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.120	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
732160		NO. 2 ENGINE - FUEL FLOW TRANSMITTER								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.120	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
732160		NO. 3 ENGINE - FUEL FLOW TRANSMITTER								Component ATA:73
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.120	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
ATA 74 - IGNITION										
741110		NO. 1 ENGINE - IGNITION UNIT								Component ATA:74
PN:3070378-2	MOS/MSC	31-Mar-08	O/C	TSO 0						
SN:92138364	HRS	6459		TSO 0						
WC#: 74.010	ENC									
					PROC. REF: LMM 74-00-01					
741110		NO. 2 ENGINE - IGNITION UNIT								Component ATA:74
PN:3073914-4	MOS/MSC	27-Jan-01	O/C							
SN:473041	HRS	3986								
WC#: 74.010	ENC	2513								
					PROC. REF: LMM 74-00-01					
741110		NO. 3 ENGINE - IGNITION UNIT								Component ATA:74
PN:3070378-1	MOS/MSC	30-Mar-91	O/C							
SN:5725	HRS	0		TSN 0						
WC#: 74.010	ENC	0		TSN 0						
					PROC. REF: LMM 74-00-01					
741120[S]		NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM								Service ATA:74
	MOS	19-Dec-11						PART OF MPI		
	HRS	7512.1	1400 (+100)							
WC#: 74.020	ENC	4826								
					PROC. REF: LMM 74-00-01					PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
741120[S]		NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM								Service ATA:74
	MOS	24-Dec-13						PART OF MPI		
	HRS	7993.6	1400 (+100)							
WC#: 74.020	ENC	5148								
					PROC. REF: LMM 74-00-01					PKG:0
741120[S]		NO. 3 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM								Service ATA:74
	MOS	13-Dec-13						PART OF MPI		
	HRS	7961.7	1400 (+100)							
WC#: 74.020	ENC	5141								
					PROC. REF: LMM 74-00-01					PKG:0
742110		NO. 1 ENGINE - 6 O'CLOCK IGNITER PLUG								Component ATA:74
PN:3074541-4	MOS/MSC	19-Dec-11	O/C	TSN 54						
SN:UNKNOWN	HRS	7512.1		TSN 1374.7						
WC#: 74.030	ENC	4826		TSN 0						
					PROC. REF: LMM 74-00-01					
742110		NO. 2 ENGINE - 6 O'CLOCK IGNITER PLUG								Component ATA:74
PN:CH31815	MOS/MSC	13-Dec-04	O/C							
SN:UNKNOWN	HRS	5335.8								
WC#: 74.030	ENC	3251								
					PROC. REF: LMM 74-00-01					
742110		NO. 3 ENGINE - 6 O'CLOCK IGNITER PLUG								Component ATA:74
PN:CH31814	MOS/MSC	10-Dec-04	O/C							
SN:UNKNOWN	HRS	5303.9		TSN 0						
WC#: 74.030	ENC	3259								
					PROC. REF: LMM 74-00-01					
742120[S]		NO. 1 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG/ LEAD TERMINALS								Service ATA:74
	MOS	19-Dec-11						PART OF MPI		
	HRS	7512.1	1400 (+100)							
WC#: 74.040	ENC	4826								
					PROC. REF: LMM 74-00-01					PKG:0
742120[S]		NO. 2 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG/ LEAD TERMINALS								Service ATA:74
	MOS	24-Dec-13						PART OF MPI		
	HRS	7993.6	1400 (+100)							
WC#: 74.040	ENC	5148								
					PROC. REF: LMM 74-00-01					PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
742120[S]		NO. 3 ENGINE - INSPECT 6 O'CLOCK IGNITER PLUG/ LEAD TERMINALS								Service ATA:74
	MOS	13-Dec-13						PART OF MPI		
	HRS	7961.7	1400 (+100)							
WC#: 74.040	ENC	5141								
					PROC. REF: LMM 74-00-01					PKG:0
742130		NO. 1 ENGINE - 7 O'CLOCK IGNITER PLUG								Component ATA:74
PN:3074541-4	MOS/MSC	19-Dec-11	O/C	TSN 0						
SN:UNKNOWN	HRS	7512.1		TSN 0						
WC#: 74.050	ENC	4826		TSN 0						
					PROC. REF: LMM 74-00-01					
742130		NO. 2 ENGINE - 7 O'CLOCK IGNITER PLUG								Component ATA:74
PN:CH31815	MOS/MSC	13-Dec-04	O/C							
SN:UNKNOWN	HRS	5335.8								
WC#: 74.050	ENC	3251								
					PROC. REF: LMM 74-00-01					
742130		NO. 3 ENGINE - 7 O'CLOCK IGNITER PLUG								Component ATA:74
PN:CH31814	MOS/MSC	10-Dec-04	O/C							
SN:UNKNOWN	HRS	5303.9		TSN 0						
WC#: 74.050	ENC	3259								
					PROC. REF: LMM 74-00-01					
742140[S]		NO. 1 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG/ LEAD TERMINALS								Service ATA:74
	MOS	19-Dec-11						PART OF MPI		
	HRS	7512.1	1400 (+100)							
WC#: 74.060	ENC	4826								
					PROC. REF: LMM 74-00-01					PKG:0
742140[S]		NO. 2 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG/ LEAD TERMINALS								Service ATA:74
	MOS	24-Dec-13						PART OF MPI		
	HRS	7993.6	1400 (+100)							
WC#: 74.060	ENC	5148								
					PROC. REF: LMM 74-00-01					PKG:0
742140[S]		NO. 3 ENGINE - INSPECT 7 O'CLOCK IGNITER PLUG/ LEAD TERMINALS								Service ATA:74
	MOS	13-Dec-13						PART OF MPI		
	HRS	7961.7	1400 (+100)							
WC#: 74.060	ENC	5141								
					PROC. REF: LMM 74-00-01					PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 75 - AIR										
75-10-01.2		NO. 1 ENGINE - [WITH ANTI-ICE] ANTI-ICE VALVE CHECK AND REPAIRS								Service ATA:75
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 75-10-01					
75-10-01.2		NO. 2 ENGINE - [WITH ANTI-ICE] ANTI-ICE VALVE CHECK AND REPAIRS								Service ATA:75
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 75-10-01					
75-10-01.2		NO. 3 ENGINE - [WITH ANTI-ICE] ANTI-ICE VALVE CHECK AND REPAIRS								Service ATA:75
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 75-10-01					
75-10-05.1		NO. 1 ENGINE - BLEED AIR DUCT								Component ATA:75
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 75-10-05					
75-10-05.1		NO. 2 ENGINE - BLEED AIR DUCT								Component ATA:75
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 75-10-05					
75-10-05.1		NO. 3 ENGINE - BLEED AIR DUCT								Component ATA:75
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 75-10-05					
75-10-05.2		NO. 1 ENGINE - BLEED AIR DUCT CHECK AND REPAIRS								Service ATA:75
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 75-10-05					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 75 - AIR										
75-10-05.2		NO. 2 ENGINE - BLEED AIR DUCT CHECK AND REPAIRS								Service ATA:75
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 75-10-05					
75-10-05.2		NO. 3 ENGINE - BLEED AIR DUCT CHECK AND REPAIRS								Service ATA:75
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 75-10-05					
75-40-01.1		NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR								Component ATA:75
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 75-40-01					
75-40-01.1		NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR								Component ATA:75
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 75-40-01					
75-40-01.1		NO. 3 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR								Component ATA:75
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 75-40-01					
75-40-01.2		NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR CHECK AND REPAIRS								Service ATA:75
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 75-40-01					
75-40-01.2		NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR CHECK AND REPAIRS								Service ATA:75
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 75-40-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 75 - AIR										
75-40-01.2		NO. 3 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR CHECK AND REPAIRS							Service	ATA:75
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 75-40-01					
751010		NO. 1 ENGINE - ANTI-ICE SHUTOFF VALVE							Component	ATA:75
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 75.010	ENC	0		TSN 0						
					PROC. REF: LMM 75-10-01					
751010		NO. 2 ENGINE - ANTI-ICE SHUTOFF VALVE							Component	ATA:75
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 75.010	ENC	0		TSN 0						
					PROC. REF: LMM 75-10-01					
751010		NO. 3 ENGINE - ANTI-ICE SHUTOFF VALVE							Component	ATA:75
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 75.010	ENC	0		TSN 0						
					PROC. REF: LMM 75-10-01					
ATA 76 - ENGINE CONTROLS										
76-10-00-220-801-01		CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 1							Service	ATA:76
PN:7-43497-1	MOS/MSC	09-Mar-18	O/C							
SN:233	HRS	8497.6								
WC#: 76.020	AFL	5470								
					PROC. REF: AMM 76-10-00-220-801					
76-10-00-220-801-02		CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 2							Service	ATA:76
PN:7-43497-2	MOS/MSC	09-Mar-18	O/C							
SN:257	HRS	8497.6								
WC#: 76.030	AFL	5470								
					PROC. REF: AMM 76-10-00-220-801					
76-10-00-220-801-03		CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 3							Service	ATA:76
PN:7-43497-3	MOS/MSC	09-Mar-18	O/C							
SN:257	HRS	8497.6								
WC#: 76.020	AFL	5470								
					PROC. REF: AMM 76-10-00-220-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
76-10-00-220-802-01	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 1									Service ATA:76
PN:7-43497-1	MOS/MSC	21-Aug-08	O/C							
SN:233	HRS	6797.3								
WC#: 76.020	AFL	4227								
					PROC. REF: AMM 76-10-00-220-802					
76-10-00-220-802-02	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 2									Service ATA:76
PN:7-43497-2	MOS/MSC	21-Aug-08	O/C							
SN:257	HRS	6797.3								
WC#: 76.030	AFL	4227								
					PROC. REF: AMM 76-10-00-220-802					
76-10-00-220-802-03	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 3									Service ATA:76
PN:7-43497-3	MOS/MSC	15-Dec-11	O/C							
SN:257	HRS	7712.7								
WC#: 76.020	AFL	4979								
					PROC. REF: AMM 76-10-00-220-802					
76-10-01.2	NO. 1 ENGINE - SURGE BLEED VALVE CHECK AND REPAIRS									Service ATA:76
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 76-10-01					
76-10-01.2	NO. 2 ENGINE - SURGE BLEED VALVE CHECK AND REPAIRS									Service ATA:76
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 76-10-01					
76-10-01.2	NO. 3 ENGINE - SURGE BLEED VALVE CHECK AND REPAIRS									Service ATA:76
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 76-10-01					
76-10-02.1	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) AND EEC HARNESS									Component ATA:76
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 76-10-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
76-10-02.1		NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) AND EEC HARNESS							Component	ATA:76
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 76-10-02					
76-10-02.1		NO. 3 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) AND EEC HARNESS							Component	ATA:76
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 76-10-02					
76-10-02.2		NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) AND EEC HARNESS CHECK AND REPAIRS							Service	ATA:76
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 76-10-02					
76-10-02.2		NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) AND EEC HARNESS CHECK AND REPAIRS							Service	ATA:76
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 76-10-02					
76-10-02.2		NO. 3 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) AND EEC HARNESS CHECK AND REPAIRS							Service	ATA:76
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 76-10-02					
76-10-03.1		NO. 1 ENGINE - [3-1C, 3-1H, POST SB TFE731-76-3067] N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS							Component	ATA:76
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 76-10-03					
76-10-03.1		NO. 2 ENGINE - [3-1C, 3-1H, POST SB TFE731-76-3067] N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS							Component	ATA:76
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 76-10-03					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
76-10-03.1		NO. 3 ENGINE - [3-1C, 3-1H, POST SB TFE731-76-3067] N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS							Component	ATA:76
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
					PROC. REF: LMM 76-10-03					
76-10-03.2		NO. 1 ENGINE - [3-1C, 3-1H, POST SB TFE731-76-3067] N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS CHECK AND REPAIRS							Service	ATA:76
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 76-10-03					
76-10-03.2		NO. 2 ENGINE - [3-1C, 3-1H, POST SB TFE731-76-3067] N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS CHECK AND REPAIRS							Service	ATA:76
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 76-10-03					
76-10-03.2		NO. 3 ENGINE - [3-1C, 3-1H, POST SB TFE731-76-3067] N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS CHECK AND REPAIRS							Service	ATA:76
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 76-10-03					
76-10-21-640-801-01		LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - LH ENGINE TELEFLEX CONTROL CABLE (L502EC)							Service	ATA:76
PN:7-43497-1	MOS/MSC	07-Sep-22	74 / E/C		07-Nov-28		1833 d			
SN:233	HRS	8823								
WC#: 76.020	AFL	5651								
					PROC. REF: AMM 76-10-21-640-801					
76-10-21-640-801-02		LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - CENTER ENGINE TELEFLEX CONTROL CABLE (M502EC)							Service	ATA:76
PN:7-43497-2	MOS/MSC	03-May-20	74 / E/C		03-Jul-26		975 d			
SN:257	HRS	8678.2								
WC#: 76.030	AFL									
					PROC. REF: AMM 76-10-21-640-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
76-10-21-640-801-03	LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - RH ENGINE TELEFLEX CONTROL CABLE (R502EC)								Service	ATA:76
PN:7-43497-3	MOS/MSC	09-Mar-18	74 / E/C		09-May-24		190 d			
SN:257	HRS	8497.6								
WC#: 76.020	AFL	5470								
					PROC. REF: AMM 76-10-21-640-801					
76-10-21-640-801-04	LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - ENGINE 1 CONTROL UNIT								Service	ATA:76
PN:7-43497-1	MOS/MSC	11-Feb-20	74 / E/C		11-Apr-26		892 d			
SN:233	HRS	8676.4								
WC#: 76.020	AFL	5582								
					PROC. REF: AMM 76-10-21-640-801					
76-10-21-640-801-05	LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - ENGINE 2 CONTROL UNIT								Service	ATA:76
PN:7-43497-2	MOS/MSC	11-Feb-20	74 / E/C		11-Apr-26		892 d			
SN:257	HRS	8676.4								
WC#: 76.030	AFL	5582								
					PROC. REF: AMM 76-10-21-640-801					
76-10-21-640-801-06	LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - ENGINE 3 CONTROL UNIT								Service	ATA:76
PN:7-43497-3	MOS/MSC	09-Mar-18	74 / E/C		09-May-24		190 d			
SN:257	HRS	8497.6								
WC#: 76.020	AFL	5470								
					PROC. REF: AMM 76-10-21-640-801					
76-10-21-900-801-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 1 AND 3 TELEFLEX CONTROL CABLES - LH ENGINE TELEFLEX CONTROL CABLE (L502EC)								Component	ATA:76
PN:7-43497-1	MOS/MSC	24-Oct-91	O/C							
SN:233	HRS	0		TSN 0						
WC#: 76.020	AFL	0								
					PROC. REF: AMM 76-10-21-900-801					
76-10-21-900-801-02	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 1 AND 3 TELEFLEX CONTROL CABLES - RH ENGINE TELEFLEX CONTROL CABLE (R502EC)								Component	ATA:76
PN:7-43497-3	MOS/MSC	24-Oct-91	O/C							
SN:257	HRS	0		TSN 0						
WC#: 76.020	AFL	0								
					PROC. REF: AMM 76-10-21-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
76-10-21-900-802-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 2 TELEFLEX CONTROL CABLE - CENTER ENGINE TELEFLEX CONTROL CABLE (M502EC)								Component	ATA:76
PN:7-43497-2	MOS/MSC	24-Oct-91	O/C							
SN:257	HRS	0		TSN 0						
WC#: 76.030	AFL	0								
					PROC. REF: AMM 76-10-21-900-802					
76-10-33-820-801-01 S	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 1 CONTROL CABLE (L501EC)								Service	ATA:76
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 76.020	AFL	5651								
					PROC. REF: AMM 76-10-33-820-801					PKG:31
76-10-33-820-801-02 S	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 2 CONTROL CABLE (M501EC)								Service	ATA:76
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 76.030	AFL	5651								
					PROC. REF: AMM 76-10-33-820-801					PKG:31
76-10-33-820-801-03 S	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 3 CONTROL CABLE (R501EC)								Service	ATA:76
	MOS	07-Sep-22	72 (+2m)							
	HRS	8823								
WC#: 76.020	AFL	5651								
					PROC. REF: AMM 76-10-33-820-801					PKG:31
760130	NO. 1 ENGINE - DOWNLOAD ECTM								Service	ATA:76
	MOS	08-Sep-23								
	HRS	8678.3								
WC#: 76.010	ENC	5775	40 (+10)		(5815) 5815	5825	19 (+10)			
					PROC. REF: MSC CAMP EHM ADENDUM, LMM 72-00-00					
760130	NO. 2 ENGINE - DOWNLOAD ECTM								Service	ATA:76
	MOS	08-Sep-23								
	HRS	8854								
WC#: 76.010	ENC	5683	40 (+10)		(5723) 5815	5733	19 (+10)			
					PROC. REF: MSC CAMP EHM ADENDUM, LMM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
760130		NO. 3 ENGINE - DOWNLOAD ECTM								Service ATA:76
	MOS	08-Sep-23								
	HRS	8836.3								
WC#: 76.010	ENC	5687	40 (+10)		(5727) 5815	5737	19 (+10)			
					PROC. REF: MSC CAMP EHM ADENDUM, LMM 72-00-00					
761101		THROTTLE CONTROL UNIT								Component ATA:76
PN:F50B771100A-3	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 76.010	AFL	0								
					PROC. REF: GENERIC NO REF					
ATA 77 - ENGINE INDICATING										
72-00-00.33		NO. 1 ENGINE - [WITH ANTI-ICE] NO ENGINE ANTI-ICE INDICATION								Service ATA:77
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.33		NO. 2 ENGINE - [WITH ANTI-ICE] NO ENGINE ANTI-ICE INDICATION								Service ATA:77
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
72-00-00.33		NO. 3 ENGINE - [WITH ANTI-ICE] NO ENGINE ANTI-ICE INDICATION								Service ATA:77
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 72-00-00					
77-10-03.2		NO. 1 ENGINE - N1 TRANSDUCER CHECK AND REPAIRS								Service ATA:77
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 77-10-03					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
77-10-03.2		NO. 2 ENGINE - N1 TRANSDUCER CHECK AND REPAIRS							Service	ATA:77
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 77-10-03					
77-10-03.2		NO. 3 ENGINE - N1 TRANSDUCER CHECK AND REPAIRS							Service	ATA:77
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 77-10-03					
77-10-05-900-801-01		REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 1 N1 INDICATOR (12E1)							Component	ATA:77
PN:224-902-002	MOS/MSC	17-Dec-10	O/C	TSR 0						
SN:UNKNOWN	HRS	7458.3		TSR 0						
WC#: 77.020	AFL	4759		TSR 0						
					PROC. REF: AMM 77-10-05-900-801					
77-10-05-900-801-02		REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 2 N1 INDICATOR (12E2)							Component	ATA:77
PN:224-902-002	MOS/MSC	15-Dec-12	O/C	TSO 182, TSR 1						
SN:1456A	HRS	7936		TSO 6269.4, TSR 0						
WC#: 77.020	AFL	5150		TSO 5075, TSR 0						
					PROC. REF: AMM 77-10-05-900-801					
77-10-05-900-801-03		REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 3 N1 INDICATOR (12E3)							Component	ATA:77
PN:224-902-002	MOS/MSC	24-Sep-12	O/C							
SN:1267A	HRS	7931								
WC#: 77.020	AFL	5144								
					PROC. REF: AMM 77-10-05-900-801					
77-10-05-900-801-04		REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 1 N2 INDICATOR (22E1)							Component	ATA:77
PN:218-901-002	MOS/MSC	24-Oct-91	O/C							
SN:1432	HRS	0		TSN 0						
WC#: 77.040	AFL	0								
					PROC. REF: AMM 77-10-05-900-801					
77-10-05-900-801-05		REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 2 N2 INDICATOR (22E2)							Component	ATA:77
PN:218-901-002	MOS/MSC	24-Oct-91	O/C							
SN:1438	HRS	0		TSN 0						
WC#: 77.040	AFL	0								
					PROC. REF: AMM 77-10-05-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
77-10-05-900-801-06	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 3 N2 INDICATOR (22E3)								Component	ATA:77
PN:218-901-002	MOS/MSC	24-Oct-91	O/C							
SN:1430	HRS	0		TSN 0						
WC#: 77.040	AFL	0								
					PROC. REF: AMM 77-10-05-900-801					
77-10-05.2	NO. 1 ENGINE - N2 TRANSDUCER CHECK AND REPAIRS								Service	ATA:77
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 77-10-05					
77-10-05.2	NO. 2 ENGINE - N2 TRANSDUCER CHECK AND REPAIRS								Service	ATA:77
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 77-10-05					
77-10-05.2	NO. 3 ENGINE - N2 TRANSDUCER CHECK AND REPAIRS								Service	ATA:77
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 77-10-05					
77-20-01.2	NO. 1 ENGINE - THERMOCOUPLE HARNESS CHECK AND REPAIRS								Service	ATA:77
	MOS/MSC	29-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 77-20-01					
77-20-01.2	NO. 2 ENGINE - THERMOCOUPLE HARNESS CHECK AND REPAIRS								Service	ATA:77
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 77-20-01					
77-20-01.2	NO. 3 ENGINE - THERMOCOUPLE HARNESS CHECK AND REPAIRS								Service	ATA:77
	MOS/MSC	30-Mar-91	A/R							
	HRS	0								
	ENC	0								
					PROC. REF: LMM 77-20-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
77-20-09-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE PT2 - TT2 SENSOR - ENGINE 1 PT2-TT2 SENSOR (L77E)									Component ATA:77
PN:3070816-12	MOS/MSC	20-May-19	O/C							
SN:56042	HRS									
WC#: 75.010	AFL									
					PROC. REF: AMM 77-20-09-900-801					
77-20-09-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE PT2 - TT2 SENSOR - ENGINE 2 PT2-TT2 SENSOR (M77E)									Component ATA:77
PN:PN	MOS/MSC	17-May-95	O/C							
SN:UNKNOWN	HRS	1646		TSN 1602						
WC#: 75.010	AFL	1169		TSN 1142						
					PROC. REF: AMM 77-20-09-900-801					
77-20-09-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE PT2 - TT2 SENSOR - ENGINE 3 PT2-TT2 SENSOR (R77E)									Component ATA:77
PN:3070816-12	MOS/MSC	20-May-19	O/C							
SN:1316901765232	HRS									
WC#: 75.010	AFL									
					PROC. REF: AMM 77-20-09-900-801					
77-20-17-900-801-01	REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 1 ITT INDICATOR (32E1)									Component ATA:77
PN:224-901-002	MOS/MSC	08-Dec-06	O/C	TSR 0						
SN:1012	HRS	5992.2		TSR 0						
WC#: 77.050	AFL	3650		TSR 0						
					PROC. REF: AMM 77-20-17-900-801					
77-20-17-900-801-02	REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 2 ITT INDICATOR (32E2)									Component ATA:77
PN:224-901-002	MOS/MSC	29-May-07	O/C	TSR 0						
SN:1182	HRS	6215.7		TSR 0						
WC#: 77.050	AFL	3817		TSR 0						
					PROC. REF: AMM 77-20-17-900-801					
77-20-17-900-801-03	REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 3 ITT INDICATOR (32E3)									Component ATA:77
PN:224-901-002	MOS/MSC	10-Oct-07	O/C							
SN:1182	HRS	6433.5								
WC#: 77.050	AFL	3978								
					PROC. REF: AMM 77-20-17-900-801					
771110	NO. 1 ENGINE - LOW PRESSURE (N1) TRANSDUCER									Component ATA:77
PN:3073827-4	MOS/MSC	17-Dec-04	O/C							
SN:UNKNOWN	HRS	5303.9								
WC#: 77.010	ENC	3252								
					PROC. REF: LMM 77-10-03					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
771110		NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER								Component ATA:77
PN:3073827-4	MOS/MSC	13-Dec-04	O/C							
SN:UNKNOWN	HRS	5335.8								
WC#: 77.010	ENC	3251								
					PROC. REF: LMM 77-10-03					
771110		NO. 3 ENGINE - LOW PRESSURE (N1) TRANSDUCER								Component ATA:77
PN:3071928-4	MOS/MSC	10-Dec-04	O/C							
SN:UNKNOWN	HRS	5303.9		TSN 0						
WC#: 77.010	ENC	3259								
					PROC. REF: LMM 77-10-03					
771120		NO. 1 ENGINE - HIGH PRESSURE (N2) TRANSDUCER								Component ATA:77
PN:224-902-002	MOS/MSC	23-Aug-02	O/C	TSO 0						
SN:1517A	HRS			TSO 0						
WC#: 77.020	ENC			TSO 0						
					PROC. REF: LMM 77-10-05					
771120		NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER								Component ATA:77
PN:PN	MOS/MSC	30-Mar-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 77.020	ENC	0		TSN 0						
					PROC. REF: LMM 77-10-05					
771120		NO. 3 ENGINE - HIGH PRESSURE (N2) TRANSDUCER								Component ATA:77
PN:PN	MOS/MSC	30-Mar-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 77.020	ENC	0		TSN 0						
					PROC. REF: LMM 77-10-05					
772110		NO. 1 ENGINE - ITT THERMOCOUPLE HARNESS								Component ATA:77
PN:3073595-1	MOS/MSC	19-Dec-11	O/C	TSN 0						
SN:1115027700121	HRS	7512.1		TSN 0						
WC#: 77.030	ENC	4826		TSN 0						
					PROC. REF: LMM 77-20-01					
772110		NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS								Component ATA:77
PN:3071849-3	MOS/MSC	30-Mar-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 77.030	ENC	0		TSN 0						
					PROC. REF: LMM 77-20-01					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 77 - ENGINE INDICATING										
772110		NO. 3 ENGINE - ITT THERMOCOUPLE HARNESS								Component ATA:77
PN:3073595-1	MOS/MSC	12-Dec-04	O/C							
SN:042021900322	HRS	5303.9		TSN 0						
WC#: 77.030	ENC	3259								
					PROC. REF: LMM 77-20-01					
ATA 78 - EXHAUST										
78-30-00-910-809-01		INHIBITION / ACTIVATION OF THE THRUST REVERSER FOR FLIGHT								Service ATA:78
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 78.120	AFL	0								
					PROC. REF: AMM 78-30-00-910-809					
78-31-00-250-801-01		SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THRUST REVERSER DOOR HINGE FITTINGS - LH THRUST-REVERSER DOOR (456DL)								Service ATA:78
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 78.100	AFL	0								
					PROC. REF: AMM 78-31-00-250-801					
78-31-00-250-801-02		SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THRUST REVERSER DOOR HINGE FITTINGS - RH THRUST-REVERSER DOOR (456DR)								Service ATA:78
	MOS/MSC	24-Oct-91	O/C							
	HRS	0								
WC#: 78.100	AFL	0								
					PROC. REF: AMM 78-31-00-250-801					
78-31-00-250-802-01[S]		SPECIAL DETAILED INSPECTION (FLUORESCENT PENETRANT) OF THE THRUST REVERSER DOOR HINGE FITTINGS - LH THRUST-REVERSER DOOR (456DL)								Service ATA:78
	MOS	08-Sep-23	24							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 78-31-00-250-802					PKG:16 ,15
78-31-00-250-802-01A		SPECIAL DETAILED INSPECTION (FLOURESCENT PENETRANT) OF THE LH THRUST REVERSER DOOR HINGE FITTINGS (MANDATORY 5-40)								Service ATA:78
	MOS	08-Sep-23						MANDATORY 5-40		
	HRS	8967								
	AFL	5775	1155		6930		1134			
					PROC. REF: AMM 78-31-00-250-802					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
78-31-00-250-802-02[S]		SPECIAL DETAILED INSPECTION (FLUORESCENT PENETRANT) OF THE THRUST REVERSER DOOR HINGE FITTINGS - RH THRUST-REVERSER DOOR (456DR)							Service	ATA:78
	MOS	08-Sep-23	24							
	HRS	8967								
	AFL	5775								
					PROC. REF: AMM 78-31-00-250-802					PKG:16 ,15
78-31-00-250-802-02A		SPECIAL DETAILED INSPECTION (FLOURESCENT PENETRANT) OF THE RH THRUST REVERSER DOOR HINGE FITTINGS (MANDATORY 5-40)							Service	ATA:78
	MOS	08-Sep-23						MANDATORY 5-40		
	HRS	8967								
	AFL	5775	1155		6930		1134			
					PROC. REF: AMM 78-31-00-250-802					
78-31-00-640-801-01[S]		GREASING OF THE THRUST REVERSER ASSEMBLY							Service	ATA:78
	MOS	08-Sep-23	12 (+1m)							
	HRS	8967								
WC#: 78.020	AFL	5775								
					PROC. REF: AMM 78-31-00-640-801					PKG:15
78-31-01-900-801-01		REMOVAL / INSTALLATION / ADJUSTMENT OF THE THRUST REVERSER DOORS - LH THRUST-REVERSER DOOR (456DL)							Component	ATA:78
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 78-31-01-900-801, AMM 78-31-01-900-801					
78-31-01-900-801-02		REMOVAL / INSTALLATION / ADJUSTMENT OF THE THRUST REVERSER DOORS - RH THRUST-REVERSER DOOR (456DR)							Component	ATA:78
PN:PN	MOS/MSC	24-Oct-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	AFL	0		TSN 0						
					PROC. REF: AMM 78-31-01-900-801, AMM 78-31-01-900-801					
78-31-13-900-801-01		REMOVAL / INSTALLATION OF THE THRUST REVERSER DOOR ACTUATORS - TR ACTUATOR (202KR)							Component	ATA:78
PN:F10A5SCH203-4	MOS/MSC	30-Nov-98	O/C							
SN:UNKNOWN	HRS	2995								
WC#: 78.080	AFL	2071								
					PROC. REF: AMM 78-31-13-900-801					
783101		THRUST REVERSER SOLENOID VALVE							Component	ATA:78
PN:A24521-102	MOS/MSC	24-Oct-91	O/C							
SN:FM1905	HRS	0		TSN 0						
WC#: 78.050	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
783106		THRUST REVERSER ACCUMULATOR								Component ATA:78
PN:60909-1	MOS/MSC	24-Oct-91	O/C							
SN:8013	HRS	0		TSN 0						
WC#: 78.010	AFL	0								
					PROC. REF: GENERIC NO REF					
783121		THRUST REVERSER PRESSURE INDICATOR								Component ATA:78
PN:18040100	MOS/MSC	24-Oct-91	O/C							
SN:29644C	HRS	0		TSN 0						
WC#: 78.040	AFL	0								
					PROC. REF: GENERIC NO REF					
783126		THRUST REVERSER FILLER VALVE								Component ATA:78
PN:MS28889-2	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 78.050	AFL	0								
					PROC. REF: GENERIC NO REF					
783131		LH THRUST REVERSER DISCHARGE VALVE								Component ATA:78
PN:3300-4	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 78.060	AFL	0								
					PROC. REF: GENERIC NO REF					
783136		RH THRUST REVERSER DISCHARGE VALVE								Component ATA:78
PN:AE99113G	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 78.060	AFL	0								
					PROC. REF: GENERIC NO REF					
783141		LH THRUST REVERSER CHECK VALVE								Component ATA:78
PN:A24515	MOS/MSC	24-Oct-91	O/C							
SN:FM1941	HRS	0		TSN 0						
WC#: 78.070	AFL	0								
					PROC. REF: GENERIC NO REF					
783146		RH THRUST REVERSER CHECK VALVE								Component ATA:78
PN:A24515	MOS/MSC	24-Oct-91	O/C							
SN:FM1940	HRS	0		TSN 0						
WC#: 78.070	AFL	0								
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
783151		THRUST REVERSER LATCHING SOLENOID								Component ATA:78
PN:A861TS4RF50	MOS/MSC	01-Nov-02	O/C	TSN 0						
SN:1543	HRS	4538.7		TSN 0						
WC#: 78.030	AFL	2880		TSN 0						
					PROC. REF: GENERIC NO REF					
783156		THRUST REVERSER LOCKING SOLENOID								Component ATA:78
PN:A861TS4RF50	MOS/MSC	24-Oct-91	O/C							
SN:971	HRS	0		TSN 0						
WC#: 78.030	AFL	0								
					PROC. REF: GENERIC NO REF					
783166		THRUST REVERSER JUNCTION ACTUATOR								Component ATA:78
PN:JEFX0500250AA	MOS/MSC	24-Oct-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 78.080	AFL	0								
					PROC. REF: GENERIC NO REF					
783201		THRUST REVERSER LOCKING SOLENOID								Component ATA:78
PN:F10A-5-SCAV200-1	MOS/MSC	24-Oct-91	O/C							
SN:1507	HRS	0		TSN 0						
WC#: 78.030	AFL	0								
					PROC. REF: GENERIC NO REF					
783826[U]		MCRSW,T/R DEPLOY (34K)								Component ATA:78
PN:83771063	MOS/MSC	27-Sep-05	O/C	TSN 0						
SN:04-40	HRS	5600.5		TSN 0						
	AFL	3449		TSN 0						
R 78-30-00		REPLACEMENT OF BUSHINGS ON THRUST REVERSER HINGE FITTINGS								Service ATA:78
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 78-30-00					
R 78-30-17		REPAIR OF CRACKS ON THRUST REVERSER STAND								Service ATA:78
	MOS/MSC	24-Oct-91	A/R							
	HRS	0								
	AFL	0								
					PROC. REF: SRM 78-30-17					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
79-30-05-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE TRANSDUCER - ENGINE 1 OIL PRESSURE TRANSMITTER (L4E)									Component ATA:79
PN:418-28044	MOS/MSC	24-Oct-91	O/C							
SN:9046246	HRS	0		TSN 0						
WC#: 79.090	AFL	0								
					PROC. REF: AMM 79-30-05-900-801					
79-30-05-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE TRANSDUCER - ENGINE 2 OIL PRESSURE TRANSMITTER (M4E)									Component ATA:79
PN:418-28044	MOS/MSC	17-May-95	O/C							
SN:9046249	HRS	1646		TSN 1602						
WC#: 79.090	AFL	1169		TSN 1142						
					PROC. REF: AMM 79-30-05-900-801					
79-30-05-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE TRANSDUCER - ENGINE 3 OIL PRESSURE TRANSMITTER (R4E)									Component ATA:79
PN:418-28044	MOS/MSC	24-Oct-91	O/C							
SN:9046253	HRS	0		TSN 0						
WC#: 79.090	AFL	0								
					PROC. REF: AMM 79-30-05-900-801					
79-30-09-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE SWITCH - ENGINE 1 OIL PRESSURE SWITCH (L6E)									Component ATA:79
PN:8G1126-2	MOS/MSC	04-Sep-20	O/C							
SN:728	HRS	8695.7								
WC#: 79.040	AFL	5595								
					PROC. REF: AMM 79-30-09-900-801					
79-30-09-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE SWITCH - ENGINE 2 OIL PRESSURE SWITCH (M6E)									Component ATA:79
PN:8G1126-2	MOS/MSC	17-May-95	O/C							
SN:948	HRS	1646		TSN 1602						
WC#: 79.040	AFL	1169		TSN 1142						
					PROC. REF: AMM 79-30-09-900-801					
79-30-09-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE SWITCH - ENGINE 3 OIL PRESSURE SWITCH (R6E)									Component ATA:79
PN:8G1126-2	MOS/MSC	19-Jan-06	O/C	TSN 0						
SN:2125	HRS	5738.2		TSN 0						
WC#: 79.040	AFL	3509		TSN 0						
					PROC. REF: AMM 79-30-09-900-801					
79-30-13-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE OIL TEMPERATURE SENSOR - ENGINE 1 TEMPERATURE SENSOR (L3E)									Component ATA:79
PN:56B17	MOS/MSC	24-Oct-91	O/C							
SN:21053	HRS	0		TSN 0						
WC#: 79.120	AFL	0								
					PROC. REF: AMM 79-30-13-900-801					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
79-30-13-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE OIL TEMPERATURE SENSOR - ENGINE 2 TEMPERATURE SENSOR (M3E)								Component	ATA:79
PN:56B17	MOS/MSC	17-May-95	O/C							
SN:29563	HRS	1646		TSN 1602						
WC#: 79.120	AFL	1169		TSN 1142						
					PROC. REF: AMM 79-30-13-900-801					
79-30-13-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE OIL TEMPERATURE SENSOR - ENGINE 3 TEMPERATURE SENSOR (R3E)								Component	ATA:79
PN:56B17	MOS/MSC	24-Oct-91	O/C							
SN:29099	HRS	0		TSN 0						
WC#: 79.120	AFL	0								
					PROC. REF: AMM 79-30-13-900-801					
79-30-17-900-801-01	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 1 OIL PRESSURE/TEMPERATURE INDICATOR (2E1)								Component	ATA:79
PN:5427-395-8	MOS/MSC	24-Oct-91	O/C							
SN:1151	HRS	0		TSN 0						
WC#: 79.130	AFL	0								
					PROC. REF: AMM 79-30-17-900-801					
79-30-17-900-801-02	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 2 OIL PRESSURE/TEMPERATURE INDICATOR (2E2)								Component	ATA:79
PN:5427-395-8	MOS/MSC	24-Oct-91	O/C							
SN:1085	HRS	0		TSN 0						
WC#: 79.130	AFL	0								
					PROC. REF: AMM 79-30-17-900-801					
79-30-17-900-801-03	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 3 OIL PRESSURE/TEMPERATURE INDICATOR (2E3)								Component	ATA:79
PN:5427-395-8	MOS/MSC	09-Apr-92	O/C							
SN:1092	HRS	26								
WC#: 79.130	AFL	13								
					PROC. REF: AMM 79-30-17-900-801					
790110[S]	NO. 1 ENGINE - ANALYZE ENGINE OIL AND FILTER								Service	ATA:79
	MOS	07-Jul-23								
	HRS	8674.8	200 (+50)							
WC#: 79.010	ENC	5769								
					PROC. REF: LMM 72-00-00					PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
790110[S]		NO. 2 ENGINE - ANALYZE ENGINE OIL AND FILTER								Service ATA:79
	MOS	10-Jan-23								
	HRS	8781.4	200 (+50)							
WC#: 79.010	ENC	5622								
					PROC. REF: LMM 72-00-00					PKG:0
790110[S]		NO. 3 ENGINE - ANALYZE ENGINE OIL AND FILTER								Service ATA:79
	MOS	10-Jan-23								
	HRS	8763.7	200 (+50)							
WC#: 79.010	ENC	5626								
					PROC. REF: LMM 72-00-00					PKG:0
790120		NO. 1 ENGINE - CHANGE OIL								Service ATA:79
	MOS	08-Sep-23								
	HRS	8678.3	1200 (+100)		(9878.3) 10167	9978.3	1174.9 (+100)			
WC#: 79.020	ENC	5775								
					PROC. REF: LMM 72-00-00					
790120		NO. 2 ENGINE - CHANGE OIL								Service ATA:79
	MOS	24-Dec-13								
	HRS	7993.6	1200 (+100)		(9193.6) 9306.6	9293.6	314.5 (+100)			
WC#: 79.020	ENC	5148								
					PROC. REF: LMM 72-00-00					
790120		NO. 3 ENGINE - CHANGE OIL								Service ATA:79
	MOS	13-Dec-13								
	HRS	7961.7	1200 (+100)		(9161.7) 9292.4	9261.7	300.3 (+100)			
WC#: 79.020	ENC	5141								
					PROC. REF: LMM 72-00-00					
790130[S]		NO. 1 ENGINE - INSPECT CHIP DETECTOR								Service ATA:79
	MOS	07-Jul-23								
	HRS	8674.8	200 (+50)							
WC#: 79.030	ENC	5769								
					PROC. REF: LMM 79-20-03					PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
790130[S]		NO. 2 ENGINE - INSPECT CHIP DETECTOR								Service ATA:79
	MOS	10-Jan-23								
	HRS	8781.4	200 (+50)							
WC#: 79.030	ENC	5622								
					PROC. REF: LMM 79-20-03					PKG:0
790130[S]		NO. 3 ENGINE - INSPECT CHIP DETECTOR								Service ATA:79
	MOS	10-Jan-23								
	HRS	8763.7	200 (+50)							
WC#: 79.030	ENC	5626								
					PROC. REF: LMM 79-20-03					PKG:0
792110		NO. 1 ENGINE - OIL PUMP								Component ATA:79
PN:3071949-12	MOS/MSC	30-Nov-07	O/C	TSR 0						
SN:8012	HRS	6306.2		TSR 0						
WC#: 79.040	ENC									
					PROC. REF: LMM 79-20-03					
792110		NO. 2 ENGINE - OIL PUMP								Component ATA:79
PN:3071949-11	MOS/MSC	27-Jan-01	O/C	TSO 0						
SN:9514057-3215	HRS	3986		TSO 0						
WC#: 79.040	ENC	2513		TSO 0						
					PROC. REF: LMM 79-20-03					
792110		NO. 3 ENGINE - OIL PUMP								Component ATA:79
PN:3071949-12	MOS/MSC	24-Sep-20	O/C							
SN:6264	HRS	8567.2								
WC#: 79.040	ENC	5509								
					PROC. REF: LMM 79-20-03					
792120		NO. 1 ENGINE - OIL FILTER BY-PASS INDICATOR								Component ATA:79
PN:3070246-4	MOS/MSC	15-Sep-99	O/C	TSN 0						
SN:UNKNOWN	HRS	3389		TSN 0						
WC#: 79.050	ENC	2234								
	(AFL)			TSN 0						
					PROC. REF: LMM 79-30-01					
792120		NO. 2 ENGINE - OIL FILTER BY-PASS INDICATOR								Component ATA:79
PN:3075323-3	MOS/MSC	03-Jan-03	O/C	TSN 0						
SN:UNKNOWN	HRS			TSN 0						
WC#: 79.050	ENC			TSN 0						
					PROC. REF: LMM 79-30-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
792120		NO. 3 ENGINE - OIL FILTER BY-PASS INDICATOR								Component ATA:79
PN:3070246-4	MOS/MSC	30-Mar-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 79.050	ENC	0		TSN 0						
					PROC. REF: LMM 79-30-01					
792130		NO. 1 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY								Component ATA:79
PN:3075323-3	MOS/MSC	21-Jun-98	O/C							
SN:970814503508	HRS	2753.2		TSN 0						
WC#: 79.060	ENC	1931								
	(AFL)			TSN 0						
					PROC. REF: LMM 79-20-02					
792130		NO. 2 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY								Component ATA:79
PN:3075323	MOS/MSC	02-Feb-07	O/C	TSO 0						
SN:UNKNOWN	HRS	5335.8		TSO 0						
WC#: 79.060	ENC									
					PROC. REF: LMM 79-20-02					
792130		NO. 3 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY								Component ATA:79
PN:3075323-3	MOS/MSC	21-Jun-98	O/C							
SN:970814503510	HRS	2753.2		TSN 0						
WC#: 79.060	ENC	1931								
	(AFL)			TSN 0						
					PROC. REF: LMM 79-20-02					
792140		NO. 1 ENGINE - UPPER OIL COOLER								Component ATA:79
PN:158600-7	MOS/MSC	27-Jul-07	O/C	TSO 0						
SN:79-1474	HRS			TSO 0						
WC#: 79.070	ENC									
					PROC. REF: LMM 79-20-09					
792140		NO. 2 ENGINE - UPPER OIL COOLER								Component ATA:79
PN:158600-7	MOS/MSC	30-Mar-91	O/C							
SN:90-9958	HRS	0		TSN 0						
WC#: 79.070	ENC	0		TSN 0						
					PROC. REF: LMM 79-20-09					

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
792140		NO. 3 ENGINE - UPPER OIL COOLER								Component ATA:79
PN:158600-7	MOS/MSC	30-Mar-91	O/C							
SN:90-9940	HRS	0		TSN 0						
WC#: 79.070	ENC	0		TSN 0						
					PROC. REF: LMM 79-20-09					
792150		NO. 1 ENGINE - LOWER LEFT OIL COOLER								Component ATA:79
PN:159900-3	MOS/MSC	27-Jul-07	O/C	TSO 0						
SN:121-4218	HRS			TSO 0						
WC#: 79.080	ENC									
					PROC. REF: LMM 79-20-09					
792150		NO. 2 ENGINE - LOWER LEFT OIL COOLER								Component ATA:79
PN:159910-3	MOS/MSC	30-Mar-91	O/C							
SN:11-7548	HRS	0		TSN 0						
WC#: 79.080	ENC	0		TSN 0						
					PROC. REF: LMM 79-20-09					
792150		NO. 3 ENGINE - LOWER LEFT OIL COOLER								Component ATA:79
PN:159900-3	MOS/MSC	30-Mar-91	O/C							
SN:41-7676	HRS	0		TSN 0						
WC#: 79.080	ENC	0		TSN 0						
					PROC. REF: LMM 79-20-09					
792160		NO. 1 ENGINE - LOWER RIGHT OIL COOLER								Component ATA:79
PN:159900-3	MOS/MSC	27-Jul-07	O/C	TSO 0						
SN:17-1176	HRS			TSO 0						
WC#: 79.090	ENC									
					PROC. REF: LMM 79-20-09					
792160		NO. 2 ENGINE - LOWER RIGHT OIL COOLER								Component ATA:79
PN:159900-3	MOS/MSC	30-Mar-91	O/C							
SN:41-7681	HRS	0		TSN 0						
WC#: 79.090	ENC	0		TSN 0						
					PROC. REF: LMM 79-20-09					
792160		NO. 3 ENGINE - LOWER RIGHT OIL COOLER								Component ATA:79
PN:159910-3	MOS/MSC	30-Mar-91	O/C							
SN:11-7535	HRS	0		TSN 0						
WC#: 79.090	ENC	0		TSN 0						
					PROC. REF: LMM 79-20-09					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
792170		NO. 1 ENGINE - OIL TEMPERATURE VALVE								Component ATA:79
PN:157025-1	MOS/MSC	29-Mar-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 79.100	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
792170		NO. 2 ENGINE - OIL TEMPERATURE VALVE								Component ATA:79
PN:158465-3	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:11-6581	HRS	0		TSN 0						
WC#: 79.100	ENC	0								
					PROC. REF: GENERIC NO REF					
792170		NO. 3 ENGINE - OIL TEMPERATURE VALVE								Component ATA:79
PN:157025-1	MOS/MSC	30-Mar-91	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 79.100	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
793110		NO. 1 ENGINE - OIL PRESSURE TRANSMITTER								Component ATA:79
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 79.110	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
793110		NO. 2 ENGINE - OIL PRESSURE TRANSMITTER								Component ATA:79
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 79.110	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
793110		NO. 3 ENGINE - OIL PRESSURE TRANSMITTER								Component ATA:79
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 79.110	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
793120		NO. 1 ENGINE - OIL PRESSURE SWITCH								Component ATA:79
PN:PN	MOS/MSC	29-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 79.120	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
793120		NO. 2 ENGINE - OIL PRESSURE SWITCH								Component ATA:79
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 79.120	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					
793120		NO. 3 ENGINE - OIL PRESSURE SWITCH								Component ATA:79
PN:PN	MOS/MSC	30-Mar-91	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 79.120	ENC	0		TSN 0						
					PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS