



Status Detail Report
Report Created On: 26 Dec 2024

Gulfstream Aerospace Corporation
G650
N380SE
S/N: 6088
Regulation: PART 91.409(F)(3)
Airworthiness Date: 21 Apr 2014

Phone: +1-912-298-1281
Fax: 1-912-963-0265/1-800-944-1775
Analyst: Pedro Alvarez

Airframe & Component Times					Total Time	
Logbook	Position	Description	Serial No.	Log Date	Hours	Cycles
Airframe		GULFSTREAM AEROSPACE CORPORATION G650	6088	14 Oct 2024	3522.4	727
Engine	1	ROLLS-ROYCE DERBY PLC BR725A1-12 (G650)	25289	14 Oct 2024	3522.4	727
Engine	2	ROLLS-ROYCE DERBY PLC BR725A1-12 (G650)	25288	14 Oct 2024	3522.4	727
APU		HONEYWELL RE220(GVI)	P-198	30 Jul 2024	1704	0

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

01 - Watch List

010010	Service Center Maintenance Induction Checklist	HRS	.4					3522		0
		AFL	1					726		0
		MOS	2.7					04 Oct 2024		
		MSC					O/C			
		Airframe								

07 - Lifting and Shoring

070005	Nose Landing Gear Axle Jacking	HRS	.4					3522		0
		AFL	1					726		0
		MOS	2.5					09 Oct 2024		
		MSC					O/C			
		Airframe								
070006	Main Gear Axle Jacking	HRS	.4					3522		0
		AFL	1					726		0
		MOS	2.5					09 Oct 2024		
		MSC					O/C			
		Airframe								

08 - Leveling and Weighing

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
080001	Weight & Balance Aircraft		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.8		36	02 Nov 2023	30 Nov 2026	31 Dec 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: COMPILED WITH PER ERSQCT-004 ITEM NUMBER 14A											
10 - Parking, Mooring, Store and Ret to Serv											
101001	Short Term Storage		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe			MSC				O/C				
101002	Long Term Storage		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe			MSC				O/C				
11 - Placards and Markings											
111000	Exterior Paint 1		HRS		3512.4			10			0
			AFL		723			4			0
			MOS		126.2			20 Jun 2014			
Airframe			MSC				O/C				
111001	Exterior Paint 2		HRS		3512.4			10			0
			AFL		723			4			0
			MOS		126.2			20 Jun 2014			
Airframe			MSC				O/C				
111002	Exterior Paint 3		HRS		3512.4			10			0
			AFL		723			4			0
			MOS		126.2			20 Jun 2014			
Airframe			MSC				O/C				
111003	Exterior Paint 4		HRS		3512.4			10			0
			AFL		723			4			0
			MOS		126.2			20 Jun 2014			
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
111004	Exterior Paint 5		HRS		3512.4			10			0
			AFL		723			4			0
			MOS		126.2			20 Jun 2014			
	Airframe		MSC				O/C				
111005	Exterior Paint 6		HRS		3512.4			10			0
			AFL		723			4			0
			MOS		126.2			20 Jun 2014			
	Airframe		MSC				O/C				
111006	Exterior Paint 7		HRS		3512.4			10			0
			AFL		723			4			0
			MOS		126.2			20 Jun 2014			
	Airframe		MSC				O/C				
111007	Exterior Paint 8		HRS		3512.4			10			0
			AFL		723			4			0
			MOS		126.2			20 Jun 2014			
	Airframe		MSC				O/C				
111008	Exterior Paint 9		HRS		3512.4			10			0
			AFL		723			4			0
			MOS		126.2			20 Jun 2014			
	Airframe		MSC				O/C				
111009	Exterior Paint 10		HRS		3512.4			10			0
			AFL		723			4			0
			MOS		126.2			20 Jun 2014			
	Airframe		MSC				O/C				
111010	Exterior Paint 11		HRS		3512.4			10			0
			AFL		723			4			0
			MOS		126.2			20 Jun 2014			
	Airframe		MSC				O/C				
111111	Exterior Strip and Paint		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
12 - Servicing											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
121100	Specification and Grades of Fluid Replenishment Materials		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
121200	Tank and Reservoir Capacities		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
121300	Refueling Procedures - Servicing		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.5			12 Oct 2024			
			MSC				O/C				
Airframe											
121301	Defueling Procedure - Servicing		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.5			11 Oct 2024			
			MSC				O/C				
Airframe											
121400	Engine Oil Tank Replenishing - Servicing		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		24.9			30 Nov 2022			
			MSC				O/C				
Airframe											
121401	Engine and APU Remote Oil Fill System - Servicing		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
121402	Main Battery Servicing		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
121403	Idg (Left) - Oil System Filling		HRS		3509.1			13.3			0
			AFL		722			5		0	
			MOS		123.3			16 Sep 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
121404	Idg (Left) - Servicing		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
121406	APU Oil - Servicing		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
121407	APU Manual Oil Level - Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
121408	No. 1 Engine - AIR Turbine Starter Oil - Discard		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			05 Oct 2024			
			[HRS: +50/-50]								
Engine											
Notes: TQ. WRENCH # 567989 CAL DUE: 12/19											
121408	No. 2 Engine - AIR Turbine Starter Oil - Discard		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			05 Oct 2024			
			[HRS: +50/-50]								
Engine											
Notes: TQ. WRENCH # 567989 CAL DUE: 12/19											
121409	No. 1 Engine - AIR Turbine Starter - Servicing		HRS		485.9			3036.5			0
			ENC		97			630			0
			MOS		26.3			18 Oct 2022			
			MSC				A/R				
Engine											
121409	No. 2 Engine - AIR Turbine Starter - Servicing		HRS		485.9			3036.5			0
			ENC		97			630			0
			MOS		26.3			18 Oct 2022			
			MSC				A/R				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
121500	Servicing Reservoir With Onboard Hydraulic Fluid Replenisher (Left) - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.1			22 Nov 2022			
			MSC				O/C				
Airframe											
121501	Servicing Reservoir With Onboard Hydraulic Fluid Replenisher (Right) - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.1			22 Nov 2022			
			MSC				O/C				
Airframe											
121502	Servicing Onboard Hydraulic Fluid Replenisher Tank - Servicing		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
121505	Main and Auxiliary Hydraulics Systems Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
121506	Left Hydraulic System Bleed - Servicing		HRS		0			3522.4			0
			AFL		0			727			0
			MOS		2.3			18 Oct 2024			
			MSC				O/C				
Airframe											
121507	Right Hydraulic System Bleed - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.2			19 Nov 2022			
			MSC				O/C				
Airframe											
Notes: T/W: 561051CAL. DUE: 11/18											
121508	Hydraulic System Reservoir (Left) - Servicing		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			09 Oct 2024			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
121509	Hydraulic System Reservoir (Right) - Servicing		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.5			09 Oct 2024			
			MSC			O/C					
121600	Parking Brake Accumulator - Servicing		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99			27 Sep 2016			
			MSC			O/C					
121601	Hydraulic System Accumulator (Left) - Servicing		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
121602	Hydraulic System Accumulator (Right) - Servicing		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
121700	Potable Water - Servicing		HRS		873.6			2648.8			0
			AFL		166			561		0	
			MOS		38.6			06 Oct 2021			
			MSC			O/C					
121701	Potable Water System Line Drain - Servicing		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
121702	Potable Water System Purge - Servicing		HRS		113.9			3408.5			0
			AFL		36			691		0	
			MOS		14.3			16 Oct 2023			
			MSC			O/C					
121703	Waste Tank - Draining		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.6			06 Oct 2024			
			MSC			O/C					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
121900	Oxygen - Servicing		HRS		113.9			3408.5			0
			AFL		36			691		0	
			MOS		13.8			31 Oct 2023			
			MSC			O/C					
122100	Approved Fuel Additives		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014		0	
			MSC			O/C					
122101	Approved Oils - Servicing		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
122200	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle - Servicing		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		25.1			22 Nov 2022			
			MSC			O/C					
122201	Landing Gear Shock Struts and Actuating Cylinders - Cleaning		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
122202	Main Landing Gear - Lubrication		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.7	-13	4	05 Oct 2024	31 Jan 2025*	28 Feb 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
122203	Main Landing Gear Door Hinges - Lubrication		HRS		3512.4			10			0
			AFL		723			4		0	
			MOS		126.4			14 Jun 2014			
			MSC			O/C					
122204	Nose Landing Gear - Lubrication		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.7	-13	4	05 Oct 2024	31 Jan 2025*	28 Feb 2025	
			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
122206	Nose Tire Assembly - Servicing		HRS		0			3522.4			0
			AFL		0			727			0
			MOS		2.3			17 Oct 2024			
			MSC				O/C				
Airframe											
Notes: SERVICE KIT 08TSK-01											
122207	Main Tire Assembly - Servicing		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7			05 Oct 2024			
			MSC				O/C				
Airframe											
Notes: GAUGE 556387 DUE 03/19											
122208	Pressed In Grease Fittings - Installation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
122209	Main Landing Gear Shock Absorber - Servicing		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7		48	05 Oct 2024	31 Oct 2028	30 Nov 2028	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
122210	Nose Landing Gear Shock Absorber - Servicing		HRS		0			3522.4			0
			AFL		0			727			0
			MOS		2.3		48	17 Oct 2024	31 Oct 2028	30 Nov 2028	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: STRUT GAUGE S/N: 564589 DUE CAL: 1/2019T/W S/N: 558138 DUE CAL: 6/2019											
122211	Nose Wheel Steering Unit - Lubrication		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.7		24	04 Oct 2024	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
122212	Nose Wheel Steering Collar Assembly / Slave Gear - Lubrication		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.7		24	04 Oct 2024	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
122213	Brake Bleeding Procedure		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122300	Control Surface Hinge Joints - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122301	Elevator Load Relief Bungee - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122302	Stall Barrier Actuator - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122303	Spoiler Load Relief Bungee - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122304	Aileron Load Relief Bungee - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122305	Spoiler Hinges Inboard / Middle / Outboard - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122306	Rudder Torque Tube Bearing - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
122307	Rudder Pedals - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122308	Aileron Trim Tab Actuator - Service / Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122309	Rudder Trim Actuator - Service / Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122310	Wing Flap Traveling Nut - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122311	Flap Actuator Bushing - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122312	Flap Actuator Travel Nut and Gearbox - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122313	Horizontal and Vertical Flap Actuators - Lubrication		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
122315	Horizontal Stabilizer Actuator - Lubrication		HRS		.4		1200	3522	4722	4772	0
			AFL		1			726			0
			MOS		2.5	22	24	09 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
122316	Spoiler Links - Lubrication (24 Months)		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
122317	Aileron Links - Lubrication (24 Months)		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
122318	Elevator Links - Lubrication (24 Months)		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
122319	Rudder Links - Lubrication (24 Months)		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
122323	Aileron Actuator Toggle Links (Left) - Lubrication		HRS		.4		1200	3522	4722	4772	0
			AFL		1			726			0
			MOS		3.1		24	22 Sep 2024	30 Sep 2026	31 Oct 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
122324	Aileron Actuator Toggle Links (Right) - Lubrication		HRS		.4		1200	3522	4722	4772	0
			AFL		1			726			0
			MOS		3.1		24	22 Sep 2024	30 Sep 2026	31 Oct 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
122325	Rudder Actuator Toggle Links - Lubrication		HRS		.4		1200	3522	4722	4772	0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
122326	Elevator Actuator Toggle Links (Left) - Lubrication		HRS		.4		1200	3522	4722	4772	0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
122327	Elevator Actuator Toggle Links (Right) - Lubrication		HRS		.4		1200	3522	4722	4772	0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
122328	Flap Actuator Ball Nut (Left) - Lubrication		HRS		.4		1500	3522	5022	5072	0
			AFL		1			726			0
			MOS		3.1	39	24	22 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
122329	Flap Actuator Ball Nut (Right) - Lubrication		HRS		.4		1500	3522	5022	5072	0
			AFL		1			726			0
			MOS		3.1	39	24	22 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
122330	Outboard Spoiler Actuator Toggle Link (Left) - Lubrication		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	26	24	05 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
122331	Outboard Spoiler Actuator Toggle Link (Right) - Lubrication		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
122332	Horizontal Actuator Oil - Discard		HRS		3522.4		6000	0	6000	6050	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe	[HRS: +50/-50]									
122333	Aileron Hinge Fitting (Left) - Lubrication		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1	39	24	22 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
122334	Aileron Hinge Fitting (Right) - Lubrication		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1	39	24	22 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
122335	Rudder Hinge Fitting - Lubrication		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
122336	Elevator Hinge Fitting (Left) - Lubrication		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
122337	Elevator Hinge Fitting (Right) - Lubrication		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
122500	External Baggage Door - Lubrication		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.2	42	12	19 Sep 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
122501	Main Entrance Door - Lubrication		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	-5	12	05 Oct 2024	30 Sep 2025*	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
122600	Ram AIR Turbine - Lubrication		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5		24	12 Oct 2024	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
20 - Standard Practices - Airframe											
200091	Pre Maintenance - Checklist		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.3			16 Sep 2024			
			MSC				O/C				
Airframe											
200092	Post Maintenance - Checklist		HRS		0			3522.4			0
			AFL		0			727			0
			MOS		2.4			14 Oct 2024			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
200093	Post Maintenance - Servicing		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
21 - AIR Conditioning											
210001	AIR Conditioning System - Functional Check		HRS		.4			3522			0
			AFL		1		726		0		
			MOS		2.5		12 Oct 2024				
			MSC			O/C					
Airframe											
212101	Cabin Silencer (Forward) - Removal / Installation 60P2121006Z0050098		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014		0		
			MSC			O/C					
Airframe											
212102	Cabin Silencer (Left Aft) - Removal / Installation 60P2121006Z0060182		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
212103	Cabin Silencer (Right Aft) - Removal / Installation 60P2121006Z0060198		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014		0		
			MSC			O/C					
Airframe											
212104	Cockpit Silencer - Removal / Installation 60P2121002Z0040075		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
212121	Pack Inlet Valve (Left) - Removal / Installation 396610-62373		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
212122	Pack Inlet Valve (Right) - Removal / Installation 396610-62372		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014		0		
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212125	Ozone Converter (Left) - Removal / Installation		HRS		3339.5			182.9			0
	1159SCAC501-1	6245	AFL		689			38			0
			MOS		118.2			19 Feb 2015			
	Airframe		MSC					O/C			
212126	Ozone Converter (Right) - Removal / Installation		HRS		3339.5			182.9			0
	1159SCAC501-1	6246	AFL		689			38			0
			MOS		118.2			19 Feb 2015			
	Airframe		MSC					O/C			
212129	Ozone Converter (Left) - Restore		HRS		3522.4		10000	0	10000	10050	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		[HRS: +50/-50]								
212130	Ozone Converter (Right) - Restore		HRS		3522.4		10000	0	10000	10050	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		[HRS: +50/-50]								
212200	Ram AIR Check Valve - Removal / Installation		HRS		3522.4			0			0
	3202776-1	2170	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC					O/C			
212202	Ram AIR Check Valve - Detailed Inspection		HRS		3522.4		7500	0	7500	7550	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		[HRS: +50/-50]								
212207	Ram AIR Plenum Assembly Left AIR Pack - Removal / Installation		HRS		3522.4			0			0
	1159ACP50002-31	P000074749-0000	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC					O/C			
212208	Ram AIR Plenum Assembly Right AIR Pack - Removal / Installation		HRS		3522.4			0			0
	1159ACP50002-33	P000075334-0000	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212500	Avionics Cooling Check Valve, Return AIR - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	3202776-1	2197	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
212501	Avionics Cooling Turret Duct, Return AIR - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	729611008	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
212505	Personal Service Unit Cooling Fan - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	011990500	C13440022	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
212508	Aft Equipment Cooling Fan (Forward Baggage Eer) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	011586501	I13470449	MOS		128.2			21 Apr 2014			
	0	0	MSC				O/C				
Airframe											
212509	Aft Equipment Cooling Fan (Aft Baggage Eer) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	011586501	I13440810	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
212512	Aft Equipment Cooling Fan (Forward Baggage Eer) - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
212515	Leer Cooling Fan - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	011989500	C14020482	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212516	Reer Cooling Fan - Removal / Installation		HRS		3522.4			0			0
	011587503	C13060021	AFL		727			0			0
	0	0	MOS	TSN:4	128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212517	Aft Equipment Cooling Fan (Baggage Compartment Bulkhead, Upper) - Removal / Installation		HRS		3522.4			0			0
	011586501	I14010930	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212518	Aft Equipment Cooling Fan (Baggage Compartment Bulkhead, Lower) - Removal / Installation		HRS		3522.4			0			0
	011586501	I13500708	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212523	Leer Cooling Fan - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212524	Reer Cooling Fan - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212525	Aft Equipment Cooling Fan (Baggage Compartment Bulkhead, Upper) - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212526	Aft Equipment Cooling Fan (Baggage Compartment Bulkhead, Lower) - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212527	Leer Cooling Fan - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212528	Reer Cooling Fan - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212529	Equipment Cooling Fan (Aft Upper) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212530	Equipment Cooling Fan (Aft Lower) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212543	Aft Equipment Cooling Fan Low-Speed Warning Detector (Baggage Compartment Bulkhead, Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	035640501	E10341911	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212544	Aft Equipment Cooling Fan Low-Speed Warning Detector (Baggage Compartment Bulkhead, Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	035640501	E10191118	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
212545	Aft Equipment Cooling Fan Low-Speed Warning Detector (Forward Baggage Eer) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	035640501	E13433559	MOS		128.2			21 Apr 2014			
	0	0	MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
212546	Aft Equipment Cooling Fan Low-Speed Warning Detector		HRS	TSN:7	3522.4			0			0
	(Aft Baggage Eer) - Removal / Installation		AFL	TSN:4	727			0			0
	035640501	E12329158	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
213100	Cabin Pressure Controller - Removal / Installation		HRS	TSN:13.3	3509.1			13.3			0
	2119314-2	2119314-00098	AFL	TSN:5	722			5			0
			MOS	TSN:3	125.2			20 Jul 2014			
			MSC				O/C				
Airframe											
213102	Cabin Pressurization Controller - System Check		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		125.2			20 Jul 2014			
			MSC				O/C				
Airframe											
Notes: PN: 2119314 SN: <NONE>.											
213103	Cabin Pressurization Control - System Check		HRS		3522.4		6000	0	6000	6050	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			[HRS: +50/-50]								
Airframe											
Notes: PN: 2119314-2 SN: <NONE>.											
213107	Outflow Valve - Removal / Installation		HRS		3522.4			0			0
	103878-1	93-A0911	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
213109	Outflow Valve - Cleaning / Painting		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
213114	Cabin Pressure Control Static Inverter - Operational		HRS		3522.4			0			0
	Check		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
213115	Cabin Pressure Control Static Inverter - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	717320-2\	0113	MOS		128.2			21 Apr 2014			
		E	MSC				O/C				
Airframe											
213117	Cabin Pressurization Control Panel - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	2119144-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
213301	Pressure Relief Valve - Removal / Installation		HRS		3522.4			0			0
	103928-1	103928-00095	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
213302	Remote AIR Filter - Removal / Installation		HRS		485.9			3036.5			0
	147240-1	NSN	AFL		97			630			0
			MOS	TSN:14	25.4			15 Nov 2022			N/A
			MSC				O/C				
Airframe											
213304	Pressure Relief Valve Remote AIR Filter - Detailed Inspection		HRS		485.9	-36.5	3750	3036.5	6750*	6800	0
			AFL		97			630			0
			MOS		25.4			15 Nov 2022			
			[HRS: +50/-50]								
Airframe											
Notes: PN: 147240-1 SN: <NONE>.											
213305	Pressure Relief Valve - Inspection / Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
213306	Pressure Relief Valve - Functional Check		HRS		485.9	-36.5	3750	3036.5	6750*	6800	0
			AFL		97			630			0
			MOS		25.4			15 Nov 2022			
			[HRS: +50/-50]								
Airframe											
Notes: PN: 147240-1 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
213307	Baggage Compartment Shut-Off Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	FYLB-52635	778	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
213308	Baggage Compartment Shut-Off Valve Reset Switch - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	MS24523-30	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
213311	Baggage Compartment Shut-Off Valve and Reset Switch - Operational Check		HRS		485.9	-36.5	3750	3036.5	6750*	6800	0
			AFL		97			630			0
			MOS		24.9			29 Nov 2022			
			[HRS: +50/-50]								
Airframe											
Notes: PN: MS24523-30 SN: <NONE>.											
213312	Baggage Compartment Ventilation Check Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	PN	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
213314	Baggage Compartment Ventilation Check Valve - Detailed Inspection		HRS		3522.4		7500	0	7500	7550	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			[HRS: +50/-50]								
Airframe											
213315	Baggage Compartment Decompression Advisory System - Functional Check		HRS		3522.4		4500	0	4500	4550	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			[HRS: +50/-50]								
Airframe											
213316	Baggage Compartment Decompression Warning Circuit - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
213400	Baggage Compartment Decompression Switch - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	P20M-H23	974	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
213410	Cabin Pressure Acquisition Module - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	733873-1-1	733873IN00199	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
215101	Pack Outlet Temperature Sensor (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	1151834-1	1151834-10904	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
215102	Pack Outlet Temperature Sensor (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	1151834-1	1151834-10902	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
215103	AIR Conditioning Pack (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	2215080-3	2249	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
215104	AIR Conditioning Pack (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	2215080-3	2250	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
215200	AIR Cycle Machine (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	2205590-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215204	Reheater / Condenser (Left) - Removal / Installation		HRS		3522.4			0			0
	70210-2341142-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215205	Reheater / Condenser (Right) - Removal / Installation		HRS		3522.4			0			0
	2341142-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215206	Turbine Inlet Temperature Sensor (Left) - Removal / Installation		HRS		3522.4			0			0
	1151144-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215207	Turbine Inlet Temperature Sensor (Right) - Removal / Installation		HRS		3522.4			0			0
	1151144-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215208	Turbine Inlet Temperature Control Valve (Left) - Removal / Installation		HRS		3522.4			0			0
	2341176-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215209	Turbine Inlet Temperature Control Valve (Right) - Removal / Installation		HRS		3522.4			0			0
	2341176-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215210	Low Limit Valve (Left) - Removal / Installation		HRS		3522.4			0			0
	3291284-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215211	Low Limit Valve (Right) - Removal / Installation		HRS		3522.4			0			0
	3291284-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215212	Primary / Secondary Heat Exchanger (Left Primary) - Removal / Installation		HRS		3522.4			0			0
	2341680-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215213	Primary / Secondary Heat Exchanger (Right Primary) - Removal / Installation		HRS		3522.4			0			0
	2341680-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215214	Primary / Secondary Heat Exchanger (Left Secondary) - Removal / Installation		HRS		3522.4			0			0
	2341682-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215215	Primary / Secondary Heat Exchanger (Right Secondary) - Removal / Installation		HRS		3522.4			0			0
	2341682-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215218	Turbine Bypass Valve (Left) - Removal / Installation		HRS		3522.4			0			0
	3291286-3	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215219	Turbine Bypass Valve (Right) - Removal / Installation		HRS		3522.4			0			0
	3291286-3	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215220	Servo Pressure Regulator (Left) - Removal / Installation		HRS		3522.4			0			0
	3215634-3	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215221	Servo Pressure Regulator (Right) - Removal / Installation		HRS		3522.4			0			0
	3215634-3	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
215238	Primary / Secondary Heat Exchanger (Left Primary) -		HRS		3522.4			0			0
	Inspection		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: PN: 2341682-1 SN: <NONE>.											
215239	Primary / Secondary Heat Exchanger (Right Primary) -		HRS		3522.4			0			0
	Inspection		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: PN: 2341682-1 SN: <NONE>.											
215240	Primary / Secondary Heat Exchanger (Left Secondary) -		HRS		3522.4			0			0
	Inspection		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: PN: 2341682-1 SN: <NONE>.											
215241	Primary / Secondary Heat Exchanger (Right Secondary) -		HRS		3522.4			0			0
	Inspection		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: PN: 2341682-1 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215242	Primary / Secondary Heat Exchanger (Left Primary) - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: PN: 2341682-1 SN: <NONE>.											
215243	Primary / Secondary Heat Exchanger (Right Primary) - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: PN: 2341682-1 SN: <NONE>.											
215244	Primary / Secondary Heat Exchanger (Left Secondary) - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: PN: 2341682-1 SN: <NONE>.											
215245	Primary / Secondary Heat Exchanger (Right Secondary) - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: PN: 2341682-1 SN: <NONE>.											
215400	Water Extractor (Left) - Removal / Installation 2341144-1 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
215401	Water Extractor (Right) - Removal / Installation 2341144-1 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215402	Water Extractor Strainer (Left) - Removal / Installation		HRS		2312.5			1209.9			0
	1159ACM50843-1	SN-UNKNOWN	AFL		479			248			0
			MOS		87.2			20 Sep 2017			
	Airframe		MSC				O/C				
Notes: TQ WRENCH 554677NEXT CAL DUE 10/17											
215403	Water Extractor Strainer (Right) - Removal / Installation		HRS		2312.5			1209.9			0
	1159ACM50843-1	SN-UNKNOWN	AFL		479			248			0
			MOS		87.2			20 Sep 2017			
	Airframe		MSC				O/C				
Notes: TQ WRENCH 554677NEXT CAL DUE 10/17											
215408	Water Extractor Aspirator Line and Nozzle (Left) -		HRS		3522.4			0			0
	Inspection		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: PN: 60P2152001S010 SN: <NONE>.											
215409	Water Extractor Aspirator Line and Nozzle (Right) -		HRS		3522.4			0			0
	Inspection		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: PN: 60P2152001S010 SN: <NONE>.											
216101	AIR Conditioning Controller (Left) - Removal / Installation		HRS	TSN:182.9	3339.5			182.9			0
	1153482-3\6(CSCI3)	1153482-00580	AFL	TSN:38	689			38			0
		6(CSC13)	MOS	TSN:10	118.3			17 Feb 2015			
	Airframe		MSC				O/C				
216102	AIR Conditioning Controller (Right) - Removal /		HRS		2312.5			1209.9			0
	Installation		AFL		479			248			0
	1153482-3	1153482-00597	MOS		87			26 Sep 2017			
	Airframe		MSC				O/C				
216111	Zone Trim AIR Check Valve (Left) - Detailed Inspection		HRS		3522.4		6000	0	6000	6050	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		[HRS: +50/-50]								
Notes: PN: 3202760-1 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216112	Zone Trim AIR Check Valve (Right) - Detailed Inspection		HRS		3522.4		6000	0	6000	6050	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		[HRS: +50/-50]								
Notes: PN: 3202760-1 SN: <NONE>.											
216113	AIR Supply Check Valve (Left) - Detailed Inspection		HRS		3522.4		12000	0	12000		0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		[HRS: -50]								
Notes: PN: 3202760-1 SN: <NONE>.											
216114	AIR Supply Check Valve (Right) - Detailed Inspection		HRS		3522.4		12000	0	12000	12050	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		[HRS: +50/-50]								
Notes: PN: 3202760-1 SN: <NONE>.											
216120	Zone Supply Check Valve - Removal / Installation		HRS		3522.4			0			0
	123312-9	20256	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
216121	AIR Supply Trim AIR Check Valve (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	3202758-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
216122	AIR Supply Trim AIR Check Valve (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	3202758-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
216123	Zone Trim AIR Check Valve (Left) - Removal / Installation		HRS		3522.4			0			0
	3202760-1	2389	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216124	Zone Trim AIR Check Valve (Right) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	3202760-1	2390	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
216125	Zone Trim AIR Valve Check Valve (Left) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	123312-9	20257	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
216126	Zone Trim AIR Valve Check Valve (Right) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	123312-9	20255	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
216130	Overheat Thermostat Zone Supply (Cockpit) - Removal /		HRS		3026.3			496.1			0
	Installation		AFL		617			110			0
	129740-1-1	2303	MOS		107.6			06 Jan 2016			
			MSC				O/C				
Airframe											
216131	Overheat Thermostat Zone Supply (Forward Cabin) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	129740-1	4477	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
216132	Overheat Thermostat Zone Supply (Aft Cabin) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	129740-1	4363	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
216135	Zone Trim AIR Valve (Cockpit) - Removal / Installation		HRS		3026.3			496.1			0
	3291688-3	851	AFL		617			110			0
			MOS		107.7			05 Jan 2016			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216136	Zone Trim AIR Valve (Forward Cabin) - Removal / Installation		HRS		3339.5			182.9			0
			AFL		689			38			0
	3291688-3	1220	MOS		118.3			18 Feb 2015			
			MSC				O/C				
Airframe											
216137	Zone Trim AIR Valve (Aft Cabin) - Removal / Installation		HRS		3522.4			0			0
	3291688-3		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
216138	Zone Trim AIR Valve Cup Assembly (Cockpit) - Removal / Installation		HRS		.4			3522			0
			AFL		1			726			0
	4000091-600-BT	NSN	MOS		2.7			03 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: TW ID: 567989CAL DUE: 12/19											
216139	Zone Trim AIR Valve Cup Assembly (Forward Cabin) - Removal / Installation		HRS		.4			3522			0
			AFL		1			726			0
	4000091-600-BT	NSN	MOS		2.7			03 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: TW ID: 567989CAL DUE: 12/19											
216140	Zone Trim AIR Valve Cup Assembly (Aft Cabin) - Removal / Installation		HRS		.4			3522			0
			AFL		1			726			0
	4000091-600-BT	NSN	MOS		2.7			03 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: TW ID: 567989CAL DUE: 12/19											
216141	Zone Trim AIR Valve Cup Assembly (Cockpit) - Discard		HRS		.4		850	3522	4372		0
	4000091-600-BT		AFL		1			726			0
			MOS		2.7			03 Oct 2024			N/A
Airframe											
Notes: TW ID: 567989CAL DUE: 12/19											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216142	Zone Trim AIR Valve Cup Assembly (Forward Cabin) - Discard		HRS		.4		850	3522	4372		0
			AFL		1			726			0
	4000091-600-BT	NSN	MOS		2.7			03 Oct 2024			N/A
Airframe											
Notes: TW ID: 567989CAL DUE: 12/19											
216143	Zone Trim AIR Valve Cup Assembly (Aft Cabin) - Discard		HRS		.4		850	3522	4372		0
			AFL		1			726			0
	4000091-600-BT	NSN	MOS		2.7			03 Oct 2024			N/A
Airframe											
Notes: TW ID: 567989CAL DUE: 12/19											
216206	Cabin / Cockpit Temperature Indication - Functional Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.3			16 Nov 2022			
Airframe											
216219	Zone Temperature Sensor Fan (Forward Cabin) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	011590500	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
Airframe											
216220	Zone Temperature Sensor Fan (Aft Cabin) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	11590500	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
Airframe											
216223	Zone Temperature Sensor Fan (Forward Cabin) - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: PN: 011590500 SN: <NONE>.											
216224	Zone Temperature Sensor Fan (Aft Cabin) - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: PN: 011590500 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216229	Zone Temperature Sensor Fan Low-Speed Warning		HRS		3522.4			0			0
	Detector (Forward Cabin) - Removal / Installation		AFL		727			0			0
	035640501	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
216230	Zone Temperature Sensor Fan Low-Speed Warning		HRS		3522.4			0			0
	Detector (Aft Cabin) - Removal / Installation		AFL		727			0			0
	035640501	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
216235	Cabin Temperature Sensor (Aft) - Removal / Installation		HRS	TSN:13.3	3509.1			13.3			0
	1151834-1	1151834-10968	AFL	TSN:5	722			5			0
			MOS	TSN:5	123.6			08 Sep 2014			
			MSC				O/C				
Airframe											
216236	Zone Supply Temperature Sensor (Cockpit) - Removal /		HRS		2533.4			989			0
	Installation		AFL		513			214			0
	1151834-1	1151834-11065	MOS		91.7			03 May 2017			
			MSC				O/C				
Airframe											
216237	Zone Supply Temperature Sensor (Forward Cabin) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	1151834-1	1151834-10900	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
216238	Zone Supply Temperature Sensor (Aft Cabin) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	1151834-1	1151834-10906	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
216239	Cockpit Temperature Sensor - Removal / Installation		HRS		485.9			3036.5			0
	1152488-1	129C-0249	AFL		97			630			0
			MOS		25.4			14 Nov 2022			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216240	Cabin Temperature Sensor (Forward) - Removal / Installation		HRS	TSN:13.3	3509.1			13.3			0
			AFL	TSN:5	722			5			0
	1151834-1	1151834-11050	MOS	TSN:5	123.6			08 Sep 2014			
			MSC				O/C				
Airframe											
216241	Leer Temperature Sensor - Removal / Installation		HRS		2312.5			1209.9			0
			AFL		479			248			0
	1151834-1	1151834-14405	MOS	TSN:8	87			25 Sep 2017			
			MSC				O/C				
Airframe											
Notes: REFERENCE CEE468000012 REV - AND GDX457001001-501 REV -											
22 - Auto Flight											
221000	Autopilot - Operational Test		HRS		1039.9			2482.5			0
			AFL		216			511			0
			MOS		43.7			04 May 2021			
			MSC				O/C				
Airframe											
Notes: PN: 7028660-951 SN: <NONE>.											
221100	Flight Guidance Panel - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7028660-951\A-B	13121507	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
223000	Auto Throttle - Operational Test		HRS		1050.2			2472.2			0
			AFL		217			510			0
			MOS		43.9			29 Apr 2021			
			MSC				O/C				
Airframe											
Notes: PN: 7028660-951 SN: <NONE>.											
23 - Communications											
230300	Modular Radio Cabinet (No. 1) - Removal / Installation		HRS	TSN:3408.5	113.9			3408.5			0
			AFL	TSN:691	36			691			0
	7517959-904\D	13111823	MOS	TSN:114	14			26 Oct 2023			N/A
			MSC				O/C				
Airframe											
230301	Modular Radio Cabinet (No. 2) - Removal / Installation		HRS		2312.5			1209.9			0
			AFL		479			248			0
	7517959-904	07032626	MOS		87.1			24 Sep 2017			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231300	HF Dual Coupler Mounting Tray / Shock Mount - Removal / Installation		HRS		3062.5			459.9			0
			AFL		625			102			0
	622-8124-001	2598	MOS	TSN:98	108.5			11 Dec 2015			
			MSC				O/C				
Airframe											
231301	HF Antenna Adapter - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	822-0089-001	1554	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
231302	HF R/T (No. 1) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	822-0102-001	4796	MOS		13.8			01 Nov 2023			N/A
			MSC				O/C				
Airframe											
231303	HF Dual Coupler Mounting Tray / Shock Mount - Replacement		HRS		3522.4			0			0
			AFL		727			0			0
	622-8124-001	4350	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 231300											
231306	HF Voice Communications - Operational Check		HRS		0			3522.4			0
			AFL		0			727			0
			MOS		2.4			14 Oct 2024			
			MSC				O/C				
Airframe											
231307	HF Shunt Antenna - Continuity Check		HRS		3113.6			408.8			0
			AFL		642			85			0
			MOS		109.6			06 Nov 2015			
			MSC				O/C				
Airframe											
231308	HF Shunt Antenna - Removal / Installation		HRS		3113.6			408.8			0
			AFL		642			85			0
	60P5531601A004	1738905	MOS		109.6			06 Nov 2015			
			MSC				O/C				
Airframe											
231310	HF Antenna Coupler Unit (No. 1) - Removal / Installation		HRS		0			3522.4			0
			AFL		0			727			0
	622-8114-002	1470	MOS		2.4			14 Oct 2024			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231311	HF Antenna Coupler Unit (No. 2) - Removal / Installation		HRS		0			3522.4			0
	622-8114-002\2-11	6184	AFL		0			727			0
			MOS		2.4			14 Oct 2024			N/A
	Airframe		MSC				O/C				
231314	HF Antenna Coupler Unit (No. 1) - Servicing		HRS		1294.7			2227.7			0
			AFL		265			462			0
			MOS		58.2			19 Feb 2020			
	Airframe		MSC				O/C				
231315	HF Antenna Coupler Unit (No. 2) - Servicing		HRS		1294.7			2227.7			0
			AFL		265			462			0
			MOS		58.2			19 Feb 2020			
	Airframe		MSC				O/C				
231316	HF R/T (No. 1) Mounting Tray / Shock Mount - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	622-8116-001	9508	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231318	HF R/T (No. 2) Mounting Tray / Shock Mount - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	622-8116-001	9507	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231320	HF R/T (No. 2) - Removal / Installation		HRS		113.9			3408.5			0
	822-0102-001	4435	AFL		36			691			0
			MOS		13.8			01 Nov 2023			N/A
	Airframe		MSC				O/C				
231400	Satellite Transceiver - Removal / Installation		HRS		3522.4			0			0
	P12023\V	1202313713	AFL		727			0			0
	V		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231401	Dual Channel Satellite Antenna - Removal / Installation		HRS	TSN:2364.2	1158			2364.4			0
	S67-1575-165	449-6620	AFL	TSN:487	239			488			0
			MOS	TSN:78	50.4			15 Oct 2020			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231402	Satellite Interface Unit - Removal / Installation		HRS		3522.4			0			0
	P12777\G	1277711360	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231403	Satellite Telephone		HRS		3522.4			0			0
	P12023\V	1202313713	AFL		727			0			0
		V	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 231400											
231404	Remote Diversity Antenna (No. 1) - Removal / Installation		HRS		3522.4			0			0
	S67-1575-165	449-6620	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 231401											
231405	Remote Diversity Antenna (No. 2) - Removal / Installation		HRS		3522.4			0			0
	P12777\G	1277711360	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 231402											
231406	In-Flight Telecommunications - Operational Check		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.6			06 Oct 2021			
	Airframe		MSC				O/C				
231407	Radio Frequency Filter - Removal / Installation		HRS		3522.4			0			0
	P13167	1316710669	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231408	Audio Bell (Crew Rest) - Removal / Installation		HRS		3522.4			0			0
	P13167	1316710669	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 231407											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231419	Cockpit Handset - Removal / Installation		HRS		873.6			2648.8			0
	P12793-011	1279372038	AFL		166			561			0
			MOS		38.9			30 Sep 2021			
	Airframe		MSC				O/C				
231420	Cockpit Handset Interface Unit - Removal / Installation		HRS		3522.4			0			0
	P12346\D	1234611913	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231425	Call Alerter - Removal / Installation		HRS		3522.4			0			0
	P12924\B	1292411853	AFL		727			0			0
	0	0	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231426	Call Speaker (Galley) - Removal / Installation		HRS		3522.4			0			0
	P12924\B	1292411853	AFL		727			0			0
	0	0	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 231425											
231430	Cabin Telecommunication Router - Removal / Installation		HRS		3522.4			0			0
	P12083-001\E	1208372706	AFL		727			0			0
		E	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231441	Aircell Lh Fwd Cabin Seat Handset - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	PN	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231442	Aircell Rh Fwd Cabin Seat Handset - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	PN	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231443	Aircell Lh Aft Cabin Seat Handset - Removal / Installation		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231444	Aircell Rh Aft Cabin Seat Handset - Removal / Installation		HRS		3522.4			0			0
	PN SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231500	SATCOM - Operational Check		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		124.1			22 Aug 2014			
	Airframe		MSC				O/C				
231502	Diplexer / Low Noise Amplifier - Removal / Installation		HRS		3522.4			0			0
	173628-101 1227-0378		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231503	SATCOM Antenna - Removal / Installation		HRS		3522.4			0			0
	806-10-1001-5\A,B OP000985		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231507	SATCOM Antenna - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
231508	Satellite Data Unit - Removal / Installation		HRS	TSN:13.3	3509.1			13.3			0
	1252-A-3800-01\1-12 1855		AFL	TSN:5	722			5			0
			MOS	TSN:2	126			25 Jun 2014			
	Airframe		MSC				O/C				
232000	Selective Calling / Data Link - Operational Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
232700	Vmbr-1500 (Bbml) - Removal / Installation		HRS		1508.2			2014.2			0
	1054023 00-002841		AFL		311			416			0
			MOS		62.9			30 Sep 2019			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
232701	Antenna Control Unit - Removal / Installation		HRS		3509.1			13.3			0
	1067697	50204-10923	AFL		722			5			0
			MOS		123			27 Sep 2014			COLLINS
	Airframe		MSC					O/C			
232702	Broad Band Multi-Link Antenna - Removal / Installation		HRS		1431.3			2091.1			0
	1060076	50204-0857	AFL		296			431			0
			MOS		61.1			22 Nov 2019			
	Airframe		MSC					O/C			
232902	Advanced Cabin Server (No. 1) - Removal / Installation		HRS		113.9			3408.5			0
	ACS-04-001	00671	AFL		36			691			0
			MOS		14			25 Oct 2023			N/A
	Airframe		MSC					O/C			
232903	Advanced Cabin Server (No. 2) - Removal / Installation		HRS		113.9			3408.5			0
	ACS-04-001	00684	AFL		36			691			0
			MOS		14			25 Oct 2023			N/A
	Airframe		MSC					O/C			
232906	Wireless Local AREA Network Interface / Broadband Multi -Link - Adjustment / Test		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.9			30 Oct 2023			
	Airframe		MSC					O/C			
232910	SATCOM Direct Router - Removal / Installation		HRS		485.9			3036.5			0
	TN1021-100 REV. P03	2113	AFL		97			630			0
			MOS	TSN:18	25.5			10 Nov 2022			SATCOM DIRECT
	Airframe		MSC					O/C			AVIONICS
233000	3G/4G Antenna - Removal / Installation		HRS		485.9			3036.5			0
	P18350-001	1835004729	AFL		97			630			0
			MOS	TSN:43	25.5			09 Nov 2022			GOGO BUSINESS
	Airframe		MSC					O/C			AVIATION LLC
233018	Switching Node, Cabin 4 Lh Psu - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001	04117	AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233019	Switching Node, Cabin 4 Rh Psu - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04144		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233020	Switching Node, Lh Fwd Psu - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04112		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233021	Switching Node, Lh Mid Psu - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04113		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233022	Switching Node, Lh Aft Psu - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04114		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233023	Switching Node, Rh Fwd Psu - Removal / Installation		HRS		3396.7			125.7			0
	GCMS-01-001		AFL		702			25			0
	02207*		MOS		120.1			24 Dec 2014			QUALITEL
	Airframe		MSC				O/C				
233024	Switching Node, Rh Mid Psu - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04135		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233025	Switching Node, Rh Aft Psu - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04136		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233026	Switching Node, Lh Fwd Ledge #1 - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04116		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233027	Switching Node, Lh Fwd Ledge #2 - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04115		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233028	Switching Node, Lh Mid Ledge #1 - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04133		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233029	Switching Node, Lh Mid Ledge #2 - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04119		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233030	Switching Node, Lh Aft Ledge #1 - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04680		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233031	Switching Node, Lh Aft Ledge #2 - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04141		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233032	Switching Node, Rh Fwd Ledge #1 - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04121		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233033	Switching Node, Rh Fwd Ledge #2 - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04122		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233034	Switching Node, Rh Mid Ledge #1 - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001		AFL		722			5			0
	04123		MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233035	Switching Node, Rh Mid Ledge #2 - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001 04124		AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233036	Switching Node, Rh Aft Ledge #1 - Removal / Installation		HRS		2624.5			897.9			0
	GCMS-01-001 04444		AFL		535			192			0
			MOS		95			27 Jan 2017			QUALITEL
	Airframe		MSC				O/C				
233037	Switching Node, Rh Aft Ledge #2 - Removal / Installation		HRS		2039.9			1482.5			0
	GCMS-01-001 08230		AFL		423			304			0
			MOS		79.3			17 May 2018			QUALITEL
	Airframe		MSC				O/C				
233038	Switching Node, Fwd Lh Closet - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001 04054		AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233039	Switching Node, Fwd Lav - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001 04065		AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233040	Switching Node, Aft Lav Vanity - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001 04053		AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233041	Switching Node, Aft Lav Toilet - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001 04145		AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233042	Switching Node, Galley - Removal / Installation		HRS		3509.1			13.3			0
	GCMS-01-001 04069		AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233100	Avds Node - Rh Fwd - Removal / Installation		HRS		3509.1			13.3			0
	100-0037-01	121072N0004	AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233102	Avds Node - Rh Aft - Removal / Installation		HRS		3509.1			13.3			0
	100-0037-01	121072N0005	AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233103	Avds Node - Lh Fwd - Removal / Installation		HRS		.4			3522			0
	100-0038-01	122846N003	AFL		1			726			0
			MOS		2.5			11 Oct 2024			N/A
	Airframe		MSC				O/C				
233105	Avds Node - Lh Aft - Removal / Installation		HRS		3509.1			13.3			0
	100-0038-01	121304N0004	AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233106	Avds Node - Baggage Upper - Removal / Installation		HRS		3509.1			13.3			0
	100-0024-01	120932N0009	AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233107	Avds Node - Baggage Lower - Removal / Installation		HRS		3509.1			13.3			0
	100-0024-01	121472N0005	AFL		722			5			0
			MOS		123			27 Sep 2014			QUALITEL
	Airframe		MSC				O/C				
233400	Cabin Entertainment Audio - Adjustment / Test		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			10 Oct 2024			
	Airframe		MSC				O/C				
233406	Audio Control Panel (Right Seat No. 1) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	RCO36791	1765	MOS		38.9			30 Sep 2021			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233407	Audio Control Panel (Right Seat No. 2) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	RCO36792	1257	MOS	TSN:3	75.2			21 Sep 2018			N/A
			MSC				O/C				
Airframe											
233408	Audio Control Panel (Right Seat No. 3) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	RCO36791	1764	MOS		38.9			30 Sep 2021			N/A
			MSC				O/C				
Airframe											
233409	Audio Control Panel (Right Seat No. 4) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	RCO36792	1261	MOS		75.2			21 Sep 2018			N/A
			MSC				O/C				
Airframe											
233410	Audio Control Panel (Right Seat No. 5) - Removal / Installation		HRS		1841.9			1680.5			0
			AFL		384			343			0
	RCO36791	1162-R	MOS	TSN:2	74			27 Oct 2018			N/A
			MSC				O/C				
Airframe											
233411	Audio Control Panel (Right Seat No. 6) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	RCO36792	1262	MOS	TSN:3	75.2			21 Sep 2018			N/A
			MSC				O/C				
Airframe											
233413	Audio Control Panel (Left Seat No. 1) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	RCO36792	1554	MOS	TSN:8	50.6			08 Oct 2020			N/A
			MSC				O/C				
Airframe											
233414	Audio Control Panel (Left Seat No. 2) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	RCO36791	1050-R	MOS	TSN:3	75.2			19 Sep 2018			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233416	Audio Control Panel (Left Seat No. 4) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	RCO36791	1065-R	MOS	TSN:3	75.2			21 Sep 2018			N/A
			MSC				O/C				
Airframe											
233500	Cabin Entertainment Video - Adjustment Test		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			10 Oct 2024			
			MSC				O/C				
Airframe											
233554	Hdmi Panel(Left Seat No. 1) - Removal / Installation		HRS		873.6			2648.8			0
	17339-1	NSN	AFL		166			561			0
			MOS	TSN:80	38.9			30 Sep 2021			N/A
			MSC				O/C				
Airframe											
233601	Advanced Cabin Server #1 - Restore		HRS		113.9			3408.5			0
	234-17-8020-10	NSN	AFL		36			691			0
			MOS		14			25 Oct 2023	10 Oct 2027		
			MSC				DUE				EXPIRATION
Airframe			[End Of Month Item]								
Notes: NEXT DUE PER CUSTOMER"S REQUEST.											
233602	Advanced Cabin Server # 2 - Restore		HRS		113.9			3408.5			0
	234-17-8020-10	NSN	AFL		36			691			0
			MOS		14			25 Oct 2023	25 Oct 2027		
			MSC				DUE				EXPIRATION
Airframe			[End Of Month Item]								
Notes: NEXT DUE PER CUSTOMER"S REQUEST.											
233700	Aft / Forward Facing Belly Camera - Removal / Installation		HRS		3522.4			0			0
	100-2689-03	1142451	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
233702	Fin CAP Camera - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	100-2687-03	1141245	AFL	TSN:630	97			630			0
			MOS	TSN:102	25.8			01 Nov 2022			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233704	Video Control Unit - Removal / Installation		HRS		3522.4			0			0
	100-2415-01	1138743	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
233706	Video Distribution Module - Removal / Installation		HRS		3522.4			0			0
	MSM2925-01-1	091300019	AFL		727			0			0
		C1	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
233708	Camera Systems - Operational Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.8			02 Nov 2022			
	Airframe		MSC				O/C				
233720	Audio Control Panel (Lh Double Seat I/B Fwd) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	RCO36793	0891-R	MOS		75.2			19 Sep 2018			N/A
	Airframe		MSC				O/C				
233721	Audio Control Panel (Lh Double Seat O/B Fwd) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	RCO36794	1370-R	MOS		75.2			19 Sep 2018			N/A
	Airframe		MSC				O/C				
233722	Audio Control Panel (Lh Double Seat I/B Aft) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	RCO36794	1354-R	MOS		75.2			19 Sep 2018			N/A
	Airframe		MSC				O/C				
233723	Audio Control Panel (Lh Double Seat O/B Aft) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	RCO36793	0897-R	MOS		75.2			19 Sep 2018			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
235000	Typical Passenger Service Unit Speaker (Left No. 1) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106508-630-4G6001	200820	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											
235001	Typical Passenger Service Unit Speaker (Left No. 2) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106508-630-4G6001	200821	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											
235002	Typical Passenger Service Unit Speaker (Left No. 3) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106508-630-4G6001	200829	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											
235003	Typical Passenger Service Unit Speaker (Left No. 4) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106508-630-4G6001	200835	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											
235006	Typical Passenger Service Unit Speaker (Right No. 1) - Removal / Installation		HRS	TSN:13.8	3495.3			27.1			0
			AFL	TSN:3	719			8			0
	106508-630-4G6001	200837	MOS	TSN:1	122.2			19 Oct 2014			ALTO
			MSC				O/C				
Airframe											
235007	Typical Passenger Service Unit Speaker (Right No. 2) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106508-630-4G6001	200839	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											
235008	Typical Passenger Service Unit Speaker (Right No. 3) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106508-630-4G6001	200840	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
235009	Typical Passenger Service Unit Speaker (Right No. 4) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106508-630-4G6001	200843	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											
235013	Forward Cabin Speaker AMP - Removal / Installation		HRS		2312.5			1209.9			0
			AFL		479			248			0
	106500-0600-10000	070935	MOS	TSN:4	87			26 Sep 2017			
			MSC				O/C				
Airframe											
235014	Aft Cabin Speaker AMP - Removal / Installation		HRS		2312.5			1209.9			0
			AFL		479			248			0
	106500-0600-10000	070936	MOS	TSN:4	87			26 Sep 2017			
			MSC				O/C				
Airframe											
235019	Subwoofer Speaker (Divan Center) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106511-565-4G6001	270337	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											
235020	Subwoofer Speaker (Right Seat No. 1) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106511-565-4G6001	270334	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											
235023	Subwoofer Speaker (Left Seat No. 4) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106511-565-4G6001	270335	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											
235024	Subwoofer Speaker (Left Seat No. 5) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106511-565-4G6001	270336	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
235031	Lavatory Speaker (Forward Lavatory) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106508-630-4G6001	200836	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											
235032	Lavatory Speaker (Aft Lavatory) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	106508-630-4G6001	200834	MOS		123			27 Sep 2014			ALTO
			MSC				O/C				
Airframe											
235035	Galley Speaker (Forward Galley) - Removal / Installation		HRS		3509.1			13.3			0
	DT-PA2N		AFL		722			5			0
		133803024	MOS		123			27 Sep 2014			DT SYSTEMS
			MSC				O/C				
Airframe											
235041	Right Divan Forward Audio Video Switch Panel - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RCO36790	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
235042	Right Divan Forward Audio Video Switch Panel #2 - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	RCO36789	2277	MOS	TSN:16	49.9			29 Oct 2020			
			MSC				O/C				
Airframe											
Notes: REF 6.7 FOR WORK PERFORMED.											
235050	Audio Integrating System - Operational Check		HRS		-17.5			3539.9			0
			AFL		-10			737			0
			MOS		.7			03 Dec 2024			
			MSC				O/C				
Airframe											
235061	Switch Panel (Left Seat No.3) - Removal / Installation		HRS		1841.9			1680.5			0
			AFL		384			343			0
	RCO36792	0890-R	MOS	TSN:2	73.9			28 Oct 2018			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
235066	Switch Panel (Right Seat No.2) - Removal / Installation		HRS		2307.2			1215.2			0
	RCO36792 0409-R		AFL		477			250			0
			MOS		86.9			29 Sep 2017			
	Airframe		MSC				O/C				
235071	Switch Panel (Conference Table Forward Inboard Seat) - Removal / Installation		HRS		3522.4			0			0
	PN SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
235072	Switch Panel (Conference Table Forward Outboard Seat) - Removal / Installation		HRS		3522.4			0			0
	PN SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
235073	Switch Panel (Conference Table Aft Inboard Seat) - Removal / Installation		HRS		3522.4			0			0
	PN SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
235074	Switch Panel (Conference Table Aft Outboard Seat) - Removal / Installation		HRS		3522.4			0			0
	PN SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
235200	Audio Control Panel (Pilot) - Removal / Installation		HRS		3522.4			0			0
	7511900-90302\AS 1310D875		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
235201	Audio Control Panel (Copilot) - Removal / Installation		HRS		3522.4			0			0
	7511900-90302\AS 1311D890		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
235202	Audio Control Panel (Observer) - Removal / Installation		HRS		-17.5			3539.9			0
	7511900-90302\AS	1301C894	AFL		-10			737			0
			MOS		.7			03 Dec 2024			
	Airframe		MSC				O/C				
235206	Audio Control Panel Sidetone - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
235303	Communication Jack Panels - (Observer) - Removal / Installation		HRS	TSN:2014.2	1508.2			2014.2			0
			AFL	TSN:416	311			416			0
	60P3110913A001	NSN	MOS	TSN:65	63.3			18 Sep 2019			N/A
	Airframe		MSC				O/C				
235307	Audio Integrating System Input / Output Device - Operational Check		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		63.3			18 Sep 2019			
	Airframe		MSC				O/C				
235308	Oxygen Mask Microphone - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			10 Oct 2024			
	Airframe		MSC				O/C				
235400	Network / Audio Interface Module (No. 1) - Removal / Installation		HRS	TSN:1483.9	1912.8			1609.6			0
			AFL	TSN:305	397			330			0
	60000091-918	13090536	MOS	TSN:44	75.3			18 Sep 2018			N/A
	Airframe		MSC				O/C				
235401	Network / Audio Interface Module (No. 2) - Removal / Installation		HRS	TSN:1483.9	1912.8			1609.6			0
			AFL	TSN:305	397			330			0
	60000091-918	13090538	MOS	TSN:59	75.3			18 Sep 2018			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
236130	Static Discharging (Left Wing) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	26	48	05 Oct 2022	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
236131	Static Discharging (Right Wing) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	26	48	05 Oct 2022	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
236132	Static Discharging (Left Horizontal Stablizer) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.1		48	23 Nov 2022	30 Nov 2026	31 Dec 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
236133	Static Discharging (Right Horizontal Stablizer) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.1		48	23 Nov 2022	30 Nov 2026	31 Dec 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
236134	Static Discharging (Center Horizontal Stablizer) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	26	48	05 Oct 2022	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
236135	Static Discharging (Tail Cone) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	26	48	05 Oct 2022	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
237000	Bulkhead Monitor (Aft Bulkhead Right) - Removal / Installation		HRS		1508.2			2014.2			0
			AFL		311			416			0
	2601-201	16060041	MOS		63			27 Sep 2019			N/A
			MSC				O/C				
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237001	Bulkhead Monitor (Forward Bulkhead Right) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	2601-201	14050190	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237003	Bulkhead Monitor (Midcabin Bulkhead Forward Right) - Removal / Installation		HRS	TSN:3.85	1508.2			2014.2			0
			AFL	TSN:42	311			416			0
	2401-201	14040300	MOS		63			27 Sep 2019			
			MSC				O/C				
Airframe											
237006	Seat Armrest Monitor (Left Seat No. 1) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	1200-128	13060353	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237008	Seat Armrest Monitor (Left Seat No. 2) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	1200-129	13030187	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237009	Seat Armrest Monitor (Left Seat No. 3) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	1200-128	13070117	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237010	Seat Armrest Monitor (Left Seat No. 4) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	1200-129	13060083	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237014	Seat Armrest Monitor (Right Seat No. 1) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	1200-129	12120199	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237015	Seat Armrest Monitor (Right Seat No. 2) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	1200-128	13070112	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237016	Seat Armrest Monitor (Right Seat No. 3) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	1200-129	13060046	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237017	Seat Armrest Monitor (Right Seat No. 4) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	1200-128	13070119	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237023	Dual Blu-Ray DVD Player #1 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	0602-205	14050170	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237025	Vestibule Touch Screen Switch Panel - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	DLT-0571D	GD0023	MOS		75			26 Sep 2018			N/A
			MSC				O/C				
Airframe											
237026	Galley T/S Monitor - Removal / Installation		HRS		285.9			3236.5			0
			AFL		61			666			0
	DLT-1011D-01	AA0183	MOS		18.4			15 Jun 2023			
			MSC				O/C				
Airframe											
237028	Seat Armrest Monitor (Right Seat No. 5) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	1200-129	14050161	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237029	Seat Armrest Monitor (Right Seat No. 6) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	1200-128	14050117	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237088	Left Forward Cabin Remote Monitor Electronics Box - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	0700-105	14020187	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237098	Right Aft Remote Monitor Electronics Box - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	0700-105	14030299	MOS		123			27 Sep 2014			ROSEN
			MSC				O/C				
Airframe											
237200	Cockpit Voice Recorder - Removal / Installation		HRS	TSN:1609.6	1912.8			1609.6			0
	1606-01-00,200002,200201\		AFL	TSN:330	397			330			0
		741	MOS	TSN:53	75.2			21 Sep 2018			N/A
			MSC				O/C				
Airframe											
237202	Cockpit Voice Recorder System - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1	38	12	23 Sep 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
237203	Remote Cockpit Control Unit - Removal / Installation		HRS		3522.4			0			0
	1642-110-02,200400		AFL		727			0			0
		508	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
237205	Cockpit AREA Microphone - Removal / Installation		HRS		3522.4			0			0
	16301-02		AFL		727			0			0
		4682	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237211	Cockpit Voice Recorder Impact Switch - Removal / Installation		HRS	TSN:3408.5	113.9			3408.5			0
			AFL	TSN:691	36			691			0
	1159SCAV402-2	4849	MOS	TSN:113	14.2			19 Oct 2023			N/A
			MSC				O/C				
Airframe											
237213	Cockpit Voice Recorder Impact Switch - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.2		72	19 Oct 2023	31 Oct 2029	30 Nov 2029	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
237214	Cockpit Voice Recorder Underwater Locator Beacon - Removal / Installation		HRS	TSN:1601.9	310.9			3211.5			0
			AFL	TSN:333	64			663			0
	DK120/90	AT121376	MOS	TSN:56	19.4			15 May 2023			
			MSC				O/C				
Airframe											
237216	Cockpit Voice Recorder Underwater Locator Beacon - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1		24	23 Sep 2024	30 Sep 2026	31 Oct 2026	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
237217	Cockpit Voice Recorder Underwater Locator Beacon - Cleaning		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1		24	23 Sep 2024	30 Sep 2026	31 Oct 2026	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
237220	Cockpit Voice Recorder Underwater Locator Beacon Battery - Discard		HRS		1912.8			1609.6			0
			AFL		397			330			0
	DK120/90	AT121376	MOS		75.2		84	21 Sep 2018	31 Oct 2025		
	[End Of Month Item]										
Airframe											
237222	Cockpit Voice Recorder Underwater Locator Beacon - Battery Replacement		HRS		1912.8			1609.6			0
			AFL		397			330			0
	DK120/90	AT121376	MOS		75.2			21 Sep 2018			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237223	Cockpit Voice Recorder Underwater Locator Beacon		HRS		3522.4			0			0
	Battery - Functional Check		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
24 - Electrical Power											
240010	Cockpit Circuit Breaker Panel - Removal / Installation		HRS		3522.4			0			0
	134TS11Y02	0184	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
241206	Idg Oil Transfer Tubes / Fittings (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
241207	Idg Oil Transfer Tubes / Fittings (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
241212	Idg Oil Cooler and Lines (Left) - General Visual Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	26	12	05 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
241213	Idg Oil Cooler and Lines (Right) - General Visual Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	26	12	05 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
242100	Integrated Drive Generator (Left) - Removal / Installation		HRS		3522.4			0			0
	1159SCAV500-3	1679	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242102	Idg - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
242103	Integrated Drive Generator (Right) - Removal / Installation 1159SCAV500-31655		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
242106	AC Generation: Engine Generators - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691		0	
			MOS		13.8			31 Oct 2023			
			MSC				O/C				
242107	Idg Disconnect System (Left) - Operational Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
242108	Idg Disconnect System (Right) - Operational Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
242109	Idg (Left) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.7			03 Oct 2024			
			[HRS: +50/-50]								
242110	Idg (Right) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.7			03 Oct 2024			
			[HRS: +50/-50]								
242111	Idg (Left) - Oil Level Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7			03 Oct 2024			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Logbook Position	Part Number									Serial Number
HW		SW									Manufacturer
MM Ref		Date Type									
Ops Number(s)											
242112	Idg (Right) - Oil Level Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7			03 Oct 2024			
	Airframe		MSC				O/C				
242117	Idg Oil Scavenge Filter Differential Pressure Indicator (Left) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7			03 Oct 2024			
	Airframe		MSC				O/C				
242118	Idg Oil Scavenge Filter Differential Pressure Indicator (Right) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7			03 Oct 2024			
	Airframe		MSC				O/C				
242200	APU Generator - Removal / Installation 1159SCAV501-11197		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
242208	AC Generation: APU AC Generation - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.8			31 Oct 2023			
	Airframe		MSC				O/C				
242301	Ram AIR Turbine Assembly - Removal / Installation 17123860208		HRS	TSN:3522	.4			3522			0
			AFL	TSN:726	1			726			0
			MOS	TSN:125	2.5			12 Oct 2024			N/A
	Airframe		MSC				O/C				
242302	Ram AIR Turbine Generator Control Unit - Removal / Installation 17123880215N/A		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
242303	Ram AIR Turbine Restow Pump - Removal / Installation 5915296C0104		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242304	Ram AIR Turbine Control Handle Assembly - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2423013Z001	207	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
242306	Ram AIR Turbine Deploy / Stow Operation - Maintenance Practice		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			12 Oct 2024			
			MSC				O/C				
Airframe											
242308	Ram AIR Turbine Ground - Functional Check		HRS		.4		1200	3522	4722	4772	0
			AFL		1			726			0
			MOS		2.5		24	12 Oct 2024	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
242312	Ram AIR Turbine - General Visual Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
242313	Ram AIR Turbine Control Assembly - Rigging		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
242314	Ram AIR Turbine Control Assembly - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
242315	Restow Pump Hydraulic Fluid Fill - Servicing		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
242316	Restow Pump Bleeding - Servicing		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242317	Ram AIR Turbine Assembly - Rigging		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			12 Oct 2024			
	Airframe		MSC				O/C				
242320	Ram AIR Turbine Deploy Actuator - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
242321	Ram AIR Turbine Deploy Actuator - Removal / Installation		HRS		3522.4			0			0
	1712390	0207	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
242331	Ram AIR Turbine Current Transformer Assembly - Removal / Installation		HRS		3522.4			0			0
	307-1	414CV1	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
242351	Ram AIR Turbine Built-In Test Switch - Operational Check		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.5		24	12 Oct 2024	31 Oct 2026	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
242500	Idg (Left) Generator Control Unit - Removal / Installation		HRS		3522.4			0			0
	1702787B\1	1983	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
242501	Idg (Right) Generator Control Unit - Removal / Installation		HRS	TSN:3408.5	113.9			3408.5			0
	1702787B\1	2672	AFL	TSN:691	36			691			0
			MOS	TSN:114	14			26 Oct 2023			N/A
	Airframe		MSC				O/C				
242502	APU Generator Control Unit - Removal / Installation		HRS	TSN:3408.5	113.9			3408.5			0
	1702787B\1	2676	AFL	TSN:691	36			691			0
			MOS	TSN:114	14			26 Oct 2023			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242720	60 HZ Converter (Left) - Removal / Installation		HRS		1841.9			1680.5			0
	717220-2R	10161411	AFL		384			343			0
			MOS		73.9			29 Oct 2018			GE Aviation
	Airframe		MSC				O/C				Systems
242721	60 HZ Converter (Right) - Removal / Installation		HRS		339.5			3182.9			0
	717220-2R	03150921	AFL		69			658			0
			MOS		20.2			20 Apr 2023			
	Airframe		MSC				O/C				
242724	60 HZ Converter - Operational Test		HRS		339.5			3182.9			0
			AFL		69			658			0
			MOS		20.2			20 Apr 2023			
	Airframe		MSC				O/C				
Notes: COMPLIANCE LIST CORRIDOR 11.25											
243000	Tail Compartment Direct Current Feeder Cables - Detailed		HRS		3522.4			0			0
	Inspection		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
243300	Transformer Rectifier Unit Hall Effect Sensor (L Main		HRS		3522.4			0			0
	HE1) - Removal / Installation		AFL		727			0			0
	1159SCAV507-3	42YCY6	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
243301	Transformer Rectifier Unit Hall Effect Sensor (R Main		HRS		3522.4			0			0
	HE2) - Removal / Installation		AFL		727			0			0
	1159SCAV507-3	42YCDH	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
243302	Transformer Rectifier Unit Hall Effect Sensor (L Ess HE3)		HRS		3522.4			0			0
	- Removal / Installation		AFL		727			0			0
	1159SCAV507-3	42YCMN	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243303	Transformer Rectifier Unit Hall Effect Sensor (R Ess HE4)		HRS		3522.4			0			0
	- Removal / Installation		AFL		727			0			0
	1159SCAV507-3	42YCDL	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
243307	Transformer Rectifier Unit Hall Effect Sensor (Aux HE8) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	1159SCAV507-3	42YCDG	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
243315	Transformer Rectifier Unit (L Ess) - Removal / Installation		HRS		1508.2			2014.2			0
	8-832-03	245113-506	AFL		311			416			0
			MOS		62.9			30 Sep 2019			
			MSC				O/C				
Airframe											
243316	Transformer Rectifier Unit (R Ess) - Removal / Installation		HRS		1508.2			2014.2			0
	8-832-03	245113-1326	AFL		311			416			0
			MOS		62.9			30 Sep 2019			
			MSC				O/C				
Airframe											
243317	Transformer Rectifier Unit (Aux) - Removal / Installation		HRS		1508.2			2014.2			0
	8-832-03	245113-500	AFL		311			416			0
			MOS		62.9			30 Sep 2019			
			MSC				O/C				
Airframe											
243318	Transformer Rectifier Unit (L Main) - Removal /		HRS	TSN:1072.1	1508.2			2014.2			0
	Installation		AFL	TSN:225	311			416			0
	8-832-03	245113-1111	MOS	TSN:2	62.9			30 Sep 2019			
			MSC				O/C				
Airframe											
243319	Transformer Rectifier Unit (R Main) - Removal /		HRS		1508.2			2014.2			0
	Installation		AFL		311			416			0
	8-832-03	245113-498	MOS		62.9			30 Sep 2019			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243329	Auxiliary Transformer Rectifier Unit AC Contactor - Operational Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
243336	Transformer Rectifier Unit - Inspection / Cleaning		HRS		1508.2			2014.2			0
			AFL		311			416		0	
			MOS		62.9			30 Sep 2019			
			MSC				O/C				
Airframe											
Notes: PN: 980-6113-010 SN: <NONE>.											
243400	Main Battery (Left) - Removal / Installation 1159SCAV519-1 09052001986D7		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.9			30 Sep 2024		N/A	
			MSC				O/C				
Airframe											
243401	Main Battery (Right) - Removal / Installation 1159SCAV519-1 090520015C9F4		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.9			30 Sep 2024		N/A	
			MSC				O/C				
Airframe											
243404	Main Battery (Left) - Restore		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.9	-6	12	30 Sep 2024	30 Sep 2025*	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
243405	Main Battery (Right) - Restore		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.9	-6	12	30 Sep 2024	30 Sep 2025*	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
243406	Main Battery (Left) - Operational Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
243407	Main Battery (Right) - Operational Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243408	Main Battery (Left) - Voltage Check		HRS		.4			3522		0	
			AFL		1		726		0		
			MOS		2.6		08 Oct 2024				
			MSC			O/C					
243409	Main Battery (Right) - Voltage Check		HRS		.4			3522		0	
			AFL		1		726		0		
			MOS		2.6		08 Oct 2024				
			MSC			O/C					
243414	Main Battery Charger (Left) - Operational Test		HRS		1158			2364.4		0	
			AFL		239		488		0		
			MOS		50.2		20 Oct 2020				
			MSC			O/C					
243415	Main Battery Charger (Right) - Operational Test		HRS		1158			2364.4		0	
			AFL		239		488		0		
			MOS		50.2		20 Oct 2020				
			MSC			O/C					
243416	Main Battery Charger (Left) - Removal / Installation 100-1311-01 1137943M		HRS		1508.2			2014.2		0	
			AFL		311		416		0		
			MOS		63		27 Sep 2019				
			MSC			O/C					
243417	Main Battery Charger (Right) - Removal / Installation 100-1311-01 1164093M		HRS		1508.2			2014.2		0	
			AFL		311		416		0		
			MOS		63		27 Sep 2019				
			MSC			O/C					
243424	Left Main Battery Hall Effect Sensor (HE7) - Removal / Installation 1159SCAV507-3 427LFY		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
243425	Right Main Battery Hall Effect Sensor (HE6)- Removal / Installation 1159SCAV507-3 427LFX		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243436	Main Battery (Left) - Inspection / Check		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		123.3			16 Sep 2014			
			MSC				O/C				
Airframe											
Notes: PN: 1159SCAV519-1 SN: 090520016296D.											
243437	Main Battery (Right) - Inspection / Check		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		123.3			16 Sep 2014			
			MSC				O/C				
Airframe											
Notes: PN: 1159SCAV519-1 SN: 090520016296C.											
243500	Emergency Battery Power System (Forward) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	-4	12	08 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
243501	Emergency Battery Power System (Aft) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	-13	12	07 Oct 2024	30 Sep 2025*	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
243502	Emergency Battery (Forward) - Functional Check (Level Test)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1	9	24	23 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
243503	Emergency Battery (Aft) - Functional Check (Level Test)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1	9	24	23 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
243504	Emergency Battery Pack (Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243505	Emergency Battery Pack (Aft) - Removal / Installation		HRS		2191.3			1331.1			0
	100-0302-03	P4759	AFL		451			276			0
			MOS		83.8			31 Dec 2017			
	Airframe		MSC				O/C				
243508	Emergency Battery (Forward) - Restore		HRS		873.6			2648.8			0
	100-0302-03	P4924	AFL		166			561			0
			MOS		38.7		48	04 Oct 2021	31 Oct 2025		
	Airframe		[End Of Month Item]								
Notes: FWD E-BATT FAILED OPERATIONAL TEST. REPLACED WITH NEW BATTERY.											
243509	Emergency Battery (Aft) - Restore		HRS		873.6			2648.8			0
	100-0302-03	P4256	AFL		166			561			0
			MOS		38.7		48	04 Oct 2021	31 Oct 2025		
	Airframe		[End Of Month Item]								
Notes: AFT E-BATT FAILED FUNCTIONAL CHECK. REPLACED WITH NEW BATTERY.											
243510	Forward Emergency Battery - Removal / Installation		HRS		873.6			2648.8			0
	100-0302-03	P4316	AFL		166			561			0
			MOS		38.7			04 Oct 2021			
	Airframe		MSC				O/C				
Notes: REF 25.22, 25.24, & 26.16											
243511	Aft Emergency Battery - Removal / Installation		HRS		873.6			2648.8			0
	100-0302-03	P4759	AFL		166			561			0
			MOS		38.7			04 Oct 2021			
	Airframe		MSC				O/C				
Notes: REF 25.23, 25.23, & 26.17											
243600	Electrical Backup Hydraulic Actuator Power Distribution		HRS		3522.4			0			0
	Box - Removal / Installation		AFL		727			0			0
	1712488A	0118	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
243602	Electrical Backup Hydraulic Actuator Battery Hall Effect		HRS		3522.4			0			0
	Sensor (HE9) - Removal / Installation		AFL		727			0			0
	1159SCAV507-3	427LKP	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
243606	Electrical Backup Hydraulic Actuator Battery - Operational Test		HRS		.4			3522			0	
			AFL		1			726			0	
			MOS		2.6			08 Oct 2024				
			MSC				O/C					
Airframe												
243607	Electrical Backup Hydraulic Actuator Nicad Battery - Restore		HRS		.4			3522			0	
			AFL		1			726			0	
			MOS		2.9	31	12	30 Sep 2024	31 Oct 2025*	30 Nov 2025		
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
243608	Ebha Battery - Inspection / Check		HRS		3509.1			13.3			0	
			AFL		722			5			0	
			MOS		123.3			16 Sep 2014				
			MSC				O/C					
Airframe												
Notes: PN: 1159SCAV519-1 SN: 0905200119E05.												
243610	Electrical Backup Hydraulic Actuator Battery - Removal / Installation		HRS		.4			3522			0	
			AFL		1			726			0	
			1159SCAV519-1	09052001EC9B7	MOS		2.9		30 Sep 2024			N/A
					MSC				O/C			
Airframe												
243611	Electrical Backup Hydraulic Actuator Battery Charger (No. 1) - Removal / Installation		HRS		1508.2			2014.2			0	
			AFL		311			416			0	
			100-1311-01	1149787M	MOS		62.9		29 Sep 2019			
					MSC				O/C			
Airframe												
243612	Electrical Backup Hydraulic Actuator Battery Charger (No. 2) - Removal / Installation		HRS		1158			2364.4			0	
			AFL		239			488			0	
			PN	NOT INSTALLED	MOS		50.5		12 Oct 2020			
					MSC				O/C			
Airframe												
243900	Uninterruptible Power Supply Battery Hall Effect Sensor (HE10) - Removal / Installation		HRS		3522.4			0			0	
			AFL		727			0			0	
			1159SCAV507-3	4JF2L	MOS	TSN:4	128.2		21 Apr 2014			
			0	0	MSC				O/C			
Airframe												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243902	Uninterruptible Power Supply Battery - Operational Test		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.8			01 Oct 2024			
			MSC				O/C				
Airframe											
Notes: COMPLIED WITH CMP G650 243902 AIRFRAME UNINTERRUPTIBLE POWER SUPPLY BATTERY - OPERATIONAL TEST											
243903	Uninterruptible Power Supply Sealed Lead ACID Battery - Functional Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	26	12	05 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: COMPLIED WITH CMP G650 243903 AIRFRAME UNINTERRUPTIBLE POWER SUPPLY SEALED LEAD ACID BATTERY - FUNCTIONAL CHECK											
243904	Uninterruptible Power Supply Battery - Removal / Installation		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.8			01 Oct 2024			N/A
			MSC				O/C				
Airframe											
243905	Flight Control System Uninterruptible Power Supply Battery - Restore		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.8		48	01 Oct 2024	30 Sep 2028		N/A
			[End Of Month Item]								
Airframe											
243906	Uninterruptible Power Supply Battery Charger - Removal / Installation		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		62.9			28 Sep 2019			
			MSC				O/C				
Airframe											
244000	Dc External Power - Operational Check		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		125.3			17 Jul 2014			
			MSC				O/C				
Airframe											
244001	AC External Power - Operational Check		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		125.4			15 Jul 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
244002	60 HZ External Power - Operational Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
244200	External AC Power Current Transformer Assembly - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	1159SCAV504-1	1897	MOS		128.2			21 Apr 2014			
			MSC				O/C				
245000	AC Electrical Load Distribution - Operational Check		HRS		1722.5			1799.9			0
			AFL		351			376			0
			MOS		68.7			04 Apr 2019			
			MSC				O/C				
245168	60 HZ Outlet, Aft Left Closet #2 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	107047-1	12301013	MOS		123			27 Sep 2014			MID CONTINENT
			MSC				O/C				
245169	60HZ Outlet, Aft Lh Closet #2		HRS		3509.1			13.3			0
			AFL		722			5			0
	107047-1	12291013	MOS		123			27 Sep 2014			MID CONTINENT
			MSC				O/C				
245300	60 Hertz Outlet (Left Seat No. 1) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	107047-1	12341013	MOS		123			27 Sep 2014			MID CONTINENT
			MSC				O/C				
245301	60 Hertz Outlet (Left Seat No. 2) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	107047-1	12271013	MOS		123			27 Sep 2014			MID CONTINENT
			MSC				O/C				
245302	60 Hertz Outlet (Left Seat No. 3) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	107047-1	12281013	MOS		123			27 Sep 2014			MID CONTINENT
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245303	60 Hertz Outlet (Left Seat No. 4) - Removal / Installation		HRS		3509.1			13.3			0
	107047-1	12471013	AFL		722			5			0
			MOS		123			27 Sep 2014			MID CONTINENT
	Airframe		MSC				O/C				
245306	60 Hertz Outlet (Right Seat No. 1) - Removal / Installation		HRS		3026.3			496.1			0
	107047-1	26030615	AFL		617			110			0
			MOS	TSN:6	107.8			01 Jan 2016			MID CONTINENT
	Airframe		MSC				O/C				
245307	60 Hertz Outlet (Right Seat No. 2) - Removal / Installation		HRS		3509.1			13.3			0
	107047-1	14550214	AFL		722			5			0
			MOS		123			27 Sep 2014			MID CONTINENT
	Airframe		MSC				O/C				
245308	60 Hertz Outlet (Right Seat No. 3) - Removal / Installation		HRS		3509.1			13.3			0
	107047-1	14560214	AFL		722			5			0
			MOS		123			27 Sep 2014			MID CONTINENT
	Airframe		MSC				O/C				
245309	60 Hertz Outlet (Right Seat No. 4) - Removal / Installation		HRS		3509.1			13.3			0
	107047-1	14610214	AFL		722			5			0
			MOS		123			27 Sep 2014			MID CONTINENT
	Airframe		MSC				O/C				
245310	60 Hertz Outlet (Right Seat No. 5) - Removal / Installation		HRS		1912.8			1609.6			0
	107047-11	17630417	AFL		397			330			0
			MOS	TSN:16	75.2			20 Sep 2018			Mid Continent Controls, Inc.
	Airframe		MSC				O/C				
245311	60 Hertz Outlet (Right Seat No. 6) - Removal / Installation		HRS		3509.1			13.3			0
	107047-1	14750214	AFL		722			5			0
			MOS		123			27 Sep 2014			MID CONTINENT
	Airframe		MSC				O/C				
245313	60 Hertz Outlet (Forward Lavatory) - Removal /		HRS		2755.9			766.5			0
	Installation		AFL		561			166			0
	107047-12	6530816	MOS		99.1			22 Sep 2016			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245314	60 Hertz Outlet (Aft Lavatory) - Removal / Installation		HRS		3509.1			13.3			0
	107047-2	5381013	AFL		722			5			0
			MOS		123			27 Sep 2014			MID CONTINENT
	Airframe		MSC				O/C				
245315	60 Hertz Outlet (Galley #1) - Removal / Installation		HRS		2624.5			897.9			0
	107047-12	7751216	AFL		535			192			0
			MOS		95			27 Jan 2017			MID CONTINENT
	Airframe		MSC				O/C				
245316	60 Hertz Outlet (Galley #2) - Removal / Installation		HRS		2755.9			766.5			0
	107047-12	6480816	AFL		561			166			0
			MOS	TSN:1	99.1			22 Sep 2016			
	Airframe		MSC				O/C				
245320	60 Hertz Outlet (Credenza) - Removal / Installation		HRS		3509.1			13.3			0
	107047-1	12311013	AFL		722			5			0
			MOS		123			27 Sep 2014			MID CONTINENT
	Airframe		MSC				O/C				
245321	60 HZ Outlet, Forward Left Closet #1 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	107047-1	12321013	MOS		123			27 Sep 2014			MID CONTINENT
	Airframe		MSC				O/C				
245333	60 HZ Outlet, Aft Left Closet #1 - Removal / Installation		HRS		3509.1			13.3			0
	107047-1	12331013	AFL		722			5			0
			MOS		123			27 Sep 2014			MID CONTINENT
	Airframe		MSC				O/C				
245336	60HZ Outlet, Conference Forward - Removal / Installation		HRS		3509.1			13.3			0
	107047-1	12481013	AFL		722			5			0
			MOS		123			27 Sep 2014			MID CONTINENT
	Airframe		MSC				O/C				
245337	60HZ Outlet, Conference Aft - Removal / Installation		HRS		3509.1			13.3			0
	107047-1	14760214	AFL		722			5			0
			MOS		123			27 Sep 2014			MID CONTINENT
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245370	60 HZ Power - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			10 Oct 2024			
	Airframe		MSC				O/C				
245375	60 HZ Outlet (Pilot) - Removal / Installation		HRS		3278			244.4			0
	GAC-AC11010-1	NSN	AFL		680			47			0
			MOS		115.7			03 May 2015			
	Airframe		MSC				O/C				
245377	60 HZ Outlet (Copilot) - Removal / Installation		HRS		3522.4			0			0
	GAC-AC11010-1	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
246000	Dc Electrical Load Distribution - Operational Check		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		62.9			30 Sep 2019			
	Airframe		MSC				O/C				
246406	Ground Service Bus - Operational Check		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		125.3			16 Jul 2014			
	Airframe		MSC				O/C				
247100	Left Power Distribution Box - Removal / Installation		HRS	TSN:1799.9	1722.5			1799.9			0
	1712480A	0118	AFL	TSN:376	351			376			0
			MOS	TSN:60	68.7			04 Apr 2019			N/A
	Airframe		MSC				O/C				
247101	Right Power Distribution Box - Removal / Installation		HRS		3522.4			0			0
	1712482A	0116	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
247120	Power Distribution Box Main Dc Circuit Breaker - Removal / Installation		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
247200	Left Bus Power Control Unit - Removal / Installation		HRS		1382.9			2139.5			0
	1702789A	2091	AFL		286			441			0
			MOS		59.9			30 Dec 2019			
	Airframe		MSC				O/C				
247201	Right Bus Power Control Unit - Removal / Installation		HRS	TSN:3408.5	113.9			3408.5			0
	1702789A	1708	AFL	TSN:691	36			691			0
			MOS	TSN:114	14			26 Oct 2023			N/A
	Airframe		MSC				O/C				
247204	Bus Power Control Unit - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.9			30 Oct 2023			
	Airframe		MSC				O/C				
247210	Cabin Bus Power Controller - Removal / Installation		HRS		3522.4			0			0
	GCBC-01-001\1	00756	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
248000	Secondary Power Distribution System - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
248001	Remote Interface Unit - Data Load		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
248004	Right Forward AC Modular Power Tile - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	202MPT3-4\1	MPTAC0439	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
248005	Left AC Modular Power Tile - Removal / Installation		HRS		3522.4			0			0
	202MPT3-4\1	MPTAC0438	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
248006	Right Aft AC Modular Power Tile - Removal / Installation		HRS		3522.4			0			0
	202MPT3-4\1		AFL		727			0			0
	1		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
248009	60 HZ Modular Power Tile - Removal / Installation		HRS		3522.4			0			0
	202MPT3-4\1		AFL		727			0			0
	1		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
248015	Left Dc Modular Power Tile No. 1 - Removal / Installation		HRS		3522.4			0			0
	201MPT3-4		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
248016	Left Dc Modular Power Tile No. 2 - Removal / Installation		HRS		3522.4			0			0
	201MPT3-4		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
248017	Right Dc Modular Power Tile No. 1 - Removal / Installation		HRS		3522.4			0			0
	201MPT3-4		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
248018	Right Dc Modular Power Tile No. 2 - Removal / Installation		HRS		3522.4			0			0
	201MPT3-4		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
248030	Left Remote Interface Unit - Removal / Installation		HRS		3522.4			0			0
	785SUE2-3\2		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
248031	Right Remote Interface Unit - Removal / Installation		HRS		3522.4			0			0
	785SUE2-3\2		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
248034	Secondary Power Distribution System Control Verification - Functional Test		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		125.3		17 Jul 2014				
			MSC			O/C					
Airframe											
248035	Secondary Power Distribution System - Software Load Verification		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
249400	Switch Assy, Fwd Lav Flush - Removal / Installation A2370-1 005117		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		123		27 Sep 2014		RADIANT		
			MSC			O/C					
Airframe											
249404	Switch Assy, Fwd Lav Psu - Removal / Installation A2430-1 005247		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		123		27 Sep 2014		RADIANT		
			MSC			O/C					
Airframe											
249408	Switch Assy, Fwd Lav Psu - Removal / Installation A2440-1 005166		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		123		27 Sep 2014		RADIANT		
			MSC			O/C					
Airframe											
249420	Master Switch, Fwd Lav Mirror - Removal / Installation A2350-3 008828		HRS	TSN:29	1158			2364.4			0
			AFL		239	488		0			
			MOS		49.9	28 Oct 2020		N/A			
			MSC				O/C				
Airframe											
249454	Switch Assy, L/H Seat #1 Psu - Removal / Installation A2440-2 005604		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		123		27 Sep 2014		RADIANT		
			MSC			O/C					
Airframe											
249470	Switch Assy, L/H Seat #2 Psu - Removal / Installation A2440-4 005368		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		123		27 Sep 2014		RADIANT		
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
249486	Switch Assy, L/H Seat #3 Psu - Removal / Installation		HRS		3509.1			13.3			0
	A2440-2		AFL		722			5			0
	005111		MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
249502	Switch Assy, L/H Seat #4 Psu - Removal / Installation		HRS		3509.1			13.3			0
	A2440-4		AFL		722			5			0
	005370		MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
249518	Switch Assy, L/H Seat #5 Psu - Removal / Installation		HRS		3509.1			13.3			0
	A2440-2		AFL		722			5			0
	005603		MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
249534	Switch Assy, L/H Seat #6 Psu - Removal / Installation		HRS		3509.1			13.3			0
	A2440-4		AFL		722			5			0
	005381		MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
249535	Switch Assy, L/H Seat #7 Psu - Removal / Installation		HRS		3506.4			16			0
	A2370-11		AFL		721			6			0
	005002		MOS		122.4			13 Oct 2014			RADIANT
	Airframe		MSC				O/C				
249550	Switch Assy, R/H Seat #1 Psu - Removal / Installation		HRS	TSN:13.8	3495.3			27.1			0
	A2440-4		AFL	TSN:3	719			8			0
	005542		MOS	TSN:1	122.2			19 Oct 2014			RADIANT
	Airframe		MSC				O/C				
249566	Switch Assy, R/H Seat #2 Psu - Removal / Installation		HRS	TSN:13.8	3495.3			27.1			0
	A2440-2		AFL	TSN:3	719			8			0
	005609		MOS	TSN:1	122.2			19 Oct 2014			RADIANT
	Airframe		MSC				O/C				
249582	Switch Assy, R/H Seat #3 Psu - Removal / Installation		HRS		3509.1			13.3			0
	A2440-4		AFL		722			5			0
	005383		MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
249598	Switch Assy, R/H Seat #4 Psu - Removal / Installation		HRS		3509.1			13.3			0
	A2440-2	005480	AFL		722			5			0
			MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
249614	Switch Assy, R/H Seat #5 Psu - Removal / Installation		HRS		3509.1			13.3			0
	A2440-4	005384	AFL		722			5			0
			MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
249630	Switch Assy, R/H Seat #6 Psu - Removal / Installation		HRS		3509.1			13.3			0
	A2440-2	005608	AFL		722			5			0
			MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
249694	Switch Assy, R/H Divan Fwd Seat Psu - Removal / Installation		HRS		3509.1			13.3			0
	A2430-4	005330	AFL		722			5			0
			MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
249709	Switch Assy, R/H Divan #2 Mid Seat Psu - Removal / Installation		HRS		3509.1			13.3			0
	A2430-4	005331	AFL		722			5			0
			MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
249725	Switch Assy, R/H Divan #2 Aft Seat Psu - Removal / Installatation		HRS		3509.1			13.3			0
	A2430-6	005205	AFL		722			5			0
			MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
249810	Switch Assy, L/H Seat #1 Electric Table Box - Removal / Installation		HRS		3509.1			13.3			0
	A2370-4	001793	AFL		722			5			0
			MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
249814	Switch Assy, L/H Seat #2 Electric Table Box - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2370-4	001800	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
249818	Switch Assy, L/H Seat #3 Electric Table Box - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2370-4	002022	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
249822	Switch Assy, L/H Seat #4 Electric Table Box - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2370-4	002024	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
249846	Switch Assy, Aft Lav Psu - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2430-4	005333	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
249848	Master Switch, Aft Lav Psu - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2460-1	005110	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
249864	Switch Assy, Aft Lav Bulkhead - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2430-3	005175	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
249876	Switch Assy, Fwd Electric Pocket Door Fwd - Removal / Installation		HRS		2755.9			766.5			0
			AFL		561			166			0
	PDS100-01	449000351	MOS	TSN:1	99.2			21 Sep 2016			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
249878	Master Switch, Fwd Electric Pocket Door Fwd - Removal / Installation		HRS		2755.9			766.5			0
			AFL		561			166			0
	PDS100-01	449000379	MOS	TSN:1	99.2			21 Sep 2016			
			MSC				O/C				
Airframe											
249884	Switch Assy, Mid Electric Pocket Door Fwd - Removal / Installation		HRS		2755.9			766.5			0
			AFL		561			166			0
	PDS100-01	449000435	MOS		99.2			21 Sep 2016			
			MSC				O/C				
Airframe											
249886	Master Switch, Mid Pocket Door Fwd - Removal / Installation		HRS		2755.9			766.5			0
			AFL		561			166			0
	PDS100-01	449000377	MOS	TSN:1	99.2			21 Sep 2016			
			MSC				O/C				
Airframe											
249900	Switch Assy, R/H Seat #1 Electric Table Box - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2370-4	001786	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
249904	Switch Assy, R/H Seat #2 Electric Table Box - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2370-4	002026	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
249908	Switch Assy, R/H Seat #3 Electric Table Box - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2370-4	001799	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
249912	Switch Assy, R/H Seat #4 Electric Table Box - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2370-4	002019	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
249916	Switch Assy, R/H Seat #5 Electric Table Box - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2370-4	002023	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
249920	Switch Assy, R/H Seat #6 Electric Table Box - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2370-4	002025	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
249924	Master Switch, Aft Cabin Privacy - Removal / Installation		HRS		1158			2364.4			0
	A2370-7		AFL		239			488			0
			MOS	TSN:16	49.9			29 Oct 2020			
			MSC				O/C				
Airframe											
25 - Equipment/Furnishings											
251101	Cockpit Overhead Panel - Removal / Installation		HRS		3522.4			0			0
	127TS11Y07		AFL		727			0			0
	3-4		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
251105	Pilot Seat - Removal / Installation		HRS		.4			3522			0
	3A317-0007-01-2		AFL		1			726			0
	72969		MOS		2.5			11 Oct 2024			N/A
			MSC				O/C				
Airframe											
251106	Copilot Seat - Removal / Installation		HRS		.4			3522			0
	3A317-0008-01-2		AFL		1			726			0
	23570		MOS		2.5			11 Oct 2024			N/A
			MSC				O/C				
Airframe											
251107	Observer Seat - Removal / Installation		HRS	TSN:3408.5	113.9			3408.5			0
	1159SCF501-1		AFL	TSN:691	36			691			0
	909-1425		MOS	TSN:114	13.9			30 Oct 2023			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
251111	Crew Seats Locking Mechanism and Seat Tracks (Pilot) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.6	25	48	06 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
251112	Crew Seats Locking Mechanism and Seat Tracks (Copilot) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.6	25	48	06 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
251113	Crew Seats Locking Mechanism and Seat Tracks (Observer) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.6	25	48	06 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
251114	Crew Seat Restraints (Pilot) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
251115	Crew Seat Restraints (Copilot) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
251116	Crew Seat Restraints (Observer) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
251117	Crew Seat Inertia Reels (Pilot) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
251118	Crew Seat Inertia Reels (Copilot) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
251119	Crew Seat Inertia Reels (Observer) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
252096	Forward Lav Toilet Seat - Removal / Installation TS-G45A-007-WH TS4436		HRS		2307.2			1215.2			0
			AFL		477			250			0
			MOS		86.9			30 Sep 2017			
	Airframe	MSC O/C									
252097	Aft Lav Toilet Seat - Removal / Installation TS-G45A-007-WH TS4435		HRS		2307.2			1215.2			0
			AFL		477			250			0
			MOS		86.9			30 Sep 2017			
	Airframe	MSC O/C									
252100	Cabin and Crew Rest Seating Attachments and Locking - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	17	48	14 Oct 2022	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
252101	Cabin and Crew Rest Seating / Berthing Restraints - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
252102	Cabin and Crew Rest Seating Inertia Reels - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
252165	Cabin Seat (Left Seat No. 1) - Removal / Installation G6SMA28LS.A01 5122810003		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe	MSC O/C									
252166	Cabin Seat (Left Seat No. 2) - Removal / Installation G6SMF28LS.A01 5112810009		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe	MSC O/C									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252167	Cabin Seat (Left Seat No. 3) - Removal / Installation		HRS		3509.1			13.3			0
	G6SMF28LS.A01	5122810004	AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe		MSC				O/C				
252168	Cabin Seat (Left Seat No. 4) - Removal / Installation		HRS		3509.1			13.3			0
	G6SMF28LS.A01	5112810010	AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe		MSC				O/C				
252171	Cabin Seat (Right Seat No. 1) - Removal / Installation		HRS		3509.1			13.3			0
	G6SMA25RS.A01	5122520001	AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe		MSC				O/C				
252172	Cabin Seat (Right Seat No. 2) - Removal / Installation		HRS		3509.1			13.3			0
	G6SMF25RS.A01	5112520001	AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe		MSC				O/C				
252173	Cabin Seat (Right Seat No. 3) - Removal / Installation		HRS		3509.1			13.3			0
	G6SMA25RS.A01	5122820002	AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe		MSC				O/C				
252174	Cabin Seat (Right Seat No. 4) - Removal / Installation		HRS		3509.1			13.3			0
	G6SMF28RS.A01	5112820006	AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe		MSC				O/C				
252175	Cabin Seat (Right Seat No. 5) - Removal / Installation		HRS		3509.1			13.3			0
	G6SMF28RS.A01	5122820005	AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe		MSC				O/C				
252176	Cabin Seat (Right Seat No. 6) - Removal / Installation		HRS		3509.1			13.3			0
	G6SMF28RS.A01	5112820009	AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252177	Fwd Double Seat - Removal / Installation		HRS		3509.1			13.3			0
	G6DMF45LS-A00	7114510002	AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe		MSC				O/C				
252178	Aft Double Seat - Removal / Installation		HRS		3509.1			13.3			0
	G6DMA45LS-A00	7124510007	AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe		MSC				O/C				
252195	Right Divan No. 2 - Removal / Installation		HRS		3509.1			13.3			0
	G6VMS77RS.000	4117720024	AFL		722			5			0
			MOS		123			27 Sep 2014			RCO
	Airframe		MSC				O/C				
252300	Pocket Door, Electric Fwd - Removal / Installation		HRS		3509.1			13.3			0
	42600-240L-001	59150	AFL		722			5			0
			MOS		123			27 Sep 2014			ENFLITE
	Airframe		MSC				O/C				
252302	Pocket Door, Electric Mid - Removal / Installation		HRS		3509.1			13.3			0
	42600-240R-022	60080	AFL		722			5			0
			MOS		123			27 Sep 2014			ENFLITE
	Airframe		MSC				O/C				
252326	Electric Console Table, Left #1- Removal / Installation		HRS		3509.1			13.3			0
	83650-22-04	60391	AFL		722			5			0
			MOS		123			27 Sep 2014			ENFLITE
	Airframe		MSC				O/C				
252327	Electric Console Table, Left #2 - Removal / Installation		HRS	TSN:231.1	3278			244.4			0
	83650-22-04	60390	AFL	TSN:42	680			47			0
			MOS	TSN:8	115.7			03 May 2015			ENFLITE
	Airframe		MSC				O/C				
252329	Electric Console Table, Right #1 - Removal / Installation		HRS		3509.1			13.3			0
	83650-28-02	59588	AFL		722			5			0
			MOS		123			27 Sep 2014			ENFLITE
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252330	Electric Console Table, Right #2 - Removal / Installation		HRS		3509.1			13.3			0
	83650-22-04	60389	AFL		722			5			0
			MOS		123			27 Sep 2014			ENFLITE
	Airframe		MSC				O/C				
252331	Electric Console Table, Right #3 - Removal / Installation		HRS		3509.1			13.3			0
	83650-22-04	60392	AFL		722			5			0
			MOS		123			27 Sep 2014			ENFLITE
	Airframe		MSC				O/C				
252332	Conference Table - Removal / Installation		HRS		3278			244.4			0
	80150-01	57074	AFL		680			47			0
			MOS		115.7			04 May 2015			ENFLITE
	Airframe		MSC				O/C				
252400	Window Shade Assembly (Left Window No. 1) - Removal / Installation		HRS		2384			1138.4			0
			AFL		491			236			0
	ATG25F006	5821-110	MOS		88.7			03 Aug 2017			ATG
	Airframe		MSC				O/C				
252401	Window Shade Assembly (Left Window No. 2) - Removal / Installation		HRS		3278			244.4			0
			AFL		680			47			0
	ATG25F006	5919-103	MOS		115.7			03 May 2015			ATG
	Airframe		MSC				O/C				
252402	Window Shade Assembly (Left Window No. 3) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	ATG25F006	5919-105	MOS		50.4			13 Oct 2020			N/A
	Airframe		MSC				O/C				
252403	Window Shade Assembly (Left Window No. 4) - Removal / Installation		HRS		3278			244.4			0
			AFL		680			47			0
	ATG25F006	5919-107	MOS		115.8			02 May 2015			ATG
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252404	Emergency Exit Window Shade Assembly (Left Window No. 5) - Removal / Installation		HRS		3278			244.4			0
			AFL		680			47			0
	ATG25F007	5919-501	MOS		115.8			02 May 2015			ATG
			MSC				O/C				
Airframe											
252405	Emergency Exit Window Shade Assembly (Left Window No. 6) - Removal / Installation		HRS		2384			1138.4			0
			AFL		491			236			0
	ATG25F007	5833-504	MOS		88.7			03 Aug 2017			ATG
			MSC				O/C				
Airframe											
252406	Window Shade Assembly (Left Window No. 7) - Removal / Installation		HRS		1556.4			1966			0
			AFL		318			409			0
	ATG25F006	4994-109	MOS		64.4			15 Aug 2019			ATG
			MSC				O/C				
Airframe											
252407	Window Shade Assembly (Left Window No. 8) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	ATG25F006	5919-111	MOS		50.4			13 Oct 2020			N/A
			MSC				O/C				
Airframe											
252408	Window Shade Assembly (Right Window No. 1) - Removal / Installation		HRS		3278			244.4			0
			AFL		680			47			0
	ATG25F006	5919-102	MOS		115.8			02 May 2015			ATG
			MSC				O/C				
Airframe											
252409	Window Shade Assembly (Right Window No. 2) - Removal / Installation		HRS		3278			244.4			0
			AFL		680			47			0
	ATG25F006	5919-104	MOS		115.8			02 May 2015			ATG
			MSC				O/C				
Airframe											
252410	Window Shade Assembly (Right Window No. 3) - Removal / Installation		HRS		3278			244.4			0
			AFL		680			47			0
	ATG25F006	5919-106	MOS		115.8			02 May 2015			ATG
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
252411	Window Shade Assembly (Right Window No. 4) - Removal / Installation		HRS		3278			244.4			0
			AFL		680			47			0
	ATG25F006	5919-108	MOS		115.8			02 May 2015			ATG
			MSC				O/C				
Airframe											
252412	Emergency Exit Window Shade Assembly (Right Window No. 5) - Removal / Installation		HRS		3278			244.4			0
			AFL		680			47			0
	ATG25F007	5919-503	MOS		115.8			02 May 2015			ATG
			MSC				O/C				
Airframe											
252413	Emergency Exit Window Shade Assembly (Right Window No. 6) - Removal / Installation		HRS		3278			244.4			0
			AFL		680			47			0
	ATG25F007	5919-504	MOS		115.8			02 May 2015			ATG
			MSC				O/C				
Airframe											
252414	Window Shade Assembly (Right Window No. 7) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	ATG25F006	5919-110	MOS		13.9			30 Oct 2023			N/A
			MSC				O/C				
Airframe											
252415	Window Shade Assembly (Right Window No. 8) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	ATG25F006	5821-110	MOS		50.4			13 Oct 2020			N/A
			MSC				O/C				
Airframe											
252416	Lh Cockpit Window Shade - Removal / Installation		HRS		3522.4			0			0
	1-6151-100	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
252417	Rh Cockpit Window Shade - Removal / Installation		HRS		3522.4			0			0
	1-6152-100	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
253200	Coffeemaker (No. 1) - Removal / Installation		HRS		485.9			3036.5			0
	HFAT2000-10	03960	AFL		97			630			0
			MOS		24.9			28 Nov 2022			N/A
	Airframe		MSC				O/C				
Notes: REF G650 AOMM 25-32-00 DATE 2 JUN 2017											
253202	Water Tank, Coffee/Esspresso Maker - Removal / Installation		HRS	TSN:375.4	3133.7			388.7			0
			AFL	TSN:70	652			75			0
	HFWTBAA15-0100	05100	MOS	TSN:12	111.4			14 Sep 2015			IACOBUCCI
			MSC				O/C				
Airframe											
253203	Water Tank RAIL, Coffee/Esspresso Maker - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	HFRLBAA15-0200	04738	MOS		123			27 Sep 2014			IACOBUCCI
			MSC				O/C				
Airframe											
253204	Mount Assy, Coffee Maker #1 - Removal / Installation		HRS		3133.7			388.7			0
	HFRLBAA15-0100	07221	AFL		652			75			0
			MOS	TSN:14	111.4			14 Sep 2015			IACOBUCCI
			MSC				O/C				
Airframe											
253205	Mount Assy, Coffee Maker #2 - Removal / Installation		HRS		3133.7			388.7			0
	HFRLBAA15-0100	05944	AFL		652			75			0
			MOS	TSN:17	111.4			14 Sep 2015			IACOBUCCI
			MSC				O/C				
Airframe											
253208	Wine Chiller - Removal / Installation		HRS		3362.1			160.3			0
	DWC-340-104	DWC340-075	AFL		695			32			0
			MOS		119.3			18 Jan 2015			DYNAMO
			MSC				O/C				
Airframe											
253210	Espresso Maker (No. 1) - Removal / Installation		HRS		485.9			3036.5			0
	HFE2005-30	13185	AFL		97			630			0
			MOS		24.9			28 Nov 2022			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
253302	Refrigerator - Removal / Installation		HRS		.4			3522			0
	DRF-1000-207	DRF207-314	AFL		1			726			0
			MOS		2.5			09 Oct 2024			
	Airframe		MSC				O/C				
Notes: COMPLIED WITH RFU INSTALL PER G650 AOMM 25-33-00 PAGE 1 OCTOBER 13/17.											
253700	Oven - Removal / Installation		HRS	TSN:2270	485.9			3036.5			0
	9155-004	66723-2	AFL	TSN:464	97			630			0
			MOS	TSN:78	24.9			28 Nov 2022			N/A
	Airframe		MSC				O/C				
253701	Microwave Oven - Removal / Installation		HRS		485.9			3036.5			0
	DMO-1000-103	DMO103-100	AFL		97			630			0
			MOS		24.9			28 Nov 2022			N/A
	Airframe		MSC				O/C				
253705	Slide Mount Assy, Microwave Oven - Removal / Installation		HRS		3133.7			388.7			0
	DA1481049-101	DRA103-111	AFL		652			75			0
			MOS		111.4			15 Sep 2015			DYNAMO
	Airframe		MSC				O/C				
253706	Sun Screen, Pilot - Removal / Installation		HRS		3509.1			13.3			0
	1-6151-100	242	AFL		722			5			0
			MOS		124			26 Aug 2014			
	Airframe		MSC				O/C				
253707	Sun Screen, Copilot - Removal / Installation		HRS		3509.1			13.3			0
	1-6152-100	211	AFL		722			5			0
			MOS		124			26 Aug 2014			
	Airframe		MSC				O/C				
256000	Flashlight (Pilot) - Removal / Installation		HRS		113.9			3408.5			0
	FLOX43553-01	200726-10	AFL		36			691			0
			MOS	TSN:4	13.8			31 Oct 2023			N/A
	Airframe		MSC				O/C				
256001	Flashlight (Copilot) - Removal / Installation		HRS		1158			2364.4			0
	FLOX43553	22482-05	AFL		239			488			0
			MOS	TSN:6	50.4			14 Oct 2020			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256003	Flashlight (Baggage Compartment) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	FLOX43553-01	28462-04	MOS		26.7			05 Oct 2022			MOXLEY DEVELOPMENT CO.
			MSC				O/C				
Airframe											
256007	Flashlight (Pilot) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.3	39	12	18 Sep 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
256014	Flashlight (Copilot) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.3	12	12	18 Sep 2024	30 Sep 2025*	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
256015	Flashlight (Baggage Compartment) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.3	43	12	18 Sep 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
256060	Flashlight Charger Base (Pilot) - Removal / Installation		HRS		3133.7			388.7			0
	FLCOX43554	13914-01	AFL		652			75			0
			MOS	TSN:6	111.4			15 Sep 2015			
			MSC				O/C				
Airframe											
256061	Flashlight Charger Base (Copilot) - Removal / Installation		HRS		3133.7			388.7			0
	FLCOX43554	13914-01	AFL		652			75			0
			MOS	TSN:6	111.4			15 Sep 2015			
			MSC				O/C				
Airframe											
256063	Flashlight Charger Base (Baggage) - Removal / Installation		HRS		3133.7			388.7			0
			AFL		652			75			0
	FLCOX43554	13914-03	MOS	TSN:6	111.4			15 Sep 2015			
			MSC				O/C				
Airframe											
256070	Life Vest (Pilot) - Restore		HRS		113.9			3408.5			0
	63600-505	L5648181	AFL		36			691			0
			MOS	TSN:10	14.2		120	19 Oct 2023	31 Dec 2033		N/A
			EXPIRATION								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256071	Life Vest (Copilot) - Restore		HRS		113.9			3408.5			0
	63600-505		AFL		36			691			0
	L5648183		MOS	TSN:10	14.2		120	19 Oct 2023	31 Dec 2033		N/A
	Airframe										EXPIRATION
256072	Life Vest (Observer) - Restore		HRS		113.9			3408.5			0
	63600-505		AFL		36			691			0
	L5648180		MOS	TSN:10	14.2		120	19 Oct 2023	31 Dec 2033		N/A
	Airframe										EXPIRATION
256074	Life Vest (No. 1) - Restore		HRS		113.9			3408.5			0
	63600-105		AFL		36			691			0
	L5719107		MOS	TSN:7	14.2		120	19 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256075	Life Vest (No. 2) - Restore		HRS		113.9			3408.5			0
	63600-105		AFL		36			691			0
	L5719342		MOS	TSN:7	14.2		120	19 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256076	Life Vest (No. 3) - Restore		HRS		113.9			3408.5			0
	63600-105		AFL		36			691			0
	L5719341		MOS	TSN:7	14.2		120	19 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256077	Life Vest (No. 4) - Restore		HRS		113.9			3408.5			0
	63600-105		AFL		36			691			0
	L5719122		MOS	TSN:7	14.2		120	19 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256078	Life Vest (No. 5) - Restore		HRS		113.9			3408.5			0
	63600-105		AFL		36			691			0
	L5719132		MOS	TSN:7	14.2		120	19 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256079	Life Vest (No. 6) - Restore		HRS		113.9			3408.5			0
	63600-105		AFL		36			691			0
	L5719353		MOS	TSN:7	14.2		120	19 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256080	Life Vest (No. 7) - Restore		HRS		113.9			3408.5			0
	63600-105	L5719110	AFL		36			691			0
			MOS	TSN:7	14.2		120	19 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256081	Life Vest (No. 8) - Restore		HRS		113.9			3408.5			0
	63600-105	L5719120	AFL		36			691			0
			MOS	TSN:7	14.2		120	19 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256082	Life Vest (No. 9) - Restore		HRS		113.9			3408.5			0
	63600-105	L5719121	AFL		36			691			0
			MOS	TSN:7	14.2		120	20 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256083	Life Vest (No. 10) - Restore		HRS		113.9			3408.5			0
	63600-105	L5719106	AFL		36			691			0
			MOS	TSN:7	14.2		120	20 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256084	Life Vest (No. 11) - Restore		HRS		113.9			3408.5			0
	63600-105	L5719348	AFL		36			691			0
			MOS	TSN:7	14.2		120	20 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256085	Life Vest (No. 12) - Restore		HRS		113.9			3408.5			0
	63600-105	L5719349	AFL		36			691			0
			MOS	TSN:7	14.2		120	20 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256086	Life Vest (No. 13) - Restore		HRS		113.9			3408.5			0
	63600-105	L5719344	AFL		36			691			0
			MOS	TSN:7	14.2		120	20 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256087	Life Vest (No. 14) - Restore		HRS		113.9			3408.5			0
	63600-105	L5719343	AFL		36			691			0
			MOS	TSN:7	14.2		120	20 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256088	Life Vest (No. 15) - Restore		HRS		113.9			3408.5			0
	63600-105	L5719352	AFL		36			691			0
			MOS	TSN:7	14.2		120	20 Oct 2023	28 Feb 2033		N/A
	Airframe										EXPIRATION
256100	Life Vest (Pilot) - Removal / Installation		HRS		113.9			3408.5			0
	63600-505	L5648181	AFL		36			691			0
			MOS	TSN:10	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256101	Life Vest (Copilot) - Removal / Installation		HRS		113.9			3408.5			0
	63600-505	L5648183	AFL		36			691			0
			MOS	TSN:10	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256102	Life Vest (Observer) - Removal / Installation		HRS		113.9			3408.5			0
	63600-505	L5648180	AFL		36			691			0
			MOS	TSN:10	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256103	Life Vest (Crew Member) - Removal / Installation		HRS	TSN:766.5	2755.9			766.5			0
	63600-505	NSN	AFL	TSN:166	561			166			0
			MOS	TSN:29	98.9			30 Sep 2016			
	Airframe		MSC				O/C				
256104	Life Vest (No. 1) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719107	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256105	Life Vest (No. 2) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719342	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256106	Life Vest (No. 3) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719341	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256107	Life Vest (No. 4) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719122	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256108	Life Vest (No. 5) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719132	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256109	Life Vest (No. 6) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719353	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256110	Life Vest (No. 7) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719110	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256111	Life Vest (No. 8) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719120	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256112	Life Vest (No. 9) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719121	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256113	Life Vest (No. 10) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719106	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256114	Life Vest (No. 11) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719348	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256115	Life Vest (No. 12) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719349	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256116	Life Vest (No. 13) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719344	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256117	Life Vest (No. 14) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719343	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256118	Life Vest (No. 15) - Removal / Installation		HRS		113.9			3408.5			0
	63600-105	L5719352	AFL		36			691			0
			MOS	TSN:7	14.2			20 Oct 2023			N/A
	Airframe		MSC				O/C				
256135	Life Raft (No. 1) - Removal /Installation		HRS		113.9			3408.5			0
	1320FAUL-6K4-1-904	13UL-01613	AFL		36			691			0
			MOS		13.8			01 Nov 2023			N/A
	Airframe		MSC				O/C				
256136	Life Raft (No. 2) - Removal /Installation		HRS		113.9			3408.5			0
	1320FAUL-6K4-1-904	13UL-01359	AFL		36			691			0
			MOS		13.8			01 Nov 2023			N/A
	Airframe		MSC				O/C				
256143	Life Raft (No. 1) - Restore		HRS		113.9			3408.5			0
	1320FAUL-6K4-1-904	13UL-01613	AFL		36			691			0
			MOS		13.8		36	01 Nov 2023	31 Oct 2026		N/A
	Airframe										EXPIRATION
256144	Life Raft (No. 2) - Restore		HRS		113.9			3408.5			0
	1320FAUL-6K4-1-904	13UL-01359	AFL		36			691			0
			MOS		13.8		36	01 Nov 2023	31 Oct 2026		N/A
	Airframe										EXPIRATION

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256147	Life Raft (No. 1) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.3	43	12	18 Sep 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
256148	Life Raft (No. 2) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.3	43	12	18 Sep 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
256181	Life Vest(S) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.3	43	12	18 Sep 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256215	Smoke Hood / Protective Breathing Equipment (Pbe)		HRS		113.9			3408.5			0
	(Observer) - Removal / Installation		AFL		36			691			0
	MR-10051N	E2207256	MOS	TSN:10	14.1			23 Oct 2023			N/A
	Airframe		MSC				O/C				
256219	Smoke Hood / Protective Breathing Equipment (Pbe)		HRS		113.9			3408.5			0
	(Pilot) - Discard		AFL		36			691			0
	MR-10010N	R2307722	MOS	TSN:2	14.2		120	19 Oct 2023	31 Dec 2033		N/A
	Airframe		EXPIRATION								
256220	Smoke Hood / Protective Breathing Equipment (Pbe)		HRS		113.9			3408.5			0
	(Copilot) - Discard		AFL		36			691			0
	MR-10010N	R2307968	MOS	TSN:2	14.2		120	19 Oct 2023	31 Dec 2033		N/A
	Airframe		EXPIRATION								
256221	Smoke Hood / Protective Breathing Equipment (Pbe)		HRS		113.9			3408.5			0
	(Observer) - Discard		AFL		36			691			0
	MR-10051N	E2207256	MOS	TSN:10	14.1		120	23 Oct 2023	30 Jun 2033		N/A
	Airframe		EXPIRATION								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256262	Smoke Hood / Protective Breathing Equipment (Pbe) (Pilot) - Visual Check		HRS		-17.5			3539.9			0
			AFL		-10		737			0	
			MOS		.7	-17	12	03 Dec 2024	16 Nov 2025*	16 Dec 2025	
			[MOS: +1m/-1m]								
Airframe											
256272	Smoke Hood / Protective Breathing Equipment (Pbe) (Copilot) - Visual Check		HRS		-17.5			3539.9			0
			AFL		-10		737			0	
			MOS		.7	-17	12	03 Dec 2024	16 Nov 2025*	16 Dec 2025	
			[MOS: +1m/-1m]								
Airframe											
256273	Smoke Hood / Protective Breathing Equipment (Pbe) / Pbe (Observer) - Visual Check		HRS		-17.5			3539.9			0
			AFL		-10		737			0	
			MOS		.7	-17	12	03 Dec 2024	16 Nov 2025*	16 Dec 2025	
			[MOS: +1m/-1m]								
Airframe											
256294	Smoke Hood (Aft Lavatory) - Removal / Installation MR-10039N E2302701		HRS		113.9			3408.5			0
			AFL		36		691			0	
			MOS	TSN:4	14.1		23 Oct 2023			N/A	
			MSC				O/C				
Airframe											
256295	Smoke Hood (Aft Lavatory) - Discard MR-10039N E2302701		HRS		113.9			3408.5			0
			AFL		36		691			0	
			MOS		14.3		120	18 Oct 2023	15 Jun 2033		N/A
			MANUFACTURE								
Airframe											
256296	Smoke Hood Tamper-Evident Seals (Aft Lavatory) - Detailed Inspection		HRS		.4			3522			0
			AFL		1		726			0	
			MOS		3.3	12	12	18 Sep 2024	30 Sep 2025*	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
256303	Emergency Locator Transmitter - Removal / Installation 453-5060 14776		HRS	TSN:3521.6	.4			3522			0
			AFL	TSN:725	1		726			0	
			MOS	TSN:124	3.1		23 Sep 2024			N/A	
			MSC				O/C				
Airframe											
Notes: ELT BATTERY EXPIRATION: JUNE 2023											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256304	ELT Transmitter Battery - Removal / Installation		HRS		485.9			3036.5			0
	452-0133	394443-025	AFL		97			630			0
			MOS	TSN:8	26.7			03 Oct 2022			N/A
	Airframe		MSC				O/C				
256307	Emergency Locator Transmitter - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1	7	12	23 Sep 2024 30 Sep 2025* 31 Oct 2025			
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
256308	Emergency Locator Transmitter Battery Pack - Discard		HRS		485.9			3036.5			0
	452-0133	394443-025	AFL		97			630			0
			MOS	TSN:8	26.7		60	03 Oct 2022 31 May 2027			N/A
	Airframe	EXPIRATION									
256309	Emergency Locator Transmitter - Operational Check (FAR 91.207)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1		12	23 Sep 2024 30 Sep 2025			
	Airframe	[End Of Month Item]									
Notes: BATTERY EXPIRATION DATE: JUNE 2023											
256310	Emergency Locator Transmitter - Functional Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1			23 Sep 2024			
	Airframe		MSC				O/C				
256313	Emergency Locator Transmitter Antenna - Removal / Installation		HRS	TSN:2364.2	1158			2364.4			0
			AFL	TSN:487	239			488			0
	110-341	50128	MOS	TSN:78	50.5			12 Oct 2020			N/A
	Airframe		MSC				O/C				
256315	Emergency Locator Transmitter Antenna - Functional Test		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.2			20 Oct 2020			
	Airframe		MSC				O/C				
256316	Emergency Locator Transmitter Buzzer - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256320	ELT Programming Adapter - Removal / Installation		HRS		3509.1			13.3			0
	453-5068	362516-028	AFL		722			5			0
			MOS		123			27 Sep 2014			ACR
	Airframe		MSC				O/C				ELECTRONICS
256330	ELT - Reregistration		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3	-18	24	18 Oct 2023	30 Sep 2025*		
	Airframe										
256331	ELT, Life Raft (No.1) - Reregistration		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3	-18	24	18 Oct 2023	30 Sep 2025*		
	Airframe										
256332	ELT, Life Raft (No.2) - Reregistration		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3	-18	24	18 Oct 2023	30 Sep 2025*		
	Airframe										
256400	First AID Kit (No. 1) - Removal / Installation		HRS		.4			3522			0
	AFAK 1.0	092424008	AFL		1			726			0
			MOS		2.7			05 Oct 2024			N/A
	Airframe		MSC				O/C				
256404	First AID Kit (No. 1) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	-12	12	05 Oct 2024	30 Sep 2025*	31 Oct 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256406	First AID Kit (No. 1) Time Limited Supplies - Discard		HRS		.4			3522			0
	AFAK 1.0	092424008	AFL		1			726			0
			MOS		2.7			05 Oct 2024	30 Nov 2025		N/A
	Airframe		MSC				-				EXPIRATION
		[End Of Month Item]									
256416	Defibrillator - Removal / Installation		HRS		113.9			3408.5			0
	500247/500248	18G00000514	AFL		36			691			0
			MOS		14			25 Oct 2023			N/A
	Airframe		MSC				O/C				
Notes: EXPIRES AUG 2022											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256418	Defibrillator - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	12	04 Oct 2024	31 Oct 2025*	30 Nov 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
Notes: EXPIRES AUG. 2022											
256419	Defibrillator Time Limited Supplies - Discard		HRS		113.9			3408.5			0
	500247/500248	18G00000514	AFL		36			691			0
			DATE		428 d			25 Oct 2023	31 May 2025		N/A
Airframe				MSC			-				EXPIRATION
Notes: EXPIRES AUG 2022											
256451	Emergency Vision Assurance System (EVAS) (Left) (STC ST00892LA) - Removal / Installation		HRS		.4			3522			0
			AFL		1			726			0
	107STC-277	049JJ10P	MOS		2.4			13 Oct 2024			VISIONSAFE
Airframe				MSC			O/C				
256452	Emergency Vision Assurance System (EVAS) (Right) (STC ST00892LA) - Removal / Installation		HRS		.4			3522			0
			AFL		1			726			0
	107STC-278	050JJ10P	MOS		2.4			13 Oct 2024			VISIONSAFE
Airframe				MSC			O/C				
256453	Emergency Vision Assurance System (EVAS) (Left) (STC ST00892LA) - Position and Location Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.4		2	13 Oct 2024	31 Dec 2024	31 Jan 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
256454	Emergency Vision Assurance System (EVAS) (Right) (STC ST00892LA) - Position and Location Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.4		2	13 Oct 2024	31 Dec 2024	31 Jan 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									
256455	Emergency Vision Assurance System (EVAS) (Left) (STC ST00892LA) - Blower and Battery Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.4		2	13 Oct 2024	31 Dec 2024	31 Jan 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256456	Emergency Vision Assurance System (EVAS) (Right) (STC ST00892LA) - Blower and Battery Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.4		2	13 Oct 2024	31 Dec 2024	31 Jan 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
256457	Emergency Vision Assurance System (EVAS) (Left) (STC ST00892LA) - Loop Fastener Verification		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.4		2	13 Oct 2024	31 Dec 2024	31 Jan 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
256458	Emergency Vision Assurance System (EVAS) (Right) (STC ST00892LA) - Loop Fastener Verification		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.4		2	13 Oct 2024	31 Dec 2024	31 Jan 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
256459	Emergency Vision Assurance System (EVAS) (Left) (STC ST00892LA) - Biennial Service		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.4		24	13 Oct 2024	31 Oct 2026	31 Jan 2027	
			[End Of Month Item] [MOS: +3m/-3m]								
Airframe											
256460	Emergency Vision Assurance System (EVAS) (Right) (STC ST00892LA) - Biennial Service		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.4		24	13 Oct 2024	31 Oct 2026	31 Jan 2027	
			[End Of Month Item] [MOS: +3m/-3m]								
Airframe											
256461	Emergency Vision Assurance System (EVAS) (Left) (STC ST00892LA) - Special Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.4			13 Oct 2024			
			MSC				O/C				
Airframe											
256462	Emergency Vision Assurance System (EVAS) (Right) (STC ST00892LA) - Special Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.4			13 Oct 2024			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
256463	Emergency Vision Assurance System (EVAS) (Left) (STC ST00892LA) - Rebuild		HRS		.4			3522			0
			AFL		1			726			0
	107STC-277	049JJ10P	MOS		2.4		120	13 Oct 2024	31 Oct 2034	31 Jan 2035	VISIONSAFE
	[End Of Month Item] [MOS: +3m/-3m]										
Airframe											
256464	Emergency Vision Assurance System (EVAS) (Right) (STC ST00892LA) - Rebuild		HRS		.4			3522			0
			AFL		1			726			0
	107STC-278	050JJ10P	MOS		2.4		120	13 Oct 2024	31 Oct 2034	31 Jan 2035	VISIONSAFE
	[End Of Month Item] [MOS: +3m/-3m]										
Airframe											
256608	Ditching Line - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	17	48	14 Oct 2022	31 Oct 2026*	30 Nov 2026	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
257208	Tail Access Door- Removal / Installation		HRS		3522.4			0			0
	60P5240051A011P01	6088	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
258000	Aircraft RE-Registration (FAA Rule)		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14			26 Oct 2023	31 Oct 2027		
			MSC				DUE				EXPIRATION
Airframe											
26 - FIRE Protection											
260300	Smoke Evacuation Valve - Removal / Installation		HRS	TSN:3522	.4			3522			0
	GACSEV1VLV001-1	0120	AFL	TSN:726	1			726			0
			MOS	TSN:125	2.5			12 Oct 2024			
			MSC				O/C				
Airframe											
260302	Baggage Compartment Smoke Evacuation System - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5	11	120	12 Oct 2024	31 Oct 2034*	30 Nov 2034	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261102	Engine FIRE and Heat Sensing (Left) - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
261103	Engine FIRE and Heat Sensing (Right) - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
261104	Engine Firewire (Left) - Continuity / Resistance Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
261105	Engine Firewire (Right) - Continuity / Resistance Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
261106	Engine FIRE Detection Assembly RAIL 1 (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-229	13-10-6208	MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
261107	Engine FIRE Detection Assembly RAIL 1 (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-229	13-10-6207	MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
261108	Engine FIRE Detection Assembly RAIL 2 (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-230	13-09-6161	MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261109	Engine FIRE Detection Assembly RAIL 2 (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-230	13-10-6213	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
261110	Engine FIRE Detection Assembly RAIL 3 (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-231	13-10-6235	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
261111	Engine FIRE Detection Assembly RAIL 3 (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-231	13-10-6236	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
261112	Engine FIRE Detection Assembly RAIL 4 (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-232	13-10-6269	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
261113	Engine FIRE Detection Assembly RAIL 4 (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-232	13-09-6181	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
261114	Engine FIRE Detection Assembly RAIL 5 (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-233	13-04-5672	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
261115	Engine FIRE Detection Assembly RAIL 5 (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-233	13-05-5731	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261140	Engine FIRE Detection Assembly RAIL (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-234	13-11-6276	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
261141	Engine FIRE Detection Assembly RAIL (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	51291-234	13-11-6279	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
261200	Pylon FIRE and Heat (Left) - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
261201	Pylon FIRE and Heat (Right) - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
261202	Pylon Thermal Switch (Left) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
261203	Pylon Thermal Switch (Right) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
261300	APU FIRE Detection Loop - Removal / Installation		HRS		3522.4			0			0
	6360-12-1000/450-7		AFL		727			0			0
	203678		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
261302	APU FIRE Detection Loop - Temperature Trip Point Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261303	APU FIRE Detection Loop - Continuity / Resistance Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
261304	APU (FIRE) Shut-Down Circuit - Operational Check		HRS		1508.2		3000	2014.2	5014.2	5064.2	0
			AFL		311		416		0		
			MOS		63.1		22 Sep 2019				
			[HRS: +50/-50]								
261305	APU Compartment FIRE Detect Loop - Operational Check		HRS		1508.2		3000	2014.2	5014.2	5064.2	0
			AFL		311		416		0		
			MOS		63.1		22 Sep 2019				
			[HRS: +50/-50]								
261446	Equipment Overheat Thermal Switch (Leer) - Functional Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		122.1		23 Oct 2014				
			MSC			O/C					
261447	Equipment Overheat Thermal Switch (Reer) - Functional Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		122.1		23 Oct 2014				
			MSC			O/C					
261448	Equipment Overheat Thermal Switch (Forward Floor) - Functional Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		122.1		23 Oct 2014				
			MSC			O/C					
261449	Equipment Overheat Thermal Switch (Forward Baggage Eer) - Functional Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		122.1		23 Oct 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* = Adj)	Max Due	Avg Man Hrs
	Logbook Position	Part Number									Serial Number
HW		SW									Manufacturer
MM Ref		Date Type									
	Ops Number(s)										
261450	Aft Baggage Eer Overheat Thermal Switch - Functional Check		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		25.4	-21	96	13 Nov 2022 31 Oct 2030*	30 Nov 2030		
			[End Of Month Item] [MOS: +1m/-1m]								
			Airframe								
261451	Baggage Compartment Below Floor Overheat Thermal Switch - Functional Check		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		26.4	10	96	13 Oct 2022 31 Oct 2030*	30 Nov 2030		
			[End Of Month Item] [MOS: +1m/-1m]								
			Airframe								
261452	Aft Equipment Overheat Thermal Switch - Functional Check		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		25.4	-21	96	13 Nov 2022 31 Oct 2030*	30 Nov 2030		
			[End Of Month Item] [MOS: +1m/-1m]								
			Airframe								
261500	FIRE Detection Control Box (Left) - Removal / Installation 51653-274\1 00577		HRS	TSN:1209.9	2312.5			1209.9			0
			AFL	TSN:248	479		248		0		
			MOS	TSN:41	87.2		21 Sep 2017				
							O/C				
			Airframe								
261501	FIRE Detection Control Box (Right) - Removal / Installation 51653-274\1 00607		HRS	TSN:1209.9	2312.5			1209.9			0
			AFL	TSN:248	479		248		0		
			MOS	TSN:41	87.2		21 Sep 2017				
							O/C				
			Airframe								
261504	FIRE Detection Control Box (Left) - Functional Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
							O/C				
			Airframe								
261505	FIRE Detection Control Box (Right) - Functional Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
							O/C				
			Airframe								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261525	Smoke Detection Unit - Removal / Installation		HRS		3522.4			0			0
	72-130001-006	11535	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
261527	Smoke Detection Unit - Functional Test		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		124.8			01 Aug 2014			
	Airframe		MSC				O/C				
Notes: PN: 72-130001-006 SN: <NONE>.											
261600	FIRE Detection and Indication - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
262100	Engine FIRE Pull Handle (Left) - Removal / Installation		HRS		3522.4			0			0
	D533-55-001	0890/12-2013	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
262101	Engine FIRE Pull Handle (Right) - Removal / Installation		HRS		3522.4			0			0
	D533-56-001	NEED S/N	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
262102	Engine FIRE Bottle (Left) - Removal / Installation		HRS	TSN:3287.9	113.9			3408.5			0
	33600102-1	84877D1	AFL	TSN:672	36			691			0
			MOS	TSN:122	14.3			17 Oct 2023			N/A
	Airframe		MSC				O/C				
262103	Engine FIRE Bottle (Right) - Removal / Installation		HRS		485.9			3036.5			0
	33600102-1	A7765D1	AFL		97			630			0
			MOS		26.6			06 Oct 2022			N/A
	Airframe		MSC				O/C				
262104	Engine FIRE Extinguisher Bottle (Left) - Weight Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7		60	03 Oct 2022	31 Oct 2027	30 Nov 2027	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262105	Engine FIRE Extinguisher Bottle (Right) - Weight Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7		60	03 Oct 2022	31 Oct 2027	30 Nov 2027	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
262106	Engine FIRE Bottle (Left) - (Hydrostatic) Functional Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC			O/C				HYDRO CHECK	
Airframe	[End Of Month Item]										
Notes: PN: 33600102-1 SN: 84877D1. MRI PARENT CODE: 262102											
262107	Engine FIRE Bottle (Right) - (Hydrostatic) Functional Check		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.2			19 Sep 2018			
			MSC			O/C				HYDRO CHECK	
Airframe	[End Of Month Item]										
262108	Engine FIRE Bottle Pressure Switch (Left) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3		60	26 Sep 2024	30 Sep 2029	31 Oct 2029	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
262109	Engine FIRE Bottle Pressure Switch (Right) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3		60	26 Sep 2024	30 Sep 2029	31 Oct 2029	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
262112	Engine FIRE Pull Handle (Left) - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
262113	Engine FIRE Pull Handle (Right) - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262115	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Left) - Removal / Installation		HRS	TSN:3522	.4			3522			0
			AFL	TSN:726	1			726			0
	35201023-1	NSN	MOS	TSN:125	2.6			08 Oct 2024			N/A
			MSC	O/C							
Airframe											
262116	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Right) - Removal / Installation		HRS	TSN:3522	.4			3522			0
			AFL	TSN:726	1			726			0
	35201023-1	NSN	MOS	TSN:125	2.6			07 Oct 2024			N/A
			MSC	O/C							
Airframe											
262120	Engine FIRE Bottle Cartridge (Left Bottle, Left Squib) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	30903959	2918DB	MOS	TSN:2	14.3			16 Oct 2023			N/A
			MSC	O/C							
Airframe											
262121	Engine FIRE Bottle Cartridge (Left Bottle, Right Squib) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	30903931	0137DD	MOS	TSN:5	14.3			17 Oct 2023			N/A
			MSC	O/C							
Airframe											
262122	Engine FIRE Bottle Cartridge (Left Bottle, APU Squib) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	30903933	1150DD	MOS	TSN:5	14.3			17 Oct 2023			N/A
			MSC	O/C							
Airframe											
262123	Engine FIRE Bottle Cartridge (Right Bottle, Left Squib) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	30903959	0912AC	MOS	TSN:4	49.7			05 Nov 2020			
			MSC	O/C							
Airframe											
Notes: TORQUE WRENCH #555487, CAL. DUE 10/2018											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262124	Engine FIRE Bottle Cartridge (Right Bottle, Right Squib) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	30903931	2453YM	MOS	TSN:4	49.7			05 Nov 2020			
			MSC				O/C				
Airframe											
Notes: TORQUE WRENCH #555487, CAL. DUE 10/2018											
262125	Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	30903933	3073AC	MOS	TSN:4	49.7			05 Nov 2020			
			MSC				O/C				
Airframe											
Notes: TORQUE WRENCH #555487, CAL. DUE 10/2018											
262132	Engine FIRE Bottle Cartridge (Left Bottle, Left Squib, Service Life) - Discard		HRS		113.9			3408.5			0
			AFL		36			691			0
	30903959	2918DB	MOS	TSN:2	14.3		120	16 Oct 2023	31 Aug 2033		N/A
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 262120											
262133	Engine FIRE Bottle Cartridge (Left Bottle, Left Squib, Manufacturers Life) - Discard		HRS		113.9			3408.5			0
			AFL		36			691			0
	30903959	2918DB	MOS		14.3		180	16 Oct 2023	28 Feb 2038		N/A
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 262120											
262134	Engine FIRE Bottle Cartridge (Left Bottle, Right Squib, Service Life) - Discard		HRS		113.9			3408.5			0
			AFL		36			691			0
	30903931	0137DD	MOS	TSN:5	14.3		120	17 Oct 2023	31 May 2033		N/A
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 262121											
262135	Engine FIRE Bottle Cartridge (Left Bottle, Right Squib, Manufacturers Life) - Discard		HRS		113.9			3408.5			0
			AFL		36			691			0
	30903931	0137DD	MOS		14.3		180	17 Oct 2023	31 Mar 2038		N/A
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 262121											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262136	Engine FIRE Bottle Cartridge (Left Bottle, APU Squib, Service Life) - Discard		HRS		113.9			3408.5			0
			AFL		36			691			0
	30903933	1150DD	MOS	TSN:5	14.3		120	17 Oct 2023	31 May 2033		N/A
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 262122											
262137	Engine FIRE Bottle Cartridge (Left Bottle, APU Squib, Manufacturers Life) - Discard		HRS		113.9			3408.5			0
			AFL		36			691			0
	30903933	1150DD	MOS		14.3		180	17 Oct 2023	30 Apr 2038		N/A
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 262122											
262138	Engine FIRE Bottle Cartridge (Right Bottle, Left Squib, Service Life) - Discard		HRS		1912.8			1609.6			0
			AFL		397			330			0
	30903959	2589VJ	MOS		75.2		120	19 Sep 2018	30 Sep 2028		
			[End Of Month Item]								
Airframe											
262139	Engine FIRE Bottle Cartridge (Right Bottle, Left Squib, Manufacturers Life) - Discard		HRS		1912.8			1609.6			0
			AFL		397			330			0
	30903959	2589VJ	MOS		75.2		180	19 Sep 2018	01 Feb 2033		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 262123											
262140	Engine FIRE Bottle Cartridge (Right Bottle, Right Squib, Service Life) - Discard		HRS		1912.8			1609.6			0
			AFL		397			330			0
	30903931	2682VK	MOS		75.2		120	19 Sep 2018	19 Sep 2028		
			[End Of Month Item]								
Airframe											
262141	Engine FIRE Bottle Cartridge (Right Bottle, Right Squib, Manufacturers Life) - Discard		HRS		1912.8			1609.6			0
			AFL		397			330			0
	30903931	2628VK	MOS		75.2		180	19 Sep 2018	01 Feb 2033		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 262124											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262142	Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib, Service Life) - Discard		HRS		1912.8			1609.6			0
			AFL		397			330			0
	30903933	0606VL	MOS		75.2		120	19 Sep 2018	19 Sep 2028		
	[End Of Month Item]										
Airframe											
262143	Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib, Manufacturers Life) - Discard		HRS		1912.8			1609.6			0
			AFL		397			330			0
	30903933	0606VL	MOS		75.2		180	19 Sep 2018	01 Feb 2033		
	[End Of Month Item]										MANUFACTURE
Airframe											
Notes: MRI PARENT CODE: 262125											
262144	Engine FIRE Bottle Cartridge (Left Bottle, Left Squib) - Inspection		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3			16 Oct 2023			
			MSC				O/C				
Airframe											
Notes: PN: 30903959 SN: 2528PD.											
262145	Engine FIRE Bottle Cartridge (Left Bottle, Right Squib) - Inspection		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3			17 Oct 2023			
			MSC				O/C				
Airframe											
Notes: PN: 30903931 SN: 1687PC.											
262146	Engine FIRE Bottle Cartridge (Left Bottle, APU Squib) - Inspection		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3			17 Oct 2023			
			MSC				O/C				
Airframe											
Notes: PN: 30903933 SN: 1771PD.											
262147	Engine FIRE Bottle Cartridge (Right Bottle, Left Squib) - Inspection		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.2			19 Sep 2018			
			MSC				O/C				
Airframe											
Notes: PN: 30903959 SN: 2589VJ.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262148	Engine FIRE Bottle Cartridge (Right Bottle, Right Squib) - Inspection		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.2			19 Sep 2018			
			MSC				O/C				
Airframe											
Notes: PN: 30903931 SN: 2682VK.											
262149	Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib) - Inspection		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.2			19 Sep 2018			
			MSC				O/C				
Airframe											
Notes: PN: 30903933 SN: 0606VL.											
262150	Engine FIRE Extinguishing Firing Circuitry Integrity (Left) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	35	24	26 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
262151	Engine FIRE Extinguishing Firing Circuitry Integrity (Right) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3		24	26 Sep 2024	30 Sep 2026	31 Oct 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: SECOND CARD!!!!											
262152	APU FIRE Extinguishing Firing Circuitry Integrity - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	35	24	26 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
262161	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Left) - Functional Test		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6			07 Oct 2024			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
262162	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Right) - Functional Test		HRS		.4			3522			0	
			AFL		1			726			0	
			MOS		2.6			07 Oct 2024				
			MSC				O/C					
Airframe												
262163	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Left) - Detailed Inspection		HRS		.4			3522			0	
			AFL		1			726			0	
			MOS		2.6	16	120	07 Oct 2024	31 Oct 2034*	30 Nov 2034		
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
262164	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Right) - Detailed Inspection		HRS		.4			3522			0	
			AFL		1			726			0	
			MOS		2.6	16	120	07 Oct 2024	31 Oct 2034*	30 Nov 2034		
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
262400	Portable FIRE Extinguisher (Cockpit) - Removal / Installation		HRS		.4			3522			0	
			AFL		1			726			0	
			898052	G09442751	MOS		2.7			05 Oct 2024		N/A
					MSC				O/C			
Airframe												
262402	Portable FIRE Extinguisher (Cockpit) - Detailed Inspection		HRS		.4			3522			0	
			AFL		1			726			0	
			MOS		2.7	26	12	05 Oct 2024	31 Oct 2025*	30 Nov 2025		
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
262403	Portable FIRE Extinguisher (Cockpit) - Weight Check		HRS		.4			3522			0	
			AFL		1			726			0	
			MOS		2.7	-6	12	05 Oct 2024	30 Sep 2025*	31 Oct 2025		
			[End Of Month Item] [MOS: +1m/-1m]									
Airframe												
262404	Portable FIRE Extinguisher (Cockpit) - (Hydrostatic) Functional Check		HRS		.4			3522			0	
			AFL		1			726			0	
			MOS		2.7	49		05 Oct 2024				
			MSC				O/C				HYDRO CHECK	
Airframe												
Notes: PN: 898052 SN: Y-364340. MRI PARENT CODE: 262400												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262412	Portable FIRE Extinguisher (Forward Cabin) - Removal / Installation		HRS	TSN:3522	.4			3522			0
			AFL	TSN:726	1			726			0
	C354	Y-510113	MOS	TSN:139	3.2			19 Sep 2024			N/A
			MSC				O/C				
Airframe											
262414	Portable FIRE Extinguisher (Forward Cabin) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.3	43	12	18 Sep 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
262415	Portable FIRE Extinguisher (Forward Cabin) - Weight Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.2		12	19 Sep 2024	30 Sep 2025	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m] WEIGHT CHECK								
Airframe											
262416	Portable FIRE Extinguisher (Forward Cabin) - (Hydrostatic) Functional Check		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		123			27 Sep 2014			
			MSC				O/C				
Airframe	[End Of Month Item]										
Notes: PN: C354TS SN: Y-510113.											
262436	Portable FIRE Extinguisher (Aft Lavatory) - Removal / Installation		HRS	TSN:3522	.4			3522			0
			AFL	TSN:726	1			726			0
	B371	Y-637030	MOS	TSN:119	3.2			19 Sep 2024			N/A
			MSC				O/C				
Airframe											
262438	Portable FIRE Extinguisher (Aft Lavatory) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.3	43	12	18 Sep 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
262439	Portable FIRE Extinguisher (Aft Lavatory) - Weight Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.2		12	19 Sep 2024	30 Sep 2025	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m] WEIGHT CHECK								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262440	Portable FIRE Extinguisher (Aft Lavatory) - (Hydrostatic)		HRS		3509.1			13.3			0
	Functional Check		AFL		722			5			0
			MOS		123			27 Sep 2014			
			MSC				O/C				HYDRO CHECK
Airframe			[End Of Month Item]								
Notes: PN: B371 SN: Y-637030.											
262448	Portable Water FIRE Extinguisher - Removal / Installation		HRS		.4			3522			0
	892480	30598	AFL		1			726			0
			MOS		3.2			19 Sep 2024			N/A
			MSC				O/C				
Airframe											
262450	Portable Water FIRE Extinguisher - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.3	43	12	18 Sep 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
262452	Portable Water FIRE Extinguisher - (Hydrostatic)		HRS		485.9			3036.5			0
	Functional Check		AFL		97			630			0
			MOS		25.1		60	22 Nov 2022	30 Nov 2027		
			[End Of Month Item]								
Airframe			HYDRO CHECK								
262500	Trash Receptacle Enclosure (Forward Lavatory) - Detailed		HRS		.4			3522			0
	Inspection		AFL		1			726			0
			MOS		2.7	27	12	04 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
27 - Flight Controls											
270001	Flight Control Cable Tension - Adjustment / Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.4			14 Nov 2022			
			MSC				O/C				
Airframe											
270002	Flight Control System Rigging (Cockpit) - Adjustment /		HRS		485.9			3036.5			0
	Test		AFL		97			630			0
			MOS		25.4			14 Nov 2022			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
270003	Control Cable Tension - Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
270100	Flight Control Computer (No. 1) Channel A Mon Module - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P2700001Z104\GA07	C13204003297	MOS	TSN:6	50.5			09 Oct 2020			THALES
	10.1		MSC				O/C				
270101	Flight Control Computer (No. 1) Channel B Com Module - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P2700001Z204/GA07	C13212003058	MOS	TSN:6	50.5			09 Oct 2020			THALES
	10.1		MSC				O/C				
270102	Flight Control Computer (No. 1) Fan Module - Removal / Installation		HRS	TSN:125.7	3396.7			125.7			0
			AFL	TSN:25	702			25			0
	60P2700001Z301	C13211003403	MOS	TSN:8	120			27 Dec 2014			
	Airframe		MSC				O/C				
270103	Flight Control Computer (No. 2) Fan Module - Removal / Installation		HRS	TSN:1209.9	2312.5			1209.9			0
			AFL	TSN:248	479			248			0
	60P2700001Z301	C13211003404	MOS	TSN:41	87.1			24 Sep 2017			
	Airframe		MSC				O/C				
270104	Flight Control Computer (No. 1) Channel A Com Module - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P2700001Z104/GA07	C13204003803	MOS	TSN:6	50.5			09 Oct 2020			THALES
	10.1		MSC				O/C				
270105	Flight Control Computer (No. 1) Channel B Mon Module - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P2700001Z204/GA07	C13212003779	MOS	TSN:6	50.5			09 Oct 2020			THALES
	10.1		MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
270110	Flight Control Computer (No. 2) Channel A Mon Module - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P2700001Z104\GA07	C13204003805	MOS	TSN:6	50.5			09 Oct 2020			THALES
	10.1		MSC			O/C					
Airframe											
270111	Flight Control Computer (No. 2) Channel B Com Module - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P2700001Z204\GA07	C13212003076	MOS	TSN:6	50.5			09 Oct 2020			THALES
	10.1		MSC			O/C					
Airframe											
270112	Flight Control Computer (No. 2) Channel A Com Module - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P2700001Z104\GA07	C13204003931	MOS	TSN:6	50.5			09 Oct 2020			THALES
	10.1		MSC			O/C					
Airframe											
270113	Flight Control Computer (No. 2) Channel B Mon Module - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P2700001Z204\GA07	C13212003921	MOS	TSN:6	50.5			09 Oct 2020			THALES
	10.1		MSC			O/C					
Airframe											
270120	Flight Control Computer Rack (No. 1) - Removal / Installation		HRS	TSN:4.6	3522.4			0			0
			AFL	TSN:2	727			0			0
	60P2700001Z400	C13213003400	MOS	TSN:7	128.2			21 Apr 2014			
	0	0	MSC			O/C					
Airframe											
270121	Flight Control Computer Rack (No. 2) - Removal / Installation		HRS	TSN:1209.9	2312.5			1209.9			0
			AFL	TSN:248	479			248			0
	60P2700001Z400	13213003406	MOS	TSN:41	87.1			24 Sep 2017			
			MSC			O/C					
Airframe											
270126	Flight Control Computer - Functional Test		HRS		2617.8			904.6			0
			AFL		534			193			0
			MOS		94.9			29 Jan 2017			
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
270127	Flight Control Electrical Backup MODE - Functional Test		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			09 Oct 2024			
	Airframe			MSC				O/C			
270200	Backup Flight Control Unit - Removal / Installation		HRS		3522.4			0			0
	60P2700002Z004\BA01	C13174003128	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
270201	Backup Flight Control Unit - Communication Check		HRS		447.3			3075.1			0
			AFL		92			635			0
			MOS		24			27 Dec 2022			
	Airframe			MSC				O/C			
270202	Backup Flight Control Unit - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
270300	Aileron and Elevator Control Module Assembly (Pilot) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2711101Z004	212360	MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
270301	Aileron and Elevator Control Module Assembly (Copilot) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2711201Z004	214653	MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
270308	Trim Control Module - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
271000	Aileron Electrical Rig (Left) - Functional Check		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.1			23 Sep 2018			
	Airframe			MSC				O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271001	Aileron Electrical Rig (Right) - Functional Check		HRS		1912.8			1609.6			0
			AFL		397			330		0	
			MOS		75.1		23 Sep 2018				
			MSC			O/C					
271002	Aileron Actuating System Ibit Suite A Test - Operational Check		HRS		.4		600	3522	4122	4172	0
			AFL		1		726		0		
			MOS		2.6		08 Oct 2024				
			[HRS: +50/-50]								
271004	Aileron (Left) - Functional Test		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		25.3		17 Nov 2022				
			MSC			O/C					
271005	Aileron (Right) - Functional Test		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		25.3		17 Nov 2022				
			MSC			O/C					
271006	Aileron / Flight Spoiler System - Functional Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
271007	Aileron Attachment (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		25.5	-10	48	10 Nov 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
271008	Aileron Attachment (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		25.5	-10	48	10 Nov 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
271009	Primary Flight Control System Actuator Integrity (Suite B) - Initiated Built-In Test - Operational Check		HRS		3522.4		6000	0	6000	6050	0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			[HRS: +50/-50]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271100	Aileron (Left) - Removal / Installation		HRS		3522.4			0			0
	60P5760001A008		AFL		727			0			0
	LM052		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271101	Aileron (Right) - Removal / Installation		HRS		3522.4			0			0
	60P5760002A004		AFL		727			0			0
	LM052		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271110	Aileron Force Sensor (Pilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711106Z003		AFL		727			0			0
	R130ZW		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271111	Aileron Force Sensor (Copilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711106Z003		AFL		727			0			0
	V13052		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271112	Secondary Load Path Lateral / Longitudinal Control (Pilot)		HRS		3522.4			0			0
	- Removal / Installation		AFL		727			0			0
	60P2711005Z001		MOS		128.2			21 Apr 2014			
	170058		MSC				O/C				
271113	Secondary Load Path Lateral / Longitudinal Control		HRS		3522.4			0			0
	(Copilot) - Removal / Installation		AFL		727			0			0
	60P2711005Z001		MOS		128.2			21 Apr 2014			
	170001		MSC				O/C				
271114	Aileron Control Override Pushrod - Removal / Installation		HRS		3522.4			0			0
	60P2711310Z001		AFL		727			0			0
	194923		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271115	Aileron Trim Interconnect Pushrod - Removal / Installation		HRS		3522.4			0			0
	60P2711309Z001		AFL		727			0			0
	168630		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271119	Aileron Trim Actuator - Removal / Installation		HRS		3522.4			0			0
	60P2711110Z001	140	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
271120	Trim Control Module - Removal / Installation		HRS	TSN:9.9	3522.4			0			0
	60P2711002Z005	169298	AFL	TSN:5	727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
271122	Aileron Control Module Rvdt (Pilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711107Z002	A646	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
271123	Elevator Control Module Rvdt (Pilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711107Z002	A644	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
271124	Elevator Control Module Rvdt (Copilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711107Z002	A685	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
271125	Aileron Control Module Rvdt (Copilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711107Z002	A683	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
271126	Aileron Control Override Pushrod Bungee Torque - Functional Check		HRS		485.9		6000	3036.5	9036.5	9086.5	0
			AFL		97			630			0
			MOS		25.4			14 Nov 2022			
	Airframe			[HRS: +50/-50]							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271127	Aileron Trim Centering Bungee - General Visual Inspection		HRS		3522.4		6000	0	6000	6050	0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014		0		
			[HRS: +50/-50]								
Airframe											
271128	Cockpit Flight Control Cable - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		25.4	-22	96	14 Nov 2022	31 Oct 2030*	30 Nov 2030	0
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
271140	ROD - Reaction, Lateral / Longitudinal Control Module - Removal / Installation 60P2711006Z001169174		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014		0		
			MSC				O/C				
Airframe											
271182	Aileron Free Play Backlash (Left) - Functional Check		HRS		485.9		1200	3036.5	4236.5	4286.5	0
			AFL		97		630		0		
			MOS		25.2		120	19 Nov 2022	30 Nov 2032	31 Dec 2032	0
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
Notes: PUSH PULL 560619 DATE 5/2018DIAL 568204 DATE 2/2018DIAL 570426 DATE 4/2018											
271183	Aileron Free Play Backlash (Right) - Functional Check		HRS		485.9		1200	3036.5	4236.5	4286.5	0
			AFL		97		630		0		
			MOS		25.2		120	19 Nov 2022	30 Nov 2032	31 Dec 2032	0
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
Notes: PUSH PULL 560619 DATE 5/2018DIAL 568204 DATE 2/2018DIAL 570426 DATE 4/2018											
271300	Elevator Remote Electronics Unit (Left Ehsa) - Removal / Installation 60P2715001Z005/35303535		HRS		1912.8			1609.6			0
			AFL		397		330		0		
			MOS		75.1		23 Sep 2018				
			MSC				O/C				
Airframe											
271301	Elevator Remote Electronics Unit (Left Ebha) - Removal / Installation 60P2715001Z006/35188735		HRS		1912.8			1609.6			0
			AFL		397		330		0		
			MOS		75.1		23 Sep 2018		Parker		
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271302	Elevator Remote Electronics Unit (Right Ehsa) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2715001Z006/35	1881	MOS		75.1			23 Sep 2018			Parker
	35		MSC				O/C				
Airframe											
271303	Elevator Remote Electronics Unit (Right Ebha) - Removal / Installation		HRS		447.3			3075.1			0
			AFL		92			635			0
	60P2715001Z306/35	9387	MOS		24			27 Dec 2022			
	A		35	MSC				O/C			
Airframe											
271304	Elevator Eb Manifold (Left) - Removal / Installation		HRS		1912.8			1609.6			0
	60P2713301Z004		AFL		397			330			0
			MOS		75.3			18 Sep 2018			N/A
			MSC				O/C				
Airframe											
271305	Elevator Eb Manifold (Right) - Removal / Installation		HRS		1912.8			1609.6			0
	60P2713301Z004		AFL		397			330			0
			MOS		75.3			18 Sep 2018			N/A
			MSC				O/C				
Airframe											
271306	Elevator Motor Control Electronics (Left) - Removal / Installation		HRS	TSN:1609.6	1912.8			1609.6			0
			AFL	TSN:330	397			330			0
	60P2715003Z309\21	0367	MOS	TSN:53	75			25 Sep 2018			Parker
	21		MSC				O/C				
Airframe											
Notes: ***SOFTWARE UPDATE ONLY***REF CORRIDOR 28.62, STAMP X-FER											
271307	Elevator Motor Control Electronics (Right) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2715003Z309\21	0371	MOS		75.1			24 Sep 2018			Parker
	21		MSC				O/C				
Airframe											
271308	Rudder Remote Electronics Unit (Ehsa) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2715001Z006/35	1403	MOS		75.1			23 Sep 2018			Parker
	35		MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271309	Rudder Remote Electronics Unit (Ha) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2715001Z006/35	1875	MOS		75.1			23 Sep 2018			Parker
		35	MSC				O/C				
Airframe											
271310	Aileron Remote Electronics Unit (Left Ehsa) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2715001Z006/35	2043	MOS		75.1			23 Sep 2018			Parker
		35	MSC				O/C				
Airframe											
271311	Aileron Remote Electronics Unit (Left Ha) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2715001Z006/35	3119	MOS		75.1			23 Sep 2018			Parker
		35	MSC				O/C				
Airframe											
271312	Aileron Remote Electronics Unit (Right Ehsa) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2715001Z006/35	2028	MOS		75.1			23 Sep 2018			Parker
		35	MSC				O/C				
Airframe											
271313	Aileron Remote Electronics Unit (Right Ha) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2715001Z006/35	1993	MOS		75.1			23 Sep 2018			Parker
		35	MSC				O/C				
Airframe											
271314	Aileron Motor Control Electronics (Left) - Removal / Installation		HRS	TSN:1609.6	1912.8			1609.6			0
			AFL	TSN:330	397			330			0
	60P2715003Z310/20	0518	MOS	TSN:53	75.2			20 Sep 2018			N/A
			MSC				O/C				
Airframe											
271315	Aileron Motor Control Electronics (Right) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2715003Z312	0480	MOS		75.1			22 Sep 2018			PARKER
		21	MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271320	Aileron Ha Manifold (Left) - Removal / Installation		HRS		3522.4			0			0
	60P2713101Z005 0219		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271321	Aileron Ha Manifold (Right) - Removal / Installation		HRS		3522.4			0			0
	60P2713101Z005 0211		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271322	Aileron Eb Manifold (Left) - Removal / Installation		HRS		1912.8			1609.6			0
	60P2713301Z004 1642D		AFL		397			330			0
			MOS		75.2			20 Sep 2018			N/A
	Airframe		MSC				O/C				
271323	Aileron Eb Manifold (Right) - Removal / Installation		HRS		1912.8			1609.6			0
	60P2713301Z004 1699D		AFL		397			330			0
			MOS		75.2			19 Sep 2018			Parker
	Airframe		MSC				O/C				
Notes: TW: 560432 DUE: 11/18 DLRO: 570985 DLRO: 11/18											
271324	Aileron Ehsa Manifold (Left) - Removal / Installation		HRS		3522.4			0			0
	60P2713201Z004 0230		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271325	Aileron Ehsa Manifold (Right) - Removal / Installation		HRS		3522.4			0			0
	60P2713201Z004 0228		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271326	Aileron Ehsa Actuator (Left) - Removal / Installation		HRS		3522.4			0			0
	60P2713002Z100 0461		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271327	Aileron Ehsa Actuator (Right) - Removal / Installation		HRS		3522.4			0			0
	60P2713002Z200 0275		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271328	Aileron Ebha Actuator (Left) - Removal / Installation		HRS		3522.4			0			0
	60P2713001Z100		AFL		727			0			0
	0476		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271329	Aileron Ebha Actuator (Right) - Removal / Installation		HRS		3522.4			0			0
	60P2713001Z200		AFL		727			0			0
	0483		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
271360	Aileron Ha Manifold (Left) - Discard		HRS		3522.4			0			0
	60P2713101Z005		AFL		727		8500	0	8500		0
	0219		MOS		128.2			21 Apr 2014			
	Airframe										
271361	Aileron Ha Manifold (Right) - Discard		HRS		3522.4			0			0
	60P2713101Z005		AFL		727		8500	0	8500		0
	0211		MOS		128.2			21 Apr 2014			
	Airframe										
271362	Aileron Ehsa Manifold (Left) - Discard		HRS		3522.4			0			0
	60P2713201Z004		AFL		727		8500	0	8500		0
	0230		MOS		128.2			21 Apr 2014			
	Airframe										
271363	Aileron Ehsa Manifold (Right) - Discard		HRS		3522.4			0			0
	60P2713201Z004		AFL		727		8500	0	8500		0
	0228		MOS		128.2			21 Apr 2014			
	Airframe										
271364	Aileron Eb Manifold (Left) - Discard		HRS		1912.8			1609.6			0
	60P2713301Z004		AFL		397			330			0
	1642D		MOS		75.2			20 Sep 2018			
	Airframe		MSC				O/C				
271365	Aileron Eb Manifold (Right) - Discard		HRS		1912.8			1609.6			0
	60P2713301Z004		AFL		397			330			0
	1699D		MOS		75.2			19 Sep 2018			
	Airframe		MSC				O/C				
Notes: TW: 560432 DUE: 11/18 DLRO: 570985 DLRO: 11/18											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
271530	Aileron Trim Actuator Range of Motion - Functional Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.4			14 Nov 2022			
			MSC				O/C				
271600	Aileron Autopilot Servo (Pilot) - Removal / Installation 2R5331A1431		HRS		1039.9			2482.5			0
			AFL		216			511			0
			MOS		43.7			04 May 2021			N/A
			MSC				O/C				
271601	Aileron Autopilot Servo (Copilot) - Removal / Installation 60P2212001Z0010456		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
272000	Rudder - Removal / Installation 60A5540000-001600		HRS	TSN:2092.9	1429.5			2092.9			0
			AFL	TSN:416	311			416			0
			MOS	TSN:69	59.9			29 Dec 2019			
			MSC				O/C				
272002	Rudder Free Play Backlash - Functional Check		HRS		485.9		1200	3036.5	4236.5	4286.5	0
			AFL		97			630			0
			MOS		25.2		120	19 Nov 2022	30 Nov 2032	31 Dec 2032	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
272003	Rudder Electrical Rig - Functional Check		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.1			23 Sep 2018			
			MSC				O/C				
272004	Rudder Actuating System Ibit Suite A Test - Operational Check		HRS		.4		600	3522	4122	4172	0
			AFL		1			726			0
			MOS		2.6			08 Oct 2024			
			[HRS: +50/-50]								
272006	Rudder - Functional Test		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.1			24 Sep 2018			
			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272008	Rudder Control Linkages and Dampers - General Visual Inspection		HRS		3522.4		6000	0	6000	6050	0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			[HRS: +50/-50]								
Airframe											
Notes: PN: 60P2212001Z001 SN: <NONE>.											
272009	Rudder Control Module Primary Stops - General Visual Inspection		HRS		3522.4		6000	0	6000	6050	0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			[HRS: +50/-50]								
Airframe											
272010	Rudder Attachment - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.2	12	48	19 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
272100	Rudder Pedal Assembly (Pilot) - Removal / Installation 60P2721100Z004199555		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
272101	Rudder Pedal Assembly (Copilot) - Removal / Installation 60P2721200Z005207318		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
272102	Rudder Force Sensor (Pilot) - Removal / Installation 60P2721101Z002176670		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
272103	Rudder Force Sensor (Copilot) - Removal / Installation 60P2721101Z002173057		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272106	Rudder Pedal Assembly (Pilot) - Discard		HRS		3522.4			0			0
	60P2721100Z004	199555	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 272100											
272107	Rudder Pedal Assembly (Copilot) - Discard		HRS		3522.4			0			0
	60P2721200Z005	207318	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 272101											
272108	Rudder Force Sensor (Pilot) - Discard		HRS		3522.4			0			0
	60P2721101Z002	176670	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 272102											
272109	Rudder Force Sensor (Copilot) - Discard		HRS		3522.4			0			0
	60P2721101Z002	173057	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 272103											
272204	Rudder Control Module Rvdt - Removal / Installation		HRS		3522.4			0			0
	60P2711107Z002	A629	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
272300	Rudder Ehsa Actuator - Removal / Installation		HRS		3522.4			0			0
	60P2723002Z003	0179	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
272301	Rudder Ebha Actuator - Removal / Installation		HRS		3522.4			0			0
	60P2723001Z004	0157	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272302	Rudder Ha Manifold - Removal / Installation		HRS		3522.4			0			0
	60P2723101Z004	0036	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
272303	Rudder Eb Manifold - Removal / Installation		HRS		1912.8			1609.6			0
	60P2713301Z004	1616D	AFL		397			330			0
			MOS		75.3			18 Sep 2018			N/A
	Airframe		MSC				O/C				
272304	Rudder Ehsa Manifold - Removal / Installation		HRS		3522.4			0			0
	60P2723201Z003	0094	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
272306	Rudder Motor Control Electronics - Removal / Installation		HRS		1912.8			1609.6			0
	60P2715003Z309\21	0372	AFL		397			330			0
		21	MOS		75.1			24 Sep 2018			Parker
	Airframe		MSC				O/C				
272314	Rudder Ha Manifold - Discard		HRS		3522.4			0			0
	60P2723101Z004	0036	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 272302											
272315	Rudder Ehsa Manifold - Discard		HRS		3522.4			0			0
	60P2723201Z003	0094	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 272304											
272316	Rudder Eb Manifold - Discard		HRS		1912.8			1609.6			0
	60P2713301Z004	1616D	AFL		397			330			0
			MOS		75.3			18 Sep 2018			
	Airframe		MSC				O/C				
272400	Rudder Control Module Assembly - Removal / Installation		HRS		3522.4			0			0
	60P2721300Z003	207868	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
272402	Rudder Control Module Assembly - Discard		HRS		3522.4			0			0
	60P2721300Z003	207868	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 272400											
272503	Rudder Damper (Pilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711108Z001	0704	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
272504	Rudder Damper (Copilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711108Z001	0709	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273000	Aileron Damper (Pilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711108Z001	0747	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273001	Aileron Damper (Copilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711108Z001	0763	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273002	Elevator (Left) - Functional Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.3			17 Nov 2022			
	Airframe		MSC				O/C				
273003	Elevator (Right) - Functional Test		HRS		447.3			3075.1			0
			AFL		92			635			0
			MOS		24			27 Dec 2022			
	Airframe		MSC				O/C				
273004	Elevator Electrical Rig (Left) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.3			17 Nov 2022			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273005	Elevator Electrical Rig (Right) - Functional Check		HRS		447.3			3075.1			0
			AFL		92			635		0	
			MOS		24			27 Dec 2022			
			MSC				O/C				
273006	Elevator Actuating System Ibit Suite A Test - Operational Check		HRS		.4		600	3522	4122	4172	0
			AFL		1			726		0	
			MOS		2.6			08 Oct 2024			
			[HRS: +50/-50]								
273008	Elevator Free Play Backlash (Left) - Functional Check		HRS		485.9		1200	3036.5	4236.5	4286.5	0
			AFL		97			630		0	
			MOS		25.2		120	19 Nov 2022	30 Nov 2032	31 Dec 2032	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
273009	Elevator Free Play Backlash (Right) - Functional Check		HRS		485.9		1200	3036.5	4236.5	4286.5	0
			AFL		97			630		0	
			MOS		25.2		120	19 Nov 2022	30 Nov 2032	31 Dec 2032	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
273010	Elevator Attachment (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		25.3	-17	48	17 Nov 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
273011	Elevator Attachment (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		25.3	-17	48	17 Nov 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
273012	Elevator Control System - General Visual Inspection		HRS		3522.4		6000	0	6000	6050	0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			[HRS: +50/-50]								
273100	Aileron Control Wheel (Left) - Removal / Installation 60P2711103Z001 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273101	Aileron Control Wheel (Right) - Removal / Installation		HRS		3522.4			0			0
	60P2711203Z004	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273102	Control Column (Pilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711102Z001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273103	Control Column (Copilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711200Z005	212127	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273104	Aileron Control Column/Wheel Assembly (Pilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711100Z005	187389	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273105	Aileron Control Column/Wheel Assembly (Copilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711200Z005	212127	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273120	Elevator Force Sensor (Pilot) - Removal / Installation		HRS		3522.4			0			0
	60P2731101Z002	208736	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273121	Elevator Force Sensor (Copilot) - Removal / Installation		HRS		3522.4			0			0
	60P2731101Z002	208737	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273122	Elevator Control Override Pushrod - Removal / Installation		HRS		3522.4			0			0
	60P2731305Z002	196886	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273124	Elevator Control Override Pushrod - Functional Check		HRS		3522.4		6000	0	6000	6050	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		[HRS: +50/-50]								
273125	Elevator (Left) - Removal / Installation		HRS		485.9			3036.5			0
	60A5520001-005	6080	AFL		97			630			0
			MOS		24.8			01 Dec 2022			FOKKER
	Airframe		MSC				O/C				
273126	Elevator (Right) - Removal / Installation		HRS		485.9			3036.5			0
	60A5520002-005	6090	AFL		97			630			0
			MOS		24.8			01 Dec 2022			FOKKER
	Airframe		MSC				O/C				
273200	Stick Shaker Motor (Pilot) - Removal / Installation		HRS		3522.4			0			0
	60P2731104Z002	0188	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273201	Stick Shaker Motor (Copilot) - Removal / Installation		HRS		3522.4			0			0
	60P2731104Z002	245	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273300	Elevator Ebha Actuator (Left) - Removal / Installation		HRS		3522.4			0			0
	60P2733001Z004	0452	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273301	Elevator Ebha Actuator (Right) - Removal / Installation		HRS	TSN:980.9	1158			2364.4			0
	60P2733001Z004	0032	AFL	TSN:403	239			488			0
			MOS	TSN:70	49.9			29 Oct 2020			N/A
	Airframe		MSC				O/C				
273302	Elevator Ehsa Actuator (Left) - Removal / Installation		HRS		3522.4			0			0
	60P2733002Z005	0409	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273303	Elevator Ehsa Actuator (Right) - Removal / Installation		HRS		1158			2364.4			0
	60P2733002Z005	0344	AFL		239			488			0
			MOS		49.9			29 Oct 2020			N/A
	Airframe		MSC				O/C				
273304	Elevator Ehsa Manifold (Left) - Removal / Installation		HRS		3522.4			0			0
	60P2733201Z002	0217	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273305	Elevator Ehsa Manifold (Right) - Removal / Installation		HRS		3522.4			0			0
	60P2733201Z002	0216	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273306	Elevator Ha Manifold (Left) - Removal / Installation		HRS		3522.4			0			0
	60P2733101Z003	0197	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273307	Elevator Ha Manifold (Right) - Removal / Installation		HRS		3522.4			0			0
	60P2733101Z003	0097	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273326	Elevator Ehsa Manifold (Left) - Discard		HRS		3522.4			0			0
	60P2733201Z002	0217	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 273304											
273327	Elevator Ehsa Manifold (Right) - Discard		HRS		3522.4			0			0
	60P2733201Z002	0216	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 273305											
273328	Elevator Eb Manifold (Left) - Discard		HRS		1912.8			1609.6			0
	60P2713301Z004	1210D	AFL		397			330			0
			MOS		75.3			18 Sep 2018			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273329	Elevator Eb Manifold (Right) - Discard		HRS		1912.8			1609.6			0
	60P2713301Z004		AFL		397			330			0
	1607D		MOS		75.3			18 Sep 2018			
	Airframe		MSC				O/C				
273500	Elevator Lvdt (Left) - Removal / Installation		HRS		3522.4			0			0
	60P2734000Z001		AFL		727			0			0
	097997		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273501	Elevator Lvdt (Right) - Removal / Installation		HRS		3522.4			0			0
	60P2734000Z001		AFL		727			0			0
	098003		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273508	Elevator Damper (Pilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711108Z001		AFL		727			0			0
	0588		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273509	Elevator Damper (Copilot) - Removal / Installation		HRS		3522.4			0			0
	60P2711108Z001		AFL		727			0			0
	0744		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
273600	Elevator Autopilot Servo (Pilot) - Removal / Installation		HRS		1039.9			2482.5			0
	2R5331A		AFL		216			511			0
	0679		MOS		43.7			04 May 2021			
	Airframe		MSC				O/C				
273601	Elevator Autopilot Servo (Copilot) - Removal / Installation		HRS		3522.4			0			0
	60P2212001Z001		AFL		727			0			0
	0464		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
274000	Horizontal Stabilizer Electrical Rig - Functional Check		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.1			23 Sep 2018			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
274001	Horizontal Stabilizer Trim Actuator Backlash - Functional Check		HRS		3522.4		6000	0	6000	6050	0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			[HRS: +50/-50]								
Airframe											
274002	Horizontal Stabilizer Trim Actuator Secondary Nut Mechanism and Clutch - Operational Check		HRS		3522.4		4800	0	4800	4850	0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			[HRS: +50/-50]								
Airframe											
274003	Horizontal Stabilizer Trim Actuator Tie ROD Mechanism - Operational Check		HRS		3522.4		4800	0	4800	4850	0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			[HRS: +50/-50]								
Airframe											
274005	Horizontal Stabilizer Trim Actuator Structure - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1	192	23 Oct 2014	31 Oct 2030	30 Nov 2030		
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
274006	Horizontal Stabilizer Trim Actuator - Detailed Inspection		HRS		3522.4		6000	0	6000	6050	0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			[HRS: +50/-50]								
Airframe											
274007	Horizontal Stabilizer Trim Actuator Motor CAP - Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC				O/C				
Airframe											
274008	Horizontal Stabilizer - Functional Test		HRS		1912.8			1609.6			0
			AFL		397			330		0	
			MOS		75.1		23 Sep 2018				
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
274200	Horizontal Stabilizer Trim Actuator - Removal / Installation		HRS		3522.4			0			0
	60P2743000Z003\2	00106	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
274201	Horizontal Stabilizer Trim Actuator Motor (Left) - Removal / Installation		HRS		3522.4			0			0
	60P2743001Z006	303	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
274202	Horizontal Stabilizer Trim Actuator Motor (Right) - Removal / Installation		HRS		3522.4			0			0
	60P2743001Z006	304	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
274300	Horizontal Stabilizer Position Resolver (Left) - Removal / Installation		HRS		3522.4			0			0
	60P2744000Z001	Y2328	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
274301	Horizontal Stabilizer Position Resolver (Right) - Removal / Installation		HRS		3522.4			0			0
	60P2744000Z001	Y2601	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
274500	Horizontal Stabilizer - Seating Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
274501	Horizontal Stabilizer Control Unit - Removal / Installation		HRS		1912.8			1609.6			0
	60P2745000Z106	41DDM2	AFL		397			330			0
			MOS		75.3			17 Sep 2018			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275000	Flap Drive System - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	16	48	15 Oct 2022	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
275001	Flap System - Functional Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.3			16 Nov 2022			
	Airframe			MSC			O/C				
275002	Flap System - Operational Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.3			16 Nov 2022			
	Airframe			MSC			O/C				
275003	Flap System Electrical Rig - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.1			22 Nov 2022			
	Airframe			MSC			O/C				
275004	Flap System - Mechanical Rig		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.1			23 Sep 2018			
	Airframe			MSC			O/C				
275009	Flap Attaching Points - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	16	48	15 Oct 2022	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
275058	A Track Flap Roller (Left Inboard) - Discard 60P5755371Z012NSN		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
			MOS	TSN:1	50.4			14 Oct 2020			
	Airframe	[HRS: +50/-50]									
Notes: MRI PARENT CODE: 275109											
275059	A Track Flap Roller (Left Outboard) - Discard 60P5755371Z012NSN		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
			MOS	TSN:1	50.4			14 Oct 2020			
	Airframe	[HRS: +50/-50]									
Notes: MRI PARENT CODE: 275110											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275060	A Track Flap Roller (Left Trailing Edge) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	KRP505-04VT		AFL		239			488			0
			MOS	TSN:7	50.4			14 Oct 2020			
	Airframe		[HRS: +50/-50]								
Notes: MRI PARENT CODE: 275111											
275061	A Track Flap Roller (Right Inboard) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	60P5755371Z005		AFL		239			488			0
			MOS		49.9			28 Oct 2020			
	Airframe		[HRS: +50/-50]								
Notes: MRI PARENT CODE: 275112											
275062	A Track Flap Roller (Right Outboard) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	60P5755371Z005		AFL		239			488			0
			MOS	TSN:1	50.4			15 Oct 2020			
	Airframe		[HRS: +50/-50]								
Notes: MRI PARENT CODE: 275113											
275063	A Track Flap Roller (Right Trailing Edge) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	KRP505-04VT		AFL		239			488			0
			MOS		50.4			15 Oct 2020			
	Airframe		[HRS: +50/-50]								
Notes: MRI PARENT CODE: 275114											
275064	B Track Flap Roller (Left Inboard Upper Aft) - Discard		HRS		485.9		2400	3036.5	5436.5	5486.5	0
	60P5755371Z014		AFL		97			630			0
			MOS		25.7			04 Nov 2022			
	Airframe		[HRS: +50/-50]								
275065	B Track Flap Roller (Left Outboard Upper Aft) - Discard		HRS		485.9		2400	3036.5	5436.5	5486.5	0
	60P5755371Z014		AFL		97			630			0
			MOS		25.7			04 Nov 2022			
	Airframe		[HRS: +50/-50]								
275066	B Track Flap Roller (Left Inboard Upper Forward) - Discard		HRS		485.9		2400	3036.5	5436.5	5486.5	0
	60P5755371Z002		AFL		97			630			0
			MOS		25.2			21 Nov 2022			
	Airframe		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275067	B Track Flap Roller (Left Outboard Upper Forward) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z002	NSN	MOS	TSN:2	50.4			14 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275124											
275068	B Track Flap Roller (Left Inboard Lower Forward) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			14 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275125											
275069	B Track Flap Roller (Left Outboard Lower Forward) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			14 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275126											
275070	B Track Flap Roller (Right Inboard Upper Aft) - Discard		HRS		485.9		2400	3036.5	5436.5	5486.5	0
	60P5755371Z014		AFL		97			630			0
		NSN	MOS	TSN:3	25.9			29 Oct 2022			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275127											
275071	B Track Flap Roller (Right Outboard Upper Aft) - Discard		HRS		485.9		2400	3036.5	5436.5	5486.5	0
	60P5755371Z014		AFL		97			630			0
		NSN	MOS	TSN:3	25.9			29 Oct 2022			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275128											
275072	B Track Flap Roller (Right Inboard Upper Forward) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z002	NSN	MOS	TSN:2	50.2			19 Oct 2020			
	[HRS: +50/-50]										
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275073	B Track Flap Roller (Right Outboard Upper Forward) -		HRS		1158		2400	2364.4	4764.4	4814.4	0
	Discard		AFL		239			488			0
	60P5755371Z002	NSN	MOS	TSN:2	50.4			15 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275130											
275074	B Track Flap Roller (Right Inboard Lower Forward) -		HRS		1158		2400	2364.4	4764.4	4814.4	0
	Discard		AFL		239			488			0
	60P5755371Z003	NSN	MOS		50.4			15 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275131											
275075	B Track Flap Roller (Right Outboard Lower Forward) -		HRS		1158		2400	2364.4	4764.4	4814.4	0
	Discard		AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			15 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275132											
275076	C Track Flap Roller (Left Inboard Upper Aft) - Discard		HRS		485.9		2400	3036.5	5436.5	5486.5	0
	60P5755371Z014		AFL		97			630			0
		NSN	MOS		25.7			04 Nov 2022			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275137											
275077	C Track Flap Roller (Left Inboard Lower Forward) -		HRS		1158		2400	2364.4	4764.4	4814.4	0
	Discard		AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			14 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275146											
275078	C Track Flap Roller (Left Inboard Upper Forward) -		HRS		1508.2		2400	2014.2	4414.2	4464.2	0
	Discard		AFL		311			416			0
	60P5755371Z007	NSN	MOS	TSN:6	63.3			18 Sep 2019			N/A
	[HRS: +50/-50]										
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275079	C Track Flap Roller (Left Outboard Upper Forward) - Discard		HRS		485.9		2400	3036.5	5436.5	5486.5	0
			AFL		97			630			0
	60P5755371Z014	NSN	MOS		25.7			04 Nov 2022			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275148											
275080	C Track Flap Roller (Left Outboard Upper Aft) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	60P5755371Z0011		AFL		239			488			0
		NSN	MOS	TSN:1	50.4			14 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275149											
275081	C Track Flap Roller (Left Outboard Lower Forward) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			14 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275150											
275082	C Track Flap Roller (Right Inboard Upper Aft) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	60P5755371Z011		AFL		239			488			0
		NSN	MOS	TSN:1	50.3			16 Oct 2020			
	[HRS: +50/-50]										
Airframe											
275083	C Track Flap Roller (Right Inboard Lower Forward) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			15 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275152											
275084	C Track Flap Roller (Right Inboard Upper Forward) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z007	NSN	MOS	TSN:5	50.2			19 Oct 2020			
	[HRS: +50/-50]										
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275085	C Track Flap Roller (Right Outboard Upper Forward) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z007	NSN	MOS	TSN:5	50.4			15 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275154											
275086	C Track Flap Roller (Right Outboard Upper Aft) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z011	NSN	MOS	TSN:1	50.4			15 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275155											
275087	C Track Flap Roller (Right Outboard Lower Forward) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			15 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275156											
275088	D Track Flap Roller (Left Inboard Upper) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	P5755371Z009	NSN	MOS	TSN:6	50.4			15 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275169											
275089	D Track Flap Roller (Left Outboard Upper) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z009	NSN	MOS	TSN:6	50.4			15 Oct 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275170											
275090	D Track Flap Roller (Left Trailing Edge Forward) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z004	NSN	MOS	TSN:14	49.8			02 Nov 2020			
	[HRS: +50/-50]										
Airframe											
Notes: MRI PARENT CODE: 275171											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275091	D Track Flap Roller (Left Trailing Edge Aft) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	60P5755371Z004		AFL		239			488			0
	NSN		MOS	TSN:2	49.8			02 Nov 2020			
	Airframe		[HRS: +50/-50]								
Notes: MRI PARENT CODE: 275172											
275092	D Track Flap Roller (Right Inboard Upper) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	60P5755371Z009		AFL		239			488			0
	NSN		MOS	TSN:6	50.4			15 Oct 2020			
	Airframe		[HRS: +50/-50]								
Notes: MRI PARENT CODE: 275173											
275093	D Track Flap Roller (Right Outboard Upper) - Discard		HRS		485.9		2400	3036.5	5436.5	5486.5	0
	60P5755371Z010		AFL		97			630			0
	NSN		MOS		25.7			04 Nov 2022			
	Airframe		[HRS: +50/-50]								
Notes: MRI PARENT CODE: 275174											
275094	D Track Flap Roller (Right Trailing Edge Forward) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	60P5755371Z004		AFL		239			488			0
	NSN		MOS	TSN:2	49.8			02 Nov 2020			
	Airframe		[HRS: +50/-50]								
Notes: MRI PARENT CODE: 275175											
275095	D Track Flap Roller (Right Trailing Edge Aft) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	60P5755371Z004		AFL		239			488			0
	NSN		MOS	TSN:2	49.8			02 Nov 2020			
	Airframe		[HRS: +50/-50]								
Notes: MRI PARENT CODE: 275176											
275096	D Track Flap Down Load Catch Roller (Left Inboard) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	60P5755371Z008		AFL		239			488			0
	NSN		MOS	TSN:5	50.4			15 Oct 2020			
	Airframe		[HRS: +50/-50]								
Notes: MRI PARENT CODE: 275177											
275097	D Track Flap Down Load Catch Roller (Left Outboard) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
	60P5755371Z008		AFL		239			488			0
	NSN		MOS	TSN:5	50.4			15 Oct 2020			
	Airframe		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275098	D Track Flap Down Load Catch Roller (Right Inboard) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z008	NSN	MOS	TSN:5	50.4			15 Oct 2020			
			[HRS: +50/-50]								
Airframe											
275099	D Track Flap Down Load Catch Roller (Right Outboard) - Discard		HRS		1158		2400	2364.4	4764.4	4814.4	0
			AFL		239			488			0
	60P5755371Z008	NSN	MOS	TSN:5	50.4			15 Oct 2020			
			[HRS: +50/-50]								
Airframe											
275101	Horizontal Stabilizer Control Unit Tray - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2745000Z005	42TC01	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
275103	Flap Yoke Fitting (Left) - Visual Inspection		HRS		3522.4			0			0
			AFL		727		15000**	0	15000		0
			MOS		128.2			21 Apr 2014			
Airframe											
275104	Flap Yoke Fitting (Right) - Visual Inspection		HRS		3522.4			0			0
			AFL		727		15000**	0	15000		0
			MOS		128.2			21 Apr 2014			
Airframe											
275108	Flap Track and Roller - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.7	27	12	04 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
275109	A Track Flap Roller (Left Inboard) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z012	NSN	MOS	TSN:1	50.4			14 Oct 2020			KAMATICS
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275110	A Track Flap Roller (Left Outboard) - Removal /		HRS		1158			2364.4			0
	Installation		AFL		239			488			0
	60P5755371Z012	NSN	MOS	TSN:1	50.4			14 Oct 2020			KAMATICS
			MSC				O/C				
Airframe											
275111	A Track Flap Roller (Left Trailing Edge) - Removal /		HRS		1158			2364.4			0
	Installation		AFL		239			488			0
	KRP505-04VT	NSN	MOS	TSN:7	50.4			14 Oct 2020			N/A
			MSC				O/C				
Airframe											
275112	A Track Flap Roller (Right Inboard) - Removal /		HRS		1158			2364.4			0
	Installation		AFL		239			488			0
	60P5755371Z005	NSN	MOS		49.9			28 Oct 2020			
			MSC				O/C				
Airframe											
275113	A Track Flap Roller (Right Outboard) - Removal /		HRS		1158			2364.4			0
	Installation		AFL		239			488			0
	60P5755371Z012	NSN	MOS	TSN:1	50.4			15 Oct 2020			KAMATICS
			MSC				O/C				
Airframe											
275114	A Track Flap Roller (Right Trailing Edge) - Removal /		HRS		1158			2364.4			0
	Installation		AFL		239			488			0
	KRP505-04VT	NSN	MOS	TSN:7	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275121	B Track Flap Roller (Left Inboard Upper Aft) - Removal /		HRS		485.9			3036.5			0
	Installation		AFL		97			630			0
	60P5755371Z014	NSN	MOS	TSN:4	25.7			04 Nov 2022			KAMATICS
			MSC				O/C				
Airframe											
275122	B Track Flap Roller (Left Outboard Upper Aft) - Removal /		HRS		485.9			3036.5			0
	Installation		AFL		97			630			0
	60P5755371Z014	NSN	MOS	TSN:4	25.7			04 Nov 2022			KAMATICS
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275123	B Track Flap Roller (Left Inboard Upper Forward) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	60P5755371Z002	NSN	MOS	TSN:4	25.2			21 Nov 2022			N/A
			MSC				O/C				
Airframe											
275124	B Track Flap Roller (Left Outboard Upper Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z002	NSN	MOS	TSN:2	50.4			14 Oct 2020			N/A
			MSC				O/C				
Airframe											
275125	B Track Flap Roller (Left Inboard Lower Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			14 Oct 2020			N/A
			MSC				O/C				
Airframe											
275126	B Track Flap Roller (Left Outboard Lower Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			14 Oct 2020			N/A
			MSC				O/C				
Airframe											
275127	B Track Flap Roller (Right Inboard Upper Aft) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	60P5755371Z014	NSN	MOS	TSN:3	25.9			29 Oct 2022			KAMATICS
			MSC				O/C				
Airframe											
275128	B Track Flap Roller (Right Outboard Upper Aft) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	60P5755371Z014	NSN	MOS	TSN:3	25.9			29 Oct 2022			KAMATICS
			MSC				O/C				
Airframe											
275129	B Track Flap Roller (Right Inboard Upper Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z002	NSN	MOS	TSN:2	50.2			19 Oct 2020			N/A
			MSC				O/C				
Airframe											

Notes: T/W S/N: 552756 DUE CAL: 11/2016T/W S/N: 558063 DUE CAL: 8/2017T/W S/N: 553005 DUE CAL: 10/2016

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275130	B Track Flap Roller (Right Outboard Upper Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z002	NSN	MOS	TSN:2	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275131	B Track Flap Roller (Right Inboard Lower Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275132	B Track Flap Roller (Right Outboard Lower Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275145	C Track Flap Roller (Left Inboard Upper Aft) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z011	NSN	MOS	TSN:1	50.2			19 Oct 2020			KAMATICS
			MSC				O/C				
Airframe											
Notes: T/W S/N: 58063 DUE CAL: 8/2017T/W S/N: 52756 DUE CAL: 1/2016											
275146	C Track Flap Roller (Left Inboard Lower Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			14 Oct 2020			N/A
			MSC				O/C				
Airframe											
275147	C Track Flap Roller (Left Inboard Upper Forward) - Removal / Installation		HRS		1508.2			2014.2			0
			AFL		311			416			0
	60P5755371Z007	NSN	MOS	TSN:6	63.3			18 Sep 2019			N/A
			MSC				O/C				
Airframe											
275148	C Track Flap Roller (Left Outboard Upper Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z007	NSN	MOS	TSN:5	50.4			14 Oct 2020			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275149	C Track Flap Roller (Left Outboard Upper Aft) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	60P5755371Z014	NSN	MOS	TSN:4	25.7			04 Nov 2022			KAMATICS
			MSC				O/C				
Airframe											
275150	C Track Flap Roller (Left Outboard Lower Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			14 Oct 2020			N/A
			MSC				O/C				
Airframe											
275151	C Track Flap Roller (Right Inboard Upper Aft) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z011	NSN	MOS	TSN:1	50.3			16 Oct 2020			KAMATICS
			MSC				O/C				
Airframe											
275152	C Track Flap Roller (Right Inboard Lower Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275153	C Track Flap Roller (Right Inboard Upper Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z007	NSN	MOS	TSN:5	50.2			19 Oct 2020			N/A
			MSC				O/C				
Airframe											
275154	C Track Flap Roller (Right Outboard Upper Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z007	NSN	MOS	TSN:5	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275155	C Track Flap Roller (Right Outboard Upper Aft) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z011	NSN	MOS	TSN:1	50.4			15 Oct 2020			KAMATICS
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275156	C Track Flap Roller (Right Outboard Lower Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z003	NSN	MOS	TSN:5	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275169	D Track Flap Roller (Left Inboard Upper) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	P5755371Z009	NSN	MOS	TSN:6	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275170	D Track Flap Roller (Left Outboard Upper) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	60P5755371Z010	NSN	MOS	TSN:4	25.7			04 Nov 2022			KAMATICS
			MSC				O/C				
Airframe											
275171	D Track Flap Roller (Left Trailing Edge Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z004	NSN	MOS	TSN:14	49.8			02 Nov 2020			N/A
			MSC				O/C				
Airframe											
275172	D Track Flap Roller (Left Trailing Edge Aft) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z004	NSN	MOS	TSN:2	49.8			02 Nov 2020			N/A
			MSC				O/C				
Airframe											
275173	D Track Flap Roller (Right Inboard Upper) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z009	NSN	MOS	TSN:6	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275174	D Track Flap Roller (Right Outboard Upper) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z010	NSN	MOS	TSN:1	50.3			16 Oct 2020			KAMATICS
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275175	D Track Flap Roller (Right Trailing Edge Forward) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z004	NSN	MOS	TSN:2	49.8			02 Nov 2020			N/A
			MSC				O/C				
Airframe											
275176	D Track Flap Roller (Right Trailing Edge Aft) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z004	NSN	MOS	TSN:2	49.8			02 Nov 2020			N/A
			MSC				O/C				
Airframe											
275185	D Track Flap Down Load Catch Roller (Left Inboard) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z008	NSN	MOS	TSN:5	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275186	D Track Flap Down Load Catch Roller (Left Outboard) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z008	NSN	MOS	TSN:5	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275187	D Track Flap Down Load Catch Roller (Right Inboard) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z008	NSN	MOS	TSN:5	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275188	D Track Flap Down Load Catch Roller (Right Outboard) - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	60P5755371Z008	NSN	MOS	TSN:5	50.4			15 Oct 2020			N/A
			MSC				O/C				
Airframe											
275200	Flap Electronic Control Unit - Removal / Installation		HRS	TSN:3164.3	1508.2			2014.2			0
			AFL	TSN:1378	311			416			0
	60P2755001Z005	045	MOS		63			25 Sep 2019			N/A
	CA54047-010		MSC				O/C				
Airframe											
Notes: P/N: ON 60P2755001Z005 S/N: ON: 045											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275300	Flap (Left) - Removal / Installation		HRS	TSN:3036.1	485.9			3036.5			0
	60P5755003-003	0105	AFL	TSN:629	97			630			0
			MOS	TSN:102	25.2			21 Nov 2022			N/A
	Airframe		MSC				O/C				
Notes: T/W: 568807, CAL DUE: 05/20											
275301	Flap (Right) - Removal / Installation		HRS	TSN:3036.1	485.9			3036.5			0
	60P5755004-003	0107	AFL	TSN:629	97			630			0
			MOS	TSN:102	25.6			08 Nov 2022			N/A
	Airframe		MSC				O/C				
Notes: T/W: 568807, CAL DUE: 05/20											
275302	Flap Door (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
	60P5755901A001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275303	Flap Door (Right Inboard) - Removal / Installation		HRS		3522.4			0			0
	60P5755902A001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275304	Flap Door (Left Mid) - Removal / Installation		HRS		3522.4			0			0
	60P5755905A001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275305	Flap Door (Right Mid) - Removal / Installation		HRS		3522.4			0			0
	60P5755906A001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275306	Flap Door (Left Outboard) - Removal / Installation		HRS		3522.4			0			0
	60P5755909A001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275307	Flap Door (Right Outboard) - Removal / Installation		HRS		3522.4			0			0
	60P5755910A001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275308	Flap Power Drive Unit - Removal / Installation		HRS	TSN:8.4	3522.4			0			0
	60P2756001Z003	0059	AFL	TSN:5	727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275315	Flap Actuator (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
	60P2753003Z005	0150	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275316	Flap Actuator (Right Inboard) - Removal / Installation		HRS		3522.4			0			0
	60P2753003Z005	0157	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275317	Flap Actuator (Left Outboard) - Removal / Installation		HRS		3522.4			0			0
	60P2753001Z004	0090	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275318	Flap Actuator (Right Outboard) - Removal / Installation		HRS		3522.4			0			0
	60P2753002Z006	0098	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275319	Flap Torque Shaft (Left No. 1) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	60P2756003Z001	0219	AFL	TSN:630	97			630			0
			MOS	TSN:103	25.2			21 Nov 2022			N/A
	Airframe		MSC				O/C				
275320	Flap Torque Shaft (Left No. 2) - Removal / Installation		HRS		3522.4			0			0
	60P2756003Z003	0174	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275321	Flap Torque Shaft (Left No. 3) - Removal / Installation		HRS		485.9			3036.5			0
	60P2756003Z004	1196	AFL		97			630			0
	N/A	N/A	MOS	TSN:1	25.6			08 Nov 2022			N/A
	Airframe		MSC				O/C				
Notes: T/W: 568807, CAL DUE: 05/20											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275322	Flap Torque Shaft (Left No. 4) - Removal / Installation		HRS		3522.4			0			0
	60P2756003Z005	0051	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275323	Flap Torque Shaft (Left No. 5) - Removal / Installation		HRS		3522.4			0			0
	60P2756003Z006	0131	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275324	Flap Torque Shaft (Left No. 6) - Removal / Installation		HRS		3522.4			0			0
	60P2756003Z008	0234	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275325	Flap Torque Shaft (Left No. 7) - Removal / Installation		HRS		3509.1			13.3			0
	60P2756003Z009	0227	AFL		722			5			0
			MOS		124.5			12 Aug 2014			
	Airframe		MSC				O/C				
275326	Flap Torque Shaft (Left No. 8) - Removal / Installation		HRS		2755.9			766.5			0
	60P2756003Z010	0270	AFL		561			166			0
			MOS		99.1			23 Sep 2016			
	Airframe		MSC				O/C				
Notes: T/W S/N: 553005 DUE CAL: 10/2016											
275327	Flap Torque Shaft (Right No. 1) - Removal / Installation		HRS		3522.4			0			0
	60P2756003Z001	0233	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275328	Flap Torque Shaft (Right No. 2) - Removal / Installation		HRS		3522.4			0			0
	60P2756003Z003	0196	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275329	Flap Torque Shaft (Right No. 3) - Removal / Installation		HRS	TSN:3036.1	485.9			3036.5			0
	60P2756003Z004	0185	AFL	TSN:629	97			630			0
			MOS	TSN:102	25.6			08 Nov 2022			N/A
	Airframe		MSC				O/C				
Notes: T/W: 568807, CAL DUE: 05/20											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275330	Flap Torque Shaft (Right No. 4) - Removal / Installation		HRS		3522.4			0			0
	60P2756003Z005		AFL		727			0			0
	0114		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275331	Flap Torque Shaft (Right No. 5) - Removal / Installation		HRS		3522.4			0			0
	60P2756003Z006		AFL		727			0			0
	0207		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275332	Flap Torque Shaft (Right No. 6) - Removal / Installation		HRS		3522.4			0			0
	60P2756003Z008		AFL		727			0			0
	0194		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275333	Flap Torque Shaft (Right No. 7) - Removal / Installation		HRS		3509.1			13.3			0
	60P2756003Z009		AFL		722			5			0
	0219		MOS		124.5			12 Aug 2014			
	Airframe		MSC				O/C				
275334	Flap Torque Shaft (Right No. 8) - Removal / Installation		HRS		3509.1			13.3			0
	60P2756003Z010		AFL		722			5			0
	0192		MOS		124.3			17 Aug 2014			
	Airframe		MSC				O/C				
275341	Flap Actuator No-Back Mechanism (Left Inboard) -		HRS		3522.4		8500	0	8500	8550	0
	Functional Check		AFL		727			0			0
			MOS		122.1		250	23 Oct 2014	31 Aug 2035	30 Sep 2035	
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
Airframe											
275342	Flap Actuator No-Back Mechanism (Right Inboard) -		HRS		3522.4		8500	0	8500	8550	0
	Functional Check		AFL		727			0			0
			MOS		122.1		250	23 Oct 2014	31 Aug 2035	30 Sep 2035	
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
Airframe											
275343	Flap Actuator No-Back Mechanism (Left Outboard) -		HRS		3522.4		8500	0	8500	8550	0
	Functional Check		AFL		727			0			0
			MOS		122.1		250	23 Oct 2014	31 Aug 2035	30 Sep 2035	
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275401	Flap Position Resolver (Right) - Removal / Installation		HRS		3522.4			0			0
	60P2754001Z001	0241	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275500	Flap Control Module - Removal / Installation		HRS		3522.4			0			0
	60P2751100Z006	175730	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275502	Flap Hydraulic Control Module - Removal / Installation		HRS		3522.4			0			0
	60P2756002Z007	0121	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275507	Flap Hydraulic Control Module - Discard		HRS		3522.4			0			0
	60P2756002Z007	0121	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 275502											
275617	Flap Drive Pillow Block (Left No. 1) - Removal / Installation		HRS		3522.4			0			0
	60P2756011Z001	1297	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275618	Flap Drive Pillow Block (Left No. 2) - Removal / Installation		HRS		3522.4			0			0
	60P2756011Z001	1094	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
275619	Flap Drive Pillow Block (Left No. 3) - Removal / Installation		HRS		3522.4			0			0
	60P2756011Z001	0997	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275620	Flap Drive Pillow Block (Left No. 4) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2756011Z001	1239	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
275621	Flap Drive Pillow Block (Left No. 5) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2756011Z001	0709	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
275622	Flap Drive Pillow Block (Left No. 6) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2756011Z001	0717	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
275623	Flap Drive Pillow Block (Right No. 1) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2756011Z001	1096	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
275624	Flap Drive Pillow Block (Right No. 2) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2756011Z001	1237	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
275625	Flap Drive Pillow Block (Right No. 3) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2756011Z001	1092	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
275626	Flap Drive Pillow Block (Right No. 4) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2756011Z001	0459	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275627	Flap Drive Pillow Block (Right No. 5) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2756011Z001	0703	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
275628	Flap Drive Pillow Block (Right No. 6) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2756011Z001	1101	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276001	Ground Spoiler System - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276002	Spoiler System - Mechanical Rig		HRS		1946.7			1575.7			0
			AFL		408			319			0
			MOS		76.9			29 Jul 2018			
			MSC				O/C				
Airframe											
276003	Spoiler Attachment Fittings (Corrosion) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.5	-10	48	10 Nov 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
276004	Spoiler Actuating System Ibit Suite A Test - Operational Check		HRS		873.6		7500	2648.8	10148.8	10198.8	0
			AFL		166			561			0
			MOS		38.9			29 Sep 2021			
			[HRS: +50/-50]								
Airframe											
276005	Spoiler Actuator Integrity (Suite B) - Initiated Built-In Test - Functional Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276008	Spoiler Free Play Backlash (Left Inboard) - Functional Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1		23 Oct 2014				
			MSC			O/C					
Airframe											
276009	Spoiler Free Play Backlash (Left Midboard) - Functional Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1		23 Oct 2014				
			MSC			O/C					
Airframe											
276010	Spoiler Free Play Backlash (Left Outboard) - Functional Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1		23 Oct 2014				
			MSC			O/C					
Airframe											
276011	Spoiler Free Play Backlash (Right Inboard) - Functional Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1		23 Oct 2014				
			MSC			O/C					
Airframe											
276012	Spoiler Free Play Backlash (Right Midboard) - Functional Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1		23 Oct 2014				
			MSC			O/C					
Airframe											
276013	Spoiler Free Play Backlash (Right Outboard) - Functional Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1		23 Oct 2014				
			MSC			O/C					
Airframe											
276014	Spoiler Electrical Rig (Left Inboard) - Functional Check		HRS		1912.8			1609.6			0
			AFL		397			330		0	
			MOS		75.1		23 Sep 2018				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276015	Spoiler Electrical Rig (Left Midboard) - Functional Check		HRS		1912.8			1609.6		0	
			AFL		397		330		0		
			MOS		75.1		23 Sep 2018				
			MSC			O/C					
Airframe											
276016	Spoiler Electrical Rig (Left Outboard) - Functional Check		HRS		1912.8			1609.6		0	
			AFL		397		330		0		
			MOS		75.1		23 Sep 2018				
			MSC			O/C					
Airframe											
276017	Spoiler Electrical Rig (Right Inboard) - Functional Check		HRS		1912.8			1609.6		0	
			AFL		397		330		0		
			MOS		75.1		23 Sep 2018				
			MSC			O/C					
Airframe											
276018	Spoiler Electrical Rig (Right Midboard) - Functional Check		HRS		1912.8			1609.6		0	
			AFL		397		330		0		
			MOS		75.1		23 Sep 2018				
			MSC			O/C					
Airframe											
276019	Spoiler Electrical Rig (Right Outboard) - Functional Check		HRS		1912.8			1609.6		0	
			AFL		397		330		0		
			MOS		75.1		23 Sep 2018				
			MSC			O/C					
Airframe											
276020	Spoiler (Left Inboard) - Functional Test		HRS		1912.8			1609.6		0	
			AFL		397		330		0		
			MOS		75.1		24 Sep 2018				
			MSC			O/C					
Airframe											
276021	Spoiler (Right Inboard) - Functional Test		HRS		1912.8			1609.6		0	
			AFL		397		330		0		
			MOS		75.1		24 Sep 2018				
			MSC			O/C					
Airframe											
276022	Spoiler (Left Midboard) - Functional Test		HRS		1912.8			1609.6		0	
			AFL		397		330		0		
			MOS		75.1		24 Sep 2018				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276023	Spoiler (Right Midboard) - Functional Test		HRS		1912.8			1609.6			0
			AFL		397			330		0	
			MOS		75.1			24 Sep 2018			
			MSC			O/C					
276024	Spoiler (Left Outboard) - Functional Test		HRS		1912.8			1609.6			0
			AFL		397			330		0	
			MOS		75.1			24 Sep 2018			
			MSC			O/C					
276025	Spoiler (Right Outboard) - Functional Test		HRS		1912.8			1609.6			0
			AFL		397			330		0	
			MOS		75.1			24 Sep 2018			
			MSC			O/C					
276100	Speed Brake Control Module - Removal / Installation 60P2761100Z006182308		HRS		3452.7			69.7			0
			AFL		711			16		0	
			MOS		120.1			23 Dec 2014			
			MSC			O/C					
276148	Inboard Spoiler (Left Ground) - Removal / Installation 60P5771001A0110109		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
276149	Inboard Spoiler (Right Ground) - Removal / Installation 60P5771002A0090107		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
276150	Midboard Spoiler (Left Inboard Flight) - Removal / Installation 60P5772001A0060112		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
276151	Midboard Spoiler (Right Inboard Flight) - Removal / Installation 60P5772002A0100109		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276152	Outboard Spoiler (Left Outboard Flight) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5773001A013	0108	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276153	Outboard Spoiler (Right Outboard Flight) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5773002A005	0106	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276225	Inboard (Ground) Spoiler Link (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5771259A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276226	Inboard (Ground) Spoiler Link (Right Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5771259A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276227	Inboard (Ground) Spoiler Link (Left Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5772289A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276228	Inboard (Ground) Spoiler Link (Right Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5771259A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276300	Outboard (Outboard Flight) Spoiler Link (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5773259A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276301	Outboard (Outboard Flight) Spoiler Link (Right Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5773259A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276302	Outboard (Outboard Flight) Spoiler Link (Left Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5773289A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276303	Outboard (Outboard Flight) Spoiler Link (Right Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5773289A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276305	Midboard (Inboard Flight) Spoiler Link (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P577289A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276306	Midboard (Inboard Flight) Spoiler Link (Right Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5771259A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276307	Midboard (Inboard Flight) Spoiler Link (Left Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5772289A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276308	Midboard (Inboard Flight) Spoiler Link (Right Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5771259A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276326	Spoiler Ha Manifold (Left Outboard) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2763101Z004	0204	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276327	Spoiler Ha Manifold (Right Outboard) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2763101Z004	0208	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276328	Spoiler Ehsa Manifold (Left Inboard) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2763201Z004	0435	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276329	Spoiler Ehsa Manifold (Left Midboard) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2763201Z004	0432	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276330	Spoiler Ehsa Manifold (Right Inboard) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2763201Z004	0438	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276331	Spoiler Ehsa Manifold (Right Midboard) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2763201Z004	0436	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276333	Spoiler Eb Manifold (Left Outboard) - Removal /		HRS		1912.8			1609.6			0
	Installation		AFL		397			330			0
	60P2763301Z006	0043D	MOS		75.2			19 Sep 2018			Parker
			MSC				O/C				
Airframe											

Notes: DLRO: 561065CAL DUE:01/19TW:555720CAL DUE:10/18

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276334	Spoiler Eb Manifold (Right Outboard) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2763301Z006	0731D	MOS		75.2			19 Sep 2018			Parker
			MSC				O/C				
Airframe											
Notes: TW: 560432 DUE: 11/18 DLRO: 570985 DLRO: 11/18											
276335	Spoiler Motor Control Electronics (Left Outboard Eb Manifold) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2715003Z310/21	0514	MOS		75.1			23 Sep 2018			Parker
			MSC				O/C				
Airframe											
276336	Spoiler Motor Control Electronics (Right Outboard Eb Manifold) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2715003Z310/21	0519	MOS		75.1			23 Sep 2018			Parker
			MSC				O/C				
Airframe											
276337	Inboard Spoiler (Ground) Ehsa Actuator (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2763001Z001	0447	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276338	Inboard Spoiler (Ground) Ehsa Actuator (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2763001Z001	0455	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276339	Midboard Spoiler (Inboard Flight) Ehsa Actuator (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2763001Z001	0251	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276340	Midboard Spoiler (Inboard Flight) Ehsa Actuator (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2763001Z001	0446	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276341	Outboard Spoiler (Outboard Flight) Ebha Actuator (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2763002Z100	0238	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276342	Outboard Spoiler (Outboard Flight) Ebha Actuator (Right) - Removal / Installation		HRS		1946.7			1575.7			0
			AFL		408			319			0
	60P2763002Z201	0383	MOS		76.9			29 Jul 2018			
			MSC				O/C				
Airframe											
276365	Spoiler Ehsa Manifold (Left Inboard) - Discard		HRS		3522.4			0			0
			AFL		727			0			0
	60P2763201Z004	0435	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276366	Spoiler Ehsa Manifold (Left Midboard) - Discard		HRS		3522.4			0			0
			AFL		727			0			0
	60P2763201Z004	0432	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276367	Spoiler Ehsa Manifold (Right Inboard) - Discard		HRS		3522.4			0			0
			AFL		727			0			0
	60P2763201Z004	0438	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276368	Spoiler Ehsa Manifold (Right Midboard) - Discard		HRS		3522.4			0			0
			AFL		727			0			0
	60P2763201Z004	0436	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
276370	Spoiler Eb Manifold (Right Outboard) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	60P2763301Z006	0731D	MOS		75.2			19 Sep 2018			
			MSC				O/C				
Airframe											
Notes: TW: 560432 DUE: 11/18 DLRO: 570985 DLRO: 11/18											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276508	Spoiler Remote Electronics Unit (Left Inboard Ehsa		HRS		1912.8			1609.6			0
	Manifold) - Removal / Installation		AFL		397			330			0
	60P2715001Z006/35	1579	MOS		75.1			23 Sep 2018			Parker
		35	MSC				O/C				
Airframe											
276509	Spoiler Remote Electronics Unit (Left Midboard Ehsa		HRS		1912.8			1609.6			0
	Manifold) - Removal / Installation		AFL		397			330			0
	60P2715001Z006/35	0907	MOS		75.1			23 Sep 2018			Parker
		35	MSC				O/C				
Airframe											
276510	Spoiler Remote Electronics Unit (Left Outboard Ha		HRS		1912.8			1609.6			0
	Manifold) - Removal / Installation		AFL		397			330			0
	60P2715001Z006/35	3185	MOS		75.1			23 Sep 2018			Parker
		35	MSC				O/C				
Airframe											
276511	Spoiler Remote Electronics Unit (Right Inboard Ehsa		HRS		1912.8			1609.6			0
	Manifold) - Removal / Installation		AFL		397			330			0
	60P2715001Z006/35	3035	MOS		75.1			23 Sep 2018			Parker
		35	MSC				O/C				
Airframe											
276512	Spoiler Remote Electronics Unit (Right Midboard Ehsa		HRS		1912.8			1609.6			0
	Manifold) - Removal / Installation		AFL		397			330			0
	60P2715001Z006/35	1659	MOS		75.1			23 Sep 2018			Parker
		35	MSC				O/C				
Airframe											
276513	Spoiler Remote Electronics Unit (Right Outboard Ha		HRS		1912.8			1609.6			0
	Manifold) - Removal / Installation		AFL		397			330			0
	60P2715001Z007/35	0943	MOS		75.1			23 Sep 2018			Parker
		35	MSC				O/C				
Airframe											
28 - Fuel											
280001	APU Fuel System - Bleed		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
280002	Fuel Tank Vapor Hazards - Reduction		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		25.3			18 Nov 2022			
			MSC			O/C					
280004	Fuel System - Upstream (Tank) Side Bleed		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
280005	Fuel System - Engine Bleed		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
280006	Complete Fuel System Bleed Procedure - Adjustment Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
280007	Microbiological Contamination Test of Fuel Tank - Special Detail Inspection		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.7	13	4	05 Oct 2024	18 Feb 2025*	18 Mar 2025	
			[MOS: +1m/-1m]								
Airframe											
280008	Fuel Tank - Sumping		HRS		-17.5			3539.9			0
			AFL		-10			737		0	
			DATE		23 d		10d	03 Dec 2024	13 Dec 2024		
Airframe											
281000	Wing Center Line Rib Leak Test - Functional Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
281001	Fuel Tank (Left Wing) - Leak Check		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.5			12 Oct 2024			
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281002	Fuel Tank (Right Wing) - Leak Check		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.5			12 Oct 2024			
			MSC				O/C				
281003	Fuel Tank (Left Hopper) - Leak Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014		0	
			MSC				O/C				
281004	Fuel Tank (Right Hopper) - Leak Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
281005	Fuel Tank Contamination (Left) - Cleaning		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014		0	
			MSC				O/C				
281006	Fuel Tank Contamination (Right) - Cleaning		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
281200	Fuel Hopper Check Valve (Left) - Leakage Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
281201	Fuel Hopper Check Valve (Right) - Leakage Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
281300	Overwing Gravity Fueling Adapter Assembly (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS	37299001	0278			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281301	Overwing Gravity Fueling Adapter Assembly (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	37289001	0206	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281304	Gravity Fueling Adapter Assembly (Left) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281305	Gravity Fueling Adapter Assembly (Right) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281306	Gravity Fueling Adapter Assembly (Left) - Repair		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281307	Gravity Fueling Adapter Assembly (Right) - Repair		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281308	Left Gravity Fuel Filler CAP - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	37299001	0278	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281309	Right Gravity Fuel Filler CAP - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	37299001	0278	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281400	Fuel / Water Drain Valve (Left No. 1) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	L83A13-633	H17257	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281401	Fuel / Water Drain Valve (Left No. 2) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	L83A13-633	J00609	MOS		122.9			29 Sep 2014			
			MSC				O/C				
Airframe											
281402	Fuel / Water Drain Valve (Left No. 3) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	L83A13-633	H27059	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281403	Fuel / Water Drain Valve (Right No. 1) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	L83A13-633	H17260	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281404	Fuel / Water Drain Valve (Right No. 2) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	L83A13-633	H21649	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281405	Fuel / Water Drain Valve (Right No. 3) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	L83A13-633	H21644	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281413	Defuel Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	775C-80NW	4936	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281420	Fuel / Water Drain Valve - Operational Test		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7			05 Oct 2024			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281421	Fuel / Water Drain Valve - Repair		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281425	Vent Plenum - Draining		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281511	Inboard Vent Float Valve (Left) - Removal / Installation L87-31-603										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281524	Pressure Relief Valve (Left) - Removal / Installation		HRS		3522.4			0			0
	L97-63-613		AFL		727			0			0
	H11399		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
281525	Pressure Relief Valve (Right) - Removal / Installation		HRS		3522.4			0			0
	L97-63-613		AFL		727			0			0
	H11402		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
281528	Wing Vent Float Valve (Left) - Operational Check		HRS		485.9		4800	3036.5	7836.5	7886.5	0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
281529	Wing Vent Float Valve (Right) - Operational Check		HRS		485.9		4800	3036.5	7836.5	7886.5	0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
281530	Fuel Vent System (Left) - Operational Check		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.5			12 Oct 2024			
	Airframe		[HRS: +50/-50]								
281531	Fuel Vent System (Right) - Operational Check		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.5			12 Oct 2024			
	Airframe		[HRS: +50/-50]								
281532	Flame Arrestor (Left) - Detailed Inspection		HRS		485.9		4800	3036.5	7836.5	7886.5	0
			AFL		97			630			0
			MOS		25.7	-11	96	03 Nov 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
281533	Flame Arrestor (Right) - Detailed Inspection		HRS		485.9		4800	3036.5	7836.5	7886.5	0
			AFL		97			630			0
			MOS		25.7	-11	96	03 Nov 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281534	Flame Arrestor (Left) - Removal / Installation		HRS		485.9			3036.5			0
	130-0510-03R	0129	AFL		97			630			0
			MOS		26			26 Oct 2022			N/A
	Airframe		MSC				O/C				
281535	Flame Arrestor (Right) - Removal / Installation		HRS		485.9			3036.5			0
	130-0510-03R	0195	AFL		97			630			0
			MOS		25.7			03 Nov 2022			PARKER
	Airframe		MSC				O/C				
281537	Flame Arrestor (Left) - Operational Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.7	-11	96	03 Nov 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281538	Flame Arrestor (Right) - Operational Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.7	-11	96	03 Nov 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281541	Wing Tank Pressure Relief Valve (Left) - Operational Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281542	Wing Tank Pressure Relief Valve (Right) - Operational Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281602	Heated Fuel Return System Valve - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5	19	24	12 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
281603	Heated Fuel Return Shut-Off Valve (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	B97-13-608	F72768	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
281604	Heated Fuel Return Shut-Off Valve Motor (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	D97C00-652	G06577	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281605	Heated Fuel Return Shut-Off Valve (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	B97-13-608	H05141	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281606	Heated Fuel Return Shut-Off Valve Motor (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	D97C00-652	G06547	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
281615	Pylon Heated Fuel Return System (Hfhrs) Shut-Off Valve FIRE Shield (Left) - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
281616	Pylon Heated Fuel Return System (Hfhrs) Shut-Off Valve FIRE Shield (Right) - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282100	Pressure Fueling / Defueling Adapter - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	K97-63-615	F27013	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282101	Defueling Suction Check Valve (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	L85H31-601	F86475	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282102	Defueling Suction Check Valve (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	L85H31-601	F82355	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282103	Double Flap Check Valve Refuel (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	K97-63-615	F27013	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 282100											
282106	Pressure Fueling - Operational Check		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		49.7			04 Nov 2020			
			MSC				O/C				
Airframe											
282107	Suction Defueling - Operational Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282108	Pressure Fueling / Defueling Adapter - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282200	Pressure Fueling Shut-Off Valve (Left) - Removal / Installation		HRS	TSN:1107.9	1158			2364.4			0
			AFL	TSN:208	239			488			0
	L94-51-603	K07557	MOS	TSN:7	49.7			04 Nov 2020			N/A
			MSC				O/C				
Airframe											
282201	Pressure Fueling Shut-Off Valve (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	L94-51-602	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282400	Intertank Shut-Off Valve - Removal / Installation		HRS		3522.4			0			0
	B97H51-610	F68216	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282401	Intertank Shut-Off Valve Motor - Removal / Installation		HRS		3522.4			0			0
	D97C00-647	G19517	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282402	Cross-Flow Shut-Off Valve - Removal / Installation		HRS		3522.4			0			0
	B97-31-616	G20224	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282403	Cross-Flow Shut-Off Valve Motor - Removal / Installation		HRS		3522.4			0			0
	D97C00-647	G11376	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282408	Fuel Cross-Flow / Intertank System - Operational Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282409	Cross-Flow Shut-Off Valve - Functional Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282410	Intertank Shut-Off Valve / Low Fuel Sensor - Functional Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282516	Fuel Boost Pump Inlet Filter Screen (Left Main) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
Logbook Position	Part Number	Serial Number									Approx Price
	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282517	Fuel Boost Pump Inlet Filter Screen (Left Alternate) - Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
282518	Fuel Boost Pump Inlet Filter Screen (Right Main) - Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
282519	Fuel Boost Pump Inlet Filter Screen (Right Alternate) - Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
282520	Fuel Boost Pump Inlet Filter Screen (Left Main) - Cleaning		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
282521	Fuel Boost Pump Inlet Filter Screen (Left Alternate) - Cleaning		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
282522	Fuel Boost Pump Inlet Filter Screen (Right Main) - Cleaning		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
282523	Fuel Boost Pump Inlet Filter Screen (Right Alternate) - Cleaning		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282600	Engine Fuel Shut-Off Valve Motor (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	D97C00-647	G16424	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282601	Engine Fuel Shut-Off Valve Motor (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	D97C00-647	G10234	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282602	Engine Fuel Shut-Off Valve (Left) - Removal / Installation		HRS		3522.4			0			0
	B97-31-613 F69546		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282603	Engine Fuel Shut-Off Valve (Right) - Removal / Installation		HRS		3522.4			0			0
	B97-31-613 F46891		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282604	Fuel Ejector Pump (Left) - Removal / Installation		HRS		3522.4			0			0
	T99A38-607 H02626		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282605	Fuel Ejector Pump (Right) - Removal / Installation		HRS		3522.4			0			0
	T99A38-607 F52024		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282606	Fuel Boost Pump (Left Main) - Removal / Installation		HRS		3522.4			0			0
	P99C31-616 H28784		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282607	Fuel Boost Pump (Right Main) - Removal / Installation		HRS		2039.9			1482.5			0
	P99C31-616 H30585		AFL		423			304			0
			MOS		79.3			17 May 2018			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282608	Fuel Boost Pump (Left Alternate) - Removal / Installation		HRS		3522.4			0			0
	P99C31-616	H30591	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282609	Fuel Boost Pump (Right Alternate) - Removal / Installation		HRS		3522.4			0			0
	P99C31-616	H15084	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282610	Fuel Boost Pump Canister (Left Main) - Removal / Installation		HRS		3522.4			0			0
	C93R31-612	H39479	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282611	Fuel Boost Pump Canister (Right Main) - Removal / Installation		HRS		3522.4			0			0
	C93R31-613	H41610	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282612	Fuel Boost Pump Canister (Left Alternate) - Removal / Installation		HRS		3522.4			0			0
	C93R31-613	H36594	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282613	Fuel Boost Pump Canister (Right Alternate) - Removal / Installation		HRS		3522.4			0			0
	C93R31-613	H36592	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282614	APU Fuel Shut-Off Valve - Removal / Installation		HRS		3522.4			0			0
	B97-13-606	G20968	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282615	APU Fuel Shut-Off Valve Motor - Removal / Installation		HRS		1158			2364.4			0
	D97C00-674		AFL		239			488			0
			MOS	TSN:1	49.7			04 Nov 2020			N/A
	Airframe		MSC				O/C				
282632	APU Fuel Shut-Off Valve - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	28	24	07 Oct 2024	30 Nov 2026*	31 Dec 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: STAMP X-FER REF CORRIDOR 18.34											
282633	Engine Fuel Shut-Off Valve (Left) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	35	24	26 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
282634	Engine Fuel Shut-Off Valve (Right) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	35	24	26 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
282635	Fuel Boost Pump Control System - Operational Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282636	Fuel Boost Pump (Left Main) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282637	Fuel Boost Pump (Left Alternate) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
282638	Fuel Boost Pump (Right Main) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282639	Fuel Boost Pump (Right Alternate) - Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282640	Fuel Distribution System (Fuel Flow, Left) - Functional Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282641	Fuel Distribution System (Fuel Flow, Right) - Functional Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282642	Dual Wall Fuel Line Shroud (Left Engine) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		25.3	-24	96	16 Nov 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282643	Dual Wall Fuel Line Shroud (Right Engine) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		25.3	-24	96	16 Nov 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282644	Dual Wall Fuel Line Shroud (APU) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		25.3	-24	96	16 Nov 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
282645	Dual Wall Fuel Line Shroud (Left Engine Heated Return) - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		25.3	-24	96	16 Nov 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282646	Dual Wall Fuel Line Shroud (Right Engine Heated Return)		HRS		485.9			3036.5			0
	- Functional Check		AFL		97			630			0
			MOS		25.3	-24	96	16 Nov 2022	31 Oct 2030*	30 Nov 2030	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
282647	Dual Wall Fuel Line (Left Engine) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282648	Dual Wall Fuel Line (Right Engine) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282649	Dual Wall Fuel Line (APU) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282650	Dual Wall Fuel Line (Left Engine Heated Return) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
282651	Dual Wall Fuel Line (Right Engine Heated Return) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284100	Ground Service Control Panel - Removal / Installation		HRS		3522.4			0			0
	742400-1-1	742400IN00212	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284102	Fuel Ground Service Control Panel - Operational Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284103	Refueling Door Fuel High-Level Warning Light - Operational Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
284106	Refueling Door Fuel High-Level Warning Light Assembly - Removal / Installation 20-3501-0001110712-3-2		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
284107	Fuel System Interface to Aircraft Systems - Operational Check		HRS		1777.1			1745.3			0
			AFL		366			361		0	
			MOS		71.6		06 Jan 2019				
			MSC			O/C					
Airframe											
284108	Fuel Quantity Measuring / Indication System - Functional Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
Notes: PN: 738740-1-1 SN: <NONE>.											
284109	Fuel Quantity Signal Conditioner High-Level Shutoff - Operational Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
Notes: PN: 738740-1-1 SN: <NONE>.											
284110	Fuel Quantity Signal Conditioner - Removal / Installation 738741-1-4738741IN00152		HRS		1777.1			1745.3			0
			AFL		366			361		0	
			MOS		71.6		06 Jan 2019				
			MSC			O/C					
Airframe											
284112	Fuel Quantity System - Capacitance Check		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26		25 Oct 2022				
			MSC			O/C					
Airframe											
Notes: PN: 738740-1-1 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284113	Fuel Quantity Signal Conditioner - Power / Ground Diode Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
Notes: PN: 738740-1-1 SN: <NONE>.											
284120	Fuel High-Level Sensor (Left Wing) - Removal / Installation 722863-1-0 722863IN00388		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
284121	Fuel High-Level Sensor (Right Wing) - Removal / Installation 722863-1-0 722863IN00387		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
284124	Fuel Tank Temperature Sensor (Left Wing) - Removal / Installation 722872-1-0 722872IN00424		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
284125	Fuel Tank Temperature Sensor (Right Wing) - Removal / Installation 722872-1-0 722872IN02002		HRS		1158			2364.4			0
			AFL		239			488		0	
			MOS	TSN:13	50		27 Oct 2020		N/A		
			MSC			O/C					
Airframe											
284130	Remote Data Concentrator (Left Inboard, Channel A) - Removal / Installation 738740-2-2 738818IN00417		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630		0	
			MOS	TSN:102	26		25 Oct 2022		N/A		
			MSC			O/C					
Airframe											
284131	Remote Data Concentrator (Right Inboard, Channel A) - Removal / Installation 738740-2-2 738818IN00598		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630		0	
			MOS	TSN:102	26		25 Oct 2022		N/A		
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284137	Remote Data Concentrator (Left Outboard, Channel B) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	738740-2-2	738818IN01030	MOS	TSN:102	26			25 Oct 2022			N/A
			MSC				O/C				
Airframe											
284138	Remote Data Concentrator (Right Outboard, Channel B) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	738740-2-2	738818IN00944	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284150	Fuel Quantity Probe No. 3 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746046-1-0	746046IN00386	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284151	Fuel Quantity Probe No. 2 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746045-1-0	746045IN00393	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284152	Fuel Quantity Probe No. 5 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746050-1-0	746050IN00402	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284153	Fuel Quantity Probe No. 4 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746049-1-0	746049IN00402	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284154	Fuel Quantity Probe No. 6 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746051-1-0	746051IN00297	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284155	Fuel Quantity Probe No. 7 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746052-1-0	746052IN00396	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284156	Fuel Quantity Probe No. 8 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746054-1-0	746054IN00340	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284157	Fuel Quantity Probe No. 9 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746053-1-0	746053IN00361	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284158	Fuel Quantity Probe No. 10 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746055-1-0	746055IN00347	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284159	Fuel Quantity Probe No. 11 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746056-1-0	746056IN00276	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284160	Fuel Quantity Probe No. 13 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746058-1-0	746058IN00398	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284161	Fuel Quantity Probe No. 12 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746057-1-0	746057IN00395	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284162	Fuel Quantity Probe No. 14 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746059-1-0	746059IN00385	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284163	Fuel Quantity Probe No. 15 (Left Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746047-1-0	746047IN00375	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284164	Double Gaging Fuel Quantity Probe No. 1 (Left Hopper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746048-1-0	746048IN00388	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284165	Fuel Characteristic Sensor (Left Wing) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	799493-1-0	799493IN01373	MOS	TSN:2	26			25 Oct 2022			N/A
			MSC				O/C				
Airframe											
284166	Fuel Quantity Probe No. 3 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746046-1-0	746046IN00395	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284167	Fuel Quantity Probe No. 2 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746045-1-0	746045IN00390	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284168	Fuel Quantity Probe No. 5 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746050-1-0	746050IN00403	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284169	Fuel Quantity Probe No. 4 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746049-1-0	746049IN00400	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284170	Fuel Quantity Probe No. 6 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746051-1-0	746051IN00324	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284171	Fuel Quantity Probe No. 7 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746052-1-0	746052IN00244	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284172	Fuel Quantity Probe No. 8 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746053-1-0	746053IN00372	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284173	Fuel Quantity Probe No. 9 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746054-1-0	746054IN00343	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284174	Fuel Quantity Probe No. 10 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746055-1-0	746055IN00399	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284175	Fuel Quantity Probe No. 11 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746056-1-0	746056IN00280	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284176	Fuel Quantity Probe No. 13 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746058-1-0	746058IN00399	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284177	Fuel Quantity Probe No. 12 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746057-1-0	746057IN00397	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284178	Fuel Quantity Probe No. 14 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746059-1-0	746059IN00386	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284179	Fuel Quantity Probe No. 15 (Right Wing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746047-1-0	746047IN00365	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284180	Double Gaging Fuel Quantity Probe No. 1 (Right Hopper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	746048-1-0	746048IN00391	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
284181	Fuel Characteristic Sensor (Right Wing) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	799493-1-0	799493IN01374	MOS	TSN:2	26			25 Oct 2022			N/A
			MSC				O/C				
Airframe											
289700	Fqms Harness, Rdc A (Left) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	746060-4-0	746060IN00742	MOS	TSN:2	26			25 Oct 2022			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
289701	Fqms Harness, Rdc B (Left) - Removal / Installation		HRS		485.9			3036.5			0
	746061-4-0	746061IN00751	AFL		97			630			0
			MOS	TSN:2	26			25 Oct 2022			N/A
	Airframe		MSC				O/C				
289702	Fqms Harness, Rdc A (Right) - Removal / Installation		HRS		485.9			3036.5			0
	746073-3-0	746073IN00739	AFL		97			630			0
			MOS	TSN:2	26			25 Oct 2022			N/A
	Airframe		MSC				O/C				
289703	Fqms Harness, Rdc B (Right) - Removal / Installation		HRS		485.9			3036.5			0
	746074-3-0	746074IN00753	AFL		97			630			0
			MOS	TSN:3	26			25 Oct 2022			N/A
	Airframe		MSC				O/C				
29 - Hydraulic Power											
290001	Engine-Driven Hydraulic Pump, Power Transfer Unit and		HRS		3522.4			0			0
	Auxiliary Pump Case Drain Filter (Left) - Check		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
290002	Engine-Driven Hydraulic Pump, Power Transfer Unit and		HRS		3522.4			0			0
	Auxiliary Pump Case Drain Filter (Right) - Check		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
290003	Hydraulic Fluid (Left) - Sampling / Analysis		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
290004	Hydraulic Fluid (Right) - Sampling / Analysis		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
290005	Hydraulic Fluid (Power Transfer Unit) - Sampling / Analysis		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
290500	Hydraulic Fluid Heat Exchanger (Left) - Removal / Installation 60P2910077Z0010148		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
290501	Hydraulic Fluid Heat Exchanger (Right) - Removal / Installation 60P2910077Z0010088		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
291000	Left Hydraulic System - Functional Test		HRS		873.6			2648.8			0
			AFL		166		561		0		
			MOS		38.9		29 Sep 2021				
			MSC			O/C					
Airframe											
291001	Right Hydraulic System - Functional Test		HRS		873.6			2648.8			0
			AFL		166		561		0		
			MOS		38.9		29 Sep 2021				
			MSC			O/C					
Airframe											
291002	Hydraulic Systems - Functional Test		HRS		873.6			2648.8			0
			AFL		166		561		0		
			MOS		38.5		12 Oct 2021				
			MSC			O/C					
Airframe											
291200	Engine-Driven Hydraulic Pump (Left) - Removal / Installation 60P2910001Z002K0195		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291201	Engine-Driven Hydraulic Pump (Right) - Removal / Installation		HRS		2191.3			1331.1			0
			AFL		451			276			0
	60P2910001Z002	K0183	MOS		83.8			01 Jan 2018			
			MSC				O/C				
Airframe											
291202	Engine-Driven Hydraulic Pump Attenuator (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2910072Z001	0223	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291203	Engine-Driven Hydraulic Pump Attenuator (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2910072Z001	0191	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291208	Engine-Driven Hydraulic Pump (Left) - Case Drain Line Flushing		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291209	Engine-Driven Hydraulic Pump (Right) - Case Drain Line Flushing		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291300	Hydraulic System Relief / Unloading Valve (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2910025Z002	0237	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291301	Hydraulic System Relief / Unloading Valve (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2910025Z002	0209	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291400	Left System Manifold - Removal / Installation		HRS		3522.4			0			0
	60P2911073Z002	G0296	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
291401	Right System Manifold - Removal / Installation		HRS		3522.4			0			0
	60P2912074Z001	C2736	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
291416	Left System Manifold Filter / Filter Bowl (Return) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	339913	NSN	MOS		25.7			03 Nov 2022			N/A
	Airframe		MSC				O/C				
291417	Left System Manifold Filter / Filter Bowl (Engine-Driven Pump Pressure) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	339913	NSN	MOS		25.7			03 Nov 2022			N/A
	Airframe		MSC				O/C				
291418	Left System Manifold Filter / Filter Bowl (Engine-Driven Pump Case Drain) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	339482	NSN	MOS		25.7			03 Nov 2022			N/A
	Airframe		MSC				O/C				
291419	Left System Manifold Filter / Filter Bowl (Power Transfer Unit Case Drain) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	339482	NSN	MOS		25.7			03 Nov 2022			N/A
	Airframe		MSC				O/C				
291420	Left System Manifold Filter / Filter Bowl (Power Transfer Unit Pressure) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	339474	NSN	MOS		25.7			03 Nov 2022			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291421	Left System Manifold Filter / Filter Bowl (Auxiliary Pump Case Drain) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	339482	NSN	MOS		25.7			03 Nov 2022			N/A
			MSC				O/C				
Airframe											
291422	Left System Manifold Filter Indicator (Ptu CD) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	R021191-4	L13222	MOS	TSN:33	38.9			28 Sep 2021			DONALDSON
			MSC				O/C				
Airframe											
291423	Left System Manifold Filter Indicator (Ptu PR) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	R021192-6	L13577	MOS	TSN:33	38.9			28 Sep 2021			DONALDSON
			MSC				O/C				
Airframe											
291424	Left System Manifold Filter Indicator (Aux CD) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	R021191-5	L13427	MOS	TSN:33	38.9			28 Sep 2021			DONALDSON
			MSC				O/C				
Airframe											
291425	Left System Manifold Filter Indicator (Return) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	R021192-2	L13917	MOS	TSN:33	38.9			28 Sep 2021			DONALDSON
			MSC				O/C				
Airframe											
291426	Left System Manifold Filter Indicator (Edp Case Drain) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	R021191-3	L13126	MOS	TSN:33	38.9			28 Sep 2021			DONALDSON
			MSC				O/C				
Airframe											
291427	Left System Manifold Intelligent Filter Indicator (Pressure) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	R021192-1	L13338	MOS	TSN:33	38.9			28 Sep 2021			DONALDSON
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291429	Left System Manifold Power Transfer Unit Bypass		HRS		3522.4			0			0
	Restrictor - Removal / Installation		AFL		727			0			0
	VXLX0503100B	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291460	Manifold Hydraulic Lines, Attachments and Wiring - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291461	Left System Manifold - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291462	Right System Manifold - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291465	Left System Manifold Component - Leak Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291466	Right System Manifold Component - Leak Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291467	Hydraulic System Acoustical Filter (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	1159H47440-1	PMS1976	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291468	Hydraulic System Acoustical Filter (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	1159H47440-1	PMS1991	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291471	Left System Manifold Fluid Sampling Valve (Return) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	239855	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291472	Right System Manifold Fluid Sampling Valve (Return) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	239855	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291475	Left System Manifold Fluid Sampling Valve (Engine-Driven Pump Case Drain) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	239855	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291476	Right System Manifold Fluid Sampling Valve (Engine-Driven Pump Case Drain) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	239855	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291479	Left System Manifold Fluid Sampling Valve (Power Transfer Unit Case Drain) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	239855	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291481	Left System Manifold Fluid Sampling Valve (Auxiliary Pump) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	239855	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291483	Left System Manifold Shut-Off Diaphragm - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	PN	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291484	Right System Manifold Shut-Off Diaphragm - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	PN	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291487	Left System Manifold Filter (Return) - Discard		HRS		485.9		3600	3036.5	6636.5	6686.5	0
	339913	NSN	AFL		97			630			0
			MOS		25.4			14 Nov 2022			
			[HRS: +50/-50]								
Airframe											
291488	Left System Manifold Filter (Engine-Driven Pump Pressure) - Discard		HRS		485.9		3600	3036.5	6636.5	6686.5	0
	339913	NSN	AFL		97			630			0
			MOS		25.4			14 Nov 2022			
			[HRS: +50/-50]								
Airframe											
291489	Left System Manifold Filter (Engine-Driven Pump Case Drain) - Discard		HRS		485.9		3600	3036.5	6636.5	6686.5	0
	339482	NSN	AFL		97			630			0
			MOS		25.4			14 Nov 2022			
			[HRS: +50/-50]								
Airframe											
291490	Left System Manifold Filter (Power Transfer Unit Case Drain) - Discard		HRS		485.9		3600	3036.5	6636.5	6686.5	0
	339482	NSN	AFL		97			630			0
			MOS		25.4			14 Nov 2022			
			[HRS: +50/-50]								
Airframe											
291491	Left System Manifold Filter (Power Transfer Unit Pressure) - Discard		HRS		485.9		3600	3036.5	6636.5	6686.5	0
	339474	NSN	AFL		97			630			0
			MOS		25.4			14 Nov 2022			
			[HRS: +50/-50]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291492	Left System Manifold Filter (Auxiliary Pump Case Drain) - Discard		HRS		485.9		3600	3036.5	6636.5	6686.5	0
			AFL		97			630			0
	339482	NSN	MOS		25.4			14 Nov 2022			
			[HRS: +50/-50]								
Airframe											
291500	Left Hydraulic System Service Line Shut-Off Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2921023Z001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291501	Right Hydraulic System Service Line Shut-Off Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2921023Z001	0286	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291502	Right System Manifold Filter / Filter Bowl (Return) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	339913	NSN	MOS		25.7			03 Nov 2022			N/A
			MSC				O/C				
Airframe											
291503	Right System Manifold Filter / Filter Bowl (Engine-Driven Pump Pressure) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	339913	NSN	MOS		25.7			03 Nov 2022			N/A
			MSC				O/C				
Airframe											
291504	Right System Manifold Filter/ Filter Bowl (Engine-Driven Pump Case Drain) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	339482	NSN	MOS		25.7			03 Nov 2022			N/A
			MSC				O/C				
Airframe											
291505	Right System Manifold Filter Indicator (Return) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	R021192-2	L22208	MOS	TSN:32	38.6			06 Oct 2021			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291506	Right System Manifold Filter Indicator (Edp Case Drain) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	R021191-3	L13134	MOS	TSN:33	38.9			28 Sep 2021		DONALDSON	
			MSC				O/C				
Airframe											
291507	Right System Manifold Filter Indicator (Edp Pressure) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	R021192-1	L13358	MOS	TSN:33	38.9			28 Sep 2021		DONALDSON	
			MSC				O/C				
Airframe											
291510	Left Hydraulic System Shut-Off Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2910022Z005	12-06159	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291511	Right Hydraulic System Shut-Off Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2910022Z005	13-0814160	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291520	Left Hydraulic System Shut-Off Valve Motor - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	A2350-0129	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291521	Right Hydraulic System Shut-Off Valve Motor - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	A2350-0129	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291524	Hydraulic System Shut-Off Valves - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	35	24	26 Sep 2024 31 Oct 2026* 30 Nov 2026			
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291525	Right System Manifold Filter (Return) - Discard		HRS		485.9		3600	3036.5	6636.5	6686.5	0
	339913	NSN	AFL		97			630			0
			MOS		25.4			14 Nov 2022			
	Airframe		[HRS: +50/-50]								
291526	Right System Manifold Filter (Engine-Driven Pump Pressure) - Discard		HRS		485.9		3600	3036.5	6636.5	6686.5	0
	339913	NSN	AFL		97			630			0
			MOS		25.4			14 Nov 2022			
	Airframe		[HRS: +50/-50]								
291527	Right System Manifold Filter (Engine-Driven Pump Case Drain) - Discard		HRS		485.9		3600	3036.5	6636.5	6686.5	0
	339482	NSN	AFL		97			630			0
			MOS		25.4			14 Nov 2022			
	Airframe		[HRS: +50/-50]								
291600	Left System Reservoir - Removal / Installation		HRS		3522.4			0			0
	60P2911011A023	55-6088 GT	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
291601	Right System Reservoir - Removal / Installation		HRS		3522.4			0			0
	60P2912012A018P01	55-6089 GT	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
291602	Left Hydraulic System Reservoir Bleed Valve - Removal / Installation		HRS		3522.4			0			0
	60P2910031Z004	0216	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
291603	Right Hydraulic System Reservoir Bleed Valve - Removal / Installation		HRS		3522.4			0			0
	60P2910031Z004	0227	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291608	Left System Reservoir Inspection - Leak Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
291609	Right System Reservoir Inspection - Leak Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
291610	Left System Reservoir - Cleaning		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
291611	Right System Reservoir - Cleaning		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
291615	Ecology Bottle (Left System) - Removal / Installation 60P2900014Z001 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
291616	Ecology Bottle (Right System) - Removal / Installation 60P2900014Z001 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
291626	Left Hydraulic System Reservoir Relief Valve - Removal / Installation 60P2910024Z001 0132		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
291627	Right Hydraulic System Reservoir Relief Valve - Removal / Installation 60P2910024Z001 0221		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291630	Hydraulic Replenisher Tank Selector Valve Check Valve (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	M25675-6	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291635	Hydraulic Replenisher Tank - Removal / Installation		HRS		3522.4			0			0
	1159SCH519-7		AFL		727			0			0
	1045		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291636	Hydraulic Replenisher Tank Selector Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2900028Z003	0137	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291637	Hydraulic Replenisher Tank Selector Valve Check Valve (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	M25675-6	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291640	Hydraulic Replenisher Pump - Removal / Installation		HRS		3522.4			0			0
	1159SCH604-1		AFL		727			0			0
	161		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291700	Hydraulic System Accumulator (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2910081Z003	0205	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291701	Hydraulic System Accumulator (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2910081Z003	0221	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291702	Hydraulic System Accumulator Pressure Gage (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GP20-36	13-102272	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291703	Hydraulic System Accumulator Pressure Gage (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GP20-36	13-102269	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
291704	Autobrake System Accumulator (3RD) - Removal / Installation		HRS		2312.5			1209.9			0
			AFL		479			248			0
	90008132	AUG16-0837	MOS	TSN:13	87.1			22 Sep 2017			
			MSC				O/C				
Airframe											
Notes: NEW INSTALL FOR ASC 055C											
291708	Hydraulic System Accumulator Precharge (Left Hydraulic System) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
291709	Hydraulic System Accumulator Precharge (Right Hydraulic System) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
291710	Hydraulic System Accumulator Precharge (Inboard Brake System) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
291711	Hydraulic System Accumulator Precharge (Outboard Brake System) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	24	04 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291712	Hydraulic System Accumulator Precharge (Autobrake System) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.3			16 Nov 2022			
			MSC				O/C				
Airframe											
292000	Auxiliary Hydraulic System - Functional Test		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.5			12 Oct 2021			
			MSC				O/C				
Airframe											
292100	Auxiliary Hydraulic Pump - Removal / Installation 93835-51194-02-B K-0387		HRS	TSN:2648.8	873.6			2648.8			0
			AFL	TSN:561	166			561			0
			MOS	TSN:89	38.8			02 Oct 2021			N/A
			MSC				O/C				
Airframe											
292102	Auxiliary Hydraulic Pump Component Inspection - Leak Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
292200	Power Transfer Unit Hydraulic Pump - Removal / Installation 1159SCH511-4 MX773434		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
292201	Power Transfer Unit Check Valve - Removal / Installation M25675-6 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
292204	Power Transfer Unit - Functional Test		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		123.3			17 Sep 2014			
			MSC				O/C				
Airframe											
292205	Power Transfer Unit ARM Circuit - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
292206	Power Transfer Unit Hydraulic Pump Inspection - Leak Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
292207	Power Transfer Unit Bearing Wear Indicator - Inspection		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
292500	Auxiliary Hydraulic Pump Manifold - Removal / Installation 60P2921076Z001 E14473		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
292501	Auxiliary Hydraulic Pump Manifold Filter Element and Bowl - Removal / Installation 339980 NSN		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		25.5		09 Nov 2022		N/A		
			MSC			O/C					
Airframe											
292504	Auxiliary Hydraulic Pump Manifold Check Valve - Removal / Installation MS25676-6 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
292506	Auxiliary Hydraulic Pump Manifold - Cleaning		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
292507	Auxiliary Hydraulic Pump Manifold Filter Indicator - Removal / Installation R021192-7 L14217		HRS		873.6			2648.8			0
			AFL		166		561		0		
			MOS	TSN:33	38.9		28 Sep 2021		DONALDSON		
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
292509	Auxiliary Hydraulic Pump Acoustical Filter (Muffler) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	1159SCH603-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
292511	Auxiliary Hydraulic Pump Manifold Filter - Discard		HRS		485.9		3600	3036.5	6636.5	6686.5	0
	339980		AFL		97			630			0
			MOS		25.5			09 Nov 2022			
			[HRS: +50/-50]								
Airframe											
292605	Power Transfer Unit Shut-Off Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2921023Z001	0359	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
293100	Hydraulic System Reservoir Temperature Transducer (Left Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2930064Z003	DTP0878	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
293101	Hydraulic System Reservoir Temperature Transducer (Right Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2930064Z003	DTN9431	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
293104	Hydraulic System Reservoir Temperature Transducer (Left Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2930064Z003	DTP1734	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
293105	Hydraulic System Reservoir Temperature Transducer (Right Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2930064Z003	DTN9428	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
293200	Left System Pressure Transducer - Removal / Installation		HRS		3522.4			0			0
	60P2930061Z001	60021	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
293201	Right System Pressure Transducer - Removal / Installation		HRS		3522.4			0			0
	60P2930061Z001	56988	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
293202	Auxiliary Pressure Transducer - Removal / Installation		HRS		3522.4			0			0
	60P2930061Z001	59733	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
293203	Power Transfer Unit Pressure Transducer - Removal / Installation		HRS		3522.4			0			0
	60P2930061Z001	60024	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
293300	Left Reservoir Hydraulic Quantity Transmitter - Removal / Installation		HRS		3522.4			0			0
	60P2930063Z001	A0119	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
293301	Right Reservoir Hydraulic Quantity Transmitter - Removal / Installation		HRS		3522.4			0			0
	60P2930063Z002	A0130	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
293304	Fluid Quantity Indicator - Removal / Installation		HRS		3522.4			0			0
	366-220-003\1	1113	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* = Adj)	Max Due	Avg Man Hrs
	Logbook Position	Part Number									Serial Number
HW		SW									Manufacturer
MM Ref		Date Type									
Ops Number(s)											
293306	Hydraulic Reservoir Quantity Transmitter - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
30 - Ice and Rain Protection											
301100	Wing Anti-Ice Control Valve (Left) - Removal / Installation		HRS		3522.4			0			0
	3291928-1	325	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
301101	Wing Anti-Ice Control Valve (Right) - Removal / Installation		HRS		3522.4			0			0
	3291928-1	322	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
301102	Wing Anti-Ice Temperature Sensor (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	1151834-1	1151834-11201	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
301103	Wing Anti-Ice Temperature Sensor (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	1151834-1	11088	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
301104	Wing Anti-Ice Overheat Temperature Switch (Left Inboard) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	975-0113-001	SN-UNKNOWN	MOS	TSN:101	26.7			05 Oct 2022			N/A
	Airframe		MSC				O/C				
301105	Wing Anti-Ice Overheat Temperature Switch (Left Mid) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	975-0113-001	SN-UNKNOWN	MOS	TSN:101	26.7			05 Oct 2022			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
301106	Wing Anti-Ice Overheat Temperature Switch (Right Inboard) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	975-0113-001	SN-UNKNOWN	MOS	TSN:101	26.7			05 Oct 2022			N/A
			MSC				O/C				
Airframe											
301107	Wing Anti-Ice Overheat Temperature Switch (Right Mid) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	975-0113-001	SN-UNKNOWN	MOS	TSN:101	26.7			05 Oct 2022			N/A
			MSC				O/C				
Airframe											
301108	Wing Anti-Ice Overheat / Low Temperature Switch (Left Outboard) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	975-0114-001	SN-UNKNOWN	MOS	TSN:101	26.7			05 Oct 2022			N/A
			MSC				O/C				
Airframe											
301109	Wing Anti-Ice Overheat / Low Temperature Switch (Right Outboard) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	975-0114-001	SN-UNKNOWN	MOS	TSN:101	26.7			05 Oct 2022			N/A
			MSC				O/C				
Airframe											
301120	Wing Anti-Ice Overheat Temperature Switch (Left Inboard) - Operational Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7			05 Oct 2022			
			MSC				O/C				
Airframe											
301121	Wing Anti-Ice Overheat Temperature Switch (Left Mid) - Operational Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7			05 Oct 2022			
			MSC				O/C				
Airframe											
301122	Wing Anti-Ice Overheat Temperature Switch (Right Inboard) - Operational Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7			05 Oct 2022			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
301123	Wing Anti-Ice Overheat Temperature Switch (Right Mid) - Operational Test		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.7		05 Oct 2022				
			MSC			O/C					
Airframe											
301124	Wing Anti-Ice Overheat / Low Temperature Switch (Left Outboard) - Operational Test		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.7		05 Oct 2022				
			MSC			O/C					
Airframe											
301125	Wing Anti-Ice Overheat / Low Temperature Switch (Right Outboard) - Operational Test		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.7		05 Oct 2022				
			MSC			O/C					
Airframe											
301126	Wing Anti-Ice Control System - Functional Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
301127	Wing Anti-Ice (Left) - Operational Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
301128	Wing Anti-Ice (Right) - Operational Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
301129	Wing Hot / Wing Temp Low Message (Left) - Functional Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Logbook Position	Part Number									Serial Number
HW		SW									Manufacturer
MM Ref		Date Type									
	Ops Number(s)										
301130	Wing Hot / Wing Temp Low Message (Right) - Functional Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
301131	Wing Anti-Ice Temperature Switch (Left) - Functional Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
301132	Wing Anti-Ice Temperature Switch (Right) - Functional Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
301137	Wing Anti-Ice Temperature Switch - Temperature Trip Point Functional Check		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.6	16	96	07 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
302100	Cowl Thermal Anti-Ice Valve (Left) - Removal / Installation RD001C0007-5										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
302201	Cowl Thermal Anti-Ice Pressure Transducer (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	APTE227SA-75G	8102-10-411	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
303108	AIR Data System Probe and Total AIR Temperature Probe Heater (Left) - Operational Check		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		124.5			09 Aug 2014			
			MSC				O/C				
Airframe											
303109	AIR Data System Probe and Total AIR Temperature Probe Heater (Right) - Operational Check		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		124.5			09 Aug 2014			
			MSC				O/C				
Airframe											
304108	Cockpit Front and Side Window Power and Thermal Sensor Blocks (Left Front) - Repair		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
304109	Cockpit Front and Side Window Power and Thermal Sensor Blocks (Left Side) - Repair		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
304110	Cockpit Front and Side Window Power and Thermal Sensor Blocks (Right Front) - Repair		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
304111	Cockpit Front and Side Window Power and Thermal Sensor Blocks (Right Side) - Repair		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
304112	Windshield Heat (Left) - Operational Test		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.2		20 Sep 2016				
			MSC			O/C					
Airframe											
304113	Windshield Heat (Right) - Operational Test		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.2		20 Sep 2016				
			MSC			O/C					
Airframe											
304114	Windshield Heat (Left) - Functional Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
304115	Windshield Heat (Right) - Functional Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
304116	Windshield Surface Seal (Left) - Serviceability Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
304117	Windshield Surface Seal (Right) - Serviceability Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
304118	Windshield Surface Seal (Left) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.7	-6	12	04 Oct 2024	30 Sep 2025*	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
304119	Windshield Surface Seal (Right) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.7	-6	12	04 Oct 2024	30 Sep 2025*	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
304400	Cabin Window Heat - Operational Test		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		25.2		19 Nov 2022				
			MSC			O/C					
304401	Cabin Window Heat Switch - Removal / Installation 318VL23AAAMNY00 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
304411	Cabin Emergency Exit Window Heat Switch (Left No. 5) - Adjustment		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
304412	Cabin Emergency Exit Window Heat Switch (Left No. 6) - Adjustment		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
304413	Cabin Emergency Exit Window Heat Switch (Right No. 5) - Adjustment		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
304414	Cabin Emergency Exit Window Heat Switch (Right No. 6) - Adjustment		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
308100	Ice Detector Probe (Left) - Removal / Installation 0871HH\1 2430		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
308101	Ice Detector Probe (Right) - Removal / Installation		HRS		3522.4			0			0
	0871HH\1	02376	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
308104	Ice Detector Probes (Left) - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
308105	Ice Detector Probes (Right) - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
308106	Ice Detector Logic (Left) - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
308107	Ice Detector Logic (Right) - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
31 - Indicating/Recording Systems											
311200	Pedestal Switch Panel - Removal / Installation		HRS		3509.1			13.3			0
	60P3110900Z040	0137	AFL		722			5			0
			MOS		123			27 Sep 2014			IDD AEROSPACE
	Airframe		MSC				O/C				
311202	Pedestal Switch Panel - Servicing		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
311600	Pilot Switch Panel - Removal / Installation		HRS		3522.4			0			0
	G7285-01\A	259	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
311601	Copilot Switch Panel - Removal / Installation		HRS		3522.4			0			0
	G7285-01\A	263	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
311602	Cabin Touch Control Panel - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: PN: G7285-01\A SN: 259. MRI PARENT CODE: 311600											
311603	Shower Controller Assembly Aft Lavatory - Removal / Installation		HRS		3522.4			0			0
	G7285-01\A	263	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 311601											
311716	Window Shade Switch Panel #1 (Left) - Removal / Installation		HRS		3509.1			13.3			0
	A2455	006757	AFL		722			5			0
			MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
311717	Window Shade Switch Panel #2 (Left) - Removal / Installation		HRS		3509.1			13.3			0
	A2455	006748	AFL		722			5			0
			MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
311718	Window Shade Switch Panel #3 (Left) - Removal / Installation		HRS		3509.1			13.3			0
	A2455	006747	AFL		722			5			0
			MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				
311719	Window Shade Switch Panel #4 (Left) - Removal / Installation		HRS		3509.1			13.3			0
	A2455	006751	AFL		722			5			0
			MOS		123			27 Sep 2014			RADIANT
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
311720	Window Shade Switch Panel #5 (Left) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2455	006756	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
311721	Window Shade Switch Panel #6 (Left) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2455	006760	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
311722	Window Shade Switch Panel #7 (Left) - Removal / Installation		HRS		3278			244.4			0
			AFL		680			47			0
	A2455	007678	MOS		115.7			04 May 2015			RADIANT
			MSC				O/C				
Airframe											
311723	Window Shade Switch Panel #8 (Left) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2455	006745	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
311725	Window Shade Switch Panel #2 (Right) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2455	006758	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
311726	Window Shade Switch Panel #3 (Right) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2455	006753	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
311727	Window Shade Switch Panel #4 (Right) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2455	006752	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
311728	Window Shade Switch Panel #5 (Right) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2455	006749	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
311729	Window Shade Switch Panel #6 (Right) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2455	006759	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
311730	Window Shade Switch Panel #7 (Right) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2455	006750	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
311731	Window Shade Switch Panel #8 (Right) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	A2455	006755	MOS		123			27 Sep 2014			RADIANT
			MSC				O/C				
Airframe											
312200	Cockpit Clock (Pilot) - Removal / Installation		HRS		3522.4			0			0
	1159SCAV409-2		AFL		727			0			0
	3697		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
312201	Cockpit Clock (Copilot) - Removal / Installation		HRS		3522.4			0			0
	1159SCAV409-2		AFL		727			0			0
	3753		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
312204	Cockpit Clock (Pilot) - Functional Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
312206	Cockpit Clock Battery (Pilot) - Servicing		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		63.2			19 Sep 2019			
	Airframe		MSC				O/C				
Notes: INSTALLED NEW BATTERY PN: MN9100, SN: NSN											
312207	Cockpit Clock Battery (Copilot) - Servicing		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
312500	Cockpit Printer - Removal / Installation		HRS		3278			244.4			0
	42905411	12C0118	AFL		680			47			0
			MOS		115.7			03 May 2015			
	Airframe		MSC				O/C				
312502	Cockpit Printer - Functional Test		HRS		3278			244.4			0
			AFL		680			47			0
			MOS		115.7			03 May 2015			
	Airframe		MSC				O/C				
312503	Cockpit Printer Paper - Servicing		HRS		3278			244.4			0
			AFL		680			47			0
			MOS		115.7			03 May 2015			
	Airframe		MSC				O/C				
313100	Tri-Axial Accelerometer - Removal / Installation		HRS		3522.4			0			0
	3001-01-100	0114-DTS4240	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
313101	FDR Unit - Removal / Installation		HRS	TSN:3408.5	113.9			3408.5			0
	1607-00-00,200002,200102\	728	AFL	TSN:691	36			691			0
			MOS	TSN:114	14.1			24 Oct 2023			N/A
	Airframe		MSC				O/C				
313104	FDR - Functional / Reasonableness Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.1		24	24 Oct 2023	31 Oct 2025	30 Nov 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
313105	FDR Fail Message - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.8		24	01 Nov 2023	30 Nov 2025	31 Dec 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
313106	FDR Impact Switch - Removal / Installation		HRS	TSN:1209.9	2312.5			1209.9			0
	1159SCAV402-2	4844	AFL	TSN:248	479			248			0
			MOS	TSN:41	87.1			24 Sep 2017			
	Airframe		MSC	O/C							
313108	FDR Impact Switch - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.8		72	01 Nov 2023	30 Nov 2029	31 Dec 2029	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
313111	FDR Underwater Locator Beacon - Removal / Installation		HRS	TSN:1601.9	310.9			3211.5			0
	DK120/90	AT121377	AFL	TSN:333	64			663			0
			MOS	TSN:56	19.4			15 May 2023			
	Airframe		MSC	O/C							
313113	FDR Underwater Locator Beacon - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1		24	23 Sep 2024	30 Sep 2026	31 Oct 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
313114	FDR Underwater Locator Beacon - Cleaning		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1		24	23 Sep 2024	23 Sep 2026	23 Oct 2026	
	Airframe		[MOS: +1m/-1m]								
313115	FDR Underwater Locator Beacon (DK120 or DK120/90) - Battery Replacement		HRS		1912.8			1609.6			0
	DK120/90	AT121377	AFL		397			330			0
			MOS		75.2			21 Sep 2018			
	Airframe		MSC	O/C							
313117	FDR Underwater Locator Beacon Battery (DK120, DK120/90 or DK290) - Discard		HRS		1912.8			1609.6			0
	DK120/90	AT121377	AFL		397			330			0
			MOS		75.2		84	21 Sep 2018	31 Oct 2025		
	Airframe		[End Of Month Item] EXPIRATION								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
313118	FDR Underwater Locator Beacon Battery (DK120 or DK120/90) - Functional Check		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
313119	FDR Underwater Locator Beacon Battery- Servicing		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
314000	Modular Avionics Unit AIR Inlet Screen (Mau No.1) - Clean / Inspect		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
314001	Modular Avionics Unit AIR Inlet Screen (Mau No.2) - Clean / Inspect		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
314002	Modular Avionics Unit AIR Inlet Screen (Mau No.3) - Clean / Inspect		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
314102	Avionics Standard Communication Bus Coupler (Mau 2) - Removal / Installation		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS	TSN:4	128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
314110	Avionics Standard Communication Bus Coupler (Mau 1) - Removal / Installation		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS	TSN:4	128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314130	Avionics Standard Communication Bus Coupler (Mau 3) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7027566-902\B-E	12129395	MOS	TSN:4	128.2			21 Apr 2014			
	0	0	MSC				O/C				
Airframe											
314274	Actuator Input / Output Processor Module (1A) - Removal / Installation		HRS	TSN:2482.5	1039.9			2482.5			0
			AFL	TSN:511	216			511			0
	7028432-1902	1311H249	MOS	TSN:86	43.7			03 May 2021			N/A
			MSC				O/C				
Airframe											
314275	Actuator Input / Output Processor Module (1B) - Removal / Installation		HRS	TSN:2482.5	1039.9			2482.5			0
			AFL	TSN:511	216			511			0
	7028432-1902	1311H176	MOS	TSN:86	43.7			03 May 2021			N/A
			MSC				O/C				
Airframe											
314276	Actuator Input / Output Processor Module (2A) - Removal / Installation		HRS	TSN:2482.5	1039.9			2482.5			0
			AFL	TSN:511	216			511			0
	7028432-1902	1311H205	MOS	TSN:86	43.7			03 May 2021			N/A
			MSC				O/C				
Airframe											
314277	Actuator Input / Output Processor Module (2B) - Removal / Installation		HRS	TSN:2482.5	1039.9			2482.5			0
			AFL	TSN:511	216			511			0
	7028432-1902	1311H224	MOS	TSN:86	43.7			03 May 2021			N/A
			MSC				O/C				
Airframe											
314300	Modular Avionics Unit Dual Channel Chassis (No. 1) - Removal / Installation		HRS	TSN:3408.5	113.9			3408.5			0
			AFL	TSN:691	36			691			0
	7024404-2913	13114013	MOS	TSN:114	14			26 Oct 2023			N/A
			MSC				O/C				
Airframe											
314301	Modular Avionics Unit Dual Channel Chassis (No. 2) - Removal / Installation		HRS	TSN:3408.5	113.9			3408.5			0
			AFL	TSN:691	36			691			0
	7024404-2913	13114011	MOS	TSN:114	14			26 Oct 2023			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314302	Modular Avionics Unit Dual Channel Chassis (No. 3) - Removal / Installation		HRS	TSN:2364.2	1158			2364.4			0
			AFL	TSN:487	239			488			0
	7024404-2913	13103984	MOS	TSN:78	50.4			13 Oct 2020			N/A
			MSC				O/C				
Airframe											
314306	Modular Avionics Unit - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.8			01 Nov 2023			
			MSC				O/C				
Airframe											
314309	Single Channel Generic Input / Output Module (No. 2) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	7038485-1901	22064975	MOS	TSN:15	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314313	Airflow Blockage Module No. 3 Mau No. 2 (Forward Reer) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7027208-1903	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314314	Airflow Blockage Module No. 4 Mau No. 2 (Forward Reer) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7027208-1903	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314315	Airflow Blockage Module No. 1 Mau No. 1 - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7027208-1903	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314316	Airflow Blockage Module No. 2 Mau No. 1 - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7027208-1903	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314317	Airflow Blockage Module - No. 9 Mau No. 2 - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	7027208-1903	2003DT40	MOS	TSN:42	14.1			22 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314321	Airflow Blockage Module No. 5 Mau No. 3 - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7027208-1903	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314322	Airflow Blockage Module No. 6 Mau No. 3 - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7027208-1903	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314323	Airflow Blockage Module No. 7 Mau No. 3 - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7027208-1903	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314324	Airflow Blockage Module No. 8 Mau No. 3 - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7027208-1903	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314325	Control Input / Output Module (No.1) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	7038472-1901	20021789	MOS	TSN:43	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314328	Single Channel Generic Input / Output Module (No. 4) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	7038485-1901	22064941	MOS	TSN:16	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314329	Single Channel Generic Input / Output Module (No. 3) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	7038485-1901	22064978	MOS	TSN:15	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314330	Single Channel Generic Input / Output Module (No. 1) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	7038485-1901	22064930	MOS	TSN:16	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314331	Single Channel Generic Input / Output Module (No. 5) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	7038485-1901	22064973	MOS	TSN:16	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314332	Single Channel Generic Input / Output Module (No. 6) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	7038485-1901	22064983	MOS	TSN:15	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314333	Dual Channel Generic Input / Output Module (No. 1) - Removal / Installation		HRS		1752.3			1770.1			0
			AFL		359			368			0
	7025365-1902\A-D,J	11047610	MOS		70.5			12 Feb 2019			
			MSC				O/C				
Airframe											
314334	Dual Channel Generic Input / Output Module (No. 2) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7025365-1902\A-D,J	13119869	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314337	Custom Input / Output Module (No. 1) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	7026540-1903	22047385	MOS	TSN:15	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314338	Custom Input / Output Module (No. 2) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	7026540-1903	22047386	MOS	TSN:15	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314339	Custom Input / Output Module (No. 3) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	7026540-1903	22037379	MOS	TSN:15	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314342	Network Interface Controller / Processor Module (No. 1) (Mau No. 1) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7038231-1902\A-E	13116268	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314343	Network Interface Controller / Processor Module (No. 2) (Mau No. 1) - Removal / Installation		HRS		936.8			2585.6			0
			AFL		179			548			0
	7038231-1902\A-E	13116262	MOS		40.6			06 Aug 2021			
			MSC				O/C				
Airframe											
314344	Network Interface Controller / Processor Module (No. 3) (Mau No. 2) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7038231-1902\A-E	13116163	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314345	Network Interface Controller / Processor Module (No. 4) (Mau No. 2) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7038231-1902\A-E	13116037	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314346	Network Interface Controller / Processor Module (No. 5) (Mau No. 3) - Removal / Installation		HRS		820.2			2702.2			0
			AFL		155			572			0
	7038231-1902	13064240	MOS		36.3			16 Dec 2021			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314347	Network Interface Controller / Processor Module (No. 6)		HRS		820.2			2702.2			0
	(Mau No. 3) - Removal / Installation		AFL		155			572			0
	7038231-1902	13095331	MOS		36.3			16 Dec 2021			
			MSC				O/C				
Airframe											
314348	Dual Channel Generic Input / Output Module (No. 3) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	7025365-1902\A-D,J	13119856	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
314350	Power Supply Module (No. 1) - Removal / Installation		HRS		113.9			3408.5			0
	7038248-1901	20019546	AFL		36			691			0
			MOS	TSN:43	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314351	Power Supply Module (No. 2) - Removal / Installation		HRS		113.9			3408.5			0
	7038248-1901	20019576	AFL		36			691			0
			MOS	TSN:43	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314352	Power Supply Module (No. 3) - Removal / Installation		HRS		113.9			3408.5			0
	7038248-1901	20029729	AFL		36			691			0
			MOS	TSN:43	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314353	Power Supply Module (No. 4)- Removal / Installation		HRS		113.9			3408.5			0
	7038248-1901	20029716	AFL		36			691			0
			MOS	TSN:43	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314354	Advanced Graphic Module (No. 1) - Removal / Installation		HRS		113.9			3408.5			0
	60000770-1901	23087225	AFL		36			691			0
			MOS	TSN:1	14			26 Oct 2023			HONEYWELL
			MSC				O/C				
Airframe											
314355	Advanced Graphic Module (No. 2) - Removal / Installation		HRS		.4			3522			0
	60000770-1901	24049765	AFL		1			726			0
			MOS	TSN:6	2.4			13 Oct 2024			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314356	Power Supply Module (No. 5) - Removal / Installation		HRS		113.9			3408.5			0
	7038248-1901	20019577	AFL		36			691			0
			MOS	TSN:43	14			26 Oct 2023			HONEYWELL
	Airframe		MSC				O/C				
314357	Power Supply Module (No. 6) - Removal / Installation		HRS		113.9			3408.5			0
	7038248-1901	20029725	AFL		36			691			0
			MOS	TSN:43	14			26 Oct 2023			HONEYWELL
	Airframe		MSC				O/C				
314358	Advanced Graphic Module (No. 4) - Removal / Installation		HRS		113.9			3408.5			0
	60000770-1901	23087018	AFL		36			691			0
			MOS	TSN:2	14			26 Oct 2023			HONEYWELL
	Airframe		MSC				O/C				
314359	Video Module (No. 1) - Removal / Installation		HRS		113.9			3408.5			0
	7038630-1901	20022352	AFL		36			691			0
			MOS	TSN:43	14			26 Oct 2023			HONEYWELL
	Airframe		MSC				O/C				
314360	Video Module (No. 2) - Removal / Installation		HRS		113.9			3408.5			0
	7038630-1901	20022327	AFL		36			691			0
			MOS	TSN:43	14			26 Oct 2023			HONEYWELL
	Airframe		MSC				O/C				
314369	Modular Avionics Unit Personality Module (No. 1) - Removal / Installation		HRS		3522.4			0			0
	7519272-901\C	40342809	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
314370	Modular Avionics Unit Personality Module (No. 2) - Removal / Installation		HRS		3522.4			0			0
	7519272-901\C	40342805	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
314373	Integrated Engine Vibration Monitor Module - Removal / Installation		HRS		3522.4			0			0
	241-326-005-011\2	AK13510	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314375	Advanced Graphic Module (No. 3) - Removal / Installation		HRS		113.9			3408.5			0
	60000770-1901	23076788	AFL		36			691			0
			MOS	TSN:1	14			26 Oct 2023			HONEYWELL
	Airframe		MSC				O/C				
314400	Central Maintenance Computer Module - Removal / Installation		HRS		2069.7			1452.7			0
			AFL		429			298			0
	7034055-1901	11122141	MOS		80.5			12 Apr 2018			
	Airframe		MSC				O/C				
Notes: TORQUE WRENCH: C/U 560287 NEXT CAL. DUE 06/18											
314402	Central Maintenance System - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.8			01 Nov 2023			
	Airframe		MSC				O/C				
314405	Pentium-M Processor Module - Removal / Installation		HRS		113.9			3408.5			0
	7034056-1903	23087032	AFL		36			691			0
			MOS	TSN:2	14			25 Oct 2023			HONEYWELL
	Airframe		MSC				O/C				
315000	Central Warning System - Operational Test		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		125.4			15 Jul 2014			
	Airframe		MSC				O/C				
315100	Planeview Software - Top Level System (TIs)		HRS		113.9			3408.5			0
	EB7038694-00105	NSN	AFL		36			691			0
			MOS	TSN:1	13.8			01 Nov 2023			HONEYWELL
	Airframe		MSC				O/C				
315101	Blue Disc - Planeview System Charts - Update		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			09 Oct 2024			
	Airframe		MSC				O/C				
315102	Planeview Master Operating System (Mos) Media		HRS		113.9			3408.5			0
	MM7038690-008	35717766	AFL		36			691			0
		UCN 35717766	MOS	TSN:1	13.8			01 Nov 2023			GAC
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
315103	Options Software		HRS		113.9			3408.5			0
	TT60004484-60073	81495	AFL		36			691			0
			MOS		13.8			01 Nov 2023			HONEYWELL
	Airframe		MSC				O/C				
315104	CD, Options Data Media		HRS		113.9			3408.5			0
	DM60004484-60073	NSN	AFL		36			691			0
			MOS		13.8			01 Nov 2023			HONEYWELL
	Airframe		MSC				O/C				
315105	Electronic Checklist S/W		HRS		.4			3522			0
	GVIPV0076000006L.ECL	NSN	AFL		1			726			0
			MOS	TSN:1	2.7			05 Oct 2024			GULFSTREAM
	Airframe		MSC				O/C				
315106	CD, Electronic Checklist Media		HRS		.4			3522			0
	GVIPV0076000006L.ECL	NSN	AFL		1			726			0
			MOS	TSN:1	2.7			04 Oct 2024			GULFSTREAM
	Airframe		MSC				O/C				
315107	Settings/Rigging S/W-TIs		HRS		113.9			3408.5			0
	6088 N380SE 9/28/2023	NSN	AFL		36			691			0
			MOS		13.8			01 Nov 2023			GAC
	Airframe		MSC				O/C				
315108	CD, Settings/Rigging Media		HRS		113.9			3408.5			0
	6088 N380SE 9/28/2023	NSN	AFL		36			691			0
			MOS		13.8			01 Nov 2023			GAC
	Airframe		MSC				O/C				
315109	Cmc Diagnostic S/W-TIs		HRS		113.9			3408.5			0
	GVI_903_00105_11_08292	NSN	AFL		36			691			0
	3		MOS		13.8			01 Nov 2023			GAC
	Airframe		MSC				O/C				
315110	CD, Cmc Diagnostic Media (Ldi)		HRS		113.9			3408.5			0
	GVI_903_00105_11_08292	NSN	AFL		36			691			0
	3		MOS		13.8			01 Nov 2023			GAC
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
315111	Programmable CAS		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14			25 Oct 2023			
	Airframe		MSC				O/C				
Notes: PN: DFC2ED81 SN: 19APR2014.											
315112	Airline Modifiable Software		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.8			01 Nov 2023			
	Airframe		MSC				O/C				
Notes: PN: 69003875-501 SN: 6088.											
315113	Magnetic Variation Database - Update		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14			25 Oct 2023			
	Airframe		MSC				-				
315114	Airport MAP Database (Amdb) - Update		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				-				
315205	Warn Inhibit Panel - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
315400	Aircraft Configuration Message - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.9	2	36	29 Oct 2023	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
316000	Electronic Display System - Display Format Control - Adjustment / Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.4			15 Nov 2022			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
316300	Cursor Control Device (Pilot) - Removal / Installation		HRS		485.9			3036.5			0
	1159F57160-9 0776A		AFL		97			630			0
			MOS		26.2			19 Oct 2022			N/A
	Airframe		MSC				O/C				
316301	Cursor Control Device (Copilot) - Removal / Installation		HRS		.4			3522			0
	1159F57160-10 0450A		AFL		1			726			0
			MOS		3			25 Sep 2024			N/A
	Airframe		MSC				O/C				
316302	Display Unit (No. 1) - Removal / Installation		HRS		3522.4			0			0
	7028140-911\A-P 13108170		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
316303	Display Unit (No. 2) - Removal / Installation		HRS	TSN:1254.4	485.9			3036.5			0
	7028140-911 18122146		AFL	TSN:260	97			630			0
			MOS	TSN:44	25.4			15 Nov 2022			N/A
	Airframe		MSC				O/C				
316304	Display Unit (No. 3) - Removal / Installation		HRS		485.9			3036.5			0
	7028140-911 18091911		AFL		97			630			0
			MOS		26.5			12 Oct 2022			N/A
	Airframe		MSC				O/C				
316305	Display Unit (No. 4) - Removal / Installation		HRS		2695			827.4			0
	7028140-911\A-P 16040351		AFL		551			176			0
			MOS		96.6			06 Dec 2016			
	Airframe		MSC				O/C				
316318	Display Unit - Cleaning		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.4			15 Nov 2022			
	Airframe		MSC				O/C				
316320	Display Brightness Control Panel - Removal / Installation		HRS		2695			827.4			0
	7007543-903 12061769		AFL		551			176			0
			MOS		96.6			06 Dec 2016			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
316322	Displays Manual Reversion - Operational Check		HRS		485.9		2250	3036.5	5286.5	5336.5	0
			AFL		97			630			0
			MOS		26.4			13 Oct 2022			
Airframe			[HRS: +50/-50]								
Notes: COMPLIED WITH CMP G650 316322 AIRFRAME DISPLAYS MANUAL REVERSION - OPERATIONAL CHECK											
316325	Cursor Control Device - Operational Test		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3			25 Sep 2024			
Airframe			MSC				O/C				
316327	Cursor Control Device - Nulling Procedure		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe			MSC				O/C				
316340	Video Amplifier - Removal / Installation		HRS		3522.4			0			0
	VA-400-1	111300016	AFL		727			0			0
	0	0	MOS	TSN:4	128.2			21 Apr 2014			
Airframe			MSC				O/C				
316600	McdU Capability to Display Standby Engine Instruments - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe			MSC				O/C				
316903	Receiver, Xm Weather System - Removal / Installation		HRS		113.9			3408.5			0
	XMD157-03	818000039	AFL		36			691			0
			MOS		14.1			22 Oct 2023			HEADS UP TECH
Airframe			MSC				O/C				
316904	Antenna - Xm Weather System - Removal / Installation		HRS	TSN:2350.9	1158			2364.4			0
	4092744-901	35557323	AFL	TSN:482	239			488			0
			MOS	TSN:73	50.5			12 Oct 2020			N/A
Airframe			MSC				O/C				
316905	Data Port (No.1) - Xm Weather System - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4092745-901	35511735	MOS		123			27 Sep 2014			HONEYWELL
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
316906	Data Port (No.2) - Xm Weather System - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4092745-901	35562545	MOS		123			27 Sep 2014			HONEYWELL
			MSC				O/C				
Airframe											
32 - Landing Gear											
320001	Landing Gear Doors - Operational Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
320002	Nose and Main Landing Gear and Doors - General Visual Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	27	12	04 Oct 2024	31 Oct 2025*	30 Nov 2025	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
320003	Nose and Main Landing Gear and Doors - Zonal Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.6	14	24	06 Oct 2024	31 Oct 2026*	30 Nov 2026	
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
Airframe											
320004	Landing Gear - Operational Test		HRS		0			3522.4			0
			AFL		0			727			0
			MOS		2.3			18 Oct 2024			
			MSC				O/C				
Airframe											
320005	Landing Gear Cycling - Operational Test		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			09 Oct 2024			
			MSC				O/C				
Airframe											
320006	Landing Gear - Free Fall Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.8			02 Nov 2022			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321000	Main Landing Gear (Left) - Removal / Installation		HRS		3522.4			0			0
	60P3212010A019	GLG0094	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
321001	Main Landing Gear (Right) - Removal / Installation		HRS		3522.4			0			0
	60P3212011A017	GLG0094	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
321002	Main Landing Gear Structural Post (Left) - Removal / Installation		HRS		3522.4			0			0
	C1A5300LA003	CD0174	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
321003	Main Landing Gear Structural Post (Right) - Removal / Installation		HRS		3522.4			0			0
	C1A5300RA003	CD0187	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
321008	Main Landing Gear (Left) - Restore		HRS		3522.4			0			0
	60P3212010A019	GLG0094	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	21 Apr 2030		
	Airframe										
Notes: MRI PARENT CODE: 321000											
321009	Main Landing Gear (Right) - Restore		HRS		3522.4			0			0
	60P3212011A017	GLG0094	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	21 Apr 2030		
	Airframe										
Notes: MRI PARENT CODE: 321001											
321012	Main Landing Gear - Rigging / Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321013	Main Landing Gear Post Machining (Left) - Discard		HRS		3522.4			0			0
	C1A5300LA003	CD0174	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321002											
321014	Main Landing Gear Post Machining (Right) - Discard		HRS		3522.4			0			0
	C1A5300RA003	CD0187	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321003											
321017	Main Landing Gear Trunnion Lugs (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		4745**	0	4745		0
			MOS		128.2			21 Apr 2014			
Airframe											
321018	Main Landing Gear Trunnion Lugs (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		4745**	0	4745		0
			MOS		128.2			21 Apr 2014			
Airframe											
321029	Main Landing Gear Door - Rigging / Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
321030	Main Landing Gear Door (Left) - Removal / Installation		HRS		3522.4			0			0
	60P5280410A016	0001518686	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
321031	Main Landing Gear Door (Right) - Removal / Installation		HRS		3522.4			0			0
	60P5280310A021	0001460040	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321032	Main Landing Gear Fairing Door (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5280421A007	0001516899	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321033	Main Landing Gear Fairing Door (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5280321A004	0001510456	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321050	Main Landing Gear and Components (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.8	-2	48	02 Nov 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: TW 562030 DATE 11/2018TW 560120 DATE 11/2018TW 571404 DATE 11/2018TW 560287 DATE 6/2019											
321051	Main Landing Gear and Components (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.8	-2	48	02 Nov 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: TW 562030 DATE 11/2018TW 560120 DATE 11/2018TW 571404 DATE 11/2018TW 560287 DATE 6/2019											
321052	Main Landing Gear Corrosion Inhibiting Compound Reapplication (Left)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	25	24	06 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
321053	Main Landing Gear Corrosion Inhibiting Compound Reapplication (Right)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	25	24	06 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: TW 562030 DATE 11/2018TW 560120 DATE 11/2018TW 571404 DATE 11/2018TW 560287 DATE 6/2019											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321200	Main Landing Gear Shock Absorber (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	C1A4200CA002	GK0207	MOS		25.9			28 Oct 2022			GOODRICH
			MSC				O/C				
Airframe											
Notes: TW 562030 DATE 11/2018TW 560120 DATE 11/2018TW 571404 DATE 11/2018TW 560287 DATE 6/2019											
321201	Main Landing Gear Shock Absorber (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	C1A4200CA002	GK0159	MOS		25.9			28 Oct 2022			GOODRICH
			MSC				O/C				
Airframe											
Notes: TW 562030 DATE 11/2018TW 560120 DATE 11/2018TW 571404 DATE 11/2018TW 560287 DATE 6/2019											
321202	Main Gear Shock Strut Cylinder (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	C1M5210CA001	GK0208	MOS	TSN:102	25.8			02 Nov 2022			
			MSC				O/C				
Airframe											
321203	Main Gear Shock Strut Cylinder (Right) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	C1M5210CA001	GK0205	MOS		25.8			02 Nov 2022			
			MSC				O/C				
Airframe											
321204	Main Landing Gear Side Brace Actuator Cylinder End CAP (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1M5601CA001	PLT0121	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321205	Main Landing Gear Side Brace Actuator Cylinder End CAP (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1M5601CA001	SPP300111	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321206	Main Gear Shock Strut Metering Pin (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1M5221CA001	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321207	Main Gear Shock Strut Metering Pin (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1M5221CA001	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321208	Main Landing Gear Shock Absorber (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1A4200CA001	GK0207	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321209	Main Landing Gear Shock Absorber (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1A4200CA001	GK0205	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321211	Upper Main Gear Shock Strut Attachment Pin (Left) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	C1M5415CA003	GRZ0166	MOS	TSN:35	25.9			28 Oct 2022			GOODRICH
			MSC				O/C				
Airframe											
321212	Lower Main Gear Shock Strut Attachment Pin (Left) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	C1M5415CA003	GRZ0438	MOS	TSN:35	25.9			28 Oct 2022			GOODRICH
			MSC				O/C				
Airframe											
321213	Upper Main Gear Shock Strut Attachment Pin (Right) - Removal / Installation		HRS		485.9			3036.5			0
			AFL		97			630			0
	C1M5415CA003	GRZ0443	MOS	TSN:35	25.9			28 Oct 2022			GOODRICH
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321214	Lower Main Gear Shock Strut Attachment Pin (Right) - Removal / Installation		HRS	TSN:485.5	.4			3522			0
			AFL	TSN:96	1			726			0
	C1M5415CA003	GRZ0440	MOS	TSN:58	2.7			05 Oct 2024			N/A
			MSC				O/C				
Airframe											
321215	Main Gear Shock Strut Piston Assembly (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1A5201CA001	GK0213	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321216	Main Gear Shock Strut Piston Assembly (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1A5201CA001	GK0210	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321235	Main Landing Gear Shock Absorber Upper and Lower Attach Pins Corrosion Inhibiting Compound Application - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.9			28 Oct 2022			
			MSC				O/C				
Airframe											
321238	Main Landing Gear Shock Absorber Cylinder Body (Left) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C1M5210CA001	GK0208	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321202											
321239	Main Landing Gear Shock Absorber Cylinder Body (Right) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C1M5210CA001	GK0205	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321203											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321240	Main Landing Gear Shock Absorber Piston Machining		HRS		3522.4			0			0
	(Left) - Discard		AFL		727		20000	0	20000		0
	C1A5201CA001	GK0213	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321215											
321241	Main Landing Gear Shock Absorber Piston Machining		HRS		3522.4			0			0
	(Right) - Discard		AFL		727		20000	0	20000		0
	C1A5201CA001	GK0210	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321216											
321244	Main Landing Gear Shock Absorber Attach Pin (Left		HRS		3522.4			0			0
	Upper) - Discard		AFL		727		20000	0	20000		0
	C1M5415CA002	EXC0411	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321211											
321245	Main Landing Gear Shock Absorber Attach Pin (Left		HRS		3522.4			0			0
	Lower) - Discard		AFL		727		20000	0	20000		0
	C1M5415CA002	EXC0414	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321212											
321246	Main Landing Gear Shock Absorber Attach Pin (Right		HRS		3522.4			0			0
	Upper) - Discard		AFL		727		20000	0	20000		0
	C1M5415CA002	EXC0420	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321213											
321247	Main Landing Gear Shock Absorber Attach Pin (Right		HRS		3522.4			0			0
	Lower) - Discard		AFL		727		20000	0	20000		0
	C1M5415CA002	EXC0413	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321214											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321248	Main Landing Gear Side Brace Actuator Cylinder End		HRS		3522.4			0			0
	CAP (Left) - Discard		AFL		727		20000	0	20000		0
	C1M5601CA001	PLT0121	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321204											
321249	Main Landing Gear Side Brace Actuator Cylinder End		HRS		3522.4			0			0
	CAP (Right) - Discard		AFL		727		20000	0	20000		0
	C1M5601CA001	SPP300111	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321205											
321250	Main Landing Gear Shock Absorber Cylinder Body (Left) -		HRS		3522.4			0			0
	Restore		AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											
321251	Main Landing Gear Shock Absorber Cylinder Body (Right)		HRS		3522.4			0			0
	- Restore		AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											
321252	Main Landing Gear Shock Absorber Piston Machining		HRS		3522.4			0			0
	(Left) - Restore		AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											
321253	Main Landing Gear Shock Absorber Piston Machining		HRS		3522.4			0			0
	(Right) - Restore		AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321254	Main Landing Gear Shock Absorber Attach Pin (Left Upper) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
321255	Main Landing Gear Shock Absorber Attach Pin (Left Lower) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
321256	Main Landing Gear Shock Absorber Attach Pin (Right Upper) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
321257	Main Landing Gear Shock Absorber Attach Pin (Right Lower) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
321258	Main Landing Gear Side Brace Actuator Cylinder End CAP (Left) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
321259	Main Landing Gear Side Brace Actuator Cylinder End CAP (Right) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
321263	Main Landing Gear Spindle Pin (Left) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321264	Main Landing Gear Spindle Pin (Right) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe		[End Of Month Item]								
321267	Main Landing Gear Side Brace Fitting Pin (Left) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe		[End Of Month Item]								
321268	Main Landing Gear Side Brace Fitting Pin (Right) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe		[End Of Month Item]								
321300	Main Landing Gear Axle Fitting Pin (Left) - Removal / Installation		HRS	TSN:1665.1	1912.8			1609.6			0
			AFL	TSN:563	397			330			0
	C1A5425CA001	EXC0208	MOS	TSN:1	75.2			21 Sep 2018			N/A
	Airframe		MSC				O/C				
321301	Main Landing Gear Axle Fitting Pin (Right) - Removal / Installation		HRS	TSN:3577.5	.4			3522			0
			AFL	TSN:959	1			726			0
	C1A5425CA001	EXC0207	MOS	TSN:73	2.7			05 Oct 2024			N/A
	Airframe		MSC				O/C				
321303	Main Landing Gear Axle Fitting (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	C1A5400CA001	ZKM0225	MOS	TSN:101	26.4			13 Oct 2022			N/A
	Airframe		MSC				O/C				
321304	Main Landing Gear Axle Fitting (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	C1A5400CA001	ZKM0233	MOS	TSN:101	26.4			13 Oct 2022			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321305	Main Landing Gear Axle Fitting and Axle Fitting Nut (Left Inboard) Corrosion Inhibiting Compound Application - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4			13 Oct 2022			
			MSC				O/C				
Airframe											
321306	Main Landing Gear Axle Fitting and Axle Fitting Nut (Right Outboard) Corrosion Inhibiting Compound Application - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4			13 Oct 2022			
			MSC				O/C				
Airframe											
321307	Main Landing Gear Axle Fitting and Axle Fitting Nut (Right Inboard) Corrosion Inhibiting Compound Application - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4			13 Oct 2022			
			MSC				O/C				
Airframe											
321308	Main Landing Gear Axle Fitting Attach Pin (Right) Corrosion Inhibiting Compound Application - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.9			28 Oct 2022			
			MSC				O/C				
Airframe											
321309	Main Landing Gear Axle Fitting Attach Pin (Left) Corrosion Inhibiting Compound Application - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4			13 Oct 2022			
			MSC				O/C				
Airframe											
321310	Main Landing Gear Axle Fitting and Axle Fitting Nut (Left Outboard) Corrosion Inhibiting Compound Application - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4			13 Oct 2022			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321313	Main Landing Gear Knee Joint Pin (Left) - Discard		HRS		1912.8			1609.6			0
	C1A5425CA001	EXC0208	AFL		397		20000	330	20330		0
			MOS		75.2			20 Sep 2018			
	Airframe										
321314	Main Landing Gear Knee Joint Pin (Right) - Discard		HRS	TSN:1665.1	1912.8			1609.6			0
	C1A5425CA001	EXC0207	AFL	TSN:563	397		20000	330	19767		0
			MOS	TSN:1	75.1			24 Sep 2018			
	Airframe										
321315	Main Landing Gear Knee Joint Pin (Left) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe [End Of Month Item]										
321316	Main Landing Gear Knee Joint Pin (Right) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe [End Of Month Item]										
321400	Main Landing Gear Side Brace Actuator Fuse Pin Link		HRS		3522.4			0			0
	Assembly (Left) - Removal / Installation		AFL		727			0			0
	60P3215911M001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321401	Main Landing Gear Side Brace Actuator Fuse Pin Link		HRS		3522.4			0			0
	Assembly (Right) - Removal / Installation		AFL		727			0			0
	60P3215911M001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321402	Main Landing Gear Side Brace Actuator (Left) - Removal /		HRS	TSN:3036.5	485.9			3036.5			0
	Installation		AFL	TSN:630	97			630			0
	60P3214000Z007	PLT0108	MOS	TSN:101	26.4			13 Oct 2022			N/A
			MSC				O/C				
Airframe											
Notes: TW 562030 DATE 11/2018TW 560120 DATE 11/2018TW 571404 DATE 11/2018TW 560287 DATE 6/2019											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321403	Main Landing Gear Side Brace Actuator (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	60P3214000Z007	SPP000136	MOS	TSN:101	26.4			13 Oct 2022			N/A
			MSC				O/C				
Airframe											
Notes: TW 562030 DATE 11/2018TW 560120 DATE 11/2018TW 571404 DATE 11/2018TW 560287 DATE 6/2019											
321404	Main Landing Gear Spindle Pin (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	C1A5315CA002	EXC0234	MOS	TSN:102	25.8			01 Nov 2022			N/A
			MSC				O/C				
Airframe											
321405	Main Landing Gear Spindle Pin (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	C1A5315CA002	EXC0232	MOS	TSN:101	26.4			13 Oct 2022			N/A
			MSC				O/C				
Airframe											
321408	Side Brace Fitting (Left) - Removal / Installation		HRS		3522.4			0			0
	60P3215103M006	0041	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321409	Side Brace Fitting (Right) - Removal / Installation		HRS		3522.4			0			0
	60P3215104M004	0025	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321412	Outboard Side Brace Fitting (Left) - Removal / Installation		HRS		3522.4			0			0
	60P3215805M006	8H31550-A20	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321413	Outboard Side Brace Fitting (Right) - Removal / Installation		HRS		3522.4			0			0
	60P3215806M004	HI5739-T1A1-4	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321416	Main Landing Gear Side Brace Upper Tie ROD (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3215901M001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321417	Main Landing Gear Side Brace Upper Tie ROD (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3215901M001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321420	Main Landing Gear Fuse Pin Link Assembly (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3215833A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321421	Main Landing Gear Fuse Pin Link Assembly (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3215833A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321428	Main Landing Gear Side Brace Fitting Pin (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1M5640CA001	EXC0192	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321429	Main Landing Gear Side Brace Fitting Pin (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1M5640CA001	EXC0208	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321432	Main Landing Gear Side Brace Actuator Attach Pins / Trunnion AREA Corrosion Inhibiting Coumpound Application - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4			13 Oct 2022			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321433	Main Landing Gear Spindle Pin (Left) - Discard		HRS		3522.4			0			0
	C1M5315CA002	EXC0234	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321404											
321434	Main Landing Gear Spindle Pin (Right) - Discard		HRS		3522.4			0			0
	C1M5315CA002	EXC0232	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321405											
321437	Main Landing Gear Side Brace Fitting Pin (Left) - Discard		HRS		3522.4			0			0
	C1M5640CA001	EXC0192	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321428											
321438	Main Landing Gear Side Brace Fitting Pin (Right) - Discard		HRS		3522.4			0			0
	C1M5640CA001	EXC0208	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321429											
321442	Main Landing Gear Side Brace Pin (Left, Upper) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
Airframe [End Of Month Item]											
321443	Main Landing Gear Side Brace Pin (Lh) (Upper) - Discard		HRS		3522.4			0			0
	60P3215911M001	SN-UNKNOWN	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
321444	Main Landing Gear Side Brace Pin (Right, Upper) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
Airframe [End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321445	Main Landing Gear Side Brace Pin (Rh) (Upper)- Discard		HRS		3522.4			0			0
	60P3215911M001 SN-UNKNOWN		AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
321500	Main Landing Gear Trunnion Pin (Left Forward) - Removal		HRS	TSN:3036.5	485.9			3036.5			0
	/ Installation		AFL	TSN:630	97			630			0
	C1A5310CA002	EXC0204	MOS	TSN:101	26.4			13 Oct 2022			N/A
Airframe											
321501	Main Landing Gear Trunnion Pin (Left Aft) - Removal /		HRS	TSN:3036.5	485.9			3036.5			0
	Installation		AFL	TSN:630	97			630			0
	C1A5311CA002	EXC0098	MOS	TSN:101	26.4			13 Oct 2022			N/A
Airframe											
Notes: TW 562030 DATE 11/2018TW 560120 DATE 11/2018TW 571404 DATE 11/2018TW 560287 DATE 6/2019											
321502	Main Landing Gear Trunnion Pin (Right Forward) -		HRS	TSN:3036.5	485.9			3036.5			0
	Removal / Installation		AFL	TSN:630	97			630			0
	C1A5310CA002	EXC0204	MOS	TSN:101	26.4			13 Oct 2022			N/A
Airframe											
321503	Main Landing Gear Trunnion Pin (Right Aft) - Removal /		HRS	TSN:3036.5	485.9			3036.5			0
	Installation		AFL	TSN:630	97			630			0
	C1A5311CA002	EXC0106	MOS	TSN:101	26.4			13 Oct 2022			N/A
Airframe											
321508	Main Landing Gear Forward Trunnion Pin (Left) - Discard		HRS		3522.4			0			0
	C1M5310CA002 EXC0208		AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321500											
321509	Main Landing Gear Aft Trunnion Pin (Left) - Discard		HRS		3522.4			0			0
	C1A5311CA002 EXC0098		AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321501											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321510	Main Landing Gear Forward Trunnion Pin (Right) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C1M5310CA002	EXC0204	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321502											
321511	Main Landing Gear Aft Trunnion Pin (Right) - Discard		HRS		3522.4			0			0
	C1A5311CA002		AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321503											
321512	Main Landing Gear Forward Trunnion Pin (Left) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
Airframe			[End Of Month Item]								
321513	Main Landing Gear Aft Trunnion Pin (Left) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
Airframe			[End Of Month Item]								
321514	Main Landing Gear Forward Trunnion Pin (Right) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
Airframe			[End Of Month Item]								
321515	Main Landing Gear Aft Trunnion Pin (Right) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
Airframe			[End Of Month Item]								
321600	Main Landing Gear Electrical Harness (Left Outboard) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	C1E5906CA002	ICO20223	MOS	TSN:9	38.9			30 Sep 2021			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
321601	Main Landing Gear Electrical Harness (Right Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1E5908CA002	ICO00145	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321604	Main Landing Gear Electrical Harness (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1E5903CA004	ICO00150	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321605	Main Landing Gear Electrical Harness (Right Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1E5907CA002	ICO00152	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321800	Main Landing Gear Door Control Links (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5280332A001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
321801	Main Landing Gear Door Control Links (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5280332A007	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322000	Nose Landing Gear - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3222010A009	GLG0101	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322002	Nose Landing Gear - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	60P3222010A009	GLG0101	MOS		128.2		192	21 Apr 2014	21 Apr 2030		
Airframe											
Notes: MRI PARENT CODE: 322000											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322003	Nose Landing Gear Components - Discard		HRS		3522.4			0			0
	60P3222010A009	GLG0101	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 322000											
322004	Nose Landing Gear Components - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	11	48	20 Oct 2022	31 Oct 2026*	30 Nov 2026	N/A
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: PN: C2M5421CA001 SN: PLT190205.											
322005	Nose Landing Gear Corrosion Inhibiting Compound		HRS		.4			3522			0
	Reapplication		AFL		1			726			0
			MOS		3.2	40	24	21 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
322006	Nose Landing Gear Door (Left) - Removal / Installation		HRS		3522.4			0			0
	60P5280111A020	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322007	Nose Landing Gear Door (Right) - Removal / Installation		HRS		3522.4			0			0
	60P5280121A020	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322008	Nose Landing Gear Downlock Swivel (Lh)		HRS		3522.4			0			0
	LSA14-14J4S	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322009	Nose Landing Gear Downlock Swivel (Rh)		HRS		3522.4			0			0
	LSA14-14J4S	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322010	Nose Landing Gear Fairing Door - Removal / Installation		HRS		3522.4			0			0
	60P5280131A019P01		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322012	Nose Landing Gear - Rigging / Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322013	Nose Landing Gear Door - Rigging / Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322014	Nose Landing Gear Fairing Door - Rigging / Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322200	Nose Landing Gear Shock Absorber - Removal / Installation		HRS	TSN:3522.4	0			3522.4			0
			AFL	TSN:727	0			727			0
	C2A4200CA006	PLT0108	MOS	TSN:125	2.3			17 Oct 2024			N/A
	Airframe		MSC				O/C				
322202	Nose Landing Gear Shock Absorber and Axle Assembly		HRS		485.9			3036.5			0
	Corrosion Inhibiting Compound Application		AFL		97			630			0
			MOS		26.5			12 Oct 2022			
	Airframe		MSC				O/C				
322203	Nose Landing Gear Shock Absorber - Discard		HRS		3522.4			0			0
	C2A4200CA006		AFL		727			0			0
	PLT0108		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 322200											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322205	Nose Landing Gear Upper Torsion Link Attach Pin - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C2M5202CA001	PLT190083	MOS		128.2			21 Apr 2014			
Airframe											
322207	Nose Landing Gear Lower Torque ARM - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2M5203CA001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322208	Nose Landing Gear Upper Torsion Link Attach Pin - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
322212	Upper Torsion Link, Machined - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2M5202CA001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322213	Lower Torsion Link, Machined - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2M5203CA001	PLT190082	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322300	Nose Landing Gear Axle Assembly - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2A5201CA001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322401	Nose Landing Gear Aft Truss Brace - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2A5413CA001	PLT190042	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322402	Nose Landing Gear Truss Brace / Trunnion Attach Pin (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2M5423CA001	PLT190566	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322403	Nose Landing Gear Truss Brace / Trunnion Attach Pin (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2M5423CA001	PLT190568	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322405	Nose Landing Gear Truss Brace Forward Link Assembly - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2M5404CA001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322406	Nose Landing Gear Truss Brace Aft Link Assembly - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2M5408CA001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322407	Nose Landing Gear Trunnion - Removal / Installation		HRS		3522.4			0			0
	C2A4300CA001	PLT0116	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322409	Nose Landing Gear Upper Drag Brace Attach Pin		HRS		485.9			3036.5			0
	Corrosion Inhibiting Compound Application		AFL		97			630			0
			MOS		26.5			12 Oct 2022			
			MSC				O/C				
Airframe											
322410	Nose Landing Gear Truss Brace Assembly Corrosion Inhibiting Compound Application		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5			12 Oct 2022			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322411	Nose Landing Gear Forward Truss Brace - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	C2M5400CA001	PLT0408	MOS	TSN:101	26.2			20 Oct 2022			N/A
			MSC				O/C				
Airframe											
322413	Nose Landing Gear Truss Brace Forward Machining - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C2M5400CA001	PLT0408	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322411											
322415	Nose Landing Gear Truss Brace Forward Machining - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
322416	Nose Landing Gear Truss Brace Apex Pin (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2M5423CA001	PLT190519	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322418	Nose Landing Gear Drag Brace - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	C2A4600CA002		AFL	TSN:630	97			630			0
	NSN		MOS	TSN:101	26.2			20 Oct 2022			N/A
			MSC				O/C				
Airframe											
322420	Nose Landing Gear Trunnion Assembly Corrosion Inhibiting Compound Application		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5			12 Oct 2022			
			MSC				O/C				
Airframe											
322421	Nose Landing Gear Trunnion Fitting - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		11140**	0	11140		0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322423	Nose Landing Gear Drag Brace Fitting Lug - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		13830**	0	13830		0
			MOS		128.2			21 Apr 2014			
Airframe											
322426	Nose Landing Gear Cylinder / Trunnion Attach Pin - Removal / Installation C2M5312CA001		HRS	TSN:3522.4	0			3522.4			0
			AFL	TSN:727	0			727			0
			MOS	TSN:125	2.3			17 Oct 2024			N/A
			MSC				O/C				
Airframe											
322427	Nose Landing Gear Cylinder / Trunnion Attach Pin - Restore PN		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
			MOS	SN-UNKNOWN	128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											
322428	Nose Landing Gear Cylinder / Trunnion Attach Pin - Discard C2M5312CA001		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
			MOS	PLT190092	128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322426											
322429	Nose Landing Gear Truss Brace Aft Machining - Discard C2M5413CA001		HRS		3522.4			0			0
			AFL	PLT190042	727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322401											
322430	Nose Landing Gear Drag Brace / Aft Truss Attach Pin - Removal / Installation C2M5421CA001		HRS		3522.4			0			0
			AFL		727			0			0
			MOS	PLT190205	128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322431	Nose Landing Gear Truss Brace Aft Machining - Restore PN		HRS		3522.4			0			0
			AFL	SN-UNKNOWN	727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322432	Nose Landing Gear Drag Brace Upper Attach Pin - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C2M5421CA001	PLT190205	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322430											
322435	Nose Landing Gear Truss Brace Apex Pin (Left) - Restore		HRS		3522.4			0			0
	C2M5423CA001	PLT190519	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											
Notes: MRI PARENT CODE: 322416											
322436	Nose Landing Gear Truss Brace Apex Pin (Left) - Discard		HRS		3522.4			0			0
	C2M5423CA001	PLT190519	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322416											
322437	Nose Landing Gear Drag Brace Upper Attach Pin - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											
322500	Nose Landing Gear Trunnion Pin (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2M5310CA001	DL0024	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322501	Nose Landing Gear Trunnion Pin (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2M5310CA001	DL0023	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322502	Nose Landing Gear Trunnion Pin (Left) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322503	Nose Landing Gear Trunnion Pin (Right) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe	[End Of Month Item]									
322504	Outer Cylinder, Machined - Removal / Installation		HRS		3522.4			0			0
	C2M5200CA001	PLT0131	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
322506	Nose Landing Gear Cylinder Machining - Restore		HRS		3522.4			0			0
	C2M5200CA001	PLT0131	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe	[End Of Month Item]									
Notes: MRI PARENT CODE: 322504											
322507	Nose Landing Gear Cylinder Machining - Discard		HRS		3522.4			0			0
	C2M5200CA001	PLT0131	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322504											
322508	Piston, Machined - Removal / Installation		HRS		3522.4			0			0
	C2M5201CA001	PLT0140	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
322509	Nose Landing Gear Upper Torque ARM - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe	[End Of Month Item]									
322510	Nose Landing Gear Piston Machining - Restore		HRS		3522.4			0			0
	C2M5201CA001	PLT0140	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe	[End Of Month Item]									
Notes: MRI PARENT CODE: 322508											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322511	Nose Landing Gear Piston Machining - Discard		HRS		3522.4			0			0
	C2M5201CA001	PLT0140	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322508											
322512	Nose Landing Gear Upper Torque ARM Link - Removal / Installation		HRS		3522.4			0			0
	C2M5202CA001	PLT190083	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322514	Upper Torsion Link, Machined - Restore		HRS		3522.4			0			0
	C2M5202CA001	PLT190083	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 322512											
322515	Nose Landing Gear Upper Torque ARM - Discard		HRS		3522.4			0			0
	C2M5202CA001	PLT190083	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322512											
322516	Nose Landing Gear Lower Torque ARM Link - Removal / Installation		HRS		3522.4			0			0
	C2M5203CA001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322517	Nose Landing Gear Lower Torque ARM - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
Airframe [End Of Month Item]											
322518	Lower Torsion Link, Machined - Restore		HRS		3522.4			0			0
	C2M5203CA001	PLT190082	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 322213											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322519	Nose Landing Gear Lower Torque ARM - Discard		HRS		3522.4			0			0
	C2M5203CA001		AFL		727		20000	0	20000		0
	PLT190082		MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322213											
322520	Metering Pin - Removal / Installation		HRS		3522.4			0			0
	C2M5206CA002		AFL		727			0			0
	PLT150135		MOS		128.2			21 Apr 2014			
Airframe			MSC				O/C				
322522	Metering Pin - Restore		HRS		3522.4			0			0
	C2M5206CA002		AFL		727			0			0
	PLT150135		MOS		128.2			21 Apr 2014			
Airframe			MSC				O/C				
Notes: MRI PARENT CODE: 322520											
322524	Nose Landing Gear Drag Brace / Cylinder Attach Pin -		HRS	TSN:3522.4	0			3522.4			0
	Removal / Installation		AFL	TSN:727	0			727			0
	C2A5234CA001		MOS	TSN:125	2.3			17 Oct 2024			N/A
Airframe			MSC				O/C				
322526	Nose Landing Gear Drag Brace Lower Attach Pin -		HRS		3522.4			0			0
	Restore		AFL		727		10000	0	10000		0
	C2A5234CA001		MOS		128.2		192	21 Apr 2014	30 Apr 2030		
Airframe			[End Of Month Item]								
Notes: MRI PARENT CODE: 322524											
322527	Nose Landing Gear Drag Brace Lower Attach Pin -		HRS		3522.4			0			0
	Discard		AFL		727		20000	0	20000		0
	C2M5234CA001		MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322524											
322528	Pin, Lower Torsion Link Attach - Removal / Installation		HRS		3522.4			0			0
	C2M5235CA001		AFL		727			0			0
	NSN		MOS		128.2			21 Apr 2014			
Airframe			MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322530	Nose Landing Gear Lower Torque ARM Attach Pin - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	C2M5235CA001	NSN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	[End Of Month Item]										
Airframe											
Notes: MRI PARENT CODE: 322528											
322531	Nose Landing Gear Lower Torque ARM Attach Pin - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C2M5235CA001	NSN	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322528											
322532	Pin, Torsion ARM Apex - Removal / Installation		HRS		3522.4			0			0
	C2M5250CA001	PLT292084	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322534	Nose Landing Gear Torque ARM Apex Pin - Restore		HRS		3522.4			0			0
	C2M5250CA001	PLT292084	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	[End Of Month Item]										
Airframe											
Notes: MRI PARENT CODE: 322532											
322535	Nose Landing Gear Torque ARM Apex Pin - Discard		HRS		3522.4			0			0
	C2M5250CA001	PLT292084	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322532											
322536	Trunnion Frame, Machining - Removal / Installation		HRS		3522.4			0			0
	C2M5300CA001	PLT0127	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322538	Nose Landing Gear Trunnion Frame Machining - Restore		HRS		3522.4			0			0
	C2M5300CA001	PLT0127	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	[End Of Month Item]										
Airframe											
Notes: MRI PARENT CODE: 322536											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322539	Nose Landing Gear Trunnion Frame Machining - Discard		HRS		3522.4			0			0
	C2M5300CA001	PLT0127	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322536											
322540	Bolt, Retaining - Removal / Installation		HRS		3522.4			0			0
	C2M5314CA001	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
O/C											
322542	Nose Landing Gear Cylinder / Trunnion Pin Retaining Bolt		HRS		3522.4			0			0
	- Restore		AFL		727		10000	0	10000		0
	C2M5314CA001	NSN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											
Notes: MRI PARENT CODE: 322540											
322543	Nose Landing Gear Cylinder / Trunnion Pin Retaining Bolt		HRS		3522.4			0			0
	- Discard		AFL		727		20000	0	20000		0
	C2M5314CA001	NSN	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322540											
322544	Truss Brace Assembly - Removal / Installation		HRS		3522.4			0			0
	C2A4400CA004	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
O/C											
322546	Truss Brace Assembly - Restore		HRS		3522.4			0			0
	C2A4400CA004	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
O/C											
Notes: MRI PARENT CODE: 322544											
322548	Nose Landing Gear Truss Brace Apex Pin (Right) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	C2M5423CA001	PLT190562	MOS		128.2			21 Apr 2014			
Airframe											
O/C											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322550	Nose Landing Gear Truss Brace Apex Pin (Right) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	C2M5423CA001	PLT190562	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	[End Of Month Item]										
Airframe											
Notes: MRI PARENT CODE: 322548											
322551	Nose Landing Gear Truss Brace Apex Pin (Right) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C2M5423CA001	PLT190562	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322548											
322552	Pin, Apex Downlock - Removal / Installation		HRS		3522.4			0			0
	C2M5425CA001	DL0067	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322554	Nose Landing Gear Downlock Apex Pin - Restore		HRS		3522.4			0			0
	C2M5425CA001	DL0067	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	[End Of Month Item]										
Airframe											
Notes: MRI PARENT CODE: 322552											
322555	Nose Landing Gear Downlock Apex Pin - Discard		HRS		3522.4			0			0
	C2M5425CA001	DL0067	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322552											
322556	Pin, Aft Downlock - Removal / Installation		HRS		3522.4			0			0
	C2M5426CA001	DL0071	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322558	Nose Landing Gear Aft Lock Link Pin - Restore		HRS		3522.4			0			0
	C2M5426CA001	DL0071	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	[End Of Month Item]										
Airframe											
Notes: MRI PARENT CODE: 322556											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322559	Nose Landing Gear Aft Lock Link Pin - Discard		HRS		3522.4			0			0
	C2M5426CA001	DL0071	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322556											
322560	Aft Lock Link, Machining - Removal / Installation		HRS		3522.4			0			0
	C2M5408CA001	PLT190132	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
322562	Nose Landing Gear Aft Lock Link Machining - Restore		HRS		3522.4			0			0
	C2M5408CA001	PLT190132	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
Airframe											
Notes: MRI PARENT CODE: 322560											
322563	Nose Landing Gear Aft Lock Link Machining - Discard		HRS		3522.4			0			0
	C2M5408CA001	PLT190132	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322560											
322564	Sleeve, Drag Brace Attach Long - Removal / Installation		HRS		3522.4			0			0
	C2M5419CA001	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
322566	Sleeve, Drag Brace Attach Long - Restore		HRS		3522.4			0			0
	C2M5419CA001	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322564											
322568	Sleeve, Drag Brace Attach Short - Removal / Installation		HRS		3522.4			0			0
	C2M5420CA001	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322570	Sleeve, Drag Brace Attach Short - Restore		HRS		3522.4			0			0
	C2M5420CA001	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322572	Pin, Forward Lock Link - Removal / Installation		HRS		3522.4			0			0
	C2M5424CA001	DL0095	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322574	Nose Landing Gear Forward Lock Link Pin - Restore		HRS		3522.4			0			0
	C2M5424CA001	DL0095	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe	[End Of Month Item]									
Notes: MRI PARENT CODE: 322572											
322575	Nose Landing Gear Forward Lock Link Pin - Discard		HRS		3522.4			0			0
	C2M5424CA001	DL0095	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322572											
322576	Strut Body - Removal / Installation		HRS		3522.4			0			0
	C2M4601CA001	PLT150127	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322578	Nose Landing Gear Drag Brace Strut Body - Restore		HRS		3522.4			0			0
	C2M4601CA001	PLT150127	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe	[End Of Month Item]									
Notes: MRI PARENT CODE: 322576											
322579	Nose Landing Gear Drag Brace Strut Body - Discard		HRS		3522.4			0			0
	C2M4601CA001	PLT150127	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322576											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322580	ROD End - Removal / Installation		HRS		3522.4			0			0
	C2M4602CA002	DL0076	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322582	Nose Landing Gear Drag Brace ROD End - Restore		HRS		3522.4			0			0
	C2M4602CA002	DL0076	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe		[End Of Month Item]								
Notes: MRI PARENT CODE: 322580											
322583	Nose Landing Gear Drag Brace ROD End - Discard		HRS		3522.4			0			0
	C2M4602CA002	DL0076	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322580											
322584	Drag Brace Nut - Removal / Installation		HRS		3522.4			0			0
	C2M4605CA001	PLT370089	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322586	Drag Brace Nut - Restore		HRS		3522.4			0			0
	C2M4605CA001	PLT370089	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 322584											
322588	Nose Landing Gear Trunnion Pin (Left) - Discard		HRS		3522.4			0			0
	C2M5310CA001	DL0024	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322500											
322589	Nose Landing Gear Trunnion Pin (Right) - Discard		HRS		3522.4			0			0
	C2M5310CA001	DL0023	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322501											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322590	Forward Lock Link, Machining - Removal / Installation		HRS		3522.4			0			0
	C2M5404CA001	PLT190128	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322592	Nose Landing Gear Forward Lock Link Machining -		HRS		3522.4			0			0
	Restore		AFL		727		10000	0	10000		0
	C2M5404CA001	PLT190128	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe		[End Of Month Item]								
Notes: MRI PARENT CODE: 322590											
322593	Nose Landing Gear Forward Lock Link Machining -		HRS		3522.4			0			0
	Discard		AFL		727		20000	0	20000		0
	C2M5404CA001	PLT190128	MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322590											
322600	NLG Taxi Light Assembly (Left) - Removal / Installation		HRS		3522.4			0			0
	01-0790460-00	00474	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322601	NLG Taxi Light Assembly (Center) - Removal / Installation		HRS		3522.4			0			0
	01-0790460-00	00475	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322602	NLG Taxi Light Assembly (Right) - Removal / Installation		HRS		3522.4			0			0
	01-0790460-00	00476	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322603	Nose Landing Gear Down and Lock Harness - Discard		HRS		3522.4			0			0
	C2E4901CA002	SN-UNKNOWN	AFL		727		18000	0	18000		0
			MOS		128.2			21 Apr 2014			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322606	Nose Landing Gear Upper Electrical Harness - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2E4901CA003	ICO10171	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322608	Nose Landing Gear Middle Electrical Harness - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C2E4904CA003	ICO10201	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322610	Nose Landing Gear Lower Electrical Harness - Removal / Installation		HRS		0			3522.4			0
			AFL		0			727			0
	C2E4905CA003	ICO10173	MOS		2.3			17 Oct 2024			N/A
			MSC				O/C				
Airframe											
322618	Nose Landing Gear Middle Electrical Harness - Discard		HRS		3522.4			0			0
	C2E4904CA003	ICO10201	AFL		727		10000	0	10000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322608											
322700	CAP, Machining (Left) - Removal / Installation		HRS		3522.4			0			0
	C1A5205CA001	AP0252	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322702	Main Landing Gear Shock Absorber CAP Machining (Left)		HRS		3522.4			0			0
	- Restore		AFL		727		10000	0	10000		0
	C1A5205CA001	AP0252	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 322700											
322703	Main Landing Gear Shock Absorber CAP Machining (Left)		HRS		3522.4			0			0
	- Discard		AFL		727		7000	0	7000		0
	C1M5205CA001	AP0252	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322700											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322704	CAP, Machining (Right) - Removal / Installation		HRS	TSN:3522	.4			3522			0
	C1A5205CA001	AP0248	AFL	TSN:726	1			726			0
			MOS	TSN:125	2.7			05 Oct 2024			N/A
	Airframe		MSC				O/C				
322706	Main Landing Gear Shock Absorber CAP Machining		HRS		3522.4			0			0
	(Right) - Restore		AFL		727		10000	0	10000		0
	C1A5205CA001	AP0248	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 322704											
322707	Main Landing Gear Shock Absorber CAP Machining		HRS		3522.4			0			0
	(Right) - Discard		AFL		727		7000	0	7000		0
	C1M5205CA001	AP0248	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322704											
322708	Nut, Cylinder (Left) - Removal / Installation		HRS		3522.4			0			0
	C1M5217CA001	GK0250	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322710	Main Landing Gear Shock Absorber Cylinder Nut (Left) -		HRS		3522.4			0			0
	Restore		AFL		727		10000	0	10000		0
	C1M5217CA001	GK0250	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 322708											
322711	Main Landing Gear Shock Absorber Cylinder Nut (Left) -		HRS		3522.4			0			0
	Discard		AFL		727		20000	0	20000		0
	C1M5217CA001	GK0250	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322708											
322712	Nut, Cylinder (Right) - Removal / Installation		HRS		3522.4			0			0
	C1M5217CA001	GK0248	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322714	Main Landing Gear Shock Absorber Cylinder Nut (Right) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	C1M5217CA001	GK0248	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											
Notes: MRI PARENT CODE: 322712											
322715	Main Landing Gear Shock Absorber Cylinder Nut (Right) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C1M5217CA001	GK0248	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322712											
322716	Left Main Post Assembly, - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	C1A5300LA003	CD0174	AFL	TSN:630	97			630			0
			MOS	TSN:101	26.4			13 Oct 2022			N/A
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 321002											
322718	Left Main Post Assembly, - Restore		HRS		3522.4			0			0
	C1A5300LA003	CD0174	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 321002											
322720	Right Main Post Assembly, - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	C1A5300RA003	CD0187	AFL	TSN:630	97			630			0
			MOS	TSN:101	26.4			13 Oct 2022			N/A
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 321003											
322722	Right Main Post Assembly, - Restore		HRS		3522.4			0			0
	C1A5300RA003	CD0187	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 321003											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322724	Nut, Spindle Pin (Left) - Removal / Installation		HRS		3522.4			0			0
	C1M5316CA002	ACR0245	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322726	Main Landing Gear Spindle Pin Nut (Left) - Restore		HRS		3522.4			0			0
	C1M5316CA002	ACR0245	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe		[End Of Month Item]								
Notes: MRI PARENT CODE: 322724											
322727	Main Landing Gear Spindle Pin Nut (Left) - Discard		HRS		3522.4			0			0
	C1M5316CA002	ACR0245	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322724											
322728	Nut, Spindle Pin (Right) - Removal / Installation		HRS		3522.4			0			0
	C1M5316CA002	ACR0248	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322730	Main Landing Gear Spindle Pin Nut (Right) - Restore		HRS		3522.4			0			0
	C1M5316CA002	ACR0248	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe		[End Of Month Item]								
Notes: MRI PARENT CODE: 322728											
322731	Main Landing Gear Spindle Pin Nut (Right) - Discard		HRS		3522.4			0			0
	C1M5316CA002	ACR0248	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322728											
322732	Nut, Aft Pintle Pin (Left) - Removal / Installation		HRS		3522.4			0			0
	C1M5313CA001	EXC0233	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322734	Main Landing Gear Aft Pintle Pin Nut (Left) - Restore		HRS		3522.4			0			0
	C1M5313CA001	EXC0233	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe		[End Of Month Item]								
Notes: MRI PARENT CODE: 322732											
322735	Main Landing Gear Aft Pintle Pin Nut (Left) - Discard		HRS		3522.4			0			0
	C1M5313CA001	EXC0233	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322732											
322736	Nut, Aft Pintle Pin (Right) - Removal / Installation		HRS		3522.4			0			0
	C1M5313CA001	EXC0282	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
322738	Main Landing Gear Aft Pintle Pin Nut (Right) - Restore		HRS		3522.4			0			0
	C1M5313CA001	EXC0282	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe		[End Of Month Item]								
Notes: MRI PARENT CODE: 322736											
322739	Main Landing Gear Aft Pintle Pin Nut (Right) - Discard		HRS		3522.4			0			0
	C1M5313CA001	EXC0282	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322736											
322740	Bolt, Forward Pintle Cross (Left) - Removal / Installation		HRS	TSN:672.1	485.9			3036.5			0
	C1A5319CA001	GRZ0168	AFL	TSN:142	97			630			0
			MOS	TSN:34	26.4			13 Oct 2022			N/A
	Airframe		MSC				O/C				
322742	Main Landing Gear Forward Pintle Crossbolt (Left) - Restore		HRS		1158			2364.4			0
	C1A5319CA001	GRZ0168	AFL		239		10000	488	10488		0
			MOS	TSN:12	50		192	26 Oct 2020	31 Oct 2035		N/A
	Airframe		[End Of Month Item]								
Notes: MRI PARENT CODE: 322740											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322743	Main Landing Gear Forward Pintle Crossbolt (Left) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C1M5319CA001	EXC0237	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322740											
322744	Bolt, Forward Pintle Cross (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	C1A5319CA001	EXC0213	AFL	TSN:630	97			630			0
			MOS	TSN:101	26.4			13 Oct 2022			N/A
			MSC				O/C				
Airframe											
322746	Main Landing Gear Forward Pintle Crossbolt (Right) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	C1A5319CA001	EXC0213	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 322744											
322747	Main Landing Gear Forward Pintle Crossbolt (Right) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C1M5319CA001	EXC0213	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322744											
322748	Bolt, Aft Pintle Cross (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	C1A5322CA001	EXC0216	AFL	TSN:630	97			630			0
			MOS	TSN:101	26.4			13 Oct 2022			N/A
			MSC				O/C				
Airframe											
322750	Main Landing Gear Aft Pintle Crossbolt (Left) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	C1A5322CA001	EXC0216	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 322748											
322751	Main Landing Gear Aft Pintle Crossbolt (Left) - Discard		HRS		3522.4			0			0
	C1M5322CA001	EXC0216	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322748											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322752	Bolt, Aft Pintle Cross (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	C1A5322CA001	EXC0213	AFL	TSN:630	97			630			0
			MOS	TSN:101	26.4			13 Oct 2022			N/A
	Airframe		MSC				O/C				
322754	Main Landing Gear Aft Pintle Crossbolt (Right) - Restore		HRS		3522.4			0			0
	C1A5322CA001	EXC0213	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe			[End Of Month Item]							
Notes: MRI PARENT CODE: 322752											
322755	Main Landing Gear Aft Pintle Crossbolt (Right) - Discard		HRS		3522.4			0			0
	C1M5322CA001	EXC0213	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322752											
322756	Trailing ARM Machining (Left) - Removal / Installation		HRS		3522.4			0			0
	C1A5400CA001	ZKM0225	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe			MSC				O/C			
322758	Main Landing Gear Trailing ARM Machining (Left) - Restore		HRS		3522.4			0			0
	C1A5400CA001	ZKM0225	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe			[End Of Month Item]							
Notes: MRI PARENT CODE: 322756											
322759	Main Landing Gear Trailing ARM Machining (Left) - Discard		HRS		3522.4			0			0
	C1M5400CA001	ZKM0225	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322756											
322760	Trailing ARM Machining (Right) - Removal / Installation		HRS	TSN:3522	.4			3522			0
	C1A5400CA001	ZKM0508	AFL	TSN:726	1			726			0
			MOS	TSN:125	2.5			12 Oct 2024			N/A
	Airframe			MSC				O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322762	Main Landing Gear Trailing ARM Machining (Right) -		HRS	TSN:3522	.4			3522			0
	Restore		AFL	TSN:726	1		10000	726	10000		0
	C1A5400CA001	ZKM0508	MOS	TSN:5	2.5		192	12 Oct 2024	31 May 2040		
	[End Of Month Item]										
Airframe											
Notes: MRI PARENT CODE: 322760											
322763	Main Landing Gear Trailing ARM Machining (Right) -		HRS		.4			3522			0
	Discard		AFL	TSN:726	1		20000	726	20000		0
	C1M5400CA001	ZKM0508	MOS		2.5			12 Oct 2024			
Airframe											
Notes: MRI PARENT CODE: 322760											
322764	Nut, Shock Absorber Attach (Left Upper) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	C1M5417CA001	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322766	Nut, Shock Absorber Attach (Left Upper) - Restore		HRS		3522.4			0			0
	C1M5417CA001		AFL		727			0			0
	NSN		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 322764											
322768	Nut, Shock Absorber Attach (Right Upper) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	C1M5417CA001	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322770	Nut, Shock Absorber Attach (Right Upper) - Restore		HRS		3522.4			0			0
	C1M5417CA001		AFL		727			0			0
	NSN		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 322768											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322772	Nut, Shock Absorber Attach (Left Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1M5417CA001	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322774	Nut, Shock Absorber Attach (Left Lower) - Restore		HRS		3522.4			0			0
			AFL		727			0			0
	C1M5417CA001	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 322772											
322776	Nut, Shock Absorber Attach (Right Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1M5417CA001	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322778	Nut, Shock Absorber Attach (Right Lower) - Restore		HRS		3522.4			0			0
			AFL		727			0			0
	C1M5417CA001	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 322776											
322780	Pin, Knee Joint Retention (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	C1M5426CA001	CFN0079	MOS	TSN:101	26.4			13 Oct 2022			N/A
			MSC				O/C				
Airframe											
322782	Main Landing Gear Knee Joint Retention Pin (Left) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	C1M5426CA001	CFN0079	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 322780											
322783	Main Landing Gear Knee Joint Retention Pin (Left) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C1M5426CA001	CFN0079	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322780											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322784	Pin, Knee Joint Retention (Right) - Removal / Installation		HRS	TSN:3522	.4			3522			0
	C1M5426CA001	CFN0067	AFL	TSN:726	1			726			0
			MOS	TSN:124	2.7			05 Oct 2024			N/A
	Airframe		MSC				O/C				
322786	Main Landing Gear Knee Joint Retention Pin (Right) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	C1M5426CA001	CFN0067	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe	[End Of Month Item]									
Notes: MRI PARENT CODE: 322784											
322787	Main Landing Gear Knee Joint Retention Pin (Right) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C1M5426CA001	CFN0067	MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 322784											
322788	Cylinder Machining (Left) - Removal / Installation		HRS		3522.4			0			0
	C1M5605CA002	PLT0115	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe										O/C
322790	Main Landing Gear Side Brace Actuator Cylinder Machining (Left) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	C1M5210CA001	GK0208	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe	[End Of Month Item]									
Notes: MRI PARENT CODE: 321202											
322791	Main Landing Gear Side Brace Actuator Cylinder Machining (Left) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C1M5605CA001	GK0208	MOS		128.2			21 Apr 2014			
	Airframe										
Notes: MRI PARENT CODE: 321202											
322792	Cylinder Machining (Right) - Removal / Installation		HRS		3522.4			0			0
	C1M5605CA002	SPP000167	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe										O/C

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322794	Main Landing Gear Side Brace Actuator Cylinder		HRS		3522.4			0			0
	Machining (Right) - Restore		AFL		727		10000	0	10000		0
	C1M5210CA001	GK0205	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 321203											
322795	Main Landing Gear Side Brace Actuator Cylinder		HRS		3522.4			0			0
	Machining (Right) - Discard		AFL		727		20000	0	20000		0
	C1M5605CA001	GK0205	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 321203											
322796	Piston Machining (Left) - Removal / Installation		HRS		3522.4			0			0
	C1M5651CA002	PLT0113	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322798	Main Landing Gear Side Brace Actuator Piston Machining		HRS		3522.4			0			0
	(Left) - Restore		AFL		727		10000	0	10000		0
	C1M5651CA002	PLT0113	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 322796											
322799	Main Landing Gear Side Brace Actuator Piston Machining		HRS		3522.4			0			0
	(Left) - Discard		AFL		727		20000	0	20000		0
	C1M5651CA002	PLT0113	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322796											
322800	Piston Machining (Right) - Removal / Installation		HRS		3522.4			0			0
	C1M5651CA002	SPP000146	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322802	Main Landing Gear Side Brace Actuator Piston Machining		HRS		3522.4			0			0
	(Right) - Restore		AFL		727		10000	0	10000		0
	C1M5651CA002	SPP000146	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 322800											
322803	Main Landing Gear Side Brace Actuator Piston Machining		HRS		3522.4			0			0
	(Right) - Discard		AFL		727		20000	0	20000		0
	C1M5651CA002	SPP000146	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322800											
322804	Lock Spool (Left) - Removal / Installation		HRS		3522.4			0			0
	C1M5654CA001	PLT320169	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322806	Main Landing Gear Side Brace Actuator Lock Spool (Left)		HRS		3522.4			0			0
	- Restore		AFL		727		10000	0	10000		0
	C1M5654CA001	PLT320169	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 322804											
322807	Main Landing Gear Side Brace Actuator Lock Spool (Left)		HRS		3522.4			0			0
	- Discard		AFL		727		20000	0	20000		0
	C1M5654CA001	PLT320169	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322804											
322808	Lock Spool (Right) - Removal / Installation		HRS		3522.4			0			0
	C1M5654CA001	KS0161	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322810	Main Landing Gear Side Brace Actuator Lock Spool		HRS		3522.4			0			0
	(Right) - Restore		AFL		727		10000	0	10000		0
	C1M5654CA001	KS0161	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											
Notes: MRI PARENT CODE: 322808											
322811	Main Landing Gear Side Brace Actuator Lock Spool		HRS		3522.4			0			0
	(Right) - Discard		AFL		727		20000	0	20000		0
	C1M5654CA001	KS0161	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322808											
322812	Main Landing Gear Side Brace Actuator Locking		HRS		3522.4			0			0
	Segments (Left) (#1) - Removal / Installation		AFL		727			0			0
	C1M5655CA002	PLT10012	MOS		128.2			21 Apr 2014			
MSC											
O/C											
Airframe											
322814	Main Landing Gear Side Brace Actuator Locking		HRS		3522.4			0			0
	Segments (Left) - Restore		AFL		727		10000	0	10000		0
	C1M5655CA002	PLT10012	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											
Notes: MRI PARENT CODE: 322812											
322815	Main Landing Gear Side Brace Actuator Locking		HRS		3522.4			0			0
	Segments (Left) - Discard		AFL		727		20000	0	20000		0
	C1M5655CA002	PLT10012	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322812											
322816	Main Landing Gear Side Brace Actuator Locking		HRS		3522.4			0			0
	Segments (Right) (#1) - Removal / Installation		AFL		727			0			0
	C1M5655CA002	BCI000211	MOS		128.2			21 Apr 2014			
MSC											
O/C											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322818	Main Landing Gear Side Brace Actuator Locking		HRS		3522.4			0			0
	Segments (Right) - Restore		AFL		727		10000	0	10000		0
	C1M5655CA002	BCI000211	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 322816											
322819	Main Landing Gear Side Brace Actuator Locking		HRS		3522.4			0			0
	Segments (Right) - Discard		AFL		727		20000	0	20000		0
	C1M5655CA002	BCI000211	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322816											
322820	Gland, Cylinder (Left) - Removal / Installation		HRS		3522.4			0			0
	C1M5602CA002	PLT410045	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322822	Main Landing Gear Side Brace Actuator Cylinder Gland		HRS		3522.4			0			0
	(Left) - Restore		AFL		727		10000	0	10000		0
	C1M5602CA002	PLT410045	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
Notes: MRI PARENT CODE: 322820											
322823	Main Landing Gear Side Brace Actuator Cylinder Gland		HRS		3522.4			0			0
	(Left) - Discard		AFL		727		20000	0	20000		0
	C1M5602CA002	PLT410045	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322820											
322824	Gland, Cylinder (Right) - Removal / Installation		HRS		3522.4			0			0
	C1M5602CA002	SPP300092	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322826	Main Landing Gear Side Brace Actuator Cylinder Gland		HRS		3522.4			0			0
	(Right) - Restore		AFL		727		10000	0	10000		0
	C1M5602CA002	SPP300092	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	[End Of Month Item]										
Airframe											
Notes: MRI PARENT CODE: 322824											
322827	Main Landing Gear Side Brace Actuator Cylinder Gland		HRS		3522.4			0			0
	(Right) - Discard		AFL		727		20000	0	20000		0
	C1M5602CA002	SPP300092	MOS		128.2			21 Apr 2014			
	[End Of Month Item]										
Airframe											
Notes: MRI PARENT CODE: 322824											
322828	ROD End Machining (Left) - Removal / Installation		HRS		3522.4			0			0
	C1M5670CA001	PLT0120	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322830	Main Landing Gear Side Brace Actuator ROD End		HRS		3522.4			0			0
	Machining (Left) - Restore		AFL		727		10000	0	10000		0
	C1M5670CA001	PLT0120	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	[End Of Month Item]										
Airframe											
Notes: MRI PARENT CODE: 322828											
322831	Main Landing Gear Side Brace Actuator ROD End		HRS		3522.4			0			0
	Machining (Left) - Discard		AFL		727		20000	0	20000		0
	C1M5670CA001	PLT0120	MOS		128.2			21 Apr 2014			
	[End Of Month Item]										
Airframe											
Notes: MRI PARENT CODE: 322828											
322832	ROD End Machining (Right) - Removal / Installation		HRS		3522.4			0			0
	C1M5670CA001	SPP000151	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322834	Main Landing Gear Side Brace Actuator ROD End		HRS		3522.4			0			0
	Machining (Right) - Restore		AFL		727		10000	0	10000		0
	C1M5670CA001	SPP000151	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
[End Of Month Item]											
Airframe											
Notes: MRI PARENT CODE: 322832											
322835	Main Landing Gear Side Brace Actuator ROD End		HRS		3522.4			0			0
	Machining (Right) - Discard		AFL		727		20000	0	20000		0
	C1M5670CA001	SPP000151	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 322832											
322836	Nose Landing Gear Door Control Rods (Left) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P5200902Z070	NSN	MOS		128.2			21 Apr 2014			
O/C											
Airframe											
322837	Nose Landing Gear Door Control Rods (Right) - Removal		HRS		3522.4			0			0
	/ Installation		AFL		727			0			0
	60P5200902Z070	NSN	MOS		128.2			21 Apr 2014			
O/C											
Airframe											
322840	Nose Landing Gear Door Hinges (Left Forward) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P5280111A019	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
O/C											
Airframe											
322841	Nose Landing Gear Door Hinges (Right Forward) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P5280121A017	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
O/C											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322842	Nose Landing Gear Door Hinges (Left Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5280111A013	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
322843	Nose Landing Gear Door Hinges (Right Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5280121A012	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323000	Main Landing Gear Control Manifold - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3230031Z005	0143	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323001	Landing Gear Control Unit - Removal / Installation		HRS		1508.2			2014.2			0
			AFL		311			416			0
	60P3230090Z002	016LG01088C	MOS	TSN:2	63.3			18 Sep 2019			N/A
			MSC				O/C				
Airframe											
Notes: COMPLIED WITH CMP G650 323001 AIRFRAME LANDING GEAR CONTROL UNIT - REMOVAL / INSTALLATION OFF: P/N 60P3230090Z002 (MOD C) S/N 016LG01053 ON: P/N 60P3230090Z002 (MOD D) S/N 016LG01088C											
323015	Main Landing Gear Post Machining (Left) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
323016	Main Landing Gear Post Machining (Right) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
323200	Main Landing Gear Door Actuator (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5280901Z004	0201	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323201	Main Landing Gear Door Actuator (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5280901Z004	0202	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323204	Main Landing Gear Uplock Roller Corrosion Inhibiting Compound Application - Servicing		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4			13 Oct 2022			
			MSC				O/C				
Airframe											
323205	Main Landing Gear Uplock Roller (Left) - Removal / Installation		HRS		1841.9			1680.5			0
			AFL		384			343			0
	C1A5331CA001	EXC0925	MOS	TSN:8	74			27 Oct 2018			N/A
			MSC				O/C				
Airframe											
323206	Main Landing Gear Uplock Roller (Right) - Removal / Installation		HRS		.4			3522			0
			AFL		1			726			0
	C1A5331CA001	EXC0501	MOS		2.7			05 Oct 2024			N/A
			MSC				O/C				
Airframe											
323209	Main Landing Gear Door Actuator (Left) - Discard		HRS		3522.4			0			0
	60P5280901Z004		AFL		727			0			0
		0201	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 323200											
323210	Main Landing Gear Door Actuator (Right) - Discard		HRS		3522.4			0			0
	60P5280901Z004		AFL		727			0			0
		0202	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 323201											
323300	Main Landing Gear Uplock Hook / Latch Assembly (Left) - Removal / Installation		HRS		3522.4			0			0
	60P3232030Z005		AFL		727			0			0
		PLT0139	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323301	Main Landing Gear Uplock Hook / Latch Assembly (Right)		HRS		3522.4			0			0
	- Removal / Installation		AFL		727			0			0
	60P3232031Z005	PLT0089	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323304	Main Landing Gear Uplock Hook / Latch Assembly		HRS		485.9			3036.5			0
	Corrosion Inhibiting Compound Application - Servicing		AFL		97			630			0
			MOS		25.9			28 Oct 2022			
			MSC				O/C				
Airframe											
323305	Main Landing Gear Uplock Hook / Latch Assembly (Left) -		HRS		3522.4			0			0
	Discard		AFL		727			0			0
	60P3232030Z005	PLT0139	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323306	Main Landing Gear Uplock Hook / Latch Assembly (Right)		HRS		3522.4			0			0
	- Discard		AFL		727			0			0
	60P3232031Z005	PLT0089	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323600	Nose Landing Gear Control Manifold - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P3230030Z005	0151	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323602	Nose Landing Gear Door Actuator - Removal / Installation		HRS		3522.4			0			0
	60P5280902Z004	0125	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323700	Nose Landing Gear Uplock Hook and Latch Assembly -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P3237010Z003	PLT0101	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323702	Nose Landing Gear Uplock Roller - Removal / Installation		HRS		3522.4			0			0
	C2M5244CA001 NSN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
323800	Nose Landing Gear Downlock Actuator - Removal / Installation		HRS		3522.4			0			0
	C2A4650CA002 PLT0214		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
323801	Nose Landing Gear Actuator - Removal / Installation		HRS		3522.4			0			0
	60P3238010Z002 0116		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
323810	Nose Landing Gear Retraction Actuator Attach Pin - Restore		HRS		3522.4			0			0
	PN SN-UNKNOWN		AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
	Airframe		[End Of Month Item]								
323811	Nose Landing Gear Retraction Actuator Attach Pin - Discard		HRS		3522.4			0			0
	C2M5311CA001 PLT420023		AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
323813	Nose Landing Gear Downlock Spring (Left) - Removal / Installation		HRS	TSN:3522	.4			3522			0
	C2E5441RA001 UN-KNOWN		AFL	TSN:726	1			726			0
			MOS	TSN:125	3.2			21 Sep 2024			N/A
	Airframe		MSC				O/C				
323814	Nose Landing Gear Downlock Spring (Right) - Removal / Installation		HRS	TSN:3522	.4			3522			0
	C2E5441RA001 SN-UNKNOWN		AFL	TSN:726	1			726			0
			MOS	TSN:125	3.2			21 Sep 2024			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323815 ^U	Nose Landing Gear Downlock Spring (Left) - Discard		HRS		3522.4			0			0
	C2E5441LA001	SN-UNKNOWN	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
Notes: Template Code Not Available; User Code Entered as Interim Solution. MDTs System Correction Request Submitted 9/21/24 By Kelly Davis.											
323816	Nose Landing Gear Downlock Spring (Right) - Discard		HRS		3522.4			0			0
	C2E5441RA001	SN-UNKNOWN	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
Airframe											
323817	Nose Landing Gear Downlock Spring (Left) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
Airframe [End Of Month Item]											
323818	Nose Landing Gear Downlock Spring (Right) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727		10000	0	10000		0
			MOS		128.2		192	21 Apr 2014	30 Apr 2030		
Airframe [End Of Month Item]											
323900	Landing Gear Emergency Extension Nitrogen Blow-Down		HRS	TSN:1660.3	485.9			3036.5			0
	Bottle (Left) - Removal / Installation		AFL	TSN:332	97			630			0
	1159SCH233-11	ALT603-13638	MOS	TSN:61	25.3			16 Nov 2022			N/A
Airframe O/C											
323901	Landing Gear Emergency Extension Nitrogen Blow-Down		HRS		485.9			3036.5			0
	Bottle (Right) - Removal / Installation		AFL		97			630			0
	1159SCH233-11	ALT603-13630	MOS		25.3			16 Nov 2022			N/A
Airframe O/C											
323904	Landing Gear Emergency Extension Blow-Down Bottle		HRS		3522.4			0			0
	Transducer - Removal / Installation		AFL		727			0			0
	60P2930061Z001	59308	MOS		128.2			21 Apr 2014			
Airframe O/C											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323905	Landing Gear Blow-Down Bottle AIR Release Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3239029Z004	0017	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323906	Landing Gear Blow-Down Bottle Pressure Gage - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GP20-36	13-102830	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323910	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Left) - Discard		HRS		3522.4			0			0
			AFL		727			0			0
	1159SCH233-11	ALT603-11895	MOS		128.2		180	21 Apr 2014	31 Aug 2028		
			[End Of Month Item]								MANUFACTURE
Airframe											
Notes: MRI PARENT CODE: 323900											
323911	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Right) - Discard		HRS		3522.4			0			0
			AFL		727			0			0
	1159SCH233-11	ALT603-11933	MOS		128.2		180	21 Apr 2014	30 Sep 2028		
			[End Of Month Item]								MANUFACTURE
Airframe											
Notes: MRI PARENT CODE: 323901											
323912	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Left) - (Hydrostatic) Restoration		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.6		60	07 Oct 2021	31 Oct 2026		
			[End Of Month Item]								HYDRO CHECK
Airframe											
Notes: PN: 1159SCH233-11 SN: ALT603-13638.											
323913	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Right) - (Hydrostatic) Restoration		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.6		60	07 Oct 2021	31 Oct 2026		
			[End Of Month Item]								HYDRO CHECK
Airframe											
Notes: PN: 1159SCH233-11 SN: ALT603-13630.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323916	Landing Gear Emergency Extension System - Operational Check		HRS		485.9		1800	3036.5	4836.5	4886.5	0
			AFL		97			630			0
			MOS		25.3		36	17 Nov 2022	30 Nov 2025	31 Dec 2025	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
323917	Landing Gear Emergency Extension System - General Visual Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	25	24	06 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
323918	Landing Gear Emergency Extension T-Handle - Rigging		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323919	Landing Gear Blow-Down Bottle Relief Valve - Removal / Installation 60P3239072Z0060940		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS	TSN:8	25.3			16 Nov 2022			N/A
			MSC				O/C				
Airframe											
Notes: TW# 558063 CAL DUE: 08/18											
323920	Landing Gear Emergency Extension T-Handle Assembly - Removal / Installation 60P3239031Z001207		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
323921	Landing Gear Emergency Extension Cable Assembly - Removal / Installation 60P3239032Z001178		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324100	Nose Wheel (Left) - Removal / Installation 90005587JAN14-0321		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.5			12 Oct 2021			
			MSC				O/C				
Airframe											
Notes: *CMP UPDATE ONLY*TIRE CHANGE IN BACK SHOP.REF SECTION 39 FOR WORK DONE.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324101	Nose Wheel (Right) - Removal / Installation		HRS		873.6			2648.8			0
	90005587	JAN14-0320	AFL		166			561			0
			MOS		38.5			12 Oct 2021			
	Airframe		MSC				O/C				
Notes: *CMP UPDATE ONLY*TIRE CHANGE IN BACK SHOP.REF SECTION 38 FOR WORK DONE.											
324102	Nose Wheel and Tire Assembly (Left) - Removal / Installation		HRS		0			3522.4			0
			AFL		0			727			0
	60P3241101A001	MAR13-0206	MOS		2.3			17 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: TW: 553005 DUE: 10/19											
324103	Nose Wheel and Tire Assembly (Right) - Removal / Installation		HRS		0			3522.4			0
			AFL		0			727			0
	60P3241101A001	DEC12-0184	MOS		2.3			17 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: TW: 553005 DUE: 10/19											
324106	Nose Tire (Left) - Removal / Installation		HRS		.4			3522			0
	217K42-1	41560912	AFL		1			726			0
			MOS	TSN:3	2.6			08 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: *CMP UPDATE ONLY*TIRE CHANGE IN BACK SHOP.REF SECTION 39 FOR WORK DONE											
324107	Nose Tire (Right) - Removal / Installation		HRS		.4			3522			0
	217K42-1	41540918	AFL		1			726			0
			MOS	TSN:3	2.6			08 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: *CMP UPDATE ONLY*TIRE CHANGE IN BACK SHOP.REF SECTION 38 FOR WORK DONE.											
324108	Nose Wheel Axle Nut (Left) - Removal / Installation		HRS		3522.4			0			0
	C2M5248CA001	PLT241246	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324109	Nose Wheel Axle Nut (Right) - Removal / Installation		HRS		3522.4			0			0
	C2M5248CA001	PLT241266	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324115	Nose Tire Assembly - Check		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
324116	Nose Wheel Bearing (Left) - Inspection / Grease		HRS		0			3522.4			0
			AFL		0		727		0		
			MOS		2.3		17 Oct 2024				
			MSC			O/C					
Airframe											
324117	Nose Wheel Bearing (Right) - Inspection / Grease		HRS		0			3522.4			0
			AFL		0		727		0		
			MOS		2.3		17 Oct 2024				
			MSC			O/C					
Airframe											
324120	Nose Wheel (Left) - Special Detailed Inspection (Ndt)		HRS		.4			3522			0
			AFL		1		726		0		
			MOS		2.6		08 Oct 2024				
			MSC			O/C					
Airframe											
Notes: PREVIOUSLY COMPLIED WITH ON SC 613386 ITEM 25.1											
324121	Nose Wheel (Right) - Special Detailed Inspection (Ndt)		HRS		.4			3522			0
			AFL		1		726		0		
			MOS		2.6		08 Oct 2024				
			MSC			O/C					
Airframe											
Notes: PREVIOUSLY COMPLIED WITH ON SC 613386 ITEM 24.1											
324122	Nose Wheel (Left) - Restore PN SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe	[End Of Month Item]										
324123	Nose Wheel (Right) - Restore PN SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324200	Main Wheel (Left Inboard) - Removal / Installation		HRS		.4			3522			0
	90005586-1	JUN14-0653	AFL		1			726			0
			MOS		2.7			04 Oct 2024			
	Airframe		MSC				O/C				
Notes: TORQUE WRENCHES USED:554255 DUE 08/19554677 DUE 10/19553268 DUE 11/19571404 DUE 11/18											
324201	Main Wheel (Left Outboard) - Removal / Installation		HRS		.4			3522			0
	90005586-1	FEB17-1614	AFL		1			726			0
			MOS		2.7			05 Oct 2024			
	Airframe		MSC				O/C				
Notes: TORQUE WRENCHES USED:554255 DUE 08/19554677 DUE 10/19553268 DUE 11/19571404 DUE 11/18											
324202	Main Wheel (Right Inboard) - Removal / Installation		HRS		.4			3522			0
	90005586-1	NOV14-0769	AFL		1			726			0
			MOS		2.7			05 Oct 2024			
	Airframe		MSC				O/C				
Notes: TORQUE WRENCHES USED:554255 DUE 08/19554677 DUE 10/19553268 DUE 11/19571404 DUE 11/18											
324203	Main Wheel (Right Outboard) - Removal / Installation		HRS		.4			3522			0
	90005586-1	MAY12-0226	AFL		1			726			0
			MOS		2.7			05 Oct 2024			
	Airframe		MSC				O/C				
Notes: TORQUE WRENCHES USED:554255 DUE 08/19554677 DUE 10/19553268 DUE 11/19571404 DUE 11/18											
324204	Main Tire (Left Inboard) - Removal / Installation		HRS		.4			3522			0
	379Q02-2	41540347	AFL		1			726			0
			MOS	TSN:3	2.7			05 Oct 2024			
	Airframe		MSC				O/C				
324205	Main Tire (Left Outboard) - Removal / Installation		HRS		.4			3522			0
	379Q02-2	42271296	AFL		1			726			0
			MOS	TSN:1	2.7			05 Oct 2024			
	Airframe		MSC				O/C				
324206	Main Tire (Right Inboard) - Removal / Installation		HRS		.4			3522			0
	379Q02-2	42261300	AFL		1			726			0
			MOS	TSN:1	2.7			05 Oct 2024			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324207	Main Tire (Right Outboard) - Removal / Installation		HRS		.4			3522			0
	379Q02-2	42271297	AFL		1			726			0
			MOS	TSN:1	2.7			05 Oct 2024			
	Airframe		MSC				O/C				
324208	Main Wheel CAP (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
	60P3247030Z001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324209	Main Wheel CAP (Left Outboard) - Removal / Installation		HRS		3522.4			0			0
	60P3247030Z001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324210	Main Wheel CAP (Right Inboard) - Removal / Installation		HRS		3278			244.4			0
	60P3247030Z001	SEP12-0420	AFL		680			47			0
			MOS		115.7			03 May 2015			
	Airframe		MSC				O/C				
324211	Main Wheel CAP (Right Outboard) - Removal / Installation		HRS		3522.4			0			0
	60P3247030Z001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324213	Main Wheel and Tire Assembly (Left Inboard) - Removal / Installation		HRS		.4			3522			0
	60P3242101A005	JUN14-0653	AFL		1			726			0
			MOS		2.6			06 Oct 2024			N/A
	Airframe		MSC				O/C				
324214	Main Wheel and Tire Assembly (Left Outboard) - Removal / Installation		HRS		.4			3522			0
	60P3242101A005	FEB17-1614	AFL		1			726			0
			MOS		2.6			06 Oct 2024			N/A
	Airframe		MSC				O/C				
324215	Main Wheel and Tire Assembly (Right Inboard) - Removal / Installation		HRS		.4			3522			0
	60P3242101A005	NOV14-0769	AFL		1			726			0
			MOS		2.6			06 Oct 2024			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324216	Main Wheel and Tire Assembly (Right Outboard) -		HRS		.4			3522			0
	Removal / Installation		AFL		1			726			0
	60P3242101A005	MAY12-0226	MOS		2.6			06 Oct 2024			N/A
			MSC				O/C				
Airframe											
324221	Main Landing Gear Wheel Bearing (Left Inboard) -		HRS		.4			3522			0
	Inspection / Grease		AFL		1			726			0
			MOS		2.7			04 Oct 2024			
			MSC				O/C				
Airframe											
324222	Main Landing Gear Wheel Bearing (Left Outboard) -		HRS		.4			3522			0
	Inspection / Grease		AFL		1			726			0
			MOS		2.7			04 Oct 2024			
			MSC				O/C				
Airframe											
324223	Main Landing Gear Wheel Bearing (Right Inboard) -		HRS		.4			3522			0
	Inspection / Grease		AFL		1			726			0
			MOS		2.7			04 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: PN: 42690H-20629 SN: NSN.											
324224	Main Landing Gear Wheel Bearing (Right Outboard) -		HRS		.4			3522			0
	Inspection / Grease		AFL		1			726			0
			MOS		2.7			04 Oct 2024			
			MSC				O/C				
Airframe											
324225	Main Wheel (Left Inboard) - Special Detailed Inspection		HRS		.4			3522			0
	(Ndt)		AFL		1			726			0
			MOS		2.7			04 Oct 2024			
			MSC				O/C				
Airframe											
Notes: PREVIOUSLY COMPLIED WITH ON SC 613386 ITEM 29.1											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324226	Main Wheel (Left Outboard) - Special Detailed Inspection (Ndt)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7			05 Oct 2024			
			MSC				O/C				
Airframe											
Notes: PREVIOUSLY COMPLIED WITH ON SC 613386 ITEM 30.1											
324227	Main Wheel (Right Inboard) - Special Detailed Inspection (Ndt)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7			05 Oct 2024			
			MSC				O/C				
Airframe											
Notes: COMPLIED WITH ON SC 613386 ITEM 32.1											
324228	Main Wheel (Right Outboard) - Special Detailed Inspection (Ndt)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7			05 Oct 2024			
			MSC				O/C				
Airframe											
Notes: COMPLIED WITH ON SC 613386 ITEM 32.1											
324231	Weight on Wheels Harness (Left Outboard) - Removal / Installation C1E5901CA004ICO00251		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324232	Weight on Wheels Harness (Left Inboard) - Removal / Installation C1E5902CA004ICO00253		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324233	Weight on Wheels Harness (Right Inboard) - Removal / Installation C1E5902CA004ICO00257		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324234	Weight on Wheels Harness (Right Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	C1E5901CA004	ICO00252	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324235	Main Wheel (Left Outboard) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
[End Of Month Item]											
324236	Main Wheel (Left Inboard) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
[End Of Month Item]											
324237	Main Wheel (Right Inboard) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
[End Of Month Item]											
324238	Main Wheel (Right Outboard) - Restore		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
[End Of Month Item]											
324300	Brake Assembly (Left Inboard) - Removal / Installation		HRS		.4			3522			0
	90005585-4	DEC13-0465	AFL		1			726			0
			MOS		2.6			06 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: TORQUE WRENCHES USED:554255 DUE 08/19554677 DUE 10/19553268 DUE 11/19571404 DUE 11/18											
324301	Brake Assembly (Left Outboard) - Removal / Installation		HRS	TSN:2166	.4			3522			0
	90005585-4	DEC13-0464	AFL	TSN:439	1			726			0
			MOS	TSN:71	2.6			06 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: TORQUE WRENCHES USED:554255 DUE 08/19554677 DUE 10/19553268 DUE 11/19571404 DUE 11/18											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324302	Brake Assembly (Right Inboard) - Removal / Installation		HRS	TSN:2166	.4			3522			0
	90005585-4 DEC13-0454		AFL	TSN:439	1			726			0
			MOS	TSN:71	2.6			06 Oct 2024			N/A
	Airframe		MSC					O/C			
Notes: TORQUE WRENCHES USED:554255 DUE 08/19554677 DUE 10/19553268 DUE 11/19571404 DUE 11/18											
324303	Brake Assembly (Right Outboard) - Removal / Installation		HRS	TSN:2166	.4			3522			0
	90005585-4 DEC13-0455		AFL	TSN:439	1			726			0
			MOS	TSN:71	2.6			06 Oct 2024			N/A
	Airframe		MSC					O/C			
Notes: TORQUE WRENCHES USED:554255 DUE 08/19554677 DUE 10/19553268 DUE 11/19571404 DUE 11/18											
324304	Brake Wear Indicators (Left Outboard) - Detailed		HRS		.4		750	3522	4272	4322	0
	Inspection		AFL		1			726			0
			MOS		2.6			06 Oct 2024			
	Airframe		[HRS: +50/-50]								
324305	Brake Wear Indicators (Left Inboard) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.6			06 Oct 2024			
	Airframe		[HRS: +50/-50]								
324306	Brake Wear Indicators (Right Inboard) - Detailed		HRS		.4		750	3522	4272	4322	0
	Inspection		AFL		1			726			0
			MOS		2.6			06 Oct 2024			
	Airframe		[HRS: +50/-50]								
324307	Brake Wear Indicators (Right Outboard) - Detailed		HRS		.4		750	3522	4272	4322	0
	Inspection		AFL		1			726			0
			MOS		2.6			06 Oct 2024			
	Airframe		[HRS: +50/-50]								
324308	Brake Assembly Torque Pin (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	C1M5420CA001 EXC0204		AFL	TSN:630	97			630			0
			MOS	TSN:101	26.5			12 Oct 2022			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324309	Brake Assembly Torque Pin (Right) - Removal / Installation		HRS	TSN:3522	.4			3522			0
			AFL	TSN:726	1			726			0
	C1M5420CA001	EXC0203	MOS	TSN:124	2.7			05 Oct 2024			N/A
			MSC				O/C				
Airframe											
324310	Main Landing Gear Brake Torque Takeout Pin (Left) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
324311	Main Landing Gear Brake Torque Takeout Pin (Right) - Restore		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
	PN	SN-UNKNOWN	MOS		128.2		192	21 Apr 2014	30 Apr 2030		
			[End Of Month Item]								
Airframe											
324312	Main Landing Gear Brake Torque Takeout Pin (Left) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C1M5420CA001	EXC0204	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 324308											
324313	Main Landing Gear Brake Torque Takeout Pin (Right) - Discard		HRS		3522.4			0			0
			AFL		727		20000	0	20000		0
	C1M5420CA001	EXC0203	MOS		128.2			21 Apr 2014			
Airframe											
Notes: MRI PARENT CODE: 324309											
324314	Brake Inlet SELF-Sealing Couplings RE-Torque (Left Inboard) - Restore		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				O/C				
Airframe											
Notes: TW ID# 558063, DUE 08/17.ASC 084 C/W											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324315	Brake Inlet SELF-Sealing Couplings RE-Torque (Left Outboard) - Restore		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.2			20 Sep 2016			
			MSC			O/C					
Airframe											
Notes: TW ID# 558063, DUE 08/17.ASC 084 C/W											
324316	Brake Inlet SELF-Sealing Couplings RE-Torque (Right Inboard) - Restore		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.2			20 Sep 2016			
			MSC			O/C					
Airframe											
Notes: TW ID# 558063, DUE 08/17.ASC 084 C/W											
324317	Brake Inlet SELF-Sealing Couplings RE-Torque (Right Outboard) - Restore		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.2			20 Sep 2016			
			MSC			O/C					
Airframe											
Notes: TW ID# 558063, DUE 08/17.ASC 084 C/W											
324320	Main Wheel Brakes (Left Inboard) - Operational Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
324321	Main Wheel Brakes (Left Outboard) - Operational Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
324322	Main Wheel Brakes (Right Inboard) - Operational Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
324323	Main Wheel Brakes (Right Outboard) - Operational Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324400	Brake Shuttle Valve (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
	60P3244030Z002	APR13-0426	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324401	Brake Shuttle Valve (Left Outboard) - Removal / Installation		HRS		3522.4			0			0
	60P3244030Z002	APR13-0432	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324402	Brake Shuttle Valve (Right Inboard) - Removal / Installation		HRS		3522.4			0			0
	60P3244030Z002	MAY13-0460	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324403	Brake Shuttle Valve (Right Outboard) - Removal / Installation		HRS		3522.4			0			0
	60P3244030Z002	MAY13-0469	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324404	Brake Shut-Off Valve (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
	60P3244070Z001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324405	Brake Shut-Off Valve (Right Outboard) - Removal / Installation		HRS		3509.1			13.3			0
	60P3244070Z002	JUL13-0136	AFL		722			5			0
			MOS		125.3			18 Jul 2014			
	Airframe		MSC				O/C				
324410	Brake Control Valve (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
	60P3244110Z001	13-10-0427	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324411	Brake Control Valve (Right Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244110Z001	13-12-0463	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324412	Brake Control Valve (Left Outboard) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	60P3244110Z001	14-04-0527	MOS		125.3			18 Jul 2014			
			MSC				O/C				
Airframe											
324413	Brake Control Valve (Right Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244110Z001	13-08-0407	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324420	Brake Control Unit - Removal / Installation		HRS	TSN:1209.9	2312.5			1209.9			0
	60P3244090Z003	DEC11-0032	AFL	TSN:248	479			248			0
		-	MOS	TSN:41	87.1			24 Sep 2017			
			MSC				O/C				
Airframe											
324422	Brake Pedal Position Transducer (Pilot Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244010Z004	JUN13-0577	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324423	Brake Pedal Position Transducer (Copilot Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244010Z004	JUN13-0582	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324424	Brake Pedal Position Transducer (Pilot Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244010Z004	MAY13-0572	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324425	Brake Pedal Position Transducer (Copilot Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244010Z004	JUL13-0591	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324431	Brake Pedal Position Transducer - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-4	96	27 Oct 2022	31 Oct 2030*	30 Nov 2030	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
324432	Main Wheel Brakes - Functional Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6			06 Oct 2024			
			MSC				O/C				
Airframe											
324433	Antiskid - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6			06 Oct 2024			
			MSC				O/C				
Airframe											
324434	Wheel Despin - Operational Check		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				O/C				
Airframe											
324435	Autobrakes - Operational Check		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				O/C				
Airframe											
324500	Nose Static Interface Unit (Left) - Removal / Installation		HRS	TSN:3522.4	0			3522.4			0
	60P3247090Z001 JUL13-0315		AFL	TSN:727	0			727			0
			MOS	TSN:125	2.3			17 Oct 2024			N/A
			MSC				O/C				
Airframe											
324501	Nose Static Interface Unit (Right) - Removal / Installation		HRS		0			3522.4			0
	60P3247090Z001 MAY13-0300		AFL		0			727			0
			MOS		2.3			17 Oct 2024			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324504	Combined Wheel Static Interface Unit (Left Inboard) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	60P3247070Z003	OCT13-0490	MOS	TSN:102	25.8			02 Nov 2022			N/A
			MSC				O/C				
Airframe											
324505	Combined Wheel Static Interface Unit (Left Outboard) - Removal / Installation		HRS	TSN:387.7	485.9			3036.5			0
			AFL	TSN:69	97			630			0
	60P3247070Z003	NOV16-2271	MOS	TSN:68	25.8			01 Nov 2022			N/A
			MSC				O/C				
Airframe											
324506	Combined Wheel Static Interface Unit (Right Inboard) - Removal / Installation		HRS	TSN:2166	.4			3522			0
			AFL	TSN:439	1			726			0
	60P3247070Z003	OCT13-0487	MOS	TSN:71	2.6			06 Oct 2024			N/A
			MSC				O/C				
Airframe											
324507	Combined Wheel Static Interface Unit (Right Outboard) - Removal / Installation		HRS	TSN:2166	.4			3522			0
			AFL	TSN:439	1			726			0
	60P3247070Z003	OCT13-0488	MOS	TSN:71	2.6			06 Oct 2024			N/A
			MSC				O/C				
Airframe											
324600	Brake System Hydraulic Fuse (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244130Z001	MAR 11-0072	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324601	Brake System Hydraulic Fuse (Left Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244130Z001	MAY13-0431	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324602	Brake System Hydraulic Fuse (Right Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244130Z001	JAN13-0335	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324603	Brake System Hydraulic Fuse (Right Outboard) - Removal		HRS		3522.4			0			0
	/ Installation		AFL		727			0			0
	60P3244130Z001	JAN13-0334	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324607	Brake Control System Hydraulic Fuse (Left, Outboard No. 1) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6		125	06 Oct 2024	31 Mar 2035	30 Apr 2035	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
324608	Brake System Hydraulic Fuse - Functional Check		HRS		1841.9			1680.5			0
			AFL		384			343			0
			MOS		73.9			30 Oct 2018			
			MSC				O/C				
Airframe											
324609	Parking Brake Accumulator Pressure Indicator - Removal		HRS		3522.4			0			0
	/ Installation		AFL		727			0			0
	60P2512201Z005	105	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324610	Brake Control System Hydraulic Fuse (Left, Inboard No. 2) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6		125	06 Oct 2024	31 Mar 2035	30 Apr 2035	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
324611	Brake Control System Hydraulic Fuse (Right, Inboard No. 3) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6		125	06 Oct 2024	31 Mar 2035	30 Apr 2035	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
324612	Brake Control System Hydraulic Fuse (Right, Outboard No. 4) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6		125	06 Oct 2024	31 Mar 2035	30 Apr 2035	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324700	Tire Pressure Monitor Unit - Removal / Installation		HRS		2312.5			1209.9			0
	60P3247010Z005	OCT13-0378	AFL		479			248			0
			MOS		87.3			17 Sep 2017			
	Airframe		MSC				O/C				
324701	Tire Pressure Monitor System - Functional Check		HRS		0			3522.4			0
			AFL		0			727			0
			MOS		2.3		24	17 Oct 2024	31 Oct 2026	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
324703	Brake System Temperature Indication - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6			06 Oct 2024			
	Airframe		MSC				O/C				
324704	Inboard Brake Pressure Transducer (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244150Z002	AUG13-0453	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324705	Inboard Brake Pressure Transducer (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244150Z002	AUG13-0441	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324706	Outboard Brake Pressure Transducer (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244150Z002	AUG13-0440	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
324707	Outboard Brake Pressure Transducer (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244150Z002	SEP13-0470	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324712	Parking Brake Pressure Transducer (Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2930061Z001	59466	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324713	Parking Brake Pressure Transducer (Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2930061Z001	59465	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324716	Parking Brake Accumulator Pressure Transducer (Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2930061Z001	59395	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324717	Parking Brake Accumulator Pressure Transducer (Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P2930061Z001	59732	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324800	Parking Brake Accumulator Thermal Relief / Dump Valve (Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244050Z001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324801	Parking Brake Accumulator Thermal Relief / Dump Valve (Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3244050Z001	0166	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324807	Parking Brake Handle / Cable Assembly - Rigging / Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324808	Parking Brake Control Handle Assembly - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3248023Z003	208	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324810	Hydraulic Repeater Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3248030Z003	FEB13-0116	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324814	Parking Brake Cable Assembly - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3248022Z002	185	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324815	Parking Brake Control Valve - Removal / Installation		HRS		3506.4			16			0
			AFL		721			6			0
	60P3248010Z003	JAN14-0124	MOS		122.4			13 Oct 2014			
			MSC				O/C				
Airframe											
324816	Parking Brake Accumulator (Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	90008132	OCT13-0224	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324817	Parking Brake Accumulator (Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	90008132	NOV13-0229	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324820	Parking Brake Accumulator Filler Gage (Inboard)- Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GP20-36	13-09067	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324821	Parking Brake Accumulator Filler Gage (Outboard)-		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	GP20-36	13-090611	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324824	Parking Brake - Operational Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.3			17 Nov 2022			
			MSC				O/C				
Airframe											
324825	Accumulator Pressure Transducer (Left) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P2930061Z001	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324900	Brake System Temperature Sensor (Left Inboard) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	6007300	SEP13-7179	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324901	Brake System Temperature Sensor (Left Outboard) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	6007300	AUG13-7123	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324902	Brake System Temperature Sensor (Right Inboard) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	6007300	FEB13-6828	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
324903	Brake System Temperature Sensor (Right Outboard) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	6007300	FEB13-6847	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324908	Nose Rotating Sensing Assembly (Left) - Removal / Installation		HRS		.4			3522			0
			AFL		1			726			0
	60P3247050Z002	MAY13-0496	MOS		2.6			08 Oct 2024			N/A
			MSC				O/C				
Airframe											
324909	Nose Rotating Sensing Assembly (Right) - Removal / Installation		HRS		.4			3522			0
			AFL		1			726			0
	60P3247050Z002	MAY12-0364	MOS		2.6			08 Oct 2024			N/A
			MSC				O/C				
Airframe											
324912	Main Rotating Pressure Sensing Assembly (Left Inboard) - Removal / Installation		HRS	TSN:3521.6	.4			3522			0
			AFL	TSN:725	1			726			0
	60P3247030Z004	SEP13-0619	MOS	TSN:124	2.6			06 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: TORQUE WRENCHES USED:554255 DUE 08/19554677 DUE 10/19553268 DUE 11/19571404 DUE 11/18											
324913	Main Rotating Pressure Sensing Assembly (Left Outboard) - Removal / Installation		HRS	TSN:3521.6	.4			3522			0
			AFL	TSN:725	1			726			0
	60P3247030Z004	NOV13-0654	MOS	TSN:124	2.6			06 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: TORQUE WRENCHES USED:554255 DUE 08/19554677 DUE 10/19553268 DUE 11/19571404 DUE 11/18											
324914	Main Rotating Pressure Sensing Assembly (Right Inboard) - Removal / Installation		HRS		.4			3522			0
			AFL		1			726			0
	60P3247030Z004	SEP12-0420	MOS		2.6			06 Oct 2024			N/A
			MSC				O/C				
Airframe											
Notes: TORQUE WRENCHES USED:554255 DUE 08/19554677 DUE 10/19553268 DUE 11/19571404 DUE 11/18											
324915	Main Rotating Pressure Sensing Assembly (Right Outboard) - Removal / Installation		HRS	TSN:3521.6	.4			3522			0
			AFL	TSN:725	1			726			0
	60P3247030Z004	SEP13-0618	MOS	TSN:124	2.6			06 Oct 2024			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
325000	Nose Wheel Steering - Functional Test		HRS		0			3522.4			0
			AFL		0		727		0		
			MOS		2.3		18 Oct 2024				
			MSC			O/C					
Airframe											
	325001	Nose Wheel Steering - Autorig Test		HRS		0			3522.4		0
				AFL		0		727		0	
				MOS		2.3		18 Oct 2024			
MSC						O/C					
Airframe											
	325100	Nose Wheel Steering Control Unit - Removal / Installation 60P3252010Z0060053		HRS		3396.7			125.7		0
				AFL		702		25		0	
				MOS		120		26 Dec 2014			
MSC						O/C					
Airframe											
	325200	Nose Wheel Steering Actuator - Removal / Installation 72434-60730		HRS	TSN:1	485.9			3036.5		0
				AFL		97	630	0			
				MOS		26.1	24 Oct 2022	EATON			
MSC						O/C					
Airframe											
	325202	Nose Wheel Steering Equipment Assembly - Removal / Installation 72434-5SN-UNKNOWN		HRS		3522.4			0		0
				AFL		727		0		0	
				MOS		128.2		21 Apr 2014			
MSC						O/C					
Airframe											
	325203	Nose Wheel Steering Collar Nut - Discard MS14144L6SN-UNKNOWN		HRS		3522.4			0		0
				AFL		727		0	12000	0	
				MOS		128.2		21 Apr 2014			
Airframe											
	325204	Nose Wheel Steering Collar Bolt - Discard NAS6706DU12SN-UNKNOWN		HRS		3522.4			0		0
				AFL		727		0	12000	0	
				MOS		128.2		21 Apr 2014			
Airframe											
	325205	Steering Equipment Assembly - Removal / Installation C2E4800CA0060122		HRS		3522.4			0		0
				AFL		727		0		0	
				MOS		128.2		21 Apr 2014			
MSC						O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
325207	Steering Equipment Assembly - Restore		HRS		3522.4			0			0
	C2E4800CA006	0122	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: MRI PARENT CODE: 325205											
325210	Oversteer Proximity Sensor - Operational Check		HRS		3522.4			0			0
			AFL		727		10000	0	10000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
325212	Nose Wheel Steering Actuator - Discard		HRS		3522.4			0			0
	C2E4805CA006	SN-UNKNOWN	AFL		727		2500	0	2500		0
			MOS		128.2			21 Apr 2014			
	Airframe										
325213	Nose Wheel Steering Collar Assembly - Discard		HRS		3522.4			0			0
	C2E4810CA006	0122	AFL		727		20000	0	20000		0
			MOS		128.2			21 Apr 2014			
	Airframe										
325401	Steering Unit Motor - Removal / Installation		HRS		3522.4			0			0
	C2E4805CA006	0126	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
326100	Landing Gear Selector Panel - Removal / Installation		HRS		3522.4			0			0
	A486-19	1304	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
326106	Nose Landing Gear Door Sensor - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
326107	Main Landing Gear Door Sensor - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
326120	Nose Landing Gear Door Sensor (Left Open) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006681	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326121	Nose Landing Gear Door Sensor (Left Closed) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006818	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326122	Nose Landing Gear Door Sensor (Right Open) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006828	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326123	Nose Landing Gear Door Sensor (Right Closed) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	007027	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326124	Main Landing Gear Door Sensor (Left Open Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006731	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326125	Main Landing Gear Door Sensor (Left Open Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006728	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326126	Main Landing Gear Door Sensor (Left Closed Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006826	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
326127	Main Landing Gear Door Sensor (Left Closed Aft) - Removal / Installation		HRS		3522.4			0		0	
			AFL		727			0		0	
	60P3261030Z001	006484	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326128	Main Landing Gear Door Sensor (Right Open Forward) - Removal / Installation		HRS		3522.4			0		0	
			AFL		727			0		0	
	60P3261030Z001	006598	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326129	Main Landing Gear Door Sensor (Right Open Aft) - Removal / Installation		HRS		3522.4			0		0	
			AFL		727			0		0	
	60P3261030Z001	006645	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326130	Main Landing Gear Door Sensor (Right Closed Forward) - Removal / Installation		HRS		3522.4			0		0	
			AFL		727			0		0	
	60P3261030Z001	007166	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326131	Main Landing Gear Door Sensor (Right Closed Aft) - Removal / Installation		HRS		3522.4			0		0	
			AFL		727			0		0	
	60P3261030Z001	006819	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326132	Nose Landing Gear Uplock Sensor - Adjustment		HRS		3522.4			0		0	
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326133	Nose Landing Gear Downlock Sensor - Adjustment		HRS		3522.4			0		0	
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
326134	Main Landing Gear Uplock Sensor - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
326135	Main Landing Gear Downlock Sensor - Adjustment		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.8			02 Nov 2022			
	Airframe		MSC				O/C				
326136	Nose Landing Gear Uplock Sensor (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	005239	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
326137	Nose Landing Gear Uplock Sensor (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	005310	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
326140	Nose Landing Gear Downlock Sensor (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006489	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
326141	Nose Landing Gear Downlock Sensor (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006568	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
326144	Main Landing Gear Uplock Sensor (Left Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	005886	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
326145	Main Landing Gear Uplock Sensor (Right Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	005144	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326146	Main Landing Gear Uplock Sensor (Left Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	005881	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326147	Main Landing Gear Uplock Sensor (Right Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	005152	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326152	Main Landing Gear Downlock Sensor (Left Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006673	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326153	Main Landing Gear Downlock Sensor (Right Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	005638	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326154	Main Landing Gear Downlock Sensor (Left Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006679	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326155	Main Landing Gear Downlock Sensor (Right Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	005968	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
326200	Wow System - Functional Test		HRS		0			3522.4			0
			AFL		0			727			0
			MOS		2.3			17 Oct 2024			
	Airframe		MSC				O/C				
326201	Nose Landing Gear Wow Sensor - Adjustment		HRS		0			3522.4			0
			AFL		0			727			0
			MOS		2.3			17 Oct 2024			
	Airframe		MSC				O/C				
326202	Main Landing Gear Wow Sensor - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
326203	Nose Landing Gear Wow Sensor (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261031Z001	3475	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
326204	Nose Landing Gear Wow Sensor (Right) - Removal / Installation		HRS	TSN:3522.4	0			3522.4			0
			AFL	TSN:727	0			727			0
	60P3261031Z001	3477	MOS	TSN:125	2.3			17 Oct 2024			N/A
	Airframe		MSC				O/C				
326207	Main Landing Gear Wow Sensor (Left Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006672	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
326208	Main Landing Gear Wow Sensor (Left Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3261030Z001	006966	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
326209	Main Landing Gear Wow Sensor (Right Inboard) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P3261030Z001	006470	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
326210	Main Landing Gear Wow Sensor (Right Outboard) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P3261030Z001	006467	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
33 - Lights											
331100	Annunciator Dim and Test Controller - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	1159SCAV526-7	1476	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
331102	Annunciator Lights Dim and Test System (Press to Test) -		HRS		3522.4			0			0
	Operational Test		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
331103	Annunciator Lights Dim and Test System (Dimming) -		HRS		3522.4			0			0
	Operational Test		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
331201	Pilot Cockpit Lighting Control Panel - Removal /		HRS	TSN:2364.2	1158			2364.4			0
	Installation		AFL	TSN:487	239			488			0
	60P3110903A012	A0246984201	MOS	TSN:78	50.6			08 Oct 2020			N/A
			MSC				O/C				
Airframe											
331202	Copilot Cockpit Lighting Control Panel - Removal /		HRS	TSN:2364.2	1158			2364.4			0
	Installation		AFL	TSN:487	239			488			0
	60P3110904A012	A023027801	MOS	TSN:78	50.6			08 Oct 2020			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
331205	Side Console Panel Lighting Control - Operational Test		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		122.7		05 Oct 2014				
			MSC			O/C					
Airframe											
331206	Glareshield and Flight Panel Lighting Control - Operational Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014		0		
			MSC			O/C					
Airframe											
331207	Standby Instrument Lighting - Operational Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014		0		
			MSC			O/C					
Airframe											
331216	Dimming Unit (Overhead and Pedestal Lights) - Removal / Installation 110ZT02Y04161		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014		0		
			MSC			O/C					
Airframe											
331217	Dimming Unit (Glareshield and Console) - Removal / Installation 110ZT02Y04226		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014		0		
			MSC			O/C					
Airframe											
331220	Cockpit Side Console Floodlight - Operational Test		HRS		.4			3522			0
			AFL		1		726		0		
			MOS		3		25 Sep 2024				
			MSC			O/C					
Airframe											
331225	MAP Lights - Operational Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014		0		
			MSC			O/C					
Airframe											
331318	Cockpit Dome Light - Operational Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014		0		
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
331336	Cockpit Overhead Panel Lighting - Operational Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
331337	Cockpit Center Pedestal Lighting - Operational Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
331338	Cockpit Circuit Breaker Panel Lighting - Operational Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
331339	Cockpit Overhead Floodlights - Operational Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
332074	Drawer Light, Galley #1 - Removal / Installation GAC-WA02D-00401166942-1-1		HRS		3133.7			388.7			0
			AFL		652			75		0	
			MOS	TSN:1	111.4			15 Sep 2015			
			MSC			O/C					
Airframe											
332100	Airstair Lighting - Operational Test		HRS		.4			3522			0
			AFL		1			726		0	
			MOS		2.6			07 Oct 2024			
			MSC			O/C					
Airframe											
333100	Baggage Compartment Lights - Operational Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
333204	Tail Compartment Lighting - Operational Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
333205	Service Lighting - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
333306	Wheel Well Lights - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334004	Ramp Lights - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334100	Left Wing Kit - Removal / Installation		HRS		3522.4			0			0
	1007-3342N001-001	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334103	Left Wing-Tip Flood / Taxi Light Assembly (Forward Facing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	01-0771125-30	00741	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334104	Right Wing-Tip Flood / Taxi Light Assembly (Forward Facing) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	01-0771125-30	00699	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334105	Left Wing-Tip Flood / Taxi Light Assembly (Wrong Code Do Not Use This Code) - Removal / Installation		HRS		1508.2			2014.2			0
			AFL		311			416			0
	01-0771125-30	02764	MOS	TSN:7	63.2			19 Sep 2019			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334109	Landing Light (Left) - Removal / Installation		HRS		1912.8			1609.6			0
	503H0081-6	GLL00302	AFL		397			330			0
			MOS		75			26 Sep 2018			N/A
	Airframe		MSC				O/C				
Notes: INSTALLED TESTED LIGHT ASSEMBLY											
334110	Landing Light (Right) - Removal / Installation		HRS		3522.4			0			0
	503H0081-6	GLL00512	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334113	Landing Light Ballast (Left) - Removal / Installation		HRS		3522.4			0			0
	503H0200-3	GLB00299	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334114	Landing Light Ballast (Right) - Removal / Installation		HRS	TSN:388.7	3133.7			388.7			0
	503H0200-3	GLB00476	AFL	TSN:75	652			75			0
			MOS	TSN:17	111.3			17 Sep 2015			
	Airframe		MSC				O/C				
334119	Landing Lights - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334120	Landing Lights - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334125	Landing Lights Control Unit - Removal / Installation		HRS		3522.4			0			0
	503H8901-3	GLC 00202	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334127	Nose Wheel Taxi Lights - Operational Test		HRS		0			3522.4			0
			AFL		0			727			0
			MOS		2.3			18 Oct 2024			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334128	Wing-Tip Floodlights / Taxi Lights - Operational Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.6			07 Oct 2022			
			MSC					O/C			
334129	Nose Wheel Taxi Light (Left) - Removal / Installation 01-0790460-00		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC					O/C			
334130	Nose Wheel Taxi Light (Center) - Removal / Installation 01-0790460-00		HRS	TSN:5	0			3522.4			0
			AFL		0			727			0
			MOS		2.3			18 Oct 2024			N/A
			MSC					O/C			
334131	Nose Wheel Taxi Light (Right) - Removal / Installation 01-0790460-00		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC					O/C			
334200	Anticollision Beacon Light - Removal / Installation 01-0771065-02		HRS	TSN:5	3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC					O/C			
334203	Wing Anticollision / Navigation Light (Left) - Removal / Installation		HRS	TSN:903.2 TSN:283	1158			2364.4			0
			AFL		239			488			0
			MOS		50.6			08 Oct 2020			
			MSC					O/C			
334204	Wing Anticollision / Navigation Light (Right) - Removal / Installation		HRS	TSN:17	485.9			3036.5			0
			AFL		97			630			0
			MOS		26.6			06 Oct 2022			N/A
			MSC					O/C			
334207	Wing Anticollision / Navigation Light (Left) - Discard 01-0790453		HRS		3522.4		20000	0	20000		0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334208	Wing Anticollision / Navigation Light (Right) - Discard		HRS		1973.6		20000	1548.8	21548.8		0
	01-0790453-01	00271	AFL		411			316			0
			MOS	TSN:33	77.9			28 Jun 2018			
	Airframe										
334211	Navigation Lights - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1	7	12	23 Sep 2024	30 Sep 2025*	31 Oct 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
334212	Anticollision Lights - Operational Test		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1	38	12	23 Sep 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
334213	Tail Anticollision / Navigation Light - Removal / Installation		HRS		3522.4			0			0
	01-0790450-00	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334215	Tail Anticollision / Navigation Light - Discard		HRS		3522.4		20000	0	20000		0
	01-0790450-00	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe										
334216	Left Wing-Tip Flood / Taxi Lights - Removal / Installation		HRS		3522.4			0			0
	01-0771125-30	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334217	Right Wing-Tip Flood / Taxi Lights - Removal / Installation		HRS		3522.4			0			0
	01-0771125-30	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334218	Fin CAP Nav / Acl Kit - Removal / Installation		HRS		3522.4			0			0
	1007-3342N001-007	00256	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334220	Wingtip Flasher / Current Source (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	01-0790456-00	00530	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
334221	Wingtipflasher / Current Source (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	01-0790456-00A	00499	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
334224	Winglet Light Assembly (Left) - Removal Installation		HRS	TSN:2364	1158			2364.4			0
	1007-3342A001-003	NSN	AFL	TSN:487	239			488			0
			MOS	TSN:78	50.6			08 Oct 2020			N/A
			MSC				O/C				
Airframe											
334225	Winglet Light Assembly (Right) - Removal Installation		HRS	TSN:3036.5	485.9			3036.5			0
	1007-3342A001-003	NSN	AFL	TSN:630	97			630			0
			MOS	TSN:101	26.6			06 Oct 2022			N/A
			MSC				O/C				
Airframe											
334228	Tail Navigation / Anticollision Light Lens Assembly - Removal / Installation		HRS		2624.5			897.9			0
			AFL		535			192			0
	1007-3342A011-003	00409	MOS	TSN:13	95			27 Jan 2017			
			MSC				O/C				
Airframe											
334302	Ice Inspection Lights - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
334303	Ice Inspection Lights (Left) - Removal / Installation		HRS		873.6			2648.8			0
	20-2001-0002	233715-1-9	AFL		166			561			0
			MOS	TSN:2	38.9			30 Sep 2021			
			MSC				O/C				
Airframe											
334400	Left Logo Light - Removal / Installation		HRS		3522.4			0			0
	20-3101-0002	123870-8-1	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334401	Right Logo Light - Removal / Installation		HRS		3522.4			0			0
	20-3101-0001	121080-9-2	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
334404	Logo Lights - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
335000	Exterior Emergency Lighting - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5	43	24	10 Oct 2024	30 Nov 2026*	31 Dec 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
335100	Cabin Emergency Lighting - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5	41	24	12 Oct 2024	30 Nov 2026*	31 Dec 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
335210	Wing Emergency Lighting - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
34 - Navigation											
340100	Reduced Vertical Separation Minimum (RVSM) Monitoring Policy		HRS		362.7			3159.7			0
			AFL		73			654			0
			MOS		20.8		24	31 Mar 2023	31 Mar 2025		
	Airframe		[End Of Month Item]								
Notes: RVSM MONITORING FLIGHT - PERFORMED BY EUROCONTROL ON 11-29-2018 - RECORDED AT CARSAMMA DATABASE - NEXT DUE 2705.1 HR / 11-29-2020 WHICHEVER OCCURS LATER.											
341200	AIR Data Probe (No. 1 - Left Upper) - Removal / Installation		HRS		1079.5			2442.9			0
			AFL		222			505			0
	2015G2H2CLU-3	0567	MOS		45.3			18 Mar 2021			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341201	AIR Data Probe (No. 3 - Left Lower) - Removal /		HRS		873.6			2648.8			0
	Installation		AFL		166			561			0
	2015G2H2CLL-3	1552	MOS		38.8			02 Oct 2021			ROSEMOUNT
			MSC				O/C				AEROSPACE INC
Airframe											
341202	AIR Data Probe (No. 2 - Right Upper) - Removal /		HRS		873.6			2648.8			0
	Installation		AFL		166			561			0
	2015G2H2CRU-3	0403	MOS		38.8			02 Oct 2021			ROSEMOUNT
			MSC				O/C				AEROSPACE INC
Airframe											
341203	AIR Data Probe (No. 4 - Right Lower) - Removal /		HRS		873.6			2648.8			0
	Installation		AFL		166			561			0
	2015G2H2CRL-3	0401	MOS		38.8			02 Oct 2021			ROSEMOUNT
			MSC				O/C				AEROSPACE INC
Airframe											
341208	AIR Data Probe (No. 1) - Functional Check		HRS		1079.5			2442.9			0
			AFL		222			505			0
			MOS		45.3			18 Mar 2021			
			MSC				O/C				
Airframe											
341212	Digital AIR Data Computing System - Functional Test		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		124.5			09 Aug 2014			
			MSC				O/C				
Airframe											
341300	AIR Data System (No. 1 - Left Upper) - Functional / Leak		HRS		113.9			3408.5			0
	Test		AFL		36			691			0
			MOS		14.3		24	16 Oct 2023	31 Oct 2025		
			[End Of Month Item]								
Airframe											
Notes: AIR DATA TEST SET C/N 561219 CAL DUE 08/2018DIGITAL THERMMOMETER C/N 568766 CAL DUE 50/2018PERFORMED AIR DATA CERTIFICATION TO 51,000 FT IN ACCORDANCE WITH FAR 91.411 P/N : 2015G2H2CLU-2S/N : 0516DATE TESTED : 09/17/17**INFO REQUIRED FOR LOG											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341301	AIR Data System (No. 2 - Right Upper) - Functional / Leak Test		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3		24	16 Oct 2023	31 Oct 2025		
			[End Of Month Item]								
Airframe											
Notes: AIR DATA TEST SET C/N 561219 CAL DUE 08/2018DIGITAL THERMMOMETER C/N 568766 CAL DUE 50/2018PERFORMED AIR DATA CERTIFICATION TO 51,000 FT IN ACCORDANCE WITH FAR 91.411 P/N : 2015G2H2CRU-2S/N : 0535DATE TESTED : 09/17/17**INFO REQUIRED FOR LOG											
341302	AIR Data System (No. 3 - Left Lower) - Functional / Leak Test		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3		24	16 Oct 2023	31 Oct 2025		
			[End Of Month Item]								
Airframe											
Notes: AIR DATA TEST SET C/N 561219 CAL DUE 08/2018DIGITAL THERMMOMETER C/N 568766 CAL DUE 50/2018PERFORMED AIR DATA CERTIFICATION TO 51,000 FT IN ACCORDANCE WITH FAR 91.411 P/N : 2015G2H2CRL-2S/N : 0522DATE TESTED : 09/17/17**INFO REQUIRED FOR LOG											
341303	AIR Data System (No. 4 / Standby - Right Lower) - Functional / Leak Test		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3		24	16 Oct 2023	31 Oct 2025		
			[End Of Month Item]								
Airframe											
Notes: AIR DATA TEST SET C/N 561219 CAL DUE 08/2018DIGITAL THERMMOMETER C/N 568766 CAL DUE 50/2018PERFORMED AIR DATA CERTIFICATION TO 51,000 FT IN ACCORDANCE WITH FAR 91.411 P/N : 2015G2H2CRL-2S/N : 0499DATE TESTED : 09/17/17**INFO REQUIRED FOR LO											
341305	AIR Data Probe - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
341306	AIR Data Probe - Inspection Check		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.8			02 Oct 2021			
			MSC				O/C				
Airframe											
341308	AIR Data Probe Fairing (Left Lower) - Inspection / Check		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.6			08 Oct 2021			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341309	AIR Data Probe Fairing (Right Upper) - Inspection / Check		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.6			08 Oct 2021			
			MSC				O/C				
Airframe											
341310	AIR Data Probe Fairing (Right Lower) - Inspection / Check		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.6			08 Oct 2021			
			MSC				O/C				
Airframe											
341311	Multi-Function Probe / AIR Data Computer (No. 1 - Left Upper) - Certification		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3		24	16 Oct 2023	31 Oct 2025		
			[End Of Month Item]								CALIBRATION
Airframe											
341312	Multi-Function Probe / AIR Data Computer (No. 2 - Right Upper) - Certification		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3		24	16 Oct 2023	31 Oct 2025		
			[End Of Month Item]								CALIBRATION
Airframe											
341313	Multi-Function Probe / AIR Data Computer (No. 3 - Left Lower) - Certification		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3		24	16 Oct 2023	31 Oct 2025		
			[End Of Month Item]								CALIBRATION
Airframe											
341314	Multi-Function Probe / AIR Data Computer (No. 4 / Standby - Right Lower) - Certification		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3		24	16 Oct 2023	31 Oct 2025		
			[End Of Month Item]								CALIBRATION
Airframe											
341315	AIR Data System - Leak Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3			16 Oct 2023			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341316	AIR Data System - Altitude Accuracy Check		HRS		113.9			3408.5			0
			AFL		36			691		0	
			MOS		14.3			16 Oct 2023			
			MSC			O/C					
Airframe											
341317	AIR Data System - Probe Heat Verification Test		HRS		113.9			3408.5			0
			AFL		36			691		0	
			MOS		14.3			16 Oct 2023			
			MSC			O/C					
Airframe											
341318	AIR Data System - Transponder Interface Test		HRS		113.9			3408.5			0
			AFL		36			691		0	
			MOS		14.3			16 Oct 2023			
			MSC			O/C					
Airframe											
341319	Multi-Function Probe / AIR Data Computer - Interface Validation Test		HRS		113.9			3408.5			0
			AFL		36			691		0	
			MOS		14.3			16 Oct 2023			
			MSC			O/C					
Airframe											
341321	Multi-Function Probe / AIR Data Computer - Heater Power Interface Validation Test		HRS		113.9			3408.5			0
			AFL		36			691		0	
			MOS		14.3			17 Oct 2023			
			MSC			O/C					
Airframe											
341400	Total AIR Temperature Probe (Left) - Removal / Installation 0102LV1DF B18411		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
341401	Total AIR Temperature Probe (Right) - Removal / Installation 0102LV1DF C10026		HRS		3506.4			16			0
			AFL		721			6		0	
			MOS		122.4			13 Oct 2014			
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341402	Total AIR Temperature Probe / Cabin Pressure Relief AIR Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	320154-4-1	2376	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
341410	Total AIR Temperature Probe - Operational Check		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		123.1			22 Sep 2014			
			MSC				O/C				
Airframe											
341412	Total AIR Temperature Probe - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
341413	Total AIR Temperature Probe - Inspection Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
342300	Attitude Heading Reference Unit (No. 1) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	HG2205AB02\1	56068872	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
342301	Attitude Heading Reference Unit (No. 2) - Removal / Installation		HRS		1556.4			1966			0
			AFL		318			409			0
	HG2205AB02	56057175	MOS		64.4			15 Aug 2019			
			MSC				O/C				
Airframe											
342302	Attitude Heading Reference Unit Configuration Module (No. 1) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	071-00188-0101	3300	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342303	Attitude Heading Reference Unit Configuration Module		HRS		3522.4			0			0
	(No. 2) - Removal / Installation		AFL		727			0			0
	071-00188-0101	3336	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
342308	Attitude Heading Reference Unit Tray (No. 1) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	WG2005AB02	0287	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
342309	Attitude Heading Reference Unit Tray (No. 2) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	WG2005AB02	0288	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
342312	Attitude Heading Reference System - Operational Check		HRS		1556.4			1966			0
			AFL		318			409			0
			MOS		64.4			15 Aug 2019			
			MSC				O/C				
Airframe											
342314	Attitude Heading Reference Unit - Tray Alignment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
342600	HUD Ii Overhead Unit - Removal / Installation		HRS		3509.1			13.3			0
	1500-3070-001	42808	AFL		722			5			0
			MOS		124.9			28 Jul 2014			
			MSC				O/C				
Airframe											
342601	HUD Ii Combiner Assembly - Removal / Installation		HRS		3522.4			0			0
	1500-3080-601	36785	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
342602	HUD Ii Computer - Removal / Installation		HRS		862.3			2660.1			0
	1500-3060-001	33906	AFL		164			563			0
			MOS		38.1			22 Oct 2021			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342603	HUD li Personality Module - Removal / Installation		HRS		3522.4			0			0
	822-1424-001	41H0F8	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
342608	HUD li Overhead Unit Lens - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
342609	HUD li Combiner Assembly - Cleaning		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
342610	HUD li System - Operational Check		HRS		862.3			2660.1			0
			AFL		164			563			0
			MOS		38.1			22 Oct 2021			
	Airframe		MSC				O/C				
342611	HUD li System - Software Check		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
	Airframe		MSC				O/C				
342612	HUD li System - Rigging Adjustment		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
	Airframe		MSC				O/C				
342700	Standby Multi-Function Controller Unit (No. 1) - Removal / Installation		HRS		3396.7			125.7			0
			AFL		702			25			0
	G7284-03	271	MOS		119.9			29 Dec 2014			
	Airframe		MSC				O/C				
342701	Standby Multi-Function Controller Unit (No. 2) - Removal / Installation		HRS		515.3			3007.1			0
			AFL		100			627			0
	G7284-03	58	MOS		27			27 Sep 2022			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342704	Standby Multi-Function Controller - Operational Check		HRS		515.3			3007.1			0
			AFL		100		627		0		
			MOS		27		27 Sep 2022				
			MSC			O/C					
342710	Standby Multi-Function Controller / Magnetometer - Compensation Adjustment		HRS		1544.6			1977.8			0
			AFL		317		410		0		
			MOS		64.2		21 Aug 2019				
			MSC			O/C					
342712	Standby Multi-Function Controller / Magnetometer - Calibration Check		HRS		1544.6			1977.8			0
			AFL		317		410		0		
			MOS		64.2		21 Aug 2019				
			MSC			O/C					
342718	Switch Panel Unit - Operational Check		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
342800	Magnetometer (160A7) - Removal / Installation 065-00189-0101 KMG7010-3214		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
342801	Magnetometer (160A8) - Removal / Installation 065-00189-0101 KMG7010-3288		HRS		1566.2			1956.2			0
			AFL		319		408		0		
			MOS		64.5		12 Aug 2019		N/A		
			MSC			O/C					
342900	Enhanced Vision System li Infrared Camera - Removal / Installation 58534-101\E 1522 005		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342901	Enhanced Vision System li Processor - Removal /		HRS		3133.7			388.7			0
	Installation		AFL		652			75			0
	48539-101	1393	MOS		111.1			22 Sep 2015			
		004	MSC				O/C				
Airframe											
342902	Enhanced Vision System li Window Assembly - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	50889-101	221	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
342906	Enhanced Vision System li Window Assembly - Restore		HRS		3522.4			0			0
	50889-101	221	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
342907	Enhanced Vision System li Sapphire Window Assembly -		HRS		3522.4		10000	0	10000	10050	0
	Functional Test		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			[HRS: +50/-50]								
Airframe											
342908	Enhanced Vision System li - Functional Check		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.1			22 Sep 2015			
			MSC				O/C				
Airframe											
342909	Enhanced Vision System Infrared Camera Lens /		HRS		3522.4			0			0
	Sapphire Window - Cleaning		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
342910	Enhanced Vision System li Windshield Heat Switch -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	318VL23AAAMEY00	NSN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342912	Enhanced Vision System li Manual Window Heat - Operational Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
344200	Inertial Reference Unit (No. 1) - Removal / Installation HG2100BB02		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
344201	Inertial Reference Unit (No. 2) - Removal / Installation HG2100BB02		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
344202	Inertial Reference Unit (No. 3) - Removal / Installation HG2100BB02		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
344210	Inertial Reference System MODE Select Panel - Removal / Installation 60A2510001N003		HRS	TSN:4	2312.5			1209.9			0
			AFL		479		248		0		
			MOS		87.1		24 Sep 2017				
			MSC				O/C				
Airframe											
344211	Inertial Reference System Personality Module (No. 1) - Removal / Installation 7519272-901\C		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
344212	Inertial Reference System Personality Module (No. 2) - Removal / Installation 7519272-901\C		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
344213	Inertial Reference System Personality Module (No. 3) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7519272-901\C	40342811	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
344214	Inertial Reference Unit (No. 1) Mounting Tray - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	WG2001AA03	2555	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
344215	Inertial Reference Unit (No. 2) Mounting Tray - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	WG2001AA03	2556	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
344216	Inertial Reference Unit (No. 3) Mounting Tray - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	WG2001AA03	2557	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
344220	Radio Altimeter R/T Unit (No. 1) - Removal / Installation		HRS		3522.4			0			0
	066-01153-0101\1-7,9-15		AFL		727			0			0
	KRA405B-14798		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
344221	Radio Altimeter R/T Unit (No. 2) - Removal / Installation		HRS		3522.4			0			0
	066-01153-0101\1-7,9-15		AFL		727			0			0
	KRA405B-14847		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
344224	Inertial Reference System - Operation Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
344227	Inertial Reference Unit Tray (No. 1) - Alignment		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
344228	Inertial Reference Unit Tray (No. 2) - Alignment		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
344229	Inertial Reference Unit Tray (No. 3) - Alignment		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
344234	Inertial Reference System MODE Select Panel - Operational Check		HRS		2312.5			1209.9			0
			AFL		479			248		0	
			MOS		87.1		24 Sep 2017				
			MSC			O/C					
Airframe											
344300	Radio Altimeter (No. 1) Transmit Antenna - Removal / Installation DM PN19-2-18019		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
344301	Radio Altimeter (No. 2) Transmit Antenna - Removal / Installation DM PN19-2-18021		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
344302	Radio Altimeter Configuration Module (No. 1) - Removal / Installation 071-00097-0100\1CM2000-27982		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
344303	Radio Altimeter Configuration Module (No. 2) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	071-00097-0100\1	CM2000-27992	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
344304	Radio Altimeter (No. 1) Receive Antenna - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	DM PN19-2-1	8020	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
344305	Radio Altimeter (No. 2) Receive Antenna - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	DM PN19-2-1	8024	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
344316	Radio Altimeter System - Operational Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.4			13 Nov 2022			
			MSC				O/C				
Airframe											
344318	Radio Altimeter R/T Unit - Zero Altitude Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
344320	Radio Altimeter Configuration Module - Configuration Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
344400	Weather Radar Flatplate Antenna - Removal / Installation		HRS	TSN:6.4	3522.4			0			0
			AFL	TSN:3	727			0			0
	930-4241-001	FP2401028	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
344401	Weather Radar Processor - Removal / Installation		HRS		113.9			3408.5			0
	930-1003-013	RPO2319	AFL		36			691			0
			MOS		13.8			31 Oct 2023			
	Airframe		MSC				O/C				
344404	Weather Radar Antenna Drive - Removal / Installation		HRS		3522.4			0			0
	930-3002-001	DA1S01133	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
344406	Weather Radar System - Operational Check		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.1			24 Sep 2015			
	Airframe		MSC				O/C				
344407	Weather Radar R/T - Removal / Installation		HRS		3522.4			0			0
	930-2000-001\26-28,30	TR02778	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
344500	Processor, Lightning Sensor - Removal / Installation		HRS		3509.1			13.3			0
	7011822-904	13072777	AFL		722			5			0
			MOS		123			27 Sep 2014			HONEYWELL
	Airframe		MSC				O/C				
344502	Antenna, Lightning Sensor - Removal / Installation		HRS		3509.1			13.3			0
	7014062-901	11071720	AFL		722			5			0
			MOS		123			27 Sep 2014			HONEYWELL
	Airframe		MSC				O/C				
344504	Controller, Lightning Sensor - Removal / Installation		HRS		3509.1			13.3			0
	7012738-905	13041067	AFL		722			5			0
			MOS		123			27 Sep 2014			HONEYWELL
	Airframe		MSC				O/C				
344600	Egpws Module (No. 1) - Removal / Installation		HRS		113.9			3408.5			0
	PN	NOT INSTALLED	AFL		36			691			0
			MOS		14			26 Oct 2023			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
344601	Egpws Module (No. 2) - Removal / Installation		HRS		113.9			3408.5			0
	PN	NOT INSTALLED	AFL		36			691			0
			MOS		14			26 Oct 2023			
	Airframe		MSC				O/C				
344604	Egpws - Return to Service Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
344605	Egpws - Operational Test		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.2			20 Oct 2020			
	Airframe		MSC				O/C				
344625	Egpwm Terrain Threat		HRS		0			3522.4			0
			AFL		0			727			0
			MOS		2.4			14 Oct 2024			
	Airframe		MSC				O/C				
344700	TCAS Computer - Removal / Installation		HRS	TSN:1799.9	1722.5			1799.9			0
	9003500-55905\A-DFG/C	TSE02107	AFL	TSN:376	351			376			0
			MOS	TSN:60	68.8			01 Apr 2019			N/A
	Airframe		MSC				O/C				
344701	TCAS Antenna (Lower) - Removal / Installation		HRS	TSN:2364.5	1158			2364.4			0
	DM NI50-9-2	16390	AFL	TSN:487	239			488			0
			MOS	TSN:78	50.5			12 Oct 2020			N/A
	Airframe		MSC				O/C				
344702	TCAS Antenna (Upper) - Removal / Installation		HRS		646.7			2875.7			0
	7514060-902	ANE59672	AFL		120			607			0
			MOS		30.1			23 Jun 2022			
	Airframe		MSC				O/C				
Notes: DLRO USED:ID: 570985NEXT CAL DATE DUE: 06/19											
344706	TCAS - Operational Check		HRS		646.7			2875.7			0
			AFL		120			607			0
			MOS		30.1			23 Jun 2022			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345200	GPS Antenna (No. 1) - Removal / Installation		HRS	TSN:2364.2	1158			2364.4			0
	S67-1575-147	888-0283	AFL	TSN:487	239			488			0
			MOS	TSN:78	50.5			12 Oct 2020			N/A
	Airframe		MSC				O/C				
345201	GPS Antenna (No. 2) - Removal / Installation		HRS	TSN:2364.2	1158			2364.4			0
	S67-1575-147	888-0337	AFL	TSN:487	239			488			0
			MOS	TSN:78	50.5			12 Oct 2020			N/A
	Airframe		MSC				O/C				
345300	VOR / Localizer Antenna Bonding - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
345304	VOR / Localizer Antenna Coupler / Diplexer (Verticle Stabilizer) - Removal / Installation		HRS		3522.4			0			0
	DM N4-17-4	8949	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
345305	VOR / Localizer Antenna (Left) - Removal / Installation		HRS		3522.4			0			0
	N4-17-1/AD	33592	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
345306	VOR / Localizer Antenna (Right) - Removal / Installation		HRS		3522.4			0			0
	N4-17-1/AD	32102	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
345307	VOR / ILS / Data Link / GPS Module (No. 1) - Removal / Installation		HRS		3522.4			0			0
	7026208-805\A,B	13110552	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
345308	VOR / ILS / Data Link / GPS Module (No. 2) - Removal / Installation		HRS		3522.4			0			0
	7026208-805\A,B	13110551	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345309	Glide Slope Antenna Diplexer - Removal / Installation		HRS		3522.4			0			0
	SSPD-332-3		AFL		727			0			0
	685-2142		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
345310	Glide Slope Dual Antenna - Removal / Installation		HRS		3522.4			0			0
	S41422-2		AFL		727			0			0
	111-8014		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
345313	Glide Slope Antenna - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: PN: S41422-2 SN: <NONE>.											
345316	VOR / ILS / Data Link / GPS - Functional Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.9			30 Oct 2023			
	Airframe		MSC				O/C				
345317	VHF / VOR / ILS / Data Link / GPS Module - Return to Service Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
345320	Marker Beacon Antenna Diplexer (Bottom Fuselage) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	DMH21-1	50032	MOS	TSN:104	25.3			16 Nov 2022			N/A
	Airframe		MSC				O/C				
345321	Marker Beacon Antenna - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	S35-2000-10		AFL	TSN:630	97			630			0
	106-0818		MOS	TSN:102	25.3			16 Nov 2022			N/A
	Airframe		MSC				O/C				
345323	VOR - Instrument Flight Rules Check		HRS		-17.5			3539.9			0
			AFL		-10			737			0
	Airframe		DATE		22 d	-23	30d	04 Dec 2024	11 Dec 2024*		

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345324	Marker Beacon Antenna Diplexer (Reer) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	SSPD-113-39	3523	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
345327	Mini Radio Cabinet - Removal / Installation		HRS	TSN:1209.9	2312.5			1209.9			0
	7026240-902	13111045	AFL	TSN:248	479			248			0
			MOS	TSN:41	87.1			24 Sep 2017			
			MSC				O/C				
Airframe											
345330	Navigation / Communication Module - Removal / Installation		HRS	TSN:1209.9	2312.5			1209.9			0
			AFL	TSN:248	479			248			0
	7026203-813\R	13111045	MOS	TSN:41	87.1			24 Sep 2017			
			MSC				O/C				
Airframe											
345331	Navigation / Communication System - Functional Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
345332	VOR / Localizer Antenna Coupler / Diplexer (Reer) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	DMH21-1	51525	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
345402	ADF - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.9			30 Oct 2023			
			MSC				O/C				
Airframe											
345403	ADF Receiver - Return to Service Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
345406	ADF Receiver - Removal / Installation		HRS	TSN:2.8	3522.4			0			0
	7510114-855\K-M	1202F995	AFL	TSN:1	727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345408	ADF Antenna - Removal / Installation		HRS	TSN:2364.2	1158			2364.4			0
	7510300-901	1308L890	AFL	TSN:487	239			488			0
			MOS	TSN:78	50.5			12 Oct 2020			N/A
	Airframe		MSC					O/C			
345500	ATC MODE S Antenna (No. 1) Lower - Removal / Installation		HRS	TSN:2364.2	1158			2364.4			0
			AFL	TSN:487	239			488			0
	DM NI50-9-2	16384	MOS	TSN:78	50.5			12 Oct 2020			N/A
	Airframe		MSC					O/C			
345501	ATC MODE S Antenna (No. 2) Lower - Removal / Installation		HRS	TSN:2364.2	1158			2364.4			0
			AFL	TSN:487	239			488			0
	DM NI50-9-2	16385	MOS	TSN:78	50.4			15 Oct 2020			N/A
	Airframe		MSC					O/C			
345502	MODE S Diversity Transponder Module (No. 1) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	7517402-970	1501K977	MOS		75.3			18 Sep 2018			Honeywell
	Airframe		MSC					O/C			
345503	MODE S Diversity Transponder Module (No. 2) - Removal / Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
	7517402-970	1203I167	MOS		75.3			18 Sep 2018			Honeywell
	Airframe		MSC					O/C			
345504	ATC MODE S Antenna (No. 1) Upper - Removal / Installation		HRS	TSN:2364.2	1158			2364.4			0
			AFL	TSN:487	239			488			0
	DM NI50-9-2	16365	MOS	TSN:78	50.5			12 Oct 2020			N/A
	Airframe		MSC					O/C			
345505	ATC MODE S Antenna (No. 2) Upper - Removal / Installation		HRS	TSN:2364.2	1158			2364.4			0
			AFL	TSN:487	239			488			0
	DM NI50-9-2	16367	MOS	TSN:78	50.5			12 Oct 2020			N/A
	Airframe		MSC					O/C			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345512	ATC (No. 1) - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.9		24	30 Oct 2023	31 Oct 2025		
	Airframe		[End Of Month Item]								
345513	ATC (No. 2) - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.3		24	16 Oct 2023	31 Oct 2025		
	Airframe		[End Of Month Item]								
345514	MODE S Diversity Transponder Module - Return to Service Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
345600	DME Antenna (No. 1) - Removal / Installation		HRS		1158			2364.4			0
	DM NI50-9-2	16393	AFL		239			488			0
			MOS		50.5			12 Oct 2020			N/A
	Airframe		MSC				O/C				
345601	DME Antenna (No. 2) - Removal / Installation		HRS		1158			2364.4			0
	DM NI50-9-2	16448	AFL		239			488			0
			MOS		50.5			12 Oct 2020			N/A
	Airframe		MSC				O/C				
345602	DME Module (No. 1) - Removal / Installation		HRS		3522.4			0			0
	7510184-855\K-S	1311J827	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
345603	DME Module (No. 2) - Removal / Installation		HRS		3522.4			0			0
	7510184-855\K-S	1311J821	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
345608	DME - Functional Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.9			30 Oct 2023			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345609	DME Module - Return to Service Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
346000	Multi-Function Control Display Unit (No. 1) - Removal / Installation A50A000-00-450A4505399		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		26.3		17 Oct 2022		L3 AVIATION		
			MSC			O/C		PRODUCTS			
Airframe											
346001	Multi-Function Control Display Unit (No. 2) - Removal / Installation A50A000-00-450A4505372		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS	TSN:2	26.3		17 Oct 2022		L3 AVIATION		
			MSC			O/C		PRODUCTS			
Airframe											
346002	Multi-Function Control Display Unit (No. 3) - Removal / Installation A50A000-00-450A4505291		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS	TSN:4	26.3		17 Oct 2022		L3 AVIATION		
			MSC			O/C		PRODUCTS			
Airframe											
346006	Multi-Function Control Display Unit - Operational Test		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		26.3		17 Oct 2022				
			MSC			O/C					
Airframe											
346009	Multi-Function Control Display Unit (No.1) - Return to Service Test		HRS		2312.5			1209.9			0
			AFL		479		248		0		
			MOS		87		25 Sep 2017				
			MSC			O/C					
Airframe											
346010	Multi-Function Control Display Unit (No.2) - Return to Service Test		HRS		2312.5			1209.9			0
			AFL		479		248		0		
			MOS		87		25 Sep 2017				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
346011	Multi-Function Control Display Unit (No.3) - Return to Service Test		HRS		2312.5			1209.9			0
			AFL		479			248		0	
			MOS		87			25 Sep 2017			
			MSC				O/C				
Airframe											
346012	FMS - Operational Check		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
346025	FMS Nav Database - Update		HRS		-17.5			3539.9			0
			AFL		-10			737		0	
			DATE		23 d		28d	03 Dec 2024	26 Dec 2024		
			[DAYS: -8]							EXPIRATION	
Airframe											
346040	Runway Overrun (Roaas) Database - Update		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				-				
Airframe											
346050	Planeview Terrain Database Update (Green Disk)		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		24.9			28 Nov 2022			
			MSC				O/C				
Airframe											
Notes: PN: 996-0146-585 SN: 6088. REFERENCE G650 AMM 20-22-00 REV 9											
35 - Oxygen											
350001	Oxygen System Torque Requirements		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
350002	Oxygen System - Operational Test		HRS		113.9			3408.5			0
			AFL		36			691		0	
			MOS		14			26 Oct 2023			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
350003	Oxygen System Venting Procedure		HRS		485.9			3036.5			0
			AFL		97		630		0		
			MOS		26		26 Oct 2022				
			MSC			O/C					
351000	Crew Oxygen System - Leak and Pressure Decay Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
351100	Crew Oxygen Mask and Regulator (Pilot) - Removal / Installation		HRS		.4			3522			0
			AFL		1		726		0		
			MOS		2.5		09 Oct 2024		N/A		
			MSC			O/C					
351101	Crew Oxygen Mask and Regulator (Copilot) - Removal / Installation		HRS		.4			3522			0
			AFL		1		726		0		
			MOS		2.5		09 Oct 2024		N/A		
			MSC			O/C					
351102	Observer Oxygen Mask and Regulator - Removal / Installation		HRS		285.9			3236.5			0
			AFL		61		666		0		
			MOS		18.4		15 Jun 2023				
			MSC			O/C					
351103	Crew Oxygen Mask (Pilot) - Restore		HRS		.4			3522			0
			AFL		1		726		0		
			MOS		2.5	72	09 Oct 2024	31 Oct 2030	N/A		
			[End Of Month Item]				OVERHAUL				
351104	Crew Oxygen Mask (Copilot) - Restore		HRS		.4			3522			0
			AFL		1		726		0		
			MOS		2.5	72	09 Oct 2024	31 Oct 2030	N/A		
			[End Of Month Item]				OVERHAUL				
351105	Crew Oxygen Mask (Observer) - Restore		HRS		285.9			3236.5			0
			AFL		61		666		0		
			MOS		18.4	72	15 Jun 2023	31 Mar 2029			
			[End Of Month Item]				OVERHAUL				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
351106	Crew Oxygen Mask and Regulator (Pilot) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5		75	10 Oct 2024	31 Jan 2031	28 Feb 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
351107	Crew Oxygen Mask and Regulator (Copilot) - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5		75	10 Oct 2024	31 Jan 2031	28 Feb 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
351108	Crew Oxygen Mask and Regulator (Observer) - Operational Check		HRS		285.9			3236.5			0
			AFL		61			666			0
			MOS		18.4		75	15 Jun 2023	30 Sep 2029	31 Oct 2029	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
351112	Crew Oxygen Mask / Regulator and Stowage Box (Pilot) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5	-11	36	09 Oct 2024	30 Sep 2027*	31 Oct 2027	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
351113	Crew Oxygen Mask / Regulator and Stowage Box (Copilot) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5	-11	36	09 Oct 2024	30 Sep 2027*	31 Oct 2027	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
351114	Crew Oxygen Mask / Regulator and Stowage Box (Observer) - Detailed Inspection		HRS		285.9			3236.5			0
			AFL		61			666			0
			MOS		18.4		36	15 Jun 2023	30 Jun 2026	31 Jul 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
351125	Crew Oxygen Mask Storage Box (Pilot) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
351126	Crew Oxygen Mask Storage Box (Copilot) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	MXP892	SE63487	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
351127	Observer Oxygen Mask Storage Box - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	MXP326-2	SE63081	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
351200	Crew Oxygen Cylinder - Removal / Installation		HRS		113.9			3408.5			0
	805983-15	C09020533	AFL		36			691			0
			MOS		14			26 Oct 2023			N/A
			MSC				O/C				
Airframe											
351202	Crew Oxygen Cylinder - Discard		HRS		113.9			3408.5			0
	805983-15	C09020533	AFL		36			691			0
			MOS		14.2		180	21 Oct 2023	30 Jun 2037		
			[End Of Month Item]								MANUFACTURE
Airframe											
351203	Crew Oxygen Cylinder - Restore		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.2			21 Oct 2023			
			MSC				O/C				HYDRO CHECK
Airframe											
351205	Crew Oxygen Pressure Transducer - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	CZ92A5-9	HAI 3338	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
351206	Crew Oxygen Lp Switch - Removal / Installation		HRS		3522.4			0			0
	P24029	4369	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
351208	Oxygen System Check Valves - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14		75	26 Oct 2023	31 Jan 2030	28 Feb 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
351210	Crew Oxygen Lp Switch - Operational Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14			26 Oct 2023			
	Airframe		MSC				O/C				
351211	Crew Oxygen Quantity Gage - Removal / Installation		HRS		3522.4			0			0
	163LCP81	13128015	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
351213	Crew Oxygen Cylinder - General Visual Inspection		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.3			18 Sep 2018			
	Airframe		MSC				O/C				
351300	Crew Oxygen Servicing Pressure Gage - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	P24094-1	1876	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
351301	Oxygen Servicing Filler Valve - Removal / Installation		HRS		3522.4			0			0
	P21103	0904	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
351304	Crew Oxygen Servicing Pressure Gage - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: PN: P21103 SN: <NONE>.											
351305	Oxygen Supply Pressure Valve - Removal / Installation		HRS		3522.4			0			0
	O2C74T01-1	17155	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
352001	Passenger Oxygen Controller - Removal / Installation		HRS		3522.4			0			0
	P27122	0350	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352100	Passenger Oxygen Drop-Down Mask Assemblies - Detailed Inspection		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14	5	24	26 Oct 2023	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: REF ITEMS 24.60 AND 26.18 FOR SQUAWKS											
352101	Drop Down Oxygen Box Assembly - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		36	23 Oct 2014	31 Oct 2025	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
352300	Passenger Oxygen Cylinder - Removal / Installation 805983-15 C22071270		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS	TSN:2	26			26 Oct 2022			N/A
			MSC				O/C				
Airframe											
352302	Passenger Oxygen Cylinder - Discard 805983-15 C22071270		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26		180	26 Oct 2022	31 Aug 2037		N/A
			[End Of Month Item]								
Airframe											
352303	Passenger Oxygen Cylinder - Restore		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.3			18 Sep 2018			
			MSC				O/C				HYDRO CHECK
Airframe											
[End Of Month Item]											
352306	Passenger Oxygen Pressure Transducer - Removal / Installation CZ92A5-9 HAJ 3339		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
352307	Passenger Oxygen Lp Switch - Removal / Installation P24029 4375		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352308	Passenger Oxygen System Check Valve - Operational Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		75**	23 Oct 2014	28 Feb 2027		
			[End Of Month Item] [MOS: -1m]								
Airframe											
352310	Passenger Oxygen Lp Switch - Operational Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26			27 Oct 2022			
			MSC				O/C				
Airframe											
352311	Passenger Oxygen Quantity Gage - Removal / Installation 163LCP81 13128012		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
352313	Passenger Oxygen Cylinder - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26			26 Oct 2022			
			MSC				O/C				
Airframe											
352400	Passenger Oxygen Servicing Pressure Gage - Removal / Installation P24094-1 1873		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
352402	Passenger Oxygen Servicing Pressure Gage - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
352403	Passenger Oxygen System (Manual MODE) - Operational Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.3		48	18 Nov 2022	30 Nov 2026	31 Dec 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352404	Passenger Oxygen System (Auto MODE) - Functional Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.9	-33	48	30 Oct 2023	30 Sep 2027*	31 Oct 2027	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: FM 559802 DATE 6/2018BARFIELD 555852 DATE 11/2017											
352600	Therapeutic Oxygen Shut-Off Valve - Removal / Installation P21046-10764		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
352601	Therapeutic Oxygen Pressure Switch - Removal / Installation P240294377		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
352604	Therapeutic Oxygen System - Functional Check		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.9	1	36	30 Oct 2023	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
352605	Therapeutic Oxygen Mask - Detailed Inspection		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.9	1	36	30 Oct 2023	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
354100	Forward Left Psu Oxygen Box Assembly #1 - Removal / Installation P283830430		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354101	Forward Left Psu Oxygen Box Assembly #2 - Removal / Installation P283850127		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
354102	Forward Left Psu Oxygen Box Assembly #3 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28383	0427	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354106	Mid Left Psu Oxygen Box Assembly #1 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28380	0302	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354107	Mid Left Psu Oxygen Box Assembly #2 - Removal / Installation		HRS		3506.4			16			0
			AFL		721			6			0
	P28384	0508	MOS		122.4			13 Oct 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354108	Mid Left Psu Oxygen Box Assembly #3 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28380	0630	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354112	Aft Left Psu Oxygen Box Assembly #1 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28380	0429	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354113	Aft Left Psu Oxygen Box Assembly #2 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28384	0411	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354114	Aft Left Psu Oxygen Box Assembly #3 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28383	0451	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
354118	Forward Right Psu Oxygen Box Assembly #1 - Removal / Installation		HRS		3495.3			27.1			0
			AFL		719			8			0
	P28380	0640	MOS		122.2			19 Oct 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354119	Forward Right Psu Oxygen Box Assembly #2 - Removal / Installation		HRS	TSN:13.8	3495.3			27.1			0
			AFL	TSN:3	719			8			0
	P28384	0398	MOS	TSN:1	122.2			19 Oct 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354120	Forward Right Psu Oxygen Box Assembly #3 - Removal / Installation		HRS	TSN:13.8	3495.3			27.1			0
			AFL	TSN:3	719			8			0
	P28380	0426	MOS	TSN:1	122.2			19 Oct 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354124	Mid Right Psu Oxygen Box Assembly #1 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28383	0452	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354125	Mid Right Psu Oxygen Box Assembly #2 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28384	0399	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354126	Mid Right Psu Oxygen Box Assembly #3 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28380	0633	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354130	Aft Right Psu Oxygen Box Assembly #1 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28383	0615	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
354131	Aft Right Psu Oxygen Box Assembly #2 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28384	0405	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354132	Aft Right Psu Oxygen Box Assembly #3 - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	P28380	0634	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354208	Vestibule Oxygen Mask Box - Removal / Installation		HRS		3509.1			13.3			0
	P25027-1		AFL		722			5			0
		0086	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354212	Galley Oxygen Mask Box - Removal / Installation		HRS		3509.1			13.3			0
	P25059		AFL		722			5			0
		0427	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354214	Forward Lav Oxygen Mask Box - Removal / Installation		HRS		3509.1			13.3			0
	P25059		AFL		722			5			0
		0442	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354216	Aft Lav Oxygen Mask Box - Removal / Installation		HRS		3509.1			13.3			0
	P25059		AFL		722			5			0
		0445	MOS		123			27 Sep 2014			PACIFIC
			MSC				O/C				PRECISION
Airframe											
354218	Forward Left Psu Oxygen Mask #1 - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	P20076	NSN	MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
354219	Forward Left Psu Oxygen Mask #2 - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	P20076	NSN	MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											
354221	Forward Left Psu Oxygen Mask #4 - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	P20076	NSN	MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											
354222	Forward Left Psu Oxygen Mask #5 - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	P20076	NSN	MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											
354223	Forward Left Psu Oxygen Mask #6 - Removal / Installation		HRS		1158			2364.4			0
			AFL		239			488			0
	P20076	NSN	MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											
354231	Mid Left Psu Oxygen Mask #2 - Removal / Installation		HRS		1158			2364.4			0
	P20076	NSN	AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											
354233	Mid Left Psu Oxygen Mask #4 - Removal / Installation		HRS		1158			2364.4			0
	P20076	NSN	AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											
354242	Aft Left Psu Oxygen Mask #1 - Removal / Installation		HRS		1158			2364.4			0
	P20076	NSN	AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
354243	Aft Left Psu Oxygen Mask #2 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354244	Aft Left Psu Oxygen Mask #3 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354245	Aft Left Psu Oxygen Mask #4 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354254	Forward Right Psu Oxygen Mask #1 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354255	Forward Right Psu Oxygen Mask #2 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354257	Forward Right Psu Oxygen Mask #4 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354266	Mid Right Psu Oxygen Mask #1 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354268	Mid Right Psu Oxygen Mask #3 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
354278	Aft Right Psu Oxygen Mask #1 - Removal / Installation		HRS		1158			2364.4			0
	P20076 NSN		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354280	Aft Right Psu Oxygen Mask #3 - Removal / Installation		HRS		1158			2364.4			0
	P20076 NSN		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354281	Aft Right Psu Oxygen Mask #4 - Removal / Installation		HRS		1158			2364.4			0
	P20076 NSN		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354290	Vestibule Oxygen Mask #1 - Removal / Installation		HRS		1158			2364.4			0
	P20076 NSN		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354298	Galley Oxygen Mask #1 - Removal / Installation		HRS		1158			2364.4			0
	P20076 NSN		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354299	Galley Oxygen Mask #2 - Removal / Installation		HRS		1158			2364.4			0
	P20076 NSN		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354302	Forward Lav Oxygen Mask #1 - Removal / Installation		HRS		1158			2364.4			0
	P20076 NSN		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				
354306	Aft Lav Oxygen Mask #1 - Removal / Installation		HRS		1158			2364.4			0
	P20076 NSN		AFL		239			488			0
			MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
354307	Aft Lav Oxygen Mask #2 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
	NSN		MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											
354326	Cabin #4 Lh Psu Oxygen Mask #1 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
	NSN		MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											
354332	Cabin #4 Rh Psu Oxygen Mask #1 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
	NSN		MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											
354333	Cabin #4 Rh Psu Oxygen Mask #2 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
	NSN		MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											
354334	Cabin #4 Rh Psu Oxygen Mask #3 - Removal / Installation		HRS		1158			2364.4			0
	P20076		AFL		239			488			0
	NSN		MOS	TSN:2	49.9			30 Oct 2020			AVOX SYSTEMS
			MSC				O/C				
Airframe											
354338	Crew Rest Oxygen Mask Box Assembly Left #1 - Removal		HRS		3506.4			16			0
	/ Installation		AFL		721			6			0
	P28384	0509	MOS		122.4			13 Oct 2014			Pacific Precision
			MSC				O/C				Products
Airframe											
354339	Crew Rest Oxygen Mask Box Assembly Right #1 -		HRS		3509.1			13.3			0
	Removal / Installation		AFL		722			5			0
	P28382	0012	MOS		123			27 Sep 2014			Pacific Precision
			MSC				O/C				Products
Airframe											

36 - Pneumatic

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
3202908-36-1912	Sb 3202908-36-1912 - Honeywell Sb 3202908-36-1912 - Rework Four Inch Diameter Check Valve, Pn 3202908-1 to Pn 3202908-2, Used on the Gulfstream G650.		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
(361106)			MSC				-				
Airframe											
3202908-36-1912	Sb 3202908-36-1912 - Honeywell Sb 3202908-36-1912 - Rework Four Inch Diameter Check Valve, Pn 3202908-1 to Pn 3202908-2, Used on the Gulfstream G650.		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
(361107)			MSC				-				
Airframe											
361100	Hp Shut-Off Valve (Left) - Removal / Installation		HRS		3026.3			496.1			0
	3215974-1	315	AFL		617			110			0
			MOS		107.8			02 Jan 2016			
(361100)			MSC				O/C				
Airframe											
361101	Hp Shut-Off Valve (Right) - Removal / Installation		HRS		3026.3			496.1			0
	3215974-1	507	AFL		617			110			0
			MOS		107.8			02 Jan 2016			
(361101)			MSC				O/C				
Airframe											
361104	Pressure Regulating and Shut-Off Valve (Left) - Removal / Installation		HRS		3509.1			13.3			0
	3215662-2	1669	AFL		722			5			0
			MOS		122.5			10 Oct 2014			
(361104)			MSC				O/C				
Airframe											
361105	Pressure Regulating and Shut-Off Valve (Right) - Removal / Installation		HRS		3509.1			13.3			0
	3215662-2	1674	AFL		722			5			0
			MOS		122.5			10 Oct 2014			
(361105)			MSC				O/C				
Airframe											
361108	Hp Stage 5 AIR Nonreturn Valve (Left) - Removal / Installation		HRS	TSN:820.7	2981.9			540.5			0
	3202908-2	628	AFL	TSN:265	608			119			0
			MOS		105.4			13 Mar 2016			
(361108)			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361109	Hp Stage 5 AIR Nonreturn Valve (Right) - Removal / Installation		HRS		2981.9			540.5			0
			AFL		608			119			0
	3202908-2	629	MOS		105.4			13 Mar 2016			
			MSC				O/C				
Airframe											
361110	Hp Stage 5 AIR Nonreturn Valve (Left) - Restore		HRS	TSN:820.7	2981.9			540.5			0
	3202908-2		AFL	TSN:265	608			119			0
			MOS		105.4			13 Mar 2016			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 361108											
361111	Hp Stage 5 AIR Nonreturn Valve (Right) - Restore		HRS		2981.9			540.5			0
	3202908-2		AFL		608			119			0
			MOS		105.4			13 Mar 2016			
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 361109											
361112	Hp Stage 5 Bleed AIR Duct (Left) - Removal / Installation		HRS		3522.4			0			0
	RD001C0006-1011	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361113	Hp Stage 5 Bleed AIR Duct (Right) - Removal / Installation		HRS		1182.8			2339.6			0
	RD001C0006-1011	SN-UNKNOWN	AFL		243			484			0
			MOS		51.3			17 Sep 2020			
			MSC				O/C				
Airframe											
361116	Hp Stage 5 / Stage 8 Interface Y-Duct (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0006-1003	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361117	Hp Stage 5 / Stage 8 Interface Y-Duct (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0006-1003	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361120	Hp Stage 8 Bleed AIR Duct (Left) - Removal / Installation		HRS		3522.4			0			0
	RD001C0006-1013 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361121	Hp Stage 8 Bleed AIR Duct (Right) - Removal / Installation		HRS		3522.4			0			0
	RD001C0006-1013 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361124	Combined Bleed AIR Duct (Left) - Removal / Installation		HRS		3522.4			0			0
	RD001C0006-1004 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361125	Combined Bleed AIR Duct (Right) - Removal / Installation		HRS		3522.4			0			0
	RD001C0006-1004 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361128	Handed Bleed AIR Duct (Left) - Removal / Installation		HRS		3522.4			0			0
	RD001C0006-1007 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361129	Handed Bleed AIR Duct (Right) - Removal / Installation		HRS		3522.4			0			0
	RD001C0006-1007 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361132	Precooler AIR Off-Take (Left) - Removal / Installation		HRS		3522.4			0			0
	RD001C0006-4003 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361133	Precooler AIR Off-Take (Right) - Removal / Installation		HRS		3522.4			0			0
	RD001C0006-4003 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361136	Precooler AIR Duct (Left) - Removal / Installation		HRS		3522.4			0			0
	RD001C0006-4002	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361137	Precooler AIR Duct (Right) - Removal / Installation		HRS		3522.4			0			0
	RD001C0006-4002	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361140	Bleed AIR Ducts (Left) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361141	Bleed AIR Ducts (Right) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361142	Precooler AIR Duct (Left) - Inspection / Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361143	Precooler AIR Duct (Right) - Inspection / Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361144	High Stage 8 Check Valve (Left) - Removal / Installation		HRS		3082.6			439.8			0
	3215974-1	315	AFL		627			100			0
			MOS		107.8			02 Jan 2016			
	Airframe		MSC				O/C				
361145	High Stage 8 Check Valve (Right) - Removal / Installation		HRS		3082.6			439.8			0
	3215974-1	SN-UNKNOWN	AFL		627			100			0
			MOS		107.8			02 Jan 2016			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361148	Cabin AIR Ducts and Insulation Blankets - Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
361200	Bleed AIR Isolation Shut-Off Valve - Removal / Installation 3291826-13266		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
361201	Bleed AIR Controller (Left) - Removal / Installation 1153482-3\6(CSCI3)1153482-00582 6(CSC13)		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
361202	Bleed AIR Controller (Right) - Removal / Installation 1153482-3\6(CSCI3)1153482-00583 6(CSC13)		HRS		3339.5			182.9			0
			AFL		689			38		0	
			MOS		118.3		17 Feb 2015				
			MSC			O/C					
361206	Bleed AIR Isolation Shut-Off Valve - Manual Override		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
361207	APU Check Valve - Removal / Installation 3202754-11720		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
361209	APU Check Valve - Detailed Inspection		HRS		3522.4		6000	0	6000	6050	0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
						[HRS: +50/-50]					
361210	Bleed AIR Flow Control and Pressure Regulation (Left) - Operational Test		HRS		3026.3			496.1			0
			AFL		617			110		0	
			MOS		107.7		05 Jan 2016				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361211	Bleed AIR Flow Control and Pressure Regulation (Right) - Operational Test		HRS		3026.3			496.1			0
			AFL		617			110		0	
			MOS		107.7			05 Jan 2016			
			MSC			O/C					
Airframe											
361212	Servo Pressure Regulator / Torque Motor (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
361213	Servo Pressure Regulator / Torque Motor (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
361214	Bleed AIR System Sense Tubes (Left Hp Shutoff Valve) - Removal / Installation RD00104631-3 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
361215	Bleed AIR System Sense Tubes (Right Hp Shutoff Valve) - Removal / Installation RD00104631-3 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
361216	Bleed AIR System Sense Tubes (Left Manifold Pressure Shutoff Valve) - Removal / Installation RD00104631-2 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
361217	Bleed AIR System Sense Tubes (Right Manifold Pressure Shutoff Valve) - Removal / Installation RD00104631-2 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361218	Bleed AIR System Sense Tubes (Left Fan AIR Valve) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD00104631-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361219	Bleed AIR System Sense Tubes (Right Fan AIR Valve, Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD00104632-2	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361220	Bleed AIR System Sense Tubes (Right Fan AIR Valve, Mid) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD00104632-4	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361221	Bleed AIR System Sense Tubes (Right Fan AIR Valve, Y-Duct) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD00104632-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361401	Fan AIR Valve (Left) - Removal / Installation		HRS		3522.4			0			0
	3291954-2	310	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361402	Fan AIR Valve (Right) - Removal / Installation		HRS		3522.4			0			0
	3291954-2	317	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361403	Bleed AIR Precooler (Left) - Removal / Installation		HRS		3522.4			0			0
	2341172-1	894	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361404	Bleed AIR Precooler (Right) - Removal / Installation		HRS		3522.4			0			0
	2341172-2 908		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361405	Precooler Inlet Temperature Sensor (Left) - Removal / Installation		HRS		3522.4			0			0
	1150124-2 1150124-11268		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361406	Precooler Inlet Temperature Sensor (Right) - Removal / Installation		HRS		3522.4			0			0
	1150124-2 1150124-11016		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361407	Precooler Outlet Temperature Sensor (Left) - Removal / Installation		HRS		3522.4			0			0
	1150124-2 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361408	Precooler Outlet Temperature Sensor (Right) - Removal / Installation		HRS		3522.4			0			0
	1150124-2 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361417	Fan AIR Valve (Left) - Functional Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
361418	Fan AIR Valve (Right) - Functional Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361419	Bleed AIR Precooler (Left) - Cleaning		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
361420	Bleed AIR Precooler (Right) - Cleaning		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
361600	External AIR Connector - Removal / Installation 4663 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
361602	External AIR Connector Check Valve - Removal / Installation 3202754-1 1721		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
361606	External AIR Connector Duct (Lower) - Removal / Installation GA0236160213-1 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
361607	External AIR Connector Duct (Mid) - Removal / Installation GA0236160212-1 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
361608	External AIR Connector Duct (Upper) - Removal / Installation GA0236160210-1 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361612	Manifold Lower Bleed AIR Duct (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3616001A004	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361613	Manifold Lower Bleed AIR Duct (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3616001A005	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361616	Manifold Crossover AIR Duct (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GA236160102-5	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361617	Manifold Crossover AIR Duct (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GA236160102-7	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361620	Pack Inlet Supply AIR Duct (Left) - Removal / Installation		HRS		3522.4			0			0
	GA236160106-1		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361621	Pack Inlet Supply AIR Duct (Right) - Removal / Installation		HRS		3522.4			0			0
	GA236160103-1		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361624	Precooler Ducting (Left Precooler Inlet) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GA0236160001-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361625	Precooler Ducting (Left Precooler Outlet) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GA0236160002-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361626	Precooler Ducting (Left Fan AIR Valve) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GA0236160003-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361627	Precooler Ducting (Left Outflow) - Removal / Installation		HRS		3522.4			0			0
	GA0236160004-1		AFL		727			0			0
	SN-UNKNOWN		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361632	Precooler Ducting (Right Precooler Inlet) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GA0236160001-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361633	Precooler Ducting (Right Precooler Outlet) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GA0236160002-1	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361634	Precooler Ducting (Right Fan AIR Valve) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	GA0236160003-2	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
361635	Precooler Ducting (Right Outflow) - Removal / Installation		HRS		3522.4			0			0
	GA0236160004-11		AFL		727			0			0
	SN-UNKNOWN		MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
362100	Manifold Pressure Sensor (Left) - Removal / Installation		HRS		3522.4			0			0
	1151584-1	1151584-06853	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
362101	Manifold Pressure Sensor (Right) - Removal / Installation		HRS		3522.4			0			0
	1151584-1	1151584-06581	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
38 - Water/Waste											
381000	Water System - Operational Test		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.9			30 Oct 2023			
	Airframe		MSC				O/C				
381002	Potable Water System (System A) - Cleaning / Sanitizing		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			18 Sep 2016			
	Airframe		MSC				O/C				
381003	Potable Water System (System B) - Cleaning / Sanitizing		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			18 Sep 2016			
	Airframe		MSC				O/C				
381029	Bidet Drain Valve - Removal / Installation		HRS		3509.1			13.3			0
	4E4350-1	N1405712	AFL		722			5			0
			MOS		123			27 Sep 2014			GOODRICH
	Airframe		MSC				O/C				
381200	Water System Level Indicators - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381201	Level Sensor Assembly (System A, Full) - Removal / Installation		HRS		1508.2			2014.2			0
			AFL		311			416			0
	3E3723-1	NSN	MOS	TSN:6	63.1			24 Sep 2019			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381211	Water System Level Indicator (Internal) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4884-2	U4541	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
381212	Water System Level Indicator (External) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4884-1	U3666	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
381215	Water Sterilizer Quartz Glass Sheath (System A) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	NPN	NSN	MOS		13.8			31 Oct 2023			N/A
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 381225											
381216	Water Sterilizer Quartz Glass Sheath (System B) - Removal / Installation		HRS	TSN:3408.5	113.9			3408.5			0
			AFL	TSN:691	36			691			0
	09-130121-303	1132	MOS	TSN:113	14.2			19 Oct 2023			N/A
			MSC				O/C				
Airframe											
Notes: MRI PARENT CODE: 381226											
381219	Clean Water Sterilizer Quartz Glass Sheath and Uv Sensor Window (System A) - Restore		HRS		113.9		1000	3408.5	4408.5		0
			AFL		36			691			0
			MOS		13.8			31 Oct 2023			
Airframe											
381220	Clean Water Sterilizer Quartz Glass Sheath and Uv Sensor Window (System B) - Restore		HRS		113.9		1000	3408.5	4408.5		0
			AFL		36			691			0
			MOS		14.2			19 Oct 2023			
Airframe											
381221	Water Sterilizer Filter (System A) - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	05-01-0001	NSN	MOS	TSN:6	14.2			19 Oct 2023			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381222	Water Sterilizer Filter (System B) - Removal / Installation		HRS		113.9			3408.5			0
	05-01-0001	NSN	AFL		36			691			0
			MOS	TSN:6	14.2			19 Oct 2023			N/A
	Airframe		MSC				O/C				
381225	Water Sterilizer (System A) - Removal / Installation		HRS		113.9			3408.5			0
	09-130321-001	1546	AFL		36			691			0
			MOS		13.8			31 Oct 2023			INTERNATIONAL
	Airframe		MSC				O/C				WATER GUARD
381226	Water Sterilizer (System B) - Removal / Installation		HRS		113.9			3408.5			0
	09-130121-304	1806	AFL		36			691			0
			MOS		14			25 Oct 2023			N/A
	Airframe		MSC				O/C				
381229	Water Sterilizer Germicidal Lamp (System A) - Removal / Installation		HRS		113.9			3408.5			0
	02-160202-006	NSN	AFL		36			691			0
			MOS		13.8			31 Oct 2023			N/A
	Airframe		MSC				O/C				
381230	Water Sterilizer Germicidal Lamp (System B) - Removal / Installation		HRS	TSN:3408.5	113.9			3408.5			0
			AFL	TSN:691	36			691			0
	02-160202-005	NSN	MOS	TSN:113	14.2			19 Oct 2023			N/A
	Airframe		MSC				O/C				
381233	Water Sterilizer Germicidal Lamp (System A) - Discard		HRS		3522.4		4600	0	4600		0
	08-130800-003	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			International Water
	Airframe										-Guard
Notes: MRI PARENT CODE: 381229											
381234	Water Sterilizer Germicidal Lamp (System B) - Discard		HRS		3522.4		4600	0	4600		0
	08-130800-003	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			International Water
	Airframe										-Guard

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381239	Water Sterilizer Sediment Filter Cartridge (System A, Polypropylene Filter) - Discard		HRS		113.9		1000	3408.5	4408.5		0
			AFL		36			691			0
	05-01-0001	NSN	MOS	TSN:6	14.2			19 Oct 2023			N/A
Airframe											
381240	Water Sterilizer Sediment Filter Cartridge (System B, Polypropylene Filter) - Discard		HRS		113.9		1000	3408.5	4408.5		0
			AFL		36			691			0
	05-01-0001	NSN	MOS	TSN:6	14.2			19 Oct 2023			N/A
Airframe											
381300	Water Tank Motor Shut-Off Valve (System A V2A) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4872-1	N1307702	MOS		128.2			21 Apr 2014			
Airframe											
381301	Water Tank Motor Shut-Off Valve (System B V2B) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4872-2	N1322601	MOS		128.2			21 Apr 2014			
Airframe											
381306	Water Supply Line Motor Drain Valve (System A, V3A) - Removal / Installation		HRS		3339.5			182.9			0
			AFL		689			38			0
	4E4873-11	N1101401	MOS		118.3			17 Feb 2015			
Airframe											
381307	Water Supply Line Motor Drain Valve (System B, V3B) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4873-2	N1304602	MOS		128.2			21 Apr 2014			
Airframe											
381314	Water Supply Line Motor Drain Valve (System A V4A) - Removal / Installation		HRS		285.9			3236.5			0
			AFL		61			666			0
	4E4874-22	N1930905	MOS		18.4			15 Jun 2023			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381315	Water Supply Line Motor Drain Valve (System A V11A) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4872-3	N1312001	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
381316	Water Supply Line Motor Drain Valve (System B V11B) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4872-4	N1314401	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
381317	Water Supply Line Motor Drain Valve (System B V4B) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4874-2	N1321001	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
381318	Water Supply Line Motor Drain Valve - Operational Test		HRS		285.9			3236.5			0
			AFL		61			666			0
			MOS		18.4			15 Jun 2023			
			MSC				O/C				
Airframe											
Notes: PN: 4E4875-2 SN: <NONE>.											
381320	Water Drain Line Motor Drain Valve (V5) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4875-3	N1311602	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
381322	Drain Line Motor Drain Valve - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: PN: 4E4875-2 SN: <NONE>.											
381325	Aft Drain Mast - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4878-5	N1331601	MOS	TSN:5	128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381340	Water Supply Fill Port (System A) - Removal / Installation		HRS		3522.4			0			0
	3E3203-3	J24719-1	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381341	Water Supply Fill Port (System B) - Removal / Installation		HRS		3522.4			0			0
	3E3203-3	J27903-2	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381344	Water System Servicing Cable (System A) - Rigging		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381345	Water System Servicing Cable (System B) - Rigging		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381346	Water System Servicing Cable (System A) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4877-1	12033	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381347	Water System Servicing Cable (System B) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4877-2	12045	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381400	Conformal Water Tank (System A) - Removal / Installation		HRS		1508.2			2014.2			0
	4E4979-1	N1315102	AFL		311			416			0
			MOS		63			27 Sep 2019			
	Airframe		MSC				O/C				
381401	Conformal Water Tank (System B) - Removal / Installation		HRS		3522.4			0			0
	4E4979-2	N1312201	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381424	Water Tank - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	4	48	27 Oct 2022	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
381500	Water Tank Motor Shut-Off Valve Heater (System A, V2A)		HRS		3522.4			0			0
	- Removal / Installation		AFL		727			0			0
	4E4882-103	8200	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381501	Water Tank Motor Shut-Off Valve Heater (System B, V2B)		HRS		3522.4			0			0
	- Removal / Installation		AFL		727			0			0
	4E4882-108	M780	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381504	Water Supply Line Drain Fitting Heater - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	4E4887-104	D144	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381505	Water Drain Line Motor Drain Valve Heater (V5) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	4E4882-102	M580	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381508	Water Supply Line Motor Drain Valve Heater (System A, V4A) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4882-105	G128	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
381509	Water Supply Line Motor Drain Valve Heater (System B, V4B) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4882-101	L613	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381510	Water Supply Line Motor Drain Valve Heater (System A, V3A) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4882-106	M072	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
381511	Water Supply Line Motor Drain Valve Heater (System B, V3B) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4882-109	L987	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
381512	Water Supply Line Innerline Heater (System A, Left Aft Supply Drain) - Removal / Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
	4E4880-129	U06209	MOS	TSN:1	38.9			30 Sep 2021			
			MSC				O/C				
Airframe											
381513	Water Supply Line Innerline Heater (System B, Left Aft Supply Drain) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4880-130	U00534	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
381517	Water System Heaters - Operational Test		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.8			02 Oct 2021			
			MSC				O/C				
Airframe											
381520	Aft Drain Mast Controller - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4952-101	U5964	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
381530	Forward Drain Port - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4879-101	N12003002	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381550	Water Supply Line Innerline Heater (System A) - Removal / Installation		HRS		1508.2			2014.2			0
			AFL		311			416			0
	4E4880-132	U00662	MOS	TSN:13	62.9			29 Sep 2019			
			MSC				O/C				
Airframe											
381555	Water Drain Line Innerline Heater (Forward Drain) - Removal / Installation		HRS		2755.9			766.5			0
			AFL		561			166			0
	4E4880-124	U02204	MOS	TSN:2	99.2			20 Sep 2016			
			MSC				O/C				
Airframe											
381564	Water Supply Line Motor Drain Valve Heater (System A, V11A) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4882-110	E761	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
381597	Water Heater- Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	MRX-1000-102	1002-2698	MOS		123			27 Sep 2014			DYNAMO
			MSC				O/C				
Airframe											
381598	Water Heater (Lav) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	MX-1000-102	1002-2700	MOS		123			27 Sep 2014			DYNAMO
			MSC				O/C				
Airframe											
381599	Water Heater (Galley) (No. 1) - Removal / Installation		HRS		3133.7			388.7			0
			AFL		652			75			0
	MRX-3000-505	3005-086	MOS		111.3			18 Sep 2015			DYNAMO
			MSC				O/C				
Airframe											
381602	Check Valve, Aft Lavatory - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4916-1	N1405605	MOS		123			27 Sep 2014			GOODRICH
			MSC				O/C				
Airframe											
381604	Check Valve, Forward Galley - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E4350-1	N1325605	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381608	Check Valve, Forward Galley Annex - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4350-1	N1331738	MOS		123			27 Sep 2014			GOODRICH
			MSC				O/C				
Airframe											
381612	Manual Supply Valve, Forward Galley - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4474-1	N1327520	MOS		123			27 Sep 2014			GOODRICH
			MSC				O/C				
Airframe											
381616	Manual Drain Valve, Forward Galley - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4474-1	N1327519	MOS		123			27 Sep 2014			GOODRICH
			MSC				O/C				
Airframe											
381624	Manual Supply Valve, Aft Vanity - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4474-1	N1327501	MOS		123			27 Sep 2014			GOODRICH
			MSC				O/C				
Airframe											
381626	Manual Drain Valve, Aft Vanity - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4474-1	N1327502	MOS		123			27 Sep 2014			GOODRICH
			MSC				O/C				
Airframe											
381628	Coffee Drain Valve - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	300-0015-01	33135252	MOS		123			27 Sep 2014			PARKER
			MSC				O/C				
Airframe											
381700	Drain Valve, Aft Lav Bidet - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4474-1	N1327504	MOS		123			27 Sep 2014			GOODRICH
			MSC				O/C				
Airframe											
383100	Vacuum Toilet (Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7900446	0137	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
383101	Vacuum Toilet (Forward) - Removal / Installation		HRS		3522.4			0			0
	7900446	0139	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
383104	Vacuum Toilet System (Forward) - Cleaning		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	25	12	06 Oct 2024	31 Oct 2025*	30 Nov 2025	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
383105	Vacuum Toilet System (Aft) - Cleaning		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	25	12	06 Oct 2024	31 Oct 2025*	30 Nov 2025	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
383106	Vacuum Toilet Waste Line - Cleaning		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6			06 Oct 2024			
	Airframe		MSC				O/C				
383107	Vacuum Toilet Flush Control Unit (Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7800551\06.00	0193	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
383108	Vacuum Toilet Flush Control Unit (Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	7800551\06.00	0234	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
383150	Bidet Water Heater - Removal / Installation		HRS		3509.1			13.3			0
	MRX1000-509	1059-88	AFL		722			5			0
			MOS		123			27 Sep 2014			DYNAMO
	Airframe		MSC				O/C				
383300	Vacuum Generator - Removal / Installation		HRS		3522.4			0			0
	7800403-1	0293	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
383302	Waste Tank Point Level Sensor - Removal / Installation		HRS	TSN:1799.9	1722.5			1799.9			0
	7800494	0129	AFL	TSN:376	351			376			0
			MOS	TSN:59	68.8			31 Mar 2019			N/A
	Airframe		MSC				O/C				
383304	Waste Tank Ambient Absolute Pressure Sensor - Removal / Installation		HRS	TSN:2364.5	1158			2364.4			0
			AFL	TSN:488	239			488			0
	7800480	O147	MOS	TSN:79	49.7			04 Nov 2020			N/A
	Airframe		MSC				O/C				
383306	Waste Tank Hydrostatic Absolute Pressure Sensor - Removal / Installation		HRS		.4			3522			0
			AFL		1			726			0
	7800548	0312	MOS		2.7			03 Oct 2024			N/A
	Airframe		MSC				O/C				
383308	Waste Tank Sensor - Cleaning		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		49.7			04 Nov 2020			
	Airframe		MSC				O/C				
383310	Waste Tank - Removal / Installation		HRS		3522.4			0			0
	7900402-5	0019	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
383325	Supply A/B/Drain 3 Way Valve (548L6) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4916-1	N1326202	MOS		123			27 Sep 2014			GOODRICH
	Airframe		MSC				O/C				
383326	Supply A/B/Drain 3 Way Valve (548L5) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4916-1	N1405601	MOS		123			27 Sep 2014			GOODRICH
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
383327	Sink Water Service/Drain Valve (548L1) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4916-5	N1329702	MOS		123			27 Sep 2014			GOODRICH
			MSC				O/C				
Airframe											
383328	Supply A/B/Drain 3 Way Valve (548L2) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4916-3	N1329704	MOS		123			27 Sep 2014			GOODRICH
			MSC				O/C				
Airframe											
383329	Supply A/B/Drain 3 Way Valve (548L4) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4916-3	N1328203	MOS		123			27 Sep 2014			GOODRICH
			MSC				O/C				
Airframe											
383330	Sink Water Service/Drain Valve (548L3) - Removal / Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
	4E4916-5	N1329703	MOS		123			27 Sep 2014			GOODRICH
			MSC				O/C				
Airframe											
384100	AIR Compressor - Removal / Installation		HRS		3462.9			59.5			0
			AFL		712			15			0
	4E3271-1	04110111	MOS		121.2			21 Nov 2014			
			MSC				O/C				
Airframe											
384101	AIR Compressor Line AIR Filter - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	3E3291-1	1978	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
384106	Bleed AIR Line AIR Filter - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	3E3291-1	1981	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
384200	Bleed AIR Supply Shut-Off Valve - Removal / Installation		HRS		3522.4			0			0
	4E4876-1	N1306401	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
384201	AIR Compressor Line Pressure Relief Valve - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	4E3263-1	3365	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
44 - Cabin Systems											
441101	Left Gulfstream Cabin Management System Input / Output Concentrator - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	GCMS-02-002	06846	MOS	TSN:1	14			25 Oct 2023			GULFSTREAM AEROSPACE
	Airframe		MSC				O/C				
441102	Gulfstream Cabin Management System - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: PN: GCMS-02-001\1 SN: 02105. MRI PARENT CODE: 441101											
441103	Right Gulfstream Cabin Management System Input / Output Concentrator - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	GCMS-02-002	06860	MOS	TSN:1	14			25 Oct 2023			GULFSTREAM AEROSPACE
	Airframe		MSC				O/C				
441105	Aft No. 1 Input / Output Concentrator - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	GCMS-02-002	06853	MOS	TSN:1	14			25 Oct 2023			GULFSTREAM AEROSPACE
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
441107	Aft No. 2 Input / Output Concentrator - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	GCMS-02-002	06848	MOS	TSN:1	13.8			31 Oct 2023			GULFSTREAM
			MSC				O/C				AEROSPACE
Airframe											
441109	Left Gulfstream Cabin Management System Controller - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	GCMS-02-002	06849	MOS	TSN:1	14			25 Oct 2023			GULFSTREAM
			MSC				O/C				AEROSPACE
Airframe											
441111	Right Gulfstream Cabin Management System Controller - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	GCMS-02-002	06859	MOS	TSN:1	14			25 Oct 2023			GULFSTREAM
			MSC				O/C				AEROSPACE
Airframe											
441113	Gulfstream Cabin Management System Maintenance Server - Removal / Installation		HRS		113.9			3408.5			0
			AFL		36			691			0
	GCMS-02-002	06852	MOS	TSN:1	14			25 Oct 2023			GULFSTREAM
			MSC				O/C				AEROSPACE
Airframe											
449002	Gcms S/B 002 Cabin System Firmware Update 1.9.1		HRS		3522.4			0			0
			AFL		727			0			0
			MOS								
			MSC				O/C				
Airframe											
449004	Csb 003A - Advanced Cabin Server (Acs) System Firmware Update 4.4.3.3		HRS		3522.4			0			0
			AFL		727			0			0
			MOS								
			MSC				O/C				
Airframe											
46 - Information Systems											
462100	Data LAN Management Unit - Removal / Installation		HRS		3278			244.4			0
	940-000175-211	211-0287	AFL		680			47			0
			MOS		115.7			03 May 2015			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
462102	Data LAN Management Unit - Operational Test		HRS		3278			244.4			0
			AFL		680			47			0
			MOS		115.7			03 May 2015			
			MSC				O/C				
463500	Aircraft Health and Trend Monitoring Unit - Removal / Installation 186702-003\B0000121		HRS	TSN:388.7	3133.7			388.7			0
			AFL	TSN:75	652			75			0
			MOS	TSN:17	111.2			21 Sep 2015			
			MSC				O/C				
463502	Aircraft Health and Trend Monitoring System - Operational Test		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99			26 Sep 2016			
			MSC				O/C				
463505	Wireless Data Network Unit - Removal / Installation 100-004-745-0050409D9A05BB		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS	TSN:2	99			26 Sep 2016			
			MSC				O/C				
463507	Remote Data Concentrator - Removal / Installation 804-1250\AB1240005AB		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
463509	Aircraft Health and Trend Monitoring System - Maintenance Laptop Setup		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
463510	Aircraft Health and Trend Monitoring System - Access Menu Functions		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
463511	Loadable Avionics Software Configuration (Options Disk)		HRS		113.9			3408.5			0
	TT60004484-60073		AFL		36			691			0
	NSN		MOS		13.8			01 Nov 2023			HONEYWELL
	Airframe		MSC				O/C				
463512	Loadable Health Information Software Configuration (Lhi Disk)		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		13.8			01 Nov 2023			
	Airframe		MSC				O/C				
Notes: PN: LHI0104-101816-011-002 SN: 6088.											
463514	Told Database		HRS		113.9			3408.5			0
	60002374-006		AFL		36			691			0
	NSN		MOS		13.8			01 Nov 2023			GAC
	Airframe		MSC				O/C				
49 - Airborne Auxiliary Power											
490001	APU - APU - Removal / Installation		HRS		1704			0			0
	WE3800836-1		APUS		0			0			0
	P-198		MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				
490003	APU - APU - Functional Test		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				
491104	Isolator Mounts - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
491107	Mount Bracket - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
491205	APU Inlet Door Actuator - Removal / Installation		HRS		3522.4			0			0
	SYLC-52630-2		AFL		727			0			0
	NSN		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
491206	APU AIR Inlet Door Actuator - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
491207	APU Inlet Door Actuator - Inspection / Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
491215	APU AIR Inlet Ducts and APU Inlet Boot Assemblies -		HRS		.4			3522			0
	General Visual Inspection		AFL		1			726			0
			MOS		2.5	14	120	09 Oct 2024	31 Oct 2034*	30 Nov 2034	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
491217	APU AIR Inlet Duct Door and Actuator - Detailed		HRS		485.9			3036.5			0
	Inspection		AFL		97			630			0
			MOS		25.5	-10	48	10 Nov 2022	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
491300	APU Turbine Plenum Drain - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5	19	24	12 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
491301	APU Drains - Operational Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
491302	APU Compartment Drains - General Visual Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	24	24	07 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
491303	Interior and Exterior Surfaces of APU Compartment (APU Box) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26		48	25 Oct 2022	25 Oct 2026	25 Nov 2026	
			[MOS: +1m/-1m]								
Airframe											
491304	APU Compartment Drains - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5	22	24	09 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe											
492000	APU - APU Combustor - Wash		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
			MSC				O/C				
APU											
492001	APU - APU Fuel and Oil System (External) - General Visual Inspection		HRS		234.5		600	1469.5	2069.5	2119.5	0
			APUS		0			0			0
			MOS		26			26 Oct 2022			
			[HRS: +50/-50]								
APU											
492100	APU - Branched Wiring Harness - Removal / Installation WE3888569-1 13-150262-34915		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
			MSC				O/C				
APU											
492102	APU - Branched Wiring Harness (Wiring Harness) - General Visual Inspection		HRS		234.5		600	1469.5	2069.5	2119.5	0
			APUS		0			0			0
			MOS		26			26 Oct 2022			
			[HRS: +50/-50]								
APU											
492300	APU - Compressor Impeller - Discard WB3822573-1 13-162053-58569		HRS		1704		10000	0	10000		0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
APU											
492301	APU - First Stage Turbine Rotor Disc - Discard WK3840141-3 132241002816		HRS		1704		10000	0	10000		0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
492302	APU - Second Stage Turbine Rotor - Discard		HRS		1704		10000	0	10000		0
	WE897994-3		APUS		0			0			0
	13-156101-06967		MOS		132.3				16 Dec 2013		
	APU										
492303	APU - APU Compressor and Turbine Section - Rotation		HRS		1704			0			0
	Check and / or Borescope Inspection		APUS		0			0			0
			MOS		132.3				16 Dec 2013		
	APU		MSC				O/C				
493000	APU - Engine Fuel and Control System - Inspection		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3				16 Dec 2013		
	APU		MSC				O/C				
493100	APU - Fuel Control Unit - Removal / Installation		HRS		1704			0			0
	441903-4		APUS		0			0			0
	CUB10944		MOS		132.3				16 Dec 2013		
	APU		MSC				O/C				
493104	APU - Fuel Filter Element - Removal / Installation		HRS	TSN:153.5	51			1653			0
	3882496-1		APUS		0			0			0
	SN-UNKNOWN		MOS	TSN:17	6.2				19 Jun 2024		
	APU		MSC				O/C				
493106	Seal Witness Drain - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2				21 Apr 2014		
	Airframe		MSC				O/C				
493108	APU - Fuel Strainer Element (Strainer) - Inspection /		HRS		1704			0			0
	Check		APUS		0			0			0
			MOS		132.3				16 Dec 2013		
	APU		MSC				O/C				
493402	APU - Fuel Filter Bypass Indicator - Detailed Inspection		HRS		234.5		600	1469.5	2069.5	2119.5	0
	(Delta P Indicator)		APUS		0			0			0
			MOS		26				26 Oct 2022		
	APU		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
494100	APU - Ignition Exciter - Removal / Installation		HRS		1018			686			0
	WE3876295-6 J1727013		APUS		0			0			0
			MOS		84.7			03 Dec 2017			
	APU		MSC				O/C				
494110	APU - Igniter Plug Lead (A) - Inspection		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				
494111	APU - Igniter Plug Lead (B) - Inspection		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				
494112	APU - Igniter Plug (A) - Inspection		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				
494113	APU - Igniter Plug (B) - Inspection		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				
494114	APU - Igniter Plug (A) - Cleaning		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				
494115	APU - Igniter Plug (B) - Cleaning		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				
494116	APU - Igniter Plug Lead (A) Electrical Properties - Inspection		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
494117	APU - Igniter Plug Lead (B) Electrical Properties - Inspection		HRS		1704			0			0
			APUS		0			0		0	
			MOS		132.3			16 Dec 2013			
			MSC				O/C				
APU											
494200	APU - Starter Motor - Removal / Installation 2704554-3 2685		HRS		1704			0			0
			APUS		0			0		0	
			MOS		132.3			16 Dec 2013			
			MSC				O/C				
APU											
494202	APU - Starter Motor - Detailed Inspection		HRS		234.5		600	1469.5	2069.5	2119.5	0
			APUS		0			0		0	
			MOS		26			26 Oct 2022			
			[HRS: +50/-50]								
APU											
494203	APU - Starter Motor - Cleaning		HRS		1704			0			0
			APUS		0			0		0	
			MOS		132.3			16 Dec 2013			
			MSC				O/C				
APU											
495100	APU - Surge Control Valve - Removal / Installation 3291212-4 1607		HRS		1704			0			0
			APUS		0			0		0	
			MOS		132.3			16 Dec 2013			
			MSC				O/C				
APU											
495101	APU - Load Control Valve - Removal / Installation 3291210-6 2649		HRS		1704			0			0
			APUS		0			0		0	
			MOS		132.3			16 Dec 2013			
			MSC				O/C				
APU											
495104	APU - Load Control Valve Filter - Removal / Cleaning / Installation		HRS		1704			0			0
			APUS		0			0		0	
			MOS		132.3			16 Dec 2013			
			MSC				O/C				
APU											
495200	APU - Bleed Diffuser - Removal / Installation WB3827396-1 13-162684-00759		HRS		1704			0			0
			APUS		0			0		0	
			MOS		132.3			16 Dec 2013			
			MSC				O/C				
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
496100	Electronic Control Unit - Removal / Installation		HRS		1722.5			1799.9			0
	WE3888570-3	2119326-00098	AFL		351			376			0
			MOS		68.7			05 Apr 2019			Honeywell
	Airframe		MSC				O/C				
496110	APU - Inlet Pressure Sensor - Removal / Installation		HRS		1704			0			0
	WE3876283-1	13112141812	APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				
497502	APU - Time Totalizing Meter - Read and Record		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				
498100	APU - APU Exhaust Duct (Internal Only) - General Visual Inspection		HRS		234.5		600	1469.5	2069.5	2119.5	0
			APUS		0			0			0
			MOS		26			26 Oct 2022			
	APU		[HRS: +50/-50]								
498101	APU - APU Fluted Exhaust and Turbine Bearing Support - General Visual Inspection		HRS		234.5		600	1469.5	2069.5	2119.5	0
			APUS		0			0			0
			MOS		26			26 Oct 2022			
	APU		[HRS: +50/-50]								
499000	APU - APU Oil System - Inspection		HRS		1704			0			0
			APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				
499002	APU - APU Soap Sample		HRS		46		500	1658	2158		0
			APUS		0			0			0
			MOS		2.4	-10	12	13 Oct 2024	31 Oct 2025*		
	APU		[End Of Month Item]								
499100	APU - Lube Pump Assembly - Removal / Installation		HRS		1704			0			0
	WE3881781-1	VE3316	APUS		0			0			0
			MOS		132.3			16 Dec 2013			
	APU		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
499202	APU - Lube and Generator Filter Elements - Removal / Installation		HRS		157			1547			0
			APUS		0			0			0
	WE3881767-1	NSN	MOS		13.8			31 Oct 2023			N/A
			MSC				O/C				
APU											
499204	APU - Chip Collector - Inspection		HRS		157			1547			0
			APUS		0			0			0
			MOS		14.3			17 Oct 2023			
			MSC				O/C				
APU											
499300	APU - AIR / Oil Cooler - Removal / Installation		HRS		1704			0			0
	160534-1	2539	APUS		0			0			0
			MOS		132.3			16 Dec 2013			
			MSC				O/C				
APU											
49APU1	APU		HRS		3522.4			0			0
	WE3800836-1	P-198	AFL		727			0			0
			MOS		130			27 Feb 2014			
			MSC				E/C				
Airframe											
APU-49 R11	APU - Sil APU-49 R11 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus)		HRS								0
			APUS								0
			DATE								
			MSC				-				
APU											
51 - STD Practices and Struct-Genrl											
512413	External Metallic Surfaces - Polishing		HRS		51.5			3470.9			0
			AFL		18			709			0
			MOS		8.5			12 Apr 2024			
			MSC				O/C				
Airframe	[End Of Month Item]										
Notes: REF IN PROCESS WORK FLOW INDEX #15 COMPLETED BY SHARPE DETAILS.											
52 - Doors											
520001	Fuselage Doors (External) - Zonal Inspection		HRS		1158.2			2364.2			0
			AFL		240			487			0
			MOS		50.2	3	72	20 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
520002	Fuselage Doors (Interior) - Zonal Inspection		HRS		3522.4			0			0
			AFL		727		0			0	
			MOS		122.1	144	23 Oct 2014	31 Oct 2026	30 Nov 2026		
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
521001	Main Entrance Door (Internal) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97		630				0
			MOS		25.5	-11	48	11 Nov 2022	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
521002	Main Entrance Door - FS 273 - FS 309 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97		630				0
			MOS		25.5	-19	96	11 Nov 2022	31 Oct 2030*	30 Nov 2030	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
521003	Main Entrance Door Viewport - Operational Check		HRS		1158			2364.4			0
			AFL		239		488				0
			MOS		50.5			09 Oct 2020			
	Airframe	MSC O/C									
521004	Main Entrance Door Cockpit Overhead Panel Safety Switch - Operational Check		HRS		.4			3522			0
			AFL		1		726				0
			MOS		2.6	25	24	06 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
521005	Main Entrance Door - Functional Check		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.5			09 Oct 2024			
	Airframe	[HRS: +50/-50]									
521012	Main Entrance Door Locking Actuator - Removal / Installation 60P5210915Z0010168		HRS		3133.7			388.7			0
			AFL		652		75				0
			MOS	TSN:8	110.9		29 Sep 2015				
	Airframe	MSC O/C									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
521016	Main Entrance Door Latching Actuator - Removal / Installation		HRS		1841.9			1680.5			0
			AFL		384			343			0
	60P5210905Z102	1117	MOS		73.9			29 Oct 2018			Woodward
			MSC				O/C				
Airframe											
Notes: TQ WRENCH: 562715 CAL: 07/19											
521025	Main Entrance Door Rigging - Adjustment / Test		HRS		1841.9			1680.5			0
			AFL		384			343			0
			MOS		73.7			03 Nov 2018			
			MSC				O/C				
Airframe											
521100	Main Entrance Door Fuselage Surround and Support Structure - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.5	-19	96	11 Nov 2022 31 Oct 2030*	30 Nov 2030		
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
521102	External Door Locks - Key Code		HRS		3522.4			0			0
	ASG650M-17P2	8MA000479CL	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
521210	Main Entrance Door - Removal / Installation		HRS	TSN:1680.5	1841.9			1680.5			0
	60P5210101N001	NSN	AFL	TSN:343	384			343			0
			MOS	TSN:55	73.7			03 Nov 2018			
			MSC				O/C				
Airframe											
Notes: TQ WRENCH: 562715 CAL: 07/19TQ WRENCH: 560120 CAL: 11/18											
521216	Airstair Bottom Folding Step - Adjustment / Test		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			09 Oct 2024			
			MSC				O/C				
Airframe											
521217	Main Entrance Door Handrail - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
521226	Main Entrance Door Airstair - Removal / Installation		HRS		.4			3522			0
	60P5210000N006	NSN	AFL		1			726			0
			MOS		2.5			09 Oct 2024			N/A
	Airframe		MSC				O/C				
521300	Main Entrance Door Latching and Locking System -		HRS		3522.4			0			0
	General Visual Inspection		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
521301	Main Entrance Door Pressure Relief Valve - General		HRS		3522.4			0			0
	Visual Inspection		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
521302	Main Entrance Door Pressure Relief Valve Seal - Detailed		HRS		.4			3522			0
	Inspection		AFL		1			726			0
			MOS		2.6	17	120	06 Oct 2024	31 Oct 2034*	30 Nov 2034	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
521303	Main Entrance Door Latching Actuator - Discard		HRS	TSN:502.8	3133.7			388.7			0
	60P5210905Z002	0040	AFL	TSN:152	652		5000	75	4923		0
			MOS	TSN:30	111.5			09 Sep 2015			
	Airframe										
Notes: MRI PARENT CODE: 521016											
521304	Main Entrance Door Pressure Relief Valve - Detailed		HRS		.4			3522			0
	Inspection		AFL		1			726			0
			MOS		2.6	17	120	06 Oct 2024	31 Oct 2034*	30 Nov 2034	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
521400	Main Entrance Door Damper - Removal / Installation		HRS		1039.9			2482.5			0
	72P5210904Z005	0222	AFL		216			511			0
			MOS		43.7			03 May 2021			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
521401	Main Entrance Door Actuator - Removal / Installation		HRS		1079.5			2442.9			0
	60P5210902Z002	0359	AFL		222			505			0
			MOS		45.3			18 Mar 2021			
	Airframe		MSC				O/C				
521406	Main Entrance Door Selector Valve - Removal / Installation		HRS		3522.4			0			0
	60P2910032Z001	0073	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
521410	Main Entrance Door Damper - Discard		HRS		1039.9			2482.5			0
	72P5210904Z005	0222	AFL		216			511			0
			MOS		43.7			03 May 2021			
	Airframe		MSC				O/C				
521500	Main Entrance Door Inner and Outer Seal - General Visual Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	60	27 Sep 2024	31 Oct 2029*	30 Nov 2029	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
521501	Main Entrance Door (Inner) Seal - Removal / Installation		HRS		3133.7			388.7			0
	60P5210901Z009	NSN	AFL		652			75			0
			MOS		111.3			17 Sep 2015			
	Airframe		MSC				O/C				
521503	Main Entrance Door (Outer) Seal - Removal / Installation		HRS		3133.7			388.7			0
	60P5210901Z010	NSN	AFL		652			75			0
			MOS		111.3			17 Sep 2015			
	Airframe		MSC				O/C				
522000	Emergency Exit Doors - Functional Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.2	-19	48	19 Nov 2022	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
522001	Emergency Exit Door Seals - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.2	-19	48	19 Nov 2022	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
522200	Emergency Exit Door FS 616.5 (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	60P5220101M020	S02268110	MOS	TSN:102	25.2			19 Nov 2022			
			MSC				O/C				
Airframe											
522201	Emergency Exit Door FS 616.5 (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	60P5220101M020	S02268114	MOS	TSN:102	25.2			19 Nov 2022			
			MSC				O/C				
Airframe											
522202	Emergency Exit Doors - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
522203	Emergency Exit Doors Internal Structure - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
522204	Emergency Exit Door FS 564 (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	60P5220101M020	S02268115	MOS	TSN:102	25.2			19 Nov 2022			
			MSC				O/C				
Airframe											
522205	Emergency Exit Door FS 564 (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	60P5220101M020	S02268113	MOS	TSN:102	25.2			19 Nov 2022			
			MSC				O/C				
Airframe											
522210	Emergency Exit Door - Rigging		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
522219	Emergency Exit Door Release Handle Switch - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
522221	Emergency Exit Stop Fittings (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		13580**	0	13580		0
			MOS		128.2			21 Apr 2014			
Airframe											
522222	Emergency Exit Stop Fittings (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		13580**	0	13580		0
			MOS		128.2			21 Apr 2014			
Airframe											
523000	Baggage Door - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
523001	Baggage Compartment Door - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
523110	Baggage Door - Removal / Installation 60P5230110A039P02 G0174059201		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
523111	Baggage Door Interior Skin and Structure - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
523112	Baggage Door Cable - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
523113	Baggage Door Stops - Adjustment		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
523400	Baggage Door Seal FS 824.5 - FS 867- Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	5	48	26 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
524400	Tail Compartment Door - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
524401	Tail Access Door Assembly - Removal / Installation 60P5240051A010 SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
525100	Auxiliary Pressure Bulkhead Door - Removal / Installation 60P5250110C016 NSN		HRS	TSN:1609.6	1912.8			1609.6			0
			AFL	TSN:330	397			330			0
			MOS	TSN:53	75.3			17 Sep 2018			N/A
			MSC				O/C				
Airframe											
525102	Auxiliary Pressure Bulkhead Door Seal - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	26	12	05 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
525200	Acoustic Door Automatic Opening - Operational Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		24.9		36	28 Nov 2022	30 Nov 2025	31 Dec 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
525205	Acoustic Door Warning Switch - Removal / Installation 80-133 550		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
525207	Acoustic Door Panel (Inboard) - Removal / Installation		HRS		.4			3522			0
	-		AFL		1			726			0
	NSN		MOS		2.5			12 Oct 2024			N/A
	Airframe		MSC				O/C				
525208	Acoustic Door Panel (Outboard) - Removal / Installation		HRS		.4			3522			0
	-		AFL		1			726			0
	NSN		MOS		2.5			12 Oct 2024			N/A
	Airframe		MSC				O/C				
525211	Acoustic Door Reels - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
525212	Acoustic Door Latch and Soleniod - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
525213	Acoustic Door Warning Switch - Adjustment Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
527100	Main Entrance Door Warning Indication - Operational Test		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.5			12 Oct 2021			
	Airframe		MSC				O/C				
527101	Emergency Exit Doors Open Warning Indication - Operational Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
527102	Emergency Exit Door Release Latch Switches - Operational Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
527103	Auxiliary Pressure Bulkhead Door Warning Indication - Operational Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	20	48	11 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
527105	Baggage Door Warning Switch - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
527110	Service Door Warning Switch - Adjustment / Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.4			15 Nov 2022			
			MSC			O/C					
Airframe											
527113	Auxiliary Pressure Bulkhead Door Switch - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
527114	Auxiliary Pressure Bulkhead Door Warning Switch - Removal / Installation 602EN55-6		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS	TSN:2	26.5			11 Oct 2022			N/A
			MSC			O/C					
Airframe											
527502	Control Display Unit - Removal / Installation 100-0106-01\01-04002		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
527504	Mat Switch (Med) - Removal / Installation 100-0106-01\01-04002		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC			O/C					
Airframe											
Notes: MRI PARENT CODE: 527502											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
527510	Battery Pack - Removal / Installation		HRS		3522.4			0			0
	100-1032-01	1127485	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
527515	Ultra High Frequency Antenna (Security) - Removal / Installation		HRS	TSN:2364.2	1158			2364.4			0
			AFL	TSN:487	239			488			0
	100-2617-01	9494	MOS	TSN:78	50.5			12 Oct 2020			N/A
	Airframe		MSC				O/C				
527517	Ultra High Frequency Voice Communications / Security System - Operational Test		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.1			22 Nov 2022			
	Airframe		MSC				O/C				
527518	Security System Radio - Removal / Installation		HRS		3517			5.4			0
	444-EX600	1127485	AFL		724			3			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
Notes: COMPLIANCE TIME WILL NOT MATCH THE FLIGHT LOG ON THE COMPLIED WITH DATE. COMPONENT HOURS WERE ENTERED TO ADJUST PART RUN TIME OF PART CHANGED PRIOR TO AIRCRAFT RECORD IN CMP AND AIRWORTHINESS DATE.											
527520	Digital Alarm Indicator - Removal / Installation		HRS		3522.4			0			0
	100-0651-01	1139285	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
527524	Passive Infrared Sensor (Nose Wheel Well Right Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	100-0401-11	0585	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
527526	Passive Infrared Sensor (Nose Wheel Well Right Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	100-0401-11	0598	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
527528	Passive Infrared Sensor (Main Wheel Well Left) -		HRS	TSN:9.3	3522.4			0			0
	Removal / Installation		AFL	TSN:4	727			0			0
	100-0401-11	0311	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
527530	Passive Infrared Sensor (Main Wheel Well Right) -		HRS	TSN:9.3	3522.4			0			0
	Removal / Installation		AFL	TSN:4	727			0			0
	100-0401-11	0348	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
53 - Fuselage											
530001	Antenna Interface - Detailed Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.3	6	72	17 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530002	Cabin Fixed Windows Internal - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530003	Exterior Skin Panel Installations (Enclosed By Pylons) FS		HRS		485.9			3036.5			0
	838 - FS 1059.625 - Detailed Inspection		AFL		97			630			0
			MOS		26.4	10	48	13 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530004	External Lower Fuselage FS 100 - FS 886 - Zonal		HRS		.4			3522			0
	Inspection		AFL		1			726			0
			MOS		2.5	22	24	09 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530005	Radome (Interior) and Equipment AREA Behind Radome -		HRS		3522.4			0			0
	Zonal Inspection		AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
530006	Lower Forward Cabin and Midcabin Sections FS 245.5 - FS 511.5 - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	11	48	20 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: ALL WORK COMPLETED IN ACCORDANCE WITH G650 AMM 05-20-00											
530007	Aft Midcabin Fuselage Below Floor Level FS 739 - FS 886 - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.6	-8	48	08 Nov 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530008	External Upper Fuselage (Viewed from Platform) FS 148.5 - FS 886 - Zonal Inspection		HRS		1158.2			2364.2			0
			AFL		240			487			0
			MOS		50.2	3	72	20 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530009	Cabin Above Floor from Vestibule to Baggage Compartment FS 245.5 - FS 886 - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530010	External Aft Fuselage and Empennage FS 886 - FS 1199.475 - Zonal Inspection		HRS		1158.2			2364.2			0
			AFL		240			487			0
			MOS		50.2	3	72	20 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530011	Lower Forward Cabin and Midcabin Sections FS 245.5 - FS 511.5 - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	11	48	20 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: ALL WORK COMPLETED IN ACCORDANCE WITH G650 AMM 05-20-00											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
530012	Lower Forward Cabin and Midcabin Cleaning and Dust Removal - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	11	48	20 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: PN: NPN SN: NSN. ALL WORK COMPLETED IN ACCORDANCE WITH G650 AMM 05-20-00											
530013	Aft Midcabin Fuselage Below Floor Level FS 739 - FS 886 - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.6	-8	48	08 Nov 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530014	Vestibule and Forward Cabin Below Floor Hirf/L - Detailed Inspection		HRS		1158.2			2364.2			0
			AFL		240			487			0
			MOS		50.4	10	72	13 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530015	Tail Compartment Hirf/L - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	18	96	05 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530016	Cabin Fixed Window Frames and Surrounds - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530017	External Fuselage - General Visual Inspection		HRS		.4			3522			0
			AFL		1		800	726	1526		0
			MOS		2.5			11 Oct 2024			
Airframe											
530022	Mid Cabin Window Rings (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		8955**	0	8955		0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
530023	Mid Cabin Window Rings (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		8955**	0	8955	0	
			MOS		128.2		21 Apr 2014				
Airframe											
530025	Fuselage Skins AT Wing Pressure Box Cutout (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5110**	0	5110	0	
			MOS		128.2		21 Apr 2014				
Airframe											
530026	Fuselage Skins AT Wing Pressure Box Cutout (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5110**	0	5110	0	
			MOS		128.2		21 Apr 2014				
Airframe											
530099	Aircraft Service Design Life PN SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727		4500**	0	4500	0	
			MOS		128.2		21 Apr 2014				
Airframe											
530100	Vortex Generator - Removal / Installation PN SN-UNKNOWN		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
Airframe											
531000	Radome - Removal / Installation 1159B57292-7 1-126		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
Airframe											
531007	Forward Fuselage Above Floor FS 148.5 - FS 245.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1	192	23 Oct 2014	31 Oct 2030	30 Nov 2030		
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531008	Forward Fuselage Below Floor FS 148.5 - FS 245.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531010	Canopy Roof - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
531011	Cockpit Interior Above Headliner FS 167 - FS 245.5 - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531012	Left and Right Cockpit Interior Floor Up to Window Level - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531013	Left and Right Cockpit Interior Floor Up to Window Level - Enhanced Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
531014	Internal Left and Right Fuselage Below Cockpit Floor AT FS 189.375 - FS 223 - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	12	96	11 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531015	Internal Left and Right Fuselage Below Cockpit Floor AT FS 223 - FS 243 - Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1	38	24	23 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531016	Internal Left and Right Fuselage Below Cockpit Floor FS 223 - FS 243 - Enhanced Zonal Inspection		HRS		1158.2			2364.2			0
			AFL		240			487			0
			MOS		50.5	11	72	12 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531017	Cockpit Above Floor Hirf/L - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531018	Cockpit Below Floor FS 189.375 - FS 223 Hirf/L - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	12	96	11 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531019	Cockpit Below Floor FS 223 - FS 243 Hirf/L - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	12	96	11 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531020	Internal Below Pedestal - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531021	Cockpit Below Floor Cleaning and Dust Removal - Enhanced Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3.1	38	24	23 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: REF 19.13 AND 19.14 FOR DISCREPANCIES FOUND DURING ZONAL INSPECTION											
531022	Leer Hirf/L - Detailed Inspection		HRS		1158.2			2364.2			0
			AFL		240			487			0
			MOS		50.6	16	72	07 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531023	Reer Hirf/L - Detailed Inspection		HRS		1158.2			2364.2			0
			AFL		240			487			0
			MOS		50.6	15	72	08 Oct 2020	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531024	Nose Landing Gear Wheel Well FS 148.5 - FS 223 - Zonal Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.5	3	24	09 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
531026	Radome Assembly - General Visual Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	26	120	27 Sep 2024	31 Oct 2034*	30 Nov 2034	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531036	Radome to Structure Perimeter Steps - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	37	24	08 Oct 2024	30 Nov 2026*	31 Dec 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: STEP GAGE:572033CAL:04/19											
531037	Internal Cockpit Below Floor FS 167 - FS 189 - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531100	Vestibule Internal Above Floor FS 245.5 - FS 324.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531101	Vestibule Internal Below Floor FS 245.5 - FS 324.5 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	10	96	13 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531105	Nose Landing Gear Skin Cutout AT FS 220 - Visual Inspection		HRS		3522.4			0			0
			AFL		727		6145**	0	6145		0
			MOS		128.2			21 Apr 2014			
Airframe											
531200	Bulkhead Installation FS 148.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531201	Bulkhead Installation FS 167 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531202	Bulkhead Installation FS 189.375 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531203	Bulkhead Installation FS 223 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531204	Bulkhead Installation FS 243 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531205	Bulkhead Installation FS 148.5 - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	5	96	18 Oct 2022	31 Oct 2030*	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531210	Forward Cabin Frame Splices - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		14230**	0	14230		0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531300	Forward Fuselage Below Floor FS 167 - FS 243 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
531301	Nose Wheel Well Trunnion and Drag Brace Fittings - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531302	Forward Fuselage Above Floor FS 189.375 - FS 243 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
531303	Forward Fuselage Splice Installations Above Floor FS 245.5 - FS 324.5 - Special Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531304	Splice Installations Below Floor Left Side FS 245.5 - FS 324.5 - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	23	24	08 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531305	Splice Installations Below Floor (Dry Areas) Right Side FS 245.5 - FS 324.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531306	Splice Installations Below Floor (Wet Areas) Right Side FS 245.5 - FS 324.5 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	6	96	17 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531310	FS 273 and FS 309 Bulkhead Splices AT Stringers 3L and 19L - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		15715**	0	15715		0
			MOS		128.2			21 Apr 2014			
Airframe											
531501	Floor Beams and Tracks Right Side Above Floor (Wet Areas) FS 245.5 - FS 324.5 - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	6	96	17 Oct 2022	31 Oct 2030*	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531502	Floor Structure Left Side FS 245.5 - FS 324.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531503	Floor Structure (Dry Areas) Right Side FS 245.5 - FS 324.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531504	Floor Structure (Wet Areas) Right Side FS 245.5 - FS 324.5 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	6	96	17 Oct 2022	31 Oct 2030*	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
531600	Cockpit Above Floor FS 167 - FS 189.375 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
MSC O/C											
Airframe											
531601	Cockpit Interior Above Floor FS 167 - FS 245.5 - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	10	96	13 Oct 2022	31 Oct 2030*	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531602	Cockpit Interior Cleaning and Dust Removal - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97		630			0	
			MOS		26.4	10	96	13 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531605	Cockpit Pressure Floor - Visual / Ndt Inspection		HRS		3522.4			0			0
			AFL		727		9820**	0	9820		0
			MOS		128.2			21 Apr 2014			
Airframe											
531700	Cockpit Center Post - Ndt Inspecton		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
531701	Cockpit Side Post - Ndt Inspecton		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
531702	Cockpit Side Window Surround Lower Corner (Left)- Ndt Inspection		HRS		3522.4			0			0
			AFL				3610**		3610		0
			MOS		128.2			21 Apr 2014			
Airframe											
531703	Cockpit Lower RAIL - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
531704	Cockpit Upper RAIL - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
531705	Cockpit Internal Structure Headliner Removed - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531706	Cockpit Splice and Crossbeam Internal - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531707	Side Window Rails and Posts Internal (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531708	Side Window Rails and Posts Internal (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531709	Windshield Rails and Posts Internal (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531710	Windshield Rails and Posts Internal (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
531711	Cockpit Windshields, Side Windows and Cabin Windows Polished Exterior Surrounds - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	-4	12	04 Oct 2024	30 Sep 2025*	31 Oct 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531712	Cockpit Windshields, Side Windows and Cabin Windows		HRS		.4			3522			0
	Polished Exterior Surrounds Corrosion Inhibiting Coating -		AFL		1			726			0
	Restore		MOS		2.5		12	12 Oct 2024	31 Oct 2025	30 Nov 2025	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
Notes: REF IN PROCESS WORK FLOW INDEX #15 COMPLETED BY SHARPE DETAILS.											
531713	Cockpit Side Window Surround Lower Corner (Right)- Ndt		HRS		3522.4			0			0
	Inspection		AFL		727		3610**	0	3610		0
			MOS		128.2			21 Apr 2014			
Airframe											
531715	Cockpit Side Window Surround Upper Corner (Left) - Ndt		HRS		3522.4			0			0
	Inspection		AFL		727		8085**	0	8085		0
			MOS		128.2			21 Apr 2014			
Airframe											
531716	Cockpit Side Window Surround Upper Corner (Right) -		HRS		3522.4			0			0
	Ndt Inspection		AFL		727		8085**	0	8085		0
			MOS		128.2			21 Apr 2014			
Airframe											
532001	Fuselage Drain Plug Assembly - Operational Check		HRS		3522.4		10000	0	10000	10050	0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe			[HRS: +50/-50]								
532100	Galley / Lavatory Below Floor (Wet Areas) FS 324.5 - FS		HRS		485.9			3036.5			0
	529 - Detailed Inspection		AFL		97			630			0
			MOS		26.3	6	96	17 Oct 2022	31 Oct 2030*	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
532101	Interior Upper Forward Midcabin Panel Installation Headliner Removed FS 324.5 - FS 529 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532102	Interior Left and Right Forward Midcabin Panel Installations Above Floor FS 324.5 - FS 529 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532103	Wing Link Fittings Interior to Wing to Body Fairing FS 470 - FS 511.5 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	6	96	17 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532104	Waste Penetration Installation Interior to Wing to Body Fairing FS 470 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	6	96	17 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532105	Forward Midcabin Below Floor (Dry Areas) FS 324.5 - FS 529 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	6	96	17 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532201	FS 511.5 Bulkhead - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		15870**	0	15870		0
			MOS		128.2			21 Apr 2014			
Airframe											
532300	Production Circle Splice, FS 805 (Upper Stringers 6L - 6 R) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
532301	Left and Right Stringer 6 and Midbay Skin Splices (Above Floor) FS 324.5 - FS 529 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532302	Left and Right Stringer 19 and Midbay Skin Splices Below Floor (Dry Areas) FS 324.5 - FS 529 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	6	96	17 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532303	Left and Right Stringer 19 and Midbay Skin Splices Below Floor Galley / Lavatories (Wet Areas) FS 324.5 - FS 529 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	6	96	17 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532500	Floor Beams and Tracks Above Floor (Dry Areas) FS 321 - FS 511.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532501	Floor Beams and Tracks Above Floor (Wet Areas) FS 321 - FS 511.5 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	10	96	13 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532502	Cabin Below Floor Seat Track Beams and Support Structure (Dry Areas) FS 321 - FS 511.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
532503	Cabin Below Floor Seat Track Beams and Support Structure (Wet Areas) FS 321 - FS 511.5 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	10	96	13 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532600	Leer FS 246 - FS 270 - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	27	48	04 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532601	Leer FS 246 - FS 270 - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	27	48	04 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532602	Reer FS 251.5 - FS 285 - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	27	48	04 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532603	Reer FS 251.5 - FS 285 - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	27	48	04 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532604	Leer Cleaning and Dust Removal - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	27	48	04 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
532605	Reer Cleaning and Dust Removal - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	27	48	04 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
532701	Forward Cabin Window Rings (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		8955**	0	8955	0	
			MOS		128.2		21 Apr 2014				
Airframe											
532702	Forward Cabin Window Rings (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		8955**	0	8955	0	
			MOS		128.2		21 Apr 2014				
Airframe											
533000	Main Landing Gear Wheel Well and Torque Box FS 671.411 - FS 739 (Left) - Zonal Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.6	19	24	06 Oct 2024	31 Oct 2026*	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]											
Airframe											
533001	Main Landing Gear Wheel Well and Torque Box FS 671.411 - FS 739 (Right) - Zonal Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.6	19	24	06 Oct 2024	31 Oct 2026*	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]											
Airframe											
533002	Main Landing Gear Wheel Well and Torque Box FS 671.411 - FS 739 (Left) - Enhanced Zonal Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.6	19	24	06 Oct 2024	31 Oct 2026*	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]											
Airframe											
533003	Main Landing Gear Wheel Well and Torque Box FS 671.411 - FS 739 (Right) - Enhanced Zonal Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.6	19	24	06 Oct 2024	31 Oct 2026*	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]											
Airframe											
533015	Vertical Fin Drag Angle AT FS 1003 - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		3580**	0	3580	0	
			MOS		128.2		21 Apr 2014				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533017	Vertical Fin Skin Cutouts - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5270**	0	5270		0
			MOS		128.2			21 Apr 2014			
Airframe											
533100	Fuselage Skin Exterior - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
533101	Interior Center Midcabin Side Panel Installation FS 529 - FS 747.75 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
533102	Interior Upper Center Midcabin Panel Installation FS 529 - FS 747.75 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
533103	Center Midcabin Mainframe Installation FS 529 and FS 686.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
533104	Emergency Exit Door Internal Surround Structures - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
533107	Fuselage Skin AT Window 7 Cutout (Left) - Visual Inspection		HRS		3522.4			0			0
			AFL		727		6620**	0	6620		0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533108	Fuselage Skin AT Window 7 Cutout (Right) - Visual Inspection		HRS		3522.4			0			0
			AFL		727		6620**	0	6620		0
			MOS		128.2			21 Apr 2014			
Airframe											
533200	Mid-Bay Circumference Splice, FS 747.75 (Upper Stringers 8L - 8R)-Discard 60P5339001N009M02NSN		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
533201	Window Frame Splices (Cabin Windows 1 Thru 4) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
533202	Mid-Bay Circumference Splice, FS747.75 (Upper Stringers 8L - 8R) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
533203	Bulkhead Aft Face Below Floor FS 739 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
533204	Bulkhead Aft Face Internal to Wtbf FS 739 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	5	96	18 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
533205	Interior Bulkhead Forward and Aft Face Above Floor FS 739 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533207	FS 529 Main Frame - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		11120**	0	11120		0
			MOS		128.2			21 Apr 2014			
Airframe											
533209	Mid Cabin Frame Splices AT Longerons 9 and 13 - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		4880**	0	4880		0
			MOS		128.2			21 Apr 2014			
Airframe											
533211	FS 739 Bulkhead AT Longeron 17 Splice - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		15870**	0	15870		0
			MOS		128.2			21 Apr 2014			
Airframe											
533300	Splice Installations Above Floor FS 529 - FS 747.75 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
533301	Splice Installations Below Floor FS 529 - FS 747.75 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	5	96	18 Oct 2022	31 Oct 2030*	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
533303	Longeron 9 and 13 Splices AT FS 529 and FS 686.5 - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		9340**	0	9340		0
			MOS		128.2			21 Apr 2014			
Airframe											
533305	Longeron 17 AT Frame Attachment - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		14545**	0	14545		0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533307	Longeron 17 AT FS 581.5 - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		3715**	0	3715	0	
			MOS		128.2		21 Apr 2014				
Airframe											
533309	Longeron 7 and 15 Splices AT FS 529 and FS 686.5 - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		9340**	0	9340	0	
			MOS		128.2		21 Apr 2014				
Airframe											
533400	Wing to Fuselage Attachment Links - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	4	96	19 Oct 2022	31 Oct 2030*	30 Nov 2030	
Airframe [End Of Month Item] [MOS: +1m/-1m]											
533402	Main Frame Assy (Lh, FS 686) 60P5334001A088		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2		21 Apr 2014				
Airframe O/C											
533405	BI 49 Wing Attach Drag Link - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		9760**	0	9760	0	
			MOS		128.2		21 Apr 2014				
Airframe											
533407	Wing to Fuselage Joints, Sleeves and Pins - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		12445**	0	12445	0	
			MOS		128.2		21 Apr 2014				
Airframe											
533500	Pressure Floor Structure Below Floor FS 511.5 - FS 739 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144**	23 Oct 2014	31 Oct 2026	30 Nov 2026	
Airframe [End Of Month Item] [MOS: +1m/-1m]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533501	Pressure Floor Structure Panels Above Floor (Dry Areas)		HRS		3522.4			0			0
	FS 511.5 - FS 739 - Detailed Inspection		AFL		727			0			0
			MOS		122.1		192**	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
533502	Pressure Floor Structure Panels Above Floor (Wet Areas)		HRS		3522.4			0			0
	FS 511.5 - FS 739 - Detailed Inspection		AFL		727			0			0
			MOS		122.1		192**	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
533503	Pressure Floor Structure AT Wheel Wells Below Floor FS		HRS		3522.4			0			0
	511.5 - FS 669 - Detailed Inspection		AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
533504	Pressure Floor Structure Forward of Wheel Wells Below		HRS		485.9			3036.5			0
	Floor FS 669 - FS 739 - Detailed Inspection		AFL		97			630			0
			MOS		26.3	5	96	18 Oct 2022	31 Oct 2030*	30 Nov 2030	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
533505	Seat Track Beams Above Floor (Dry Areas) FS 511.5 - FS		HRS		3522.4			0			0
	739 - Detailed Inspection		AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
533506	Seat Track Beams Above Floor (Wet Areas) FS 511.5 - FS		HRS		3522.4			0			0
	739 - Detailed Inspection		AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe											
533510	FS 686.5 Floor Beam Connection - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		9145**	0	9145		0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533511	FS 686.5 Floor Beam Lower CAP - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		3610**	0	3610		0
			MOS		128.2			21 Apr 2014			
Airframe											
533513	Mid Cabin Pressure Floor Structure - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		9410**	0	9410		0
			MOS		128.2			21 Apr 2014			
Airframe											
533515	FS 529 Floor Beam Connection - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		9145**	0	9145		0
			MOS		128.2			21 Apr 2014			
Airframe											
533800	Wing to Fuselage Drag Links FS 529 - FS 581.5 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	7	96	16 Oct 2022	31 Oct 2030*	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
533900	Torque Box Interior - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
533901	Torque Box Exterior and Links - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
533903	Torque Box Internal Side (FS 680 - FS 735) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26		48	25 Oct 2022	25 Oct 2026	25 Nov 2026	
[MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
533904	Wiring and Fuel Installations Located Inside Torque Box Upper Portion (FS 680 - FS 735) - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26		48	25 Oct 2022	25 Oct 2026	25 Nov 2026	
			[MOS: +1m/-1m]								
Airframe											
533906	Forward Torque Box Connection to Wing Rear Spar - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		13550**	0	13550		0
			MOS		128.2			21 Apr 2014			
Airframe											
533908	Aft Torque Box Connection to Longerons 24 - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		13550**	0	13550		0
			MOS		128.2			21 Apr 2014			
Airframe											
534000	Baggage Compartment Wiring Installation FS 805.5 - FS 886 - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534001	Baggage Compartment Below Floor Hirf/L - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	19	48	12 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534002	Baggage Compartment Above Floor Hirf/L - Detailed Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.2	3	72	20 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534003	Baggage Compartment Above Floor Hirf/L - General Visual Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.2	3	72	20 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534004	Baggage Compartment Forward Electronic Equipment Rack Hirf/L - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	19	96	04 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534100	Interior Upper Aft Mid Panel Installation FS 739 - FS 886 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534101	Interior Aft Mid Side Panel Installations FS 739 - FS 886 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534102	Aft Mid Internal Structure Below Floor (Wet Areas) FS 739 - FS 886 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534103	Aft Mid Internal Structure Below Floor (Dry Areas) FS 739 - FS 886 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534104	Aft Mid Splice Installations Above Floor FS 739 - FS 886 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.6		144	08 Nov 2022	30 Nov 2034	31 Dec 2034	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534105	Aft Mid Splice Installations FS 886 - FS 951.31 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	5	96	18 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534106	Aft Mid Splice Installations Below Floor (Dry Areas) FS 739 - FS 886 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534107	Aft Mid Splice Installations Below Floor (Wet Areas) FS 739 - FS 886 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534110	Baggage Door Surround Structure (Cutout Corners) - Visual Inspection		HRS		3522.4			0			0
			AFL		727		11945**	0	11945		0
			MOS		128.2			21 Apr 2014			
Airframe											
534112	FS 805.5 Circumferential Skin Splice (Above Stringer 8) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5380**	0	5380		0
			MOS		128.2			21 Apr 2014			
Airframe											
534115	Pylon AREA Skin Cutouts (Left) - Visual Inspection		HRS		3522.4			0			0
			AFL		727		11945**	0	11945		0
			MOS		128.2			21 Apr 2014			
Airframe											
534116	Pylon AREA Skin Cutouts (Right) - Visual Inspection		HRS		3522.4			0			0
			AFL		727		11945**	0	11945		0
			MOS		128.2			21 Apr 2014			
Airframe											
534119	Lower Access Cutouts - Visual Inspection		HRS		3522.4			0			0
			AFL		727		11945**	0	11945		0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534121	APU Access Door Surround Structure, Cutout Corners - Visual Inspection		HRS		3522.4			0			0
			AFL		727		11945**	0	11945		0
			MOS		128.2			21 Apr 2014			
Airframe											
534200	Aft Engine Mount Frame Installation Above Floor FS 951.31 - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	5	96	18 Oct 2022	31 Oct 2030*	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
534201	Aft Engine Mount Frame Installation Below Floor FS 951.31 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
534202	Aft Mid Frame Installations Above Floor FS 823 and FS 868.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
534203	Baggage Door Support Internal Structure - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	4	96	19 Oct 2022	31 Oct 2030*	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
534204	Secondary Pressure Bulkhead Door FS 805.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
534205	Secondary Pressure Bulkhead Above Floor FS 805.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534206	Secondary Pressure Bulkhead Below Floor FS 805.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534207	Primary Pressure Bulkhead - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534208	Baggage Door Support External Structure - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	5	96	18 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534210	Frames AT Floor Beam Connections, Left Side, FS 838 and FS 853 - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		13710**	0	13710		0
			MOS		128.2			21 Apr 2014			
Airframe											
534211	Frames AT Floor Beam Connections, Right Side, FS 838 and FS 853 - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		3745**	0	3745		0
			MOS		128.2			21 Apr 2014			
Airframe											
534213	Composite Pressure Bulkhead FS 886 - Visual Inspection		HRS		3522.4			0			0
			AFL		727		4000**	0	4000		0
			MOS		128.2			21 Apr 2014			
Airframe											
534214	Composite Pressure Bulkhead Attach FS 886 - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		11880**	0	11880		0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534500	Aft Mid Auxiliary Pressure Floor Structures Above Floor (Dry Areas) FS 739 - FS 805.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534501	Aft Mid Auxiliary Pressure Floor Structures Above Floor (Wet Areas) FS 739 - FS 805.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534502	Aft Mid Auxiliary Pressure Floor Structures Below Floor (Dry Areas) FS 739 - FS 805.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534503	Aft Mid Auxiliary Pressure Floor Structures Below Floor (Wet Areas) FS 739 - FS 805.5 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534504	Baggage Floor Structures Below Floor FS 805.5 - FS 886 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534600	APU Enclosure FS 886 - FS 951.3 - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	6	48	25 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534700	Engine Mount Installation FS 886 - FS 951.31 - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534701	FS 886 Upper Engine Mount Fittings (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5780**	0	5780		0
			MOS		128.2			21 Apr 2014			
Airframe											
534702	FS 886 Upper Engine Mount Fittings (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5780**	0	5780		0
			MOS		128.2			21 Apr 2014			
Airframe											
534703	FS 886 Upper Fuselage Link (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		10000**	0	10000		0
			MOS		128.2			21 Apr 2014			
Airframe											
534704	FS 886 Upper Fuselage Link (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		10000**	0	10000		0
			MOS		128.2			21 Apr 2014			
Airframe											
534800	Baggage Compartment Forward Electronic Equipment Rack Internal - Zonal Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.6	16	72	07 Oct 2020	31 Oct 2026*	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
534801	Baggage Compartment Forward Electronic Equipment Rack Cleaning and Dust Removal - Enhanced Zonal Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.6	16	72	07 Oct 2020	31 Oct 2026*	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
534802	Baggage Compartment Aft Electronic Equipment Rack Internal - Zonal Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.6	16	72	07 Oct 2020	31 Oct 2026*	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534803	Baggage Compartment Aft Electronic Equipment Rack Cleaning and Dust Removal - Enhanced Zonal Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.6	16	72	07 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534804	Water Supply Cabinet Internal - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7	19	96	04 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
535000	APU and Aft Fuselage Below Floor - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	13	48	18 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
535001	APU Interior and Exterior Enclosure - Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	24	24	07 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
535002	Aft Fuselage Below Floor FS 951.31 - FS 1071.75 - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
535003	Aft Fuselage Above Floor FS 886 - FS 1083.46 - Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	24	24	07 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
535004	Aft Fuselage Internal Tail Cone - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
535100	Aft Fuselage Above Floor FS 951.31 - FS 1103.25 - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
535101	Aft Fuselage Interior Below Floor FS 951.31 - FS 1103.25 - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
535102	Tail Compartment Stringers 6 and 20 Splices FS 951.31 - FS 1103.25 - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.5	-18	96	10 Nov 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
535103	Aft Fuselage Interior Above Floor FS 951.31 - FS 1103.25 - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
535201	FS 1003 Frame AT Fin Attachment - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		4920**	0	4920		0
			MOS		128.2				21 Apr 2014		
Airframe											
535203	FS 1083 Bulkhead AT Fin Attachment - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		6010**	0	6010		0
			MOS		128.2				21 Apr 2014		
Airframe											
539101	Ram AIR Turbine Enclosure Internal - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.1	-1	96	24 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
539102	Forward Wtbf Internal - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.1	-1	96	24 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
539103	Forward Wtbf Internal - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.1	-1	96	24 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
539104	Forward Wtbf Drain Holes - Enhanced Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
539301	Mid Wtbf Internal - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	3	96	20 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
539302	Mid Wtbf Internal - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	3	96	20 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
539303	Lower Mid Wtbf Drain Holes - Enhanced Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
539308	Forward Wing to Body Fairing Panel 02 (FS. 406-50) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5391202A004	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
539309	Forward Wing to Body Fairing Panel 04 (FS. 406-50) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5391204A005	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
539501	Aft Wtbf Internal - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.1	-1	96	24 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
539502	Aft Wtbf Internal - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.1	-1	96	24 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
539503	Aft Wtbf Drain Holes - Enhanced Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
54 - Nacelles/Pylons											
540001	Nacelle, Thrust Reverser and Exhaust External (Viewed from Ground) - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC O/C								
545000	Pylons (External) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
545001	Pylons (Internal) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	19	48	12 Oct 2022	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
545004	Idg Feeder Cables and Wiring Installations - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	19	48	12 Oct 2022	31 Oct 2026*	30 Nov 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
545005	Pylon Leading Edge (Left) - Polishing		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5		12	12 Oct 2024	31 Oct 2025	30 Nov 2025	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: REF IN PROCESS WORK FLOW INDEX #15 COMPLETED BY SHARPE DETAILS.											
545006	Pylon Leading Edge (Right) - Polishing		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5		12	12 Oct 2024	31 Oct 2025	30 Nov 2025	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
545007	External Metallic Surfaces (Pylon Leading Edge - Left) - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		6	23 Oct 2014	31 Mar 2025	30 Apr 2025	
Airframe			[MOS: +1m/-1m]								
545008	External Metallic Surfaces (Pylon Leading Edge - Right) - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		6	23 Oct 2014	31 Mar 2025	30 Apr 2025	
Airframe			[MOS: +1m/-1m]								
55 - Stabilizers											
551000	Horizontal Stabilizer Rear Spar Splice Angles - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe			MSC O/C								
551001	Horizontal Stabilizer Rub Block Adjustment - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe			MSC O/C								
551002	Horizontal Stabilizer Assembly (External) Left - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	21	48	10 Oct 2022	31 Oct 2026*	30 Nov 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551003	Horizontal Stabilizer Assembly (External) Right - General Visual Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	21	48	10 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551004	Horizontal Stabilizer Assembly (External) Left - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551005	Horizontal Stabilizer Assembly (External) Right - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551006	Horizontal Stabilizer Front Beam (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551007	Horizontal Stabilizer Front Beam (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551008	Horizontal Stabilizer Rear Beam (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551009	Horizontal Stabilizer Rear Beam (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551010	Horizontal Stabilizer Rub Blocks (Left) - General Visual Inspection		HRS		485.9	-36.5	3750	3036.5	6750*	6800	0
			AFL		97			630		0	
			MOS		26.5			10 Oct 2022			
			[HRS: +50/-50]								
Airframe											
551011	Horizontal Stabilizer Rub Blocks (Right) - General Visual Inspection		HRS		485.9	-36.5	3750	3036.5	6750*	6800	0
			AFL		97			630		0	
			MOS		26.5			10 Oct 2022			
			[HRS: +50/-50]								
Airframe											
551012	Horizontal Stabilizer Hirf/L (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551013	Horizontal Stabilizer Hirf/L (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551014	Horizontal Stabilizer Rear Beam Hirf/L (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551015	Horizontal Stabilizer Rear Beam Hirf/L (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551016	Horizontal Stabilizer Rub Block / Vertical Fin Rub Strip Gaps - Functional Check		HRS		485.9	-36.5	3750	3036.5	6750*	6800	0
			AFL		97			630		0	
			MOS		26.3			17 Oct 2022			
			[HRS: +50/-50]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Logbook Position	Part Number									Serial Number
HW		SW									Manufacturer
MM Ref		Date Type									
Ops Number(s)											
551017	Horizontal Stabilizer Assembly (Internal) Left - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
	Airframe										
551018	Horizontal Stabilizer Assembly (Internal) Right - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
	Airframe										
551019	Horizontal Stabilizer - Removal / Installation		HRS		3522.4			0			0
	60P5510000-001	6089	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
	Airframe										
551100	Horizontal Stabilizer Inboard Leading Edge (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	PN	SN-UNKNOWN	MOS	TSN:103	24.9			29 Nov 2022			
			MSC				O/C				
	Airframe										
551101	Horizontal Stabilizer Inboard Leading Edge (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
	PN	NSN	MOS	TSN:103	24.9			29 Nov 2022			
			MSC				O/C				
	Airframe										
551108	Horizontal Stabilizer Leading Edge (Left) - Polishing		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5		12	12 Oct 2024	31 Oct 2025	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
	Airframe										
Notes: REF IN PROCESS WORK FLOW INDEX #15 COMPLETED BY SHARPE DETAILS.											
551109	Horizontal Stabilizer Leading Edge (Right) - Polishing		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		12	23 Oct 2014	30 Apr 2025	31 May 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551110	External Metallic Surfaces (Horizontal Stabilizer Leading Edge - Left) - General Visual Inspection		HRS		3522.4			0			0
			AFL		727		0			0	
			MOS		122.1	6	23 Oct 2014	31 Mar 2025	30 Apr 2025		
			[MOS: +1m/-1m]								
Airframe											
551111	External Metallic Surfaces (Horizontal Stabilizer Leading Edge - Right) - General Visual Inspection		HRS		3522.4			0			0
			AFL		727		0			0	
			MOS		122.1	6	23 Oct 2014	31 Mar 2025	30 Apr 2025		
			[MOS: +1m/-1m]								
Airframe											
551200	Horizontal Stabilizer Center Box and Actuator Attachments - Detailed Inspection		HRS		3522.4			0			0
			AFL		727		0			0	
			MOS		122.1	144	23 Oct 2014	31 Oct 2026	30 Nov 2026		
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551400	Elevator Exterior - Zonal Inspection		HRS		3522.4			0			0
			AFL		727		0			0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
551401	Elevator Attachments - Zonal Inspection		HRS		3522.4			0			0
			AFL		727		0			0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
551403	Horizontal Stabilizer Trailing Edge (Left) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97		630			0	
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551404	Horizontal Stabilizer Trailing Edge (Right) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97		630			0	
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551500	Horizontal Stabilizer Elevator Hinge Brackets (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551501	Horizontal Stabilizer Elevator Hinge Brackets (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551502	Horizontal Stabilizer Pivot Fitting - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		96	23 Oct 2014	30 Oct 2025	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
551700	Horizontal Stabilizer Actuator Structural Attachments - Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
551701	Horizontal Stabilizer Actuator Connectors - Seating Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
552006	Elevator Hinge Brackets AT Interior of Elevator (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
552007	Elevator Hinge Brackets AT Interior of Elevator (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
552008	Elevator (External) Left - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		24.9	-28	48	28 Nov 2022	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
552009	Elevator (External) Right - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		24.9	-28	48	28 Nov 2022	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
552010	Elevator (Internal) Nonmetal Parts (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
552011	Elevator (Internal) Nonmetal Parts (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
552300	Elevator Hinge (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.3	-25	96	17 Nov 2022	31 Oct 2030*	30 Nov 2030	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
552301	Elevator Hinge (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.3	-25	96	17 Nov 2022	31 Oct 2030*	30 Nov 2030	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
553000	Vertical Stabilizer Exterior - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe	O/C									
553001	Rudder Exterior - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe	O/C									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* = Adj)	Max Due	Avg Man Hrs
	Logbook Position	Part Number									Serial Number
HW		SW									Manufacturer
MM Ref		Date Type									
Ops Number(s)											
553003	Vertical Stabilizer Interior of Fin CAP / Rear Bullet Fairings - Zonal Inspection		HRS		485.9			3036.5		0	
			AFL		97		630		0		
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
	Airframe										
553005	Vertical Stabilizer Rear Spar Aft Face - Zonal Inspection		HRS		485.9			3036.5		0	
			AFL		97		630		0		
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
	Airframe										
553006	Vertical Stabilizer (External) - General Visual Inspection		HRS		485.9			3036.5		0	
			AFL		97		630		0		
			MOS		26.5	19	48	12 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
	Airframe										
553007	Vertical Stabilizer Assembly (Internal) - Detailed Inspection		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
	Airframe										
553008	Vertical Stabilizer Hirf/L - Detailed Inspection		HRS		485.9			3036.5		0	
			AFL		97		630		0		
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
	Airframe										
553009	Vertical Stabilizer Rear Beam Hirf/L - Detailed Inspection		HRS		485.9			3036.5		0	
			AFL		97		630		0		
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
	Airframe										
553010	Vertical Stabilizer - Removal / Installation 60P5530000-001 6089		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		128.2			21 Apr 2014			
			MSC								
	Airframe		O/C								
553011	Vertical Stabilizer Leading Edge - Polishing		HRS		.4			3522		0	
			AFL		1		726		0		
			MOS		2.5		12	12 Oct 2024	31 Oct 2025	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
553012	External Metallic Surfaces (Vertical Stabilizer Leading Edge) - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		6	23 Oct 2014	31 Mar 2025	30 Apr 2025	
			[MOS: +1m/-1m]								
Airframe											
553100	Vertical Stabilizer Interior of Leading Edge - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
553101	Leading Edge HF Anenna Assembly - Removal / Installation 60P5531601A0046090		HRS	TSN:13.3	3509.1			13.3			0
			AFL	TSN:5	722			5			0
			MOS	TSN:4	124.4			13 Aug 2014			
			MSC				O/C				
Airframe											
553200	Vertical Stabilizer Box Section Internal Structure - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
553201	Vertical Stabilizer Box Section (Internal) Flight Controls - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	11	96	12 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
553500	Vertical Stabilizer Pivot Lugs and Interface - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
553501	Vertical Stabilizer (Internal) Boomerang Fittings - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
554000	Vertical Stabilizer Rudder Hinges and Support Fittings - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
554001	Rudder Assembly Hinge Brackets and Swivel Links - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	4	96	19 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
554002	Rudder (External) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	10	48	21 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
554003	Rudder Assembly Front Beam (Internal) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
56 - Windows											
561100	Windshield (Left) - Removal / Installation 1159SCB5102-913273H0886		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
561101	Windshield (Right) - Removal / Installation 1159SCB5102-1113255H8966		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
561102	Side Window (Left) - Removal / Installation 60P5612001Z00313149H7921		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
561103	Side Window (Right) - Removal / Installation		HRS		3522.4			0			0
	60P5612002Z003		AFL		727			0			0
	1269H1129		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
561106	Cockpit Windshield Nonmetallic Interior Structures (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
561107	Cockpit Windshield Nonmetallic Interior Structures (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
561108	Cockpit Windshield Metallic Interior Structures (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
561109	Cockpit Windshield Metallic Interior Structures (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
561111	Windshield Weather Seals (Humpseal) (Left) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.7	37	24	04 Oct 2024	30 Nov 2026*	31 Dec 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
561112	Windshield Weather Seals (Humpseal) (Right) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			AFL		1			726			0
			MOS		2.7	37	24	04 Oct 2024	30 Nov 2026*	31 Dec 2026	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
561200	Cockpit Side Window Nonmetallic Interior Structures (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
561201	Cockpit Side Window Nonmetallic Interior Structures (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
561202	Cockpit Side Window Metallic Interior Structures (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
561203	Cockpit Side Window Metallic Interior Structures (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562100	Cabin Window (Left No. 1) - Removal / Installation 60P5621001Z004 12080H1909		HRS	TSN:12.9	3522.4			0			0
			AFL	TSN:8	727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
562101	Cabin Window (Left No. 2) - Removal / Installation 60P5621001Z004 13339H8324		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
562102	Cabin Window (Left No. 3) - Removal / Installation 60P5621001Z004 13344H8681		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562103	Cabin Window (Left No. 4) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13346H812	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562104	Cabin Window (Left No. 5) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13350H9078	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562105	Cabin Window (Left No. 6) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	1333H8326	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562106	Cabin Window (Left No. 7) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13346H8813	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562107	Cabin Window (Left No. 8) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13345H8777	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562108	Cabin Window (Right No. 1) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13345H8778	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562109	Cabin Window (Right No. 2) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13350H9077	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562110	Cabin Window (Right No. 3) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13344H8680	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562111	Cabin Window (Right No. 4) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13344H8679	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562112	Cabin Windows (Right No. 5) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13350H9161	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562113	Cabin Window (Right No. 6) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13350H960	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562114	Cabin Window (Right No. 7) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13344H8682	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562115	Cabin Window (Right No. 8) - Removal / Installation		HRS		3522.4			0			0
	60P5621001Z004	13343H8530	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
562164	Cabin Windows - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1			23 Oct 2014			
	Airframe		MSC				O/C				
562165	Cabin Windows - Leak Check		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.2			19 Nov 2022			
	Airframe		MSC				O/C				
562166	Cabin Fixed Window Nonmetallic Interior Structures (Left No. 1) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562167	Cabin Fixed Window Nonmetallic Interior Structures (Left No. 2) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562168	Cabin Fixed Window Nonmetallic Interior Structures (Left No. 3) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562169	Cabin Fixed Window Nonmetallic Interior Structures (Left No. 4) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562170	Cabin Fixed Window Nonmetallic Interior Structures (Left No. 5) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562171	Cabin Fixed Window Nonmetallic Interior Structures (Left No. 6) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562172	Cabin Fixed Window Nonmetallic Interior Structures (Left No. 7) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562173	Cabin Fixed Window Nonmetallic Interior Structures (Left No. 8) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562174	Cabin Fixed Window Nonmetallic Interior Structures (Right No. 1) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562175	Cabin Fixed Window Nonmetallic Interior Structures (Right No. 2) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562176	Cabin Fixed Window Nonmetallic Interior Structures (Right No. 3) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562177	Cabin Fixed Window Nonmetallic Interior Structures (Right No. 4) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562178	Cabin Fixed Window Nonmetallic Interior Structures (Right No. 5) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562179	Cabin Fixed Window Nonmetallic Interior Structures (Right No. 6) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562180	Cabin Fixed Window Nonmetallic Interior Structures (Right No. 7) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562181	Cabin Fixed Window Nonmetallic Interior Structures (Right No. 8) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562182	Cabin Fixed Window Metallic Interior Structures (Left No. 1) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562183	Cabin Fixed Window Metallic Interior Structures (Left No. 2) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562184	Cabin Fixed Window Metallic Interior Structures (Left No. 3) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562185	Cabin Fixed Window Metallic Interior Structures (Left No. 4) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562186	Cabin Fixed Window Metallic Interior Structures (Left No. 5) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562187	Cabin Fixed Window Metallic Interior Structures (Left No. 6) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562188	Cabin Fixed Window Metallic Interior Structures (Left No. 7) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562189	Cabin Fixed Window Metallic Interior Structures (Left No. 8) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562190	Cabin Fixed Window Metallic Interior Structures (Right No. 1) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562191	Cabin Fixed Window Metallic Interior Structures (Right No. 2) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562192	Cabin Fixed Window Metallic Interior Structures (Right No. 3) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562193	Cabin Fixed Window Metallic Interior Structures (Right No. 4) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562194	Cabin Fixed Window Metallic Interior Structures (Right No. 5) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562195	Cabin Fixed Window Metallic Interior Structures (Right No. 6) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562196	Cabin Fixed Window Metallic Interior Structures (Right No. 7) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
562197	Cabin Fixed Window Metallic Interior Structures (Right No. 8) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		200	23 Oct 2014	30 Jun 2031	31 Jul 2031	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
564000	Primary and Auxiliary Pressure Bulkhead Viewport - Operational Check		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.6	24	24	07 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
57 - Wings											
570001	Wing Lower Cover Skins - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
570003	Wing (Internal) (Left) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570004	Wing (Internal) (Right) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
570005	Wing (Internal) Wiring Installations (Left) - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570006	Wing (Internal) Wiring Installations (Right) - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570007	Wing (Upper Surface External) from Wtbf to Winglet (Left) - Zonal Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.5	12	72	11 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570008	Wing (Upper Surface External) from Wtbf to Winglet (Right) - Zonal Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.5	12	72	11 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570009	Wing (Lower Surface External) from Wtbf to Winglet (Left) - Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570010	Wing (Lower Surface External) from Wtbf to Winglet (Right) - Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570011	Wing (External) Flaps, Spoilers and Ailerons (Left) - Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
570012	Wing (External) Flaps, Spoilers and Ailerons (Right) - Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571016	Wing - Removal / Installation 60P5700000A001		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
571021	Wing Forward Spar Splices (External) Surfaces (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571022	Wing Forward Spar Splices (External) Surfaces (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571023	Wing Aft, Spars, Splices and Spar Cans (External) Surfaces (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571024	Wing Aft, Spars, Splices and Spar Cans (External) Surfaces (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571025	Wing Aft Spar Splices (External) Surfaces (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571026	Wing Aft Spar Splices (External) Surfaces (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571027	Wing Tank (Internal) BI 0 - Rbs 135 (Left) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	26	24	05 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571028	Wing Tank (Internal) BI 0 - Rbs 135 (Right) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.7	26	24	05 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571029	Wing Tank Internal Rbs 135 - Ws 551 (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571030	Wing Tank Internal Rbs 135 - Ws 551 (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26	-2	96	25 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571031	Main Landing Gear Sponsons and Support Fittings (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	19	48	12 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: REF SQUAWK 16.3											
571032	Main Landing Gear Sponsons and Support Fittings (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	19	48	12 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571033	Sponson Beam, Main Landing Gear (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3215105M005	000115	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
571034	Sponson Beam, Main Landing Gear (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P3215106M007	000112	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
571035	Main Landing Gear Sponson Bores (With Main Landing Gear Removed) (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571036	Main Landing Gear Sponson Bores (With Main Landing Gear Removed) (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571040	BI 34 Rib (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		13510**	0	13510		0
			MOS		128.2			21 Apr 2014			
Airframe											
571041	BI 34 Rib (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		13510**	0	13510		0
			MOS		128.2			21 Apr 2014			
Airframe											
571044	Sponson Outboard Beam (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		12710**	0	12710		0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571045	Sponson Outboard Beam (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		12710**	0	12710		0
			MOS		128.2			21 Apr 2014			
Airframe											
571200	Wing Rear Beam Wiring Harness Installation (Left) - Enhanced Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
571201	Wing Rear Beam Wiring Harness Installation (Right) - Enhanced Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
571202	Wing Drain Holes (Left) - Enhanced Zonal Inspection		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			16 Sep 2016			
Airframe											
571203	Wing Drain Holes (Right) - Enhanced Zonal Inspection		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			16 Sep 2016			
Airframe											
571204	Wing Rear Beam Spar and Aileron (Left) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	16	48	15 Oct 2022	31 Oct 2026*	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
571205	Wing Rear Beam Spar and Aileron (Right) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	16	48	15 Oct 2022	31 Oct 2026*	30 Nov 2026	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571206	Wing Rear Spar / Flap / Spoiler (Left) - Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571207	Wing Rear Spar / Flap / Spoiler (Right) - Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571208	Wing Rear Beam Rbs 135.66 - Rbs 441 Hirf/L (Left) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571209	Wing Rear Beam Rbs 135.66 - Rbs 441 Hirf/L (Right) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571210	Wing Rear Beam Rbs 441 - Rbs 534 Hirf/L (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	7	96	16 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571211	Wing Rear Beam Rbs 441 - Rbs 534 Hirf/L (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	7	96	16 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571214	Rear Spar AT Sponson Attachment (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		3655**	0	3655		0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571215	Rear Spar AT Sponson Attachment (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		3655**	0	3655	0	
			MOS		128.2			21 Apr 2014			
Airframe											
571218	Rear Spar AT BI 49 Attachment Fitting (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		14325**	0	14325	0	
			MOS		128.2			21 Apr 2014			
Airframe											
571219	Rear Spar AT BI 49 Attachment Fitting (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		14325**	0	14325	0	
			MOS		128.2			21 Apr 2014			
Airframe											
571222	Rear Spar AT Main Landing Gear Side Brace Fitting (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		14325**	0	14325	0	
			MOS		128.2			21 Apr 2014			
Airframe											
571223	Rear Spar AT Main Landing Gear Side Brace Fitting (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		14325**	0	14325	0	
			MOS		128.2			21 Apr 2014			
Airframe											
571307	Sponson Lower Skin AT Rear Spar Attach (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		14450**	0	14450	0	
			MOS		128.2			21 Apr 2014			
Airframe											
571308	Sponson Lower Skin AT Rear Spar Attach (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		14450**	0	14450	0	
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571600	Wing to Fuselage, Floor Support and Wtbf Fittings (Left) - Detailed Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.4	8	72	15 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571601	Wing to Fuselage, Floor Support and Wtbf Fittings (Right) - Detailed Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.4	8	72	15 Oct 2020	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571602	Fitting, Wing to Fuselage-Aft Torque Box (Left) - Removal / Installation 60P5700131M006H17615-T1		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
571603	Fitting, Wing to Fuselage-Aft Torque Box (Right) - Removal / Installation 60P5700132M0048H30168-T23		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
571606	FS 529 Vertical Fitting - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		14410**	0	14410		0
			MOS		128.2			21 Apr 2014			
Airframe											
571607	BI 49 Drag Fitting - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		6205**	0	6205		0
			MOS		128.2			21 Apr 2014			
Airframe											
571900	Wing to Wing Mate (External) Splices and Skegs (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	7	96	16 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571901	Wing to Wing Mate (External) Splices and Skegs (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.3	7	96	16 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
571904	Front Spar Splice AT BI 103 (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		15250**	0	15250		0
			MOS		128.2			21 Apr 2014			
Airframe											
571905	Front Spar Splice AT BI 103 (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		15250**	0	15250		0
			MOS		128.2			21 Apr 2014			
Airframe											
571907	Rear Spar Rbs 150 Splice (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		8610**	0	8610		0
			MOS		128.2			21 Apr 2014			
Airframe											
571908	Rear Spar Rbs 150 Splice (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		8610**	0	8610		0
			MOS		128.2			21 Apr 2014			
Airframe											
571910	Lower Cover Splice Stringers (Left) - Visual Inspection		HRS		3522.4			0			0
			AFL		727		10200**	0	10200		0
			MOS		128.2			21 Apr 2014			
Airframe											
571911	Lower Cover Splice Stringers (Right) - Visual Inspection		HRS		3522.4			0			0
			AFL		727		10200**	0	10200		0
			MOS		128.2			21 Apr 2014			
Airframe											
571912	Lower Cover Coaming Stringers (Left) - Visual Inspection		HRS		3522.4			0			0
			AFL		727		16870**	0	16870		0
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571913	Lower Cover Coaming Stringers (Right) - Visual Inspection		HRS		3522.4			0			0
			AFL		727		16870**	0	16870		0
			MOS		128.2			21 Apr 2014			
Airframe											
571915	BI 0 Splice AT Front Spar - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		15250**	0	15250		0
			MOS		128.2			21 Apr 2014			
Airframe											
571917	BI 0 Splice AT Rear Spar - Ndt Inspecton		HRS		3522.4			0			0
			AFL		727		8610**	0	8610		0
			MOS		128.2			21 Apr 2014			
Airframe											
572000	Lightning Ignition Source Protection Feature - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.3	-24	96	16 Nov 2022	31 Oct 2030*	30 Nov 2030	
[End Of Month Item] [MOS: +1m/-1m]											
Airframe											
573200	Winglet (Left) - Removal / Installation 60P5730011A001TIG050L		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
573201	Winglet (Right) - Removal / Installation 60P5730012A001TIG031R		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
Airframe											
573202	Winglet Leading Edge - Polishing		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.5			12 Oct 2021			
Airframe											
[End Of Month Item]											
573204	Winglet (Internal) (Left) - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
Airframe											
[End Of Month Item] [MOS: +1m/-1m]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
573205	Winglet (Internal) (Right) - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
573206	Winglet Exterior Surfaces (Left) - Zonal Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.4	9	72	14 Oct 2020	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
573207	Winglet Exterior Surfaces (Right) - Zonal Inspection		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.4	9	72	14 Oct 2020	31 Oct 2026*	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
574000	Wing Inboard Leading Edge Assembly (Left) - Removal / Installation 60P5740001A012CPI 096		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe	MSCO/C									
574001	Wing Inboard Center Leading Edge Assembly (Left) - Removal / Installation 60P5740003A017CPI 100		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe	MSCO/C									
574002	Wing Inboard Center Mid Leading Edge Assembly (Left) - Removal / Installation 60P5740005A016CPI 111		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe	MSCO/C									
574003	Wing Outboard Center Leading Edge Assembly (Left) - Removal / Installation 60P5740007A015CPI 098		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe	MSCO/C									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574004	Wing Outboard Leading Edge Assembly (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5740009A017	CPI 098	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
574005	Wing Inboard Leading Edge Assembly (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5740014A008	CPI 096	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
574006	Wing Inboard Center Leading Edge Assembly (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5740004A014	CPI 101	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
574007	Wing Inboard Center Mid Leading Edge Assembly (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5740006A014	CPI 098	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
574008	Wing Outboard Center Leading Edge Assembly (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5740008A013	CPI 100	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
574009	Wing Outboard Leading Edge Assembly (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5740010A015	CPI 096	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
574010	Wing Leading Edge (Left) - Polishing		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5		12	12 Oct 2024	31 Oct 2025	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

Notes: REF IN PROCESS WORK FLOW INDEX #15 COMPLETED BY SHARPE DETAILS.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574011	Wing Leading Edge (Right) - Polishing		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5		12	12 Oct 2024	31 Oct 2025	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
574013	External Metallic Surfaces (Wing Leading Edge - Left) - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		6	23 Oct 2014	31 Mar 2025	30 Apr 2025	
			[MOS: +1m/-1m]								
574014	External Metallic Surfaces (Wing Leading Edge - Right) - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		6	23 Oct 2014	31 Mar 2025	30 Apr 2025	
			[MOS: +1m/-1m]								
574020	Wing Leading Edge Wiring Installations (Left) - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	9	96	14 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
574021	Wing Leading Edge Wiring Installations (Right) - Enhanced Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.4	9	96	14 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
574022	Wing Leading Edge (Internal) (Left) - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
574023	Wing Leading Edge (Internal) (Right) - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574024	Wing Leading Edge With Gap Bands Removed (Left) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
574025	Wing Leading Edge With Gap Bands Removed (Right) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5	13	96	10 Oct 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
574026	Wing Leading Edge and Gap Bands (External) (Left) - Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: VERIFIED COMPLETION DONE BY KENNETH LAFLEUR 311724 IN CORRIDOR ON 09/16/2018											
574027	Wing Leading Edge and Gap Bands (External) (Right) - Zonal Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: VERIFIED COMPLETION DONE BY KENNETH LAFLEUR 311724 IN CORRIDOR ON 09/16/2018											
574032	Blend Panel (Left) - Removal / Installation 60P5740417A001L01 SN-UNKNOWN		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
			MOS	TSN:102	25.3			18 Nov 2022			N/A
			MSC				O/C				
Airframe											
574033	Blend Panel (Right) - Removal / Installation 60P5740418A003L01 SN-UNKNOWN		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
			MOS	TSN:102	25.3			18 Nov 2022			N/A
			MSC				O/C				
Airframe											
574036	Gap Band 01 (Left) - Removal / Installation 60P5740471A003L01 SN-UNKNOWN		HRS	TSN:3036.5	485.9			3036.5			0
			AFL	TSN:630	97			630			0
			MOS	TSN:101	26.3			18 Oct 2022			N/A
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574037	Gap Band 01 (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	60P40472A003L01 SN-UNKNOWN		AFL	TSN:630	97			630			0
			MOS	TSN:101	26.3			18 Oct 2022			N/A
	Airframe		MSC				O/C				
574038	Gap Band 02 (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	60P5740473A003L01 SN-UNKNOWN		AFL	TSN:630	97			630			0
			MOS	TSN:101	26.3			18 Oct 2022			N/A
	Airframe		MSC				O/C				
574039	Gap Band 02 (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	60P5740474A003L01 SN-UNKNOWN		AFL	TSN:630	97			630			0
			MOS	TSN:101	26.3			18 Oct 2022			N/A
	Airframe		MSC				O/C				
574040	Gap Band 03 (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	60P5740475A003L01 SN-UNKNOWN		AFL	TSN:630	97			630			0
			MOS	TSN:101	26.3			18 Oct 2022			N/A
	Airframe		MSC				O/C				
574041	Gap Band 03 (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	60P5740476A003L01 SN-UNKNOWN		AFL	TSN:630	97			630			0
			MOS	TSN:101	26.3			18 Oct 2022			N/A
	Airframe		MSC				O/C				
574042	Gap Band 04 (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	60P5740477A003L01 SN-UNKNOWN		AFL	TSN:630	97			630			0
			MOS	TSN:101	26.3			18 Oct 2022			N/A
	Airframe		MSC				O/C				
574043	Gap Band 04 (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	60P5740478A003L01 SN-UNKNOWN		AFL	TSN:630	97			630			0
			MOS	TSN:101	26.3			18 Oct 2022			N/A
	Airframe		MSC				O/C				
574044	Gap Band 05 (Left) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	60P5740481A001L01 SN-UNKNOWN		AFL	TSN:630	97			630			0
			MOS	TSN:101	26.3			18 Oct 2022			N/A
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574045	Gap Band 05 (Right) - Removal / Installation		HRS	TSN:3036.5	485.9			3036.5			0
	60P57482A001L01	SN-UNKNOWN	AFL	TSN:630	97			630			0
			MOS	TSN:101	26.3			18 Oct 2022			N/A
	Airframe		MSC				O/C				
574056	Winglet Inboard Leading Edge Assembly (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	PN	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
574057	Winglet Inboard Leading Edge Assembly (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	PN	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575006	Wing Trailing Edge Box (Interior) (Left) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	2	96	21 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
575007	Wing Trailing Edge Box (Interior) (Right) - Zonal Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.2	2	96	21 Oct 2022	31 Oct 2030*	30 Nov 2030	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
575008	Wing Flight Control Attach Fittings (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									
575009	Wing Flight Control Attach Fittings (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
	Airframe	[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575010	Inboard / Outboard Fixed Trailing Edges and Cove Panels (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
575011	Inboard / Outboard Fixed Trailing Edges and Cove Panels (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
575301	Flap Upper Surface (Left) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
575302	Flap Upper Surface (Right) - Detailed Inspection		HRS		.4			3522			0
			AFL		1			726			0
			MOS		3	34	24	27 Sep 2024	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
575307	Flap Fittings (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
575308	Flap Fittings (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
575309	Flap Track Fitting A (Left Upper) - Removal / Installation 60P5755231M003 22891 8-3-1 0090		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
575310	Flap Track Fitting A (Left Lower) - Removal / Installation 60P5755233M005 22852 2-2-41 0100		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575311	Flap Track Fitting B (Left Upper) - Removal / Installation		HRS		3522.4			0			0
	60P5755235M001 E782 2-3-84 0084		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575312	Flap Track Fitting B (Left Lower) - Removal / Installation		HRS		3522.4			0			0
	60P5755237M001 E782 2-3-25 0088		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575313	Flap Track Fitting C (Left Upper) - Removal / Installation		HRS		3522.4			0			0
	60P5755239M001 A048 2-1-2 0042		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575314	Flap Track Fitting C (Left Lower) - Removal / Installation		HRS		3522.4			0			0
	60P5755241M001 G19658 K01-22 0079		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575315	Flap Track Fitting D (Left Upper) - Removal / Installation		HRS		3522.4			0			0
	60P5755243M001 06666 DD-5 0076		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575317	Flap Track Fitting A (Right Upper) - Removal / Installation		HRS		3522.4			0			0
	60P5755232M001 22801 7-1-45 0055		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575318	Flap Track Fitting A (Right Lower) - Removal / Installation		HRS		3522.4			0			0
	60P5755234M003 22852 2-2-31 0097		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575319	Flap Track Fitting B (Right Upper) - Removal / Installation		HRS		3522.4			0			0
	60P5755236M002 22891		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575320	Flap Track Fitting B (Right Lower) - Removal / Installation		HRS		3522.4			0			0
	60P5755238M003	22891 9-3-52 0094	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575321	Flap Track Fitting C (Right Upper) - Removal / Installation		HRS		3522.4			0			0
	60P5755240M001	22891 9-3-73 0085	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575322	Flap Track Fitting C (Right Lower) - Removal / Installation		HRS		3522.4			0			0
	60P5755242M001	22891 8-2-2 0085	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575323	Flap Track Fitting D (Right Upper) - Removal / Installation		HRS		3522.4			0			0
	60P5755244M001	06666 DD-3 0083	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575340	Flaptrack A (Left) - Removal / Installation		HRS		3522.4			0			0
	60P5755211M005	J056250-09KL-1-15-1-1	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575341	Flaptrack A (Right) - Removal / Installation		HRS		3522.4			0			0
	60P5755212M001	J058865-228343-1-5-1-2	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575342	Flaptrack B (Left) - Removal / Installation		HRS		3522.4			0			0
	60P5755213M007	J058876-228783-3-3-1-2	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575343	Flaptrack B (Right) - Removal / Installation		HRS		3522.4			0			0
	60P5755214M003	J052273-228517-2-4-1-1	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575344	Flaptrack C (Left) - Removal / Installation		HRS		3522.4			0			0
	60P5755215M006	J058893-228784-2-3-1-1	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575345	Flaptrack C (Right) - Removal / Installation		HRS		3522.4			0			0
	60P5755216M003	J055000-73KT-2-5-1-1	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575346	Flaptrack D (Left) - Removal / Installation		HRS		3522.4			0			0
	60P5755217M003	J056312-228519-2-8-1-1	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575347	Flaptrack D (Right) - Removal / Installation		HRS		3522.4			0			0
	60P5755218M001	J055111-228342-1-2-1-1	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
575360	Flap Track A (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5050**	0	5050		0
			MOS		128.2			21 Apr 2014			
	Airframe										
575361	Flap Track A (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5050**	0	5050		0
			MOS		128.2			21 Apr 2014			
	Airframe										
575364	Flap Track A Attach Fittings (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		11680**	0	11680		0
			MOS		128.2			21 Apr 2014			
	Airframe										
575365	Flap Track A Attach Fittings (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		11680**	0	11680		0
			MOS		128.2			21 Apr 2014			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575367	Flap Track B (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		7355**	0	7355	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575368	Flap Track B (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		7355**	0	7355	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575369	Flap Track B Lugs (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5505**	0	5505	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575370	Flap Track B Lugs (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5505**	0	5505	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575371	Flap Track B Attach Fittings (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5410**	0	5410	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575372	Flap Track B Attach Fittings (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5410**	0	5410	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575374	Flap Track C (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		4815**	0	4815	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575375	Flap Track C (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		4815**	0	4815	0	
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575376	Flap Track C Lugs (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5905**	0	5905	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575377	Flap Track C Lugs (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		5905**	0	5905	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575378	Flap Track C Attach Fittings (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		6835**	0	6835	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575379	Flap Track C Attach Fittings (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		6835**	0	6835	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575381	Flap Track D (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		6495**	0	6495	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575382	Flap Track D (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		6495**	0	6495	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575383	Flap Track D Attach Fittings (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		12315**	0	12315	0	
			MOS		128.2			21 Apr 2014			
Airframe											
575384	Flap Track D Attach Fittings (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		12315**	0	12315	0	
			MOS		128.2			21 Apr 2014			
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
576000	Aileron Hinge Fittings and Forward Spar (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
576001	Aileron Hinge Fittings and Forward Spar (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
577000	Spoiler Hinge Fittings (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
577001	Spoiler Hinge Fittings (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		144	23 Oct 2014	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
577002	Spoiler Panels (Left) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.5	-18	96	10 Nov 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
577003	Spoiler Panels (Right) - Detailed Inspection		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.5	-20	96	12 Nov 2022	31 Oct 2030*	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
71 - Power Plant											
710001	Engine (Left) - Removal / Installation BR700-725A1-12		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710002	Engine (Right) - Removal / Installation		HRS		3522.4			0			0
	BR700-725A1-12		AFL		727			0			0
	25288		MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
710005	No. 1 Engine - Powerplant - N2 Overspeed		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
710005	No. 2 Engine - Powerplant - N2 Overspeed		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
710006	No. 1 Engine - Powerplant - N1 Overspeed In Forward Thrust		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
710006	No. 2 Engine - Powerplant - N1 Overspeed In Forward Thrust		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
710007	No. 1 Engine - Powerplant - N1 Overspeed In Reverse Thrust		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
710007	No. 2 Engine - Powerplant - N1 Overspeed In Reverse Thrust		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710008	No. 1 Engine - Powerplant - Engine Overtemperature AT High Power		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710008	No. 2 Engine - Powerplant - Engine Overtemperature AT High Power		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710009	No. 1 Engine - Powerplant - Engine Overtemperature During Engine Start and Relight		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710009	No. 2 Engine - Powerplant - Engine Overtemperature During Engine Start and Relight		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710010	No. 1 Engine - Powerplant - Combined Engine Overtemperature AT High Power and N2 Overspeed or N1 Overspeed (In Forward Thrust)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710010	No. 2 Engine - Powerplant - Combined Engine Overtemperature AT High Power and N2 Overspeed or N1 Overspeed (In Forward Thrust)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710011	No. 1 Engine - Powerplant - Uncommand Engine Shutdown Following Ground Start of Both Engines		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710011	No. 2 Engine - Powerplant - Uncommand Engine Shutdown Following Ground Start of Both Engines		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710012	No. 1 Engine - Procedure after Lp Vibration Exceedance		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710012	No. 2 Engine - Procedure after Lp Vibration Exceedance		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710013	No. 1 Engine - Procedure after Hp Vibration Exceedance		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710013	No. 2 Engine - Procedure after Hp Vibration Exceedance		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710015	No. 1 Engine - Engine (Test 1) - Wet Motor Operation Leak Check		HRS		422.3			3100.1			0
			ENC		82			645			0
			MOS		22.9			30 Jan 2023			
			MSC				O/C				
Engine											
710015	No. 2 Engine - Engine (Test 1) - Wet Motor Operation Leak Check		HRS		422.3			3100.1			0
			ENC		82			645			0
			MOS		22.9			30 Jan 2023			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710016	No. 1 Engine - Engine Run Leak Check (Test 2A) - Lp and Bypass Duct Mounted Hp Fuel Systems and Oil System		HRS		.4			3522			0
			ENC		1			726			0
			MOS		2.5			12 Oct 2024			
			MSC				O/C				
Engine											
710016	No. 2 Engine - Engine Run Leak Check (Test 2A) - Lp and Bypass Duct Mounted Hp Fuel Systems and Oil System		HRS		.4			3522			0
			ENC		1			726			0
			MOS		2.5			12 Oct 2024			
			MSC				O/C				
Engine											
710017	No. 1 Engine - Engine Run Leak Check (Test 2B) - Hp Fuel System		HRS		1841.9			1680.5			0
			ENC		384			343			0
			MOS		73.8			02 Nov 2018			
			MSC				O/C				
Engine											
710017	No. 2 Engine - Engine Run Leak Check (Test 2B) - Hp Fuel System		HRS		1841.9			1680.5			0
			ENC		384			343			0
			MOS		73.8			02 Nov 2018			
			MSC				O/C				
Engine											
710018	Engine (Test 3A, Left) - T/Rev Check		HRS		1050.2			2472.2			0
			AFL		217			510			0
			MOS		43.9			29 Apr 2021			
			MSC				O/C				
Airframe											
710019	Engine (Test 3A, Right) - T/Rev Check		HRS		1050.2			2472.2			0
			AFL		217			510			0
			MOS		43.9			29 Apr 2021			
			MSC				O/C				
Airframe											
710020	Engine (Test 3B, Left) - T/Rev / Line Replaceable Unit Leak Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710021	Engine (Test 3B, Right) - T/Rev / Line Replaceable Unit Leak Check		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
710022	No. 1 Engine - Engine (Test 4) - Engine Power Assurance Check		HRS		1050.2			2472.2			0
			ENC		217			510			0
			MOS		43.9			29 Apr 2021			
			MSC				O/C				
Engine											
710022	No. 2 Engine - Engine (Test 4) - Engine Power Assurance Check		HRS		1050.2			2472.2			0
			ENC		217			510			0
			MOS		43.9			29 Apr 2021			
			MSC				O/C				
Engine											
710023	No. 1 Engine - Engine (Test 5) - Pretested Replacement Engine Test		HRS		3509.1			13.3			0
			ENC		722			5			0
			MOS		123.1			23 Sep 2014			
			MSC				O/C				
Engine											
710023	No. 2 Engine - Engine (Test 5) - Pretested Replacement Engine Test		HRS		3509.1			13.3			0
			ENC		722			5			0
			MOS		123.1			23 Sep 2014			
			MSC				O/C				
Engine											
710024	No. 1 Engine - Engine (Test 6) - Vibration Survey		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710024	No. 2 Engine - Engine (Test 6) - Vibration Survey		HRS		1508.2			2014.2			0
			ENC		311			416			0
			MOS		62.9			28 Sep 2019			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710025	No. 1 Engine - Engine (Test 7) - Lp Compressor (Fan) Trim Balance		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710025	No. 2 Engine - Engine (Test 7) - Lp Compressor (Fan) Trim Balance		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710026	No. 1 Engine - Engine (Test 7A) - Fan Trim Balance Check (Using One-Shot Method With External Vibration Analyzer - 1ST Alternate Method)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710026	No. 2 Engine - Engine (Test 7A) - Fan Trim Balance Check (Using One-Shot Method With External Vibration Analyzer - 1ST Alternate Method)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710027	No. 1 Engine - Engine (Test 7B) - Fan Trim Balance Check (Using Trial Weight Method With External Vibration Analyzer - 2ND Alternate Method)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710027	No. 2 Engine - Engine (Test 7B) - Fan Trim Balance Check (Using Trial Weight Method With External Vibration Analyzer - 2ND Alternate Method)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710028	No. 1 Engine - Engine (Test 8) - Oil Consumption Test		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
710028	No. 2 Engine - Engine (Test 8) - Oil Consumption Test		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
710029	No. 1 Engine - Engine (Test 9) - Fadec Operational Test		HRS		485.9			3036.5			0
			ENC		97			630		0	
			MOS		24.9		29 Nov 2022				
			MSC			O/C					
710029	No. 2 Engine - Engine (Test 9) - Fadec Operational Test		HRS		485.9			3036.5			0
			ENC		97			630		0	
			MOS		24.9		29 Nov 2022				
			MSC			O/C					
710030	No. 1 Engine - Lp Compressor (Fan) Blade SET - RE-Index		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
710030	No. 2 Engine - Lp Compressor (Fan) Blade SET - RE-Index		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
710031	No. 1 Engine - Lp Compressor (Fan) Blade SET - RE-Distribute (Shuffle)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710031	No. 2 Engine - Lp Compressor (Fan) Blade SET - RE-Distribute (Shuffle)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710032	No. 1 Engine - Inspection for Internal Oil Leaks - Inspection / Check		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710032	No. 2 Engine - Inspection for Internal Oil Leaks - Inspection / Check		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710033	No. 1 Engine - High Oil Consumption - Troubleshooting / Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710033	No. 2 Engine - High Oil Consumption - Troubleshooting / Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710034	No. 1 Engine - Powerplant - Inspection after Activation of Pressure Relief Door(S)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710034	No. 2 Engine - Powerplant - Inspection after Activation of Pressure Relief Door(S)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710035	Nacelle, T/Rev and Exhaust External (Left, Viewed from Platform) - Zonal Inspection		HRS		485.9		3000	3036.5	6036.5	6086.5	0
			AFL		97		630			0	
			MOS		26.3	15	48	16 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
710036	Nacelle, T/Rev and Exhaust External (Right, Viewed from Platform) - Zonal Inspection		HRS		485.9		3000	3036.5	6036.5	6086.5	0
			AFL		97		630			0	
			MOS		26.3	15	48	16 Oct 2022	31 Oct 2026*	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
710037	No. 1 Engine - Engine - Core Wash		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710037	No. 2 Engine - Engine - Core Wash		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710038	No. 1 Engine - Engine - Cleaning (after Contamination With FIRE Extinguishant)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
710038	No. 2 Engine - Engine - Cleaning (after Contamination With FIRE Extinguishant)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
710039	No. 1 Engine - Engine Maintenance Program Declaration		HRS		3133.7			388.7	0		0
			ENC		652			75	0	0	
			MOS		111.3			17 Sep 2015			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710039	No. 2 Engine - Engine Maintenance Program Declaration		HRS		3133.7			388.7	0		0
			ENC		652			75	0		0
			MOS		111.3			16 Sep 2015			
			MSC				O/C				
Engine											
710042	No. 1 Engine - Engine Calendar Life - Task Orientated BR700-725A1-12										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
711005	Engine Lower Fan Cowl Door (Right) - Enhanced Zonal Inspection		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			AFL		97			630			0
			MOS		26.3		48	17 Oct 2022	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
711006	Lower and Upper Cowl Door Latches (Upper Left) - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
711007	Lower and Upper Cowl Door Latches (Upper Right) - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
711008	Lower and Upper Cowl Door Latches (Lower Left) - Adjustment		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		63.1			23 Sep 2019			
			MSC				O/C				
Airframe											
711009	Lower and Upper Cowl Door Latches (Lower Right) - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
711100	Engine Inlet Cowl (Left) - Removal / Installation RD00101001-1RD1001L0093		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
711101	Engine Inlet Cowl (Right) - Removal / Installation RD00101001-2RD1001R0093		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
711104	Inlet Cowl (Left) - General Visual Inspection		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			AFL		97			630			0
			MOS		25.5			10 Nov 2022			
	Airframe		[HRS: +50/-50]								
711105	Inlet Cowl (Right) - General Visual Inspection		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			AFL		97			630			0
			MOS		25.5			10 Nov 2022			
	Airframe		[HRS: +50/-50]								
711106	Nose Cowl Structure FS 828.3 - FS 860.08 (Left) - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
711107	Nose Cowl Structure FS 828.3 - FS 860.08 (Right) - Zonal Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
711108	Inlet Cowl Lipskin (Left) - Nonabrasive Polish		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5		12	12 Oct 2024	31 Oct 2025	30 Nov 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: REF IN PROCESS WORK FLOW INDEX #15 COMPLETED BY SHARPE DETAILS.											
711109	Inlet Cowl Lipskin (Right) - Nonabrasive Polish		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5		12	12 Oct 2024	31 Oct 2025	30 Nov 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: REF IN PROCESS WORK FLOW INDEX #15 COMPLETED BY SHARPE DETAILS.											
711110	Inlet Cowl Lipskin (Left) - Cleaning		HRS		51.5			3470.9			0
			AFL		18			709			0
			MOS		8.5			12 Apr 2024			
	Airframe		MSC O/C								
Notes: REF IN PROCESS WORK FLOW INDEX #15 COMPLETED BY SHARPE DETAILS.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
711111	Inlet Cowl Lipskin (Right)- Cleaning		HRS		51.5			3470.9			0
			AFL		18			709			0
			MOS		8.5			12 Apr 2024			
			MSC				O/C				
Airframe											
Notes: REF IN PROCESS WORK FLOW INDEX #15 COMPLETED BY SHARPE DETAILS.											
711113	External Metallic Surfaces (Inlet Cowl Lipskin - Left) - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		6	23 Oct 2014	31 Mar 2025	30 Apr 2025	
			[MOS: +1m/-1m]								
Airframe											
711114	External Metallic Surfaces (Inlet Cowl Lipskin - Right) - General Visual Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		6	23 Oct 2014	31 Mar 2025	30 Apr 2025	
			[MOS: +1m/-1m]								
Airframe											
711200	Upper Cowl Door (Left) - Removal / Installation RD00102006-9 RD2006L0093		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
711201	Upper Cowl Door (Right) - Removal / Installation RD00102006-10 RD2006R0093		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
711300	Lower Cowl Door (Left) - Removal / Installation RD00102005-9 RD2005L0093		HRS	TSN:2014.2	1508.2			2014.2			0
			AFL	TSN:416	311			416			0
			MOS	TSN:65	63.1			23 Sep 2019			N/A
			MSC				O/C				
Airframe											
711301	Lower Cowl Door (Right) - Removal / Installation RD00102005-10 RD2005R0093		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
711400	Engine Fixed Cowl (Left) - Removal / Installation RD00102007-9 RD2007L0093		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
711401	Engine Fixed Cowl (Right) - Removal / Installation		HRS		3522.4			0			0
	RD00102007-10 RD2007R0093		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
711404	Engine Fixed Cowl (Left) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
711405	Engine Fixed Cowl (Right) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
711406	Engine Fixed Cowl (Left) - Detailed Inspection		HRS		485.9		1500	3036.5	4536.5		0
			AFL		97			630			0
			MOS		25.5			10 Nov 2022			
	Airframe		[HRS: -50]								
711407	Engine Fixed Cowl (Right) - Detailed Inspection		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			AFL		97			630			0
			MOS		25.5			10 Nov 2022			
	Airframe		[HRS: +50/-50]								
712000	Engine Attach Pins and Bolts (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: PN: 50028001-11 SN: <NONE>.											
712001	Engine Attach Pins and Bolts (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: PN: 50028001-11 SN: <NONE>.											
712004	Engine Mount Attach Pins (Left) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		10000**	0	10000		0
			MOS		128.2			21 Apr 2014			
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712005	Engine Mount Attach Pins (Right) - Ndt Inspection		HRS		3522.4			0			0
			AFL		727		10000**	0	10000		0
			MOS		128.2			21 Apr 2014			
Airframe											
712100	Chatterproof Bolt Assembly (Left Engine) Forward Inboard		HRS		3522.4			0			0
	Upper - Removal / Installation		AFL		727			0			0
	JR29859A	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712101	Chatterproof Bolt Assembly (Left Engine) Forward Inboard		HRS		3522.4			0			0
	Lower - Removal / Installation		AFL		727			0			0
	JR29859A	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712102	Chatterproof Bolt Assembly (Right Engine) Forward		HRS		3522.4			0			0
	Inboard Upper - Removal / Installation		AFL		727			0			0
	JR29859A	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712103	Chatterproof Bolt Assembly (Right Engine) Forward		HRS		3522.4			0			0
	Inboard Lower - Removal / Installation		AFL		727			0			0
	JR29859A	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712104	Engine Mount Fitting (Left Forward, FS 886) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P7121001A001	0214	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712105	Engine Mount Fitting (Right Forward, FS 886) - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P7121002A001	0143	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712112	Engine Mount Attach Pins (Left Upper Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5344001A004P01	PMSO232	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712113	Engine Mount Attach Pins (Left Upper Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5344001A045P01	PMSO293	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712114	Engine Mount Attach Pins (Left Lower Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5344001A002P01	PMSO247	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712115	Engine Mount Attach Pins (Left Lower Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5344001A046P01	PMSO235	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712116	Engine Mount Attach Pins (Right Upper Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5344001A004P01	PMSO250	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712117	Engine Mount Attach Pins (Right Upper Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5344001A045P01	PMSO296	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712118	Engine Mount Attach Pins (Right Lower Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5344001A002P01	PMSO252	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712119	Engine Mount Attach Pins (Right Lower Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5344001A046P01	PMSO290	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712120	Engine Mount Attach Pins (Left Upper Forward) - Replacement		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: PN: 60P5344001A004P01 SN: PMSO232. MRI PARENT CODE: 712112											
712121	Engine Mount Attach Pins (Left Upper Aft) - Replacement		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: PN: 60P5344001A045P01 SN: PMSO293. MRI PARENT CODE: 712113											
712122	Engine Mount Attach Pins (Left Lower Forward) - Replacement		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: PN: 60P5344001A002P01 SN: PMSO247. MRI PARENT CODE: 712114											
712123	Engine Mount Attach Pins (Left Lower Aft) - Replacement		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: PN: 60P5344001A046P01 SN: PMSO235. MRI PARENT CODE: 712115											
712124	Engine Mount Attach Pins (Right Upper Forward) - Replacement		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: PN: 60P5344001A004P01 SN: PMSO250. MRI PARENT CODE: 712116											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712125	Engine Mount Attach Pins (Right Upper Aft) - Replacement		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC				O/C				
Airframe											
Notes: PN: 60P5344001A045P01 SN: PMSO296. MRI PARENT CODE: 712117											
712126	Engine Mount Attach Pins (Right Lower Forward) - Replacement		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC				O/C				
Airframe											
Notes: PN: 60P5344001A002P01 SN: PMSO252. MRI PARENT CODE: 712118											
712127	Engine Mount Attach Pins (Right Lower Aft) - Replacement		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC				O/C				
Airframe											
Notes: PN: 60P5344001A046P01 SN: PMSO290. MRI PARENT CODE: 712119											
712128	Forward Engine Mount (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1	192	23 Oct 2014	31 Oct 2030	30 Nov 2030		
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712129	Forward Engine Mount (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1	192	23 Oct 2014	31 Oct 2030	30 Nov 2030		
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712130	Forward Engine Mount Thrust Pin and Sleeve (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1	192	23 Oct 2014	31 Oct 2030	30 Nov 2030		
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712131	Forward Engine Mount Thrust Pin and Sleeve (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1	192	23 Oct 2014	31 Oct 2030	30 Nov 2030		
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712132	Thrust and Alignment Strut Assemblies External (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712133	Thrust and Alignment Strut Assemblies External (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712134	Thrust and Alignment Strut Assemblies Internal (Left) - Special Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712135	Thrust and Alignment Strut Assemblies Internal (Right) - Special Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712200	Engine Mount (Left Aft, FS 951) - Removal / Installation 60P7122601Z001TY-141		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712201	Engine Mount (Right Aft, FS 951) - Removal / Installation 60P7122601Z001TY-195		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712206	Aft Engine Mount Fitting - Left Upper Forward - Removal / Installation 60P5342001A020P02C110133		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712207	Aft Engine Mount Fitting - Left Upper Aft - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P5342001A021P02	C110155	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712208	Aft Engine Mount Fitting - Left Lower Forward - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P5342001A018P02	C110135	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712209	Aft Engine Mount Fitting - Left Lower Aft - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P5342001A019P02	C110159	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712210	Aft Engine Mount Fitting - Right Upper Forward - Removal		HRS		3522.4			0			0
	/ Installation		AFL		727			0			0
	60P5342001A020P02	C110136	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712211	Aft Engine Mount Fitting - Right Upper Aft - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P5342001A021P02	C110160	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712212	Aft Engine Mount Fitting - Right Lower Forward - Removal		HRS		3522.4			0			0
	/ Installation		AFL		727			0			0
	60P5342001A018P02	C110165	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712213	Aft Engine Mount Fitting - Right Lower Aft - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P5342001A019P02	C110166	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712226	Aft Engine Mount Strut Assemblies External (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712227	Aft Engine Mount Strut Assemblies External (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712228	Aft Engine Mount Strut Assemblies Internal (Left) - Special Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712229	Aft Engine Mount Strut Assemblies Internal (Right) - Special Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
712230	Engine Aft Upper Suspension Strut (Left) - Removal / Installation 60P7122201Z001TY-0154		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712231	Engine Aft Upper Suspension Strut (Right) - Removal / Installation 60P7122201Z001TY-0210		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712232	Engine Aft Lower Suspension Strut (Left) - Removal / Installation 60P7122301Z001TY-0159		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712233	Engine Aft Lower Suspension Strut (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7122301Z001	TY-0218	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712300	Forward Upper Inboard Link (Left Engine) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123101Z001	0380	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712301	Forward Lower Engine Link (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123101Z001	0389	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712302	Forward Upper Inboard Link (Right Engine) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123101Z001	0388	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712303	Forward Lower Engine Link (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123101Z001	0392	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712304	Fuselage Engine Mount Link (Left Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001A010	J086452-000-012	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712305	Fuselage Engine Mount Link (Right Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001A010	J086452-000-002	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712306	Engine Mount Retaining CAP (Left Aft Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	525	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712307	Engine Mount Retaining CAP (Right Aft Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	973	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712308	Engine Mount Retaining CAP (Left Aft Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	527	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712309	Engine Mount Retaining CAP (Right Aft Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	1146	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712310	Engine Mount Retaining CAP (Left Forward Inboard Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M005	318	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712311	Engine Mount Retaining CAP (Right Forward Inboard Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M005	490	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712312	Engine Mount Retaining CAP (Left Forward Inboard Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M005	319	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712313	Engine Mount Retaining CAP (Right Forward Inboard Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M005	462	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712314	Engine Mount Retaining CAP (Left Forward Outboard Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M005	317	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712315	Engine Mount Retaining CAP (Right Forward Outboard Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M005	464	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712316	Engine Mount Thrust Strut Retaining CAP (Left Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	589	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712317	Engine Mount Thrust Strut Retaining CAP (Right Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	1126	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712318	Engine Mount Thrust Strut Retaining CAP (Left Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	590	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712319	Engine Mount Thrust Strut Retaining CAP (Right Aft) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	994	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712320	Engine Mount Alignment Strut Retaining CAP (Left Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M006	99	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712321	Engine Mount Alignment Strut Retaining CAP (Right Forward) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M006	167	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712322	Engine Mount Thrust Strut (Left) - Removal / Installation		HRS		3522.4			0			0
	60P7123401Z001 TY-0140		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712323	Engine Mount Thrust Strut (Right) - Removal / Installation		HRS		3522.4			0			0
	60P7123401Z002 TY-0221		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712324	Engine Mount Alignment Strut (Left) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123501Z001	TY-0215	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712325	Engine Mount Alignment Strut (Right) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123501Z002	TY-0239	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712326	Engine Mount Link Attach Pin (Left Forward Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M025	100	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712327	Engine Mount Link Attach Pin (Right Forward Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M025	158	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712328	Engine Mount Link Attach Pin (Left Forward Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M024	069	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712329	Engine Mount Link Attach Pin (Right Forward Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M024	157	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712330	Engine Mount Attach Pin (Left Forward Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M030	070	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712331	Engine Mount Attach Pin (Right Forward Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M030	134	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712332	Engine Mount Attach Pin (Left Aft Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M034	099	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712333	Engine Mount Attach Pin (Right Aft Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M034	144	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712334	Engine Mount Attach Pin (Left Aft Inboard Upper) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P7123001M026	099	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712335	Engine Mount Attach Pin (Right Aft Inboard Upper) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P7123001M026	134	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712336	Engine Mount Thrust Strut Attach Pin (Left Forward) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P7123001M027	231	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712337	Engine Mount Thrust Strut Attach Pin (Right Forward) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P7123001M027	185	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712338	Engine Mount Thrust Strut Attach Pin (Left Aft) - Removal		HRS		3522.4			0			0
	/ Installation		AFL		727			0			0
	60P7123001M029	183	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712339	Engine Mount Thrust Strut Attach Pin (Right Aft) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P7123001M029	173	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712340	Engine Mount Alignment Strut Attach Pin (Left Forward) -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P7123001M028	189	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712341	Engine Mount Alignment Strut Attach Pin (Right Forward)		HRS		3522.4			0			0
	- Removal / Installation		AFL		727			0			0
	60P7123001M028	157	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712342	Pin, - Engine to Engine Mount, Right Engine Forward		HRS		3522.4			0			0
	Inboard Lower - Removal / Installation		AFL		727			0			0
	60P7123001M022	290	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712343	Pin, - Engine to Engine Mount, Left Engine Forward		HRS		3522.4			0			0
	Inboard Upper - Removal / Installation		AFL		727			0			0
	60P7123001M022	189	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712344	Pin, - Engine to Engine Mount, Aft - Left - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P7123001M023	159	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712345	Pin, Thrust - Engine Mount, Forward - Left Engine -		HRS		3522.4			0			0
	Removal / Installation		AFL		727			0			0
	60P7123001A001	MX02916-002	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712346	Pin, Hollow - Engine to Engine Mount, Fwd - Removal /		HRS		3522.4			0			0
	Installation		AFL		727			0			0
	60P7123001M022	304	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712347	Pin, - Engine to Engine Mount, Forward - Right - Removal		HRS		3522.4			0			0
	/ Installation		AFL		727			0			0
	60P7123001M022	188	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712348	Pin, - Engine to Engine Mount, Aft - Right - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M023	148	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712349	Pin, Thrust - Engine Mount, Forward - Right Engine - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001A001	J084622-000-023	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712352	Retaining CAP - Forward Engine Mount Link Upper (Left Engine) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	455	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712353	Retaining CAP - Forward Engine Mount Link Upper (Right Engine) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	1021	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712354	Retaining CAP - Forward Engine Mount Link Lower (Left Engine) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	459	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712355	Retaining CAP - Forward Engine Mount Link Lower (Right Engine) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P7123001M004	1140	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
712394	Left Thrust Strut Fitting Assembly - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	60P5347001A005	PMS0039	MOS	TSN:15	128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712396	Right Thrust Strut Fitting Assembly - Removal / Installation 60P5347002A004 PMS0041		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS	TSN:7	128.2		21 Apr 2014				
			MSC			O/C					
712398	Link Assemblies (Left) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1	192	23 Oct 2014	31 Oct 2030	30 Nov 2030		
			[End Of Month Item] [MOS: +1m/-1m]								
712399	Link Assemblies (Right) - Detailed Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		122.1	192	23 Oct 2014	31 Oct 2030	30 Nov 2030		
			[End Of Month Item] [MOS: +1m/-1m]								
715000	No. 1 Engine - Electrical Harnesses - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
715000	No. 2 Engine - Electrical Harnesses - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
715001	No. 1 Engine - Electrical Harnesses - Insulation Resistance Check		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
715001	No. 2 Engine - Electrical Harnesses - Insulation Resistance Check		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
715002	No. 1 Engine - Electrical Harnesses - Continuity Check		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
715002	No. 2 Engine - Electrical Harnesses - Continuity Check		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
715003	No. 1 Engine - Harnesses - Cleaning		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
715003	No. 2 Engine - Harnesses - Cleaning		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
717100	No. 1 Engine - Drains Tank Ejector - Removal / Installation CV41-14-2 13-0605181		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
717100	No. 2 Engine - Drains Tank Ejector - Removal / Installation CV41-14-2 13-081795		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
717104	No. 1 Engine - Drains Tank Ejector Filter (Conical) - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
717104	No. 2 Engine - Drains Tank Ejector Filter (Conical) - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
717107	No. 1 Engine - Drains Collection Tank - General Visual Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
717107	No. 2 Engine - Drains Collection Tank - General Visual Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
717108	No. 1 Engine - Drains Tubes and Fittings - Detailed Inspection		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			ENC		97		630		0		
			MOS		26.3		17 Oct 2022				
			[HRS: +50/-50]								
Engine											
717108	No. 2 Engine - Drains Tubes and Fittings - Detailed Inspection		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			ENC		97		630		0		
			MOS		26.3		17 Oct 2022				
			[HRS: +50/-50]								
Engine											
717109	No. 1 Engine - Engine Drain System - Leakage Rate Test		HRS		13.2			3509.2			0
			ENC		7		720		0		
			MOS		6.2		19 Jun 2024				
			MSC			O/C					
Engine											
717109	No. 2 Engine - Engine Drain System - Leakage Rate Test		HRS		13.2			3509.2			0
			ENC		7		720		0		
			MOS		6.2		19 Jun 2024				
			MSC			O/C					
Engine											
71EN1	No. 1 Engine BR700-725A1-12	25289	HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.7		04 Apr 2014				
			MSC			E/C					
Airframe											
71EN2	No. 2 Engine BR700-725A1-12	25288	HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.7		04 Apr 2014				
			MSC			E/C					
Airframe											
72 - Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720001	No. 1 Engine - Lp Compressor Module (Bladed and Unbladed) - Removal / Installation - Inlet Cowl Removed FW73627 RRSUNDL470		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720001	No. 2 Engine - Lp Compressor Module (Bladed and Unbladed) - Removal / Installation - Inlet Cowl Removed FW73627 RRSUNDL181		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720003	No. 1 Engine - Lp Compressor Module (Unbladed) - Removal / Installation - Inlet Cowl Installed FW73627 RRSUNDL181		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720003	No. 2 Engine - Lp Compressor Module (Unbladed) - Removal / Installation - Inlet Cowl Installed FW73627 RRSUNDL181		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720005	No. 1 Engine - Hp Compressor - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720005	No. 2 Engine - Hp Compressor - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720006	No. 1 Engine - Combustion Section - Special Detailed Inspection		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			ENC		97			630		0	
			MOS		25.7			03 Nov 2022			
			[HRS: +50/-50]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720006	No. 2 Engine - Combustion Section - Special Detailed Inspection		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			ENC		97			630			0
			MOS		25.7			03 Nov 2022			
			[HRS: +50/-50]								
Engine											
720007	No. 1 Engine - Hp Turbine - Special Detailed Inspection		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			ENC		97			630			0
			MOS		25.7			03 Nov 2022			
			[HRS: +50/-50]								
Engine											
720007	No. 2 Engine - Hp Turbine - Special Detailed Inspection		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			ENC		97			630			0
			MOS		25.7			03 Nov 2022			
			[HRS: +50/-50]								
Engine											
720008	No. 1 Engine - Lp Turbine - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720008	No. 2 Engine - Lp Turbine - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720009	No. 1 Engine - Engine after Surge - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720009	No. 2 Engine - Engine after Surge - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720010	No. 1 Engine - Engine Lightning Strike - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720010	No. 2 Engine - Engine Lightning Strike - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013				
			MSC			O/C					
720011	No. 1 Engine - Engine after Contamination With Volcanic ASH - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013		0		
			MSC			O/C					
720011	No. 2 Engine - Engine after Contamination With Volcanic ASH - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013		0		
			MSC			O/C					
720012	No. 1 Engine - Engine after Birdstrike or Slush Ingestion - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013		0		
			MSC			O/C					
720012	No. 2 Engine - Engine after Birdstrike or Slush Ingestion - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013		0		
			MSC			O/C					
720013	No. 1 Engine - Engine after Shock Loading - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013		0		
			MSC			O/C					
720013	No. 2 Engine - Engine after Shock Loading - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013		0		
			MSC			O/C					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720014	No. 1 Engine - Engine after In-Flight Shutdown - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
720014	No. 2 Engine - Engine after In-Flight Shutdown - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
720015	No. 1 Engine - Reverse Thrust Use In Emergency Aborted Take-Off, Emergency Stop or Above Idle With 60 Knots or Less Aircraft Speed - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
720015	No. 2 Engine - Reverse Thrust Use In Emergency Aborted Take-Off, Emergency Stop or Above Idle With 60 Knots or Less Aircraft Speed - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
720016	No. 1 Engine - Engine after Shedding / Ingestion of Ice - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
720016	No. 2 Engine - Engine after Shedding / Ingestion of Ice - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
720017	No. 1 Engine - Engine after Foreign Object Ingestion - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720017	No. 2 Engine - Engine after Foreign Object Ingestion - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720018	No. 1 Engine - Engine after Bypass Duct Blockage - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720018	No. 2 Engine - Engine after Bypass Duct Blockage - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720020	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 1) - Removal / Installation FW68304210067013009128		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720020	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 1) - Removal / Installation FW68304210067013009122		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720021	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 2) - Removal / Installation FW68304210067013009190		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720021	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 2) - Removal / Installation FW68304210067013009135		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720022	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 3)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009201	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720022	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 3)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009196	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720023	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 4)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009211	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720023	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 4)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009203	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720024	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 5)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009220	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720024	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 5)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009212	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720025	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 6)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009232	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720025	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 6)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009279	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720026	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 7)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009236	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720026	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 7)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009345	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720027	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 8)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009239	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720027	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 8)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009455	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720028	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 9)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009242	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720028	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 9)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	FW68304	210067013009450	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720029	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 10) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009258	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720029	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 10) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009447	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720030	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 11) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009266	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720030	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 11) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009442	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720031	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 12) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009280	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720031	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 12) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009441	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720032	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 13) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009290	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720032	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 13) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009428	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720033	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 14) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009295	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720033	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 14) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009421	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720034	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 15) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009301	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720034	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 15) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009382	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720035	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 16) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009307	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720035	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 16) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009367	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720036	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 17) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009308	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720036	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 17) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009365	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720037	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 18) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009312	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720037	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 18) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009361	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720038	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 19) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009313	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720038	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 19) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009353	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720039	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 20) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009321	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720039	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 20) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009352	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720040	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 21) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009326	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720040	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 21) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009347	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720041	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 22) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009327	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720041	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 22) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009298	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720042	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 23) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009328	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720042	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 23) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009214	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720043	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 24) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009340	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720043	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 24) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009205	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720044	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 25) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009349	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720044	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 25) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009200	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720045	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 26) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009401	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720045	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 26) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009177	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720046	No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 27) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009438	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720046	No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 27) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW68304	210067013009123	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720300	No. 1 Engine - Core Fairing Fireseals - General Visual Inspection		HRS		485.9			3036.5			0
			ENC		97			630			0
			MOS		25.8			02 Nov 2022			
			MSC				-				
Engine											
720300	No. 2 Engine - Core Fairing Fireseals - General Visual Inspection		HRS		485.9			3036.5			0
			ENC		97			630			0
			MOS		25.8			02 Nov 2022			
			MSC				-				
Engine											
720316	No. 1 Engine - Lp Turbine Fairings - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720316	No. 2 Engine - Lp Turbine Fairings - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720321	No. 1 Engine - Left Engine Flow Plates - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	PN	SN-UNKNOWN	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720321	No. 2 Engine - Left Engine Flow Plates - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	PN	SN-UNKNOWN	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720325	No. 1 Engine - Left Engine Core FIRE Detection Sensor		HRS		3522.4			0			0
	Assembly Grommet - Removal / Installation		ENC		727			0			0
	PN	SN-UNKNOWN	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720325	No. 2 Engine - Left Engine Core FIRE Detection Sensor		HRS		3522.4			0			0
	Assembly Grommet - Removal / Installation		ENC		727			0			0
	PN	SN-UNKNOWN	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
720329	No. 1 Engine - Left Engine Core FIRE Detection Sensor		HRS		3522.4			0			0
	Assembly Grommet - Inspection		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
720329	No. 2 Engine - Left Engine Core FIRE Detection Sensor		HRS		3522.4			0			0
	Assembly Grommet - Inspection		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
721600	No. 1 Engine - Accessory Gearbox - Removal / Installation		HRS		3522.4			0			0
	87500-11	725B00222	ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
721600	No. 2 Engine - Accessory Gearbox - Removal / Installation		HRS		3522.4			0			0
	87500-11	725B00221	ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723100	No. 1 Engine - Lp Compressor (Fan) Disc - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723100	No. 2 Engine - Lp Compressor (Fan) Disc - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723101	No. 1 Engine - Lp Compressor Fan Blades - Detailed Inspection		HRS		.4		1500	3522	5022	5072	0
			ENC		1			726			0
			MOS		2.7			05 Oct 2024			
			[HRS: +50/-50]								
Engine											
723101	No. 2 Engine - Lp Compressor Fan Blades - Detailed Inspection		HRS		.4		1500	3522	5022	5072	0
			ENC		1			726			0
			MOS		2.7			05 Oct 2024			
			[HRS: +50/-50]								
Engine											
723102	No. 1 Engine - Lp Compressor Disc and Fan Shaft Curvic Couplings - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723102	No. 2 Engine - Lp Compressor Disc and Fan Shaft Curvic Couplings - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723103	No. 1 Engine - Lp Compressor Anti-Score Ring - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723103	No. 2 Engine - Lp Compressor Anti-Score Ring - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723110	No. 2 Engine - Lp Compressor Fan Blades (No. 1) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JLA676-57	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723111	No. 1 Engine - Lp Compressor Fan Blades (No. 2) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JLT756-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723111	No. 2 Engine - Lp Compressor Fan Blades (No. 2) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JMW824-58	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723112	No. 1 Engine - Lp Compressor Fan Blades (No. 3) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JMW804-58	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723112	No. 2 Engine - Lp Compressor Fan Blades (No. 3) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JKN498-56	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723113	No. 1 Engine - Lp Compressor Fan Blades (No. 4) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JMW829-58	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723113	No. 2 Engine - Lp Compressor Fan Blades (No. 4) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JLA669-57	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723114	No. 1 Engine - Lp Compressor Fan Blades (No. 5) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA639-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723114	No. 2 Engine - Lp Compressor Fan Blades (No. 5) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JKN471-56	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723115	No. 1 Engine - Lp Compressor Fan Blades (No. 6) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA660-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723115	No. 2 Engine - Lp Compressor Fan Blades (No. 6) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JMW786-58	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723116	No. 1 Engine - Lp Compressor Fan Blades (No. 7) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLT745-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723116	No. 2 Engine - Lp Compressor Fan Blades (No. 7) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JMW846-58	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723117	No. 1 Engine - Lp Compressor Fan Blades (No. 8) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA622-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723117	No. 2 Engine - Lp Compressor Fan Blades (No. 8) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JLT742-57	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723118	No. 1 Engine - Lp Compressor Fan Blades (No. 9) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JLT783-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723118	No. 2 Engine - Lp Compressor Fan Blades (No. 9) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JLA586-57	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723119	No. 1 Engine - Lp Compressor Fan Blades (No. 10) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JLA589-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723119	No. 2 Engine - Lp Compressor Fan Blades (No. 10) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JMW834-58	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723120	No. 1 Engine - Lp Compressor Fan Blades (No. 11) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JLT738-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723120	No. 2 Engine - Lp Compressor Fan Blades (No. 11) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	FW86142	222977JLA562-56	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723121	No. 1 Engine - Lp Compressor Fan Blades (No. 12) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA712-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723121	No. 2 Engine - Lp Compressor Fan Blades (No. 12) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLT770-57	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723122	No. 1 Engine - Lp Compressor Fan Blades (No. 13) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLT746-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723122	No. 2 Engine - Lp Compressor Fan Blades (No. 13) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JMW861-58	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723123	No. 1 Engine - Lp Compressor Fan Blades (No. 14) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLT751-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723123	No. 2 Engine - Lp Compressor Fan Blades (No. 14) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLT752-57	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723124	No. 1 Engine - Lp Compressor Fan Blades (No. 15) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA656-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723124	No. 2 Engine - Lp Compressor Fan Blades (No. 15) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JMW844-58	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723125	No. 1 Engine - Lp Compressor Fan Blades (No. 16) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA700-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723125	No. 2 Engine - Lp Compressor Fan Blades (No. 16) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JMW848-58	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723126	No. 1 Engine - Lp Compressor Fan Blades (No. 17) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JMW790-58	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723126	No. 2 Engine - Lp Compressor Fan Blades (No. 17) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLT758-57	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723127	No. 1 Engine - Lp Compressor Fan Blades (No. 18) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA728-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723127	No. 2 Engine - Lp Compressor Fan Blades (No. 18) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JMW808-58	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723128	No. 1 Engine - Lp Compressor Fan Blades (No. 19) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JMW836-58	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723128	No. 2 Engine - Lp Compressor Fan Blades (No. 19) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLT780-57	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723129	No. 1 Engine - Lp Compressor Fan Blades (No. 20) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA583-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723129	No. 2 Engine - Lp Compressor Fan Blades (No. 20) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA658-57	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723130	No. 1 Engine - Lp Compressor Fan Blades (No. 21) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JKN499-56	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723130	No. 2 Engine - Lp Compressor Fan Blades (No. 21) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JMW826-58	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723131	No. 1 Engine - Lp Compressor Fan Blades (No. 22) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JDZ598-48	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723131	No. 2 Engine - Lp Compressor Fan Blades (No. 22) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA630-57	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723132	No. 1 Engine - Lp Compressor Fan Blades (No. 23) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA627-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723132	No. 2 Engine - Lp Compressor Fan Blades (No. 23) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLT736-57	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723133	No. 1 Engine - Lp Compressor Fan Blades (No. 24) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JLA693-57	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723133	No. 2 Engine - Lp Compressor Fan Blades (No. 24) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW86142	222977JMW821-58	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723158	No. 1 Engine - Lp Compressor (Fan) Disc Assembly - Touch-Up Dry Film Lubricant (BRG3183)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723158	No. 2 Engine - Lp Compressor (Fan) Disc Assembly - Touch-Up Dry Film Lubricant (BRG3183)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723159	No. 1 Engine - Lp Compressor Rotor Blade Assembly - Repair Leading and Trailing Edges By Scalloping (BRG3137)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
723159	No. 2 Engine - Lp Compressor Rotor Blade Assembly - Repair Leading and Trailing Edges By Scalloping (BRG3137)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
723160	No. 1 Engine - Lp Compressor Fan Blade Assembly - Replace Chocking PAD (BRG3138)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
723160	No. 2 Engine - Lp Compressor Fan Blade Assembly - Replace Chocking PAD (BRG3138)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
723161	No. 1 Engine - Lp Compressor Fan Blade Assembly - Repair Airfoil Surface Damage (BRG3181)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
723161	No. 2 Engine - Lp Compressor Fan Blade Assembly - Repair Airfoil Surface Damage (BRG3181)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
723162	No. 1 Engine - Lp Compressor Fan Blade Assembly - Touch-Up Dry Film Lubricant (BRG3184)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723162	No. 2 Engine - Lp Compressor Fan Blade Assembly - Touch-Up Dry Film Lubricant (BRG3184)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723174	No. 1 Engine - Fan Disc - Removal / Installation FW73627RRSUNDL181		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723174	No. 2 Engine - Fan Disc - Removal / Installation FW73627RRSUNDL181		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723175	No. 1 Engine - Fan Disc - Discard FW73627RRSUNDL181		HRS		3522.4			0			0
			ENC		727		10000	0	10000		0
			MOS		132.2			19 Dec 2013			
Engine											
723175	No. 2 Engine - Fan Disc - Discard FW73627RRSUNDL181		HRS		3522.4			0			0
			ENC		727		10000	0	10000		0
			MOS		133			25 Nov 2013			
Engine											
723176	No. 1 Engine - Low-Pressure Compressor (Fan) Blade No. 1 - Discard FW86142222977JLA674-57		HRS		3522.4			0			0
			ENC		727		5000	0	5000		0
			MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723110											
723176	No. 2 Engine - Low-Pressure Compressor (Fan) Blade No. 1 - Discard FW86142222977JLA676-57		HRS		3522.4			0			0
			ENC		727		5000	0	5000		0
			MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723110											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723177	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 2 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT756-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723111											
723177	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 2 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW824-58	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723111											
723178	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 3 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW804-58	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723112											
723178	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 3 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JKN498-56	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723112											
723179	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 4 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW829-58	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723113											
723179	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 4 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA669-57	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723113											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723180	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 5 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA639-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723114											
723180	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 5 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JKN471-56	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723114											
723181	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 6 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA660-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723115											
723181	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 6 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW786-58	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723115											
723182	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 7 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT745-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723116											
723182	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 7 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW846-58	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723116											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723183	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 8 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA622-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723117											
723183	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 8 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT742-57	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723117											
723184	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 9 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT783-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723118											
723184	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 9 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA586-57	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723118											
723185	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 10 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA589-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723119											
723185	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 10 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW834-58	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723119											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723186	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 11 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT738-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723120											
723186	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 11 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA562-56	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723120											
723187	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 12 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA712-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723121											
723187	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 12 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT770-57	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723121											
723188	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 13 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT746-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723122											
723188	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 13 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW861-58	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723122											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723189	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 14 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT751-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723123											
723189	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 14 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT752-57	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723123											
723190	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 15 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA656-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723124											
723190	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 15 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW844-58	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723124											
723191	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 16 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA700-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723125											
723191	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 16 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW848-58	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723125											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723192	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 17 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW790-58	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723126											
723192	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 17 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT758-57	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723126											
723193	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 18 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA728-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723127											
723193	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 18 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW808-58	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723127											
723194	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 19 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW836-58	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723128											
723194	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 19 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT780-57	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723128											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723195	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 20 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA583-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723129											
723195	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 20 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA658-57	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723129											
723196	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 21 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JKN499-56	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723130											
723196	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 21 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW826-58	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723130											
723197	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 22 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JDZ598-48	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723131											
723197	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 22 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA630-57	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723131											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723198	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 23 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA627-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723132											
723198	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 23 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLT736-57	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723132											
723199	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 24 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JLA693-57	MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 723133											
723199	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 24 - Discard		ENC		727		5000	0	5000		0
	FW86142	222977JMW821-58	MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 723133											
723200	No. 1 Engine - Lp Compressor Outlet Guide Vanes -		HRS		3522.4		4800	0	4800	4850	0
	Detailed Inspection		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
[HRS: +50/-50]											
Engine											
723200	No. 2 Engine - Lp Compressor Outlet Guide Vanes -		HRS		3522.4		4800	0	4800	4850	0
	Detailed Inspection		ENC		727			0			0
			MOS		133			25 Nov 2013			
[HRS: +50/-50]											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723201	No. 1 Engine - Intermediate Case - Detailed Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		122.1		240	23 Oct 2014	31 Oct 2034	30 Nov 2034	
			[End Of Month Item] [MOS: +1m/-1m]								
723201	No. 2 Engine - Intermediate Case - Detailed Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		122.1		240	23 Oct 2014	31 Oct 2034	30 Nov 2034	
			[End Of Month Item] [MOS: +1m/-1m]								
723202	No. 1 Engine - Intermediate Case Struts - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
723202	No. 2 Engine - Intermediate Case Struts - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
723203	No. 1 Engine - Lp Compressor Static Seal Housing - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
723203	No. 2 Engine - Lp Compressor Static Seal Housing - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
723204	No. 1 Engine - NI Speed Probe Plugs (N1-1 to Eec) - Interchange		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723204	No. 2 Engine - NI Speed Probe Plugs (N1-1 to Eec) - Interchange		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723205	No. 1 Engine - NI Speed Probe Plugs (N1-2 to Eec) - Interchange		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723205	No. 2 Engine - NI Speed Probe Plugs (N1-2 to Eec) - Interchange		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723206	No. 1 Engine - NI Speed Probe Plugs (N1 OPR Harness to Airframe) - Interchange		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723206	No. 2 Engine - NI Speed Probe Plugs (N1 OPR Harness to Airframe) - Interchange		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723207	No. 1 Engine - NI Speed Probe Plugs (N2 OPR Harness to Airframe) - Interchange		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723207	No. 2 Engine - NI Speed Probe Plugs (N2 OPR Harness to Airframe) - Interchange		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723208	No. 1 Engine - Lp Compressor Outlet Guide Vanes - Repair By Damage Dressing and Restoration of Airfoil (BRG3144)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
723208	No. 2 Engine - Lp Compressor Outlet Guide Vanes - Repair By Damage Dressing and Restoration of Airfoil (BRG3144)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
723209	No. 1 Engine - Lp Compressor Outlet Guide Vanes - Repair Leading Edge Using Doubler (BRG3139)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
723209	No. 2 Engine - Lp Compressor Outlet Guide Vanes - Repair Leading Edge Using Doubler (BRG3139)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
723210	No. 1 Engine - Lp Compressor Outlet Guide Vanes - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
723210	No. 2 Engine - Lp Compressor Outlet Guide Vanes - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
723211	No. 1 Engine - Fan Shaft - Removal / Installation FW50313RRDSFTB42954		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			-					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723211	No. 2 Engine - Fan Shaft - Removal / Installation		HRS		3522.4			0			0
	FW50313	RRDSFTB43191	ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				-				
723212	No. 1 Engine - Fan Shaft - Discard		HRS		3522.4			0			0
	FW50313	RRDSFTB42954	ENC		727		10000	0	10000		0
			MOS		132.2			19 Dec 2013			
	Engine										
Notes: MRI PARENT CODE: 723211											
723212	No. 2 Engine - Fan Shaft - Discard		HRS		3522.4			0			0
	FW50313	RRDSFTB43191	ENC		727		10000	0	10000		0
			MOS		133			25 Nov 2013			
	Engine										
Notes: MRI PARENT CODE: 723211											
723213	No. 1 Engine - Intermediate Case - Removal / Installation		HRS		3522.4			0			0
	FW84603	200210AS0188	ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
723213	No. 2 Engine - Intermediate Case - Removal / Installation		HRS		3522.4			0			0
	FW84603	200210AS0187	ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
723214	No. 1 Engine - Intermediate Case - Discard		HRS		3522.4			0			0
	FW84603	200210AS0188	ENC		727		15000	0	15000		0
			MOS		132.2			19 Dec 2013			
	Engine										
Notes: MRI PARENT CODE: 723213											
723214	No. 2 Engine - Intermediate Case - Discard		HRS		3522.4			0			0
	FW84603	200210AS0187	ENC		727		15000	0	15000		0
			MOS		133			25 Nov 2013			
	Engine										
Notes: MRI PARENT CODE: 723213											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723215	No. 1 Engine - Lp Compressor Engine Section Stators - Detailed Inspection		HRS		3522.4		4800	0	4800		0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013				
Engine											
723215	No. 2 Engine - Lp Compressor Engine Section Stators - Detailed Inspection		HRS		3522.4		4800	0	4800		0
			ENC		727		0		0		
			MOS		133		25 Nov 2013				
Engine											
723300	No. 1 Engine - Hp Compressor Front Drum (Stage 1 Disc, Stages 2-6 Blisks) - Removal / Installation FW76921 2190		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013				
			MSC			-					
Engine											
723300	No. 2 Engine - Hp Compressor Front Drum (Stage 1 Disc, Stages 2-6 Blisks) - Removal / Installation FW76921 2173		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013				
			MSC			-					
Engine											
723301	No. 1 Engine - Hp Compressor Front Drum (Stage 1 Disc, Stages 2-6 Blisks) - Discard FW76921 2190		HRS		3522.4			0			0
			ENC		727		10000	0	10000		0
			MOS		132.2		19 Dec 2013				
Engine											
Notes: MRI PARENT CODE: 723300											
723301	No. 2 Engine - Hp Compressor Front Drum (Stage 1 Disc, Stages 2-6 Blisks) - Discard FW76921 2173		HRS		3522.4			0			0
			ENC		727		10000	0	10000		0
			MOS		133		25 Nov 2013				
Engine											
Notes: MRI PARENT CODE: 723300											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723302	No. 1 Engine - Hp Compressor Rear Drum (Stages 7-10 Disc) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW84118	1186	MOS		132.2			19 Dec 2013			
			MSC				-				
Engine											
723302	No. 2 Engine - Hp Compressor Rear Drum (Stages 7-10 Disc) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW84118	1183	MOS		133			25 Nov 2013			
			MSC				-				
Engine											
723303	No. 1 Engine - Hp Compressor Rear Drum (Stages 7-10 Discs) - Discard		HRS		3522.4			0			0
			ENC		727		10000	0	10000		0
	FW84118	1186	MOS		132.2			19 Dec 2013			
Engine											
723303	No. 2 Engine - Hp Compressor Rear Drum (Stages 7-10 Discs) - Discard		HRS		3522.4			0			0
			ENC		727		10000	0	10000		0
	FW84118	1183	MOS		133			25 Nov 2013			
Engine											
723334	No. 1 Engine - Variable Stator Vane Actuating Mechanism - Functional Check		HRS		485.9		1200	3036.5	4236.5	4286.5	0
			ENC		97			630			0
			MOS		26.1		48	23 Oct 2022	31 Oct 2026	30 Nov 2026	
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
(723334) Engine											
723334	No. 2 Engine - Variable Stator Vane Actuating Mechanism - Functional Check		HRS		485.9		1200	3036.5	4236.5	4286.5	0
			ENC		97			630			0
			MOS		26.1		48	23 Oct 2022	31 Oct 2026	30 Nov 2026	
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
(723334) Engine											
723335	No. 1 Engine - Variable Stator Vane Actuation Mechanism - Lubrication		HRS		485.9		1200	3036.5	4236.5	4286.5	0
			ENC		97			630			0
			MOS		26.1		48	23 Oct 2022	31 Oct 2026	30 Nov 2026	
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]										
(723335) Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723335	No. 2 Engine - Variable Stator Vane Actuation Mechanism - Lubrication		HRS		485.9		1200	3036.5	4236.5	4286.5	0
			ENC		97			630			0
			MOS		26.1		48	23 Oct 2022	31 Oct 2026	30 Nov 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
(723335)											
Engine											
723400	No. 1 Engine - Lp Compressor Case Outer Surface - Detailed Inspection		HRS		.4			3522			0
			ENC		1			726			0
			MOS		2.5	13	120	10 Oct 2024	31 Oct 2034*	30 Nov 2034	
			[End Of Month Item] [MOS: +1m/-1m]								
Engine											
723400	No. 2 Engine - Lp Compressor Case Outer Surface - Detailed Inspection		HRS		.4			3522			0
			ENC		1			726			0
			MOS		2.5	13	120	10 Oct 2024	31 Oct 2034*	30 Nov 2034	
			[End Of Month Item] [MOS: +1m/-1m]								
Engine											
723401	No. 1 Engine - Lp Compressor Case Inner Surface - General Visual Inspection		HRS		.4		1500	3522	5022	5072	0
			ENC		1			726			0
			MOS		2.6			06 Oct 2024			
			[HRS: +50/-50]								
Engine											
723401	No. 2 Engine - Lp Compressor Case Inner Surface - General Visual Inspection		HRS		.4		1500	3522	5022	5072	0
			ENC		1			726			0
			MOS		2.6			06 Oct 2024			
			[HRS: +50/-50]								
Engine											
723402	No. 1 Engine - Lp Compressor Case Assembly - Repair Fan Track Liner Without Damaged Honeycomb Above Grp Layer Using Filler (BRG3140)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723402	No. 2 Engine - Lp Compressor Case Assembly - Repair Fan Track Liner Without Damaged Honeycomb Above Grp Layer Using Filler (BRG3140)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723403	No. 1 Engine - Lp Compressor Case Assembly - Repair Fan Track Liner With Damaged Honeycomb Above Grp Layer Using Filler (BRG3141)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC			O/C					
Engine											
723403	No. 2 Engine - Lp Compressor Case Assembly - Repair Fan Track Liner With Damaged Honeycomb Above Grp Layer Using Filler (BRG3141)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC			O/C					
Engine											
723404	No. 1 Engine - Lp Compressor Case Assembly - Repair Rear Lining Panel Using Polysulphide Compound (BRG3142)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC			O/C					
Engine											
723404	No. 2 Engine - Lp Compressor Case Assembly - Repair Rear Lining Panel Using Polysulphide Compound (BRG3142)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC			O/C					
Engine											
723409	No. 1 Engine - Case Assembly - Removal / Installation FW77996 230479Y1BA00050		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC			O/C					
Engine											
723409	No. 2 Engine - Case Assembly - Removal / Installation FW77996 230479Y1BA00049		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC			O/C					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723500	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 1- Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA674-57. MRI PARENT CODE: 723110											
723500	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 1- Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA676-57. MRI PARENT CODE: 723110											
723501	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 2 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT756-57. MRI PARENT CODE: 723111											
723501	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 2 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW824-58. MRI PARENT CODE: 723111											
723502	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 3 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW804-58. MRI PARENT CODE: 723112											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723502	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 3 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JKN498-56. MRI PARENT CODE: 723112											
723503	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 4 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW829-58. MRI PARENT CODE: 723113											
723503	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 4 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA669-57. MRI PARENT CODE: 723113											
723504	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 5 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA639-57. MRI PARENT CODE: 723114											
723504	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 5 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JKN471-56. MRI PARENT CODE: 723114											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723505	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 6 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA660-57. MRI PARENT CODE: 723115											
723505	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 6 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW786-58. MRI PARENT CODE: 723115											
723506	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 7 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT745-57. MRI PARENT CODE: 723116											
723506	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 7 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW846-58. MRI PARENT CODE: 723116											
723507	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 8 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA622-57. MRI PARENT CODE: 723117											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723507	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 8 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT742-57. MRI PARENT CODE: 723117											
723508	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 9 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT783-57. MRI PARENT CODE: 723118											
723508	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 9 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA586-57. MRI PARENT CODE: 723118											
723509	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 10 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA589-57. MRI PARENT CODE: 723119											
723509	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 10 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW834-58. MRI PARENT CODE: 723119											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723510	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 11- Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT738-57. MRI PARENT CODE: 723120											
723510	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 11- Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA562-56. MRI PARENT CODE: 723120											
723511	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 12 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA712-57. MRI PARENT CODE: 723121											
723511	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 12 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT770-57. MRI PARENT CODE: 723121											
723512	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 13 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT746-57. MRI PARENT CODE: 723122											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723512	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 13 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW861-58. MRI PARENT CODE: 723122											
723513	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 14 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT751-57. MRI PARENT CODE: 723123											
723513	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 14 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT752-57. MRI PARENT CODE: 723123											
723514	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 15 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA656-57. MRI PARENT CODE: 723124											
723514	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 15 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW844-58. MRI PARENT CODE: 723124											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723515	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 16 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA700-57. MRI PARENT CODE: 723125											
723515	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 16 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW848-58. MRI PARENT CODE: 723125											
723516	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 17 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW790-58. MRI PARENT CODE: 723126											
723516	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 17 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT758-57. MRI PARENT CODE: 723126											
723517	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 18 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA728-57. MRI PARENT CODE: 723127											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723517	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 18 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW808-58. MRI PARENT CODE: 723127											
723518	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 19 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW836-58. MRI PARENT CODE: 723128											
723518	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 19 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT780-57. MRI PARENT CODE: 723128											
723519	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 20 - Blade Root Copper Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA583-57. MRI PARENT CODE: 723129											
723519	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 20 - Blade Root Copper Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA658-57. MRI PARENT CODE: 723129											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723520	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 21- Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JKN499-56. MRI PARENT CODE: 723130											
723520	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 21- Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JMW826-58. MRI PARENT CODE: 723130											
723521	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 22 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JDZ598-48. MRI PARENT CODE: 723131											
723521	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 22 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA630-57. MRI PARENT CODE: 723131											
723522	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 23 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA627-57. MRI PARENT CODE: 723132											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723522	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 23 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLT736-57. MRI PARENT CODE: 723132											
723523	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 24 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		132.2			19 Dec 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA674-57. MRI PARENT CODE: 723110											
723523	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 24 - Blade Root Copper Nickel Indium Coating -		ENC		727		5000	0	5000		0
	Refurbishment		MOS		133			25 Nov 2013			
Engine											
Notes: PN: FW86142 SN: 222977JLA676-57. MRI PARENT CODE: 723110											
723524	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 1- Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT756-57. MRI PARENT CODE: 723111											
723524	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 1- Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW824-58. MRI PARENT CODE: 723111											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723525	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 2 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW804-58. MRI PARENT CODE: 723112											
723525	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 2 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JKN498-56. MRI PARENT CODE: 723112											
723526	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 3 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW829-58. MRI PARENT CODE: 723113											
723526	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 3 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA669-57. MRI PARENT CODE: 723113											
723527	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 4 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA639-57. MRI PARENT CODE: 723114											
723527	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 4 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JKN471-56. MRI PARENT CODE: 723114											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723528	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 5 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA660-57. MRI PARENT CODE: 723115											
723528	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 5 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW786-58. MRI PARENT CODE: 723115											
723529	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 6 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT745-57. MRI PARENT CODE: 723116											
723529	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 6 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW846-58. MRI PARENT CODE: 723116											
723530	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 7 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA622-57. MRI PARENT CODE: 723117											
723530	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 7 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT742-57. MRI PARENT CODE: 723117											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723531	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 8 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT783-57. MRI PARENT CODE: 723118											
723531	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 8 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA586-57. MRI PARENT CODE: 723118											
723532	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 9 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA589-57. MRI PARENT CODE: 723119											
723532	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 9 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW834-58. MRI PARENT CODE: 723119											
723533	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 10 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT738-57. MRI PARENT CODE: 723120											
723533	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 10 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA562-56. MRI PARENT CODE: 723120											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723534	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 11 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA712-57. MRI PARENT CODE: 723121											
723534	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 11 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT770-57. MRI PARENT CODE: 723121											
723535	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 12 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT746-57. MRI PARENT CODE: 723122											
723535	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 12 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW861-58. MRI PARENT CODE: 723122											
723536	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 13 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT751-57. MRI PARENT CODE: 723123											
723536	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 13 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT752-57. MRI PARENT CODE: 723123											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723537	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 14 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA656-57. MRI PARENT CODE: 723124											
723537	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 14 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW844-58. MRI PARENT CODE: 723124											
723538	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 15 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA700-57. MRI PARENT CODE: 723125											
723538	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 15 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW848-58. MRI PARENT CODE: 723125											
723539	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 16 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW790-58. MRI PARENT CODE: 723126											
723539	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 16 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT758-57. MRI PARENT CODE: 723126											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723540	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 17 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA728-57. MRI PARENT CODE: 723127											
723540	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 17 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW808-58. MRI PARENT CODE: 723127											
723541	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 18 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW836-58. MRI PARENT CODE: 723128											
723541	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 18 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT780-57. MRI PARENT CODE: 723128											
723542	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 19 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA583-57. MRI PARENT CODE: 723129											
723542	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 19 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA658-57. MRI PARENT CODE: 723129											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723543	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 20 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JKN499-56. MRI PARENT CODE: 723130											
723543	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 20 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW826-58. MRI PARENT CODE: 723130											
723544	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 21- Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JDZ598-48. MRI PARENT CODE: 723131											
723544	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 21- Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA630-57. MRI PARENT CODE: 723131											
723545	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 22 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA627-57. MRI PARENT CODE: 723132											
723545	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 22 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLT736-57. MRI PARENT CODE: 723132											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723546	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 23 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JLA693-57. MRI PARENT CODE: 723133											
723546	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 23 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: 222977JMW821-58. MRI PARENT CODE: 723133											
723547	No. 1 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 24 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: <NONE>.											
723547	No. 2 Engine - Low-Pressure Compressor (Fan) Blade		HRS		3522.4			0			0
	No. 24 - Dry Film Coating - Refurbishment		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
Notes: PN: FW86142 SN: <NONE>.											
723801	No. 1 Engine - Lp Compressor Intake Rotating Fairing - Touch-Up Surface Protection (BRG3136)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723801	No. 2 Engine - Lp Compressor Intake Rotating Fairing - Touch-Up Surface Protection (BRG3136)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723802	No. 1 Engine - Lp Compressor Intake Rotating Fairing - Apply Filler Compound to Eroded Seal Between Nose Cone and Cone CAP (BRG3169)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723802	No. 2 Engine - Lp Compressor Intake Rotating Fairing - Apply Filler Compound to Eroded Seal Between Nose Cone and Cone CAP (BRG3169)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723804	No. 1 Engine - Lp Compressor Intake Rotating Fairing - Touch-Up Timing Mark (BRG3187)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723804	No. 2 Engine - Lp Compressor Intake Rotating Fairing - Touch-Up Timing Mark (BRG3187)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723805	No. 1 Engine - Lp Compressor Fan Retention Shaft and Locking Ring Nut - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
723805	No. 2 Engine - Lp Compressor Fan Retention Shaft and Locking Ring Nut - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
723806	No. 1 Engine - Lp Compressor Intake Rotating Fairing - General Visual Inspection		HRS		.4		1500	3522	5022	5072	0
			ENC		1			726			0
			MOS		2.7			05 Oct 2024			
			[HRS: +50/-50]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723806	No. 2 Engine - Lp Compressor Intake Rotating Fairing - General Visual Inspection		HRS		.4		1500	3522	5022	5072	0
			ENC		1			726			0
			MOS		2.7			05 Oct 2024			
			[HRS: +50/-50]								
Engine											
724100	No. 1 Engine - Curvic Ring - Removal / Installation BRH20340 8166		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
724100	No. 2 Engine - Curvic Ring - Removal / Installation BRH20340 8221		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
724101	No. 1 Engine - Curvic Ring - Discard BRH20340 8166		HRS		3522.4			0			0
			ENC		727		10000	0	10000		0
			MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 724100											
724101	No. 2 Engine - Curvic Ring - Discard BRH20340 8221		HRS		3522.4			0			0
			ENC		727		10000	0	10000		0
			MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 724100											
724102	No. 1 Engine - Hp Turbine Stage 1 Disc - Removal / Installation FW51438 1236		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
724102	No. 2 Engine - Hp Turbine Stage 1 Disc - Removal / Installation FW51438 1182		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
724103	No. 1 Engine - Hp Turbine Stage 1 Disc - Discard		HRS		3522.4			0			0
	FW51438	1236	ENC		727		10000	0	10000		0
			MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 724102											
724103	No. 2 Engine - Hp Turbine Stage 1 Disc - Discard		HRS		3522.4			0			0
	FW51438	1182	ENC		727		10000	0	10000		0
			MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 724102											
724104	No. 1 Engine - Hp Turbine Stage 2 Disc - Removal /		HRS		3522.4			0			0
	Installation		ENC		727			0			0
	FW51470	RRSUNDL668	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
724104	No. 2 Engine - Hp Turbine Stage 2 Disc - Removal /		HRS		3522.4			0			0
	Installation		ENC		727			0			0
	FW51470	RRSUNDL591	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
724105	No. 1 Engine - Hp Turbine Stage 2 Disc - Discard		HRS		3522.4			0			0
	FW51470	RRSUNDL668	ENC		727		10000	0	10000		0
			MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 724104											
724105	No. 2 Engine - Hp Turbine Stage 2 Disc - Discard		HRS		3522.4			0			0
	FW51470	RRSUNDL591	ENC		727		10000	0	10000		0
			MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 724104											
725100	No. 1 Engine - Lp Turbine Stage 1 Disc - Removal /		HRS		3522.4			0			0
	Installation		ENC		727			0			0
	FW77528	390	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
725100	No. 2 Engine - Lp Turbine Stage 1 Disc - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW77528	385	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
725101	No. 1 Engine - Lp Turbine Stage 1 Disc - Discard		HRS		3522.4			0			0
	FW77528		ENC		727		10000	0	10000		0
			MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 725100											
725101	No. 2 Engine - Lp Turbine Stage 1 Disc - Discard		HRS		3522.4			0			0
	FW77528		ENC		727		10000	0	10000		0
			MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 725100											
725102	No. 1 Engine - Lp Turbine Stage 2 Disc - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW77541	363	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
725102	No. 2 Engine - Lp Turbine Stage 2 Disc - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW77541	299	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
725103	No. 1 Engine - Lp Turbine Stage 2 Disc - Discard		HRS		3522.4			0			0
	FW77541		ENC		727		10000	0	10000		0
			MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 725102											
725103	No. 2 Engine - Lp Turbine Stage 2 Disc - Discard		HRS		3522.4			0			0
	FW77541		ENC		727		10000	0	10000		0
			MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 725102											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
725104	No. 1 Engine - Lp Turbine Stage 3 Disc - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW85781	442	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
725104	No. 2 Engine - Lp Turbine Stage 3 Disc - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	FW85781	424	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
725105	No. 1 Engine - Lp Turbine Stage 3 Disc - Discard		HRS		3522.4			0			0
	FW85781	442	ENC		727		10000	0	10000		0
			MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 725104											
725105	No. 2 Engine - Lp Turbine Stage 3 Disc - Discard		HRS		3522.4			0			0
	FW85781	424	ENC		727		10000	0	10000		0
			MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 725104											
725106	No. 1 Engine - Lp Turbine Shaft - Removal / Installation		HRS		3522.4			0			0
	FW50312	RRDSFTBBAN2837	ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
725106	No. 2 Engine - Lp Turbine Shaft - Removal / Installation		HRS		3522.4			0			0
	FW50312	RRDSFTBBAN2831	ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
725107	No. 1 Engine - Lp Turbine Shaft - Discard		HRS		3522.4			0			0
	FW50312	RRDSFTBBAN2837	ENC		727		10000	0	10000		0
			MOS		132.2			19 Dec 2013			
Engine											
Notes: MRI PARENT CODE: 725106											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
725107	No. 2 Engine - Lp Turbine Shaft - Discard		HRS		3522.4			0			0
	FW50312	RRDSFTBBAN2831	ENC		727		10000	0	10000		0
			MOS		133			25 Nov 2013			
Engine											
Notes: MRI PARENT CODE: 725106											
725602	No. 1 Engine - Turbine Exhaust Support Strut Assembly - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
725602	No. 2 Engine - Turbine Exhaust Support Strut Assembly - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
725603	No. 1 Engine - Rear Mount Ring - Detailed Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		122.1		240	23 Oct 2014	31 Oct 2034	30 Nov 2034	
			[End Of Month Item] [MOS: +1m/-1m]								
Engine											
725603	No. 2 Engine - Rear Mount Ring - Detailed Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		122.1		240	23 Oct 2014	31 Oct 2034	30 Nov 2034	
			[End Of Month Item] [MOS: +1m/-1m]								
Engine											
725606	No. 1 Engine - Lp Turbine Fuel Shut-Off Cable - Special Detailed Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		122.1		240	23 Oct 2014	31 Oct 2034	30 Nov 2034	
			[End Of Month Item] [MOS: +1m/-1m]								
Engine											
725606	No. 2 Engine - Lp Turbine Fuel Shut-Off Cable - Special Detailed Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		122.1		240	23 Oct 2014	31 Oct 2034	30 Nov 2034	
			[End Of Month Item] [MOS: +1m/-1m]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
725609	No. 1 Engine - Turbine Exhaust AIR Baffles - Inspection / Check		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
725609	No. 2 Engine - Turbine Exhaust AIR Baffles - Inspection / Check		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
727102	No. 1 Engine - Bypass Duct - General Visual Inspection		HRS		3522.4		6000	0	6000	6050	0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			[HRS: +50/-50]								
Engine											
727102	No. 2 Engine - Bypass Duct - General Visual Inspection		HRS		3522.4		6000	0	6000	6050	0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			[HRS: +50/-50]								
Engine											
727103	No. 1 Engine - Engine Bypass Duct Internal FS 894.6 - FS 950.3 - Zonal Inspection		HRS		3522.4		4800	0	4800	4850	0
			ENC		727			0		0	
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Engine											
727103	No. 2 Engine - Engine Bypass Duct Internal FS 894.6 - FS 950.3 - Zonal Inspection		HRS		3522.4		4800	0	4800	4850	0
			ENC		727			0		0	
			MOS		122.1		192	23 Oct 2014	31 Oct 2030	30 Nov 2030	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Engine											
727104	No. 1 Engine - Bypass Duct Access Panels - Repair Damage to Perforate Skin Using Filler (BRG3145)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
727104	No. 2 Engine - Bypass Duct Access Panels - Repair Damage to Perforate Skin Using Filler (BRG3145)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
727105	No. 1 Engine - Bypass Duct Access Assembly - Repair Damage to Perforate Skin Using Filler (BRG3147)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
727105	No. 2 Engine - Bypass Duct Access Assembly - Repair Damage to Perforate Skin Using Filler (BRG3147)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
727106	No. 1 Engine - Bypass Duct Assembly - Touch-Up Pressure Skin (Outer Surface) Surface Protection (BRG3146)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
727106	No. 2 Engine - Bypass Duct Assembly - Touch-Up Pressure Skin (Outer Surface) Surface Protection (BRG3146)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
727107	No. 1 Engine - Bypass Duct - Replace Insert Carrier(S) and Bushing(S) (BRG3186)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
727107	No. 2 Engine - Bypass Duct - Replace Insert Carrier(S) and Bushing(S) (BRG3186)		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

73 - Engine Fuel and Control											
731100	No. 1 Engine - Fuel Pump - Removal / Installation		HRS		3522.4			0			0
	G3000FPU03	SPX13-048	ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine			MSC			O/C				
731100	No. 2 Engine - Fuel Pump - Removal / Installation		HRS		3522.4			0			0
	G3000FPU03	SPX13-045	ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine			MSC			O/C				
731200	No. 1 Engine - Lp Fuel Filter Element - Removal / Installation		HRS		13.2			3509.2			0
			ENC		7			720			0
	QA07865	SN-UNKNOWN	MOS		6.2			19 Jun 2024			
	Engine			MSC			O/C				
Notes: TWQ # 554642 DUE DATE 11/18TQW # 553838 DUE DATE 08/19											
731200	No. 2 Engine - Lp Fuel Filter Element - Removal / Installation		HRS		13.2			3509.2			0
			ENC		7			720			0
	QA07865	SN-UNKNOWN	MOS		6.2			19 Jun 2024			
	Engine			MSC			O/C				
731201	No. 1 Engine - Hp Fuel Filter Element - Removal / Installation		HRS		1841.9			1680.5			0
			ENC		384			343			0
	QA07518	RE4-7330	MOS	TSN:5	74.1			24 Oct 2018			N/A
	Engine			MSC			O/C				
Notes: THIS CARD IS FOR ENGINE 2. IT IS LOADED AS #2 ENGINE IN CORRIDOR											
731201	No. 2 Engine - Hp Fuel Filter Element - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	QA07865	SN-UNKNOWN	MOS		133			25 Nov 2013			
	Engine			MSC			O/C				
731206	No. 1 Engine - Lp Fuel Filter Element - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine			MSC			O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731212	No. 2 Engine - Fuel Distribution Tubes and Fittings - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731217	Left Engine Fuel Return to Tank Tubes and Fittings Assembly - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
731218	Right Engine Fuel Return to Tank Tubes and Fittings Assembly - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
731300	No. 1 Engine - Fuel Spray Nozzle (No. 1) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731300	No. 2 Engine - Fuel Spray Nozzle (No. 1) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731301	No. 1 Engine - Fuel Spray Nozzle (No. 2) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731301	No. 2 Engine - Fuel Spray Nozzle (No. 2) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731302	No. 1 Engine - Fuel Spray Nozzle (No. 3) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4167	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731302	No. 2 Engine - Fuel Spray Nozzle (No. 3) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4183	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731303	No. 1 Engine - Fuel Spray Nozzle (No. 4) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4166	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731303	No. 2 Engine - Fuel Spray Nozzle (No. 4) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4188	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731304	No. 1 Engine - Fuel Spray Nozzle (No. 5) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4168	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731304	No. 2 Engine - Fuel Spray Nozzle (No. 5) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4191	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731305	No. 1 Engine - Fuel Spray Nozzle (No. 6) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4170	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731305	No. 2 Engine - Fuel Spray Nozzle (No. 6) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4190	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731306	No. 1 Engine - Fuel Spray Nozzle (No. 7) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4172	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731306	No. 2 Engine - Fuel Spray Nozzle (No. 7) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4189	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731307	No. 1 Engine - Fuel Spray Nozzle (No. 8) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4174	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731307	No. 2 Engine - Fuel Spray Nozzle (No. 8) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4184	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731308	No. 1 Engine - Fuel Spray Nozzle (No. 9) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4176	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731308	No. 2 Engine - Fuel Spray Nozzle (No. 9) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4192	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731309	No. 1 Engine - Fuel Spray Nozzle (No. 10) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4187	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731309	No. 2 Engine - Fuel Spray Nozzle (No. 10) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4201	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731310	No. 1 Engine - Fuel Spray Nozzle (No. 11) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4186	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731310	No. 2 Engine - Fuel Spray Nozzle (No. 11) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4200	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731311	No. 1 Engine - Fuel Spray Nozzle (No. 12) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4185	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731311	No. 2 Engine - Fuel Spray Nozzle (No. 12) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4199	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731312	No. 1 Engine - Fuel Spray Nozzle (No. 13) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4182	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731312	No. 2 Engine - Fuel Spray Nozzle (No. 13) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4198	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731313	No. 1 Engine - Fuel Spray Nozzle (No. 14) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4179	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731313	No. 2 Engine - Fuel Spray Nozzle (No. 14) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4197	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731314	No. 1 Engine - Fuel Spray Nozzle (No. 15) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4178	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731314	No. 2 Engine - Fuel Spray Nozzle (No. 15) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4196	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731315	No. 1 Engine - Fuel Spray Nozzle (No. 16) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4177	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731315	No. 2 Engine - Fuel Spray Nozzle (No. 16) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4195	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731316	No. 1 Engine - Fuel Spray Nozzle (No. 17) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4175	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731316	No. 2 Engine - Fuel Spray Nozzle (No. 17) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4194	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731317	No. 1 Engine - Fuel Spray Nozzle (No. 18) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4173	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731317	No. 2 Engine - Fuel Spray Nozzle (No. 18) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4193	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731318	No. 1 Engine - Fuel Spray Nozzle (No. 19) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4171	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731318	No. 2 Engine - Fuel Spray Nozzle (No. 19) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4203	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731319	No. 1 Engine - Fuel Spray Nozzle (No. 20) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4169	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731319	No. 2 Engine - Fuel Spray Nozzle (No. 20) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6080016E01	AD4202	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
731340	No. 1 Engine - Lp Turbine Overspeed and Manifold Splitter Unit - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	1014205-2	F80541	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
731340	No. 2 Engine - Lp Turbine Overspeed and Manifold Splitter Unit - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	1014205-2	F80103	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
732100	No. 1 Engine - Permanent Magnetic Alternator Rotor - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	G3000DGR01	0361	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
732100	No. 2 Engine - Permanent Magnetic Alternator Rotor - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	G3000DGR01	0284	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
732102	No. 1 Engine - Permanent Magnetic Alternator Stator - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	G3000DGS02	0285	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
732102	No. 2 Engine - Permanent Magnetic Alternator Stator - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	G3000DGS02	1016	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
732104	No. 1 Engine - T30 Thermocouple (Right) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6010KTC01	1306226	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
732104	No. 2 Engine - T30 Thermocouple (Right) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6010KTC01	1306871	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
732105	No. 1 Engine - T30 Thermocouple (Left) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6010KTC01	1306228	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
732105	No. 2 Engine - T30 Thermocouple (Left) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6010KTC01	1306868	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
732108	No. 1 Engine - Fuel Metering Unit - Removal / Installation		HRS	TSN:499.6	2312.5			1209.9			0
	G3000FMU04 SFX14-053		ENC	TSN:162	479			248			0
			MOS		87			26 Sep 2017			
			MSC				O/C				
Engine											
732108	No. 2 Engine - Fuel Metering Unit - Removal / Installation		HRS		2312.5			1209.9			0
	G3000FMU04 SFX14-040		ENC		479			248			0
			MOS		87			26 Sep 2017			
			MSC				O/C				
Engine											
732110	No. 1 Engine - Data Entry Plug - Removal / Installation		HRS		3522.4			0			0
	G3000DEP01 00000224		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
732110	No. 2 Engine - Data Entry Plug - Removal / Installation		HRS		3522.4			0			0
	G3000DEP01		ENC		727			0			0
	00000237		MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
732112	No. 1 Engine - Data Entry Plug Program Trims Using		HRS		3522.4			0			0
	External Loader - Adjustment / Test		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
732112	No. 2 Engine - Data Entry Plug Program Trims Using		HRS		3522.4			0			0
	External Loader - Adjustment / Test		ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
732114	No. 1 Engine - Eec - Removal / Installation		HRS		485.9			3036.5			0
	G3010ECU01BC		ENC		97			630			0
	K10.1		MOS		26.7			05 Oct 2022			AERO ENGINE
	Engine		MSC				O/C				CONTROLS
732114	No. 2 Engine - Eec - Removal / Installation		HRS		485.9			3036.5			0
	G3010ECU01BC		ENC		97			630			0
	K10.1		MOS		26.7			05 Oct 2022			AERO ENGINE
	Engine		MSC				O/C				CONTROLS
732118	No. 1 Engine - Fuel System AIR Tubes and Fittings -		HRS		3522.4			0			0
	Inspection		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
732118	No. 2 Engine - Fuel System AIR Tubes and Fittings -		HRS		3522.4			0			0
	Inspection		ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
733100	No. 1 Engine - Fuel Flow Transmitter - Removal /		HRS		3522.4			0			0
	Installation		ENC		727			0			0
	9-217-49	170436-1756	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
733100	No. 2 Engine - Fuel Flow Transmitter - Removal /		HRS		3522.4			0			0
	Installation		ENC		727			0			0
	9-217-49	170436-1809	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
733200	No. 1 Engine - Fuel Temperature Transducer (Channel A		HRS		3522.4			0			0
	and B) - Removal / Installation		ENC		727			0			0
	6060KTC01	1306470	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
733200	No. 2 Engine - Fuel Temperature Transducer (Channel A		HRS		3522.4			0			0
	and B) - Removal / Installation		ENC		727			0			0
	6060KTC01	1306472	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
733201	No. 1 Engine - Fuel Temperature Transducer (Channel B)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	6060KTC01	SN-UNKNOWN	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
733201	No. 2 Engine - Fuel Temperature Transducer (Channel B)		HRS		3522.4			0			0
	- Removal / Installation		ENC		727			0			0
	6060KTC01	SN-UNKNOWN	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
733300	No. 1 Engine - Low Fuel Pressure Switch - Removal /		HRS		2312.5			1209.9			0
	Installation		ENC		479			248			0
	8H0134-1G	1477	MOS		87			26 Sep 2017			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
733300	No. 2 Engine - Low Fuel Pressure Switch - Removal / Installation		HRS		2312.5			1209.9			0
			ENC		479			248			0
	8H0134-1G	1464	MOS		87			26 Sep 2017			
			MSC				O/C				
Engine											
733302	No. 1 Engine - Fuel Differential Lp Transducer - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	APT400A1500	8050-9-63	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
733302	No. 2 Engine - Fuel Differential Lp Transducer - Removal / Installation		HRS		3396.7			125.7			0
			ENC		702			25			0
	APT400A1500	8050-4-152	MOS	TSN:1	119.8			02 Jan 2015			
			MSC				O/C				
Engine											
733500	No. 1 Engine - Fuel Return to Tank Differential Pressure Transducer - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	APT401-1500	8102-6-848	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
733500	No. 2 Engine - Fuel Return to Tank Differential Pressure Transducer - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	APT401-1500	7997-2-369	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
74 - Ignition											
741000	No. 1 Engine - High Energy Ignition Unit (No. 1) - Removal / Installation		HRS		2965.7			556.7			0
			ENC		600			127			0
	HE3392	01384	MOS		104.5			12 Apr 2016			
			MSC				O/C				
Engine											
741000	No. 2 Engine - High Energy Ignition Unit (No. 1) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	HE3392	00547	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
741001	No. 1 Engine - High Energy Ignition Unit (No. 2) - Removal / Installation		HRS	TSN:556.7	2965.7			556.7			0
			ENC	TSN:127	600			127			0
	HE3392	0553	MOS		104.5			12 Apr 2016			
			MSC				O/C				
Engine											
741001	No. 2 Engine - High Energy Ignition Unit (No. 2) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	HE3392	00549	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
742000	No. 1 Engine - Igniter Plug (No. 1) - Removal / Installation		HRS		485.9			3036.5			0
	CH34760-2	20011737	ENC		97			630			0
			MOS		25.6			07 Nov 2022			N/A
			MSC				O/C				
Engine											
Notes: TW ID 568807 DATE DUE 05/20											
742000	No. 2 Engine - Igniter Plug (No. 1) - Removal / Installation		HRS		485.9			3036.5			0
	CH34760-2	19105915	ENC		97			630			0
			MOS		25.6			07 Nov 2022			N/A
			MSC				O/C				
Engine											
Notes: TW ID 568807 DATE DUE 05/20											
742001	No. 1 Engine - Igniter Plug (No. 2) - Removal / Installation		HRS		1508.2			2014.2			0
	CH34760-2	9086205	ENC		311			416			0
			MOS		63.2			20 Sep 2019			CHAMPION
			MSC				O/C				
Engine											
Notes: TW ID 568807DATE DUE 05/20											
742001	No. 2 Engine - Igniter Plug (No. 2) - Removal / Installation		HRS		485.9			3036.5			0
	CH34760-2	19109521	ENC		97			630			0
			MOS		25.6			07 Nov 2022			N/A
			MSC				O/C				
Engine											
Notes: TW ID 568807DATE DUE 05/20											
742004	No. 1 Engine - Igniter Plug (No.1) - Discard		HRS		485.9			3036.5			0
	CH34760-2	NSN	ENC		97			630			0
			MOS		25.7			03 Nov 2022			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
742004	No. 2 Engine - Igniter Plug (No.1) - Discard		HRS		485.9			3036.5			0
	CH34760-2		ENC		97			630			0
	NSN		MOS		25.7			03 Nov 2022			
	Engine		MSC				O/C				
742005	No. 1 Engine - Igniter Plug (No.2) - Discard		HRS		485.9			3036.5			0
	CH34760-2		ENC		97			630			0
	NSN		MOS		25.7			03 Nov 2022			
	Engine		MSC				O/C				
742005	No. 2 Engine - Igniter Plug (No.2) - Discard		HRS		485.9			3036.5			0
	CH34760-2		ENC		97			630			0
	NSN		MOS		25.7			03 Nov 2022			
	Engine		MSC				O/C				
742006	No. 1 Engine - Igniter Plug (No. 1) - Inspection		HRS		485.9			3036.5			0
			ENC		97			630			0
			MOS		26.2			20 Oct 2022			
	Engine		MSC				O/C				
742006	No. 2 Engine - Igniter Plug (No. 1) - Inspection		HRS		485.9			3036.5			0
			ENC		97			630			0
			MOS		26.2			20 Oct 2022			
	Engine		MSC				O/C				
742007	No. 1 Engine - Igniter Plug (No. 2) - Inspection		HRS		1508.2			2014.2			0
			ENC		311			416			0
			MOS		63.2			20 Sep 2019			
	Engine		MSC				O/C				
742007	No. 2 Engine - Igniter Plug (No. 2) - Inspection		HRS		485.9			3036.5			0
			ENC		97			630			0
			MOS		26.2			20 Oct 2022			
	Engine		MSC				O/C				
742008	No. 1 Engine - Ignition Lead (No. 1) - Removal /		HRS		3522.4			0			0
	Installation		ENC		727			0			0
	CLB3032	00419	MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
742008	No. 2 Engine - Ignition Lead (No. 1) - Removal /		HRS		3522.4			0			0
	Installation		ENC		727			0			0
	CLB3032	00514	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
742009	No. 1 Engine - Ignition Lead (No. 2) - Removal /		HRS		3522.4			0			0
	Installation		ENC		727			0			0
	CLB3032	00418	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
742009	No. 2 Engine - Ignition Lead (No. 2) - Removal /		HRS		3522.4			0			0
	Installation		ENC		727			0			0
	CLB3032	00515	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
742026	No. 1 Engine - Ignition Lead (No. 1) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
742026	No. 2 Engine - Ignition Lead (No. 1) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
742027	No. 1 Engine - Ignition Lead (No. 2) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
742027	No. 2 Engine - Ignition Lead (No. 2) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
742028	No. 1 Engine - Ignition System - Operational Check		HRS		485.9			3036.5			0
			ENC		97			630			0
			MOS		24.9			29 Nov 2022			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
742028	No. 2 Engine - Ignition System - Operational Check		HRS		485.9			3036.5			0
			ENC		97			630		0	
			MOS		24.9		29 Nov 2022				
			MSC			O/C					
742029	No. 1 Engine - Igniter Plug (No. 1) - Cleaning		HRS		485.9			3036.5			0
			ENC		97			630		0	
			MOS		26.2		20 Oct 2022				
			MSC			O/C					
742029	No. 2 Engine - Igniter Plug (No. 1) - Cleaning		HRS		485.9			3036.5			0
			ENC		97			630		0	
			MOS		26.2		20 Oct 2022				
			MSC			O/C					
742030	No. 1 Engine - Igniter Plug (No. 2) - Cleaning		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
742030	No. 2 Engine - Igniter Plug (No. 2) - Cleaning		HRS		485.9			3036.5			0
			ENC		97			630		0	
			MOS		26.2		20 Oct 2022				
			MSC			O/C					
742031	No. 1 Engine - Ignition Lead Core Cable (No. 1) - Repair		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
742031	No. 2 Engine - Ignition Lead Core Cable (No. 1) - Repair		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
742032	No. 1 Engine - Ignition Lead Core Cable (No. 2) - Repair		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Logbook Position	Part Number									Serial Number
HW		SW									Manufacturer
MM Ref		Date Type									
Ops Number(s)											
742032	No. 2 Engine - Ignition Lead Core Cable (No. 2) - Repair		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
742033	No. 1 Engine - Ignition Lead Spiral Lock Nut (No. 1) - Repair		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
742033	No. 2 Engine - Ignition Lead Spiral Lock Nut (No. 1) - Repair		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
742034	No. 1 Engine - Ignition Lead Spiral Lock Nut (No. 2) - Repair		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
742034	No. 2 Engine - Ignition Lead Spiral Lock Nut (No. 2) - Repair		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
75 - AIR											
752200	No. 1 Engine - Turbine Case Cooling Control Valve Thermocouple (Pre-Sb 71-101987, Clock 2 Position) - Removal / Installation 6050KTC021306660		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
752200	No. 2 Engine - Turbine Case Cooling Control Valve		HRS		3522.4			0			0
	Thermocouple (Pre-Sb 71-101987, Clock 2 Position) -		ENC		727			0			0
	Removal / Installation		MOS		133			25 Nov 2013			
	6050KTC02	1207726	MSC				O/C				
Engine											
752201	No. 1 Engine - Turbine Case Cooling Control Valve		HRS		3522.4			0			0
	Thermocouple (Pre-Sb 71-101987, Clock 10 Position) -		ENC		727			0			0
	Removal / Installation		MOS		132.2			19 Dec 2013			
	6050KTC02	1307846	MSC				O/C				
Engine											
752201	No. 2 Engine - Turbine Case Cooling Control Valve		HRS		3522.4			0			0
	Thermocouple (Pre-Sb 71-101987, Clock 10 Position) -		ENC		727			0			0
	Removal / Installation		MOS		133			25 Nov 2013			
	6050KTC02	1305344	MSC				O/C				
Engine											
752204	No. 1 Engine - Buffer AIR Valve - Removal / Installation		HRS		3522.4			0			0
	8910-513		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
752204	No. 2 Engine - Buffer AIR Valve - Removal / Installation		HRS		3522.4			0			0
	8910-513		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
752206	No. 1 Engine - Turbine Case Cooling Valve (Clock 2		HRS		3522.4			0			0
	Position) - Removal / Installation		ENC		727			0			0
	AA1022-04	NMB596	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
752206	No. 2 Engine - Turbine Case Cooling Valve (Clock 2		HRS		3522.4			0			0
	Position) - Removal / Installation		ENC		727			0			0
	AA1022-04	NMA007	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
752207	No. 1 Engine - Turbine Case Cooling Valve (Clock 7 Position) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1022-04	NMB597	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
752207	No. 2 Engine - Turbine Case Cooling Valve (Clock 7 Position) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1022-04	NMB592	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
752208	No. 1 Engine - Turbine Case Cooling Valve (Clock 11 Position) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1022-04	NMB846	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
752208	No. 2 Engine - Turbine Case Cooling Valve (Clock 11 Position) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1022-04	NMA012	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
752212	No. 1 Engine - Turbine Case Cooling Valve (Clock 2 Position) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
752212	No. 2 Engine - Turbine Case Cooling Valve (Clock 2 Position) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
752213	No. 1 Engine - Turbine Case Cooling Valve (Clock 7 Position) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
752213	No. 2 Engine - Turbine Case Cooling Valve (Clock 7 Position) - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
752214	No. 1 Engine - Turbine Case Cooling Valve (Clock 11 Position) - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
752214	No. 2 Engine - Turbine Case Cooling Valve (Clock 11 Position) - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
753100	No. 1 Engine - Variable Stator Vane Actuator - Removal / Installation G3000VSVA01 SAX13-044		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753100	No. 2 Engine - Variable Stator Vane Actuator - Removal / Installation G3000VSVA01 SAX13-035		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
753102	No. 1 Engine - AIR Bleed Control Solenoid Block - Removal / Installation AA1021-01 NMB581		HRS		1182.8			2339.6			0
			ENC		243			484		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753102	No. 2 Engine - AIR Bleed Control Solenoid Block - Removal / Installation AA1111-00 XAB255		HRS		1182.8			2339.6			0
			ENC		243			484		0	
			MOS		51.3			17 Sep 2020			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
753104	No. 1 Engine - Lower Left Handling Bleed Valve (HP5.3) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1024-00	NMA166	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753104	No. 2 Engine - Lower Left Handling Bleed Valve (HP5.3) - Removal / Installation		HRS		1182.8			2339.6			0
			ENC		243			484			0
	AA1024-00	NAA058	MOS		51.3			17 Sep 2020			
			MSC				O/C				
Engine											
753105	No. 1 Engine - Lower Right Handling Bleed Valve (HP5.2) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1024-00	NMA168	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753105	No. 2 Engine - Lower Right Handling Bleed Valve (HP5.2) - Removal / Installation		HRS		1182.8			2339.6			0
			ENC		243			484			0
	AA1024-00	MPB052	MOS		51.3			17 Sep 2020			
			MSC				O/C				
Engine											
753106	No. 1 Engine - Upper Right Handling Bleed Valve (HP5.1) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1024-00	NMA169	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753106	No. 2 Engine - Upper Right Handling Bleed Valve (HP5.1) - Removal / Installation		HRS		1182.8			2339.6			0
			ENC		243			484			0
	AA1024-00	NDB032	MOS		51.3			17 Sep 2020			
			MSC				O/C				
Engine											
753107	No. 1 Engine - Upper Left Handling Bleed Valve (HP8) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1024-00	NMA167	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
753107	No. 2 Engine - Upper Left Handling Bleed Valve (HP8) - Removal / Installation		HRS		1182.8			2339.6			0
			ENC		243			484			0
	AA1024-00	MNB407	MOS		51.3			17 Sep 2020			
			MSC				O/C				
Engine											
753112	No. 1 Engine - Bleed Valve Standpipe (Upper HP5) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1025-00	MNA590	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753112	No. 2 Engine - Bleed Valve Standpipe (Upper HP5) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1025-00	NLB317	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
753113	No. 1 Engine - Bleed Valve Standpipe (Lower HP5) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1025-00	MNA597	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753113	No. 2 Engine - Bleed Valve Standpipe (Lower HP5) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1025-00	NLB321	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
753114	No. 1 Engine - Bleed Valve Standpipe (HP8) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1025-00	NLB320	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753114	No. 2 Engine - Bleed Valve Standpipe (HP8) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	AA1025-00	MCB498	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
753118	No. 1 Engine - Bleed Valve HP5 Attenuator S-Seal (Lower Left) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753118	No. 2 Engine - Bleed Valve HP5 Attenuator S-Seal (Lower Left) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
753119	No. 1 Engine - Bleed Valve HP5 Attenuator S-Seal (Lower Right) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753119	No. 2 Engine - Bleed Valve HP5 Attenuator S-Seal (Lower Right) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
753120	No. 1 Engine - Bleed Valve HP5 Attenuator S-Seal (Upper Left) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753120	No. 2 Engine - Bleed Valve HP5 Attenuator S-Seal (Upper Left) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
753121	No. 1 Engine - Bleed Valve HP5 Attenuator S-Seal (Upper Right) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
753121	No. 2 Engine - Bleed Valve HP5 Attenuator S-Seal (Upper Right) - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
753122	No. 1 Engine - AIR Tubes and Fittings - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753122	No. 2 Engine - AIR Tubes and Fittings - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
753123	No. 1 Engine - Bleed Valve Standpipe (Lower HP8) - Removal / Installation AA1025-00MNA606		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
753123	No. 2 Engine - Bleed Valve Standpipe (Lower HP8) - Removal / Installation AA1025-00NLB323		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
76 - Engine Controls											
761000	Throttle Quadrant - Removal / Installation 60P7610001Z0110325		HRS		1050.2			2472.2			0
			AFL		217			510		0	
			MOS		43.9			29 Apr 2021			
			MSC				O/C				
Airframe											
761002	Throttle Quadrant - Functional Test		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
Notes: PN: 60P2510001A005 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
762301	Engine Fuel Control Switch Panel - Removal / Installation		HRS		3522.4			0			0
	60P3110909A007	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
77 - Engine Indicating											
770001	No. 1 Engine - Thermocouple, #2 Turbine O/H - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6020KTC02	1305507	MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
770001	No. 2 Engine - Thermocouple, #2 Turbine O/H - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6020KTC02	1305509	MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
771200	No. 1 Engine - #1 Lp Speed Probe - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	7010KGB02	1300060	MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
771200	No. 2 Engine - #1 Lp Speed Probe - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	7010KGB02	1300057	MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
771201	No. 1 Engine - #2 Lp Speed Probe - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	7010KGB02	1304204	MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
771201	No. 2 Engine - #2 Lp Speed Probe - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	7010KGB02	1300046	MOS		133			25 Nov 2013			
	Engine		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
771202	No. 1 Engine - #3 Lp Speed Probe - Removal / Installation		HRS		3522.4			0			0
	7010KGB02	1300063	ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
771202	No. 2 Engine - #3 Lp Speed Probe - Removal / Installation		HRS		3522.4			0			0
	7010KGB02	1304205	ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
771203	No. 1 Engine - #4 Lp Speed Probe - Removal / Installation		HRS		3522.4			0			0
	7020KGB02	1305539	ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
771203	No. 2 Engine - #4 Lp Speed Probe - Removal / Installation		HRS		3522.4			0			0
	7020KGB02	1300589	ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
771208	No. 1 Engine - Engine N2 Speed Probe (No. 1) - Removal / Installation		HRS		3522.4			0			0
	7001KGB01	1301616	ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
771208	No. 2 Engine - Engine N2 Speed Probe (No. 1) - Removal / Installation		HRS		3522.4			0			0
	7001KGB01	1203647	ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
771209	No. 1 Engine - Engine N2 Speed Probe (No. 2) - Removal / Installation		HRS		3522.4			0			0
	7001KGB01	1301618	ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
771209	No. 2 Engine - Engine N2 Speed Probe (No. 2) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	7001KGB01	1203649	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
771210	No. 1 Engine - Generator Control Unit N2 Speed Probe - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	7030KGB01	1302738	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
771210	No. 2 Engine - Generator Control Unit N2 Speed Probe - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	7030KGB01	1302742	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
771214	No. 1 Engine - #5 Lp Speed Probe - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	7020KGB02	1305538	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
771214	No. 2 Engine - #5 Lp Speed Probe - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	7020KGB02	1300591	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
772100	No. 1 Engine - Engine Tgt Thermocouple Harness - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	0301KHS01	1306816	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
772100	No. 2 Engine - Engine Tgt Thermocouple Harness - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	0301KHS01	1306815	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
772102	No. 1 Engine - Engine Tgt Thermocouple (No. 1) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1306196	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
772102	No. 2 Engine - Engine Tgt Thermocouple (No. 1) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1306203	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
772103	No. 1 Engine - Engine Tgt Thermocouple (No. 2) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1307517	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
772103	No. 2 Engine - Engine Tgt Thermocouple (No. 2) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1307496	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
772104	No. 1 Engine - Engine Tgt Thermocouple (No. 3) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1308442	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
772104	No. 2 Engine - Engine Tgt Thermocouple (No. 3) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1307492	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
772105	No. 1 Engine - Engine Tgt Thermocouple (No. 4) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1307508	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
772105	No. 2 Engine - Engine Tgt Thermocouple (No. 4) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1307494	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
772106	No. 1 Engine - Engine Tgt Thermocouple (No. 5) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1306200	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
772106	No. 2 Engine - Engine Tgt Thermocouple (No. 5) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1307497	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
772107	No. 1 Engine - Engine Tgt Thermocouple (No. 6) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1307507	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
772107	No. 2 Engine - Engine Tgt Thermocouple (No. 6) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1307499	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
772108	No. 1 Engine - Engine Tgt Thermocouple (No. 7) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1306202	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
772108	No. 2 Engine - Engine Tgt Thermocouple (No. 7) -		HRS		3522.4			0			0
	Removal / Installation		ENC		727			0			0
	6001KTC03	1307498	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
772200	No. 1 Engine - Oil FIRE Detection Thermocouple - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6030KTC01	SN-UNKNOWN	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
772200	No. 2 Engine - Oil FIRE Detection Thermocouple - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6030KTC01	SN-UNKNOWN	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
772202	No. 1 Engine - Engine Thermocouple Harness - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6030KTC01	SN-UNKNOWN	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
772202	No. 2 Engine - Engine Thermocouple Harness - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6030KTC01	SN-UNKNOWN	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
773100	Integrated Engine Vibration Monitor System - Adjustment / Test		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
773101	Engine Vibration Monitor Secondary Pickup Selector Switch - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	318VL23AAARY00	SN-UNKNOWN	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
773102	No. 1 Engine - Engine Vibration Transducer A (Primary) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	144-151-000-301	AJ94572	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
773102	No. 2 Engine - Engine Vibration Transducer A (Primary) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	144-151-000-301	AJ84298	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
773103	No. 1 Engine - Engine Vibration Transducer B (Secondary) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	144-151-000-301	AJ88400	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
773103	No. 2 Engine - Engine Vibration Transducer B (Secondary) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	144-151-000-301	AJ81025	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
78 - Exhaust											
780001	No. 1 Engine - Engine Exhaust - General Visual Inspection		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			05 Oct 2024			
			[HRS: +50/-50]								
Engine											
780001	No. 2 Engine - Engine Exhaust - General Visual Inspection		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			05 Oct 2024			
			[HRS: +50/-50]								
Engine											
781000	Exhaust Cone Assembly (Left) - Removal / Installation		HRS		3522.4			0			0
	FW71895	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
781001	Exhaust Cone Assembly (Right) - Removal / Installation		HRS		3522.4			0			0
	FW71895	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
781004	Exhaust Cone Assembly (Left) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
781005	Exhaust Cone Assembly (Right) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
781006	Exhaust Mixer Nozzle (Left) - Removal / Installation		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
781007	Exhaust Mixer Nozzle (Right) - Removal / Installation		HRS		3522.4			0			0
	PN	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
781050	No. 1 Engine - Engine Exhaust Outlet Guide Vane, Exhaust Mixer and Exhaust Cone - General Visual Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
781050	No. 2 Engine - Engine Exhaust Outlet Guide Vane, Exhaust Mixer and Exhaust Cone - General Visual Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
783100	Engine T/Rev (Left) - Removal / Installation		HRS		3522.4			0			0
	RD00103001-1	RD3001L0092	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783101	Engine T/Rev (Right) - Removal / Installation		HRS		3522.4			0			0
	RD00103001-2 RD3001R0093		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783104	T/Rev Deactivate / Activate (Left) - Procedure		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			11 Oct 2024			
	Airframe		MSC				O/C				
783105	T/Rev Deactivate / Activate (Right) - Procedure		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			11 Oct 2024			
	Airframe		MSC				O/C				
783106	T/Rev Pivoting Doors Lockout (Left) - Procedure		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783107	T/Rev Pivoting Doors Lockout (Right) - Procedure		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783108	Pivoting Doors Actuator Locking Sleeve (Left) - Safety Procedure		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783109	Pivoting Doors Actuator Locking Sleeve (Right) - Safety Procedure		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783110	T/Rev (Left) - General Visual Inspection		HRS		1508.2		3000	2014.2	5014.2	5064.2	0
			AFL		311			416			0
			MOS		63.3			18 Sep 2019			
	Airframe		[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783111	T/Rev (Right) - General Visual Inspection		HRS		1508.2		3000	2014.2	5014.2	5064.2	0
			AFL		311			416			0
			MOS		63.3			18 Sep 2019			
	Airframe		[HRS: +50/-50]								
783116	T/Rev (Left) - Bleed Procedure		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783117	T/Rev (Right) - Bleed Procedure		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783130	Batwing (Left) - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783131	Batwing (Right) - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783200	Primary Lock Assembly Gap (Left) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783201	Primary Lock Assembly Gap (Right) - Inspection		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783300	T/Rev Upper Pivoting Door (Left) - Removal / Installation		HRS		3522.4			0			0
	RD00103040-5	SN-UNKNOWN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783301	T/Rev Upper Pivoting Door (Right) - Removal / Installation		HRS		3522.4			0			0
	RD00103040-5 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783302	T/Rev Lower Pivoting Door (Left) - Removal / Installation		HRS		3522.4			0			0
	RD00103040-7 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783303	T/Rev Lower Pivoting Door (Right) - Removal / Installation		HRS		3522.4			0			0
	RD00103040-7 SN-UNKNOWN		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783308	Pivoting Door Actuator (Left Upper) - Removal / Installation		HRS		3522.4			0			0
	RD001C0001-20 A0153156		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783309	Pivoting Door Actuator (Right Upper) - Removal / Installation		HRS		3522.4			0			0
	RD001C0001-20 A0156265		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783310	Pivoting Door Actuator (Left Lower) - Removal / Installation		HRS		3522.4			0			0
	RD001C0001-20 A0153157		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783311	Pivoting Door Actuator (Right Lower) - Removal / Installation		HRS		3522.4			0			0
	RD001C0001-20 A0156266		AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783312	Pivoting Door Actuator (Left Upper) - Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
783313	Pivoting Door Actuator (Right Upper) - Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
783314	Pivoting Door Actuator (Left Lower) - Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
783315	Pivoting Door Actuator (Right Lower) - Inspection		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
783316	Direction Control Unit (Left) - Removal / Installation RD001C0001-34 A0138673		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
783317	Direction Control Unit (Right) - Removal / Installation RD001C0001-34 A0158520		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
783320	Isolation Control Unit Filter Element - Replacement RD001C0001-27 A0154162		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
783321	Isolation Control Unit Filter Element - Replacement RD001C0001-27 A0160648		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783324	Tertiary Lock Actuator (Left Upper) - Removal / Installation		HRS		3522.4			0			0
	RD001C0001-29	A0159086	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783325	Tertiary Lock Actuator (Right Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-29	A0159900	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783326	Tertiary Lock Actuator (Left Lower) - Removal / Installation		HRS		3522.4			0			0
	RD001C0001-29	A0159097	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783327	Tertiary Lock Actuator (Right Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-29	A0159899	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783332	Primary Lock Actuator (Left Engine Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-4	A0160276	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783333	Primary Lock Actuator (Right Engine Outboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-4	A0160278	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				
783334	Primary Lock Actuator (Left Engine Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-4	A0160275	MOS		128.2			21 Apr 2014			
	Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783335	Primary Lock Actuator (Right Engine Inboard) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-4	A0157887	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
783400	Door Stow Switch (Left Inboard Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-32	00657	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
783401	Door Stow Switch (Right Inboard Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-32	00897	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
783402	Door Stow Switch (Left Outboard Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-32	00681	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
783403	Door Stow Switch (Right Outboard Upper) - Removal / Installation		HRS		3512.4			10			0
			AFL		723			4			0
	RD001C0001-32	00155	MOS		126.3			17 Jun 2014			
			MSC				O/C				
Airframe											
783404	Door Stow Switch (Left Inboard Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-32	00686	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
783405	Door Stow Switch (Right Inboard Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-32	00759	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783406	Door Stow Switch (Left Outboard Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-32	00798	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
783407	Door Stow Switch (Right Outboard Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-32	00858	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
783416	Door Position Transducer (Left Engine Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-24	ET2244-10421	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
783417	Door Position Transducer (Right Engine Upper) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-24	ET2244-10418	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
783418	Door Position Transducer (Left Engine Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-24	ET2244-10443	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
783419	Door Position Transducer (Right Engine Lower) - Removal / Installation		HRS		3522.4			0			0
			AFL		727			0			0
	RD001C0001-24	ET2244-10410	MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
783424	Door Position Transducer (Lvdt, Left Engine Upper) - Adjustment		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783425	Door Position Transducer (Lvdt, Right Engine Upper) - Adjustment		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
783426	Door Position Transducer (Lvdt, Left Engine Lower) - Adjustment		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
783427	Door Position Transducer (Lvdt, Right Engine Lower) - Adjustment		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
783436	Tertiary Lock (Left) - Functional Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
783437	Tertiary Lock (Right) - Functional Test		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
784105	Wire Harness Assy R/H RD001C0010-113		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
Airframe											
79 - Oil											
790001	No. 1 Engine - Oil Filter POP-Up Indicator - Removal / Installation		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
790001	No. 2 Engine - Oil Filter POP-Up Indicator - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	QA07508	RZ10-1913	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
790003	No. 1 Engine - Oil Pressure Differential Pressure Switch - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	QA07508	SN-UNKNOWN	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
790003	No. 2 Engine - Oil Pressure Differential Pressure Switch - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	QA07508	SN-UNKNOWN	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
790007	No. 1 Engine - Engine Oil System Check for Contamination		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
790007	No. 2 Engine - Engine Oil System Check for Contamination		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
790008	No. 1 Engine - Oil System Pressure Filter POP-Up Indicator - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
790008	No. 2 Engine - Oil System Pressure Filter POP-Up Indicator - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
791000	No. 1 Engine - Engine Oil System - Draining		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
791000	No. 2 Engine - Engine Oil System - Draining		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
791300	Oil Servicing Reservoir - Removal / Installation 1159SCP565-31063		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
791301	Oil Servicing Selector Valve - Removal / Installation 1159SCP105-11211		HRS	TSN:323.6	2665.7			856.7			0
			AFL	TSN:144	546			181		0	
			MOS		96.4		14 Dec 2016				
			MSC			O/C					
791315	Engine and APU Oil Servicing Pump - Removal / Installation 1B5-179BJ77		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		128.2		21 Apr 2014				
			MSC			O/C					
792100	No. 1 Engine - Oil Pump - Removal / Installation LR47980AC0226		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
792100	No. 2 Engine - Oil Pump - Removal / Installation LR47980AC0225		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
792102	No. 1 Engine - Oil Pump Spline Coupling - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
792102	No. 2 Engine - Oil Pump Spline Coupling - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013				
			MSC			O/C					
792103	No. 1 Engine - Oil Pump Seal Plate - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
792103	No. 2 Engine - Oil Pump Seal Plate - Inspection		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013				
			MSC			O/C					
792104	No. 1 Engine - Oil System Pressure Filter Element - Removal / Installation		HRS		485.9			3036.5			0
			ENC		97		630		0		
			MOS	TSN:9	25.5		10 Nov 2022		N/A		
			MSC			O/C					
792104	No. 2 Engine - Oil System Pressure Filter Element - Removal / Installation		HRS		485.9			3036.5			0
			ENC		97		630		0		
			MOS	TSN:9	25.5		10 Nov 2022		N/A		
			MSC			O/C					
792106	No. 1 Engine - Oil System Pressure Filter Element - Discard		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			ENC		97		630		0		
			MOS	TSN:9	25.5		10 Nov 2022				
			[HRS: +50/-50]								
792106	No. 2 Engine - Oil System Pressure Filter Element - Discard		HRS		485.9		1500	3036.5	4536.5	4586.5	0
			ENC		97		630		0		
			MOS	TSN:9	25.5		10 Nov 2022				
			[HRS: +50/-50]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
792107	No. 1 Engine - Oil System Pressure Filter Element - Inspection		HRS		1912.8			1609.6			0
			ENC		397			330			0
			MOS		75.3			16 Sep 2018			
			MSC				O/C				
Engine											
Notes: REF 15.5 AND 11.10 FOR FILTER DELTA P EXTENSION AND FILTER REMOVAL AND INSTALLATION											
792107	No. 2 Engine - Oil System Pressure Filter Element - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
792108	No. 1 Engine - Oil Tubes and Fittings - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
792108	No. 2 Engine - Oil Tubes and Fittings - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
792109	No. 1 Engine - Magnetic Chip Detectors (Front Bearing Chamber) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			03 Oct 2024			
			[HRS: +50/-50]								
Engine											
792109	No. 2 Engine - Magnetic Chip Detectors (Front Bearing Chamber) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			03 Oct 2024			
			[HRS: +50/-50]								
Engine											
792110	No. 1 Engine - Magnetic Chip Detectors (Rear Bearing Chamber) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			03 Oct 2024			
			[HRS: +50/-50]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
792110	No. 2 Engine - Magnetic Chip Detectors (Rear Bearing Chamber) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			03 Oct 2024			
			[HRS: +50/-50]								
Engine											
792111	No. 1 Engine - Magnetic Chip Detectors (Accessory Gearbox) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			03 Oct 2024			
			[HRS: +50/-50]								
Engine											
792111	No. 2 Engine - Magnetic Chip Detectors (Accessory Gearbox) - Detailed Inspection		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			03 Oct 2024			
			[HRS: +50/-50]								
Engine											
792112	No. 1 Engine - Transfer of Electromagnetic Chip Detector (Front Bearing Chamber to Rear Bearing Chamber)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
792112	No. 2 Engine - Transfer of Electromagnetic Chip Detector (Front Bearing Chamber to Rear Bearing Chamber)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
792113	No. 1 Engine - Transfer of Electromagnetic Chip Detector (Front Bearing Chamber to Accessory Gearbox)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
792113	No. 2 Engine - Transfer of Electromagnetic Chip Detector (Front Bearing Chamber to Accessory Gearbox)		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
792114	No. 1 Engine - Transfer of Electromagnetic Chip Detector (Rear Bearing Chamber to Front Bearing Chamber)		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
792114	No. 2 Engine - Transfer of Electromagnetic Chip Detector (Rear Bearing Chamber to Front Bearing Chamber)		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
792115	No. 1 Engine - Transfer of Electromagnetic Chip Detector (Accessory Gearbox to Front Bearing Chamber)		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											
792115	No. 2 Engine - Transfer of Electromagnetic Chip Detector (Accessory Gearbox to Front Bearing Chamber)		HRS		3522.4			0			0
			ENC		727		0		0		
			MOS		133		25 Nov 2013				
			MSC			O/C					
Engine											
792116	No. 1 Engine - Magnetic Chip Detector (Magnetic Chip Detector on Front Bearing Chamber Position) - Removal / Installation		HRS		485.9			3036.5			0
			ENC		97		630		0		
			MOS		26.3		17 Oct 2022		N/A		
			MSC			O/C					
Engine											
792116	No. 2 Engine - Magnetic Chip Detector (Magnetic Chip Detector on Front Bearing Chamber Position) - Removal / Installation		HRS		485.9			3036.5			0
			ENC		97		630		0		
			MOS		26.3		17 Oct 2022		N/A		
			MSC			O/C					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
792117	No. 1 Engine - Magnetic Chip Detector (Magnetic Chip Detector on Rear Bearing Chamber Position) - Removal / Installation		HRS		.4			3522			0
			ENC		1			726			0
			MOS		2.7			03 Oct 2024			N/A
	3002261	00458	MSC				O/C				
Engine											
792117	No. 2 Engine - Magnetic Chip Detector (Magnetic Chip Detector on Rear Bearing Chamber Position) - Removal / Installation		HRS		.4			3522			0
			ENC		1			726			0
			MOS		2.7			03 Oct 2024			N/A
	3002261	00466	MSC				O/C				
Engine											
792118	No. 1 Engine - Magnetic Chip Detector (Magnetic Chip Detector on Accessory Gearbox Position) - Removal / Installation		HRS		.4			3522			0
			ENC		1			726			0
			MOS		2.7			03 Oct 2024			N/A
	3002261	00459	MSC				O/C				
Engine											
792118	No. 2 Engine - Magnetic Chip Detector (Magnetic Chip Detector on Accessory Gearbox Position) - Removal / Installation		HRS		.4			3522			0
			ENC		1			726			0
			MOS		2.7			03 Oct 2024			N/A
	3002261	00460	MSC				O/C				
Engine											
792122	No. 1 Engine - Electromagnetic Chip Detector (Electromagnetic Chip Detector on Front Bearing Chamber Position) - Removal / Installation		HRS	TSN:2482.5	1039.9			2482.5			0
			ENC	TSN:511	216			511			0
			MOS	TSN:93	38.9			28 Sep 2021			
	3002251	00267	MSC				O/C				
Engine											
792122	No. 2 Engine - Electromagnetic Chip Detector (Electromagnetic Chip Detector on Front Bearing Chamber Position) - Removal / Installation		HRS		.4			3522			0
			ENC		1			726			0
			MOS		2.7			03 Oct 2024			N/A
	3002251	00272	MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
792123	No. 1 Engine - Electromagnetic Chip Detector		HRS		.4			3522			0
	(Electromagnetic Chip Detector on Rear Bearing		ENC		1			726			0
	Chamber Position) - Removal / Installation		MOS		2.7			03 Oct 2024			N/A
	3002251	00267	MSC				O/C				
Engine											
792123	No. 2 Engine - Electromagnetic Chip Detector		HRS		3522.4			0			0
	(Electromagnetic Chip Detector on Rear Bearing		ENC		727			0			0
	Chamber Position) - Removal / Installation		MOS		133			25 Nov 2013			
	1102381-00	SN-UNKNOWN	MSC				O/C				
Engine											
792124	No. 1 Engine - Electromagnetic Chip Detector		HRS		3522.4			0			0
	(Electromagnetic Chip Detector on Accessory Gearbox		ENC		727			0			0
	Position) - Removal / Installation		MOS		132.2			19 Dec 2013			
	1002381-00	00267	MSC				O/C				
Engine											
792124	No. 2 Engine - Electromagnetic Chip Detector		HRS		3522.4			0			0
	(Electromagnetic Chip Detector on Accessory Gearbox		ENC		727			0			0
	Position) - Removal / Installation		MOS		133			25 Nov 2013			
	1002381-00	00272	MSC				O/C				
Engine											
792146	No. 1 Engine - Scavenge Strainer (Forward Gearbox) -		HRS		3522.4			0			0
	Inspection		ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
792146	No. 2 Engine - Scavenge Strainer (Forward Gearbox) -		HRS		3522.4			0			0
	Inspection		ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
792147	No. 1 Engine - Scavenge Strainer (Aft Gearbox, Left) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
792147	No. 2 Engine - Scavenge Strainer (Aft Gearbox, Left) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
792148	No. 1 Engine - Scavenge Strainer (Aft Gearbox, Right) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
792148	No. 2 Engine - Scavenge Strainer (Aft Gearbox, Right) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
792149	No. 1 Engine - Scavenge Strainer (Accessory Gearbox) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
792149	No. 2 Engine - Scavenge Strainer (Accessory Gearbox) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
792150	No. 1 Engine - Scavenge Strainer (Front Bearing Chamber) - Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
792150	No. 2 Engine - Scavenge Strainer (Front Bearing Chamber) - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
792151	No. 1 Engine - Scavenge Strainer (Rear Bearing Chamber) - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
792151	No. 2 Engine - Scavenge Strainer (Rear Bearing Chamber) - Inspection		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
792200	No. 1 Engine - Fuel-Cooled Oil Cooler - Removal / Installation 55045001-2155045-0174		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
792200	No. 2 Engine - Fuel-Cooled Oil Cooler - Removal / Installation 55045001-2155045-0198		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
792202	No. 1 Engine - Cooler, Oil, Surface AIR Cooled - Removal / Installation 50028001-1150028-2084		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
792202	No. 2 Engine - Cooler, Oil, Surface AIR Cooled - Removal / Installation 50028001-1150028-2016		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
793110	No. 1 Engine - Oil Quantity Transducer - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	87D12000	SN-UNKNOWN	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
793110	No. 2 Engine - Oil Quantity Transducer - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	87D12000	SN-UNKNOWN	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
793200	No. 1 Engine - Oil Temperature Transducer - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6030KTC01	1307273	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
793200	No. 2 Engine - Oil Temperature Transducer - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6030KTC01	1307275	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
793201	No. 1 Engine - Oil Temperature Transducer Assembly (No.2) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6030KTC01	SN-UNKNOWN	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
793201	No. 2 Engine - Oil Temperature Transducer Assembly (No.2) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	6030KTC01	SN-UNKNOWN	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
793300	No. 1 Engine - Oil Differential Pressure Transducer - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	APT399-1500	8095-8-378	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
793300	No. 2 Engine - Oil Differential Pressure Transducer - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	APT399-1500	8095-8-372	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
793301	No. 1 Engine - Oil Differential Pressure Transducer (No.2) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	APT400A1500	SN-UNKNOWN	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
793301	No. 2 Engine - Oil Differential Pressure Transducer (No.2) - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	APT400A1500	SN-UNKNOWN	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
793400	No. 1 Engine - Oil Filter Differential Pressure Transducer - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	APT401-1500	8102-6-865	MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
793400	No. 2 Engine - Oil Filter Differential Pressure Transducer - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	APT401-1500	7997-2-390	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
80 - Starting											
801100	No. 1 Engine - AIR Turbine Starter - Removal / Installation		HRS		3522.4			0			0
	3506062-2	3506062-317	ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
801100	No. 2 Engine - AIR Turbine Starter - Removal / Installation		HRS		3522.4			0			0
	3506062-2	303	ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
801101	No. 1 Engine - Starter AIR Valve - Removal / Installation		HRS	TSN:632.9	1508.2			2014.2			0
	424025-1	1241B	ENC	TSN:162	311			416			0
			MOS		63.1			23 Sep 2019			
	Engine		MSC				O/C				
801101	No. 2 Engine - Starter AIR Valve - Removal / Installation		HRS		234.4			3288			0
	424025	1220B	ENC		55			672			0
			MOS		16.5			11 Aug 2023			
	Engine		MSC				O/C				
801104	No. 1 Engine - AIR Turbine Starter Magnetic Chip		HRS		.4		750	3522	4272	4322	0
	Collector - Detailed Inspection		ENC		1			726			0
			MOS		2.7			05 Oct 2024			
	Engine		[HRS: +50/-50]								
801104	No. 2 Engine - AIR Turbine Starter Magnetic Chip		HRS		.4		750	3522	4272	4322	0
	Collector - Detailed Inspection		ENC		1			726			0
			MOS		2.7			05 Oct 2024			
	Engine		[HRS: +50/-50]								
801105	No. 1 Engine - AIR Turbine Starter Oil - Change		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
801105	No. 2 Engine - AIR Turbine Starter Oil - Change		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				
801106	No. 1 Engine - Starter Oil Level - Detailed Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
	Engine		MSC				O/C				
801106	No. 2 Engine - Starter Oil Level - Detailed Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
	Engine		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
801107	No. 1 Engine - AIR Turbine Starter - Inspection / Check		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
801107	No. 2 Engine - AIR Turbine Starter - Inspection / Check		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
801108	No. 1 Engine - Starter AIR Valve - Manual Override		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Notes: PN: AA1033-01 SN: <NONE>.											
801108	No. 2 Engine - Starter AIR Valve - Manual Override		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
Notes: PN: AA1033-01 SN: <NONE>.											
801109	No. 1 Engine - Front Starter AIR Duct - Removal / Installation RD001C0006-3002 SN-UNKNOWN		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
801109	No. 2 Engine - Front Starter AIR Duct - Removal / Installation RD001C0006-3002 SN-UNKNOWN		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		133		25 Nov 2013				
			MSC			O/C					
801110	No. 1 Engine - Rear Starter AIR Duct - Removal / Installation RD001C0006-3001 SN-UNKNOWN		HRS		3522.4			0			0
			ENC		727			0		0	
			MOS		132.2		19 Dec 2013				
			MSC			O/C					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
801110	No. 2 Engine - Rear Starter AIR Duct - Removal / Installation		HRS		3522.4			0			0
			ENC		727			0			0
	RD001C0006-3001	SN-UNKNOWN	MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
801113	No. 1 Engine - Starter AIR Ducts - General Visual Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		132.2			19 Dec 2013			
			MSC				O/C				
Engine											
801113	No. 2 Engine - Starter AIR Ducts - General Visual Inspection		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		133			25 Nov 2013			
			MSC				O/C				
Engine											
801114	Starter AIR Valve Relay (Left) - Removal / Installation		HRS		3522.4			0			0
	Y-E4N-024	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
801115	Starter AIR Valve Relay (Right) - Removal / Installation		HRS		3522.4			0			0
	Y-E4N-024	NSN	AFL		727			0			0
			MOS		128.2			21 Apr 2014			
			MSC				O/C				
Airframe											
801118	No. 1 Engine - AIR Turbine Starter - General Visual Inspection		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			05 Oct 2024			
			[HRS: +50/-50]								
Engine											
801118	No. 2 Engine - AIR Turbine Starter - General Visual Inspection		HRS		.4		750	3522	4272	4322	0
			ENC		1			726			0
			MOS		2.7			05 Oct 2024			
			[HRS: +50/-50]								
Engine											
88 - Engine Sb/MOD											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-71-101776 R01	No. 1 Engine - Sb BR700-71-101776 R01 - Power Plant - Drains Tank Ejector - Introduction of A Revised Seal Ring Part Number for Spares Purposes, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880234)											
Engine											
BR700-71-101776 R01	No. 2 Engine - Sb BR700-71-101776 R01 - Power Plant - Drains Tank Ejector - Introduction of A Revised Seal Ring Part Number for Spares Purposes, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880234)											
Engine											
BR700-71-101786	No. 1 Engine - Sb BR700-71-101786 - Power Plant - Eng Lt Engine Electronic Controller (Eec) Lane A E2-A Loom 1A and Lane B E2-B Loom 1B Electrical Harnesses - Introduction of an Alternative Part Number for the Protective Covers on the Spare Receptacles		HRS		3522.4			0			0
			ENC		727			0		0	
			DATE								
			MSC				-				
(880059)											
Engine											
Notes: PN: P0L2997KE3D08 SN: <NONE>.											
BR700-71-101786	No. 2 Engine - Sb BR700-71-101786 - Power Plant - Eng Lt Engine Electronic Controller (Eec) Lane A E2-A Loom 1A and Lane B E2-B Loom 1B Electrical Harnesses - Introduction of an Alternative Part Number for the Protective Covers on the Spare Receptacles		HRS		3522.4			0			0
			ENC		727			0		0	
			DATE								
			MSC				-				
(880059)											
Engine											
Notes: PN: P0L2997KE3D08 SN: <NONE>.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-71-101928	No. 1 Engine - Sb BR700-71-101928 - Power Plant - Left and Right Quick Engine Change Unit (Qecu) - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments for the Hydraulic Pump		HRS		2755.9			766.5			0
			ENC		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
(880109)											
Engine											
Notes: R&I PG. 17TW#: 558138 DUE: 6/17											
BR700-71-101928	No. 2 Engine - Sb BR700-71-101928 - Power Plant - Left and Right Quick Engine Change Unit (Qecu) - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments for the Hydraulic Pump		HRS		2755.9			766.5			0
			ENC		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
(880109)											
Engine											
Notes: R&I PG. 17TW#: 558138 DUE: 6/17											
BR700-71-101928 R01	No. 1 Engine - Sb BR700-71-101928 R01 - Power Plant - Left and Right Quick Engine Change Unit (Qecu) - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments for the Hydraulic Pump, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880265)											
Engine											
BR700-71-101928 R01	No. 2 Engine - Sb BR700-71-101928 R01 - Power Plant - Left and Right Quick Engine Change Unit (Qecu) - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments for the Hydraulic Pump, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880265)											
Engine											
BR700-71-101987 R01	No. 1 Engine - Sb BR700-71-101987 R01 - Power Plant - Core Engine Harness - Introduction of New Lane A and Lane B Core Engine Harnesses and Deletion of the Turbine Case Cooling (TCC) Valve Thermocouples, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880235)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-71-101987 R01	No. 2 Engine - Sb BR700-71-101987 R01 - Power Plant - Core Engine Harness - Introduction of New Lane A and Lane B Core Engine Harnesses and Deletion of the Turbine Case Cooling (TCC) Valve Thermocouples, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880235)											
Engine											
BR700-71-102011	No. 1 Engine - Sb BR700-71-102011 - Power Plant - Core Engine Lane A Loom 2A and Lane B Loom 2B Harnesses - Introduction of an Alternative Harness Tape		HRS		3522.4			0			0
			ENC		727			0		0	
			DATE								
			MSC				-				
(880149)											
Engine											
BR700-71-102011	No. 2 Engine - Sb BR700-71-102011 - Power Plant - Core Engine Lane A Loom 2A and Lane B Loom 2B Harnesses - Introduction of an Alternative Harness Tape		HRS		3522.4			0			0
			ENC		727			0		0	
			DATE								
			MSC				-				
(880149)											
Engine											
BR700-71-102269	No. 1 Engine - Sb BR700-71-102269 - Sb BR700-71-102269 - Power Plant - Eng Lt Engine Electronic Controller (Eec) Lane A and Lane B Harnesses - Introduction of Alternative Marker Sleeves for the Eec Harness Assemblies		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880224)											
Engine											
BR700-71-102269 (890224)	No. 2 Engine - Sb BR700-71-102269 - Sb BR700-71-102269 - Power Plant - Eng Lt Engine Electronic Controller (Eec) Lane A and Lane B Harnesses - Introduction of Alternative Marker Sleeves for the Eec Harness Assemblies		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880224)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-71-900003	No. 1 Engine - Sb BR700-71-900003 - Power Plant - Left and Right Quick Engine Change Unit - Inspection of the V-Band Coupling Clamp - Non-Modification Service Bulletin		HRS		3396.7			125.7			0
			ENC		702		25		0		
			MOS		120.1		23 Dec 2014				
			MSC								
(880086)											
Engine											
BR700-71-900003	No. 2 Engine - Sb BR700-71-900003 - Power Plant - Left and Right Quick Engine Change Unit - Inspection of the V-Band Coupling Clamp - Non-Modification Service Bulletin		HRS		3396.7			125.7			0
			ENC		702		25		0		
			MOS		120.1		23 Dec 2014				
			MSC								
(880086)											
Engine											
BR700-71-900003 R01	No. 1 Engine - Sb BR700-71-900003 R01 - Power Plant - Left and Right Quick Engine Change Unit - Inspection of the V-Band Coupling Clamp - Non-Modification Service Bulletin (This Sb Is No Longer Valid)		HRS								0
			ENC							0	
			DATE								
			MSC								
(880206)											
Engine											
BR700-71-900003 R01	No. 2 Engine - Sb BR700-71-900003 R01 - Power Plant - Left and Right Quick Engine Change Unit - Inspection of the V-Band Coupling Clamp - Non-Modification Service Bulletin (This Sb Is No Longer Valid)		HRS								0
			ENC							0	
			DATE								
			MSC								
(880206)											
Engine											
BR700-72-101737 R01	No. 1 Engine - Sb BR700-72-101737 R01 - High Pressure (Hp) Compressor Front Split Case - Introduction of Two Additional Borescope Access Ports to the Hp Compressor, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC								
(880238)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101737 R01	No. 2 Engine - Sb BR700-72-101737 R01 - High Pressure (Hp) Compressor Front Split Case - Introduction of Two Additional Borescope Access Ports to the Hp Compressor, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880238)											
Engine											
BR700-72-101743 R02	No. 1 Engine - Sb BR700-72-101743 R02 - Low Pressure (Lp) Compressor Blades - Introduction of New Lp Compressor Blades With Laser Shock Peening Treatment on the Hub Leading Edge of the Blade Airfoil, Service Bulletin (Recommended)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880232)											
Engine											
BR700-72-101743 R02	No. 2 Engine - Sb BR700-72-101743 R02 - Low Pressure (Lp) Compressor Blades - Introduction of New Lp Compressor Blades With Laser Shock Peening Treatment on the Hub Leading Edge of the Blade Airfoil, Service Bulletin (Recommended)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880232)											
Engine											
BR700-72-101773	No. 1 Engine - Sb BR700-72-101773 - NI Speed Probe Harness and Accessories - Introduction of New Alternative NI Speed Probe Brackets With Integrated Bushes		HRS		3522.4			0			0
			ENC		727			0		0	
			DATE								
			MSC				-				
(880081)											
Engine											
BR700-72-101773	No. 2 Engine - Sb BR700-72-101773 - NI Speed Probe Harness and Accessories - Introduction of New Alternative NI Speed Probe Brackets With Integrated Bushes		HRS		3522.4			0			0
			ENC		727			0		0	
			DATE								
			MSC				-				
(880081)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101783 R01	No. 1 Engine - Sb BR700-72-101783 R01 - Intermediate		HRS		3522.4			0			0
	Case Module, Combustion and High Pressure (Hp)		ENC		727			0			0
	Turbine Module and Low Pressure (Lp) Turbine Module -		DATE								
	Introduction of Alternative Mainline Bearings		MSC				-				
(880152)											
Engine											
Notes: PN: BRR24148 SN: <NONE>.											
BR700-72-101783 R01	No. 2 Engine - Sb BR700-72-101783 R01 - Intermediate		HRS		3522.4			0			0
	Case Module, Combustion and High Pressure (Hp)		ENC		727			0			0
	Turbine Module and Low Pressure (Lp) Turbine Module -		DATE								
	Introduction of Alternative Mainline Bearings		MSC				-				
(880152)											
Engine											
Notes: PN: BRR24148 SN: <NONE>.											
BR700-72-101812	No. 1 Engine - Sb BR700-72-101812 - High Pressure (Hp)		HRS		3522.4			0			0
	Turbine Rotor Discs - Introduction of New Part Numbers		ENC		727			0			0
	for the Hp Turbine Curvic Ring		DATE								
			MSC				-				
(880053)											
Engine											
BR700-72-101812	No. 2 Engine - Sb BR700-72-101812 - High Pressure (Hp)		HRS		3522.4			0			0
	Turbine Rotor Discs - Introduction of New Part Numbers		ENC		727			0			0
	for the Hp Turbine Curvic Ring		DATE								
			MSC				-				
(880053)											
Engine											
BR700-72-101836	No. 1 Engine - Sb BR700-72-101836 - Low Pressure (Lp)		HRS		3522.4			0			0
	Turbine Fuel Shut-Off (Fso) Carrier - Introduction of A		ENC		727			0			0
	Redesigned Lp Turbine Fso Pawl Carrier With Two		DATE								
	Modified Retaining Plate Bolt Holes		MSC				-				
(880048)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101836	No. 2 Engine - Sb BR700-72-101836 - Low Pressure (Lp)		HRS		3522.4			0			0
	Turbine Fuel Shut-Off (Fso) Carrier - Introduction of A		ENC		727			0			0
	Redesigned Lp Turbine Fso Pawl Carrier With Two		DATE								
	Modified Retaining Plate Bolt Holes		MSC				-				
(880048)											
Engine											
BR700-72-101853 R01	No. 1 Engine - Sb BR700-72-101853 R01 - Low Pressure		HRS		3522.4			0			0
	(Lp) Turbine Case - Introduction of Lp Turbine Stage 1		ENC		727			0			0
	Liner Segment Assemblies With A Revised Geometry		DATE								
			MSC				-				
(880079)											
Engine											
BR700-72-101853 R01	No. 2 Engine - Sb BR700-72-101853 R01 - Low Pressure		HRS		3522.4			0			0
	(Lp) Turbine Case - Introduction of Lp Turbine Stage 1		ENC		727			0			0
	Liner Segment Assemblies With A Revised Geometry		DATE								
			MSC				-				
(880079)											
Engine											
BR700-72-101857 R01	No. 1 Engine - Sb BR700-72-101857 R01 - Low Pressure		HRS		3522.4			0			0
	(Lp) Compressor Outlet Guide Stator Vanes - Introduction		ENC		727			0			0
	of A New Standard of Lp Compressor Outlet Guide Vane		DATE								
	(Ogv) Assemblies		MSC				-				
(880080)											
Engine											
BR700-72-101857 R01	No. 2 Engine - Sb BR700-72-101857 R01 - Low Pressure		HRS		3522.4			0			0
	(Lp) Compressor Outlet Guide Stator Vanes - Introduction		ENC		727			0			0
	of A New Standard of Lp Compressor Outlet Guide Vane		DATE								
	(Ogv) Assemblies		MSC				-				
(880080)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101861	No. 1 Engine - Sb BR700-72-101861 - Combustion and High Pressure (Hp) Turbine Module Attaching Parts and Fittings - Introduction of Two New Brackets Made from Different Material and Installed AT the Combustion Chamber Outer Case (Ccoc)		HRS		3522.4			0		0	
			ENC		727			0		0	
			DATE								
			MSC				-				
(880051)											
Engine											
BR700-72-101861	No. 2 Engine - Sb BR700-72-101861 - Combustion and High Pressure (Hp) Turbine Module Attaching Parts and Fittings - Introduction of Two New Brackets Made from Different Material and Installed AT the Combustion Chamber Outer Case (Ccoc)		HRS		3522.4			0		0	
			ENC		727			0		0	
			DATE								
			MSC				-				
(880051)											
Engine											
BR700-72-101903	No. 1 Engine - Sb BR700-72-101903 - Low Pressure (Lp) /High Pressure (Hp) Turbine Stator Retainers/Seals - Introduction of New Bearing Carriers With Tightened Geometrical Tolerances		HRS		3522.4			0		0	
			ENC		727			0		0	
			MOS		110.9			28 Sep 2015			
			MSC				-				
(880085)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-101903	No. 2 Engine - Sb BR700-72-101903 - Low Pressure (Lp) /High Pressure (Hp) Turbine Stator Retainers/Seals - Introduction of New Bearing Carriers With Tightened Geometrical Tolerances		HRS		3522.4			0		0	
			ENC		727			0		0	
			MOS		110.9			28 Sep 2015			
			MSC				-				
(880085)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101907 R02	No. 1 Engine - Sb BR700-72-101907 R02 - BR700-72-101907 R02 - High Pressure (Hp) Compressor Rotor		HRS								0
	Hydraulic Seal - Introduction of A Modified Hp		ENC								0
	Compressor Hydraulic Seal Assembly With A Shortened		DATE								
	Timing Lug and Modified Surface Treatment of the Timing Lug		MSC				-				
(880211)											
Engine											
BR700-72-101907 R02	No. 2 Engine - Sb BR700-72-101907 R02 - BR700-72-101907 R02 - High Pressure (Hp) Compressor Rotor		HRS								0
	Hydraulic Seal - Introduction of A Modified Hp		ENC								0
	Compressor Hydraulic Seal Assembly With A Shortened		DATE								
	Timing Lug and Modified Surface Treatment of the Timing Lug		MSC				-				
(880211)											
Engine											
BR700-72-101938	No. 1 Engine - Sb BR700-72-101938 - High Pressure (Hp) Compressor Stage 5 Onward Stator Vanes - Introduction of Alternative Hp Compressor Stage 7 Vanes Produced to A New Manufacturing Method		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880157)											
Engine											
BR700-72-101938	No. 2 Engine - Sb BR700-72-101938 - High Pressure (Hp) Compressor Stage 5 Onward Stator Vanes - Introduction of Alternative Hp Compressor Stage 7 Vanes Produced to A New Manufacturing Method		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880157)											
Engine											
BR700-72-101963	No. 1 Engine - Sb BR700-72-101963 - High Pressure (Hp) Turbine Case Impingement Cooling Manifold - Introduction of Alternative Rivets for the Turbine Case Cooling (TCC) Manifold		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880144)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-101963	No. 2 Engine - Sb BR700-72-101963 - High Pressure (Hp)		HRS		3522.4			0			0
	Turbine Case Impingement Cooling Manifold -		ENC		727			0			0
	Introduction of Alternative Rivets for the Turbine Case		DATE								
	Cooling (TCC) Manifold		MSC				-				
(880144)											
Engine											
BR700-72-101991	No. 1 Engine - Sb BR700-72-101991 - Low Pressure (Lp)		HRS		3522.4			0			0
	/High Pressure (Hp) Turbine Stator Retainers/Seals -		ENC		727			0			0
	Introduction of A New Front Seal Carrier, A New Rear Seal		DATE								
	Carrier and New Bearing Carriers		MSC				-				
(880148)											
Engine											
BR700-72-101991	No. 2 Engine - Sb BR700-72-101991 - Low Pressure (Lp)		HRS		3522.4			0			0
	/High Pressure (Hp) Turbine Stator Retainers/Seals -		ENC		727			0			0
	Introduction of A New Front Seal Carrier, A New Rear Seal		DATE								
	Carrier and New Bearing Carriers		MSC				-				
(880148)											
Engine											
BR700-72-101995	No. 1 Engine - Sb BR700-72-101995 - Combustion and		HRS		3522.4			0			0
	High Pressure (Hp) Turbine Module Attach Parts and		ENC		727			0			0
	Fittings - Introduction of A Redesigned FIRE Extinguisher		DATE								
	Nozzle AT the Core Engine Flange CC		MSC				-				
(880154)											
Engine											
BR700-72-101995	No. 2 Engine - Sb BR700-72-101995 - Combustion and		HRS		3522.4			0			0
	High Pressure (Hp) Turbine Module Attach Parts and		ENC		727			0			0
	Fittings - Introduction of A Redesigned FIRE Extinguisher		DATE								
	Nozzle AT the Core Engine Flange CC		MSC				-				
(880154)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102030	No. 1 Engine - Sb BR700-72-102030 - Low Pressure (Lp)		HRS		3522.4			0			0
	Compressor Front Bearing and Support - Removal of One		ENC		727			0			0
	Existing Alternative No.1 Bearing Assembly		DATE								
			MSC				-				
(880153)											
Engine											
Notes: PN: BRR24148 SN: <NONE>.											
BR700-72-102030	No. 2 Engine - Sb BR700-72-102030 - Low Pressure (Lp)		HRS		3522.4			0			0
	Compressor Front Bearing and Support - Removal of One		ENC		727			0			0
	Existing Alternative No.1 Bearing Assembly		DATE								
			MSC				-				
(880153)											
Engine											
Notes: PN: BRR24148 SN: <NONE>.											
BR700-72-102059	No. 1 Engine - Sb BR700-72-102059 - NI Speed Probe		HRS		3522.4			0			0
	Harness and Accessories - Introduction of New NI Speed		ENC		727			0			0
	Probe Brackets		DATE								
			MSC				-				
(880159)											
Engine											
BR700-72-102059	No. 2 Engine - Sb BR700-72-102059 - NI Speed Probe		HRS		3522.4			0			0
	Harness and Accessories - Introduction of New NI Speed		ENC		727			0			0
	Probe Brackets		DATE								
			MSC				-				
(880159)											
Engine											
BR700-72-102065	No. 1 Engine - Sb BR700-72-102065 - Accessory		HRS		3522.4			0			0
	Gearbox Module - Introduction of an Alternative Transfer		ENC		727			0			0
	Tube and an Alternative Identification Plate Support Plate		DATE								
	for the Accessory Gearbox		MSC				-				
(880158)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102065	No. 2 Engine - Sb BR700-72-102065 - Accessory		HRS		3522.4			0			0
	Gearbox Module - Introduction of an Alternative Transfer		ENC		727			0			0
	Tube and an Alternative Identification Plate Support Plate		DATE								
	for the Accessory Gearbox		MSC				-				
(880158)											
Engine											
BR700-72-102076	No. 1 Engine - Sb BR700-72-102076 - Accessory		HRS		3522.4			0			0
	Gearbox Module - Introduction of Alternative Drain Plugs		ENC		727			0			0
	AT the Engine Oil Tank Drain Location of the Accessory		DATE								
	Gearbox		MSC				-				
(880164)											
Engine											
BR700-72-102076	No. 2 Engine - Sb BR700-72-102076 - Accessory		HRS		3522.4			0			0
	Gearbox Module - Introduction of Alternative Drain Plugs		ENC		727			0			0
	AT the Engine Oil Tank Drain Location of the Accessory		DATE								
	Gearbox		MSC				-				
(880164)											
Engine											
BR700-72-102086	No. 1 Engine - Sb BR700-72-102086 - Low Pressure (Lp)		HRS		3522.4			0			0
	Compressor Front Bearing and Support - Introduction of		ENC		727			0			0
	an Alternative Bearing No.1 from Another Manufacturer		DATE								
			MSC				-				
(880172)											
Engine											
BR700-72-102086 (890172)	No. 2 Engine - Sb BR700-72-102086 - Low Pressure (Lp)		HRS		3522.4			0			0
	Compressor Front Bearing and Support - Introduction of		ENC		727			0			0
	an Alternative Bearing No.1 from Another Manufacturer		DATE								
			MSC				-				
(880172)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102157	No. 1 Engine - Sb BR700-72-102157 - Low Pressure (Lp)		HRS								0
	Compressor/Internal Gearbox AIR Distribution Tubes -		ENC								0
	Introduction of an AIR Manifold Housing Manufactured In		DATE								
	Accordance With A More Precise Machining Definition		MSC				-				
(880194)											
Engine											
BR700-72-102157 (890194)	No. 2 Engine - Sb BR700-72-102157 - Low Pressure (Lp)		HRS								0
	Compressor/Internal Gearbox AIR Distribution Tubes -		ENC								0
	Introduction of an AIR Manifold Housing Manufactured In		DATE								
	Accordance With A More Precise Machining Definition		MSC				-				
(880194)											
Engine											
BR700-72-102165	No. 1 Engine - Sb BR700-72-102165 - Low Pressure (Lp)		HRS								0
	Turbine Fuel Shut-Off (Fso) Cable and Fittings -		ENC								0
	Introduction of A New Conduit Assembly for the Fuel Shut-		DATE								
	Off Mechanism		MSC				-				
(880207)											
Engine											
BR700-72-102165	No. 2 Engine - Sb BR700-72-102165 - Low Pressure (Lp)		HRS								0
	Turbine Fuel Shut-Off (Fso) Cable and Fittings -		ENC								0
	Introduction of A New Conduit Assembly for the Fuel Shut-		DATE								
	Off Mechanism		MSC				-				
(880207)											
Engine											
BR700-72-102171	No. 1 Engine - Sb BR700-72-102171 - Internal Gearbox		HRS								0
	Drive-Driven Assembly - Introduction of an Alternative		ENC								0
	Spiralock Insert for the Radial Drive Shaft (Rds) Lower		DATE								
	Support Housing		MSC				-				
(880195)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102171 (890195)	No. 2 Engine - Sb BR700-72-102171 - Internal Gearbox Drive-Driven Assembly - Introduction of an Alternative Spiralock Insert for the Radial Drive Shaft (Rds) Lower Support Housing		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880195)											
Engine											
BR700-72-102214	No. 1 Engine - Sb BR700-72-102214 - Sb BR700-72-102214 - High Pressure (Hp) Compressor Front Case - Introduction of A New Hp Compressor Front Case Assembly Made By A Different Supplier		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880215)											
Engine											
BR700-72-102214 (890215)	No. 2 Engine - Sb BR700-72-102214 - Sb BR700-72-102214 - High Pressure (Hp) Compressor Front Case - Introduction of A New Hp Compressor Front Case Assembly Made By A Different Supplier		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880215)											
Engine											
BR700-72-102214 R01	No. 1 Engine - Sb BR700-72-102214 R01 - Sb BR700-72-102214 R01 - High Pressure (Hp) Compressor Front Case - Introduction of A New Hp Compressor Front Case Assembly Made By A Different Supplier		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880218)											
Engine											
BR700-72-102214 R01 (890218)	No. 2 Engine - Sb BR700-72-102214 R01 - Sb BR700-72-102214 R01 - High Pressure (Hp) Compressor Front Case - Introduction of A New Hp Compressor Front Case Assembly Made By A Different Supplier		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880218)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102214 R02	No. 1 Engine - Sb BR700-72-102214 R02 - High Pressure (Hp) Compressor Front Case - Introduction of A New Hp Compressor Front Case Assembly Made By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880230)											
Engine											
BR700-72-102214 R02 (890230)	No. 2 Engine - Sb BR700-72-102214 R02 - High Pressure (Hp) Compressor Front Case - Introduction of A New Hp Compressor Front Case Assembly Made By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880230)											
Engine											
BR700-72-102227	No. 1 Engine - Sb BR700-72-102227 - Sb BR700-72-102227 - Accessory Gearbox Module - Introduction of an Alternative Nut Standard and an Alternative Nail Standard Used for the Installation of the Nameplate Support		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880217)											
Engine											
BR700-72-102227 (890217)	No. 2 Engine - Sb BR700-72-102227 - Sb BR700-72-102227 - Accessory Gearbox Module - Introduction of an Alternative Nut Standard and an Alternative Nail Standard Used for the Installation of the Nameplate Support		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880217)											
Engine											
BR700-72-102227 R01	No. 1 Engine - Sb BR700-72-102227 R01 - BR700-72-102227 R01 - Accessory Gearbox Module - Introduction of an Alternative Nut Standard and an Alternative Nail Standard Used for the Installation of the Nameplate Support		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880222)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102227 R01 (890222)	No. 2 Engine - Sb BR700-72-102227 R01 - BR700-72-102227 R01 - Accessory Gearbox Module - Introduction of an Alternative Nut Standard and an Alternative Nail Standard Used for the Installation of the Nameplate Support		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880222)											
Engine											
BR700-72-102232	No. 1 Engine - Sb BR700-72-102232 - Sb BR700-72-102232 - High Pressure (Hp) Compressor Stage 4 Onward Stator Vanes - Introduction of A New Definition of the Maximum Permitted Quantity of Hp Compressor Stages 5 and 6 Undersize Vanes		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880216)											
Engine											
BR700-72-102232 (890216)	No. 2 Engine - Sb BR700-72-102232 - Sb BR700-72-102232 - High Pressure (Hp) Compressor Stage 4 Onward Stator Vanes - Introduction of A New Definition of the Maximum Permitted Quantity of Hp Compressor Stages 5 and 6 Undersize Vanes		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880216)											
Engine											
BR700-72-102270	No. 1 Engine - Sb BR700-72-102270 - Sb BR700-72-102270 - High Pressure (Hp) Compressor Front Case - Introduction of Modified Hp Compressor Variable Inlet Guide Vane (Vigv) Bushes and Modified Hp Compressor Stages 1 to 3 Variable Stator Vane (Vsv) Bushes for the Hp Compressor Front Case Assembly		HRS								0
			ENC							0	
			DATE								
			MSC				ESV**				
(880226)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102270 (890226)	No. 2 Engine - Sb BR700-72-102270 - Sb BR700-72-102270 - High Pressure (Hp) Compressor Front Case - Introduction of Modified Hp Compressor Variable Inlet Guide Vane (Vigv) Bushes and Modified Hp Compressor Stages 1 to 3 Variable Stator Vane (Vsv) Bushes for the Hp Compressor Front Case Assembly		HRS								0
			ENC							0	
			DATE								
			MSC				ESV**				
(880226)											
Engine											
BR700-72-102277	No. 1 Engine - Sb BR700-72-102277 - BR700-72-102277 - High Pressure (Hp) Turbine Rotor Discs and Hp Turbine Stage 1 Nozzle Guide Seals - Introduction of an Hp Turbine Stage 1 Disc Without Coating on All Seal Fins and Introduction of A Modified Hp Turbine Stage 1 Preswirl Web Seal Assembly		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880228)											
Engine											
BR700-72-102277 (890228)	No. 2 Engine - Sb BR700-72-102277 - BR700-72-102277 - High Pressure (Hp) Turbine Rotor Discs and Hp Turbine Stage 1 Nozzle Guide Seals - Introduction of an Hp Turbine Stage 1 Disc Without Coating on All Seal Fins and Introduction of A Modified Hp Turbine Stage 1 Preswirl Web Seal Assembly		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880228)											
Engine											
BR700-72-102277 R01	No. 1 Engine - Sb BR700-72-102277 R01 - High Pressure (Hp) Turbine Rotor Discs and Hp Turbine Stage 1 Nozzle Guide Seals - Introduction of an Hp Turbine Stage 1 Disc Without Coating on All Seal Fins and Introduction of A Modified Hp Turbine Stage 1 Preswirl Web Seal Assembly, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880266.001)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102277 R01	No. 2 Engine - Sb BR700-72-102277 R01 - High Pressure		HRS								0
	(Hp) Turbine Rotor Discs and Hp Turbine Stage 1 Nozzle		ENC								0
	Guide Seals - Introduction of an Hp Turbine Stage 1 Disc		DATE								
	Without Coating on All Seal Fins and Introduction of A		MSC					-			
Modified Hp Turbine Stage 1 Preswirl Web Seal											
Assembly, Service Bulletin (Optional)											
(880266.001)											
Engine											
BR700-72-102282	No. 1 Engine - Sb BR700-72-102282 - BR700-72-102282		HRS								0
	- Low Pressure (Lp) Turbine Nozzle Guide Vanes (Ngv) -		ENC								0
	Introduction of Two Changed Lp Turbine Stage 1 Ngv		DATE								
	Assemblies Containing Modified Oil Scavenge and		MSC					-			
Oil/AIR Vent Pipes With Uncoated Union Adapters and											
Introduction of A Modified Oil Feed Pipe With an Uncoated											
Union Adapter											
(880229)											
Engine											
BR700-72-102282 (890229)	No. 2 Engine - Sb BR700-72-102282 - BR700-72-102282		HRS								0
	- Low Pressure (Lp) Turbine Nozzle Guide Vanes (Ngv) -		ENC								0
	Introduction of Two Changed Lp Turbine Stage 1 Ngv		DATE								
	Assemblies Containing Modified Oil Scavenge and		MSC					-			
Oil/AIR Vent Pipes With Uncoated Union Adapters and											
Introduction of A Modified Oil Feed Pipe With an Uncoated											
Union Adapter											
(880229)											
Engine											
BR700-72-102306	No. 1 Engine - Sb BR700-72-102306 - Low Pressure (Lp)		HRS								0
	Turbine Stage 2 Onward Nozzle Guide Vanes (Ngv) -		ENC								0
	Introduction of A Modified Lp Turbine Interstage 1-2 Seal		DATE								
	Assembly Made from A Different Material and According to		MSC					-			
A Different Manufacturing Method, Service Bulletin											
(Optional)											
(880262)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102306	No. 2 Engine - Sb BR700-72-102306 - Low Pressure (Lp)		HRS								0
	Turbine Stage 2 Onward Nozzle Guide Vanes (Ngv) -		ENC								0
	Introduction of A Modified Lp Turbine Interstage 1-2 Seal		DATE								
	Assembly Made from A Different Material and According to A Different Manufacturing Method, Service Bulletin (Optional)		MSC				-				
(880262)											
Engine											
BR700-72-102317	No. 1 Engine - Sb BR700-72-102317 - High Pressure (Hp)		HRS								0
	Compressor Front Case - Introduction of Modified Bushes		ENC								0
	Made from A Different Material Used AT the Hp		DATE								
	Compressor Variable Inlet Guide Vanes (Vigv) and AT the Stages 1 to 3 Variable Stator Vanes (Vsv), Service Bulletin (Optional)		MSC				-				
(880264)											
Engine											
BR700-72-102317	No. 2 Engine - Sb BR700-72-102317 - High Pressure (Hp)		HRS								0
	Compressor Front Case - Introduction of Modified Bushes		ENC								0
	Made from A Different Material Used AT the Hp		DATE								
	Compressor Variable Inlet Guide Vanes (Vigv) and AT the Stages 1 to 3 Variable Stator Vanes (Vsv), Service Bulletin (Optional)		MSC				-				
(880264)											
Engine											
BR700-72-102323	No. 1 Engine - BR700-72-102323 - High Pressure (Hp)		HRS								0
	Turbine Rotor Discs - Introduction of A New Hp Turbine		ENC								0
	Stage 1 Disc Standard Produced from A Forging Made		DATE								
	from A Different Raw Material Size, Service Bulletin (Optional)		MSC				-				
(880263)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-102323	No. 2 Engine - BR700-72-102323 - High Pressure (Hp)		HRS								0
	Turbine Rotor Discs - Introduction of A New Hp Turbine		ENC								0
	Stage 1 Disc Standard Produced from A Forging Made		DATE								
	from A Different Raw Material Size, Service Bulletin (Optional)		MSC				-				
(880263)											
Engine											
BR700-72-102323 R01	No. 1 Engine - Sb BR700-72-102323 R01 - High Pressure		HRS								0
	(Hp) Turbine Rotor Discs - Introduction of A New Hp		ENC								0
	Turbine Stage 1 Disc Standard Produced from A Forging		DATE								
	Made from A Different Raw Material Size, Service Bulletin (Optional)		MSC				-				
(880267.001)											
Engine											
BR700-72-102323 R01	No. 2 Engine - Sb BR700-72-102323 R01 - High Pressure		HRS								0
	(Hp) Turbine Rotor Discs - Introduction of A New Hp		ENC								0
	Turbine Stage 1 Disc Standard Produced from A Forging		DATE								
	Made from A Different Raw Material Size, Service Bulletin (Optional)		MSC				-				
(880267.001)											
Engine											
BR700-72-900178	No. 1 Engine - Sb BR700-72-900178 - Inspection and		HRS		3522.4			0			0
	Lubrication of the Vigv Actuating Mechanism on Engines		ENC		727			0			0
	Operating Under Specific Environmental Conditions		MOS		69.3			18 Mar 2019			
			MSC				-				
(880165)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-900178	No. 2 Engine - Sb BR700-72-900178 - Inspection and		HRS		3522.4			0			0
	Lubrication of the Vigv Actuating Mechanism on Engines		ENC		727			0			0
	Operating Under Specific Environmental Conditions		MOS		69.3			18 Mar 2019			
			MSC				-				
(880165)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-900178 R01	No. 1 Engine - Sb BR700-72-900178 R01 - High Pressure		HRS		3522.4			0			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		727			0			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		MOS		67.5			09 May 2019			
	Modification Service Bulletin		MSC				-				
(880168)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-900178 R01	No. 2 Engine - Sb BR700-72-900178 R01 - High Pressure		HRS		3522.4			0			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		727			0			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		MOS		67.5			09 May 2019			
	Modification Service Bulletin		MSC				-				
(880168)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-900178 R02	No. 1 Engine - Sb BR700-72-900178 R02 - High Pressure		HRS		1585.8			1936.6			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		321			406			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		MOS		65			25 Jul 2019			
	Modification Service Bulletin		MSC				-				
(880171)											
Engine											
Notes: TW 574813 DUE 07/20TW 569509 DUE 09/19TW 561051 DUE 11/19											
BR700-72-900178 R02	No. 2 Engine - Sb BR700-72-900178 R02 - High Pressure		HRS		1585.8			1936.6			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		321			406			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		MOS		65.1			23 Jul 2019			
	Modification Service Bulletin		MSC				-				
(880171)											
Engine											
Notes: TW 574813 DUE 07/20TW 569509 DUE 09/19TW 561051 DUE 11/19											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-900178 R03	No. 1 Engine - Sb BR700-72-900178 R03 - High Pressure		HRS		3522.4			0			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		727			0			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		MOS		65.3			17 Jul 2019			
	Modification Service Bulletin		MSC				-				
(880178)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-900178 R03	No. 2 Engine - Sb BR700-72-900178 R03 - High Pressure		HRS		3522.4			0			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		727			0			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		MOS		65.3			17 Jul 2019			
	Modification Service Bulletin		MSC				-				
(880178)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-900178 R04	No. 1 Engine - Sb BR700-72-900178 R04 - High Pressure		HRS		3522.4			0			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		727			0			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		MOS		65.1			23 Jul 2019			
	Modification Service Bulletin		MSC				-				
(880179)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-900178 R04	No. 2 Engine - Sb BR700-72-900178 R04 - High Pressure		HRS		3522.4			0			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		727			0			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		MOS		65.1			23 Jul 2019			
	Modification Service Bulletin		MSC				-				
(880179)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-900178 R05	No. 1 Engine - Sb BR700-72-900178 R05 - High Pressure		HRS		3522.4			0			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		727			0			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		MOS		64.9			29 Jul 2019			
	Modification Service Bulletin		MSC				-				
(880180)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-900178 R05	No. 2 Engine - Sb BR700-72-900178 R05 - High Pressure		HRS		3522.4			0			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		727			0			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		MOS		64.9			29 Jul 2019			
	Modification Service Bulletin		MSC				-				
(880180)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-72-900178 R06	No. 1 Engine - Sb BR700-72-900178 R06 - High Pressure		HRS		3522.4			0			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		727			0			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		DATE								
	Modification Service Bulletin		MSC				-				
(880181)											
Engine											
BR700-72-900178 R06	No. 2 Engine - Sb BR700-72-900178 R06 - High Pressure		HRS		3522.4			0			0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC		727			0			0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		DATE								
	Modification Service Bulletin		MSC				-				
(880181)											
Engine											
BR700-72-900178 R07	No. 1 Engine - Sb BR700-72-900178 R07 - High Pressure		HRS								0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC								0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		DATE								
	Modification Service Bulletin		MSC				-				
(880193)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-72-900178 R07 (890193)	No. 2 Engine - Sb BR700-72-900178 R07 - High Pressure		HRS								0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC								0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		DATE								
	Modification Service Bulletin		MSC				-				
(880193)											
Engine											
BR700-72-900178 R08	No. 1 Engine - Sb BR700-72-900178 R08 - High Pressure		HRS								0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC								0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		DATE								
	Modification Service Bulletin		MSC				-				
(880199)											
Engine											
BR700-72-900178 R08	No. 2 Engine - Sb BR700-72-900178 R08 - High Pressure		HRS								0
	(Hp) Compressor Variable Stator Vanes (Vsv) Mechanism		ENC								0
	- Inspection and Lubrication of the Vsv Mechanism - Non-		DATE								
	Modification Service Bulletin		MSC				-				
(880199)											
Engine											
BR700-72- A900628	No. 1 Engine - Sb BR700-72-A900628 - Asb BR700-72-		HRS								0
	A900628 - High Pressure (Hp) Turbine Blades -		ENC								0
	Replacement of Seven Hp Turbine Stage 1 Blades - Non-		DATE								
	Modification Service Bulletin		MSC				-				
(880210)											
Engine											
BR700-72- A900628	No. 2 Engine - Sb BR700-72-A900628 - Asb BR700-72-		HRS								0
	A900628 - High Pressure (Hp) Turbine Blades -		ENC								0
	Replacement of Seven Hp Turbine Stage 1 Blades - Non-		DATE								
	Modification Service Bulletin		MSC				-				
(880210)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101708 R01	No. 1 Engine - Sb BR700-73-101708 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised Main Fuel Pump, Service Bulletin (Recommended)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880240)											
Engine											
BR700-73-101708 R01	No. 2 Engine - Sb BR700-73-101708 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised Main Fuel Pump, Service Bulletin (Recommended)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880240)											
Engine											
BR700-73-101767 R01	No. 1 Engine - Sb BR700-73-101767 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A New Main Fuel Pump With Modified Gears and Impeller Housing, Service Bulletin (Recommended)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880242)											
Engine											
BR700-73-101767 R01	No. 2 Engine - Sb BR700-73-101767 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A New Main Fuel Pump With Modified Gears and Impeller Housing, Service Bulletin (Recommended)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880242)											
Engine											
BR700-73-101769 R01	No. 1 Engine - Sb BR700-73-101769 R01 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Introduction of A Revised Shut-Off Valve Servo Valve (Sovsv) With A New Gas Discharge Tube, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880244)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101769 R01	No. 2 Engine - Sb BR700-73-101769 R01 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Introduction of A Revised Shut-Off Valve Servo Valve (Sovsv) With A New Gas Discharge Tube, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880244)											
Engine											
BR700-73-101775 R01	No. 1 Engine - Sb BR700-73-101775 R01 - Engine Fuel and Control - Low Pressure (Lp) Turbine Overspeed Control Unit and Manifold Splitter - Introduction of A Revised Overspeed and Splitter Unit (Osu), Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880246)											
Engine											
BR700-73-101775 R01	No. 2 Engine - Sb BR700-73-101775 R01 - Engine Fuel and Control - Low Pressure (Lp) Turbine Overspeed Control Unit and Manifold Splitter - Introduction of A Revised Overspeed and Splitter Unit (Osu), Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880246)											
Engine											
BR700-73-101792 R02	No. 1 Engine - Sb BR700-73-101792 R02 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.1 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880248)											
Engine											
BR700-73-101792 R02	No. 2 Engine - Sb BR700-73-101792 R02 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.1 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880248)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101793 R04	No. 1 Engine - Sb BR700-73-101793 R04 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.1.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880250)											
Engine											
BR700-73-101793 R04	No. 2 Engine - Sb BR700-73-101793 R04 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.1.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880250)											
Engine											
BR700-73-101801 R01	No. 1 Engine - Sb BR700-73-101801 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.1.4 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880252)											
Engine											
BR700-73-101801 R01	No. 2 Engine - Sb BR700-73-101801 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.1.4 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880252)											
Engine											
BR700-73-101838	No. 1 Engine - Sb BR700-73-101838 - Engine Fuel and Control - Fuel Spray Nozzles - Introduction of A Redesigned Bracket Assembly Installed on the No.1 Burner Assembly Flange and Supporting A Stage 4 Pressure AIR Tube		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880054)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101838	No. 2 Engine - Sb BR700-73-101838 - Engine Fuel and Control - Fuel Spray Nozzles - Introduction of A Redesigned Bracket Assembly Installed on the No.1 Burner Assembly Flange and Supporting A Stage 4 Pressure AIR Tube		HRS		3522.4			0			0
			ENC		727			0		0	
			DATE								
			MSC				-				
(880054)											
Engine											
BR700-73-101847 R02	No. 1 Engine - Sb BR700-73-101847 R02 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Spill Return to Fuel Pump Tube Made from A Different Material and A New Assembly Procedure, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880254)											
Engine											
BR700-73-101847 R02	No. 2 Engine - Sb BR700-73-101847 R02 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Spill Return to Fuel Pump Tube Made from A Different Material and A New Assembly Procedure, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880254)											
Engine											
BR700-73-101886	No. 1 Engine - Sb BR700-73-101886 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.2 Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		3509.1			13.3			0
			ENC		722			5		0	
			MOS		122.5			10 Oct 2014			
			MSC				-				
(880063)											
Engine											
BR700-73-101886	No. 2 Engine - Sb BR700-73-101886 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.2 Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		3509.1			13.3			0
			ENC		722			5		0	
			MOS		122.5			10 Oct 2014			
			MSC				-				
(880063)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101886 R01	No. 1 Engine - Sb BR700-73-101886 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880256)											
Engine											
BR700-73-101886 R01	No. 2 Engine - Sb BR700-73-101886 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880256)											
Engine											
BR700-73-101892	No. 1 Engine - Sb BR700-73-101892 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A Low Pressure (Lp) Fuel Switch Sense Line Tube With Increased Volume		HRS		2312.5			1209.9			0
			ENC		479			248		0	
			MOS		87			26 Sep 2017			
			MSC				-				
(880082)											
Engine											
BR700-73-101892	No. 2 Engine - Sb BR700-73-101892 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A Low Pressure (Lp) Fuel Switch Sense Line Tube With Increased Volume		HRS		2312.5			1209.9			0
			ENC		479			248		0	
			MOS		87			26 Sep 2017			
			MSC				-				
(880082)											
Engine											
BR700-73-101892 R01	No. 1 Engine - Sb BR700-73-101892 R01 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A Low Pressure (Lp) Fuel Switch Sense Line Tube With Increased Volume		HRS		2312.5			1209.9			0
			ENC		479			248		0	
			MOS		87			26 Sep 2017			
			MSC				-				
(880132)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101892 R01	No. 2 Engine - Sb BR700-73-101892 R01 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A Low Pressure (Lp) Fuel Switch Sense Line Tube With Increased Volume		HRS		2312.5			1209.9			0
			ENC		479			248		0	
			MOS		87		26 Sep 2017				
			MSC			-					
(880132)											
Engine											
BR700-73-101892 R02	No. 1 Engine - Sb BR700-73-101892 R02 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A Low Pressure (Lp) Fuel Switch Sense Line Tube With Increased Volume, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC			-					
(880258)											
Engine											
BR700-73-101892 R02	No. 2 Engine - Sb BR700-73-101892 R02 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A Low Pressure (Lp) Fuel Switch Sense Line Tube With Increased Volume, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC			-					
(880258)											
Engine											
BR700-73-101902 R02	No. 1 Engine - Sb BR700-73-101902 R02 - Engine Fuel and Control - T30 Thermocouples - Introduction of A Revised T30 Thermocouple Installation on the Left Side of the Core Engine, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC			-					
(880261)											
Engine											
BR700-73-101902 R02	No. 2 Engine - Sb BR700-73-101902 R02 - Engine Fuel and Control - T30 Thermocouples - Introduction of A Revised T30 Thermocouple Installation on the Left Side of the Core Engine, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC			-					
(880261)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101923	No. 1 Engine - Sb BR700-73-101923 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Fuel Tube With an Increased Wall Thickness, Which Is Installed Between the Fuel Cooled Oil Cooler (Fcoc) and the Main Fuel Pump		HRS		3133.7			388.7			0
			ENC		652			75			0
			MOS		111.4			15 Sep 2015			
			MSC				-				
(880092)											
Engine											
BR700-73-101923	No. 2 Engine - Sb BR700-73-101923 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Fuel Tube With an Increased Wall Thickness, Which Is Installed Between the Fuel Cooled Oil Cooler (Fcoc) and the Main Fuel Pump		HRS		3133.7			388.7			0
			ENC		652			75			0
			MOS		111.3			16 Sep 2015			
			MSC				-				
(880092)											
Engine											
BR700-73-101923 R01	No. 1 Engine - BR700-73-101923 R01 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Fuel Tube With an Increased Wall Thickness, Which Is Installed Between the Fuel Cooled Oil Cooler (Fcoc) and the Main Fuel Pump, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880260)											
Engine											
BR700-73-101923 R01	No. 2 Engine - BR700-73-101923 R01 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Fuel Tube With an Increased Wall Thickness, Which Is Installed Between the Fuel Cooled Oil Cooler (Fcoc) and the Main Fuel Pump, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880260)											
Engine											
BR700-73-101929	No. 1 Engine - Sb BR700-73-101929 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments		HRS		3133.7			388.7			0
			ENC		652			75			0
			MOS		111.4			15 Sep 2015			
			MSC				-				
(880098)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101929	No. 2 Engine - Sb BR700-73-101929 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments		HRS		3133.7			388.7			0
			ENC		652			75			0
			MOS		111.4			15 Sep 2015			
			MSC				-				
(880098)											
Engine											
BR700-73-101929 R01	No. 1 Engine - BR700-73-101929 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880259)											
Engine											
BR700-73-101929 R01	No. 2 Engine - BR700-73-101929 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880259)											
Engine											
BR700-73-101957	No. 1 Engine - Sb BR700-73-101957 - Engine Fuel and Control - Fuel System - Introduction of A Revised Fuel System		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		99.1			23 Sep 2016			
			MSC				-				
(880124)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-73-101957	No. 2 Engine - Sb BR700-73-101957 - Engine Fuel and Control - Fuel System - Introduction of A Revised Fuel System		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		99.1			23 Sep 2016			
			MSC				-				
(880124)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101957 R01	No. 1 Engine - Sb BR700-73-101957 R01 - Engine Fuel and Control - Fuel System - Introduction of A Revised Fuel System		HRS		2312.5			1209.9			0
			ENC		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
(880131)											
Engine											
BR700-73-101957 R01	No. 2 Engine - Sb BR700-73-101957 R01 - Engine Fuel and Control - Fuel System - Introduction of A Revised Fuel System		HRS		2312.5			1209.9			0
			ENC		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
(880131)											
Engine											
BR700-73-101957 R02	No. 1 Engine - Sb BR700-73-101957 R02 - Engine Fuel and Control - Fuel System - Introduction of A Revised Fuel System, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880231)											
Engine											
BR700-73-101957 R02	No. 2 Engine - Sb BR700-73-101957 R02 - Engine Fuel and Control - Fuel System - Introduction of A Revised Fuel System, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880231)											
Engine											
BR700-73-101965	No. 1 Engine - Sb BR700-73-101965 - Engine Fuel and Control - Fuel Low Pressure Switch - Introduction of A Revised Fuel Low Pressure (Lp) Switch With A Decreased Pressure Trigger Point, Service Bulletin		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		99.3			16 Sep 2016			
			MSC				-				
(880125)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101965	No. 2 Engine - Sb BR700-73-101965 - Engine Fuel and		HRS		3522.4			0			0
	Control - Fuel Low Pressure Switch - Introduction of A		ENC		727			0			0
	Revised Fuel Low Pressure (Lp) Switch With A Decreased		MOS		99.3			16 Sep 2016			
	Pressure Trigger Point, Service Bulletin		MSC				-				
(880125)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-73-101965 R01	No. 1 Engine - Sb BR700-73-101965 R01 - Engine Fuel		HRS		2312.5			1209.9			0
	and Control - Fuel Low Pressure Switch - Introduction of A		ENC		479			248			0
	Revised Fuellow Pressure (Lp) Switch With A Decreased		MOS		87			26 Sep 2017			
	Pressure Trigger Point		MSC				-				
(880129)											
Engine											
BR700-73-101965 R01	No. 2 Engine - Sb BR700-73-101965 R01 - Engine Fuel		HRS		2312.5			1209.9			0
	and Control - Fuel Low Pressure Switch - Introduction of A		ENC		479			248			0
	Revised Fuellow Pressure (Lp) Switch With A Decreased		MOS		87			26 Sep 2017			
	Pressure Trigger Point		MSC				-				
(880129)											
Engine											
BR700-73-101965 R02	No. 1 Engine - BR700-73-101965 R02 - Engine Fuel and		HRS								0
	Control - Fuel Low Pressure Switch - Introduction of A		ENC								0
	Revised Fuel Low Pressure (Lp) Switch With A Decreased		DATE								
	Pressure Trigger Point, Service Bulletin (Optional)		MSC				-				
(880257)											
Engine											
BR700-73-101965 R02	No. 2 Engine - BR700-73-101965 R02 - Engine Fuel and		HRS								0
	Control - Fuel Low Pressure Switch - Introduction of A		ENC								0
	Revised Fuel Low Pressure (Lp) Switch With A Decreased		DATE								
	Pressure Trigger Point, Service Bulletin (Optional)		MSC				-				
(880257)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101967	No. 1 Engine - Sb BR700-73-101967 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K7.1.3 Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		99.3			16 Sep 2016			
			MSC				-				
(880126)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-73-101967	No. 2 Engine - Sb BR700-73-101967 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K7.1.3 Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		99.3			16 Sep 2016			
			MSC				-				
(880126)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-73-101967 R01	No. 1 Engine - Sb BR700-73-101967 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K7.1.3 Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		2312.5			1209.9			0
			ENC		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
(880130)											
Engine											
BR700-73-101967 R01	No. 2 Engine - Sb BR700-73-101967 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K7.1.3 Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		2312.5			1209.9			0
			ENC		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
(880130)											
Engine											
BR700-73-101967 R02	No. 1 Engine - BR700-73-101967 R02 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K7.1.3 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880255)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-101967 R02	No. 2 Engine - BR700-73-101967 R02 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K7.1.3 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880255)											
Engine											
BR700-73-102000	No. 1 Engine - Sb BR700-73-102000 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K8.0.2 Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		1722.5			1799.9			0
			ENC		351			376		0	
			MOS		68.7		04 Apr 2019				
			MSC				-				
(880162)											
Engine											
BR700-73-102000	No. 2 Engine - Sb BR700-73-102000 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K8.0.2 Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		1722.5			1799.9			0
			ENC		351			376		0	
			MOS		68.7		04 Apr 2019				
			MSC				-				
(880162)											
Engine											
BR700-73-102000 R01	No. 1 Engine - BR700-73-102000 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K8.0.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880253)											
Engine											
BR700-73-102000 R01	No. 2 Engine - BR700-73-102000 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K8.0.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880253)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-102075 (880166) Engine	No. 1 Engine - Sb BR700-73-102075 - Engine Fuel and Control - Fuel Temperature Transducer - Introduction of A New Duplex Fuel Temperature Transducer		HRS		3522.4			0			0
			ENC		727			0		0	
			DATE								
			MSC				-				
BR700-73-102075 (880166) Engine	No. 2 Engine - Sb BR700-73-102075 - Engine Fuel and Control - Fuel Temperature Transducer - Introduction of A New Duplex Fuel Temperature Transducer		HRS		3522.4			0			0
			ENC		727			0		0	
			DATE								
			MSC				-				
BR700-73-102134 R01 (880182) Engine	No. 1 Engine - Sb BR700-73-102134 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K9.0.1 Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		1566.2			1956.2	0		0
			ENC		319			408	0		0
			MOS		64.5			10 Aug 2019			
			MSC				-				
BR700-73-102134 R01 (880182) Engine	No. 2 Engine - Sb BR700-73-102134 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K9.0.1 Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		1566.2			1956.2	0		0
			ENC		319			408	0		0
			MOS		64.5			10 Aug 2019			
			MSC				-				
BR700-73-102134 R02 (880185) Engine	No. 1 Engine - Sb BR700-73-102134 R02 -		HRS								0
			ENC								0
			DATE								
			MSC				-				
BR700-73-102134 R02 (880185) Engine	No. 2 Engine - Sb BR700-73-102134 R02 -		HRS								0
			ENC								0
			DATE								
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-102134 R03	No. 1 Engine - BR700-73-102134 R03 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K9.0.1 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880251)											
Engine											
BR700-73-102134 R03	No. 2 Engine - BR700-73-102134 R03 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K9.0.1 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880251)											
Engine											
BR700-73-102183	No. 1 Engine - Sb BR700-73-102183 - BR700-73-102183 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K10.1Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		485.9			3036.5			0
			ENC		97			630			0
			DATE		813 d			05 Oct 2022			
			MSC				-				
(880212)											
Engine											
BR700-73-102183	No. 2 Engine - Sb BR700-73-102183 - BR700-73-102183 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K10.1Software Standard on an Eec With Hardware Standard G3010ECU01		HRS		485.9			3036.5			0
			ENC		97			630			0
			DATE		813 d			05 Oct 2022			
			MSC				-				
(880212)											
Engine											
BR700-73-102183 R01	No. 1 Engine - BR700-73-102183 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K10.1 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Recommended)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880249)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-102183 R01	No. 2 Engine - BR700-73-102183 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K10.1 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Recommended)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880249)											
Engine											
BR700-73-900009	No. 1 Engine - Sb BR700-73-900009 - Engine Fuel and Control - Main Fuel Pump - Inspection of the V-Band Coupling Clamp - Non-Modification Service Bulletin		HRS		3396.7			125.7			0
			ENC		702			25			0
			MOS		120.1			23 Dec 2014			
			MSC				-				
(880087)											
Engine											
BR700-73-900009	No. 2 Engine - Sb BR700-73-900009 - Engine Fuel and Control - Main Fuel Pump - Inspection of the V-Band Coupling Clamp - Non-Modification Service Bulletin		HRS		3396.7			125.7			0
			ENC		702			25			0
			MOS		120.1			23 Dec 2014			
			MSC				-				
(880087)											
Engine											
BR700-73-900009 R01	No. 1 Engine - Sb BR700-73-900009 R01 - Engine Fuel and Control - Main Fuel Pump - Inspection of the V-Band Coupling Clamp - Non-Modification Service Bulletin		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880160)											
Engine											
BR700-73-900009 R01	No. 2 Engine - Sb BR700-73-900009 R01 - Engine Fuel and Control - Main Fuel Pump - Inspection of the V-Band Coupling Clamp - Non-Modification Service Bulletin		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880160)											
Engine											
BR700-73-900636	No. 1 Engine - Sb BR700-73-900636 - Engine Fuel and Control - Fuel Low Pressure (Lp) Switch - Replacement of the Fuel Lp Switch - Non-Modification Service Bulletin		HRS		1158			2364.4			0
			ENC		239			488			0
			DATE		1533 d			15 Oct 2020			
			MSC				-				
(880150)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-73-900636	No. 2 Engine - Sb BR700-73-900636 - Engine Fuel and Control - Fuel Low Pressure (Lp) Switch - Replacement of the Fuel Lp Switch - Non-Modification Service Bulletin		HRS		1158			2364.4			0
			ENC		239			488			0
			DATE		1533 d			15 Oct 2020			
			MSC				-				
(880150)											
Engine											
BR700-73-A900309 R02	No. 1 Engine - Sb BR700-73-A900309 R02 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Replacement of the Fmu - Non-Modification Service Bulletin		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		114.9			28 May 2015			
			MSC				-				
(880055)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-73-A900309 R02	No. 2 Engine - Sb BR700-73-A900309 R02 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Replacement of the Fmu - Non-Modification Service Bulletin		HRS		3522.4			0			0
			ENC		727			0			0
			MOS		114.9			28 May 2015			
			MSC				-				
(880055)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
BR700-73-A900309 R03	No. 1 Engine - Sb BR700-73-A900309 R03 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Replacement of the Fmu - Non-Modification Service Bulletin		HRS		2312.5			1209.9			0
			ENC		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
(880097)											
Engine											
BR700-73-A900309 R03	No. 2 Engine - Sb BR700-73-A900309 R03 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Replacement of the Fmu - Non-Modification Service Bulletin		HRS		2312.5			1209.9			0
			ENC		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
(880097)											
Engine											
BR700-74-101762 R02	No. 1 Engine - BR700-74-101762 R02 - Ignition - Igniter Plug - Introduction of Igniter Plugs With Silver Coated Threads, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880247)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-74-101762 R02	No. 2 Engine - BR700-74-101762 R02 - Ignition - Igniter Plug - Introduction of Igniter Plugs With Silver Coated Threads, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC								
(880247)											
Engine											
BR700-74-102002	No. 1 Engine - Sb BR700-74-102002 - Ignition - Igniter Plug - Introduction of an Igniter Plug With Revised Semiconductorpellet Bonding		HRS		1912.8			1609.6			0
			ENC		397			330		0	
			MOS		75.2			20 Sep 2018			
			MSC								
(880147)											
Engine											
BR700-74-102002	No. 2 Engine - Sb BR700-74-102002 - Ignition - Igniter Plug - Introduction of an Igniter Plug With Revised Semiconductorpellet Bonding		HRS		1912.8			1609.6			0
			ENC		397			330		0	
			MOS		75.2			20 Sep 2018			
			MSC								
(880147)											
Engine											
Notes: SB BR700-74-900649 IS NOT REQUIRED AT THIS TIME DUE TO SB BR700-74-102002 BEING INCORPORATED AT THIS TIME.SB BR700-74-900649 NEXT DUE IN 1250 FLIGHT HOURS OR AT A/C TT 2859.6											
BR700-74-102002 R01	No. 1 Engine - BR700-74-102002 R01 - Ignition - Igniter Plug - Introduction of an Igniter Plug With Revised Semiconductor Pellet Bonding, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC								
(880245)											
Engine											
BR700-74-102002 R01	No. 2 Engine - BR700-74-102002 R01 - Ignition - Igniter Plug - Introduction of an Igniter Plug With Revised Semiconductor Pellet Bonding, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC								
(880245)											
Engine											
BR700-74-102003	No. 1 Engine - Sb BR700-74-102003 - Ignition - Igniter Plug - Introduction of an Alternative Igniter Plug Manufactured By A Different Supplier		HRS		1508.2			2014.2			0
			ENC		311			416		0	
			MOS		63.2			20 Sep 2019			
			MSC								
(880173)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-74-102003 (890173) (880173) Engine	No. 2 Engine - Sb BR700-74-102003 - Ignition - Igniter Plug - Introduction of an Alternative Igniter Plug Manufactured By A Different Supplier		HRS		1508.2			2014.2			0
			ENC		311			416			0
			MOS		63.2			20 Sep 2019			
			MSC				-				
BR700-74-102003 R02 (880243) Engine	No. 1 Engine - Sb BR700-74-102003 R02 - Ignition - Igniter Plug - Introduction of an Alternative Igniter Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
BR700-74-102003 R02 (880243) Engine	No. 2 Engine - Sb BR700-74-102003 R02 - Ignition - Igniter Plug - Introduction of an Alternative Igniter Plug Manufactured By A Different Supplier, Service Bulletin (Optional)		HRS								0
			ENC								0
			DATE								
			MSC				-				
BR700-74-102151 (880192) Engine	No. 1 Engine - Sb BR700-74-102151 - Ignition - Igniter Plug - Definition of One Existing Igniter Plug as the Single Standard for Future Use		HRS								0
			ENC								0
			DATE								
			MSC				-				
BR700-74-102151 (890192) (880192) Engine	No. 2 Engine - Sb BR700-74-102151 - Ignition - Igniter Plug - Definition of One Existing Igniter Plug as the Single Standard for Future Use		HRS								0
			ENC								0
			DATE								
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-74-102151 R01	No. 1 Engine - Sb BR700-74-102151 R01 - Ignition - Igniter Plug - Definition of One Existing Igniter Plug as the Single Standard for Future Use, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880241)											
Engine											
BR700-74-102151 R01	No. 2 Engine - Sb BR700-74-102151 R01 - Ignition - Igniter Plug - Definition of One Existing Igniter Plug as the Single Standard for Future Use, Service Bulletin (Optional)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880241)											
Engine											
BR700-74-900594 R01	No. 1 Engine - Sb BR700-74-900594 R01 - Ignition - Igniter Plug - Replacement of the Igniter Plugs AT A Specified Interval - Non-Modification Service Bulletin		HRS		1912.8			1609.6			0
			ENC		397		330		0		
			MOS		75.2		20 Sep 2018				
			MSC				-				
(880155)											
Engine											
Notes: SB BR700-74-900594R1 IS NOT REQUIRED DUE TO SB BR700-74-102002 BEING INCORPORATED AT THIS TIME.REF ITEM 24.4											
BR700-74-900594 R01	No. 2 Engine - Sb BR700-74-900594 R01 - Ignition - Igniter Plug - Replacement of the Igniter Plugs AT A Specified Interval - Non-Modification Service Bulletin		HRS		1912.8			1609.6			0
			ENC		397		330		0		
			MOS		75.2		20 Sep 2018				
			MSC				-				
(880155)											
Engine											
Notes: SB BR700-74-900594R1 IS NOT REQUIRED DUE TO SB BR700-74-102002 BEING INCORPORATED AT THIS TIME.REF ITEM 24.5											
BR700-74-900649	No. 1 Engine - Sb BR700-74-900649 - Ignition - Igniter Plug - Inspection of the Igniter Plugs AT A Specified Interval - Non-Modification Service Bulletin		HRS		1912.8			1609.6			0
			ENC		397		330		0		
			MOS		75.2		20 Sep 2018				
			MSC				-				
(880156)											
Engine											
Notes: SB BR700-74-900649 IS NOT REQUIRED AT THIS TIME DUE TO SB BR700-74-102002 BEING INCORPORATED AT THIS TIME.SB BR700-74-900649 NEXT DUE IN 1250 FLIGHT HOURS OR AT A/C TT 2859.6REF ITEM 24.4											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-74-900649	No. 2 Engine - Sb BR700-74-900649 - Ignition - Igniter		HRS		1912.8			1609.6			0
	Plug - Inspection of the Igniter Plugs AT A Specified		ENC		397			330			0
	Interval - Non-Modification Service Bulletin		MOS		75.2			20 Sep 2018			
			MSC								
(880156)											
Engine											
Notes: SB BR700-74-900649 IS NOT REQUIRED AT THIS TIME DUE TO SB BR700-74-102002 BEING INCORPORATED AT THIS TIME.SB BR700-74-900649 NEXT DUE IN 1250 FLIGHT HOURS OR AT A/C TT 2859.6REF ITEM 24.5											
BR700-74-900649 R01	No. 1 Engine - Sb BR700-74-900649 R01 - Ignition - Igniter Plug - Inspection of the Igniter Plugs AT A Specified		HRS								0
	Interval - Non-Modification Service Bulletin		ENC								0
			DATE								
			MSC								
(880209)											
Engine											
BR700-74-900649 R01	No. 2 Engine - Sb BR700-74-900649 R01 - Ignition - Igniter Plug - Inspection of the Igniter Plugs AT A Specified		HRS								0
	Interval - Non-Modification Service Bulletin		ENC								0
			DATE								
			MSC								
(880209)											
Engine											
BR700-75-101799 R01	No. 1 Engine - Sb BR700-75-101799 R01 - AIR - Buffer AIR Valve - Introduction of A New Buffer AIR Valve, Changes to the HP4 AIR Tube and the HP2 Restrictor Adapter and Introduction of A New Buffer AIR Valve Setting Procedure, Service Bulletin (Recommended)		HRS								0
			ENC								0
			DATE								
			MSC								
(880239)											
Engine											
BR700-75-101799 R01	No. 2 Engine - Sb BR700-75-101799 R01 - AIR - Buffer AIR Valve - Introduction of A New Buffer AIR Valve, Changes to the HP4 AIR Tube and the HP2 Restrictor Adapter and Introduction of A New Buffer AIR Valve Setting Procedure, Service Bulletin (Recommended)		HRS								0
			ENC								0
			DATE								
			MSC								
(880239)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-75-101831 R02	No. 1 Engine - Sb BR700-75-101831 R02 - AIR - AIR		HRS								0
	Tubes and Fittings - Deactivation of the Turbine Case		ENC								0
	Cooling (TCC) System to Mitigate TCC Valve Reliability		DATE								
	Concerns, Service Bulletin (Optional)		MSC				-				
(880237)											
Engine											
BR700-75-101831 R02	No. 2 Engine - Sb BR700-75-101831 R02 - AIR - AIR		HRS								0
	Tubes and Fittings - Deactivation of the Turbine Case		ENC								0
	Cooling (TCC) System to Mitigate TCC Valve Reliability		DATE								
	Concerns, Service Bulletin (Optional)		MSC				-				
(880237)											
Engine											
BR700-75-101918 R01	No. 1 Engine - BR700-75-101918 R01 - AIR - Turbine		HRS								0
	Case Cooling (TCC) Control Valve System and AIR Tubes		ENC								0
	and Fittings - Deletion of the TCC Control Valve System		DATE								
	and Modification of Adjacent Components, Service		MSC				-				
Bulletin (Optional)											
(880236)											
Engine											
BR700-75-101918 R01	No. 2 Engine - BR700-75-101918 R01 - AIR - Turbine		HRS								0
	Case Cooling (TCC) Control Valve System and AIR Tubes		ENC								0
	and Fittings - Deletion of the TCC Control Valve System		DATE								
	and Modification of Adjacent Components, Service		MSC				-				
Bulletin (Optional)											
(880236)											
Engine											
BR700-75-101999	No. 1 Engine - Sb BR700-75-101999 - AIR - AIR Bleed		HRS		3522.4			0			0
	Control Solenoid - Introduction of A Revised Handling		ENC		727			0			0
	Bleed Valve Solenoid Control Block Without A Control		DATE								
	Valve for the Turbine Case Cooling (TCC) Valve		MSC				-				
(880161)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-75-101999	No. 2 Engine - Sb BR700-75-101999 - AIR - AIR Bleed		HRS		3522.4			0			0
	Control Solenoid - Introduction of A Revised Handling		ENC		727			0			0
	Bleed Valve Solenoid Control Block Without A Control		DATE								
	Valve for the Turbine Case Cooling (TCC) Valve		MSC				-				
(880161)											
Engine											
BR700-75-101999 R01	No. 1 Engine - BR700-75-101999 R01 - AIR - AIR Bleed		HRS								0
	Control Solenoid - Introduction of A Revised Handling		ENC								0
	Bleed Valve Solenoid Control Block Without A Control		DATE								
	Valve for the Turbine Case Cooling (TCC) Valve, Service		MSC				-				
Bulletin (Optional)											
(880233)											
Engine											
BR700-75-101999 R01	No. 2 Engine - BR700-75-101999 R01 - AIR - AIR Bleed		HRS								0
	Control Solenoid - Introduction of A Revised Handling		ENC								0
	Bleed Valve Solenoid Control Block Without A Control		DATE								
	Valve for the Turbine Case Cooling (TCC) Valve, Service		MSC				-				
Bulletin (Optional)											
(880233)											
Engine											
BR700-75-102127	No. 1 Engine - Sb BR700-75-102127 - AIR - AIR Bleed		HRS		1158			2364.4			0
	Control Valve and Stand Pipe - Introduction of High		ENC		239			488			0
	Pressure (Hp) Compressor Handling Bleed Valves (Hbv)		MOS		50.4			15 Oct 2020			
	With Changed Material for the Carbon Bush and the Triple		MSC				-				
Seal Assembly											
(880196)											
Engine											
BR700-75-102127	No. 2 Engine - Sb BR700-75-102127 - AIR - AIR Bleed		HRS		1158			2364.4			0
	Control Valve and Stand Pipe - Introduction of High		ENC		239			488			0
	Pressure (Hp) Compressor Handling Bleed Valves (Hbv)		MOS		50.4			15 Oct 2020			
	With Changed Material for the Carbon Bush and the Triple		MSC				-				
Seal Assembly											
(880196)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-75-900655 PART A	No. 1 Engine - Sb BR700-75-900655 Part A - AIR -		HRS								0
	Handling Bleed Vavle - Inspection of Bleed Vavle AT High		ENC								0
	Pressure (Hp) Copmpressor Stage 5 and Stage 8 for		DATE								
	Deposities on the Inner Piston Surface - Non-Modification		MSC				-				
(880186)		Service Bulletin									
Engine											
BR700-75-900655 PART A	No. 2 Engine - Sb BR700-75-900655 Part A - AIR -		HRS		1182.8			2339.6			0
	Handling Bleed Vavle - Inspection of Bleed Vavle AT High		ENC		243			484			0
	Pressure (Hp) Copmpressor Stage 5 and Stage 8 for		MOS		51.3			17 Sep 2020			
	Deposities on the Inner Piston Surface - Non-Modification		MSC				-				
(880186)		Service Bulletin									
Engine											
BR700-75-900655 PART B	No. 1 Engine - Sb BR700-75-900655 Part B - AIR -		HRS								0
	Handling Bleed Vavle - Inspection of Bleed Vavle AT High		ENC								0
	Pressure (Hp) Copmpressor Stage 5 and Stage 8 for		DATE								
	Deposities on the Inner Piston Surface - Non-Modification		MSC				-				
(880187)		Service Bulletin									
Engine											
BR700-75-900655 PART B	No. 2 Engine - Sb BR700-75-900655 Part B - AIR -		HRS		1182.8			2339.6			0
	Handling Bleed Vavle - Inspection of Bleed Vavle AT High		ENC		243			484			0
	Pressure (Hp) Copmpressor Stage 5 and Stage 8 for		MOS		51.3			17 Sep 2020			
	Deposities on the Inner Piston Surface - Non-Modification		MSC				-				
(880187)		Service Bulletin									
Engine											
BR700-75-900655 PART C	No. 1 Engine - Sb BR700-75-900655 Part C - AIR -		HRS								0
	Handling Bleed Vavle - Inspection of Bleed Vavle AT High		ENC								0
	Pressure (Hp) Copmpressor Stage 5 and Stage 8 for		DATE								
	Deposities on the Inner Piston Surface - Non-Modification		MSC				-				
(880188)		Service Bulletin									
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-75-900655 PART C	No. 2 Engine - Sb BR700-75-900655 Part C - AIR -		HRS		1182.8			2339.6			0
	Handling Bleed Vavle - Inspection of Bleed Vavle AT High		ENC		243			484			0
	Pressure (Hp) Copmpressor Stage 5 and Stage 8 for		MOS		51.3			17 Sep 2020			
	Deposities on the Inner Piston Surface - Non-Modification		MSC				-				
(880188)											
Engine											
BR700-75-900655 PART D	No. 1 Engine - Sb BR700-75-900655 Part D - AIR -		HRS								0
	Handling Bleed Vavle - Inspection of Bleed Vavle AT High		ENC								0
	Pressure (Hp) Copmpressor Stage 5 and Stage 8 for		DATE								
	Deposities on the Inner Piston Surface - Non-Modification		MSC				-				
(880189)											
Engine											
BR700-75-900655 PART D	No. 2 Engine - Sb BR700-75-900655 Part D - AIR -		HRS		1182.8			2339.6			0
	Handling Bleed Vavle - Inspection of Bleed Vavle AT High		ENC		243			484			0
	Pressure (Hp) Copmpressor Stage 5 and Stage 8 for		MOS		51.3			17 Sep 2020			
	Deposities on the Inner Piston Surface - Non-Modification		MSC				-				
(880189)											
Engine											
BR700-75-900673	No. 1 Engine - Sb BR700-75-900673 - AIR - AIR Bleed		HRS								0
	Control Vavle and Stand Pipe - Replacement of Stage 5		ENC								0
	High Pressure (Hp) Compressor Handling Bleed Valves		DATE								
	(Hbv) - Non-Modification Service Bulletin		MSC				DUE**				
(889196)											
Engine											
BR700-75-900673	No. 2 Engine - Sb BR700-75-900673 - AIR - AIR Bleed		HRS								0
	Control Vavle and Stand Pipe - Replacement of Stage 5		ENC								0
	High Pressure (Hp) Compressor Handling Bleed Valves		DATE								
	(Hbv) - Non-Modification Service Bulletin		MSC				DUE**				
(889196)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-75-900673 R01	No. 1 Engine - Sb BR700-75-900673 R01 - AIR - AIR		HRS								0
	Bleed Control Valve and Stand Pipe - Replacement of		ENC								0
	Stage 5 High Pressure (Hp) Compressor Handling Bleed		DATE								
	Valves (Hbv) - Non-Modification Service Bulletin		MSC				-				
(880197)											
Engine											
BR700-75-900673 R01	No. 2 Engine - Sb BR700-75-900673 R01 - AIR - AIR		HRS								0
	Bleed Control Valve and Stand Pipe - Replacement of		ENC								0
	Stage 5 High Pressure (Hp) Compressor Handling Bleed		DATE								
	Valves (Hbv) - Non-Modification Service Bulletin		MSC				-				
(880197)											
Engine											
BR700-75-900673 R02	No. 1 Engine - Sb BR700-75-900673 R02 - AIR - AIR		HRS								0
	Bleed Control Valve and Stand Pipe - Replacement of		ENC								0
	Stage 5 High Pressure (Hp) Compressor Handling Bleed		DATE								
	Valves (Hbv) - Non-Modification Service Bulletin		MSC				-				
(880200)											
Engine											
BR700-75-900673 R02	No. 2 Engine - Sb BR700-75-900673 R02 - AIR - AIR		HRS								0
	Bleed Control Valve and Stand Pipe - Replacement of		ENC								0
	Stage 5 High Pressure (Hp) Compressor Handling Bleed		DATE								
	Valves (Hbv) - Non-Modification Service Bulletin		MSC				-				
(880200)											
Engine											
BR700-75-900673 R03	No. 1 Engine - Sb BR700-75-900673 R03 - Sb BR700-75-		HRS								0
	900673 R03 - AIR - AIR Bleed Control Valve and Stand		ENC								0
	Pipe - Replacement of Stage 5 High Pressure (Hp)		DATE								
	Compressor Handling Bleed Valves (Hbv) - Non-		MSC				-				
Modification Service Bulletin (This Nmsb Sb-BR700-75-											
900673 Is No Longer Required and Can Be Closed)											
(880214)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-75-900673 R03 (890214)	No. 2 Engine - Sb BR700-75-900673 R03 - Sb BR700-75-900673 R03 - AIR - AIR Bleed Control Valve and Stand Pipe - Replacement of Stage 5 High Pressure (Hp) Compressor Handling Bleed Valves (Hbv) - Non-Modification Service Bulletin (This Nmsb Sb-BR700-75-900673 Is No Longer Required and Can Be Closed)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880214)											
Engine											
BR700-77-101866	No. 1 Engine - Sb BR700-77-101866 - Engine Indicating - Nh Speed Signal Attenuating Plug - Introduction of A Nh 1/Rev Signal Attenuating Plug		HRS		3509.1			13.3			0
			ENC		722			5			0
			MOS		122.5			10 Oct 2014			
			MSC				-				
(880049)											
Engine											
BR700-77-101866	No. 2 Engine - Sb BR700-77-101866 - Engine Indicating - Nh Speed Signal Attenuating Plug - Introduction of A Nh 1/Rev Signal Attenuating Plug		HRS		3509.1			13.3			0
			ENC		722			5			0
			MOS		122.5			10 Oct 2014			
			MSC				-				
(880049)											
Engine											
BR700-77-101866 R01	No. 1 Engine - Sb BR700-77-101866 R01 - Engine Indicating - Nh Speed Signal Attenuating Plug - Introduction of A Nh 1/Rev Signal Attenuating Plug		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880151)											
Engine											
BR700-77-101866 R01	No. 2 Engine - Sb BR700-77-101866 R01 - Engine Indicating - Nh Speed Signal Attenuating Plug - Introduction of A Nh 1/Rev Signal Attenuating Plug		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880151)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-77-102159	No. 1 Engine - Sb BR700-77-102159 - Engine Indicating - Oil FIRE Detection Thermocouple - Introduction of A New Turbine Oil FIRE (TOF) Thermocouple		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880201)											
Engine											
BR700-77-102159	No. 2 Engine - Sb BR700-77-102159 - Engine Indicating - Oil FIRE Detection Thermocouple - Introduction of A New Turbine Oil FIRE (TOF) Thermocouple		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880201)											
Engine											
BR700-77-102160	No. 1 Engine - Sb BR700-77-102160 - Engine Indicating - Turbine Gas Temperature Thermocouple - Introduction of New Turbine Gas Temperature (Tgt) Probes		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880202)											
Engine											
BR700-77-102160	No. 2 Engine - Sb BR700-77-102160 - Engine Indicating - Turbine Gas Temperature Thermocouple - Introduction of New Turbine Gas Temperature (Tgt) Probes		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880202)											
Engine											
BR700-78-900332 R02	No. 1 Engine - Sb BR700-78-900332 R02 - Exhaust - Thrust Reverser Unit (Tru) - Leak Check With Subsequent RE-Torque of the Direction Control Unit (Dcu) Double Ended Unions and Attached B-Nuts - Non-Modification Service Bulletin		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(880191)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-78-900332 R02	No. 2 Engine - Sb BR700-78-900332 R02 - Exhaust - Thrust Reverser Unit (Tru) - Leak Check With Subsequent RE-Torque of the Direction Control Unit (Dcu) Double Ended Unions and Attached B-Nuts - Non-Modification Service Bulletin		HRS								0
			ENC								0
			DATE								
			MSC				-				
(880191)											
Engine											
BR700-79-101718	No. 1 Engine - Sb BR700-79-101718 - Oil - Engine Lubricating Oil Pump Unit (Pressure and Scavenge Pumps) - Introduction of A New Sealing Plate		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880003)											
Engine											
BR700-79-101718	No. 2 Engine - Sb BR700-79-101718 - Oil - Engine Lubricating Oil Pump Unit (Pressure and Scavenge Pumps) - Introduction of A New Sealing Plate		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880003)											
Engine											
BR700-79-101829	No. 1 Engine - Sb BR700-79-101829 - Oil - Oil Debris Monitoring System Magnetic and Electro Magnetic Chip Detectors - Introduction of SELF Closing Valve With Molded-In Seal Ring		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880070)											
Engine											
BR700-79-101829	No. 2 Engine - Sb BR700-79-101829 - Oil - Oil Debris Monitoring System Magnetic and Electro Magnetic Chip Detectors - Introduction of SELF Closing Valve With Molded-In Seal Ring		HRS		3522.4			0			0
			ENC		727			0			0
			DATE								
			MSC				-				
(880070)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
BR700-79-102074	No. 1 Engine - Sb BR700-79-102074 - Oil - Oil		HRS		3522.4			0			0
	Temperature Transducer - Introduction of A New Duplex		ENC		727			0			0
	Oil Temperature Transducer		DATE								
			MSC				-				
(880167)											
Engine											
BR700-79-102074	No. 2 Engine - Sb BR700-79-102074 - Oil - Oil		HRS		3522.4			0			0
	Temperature Transducer - Introduction of A New Duplex		ENC		727			0			0
	Oil Temperature Transducer		DATE								
			MSC				-				
(880167)											
Engine											
BR700-80-900634	No. 1 Engine - Sb BR700-80-900634 - Replacement of		HRS		1508.2			2014.2			0
	Starter AIR Valves With Potential of Internal Freezing		ENC		311			416			0
			MOS		63.2			20 Sep 2019			
			MSC				-				
(880163)											
Engine											
BR700-80-900634	No. 2 Engine - Sb BR700-80-900634 - Replacement of		HRS		1508.2			2014.2			0
	Starter AIR Valves With Potential of Internal Freezing		ENC		311			416			0
			MOS		63.2			20 Sep 2019			
			MSC				-				
(880163)											
Engine											
90 - Supplemental Type Certificates/Modifications											
ST00892LA	STC ST00892LA Emergency Vision Assurance System		HRS		.4			3522			0
	(EVAS)		AFL		1			726			0
			DATE		74 d			13 Oct 2024			
			MSC				O/C				
(900180)											
Airframe											
ST04027AT-D	STC ST04027AT-D - SATCOM Direct Router (SDR)		HRS		485.9			3036.5			0
	Installation		AFL		97			630			0
			MOS		24.8			01 Dec 2022			
			MSC				-				
(900007)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ST04252AT-D (900001) Airframe	STC ST04252AT-D - Aircraft Interior		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		122.5			10 Oct 2014			
			MSC				-				
ST04254AT-D (900004) Airframe	STC ST04254AT-D - Broad Band Multi-Link (Bbml) Highspeed Data System Viasat Mobile Terminal Vmt-1500 -03		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		122.5			10 Oct 2014			
			MSC				-				
ST04277AT-D (900002) Airframe	STC ST04277AT-D - Lightning Sensor		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		122.5			10 Oct 2014			
			MSC				-				
92 - -											
920700 ^U Airframe	ASC Validation Document		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		98.9			29 Sep 2016			
			MSC				-				
Notes: ***VALIDATION*** CMP G650 920700 AIRFRAME COCKPIT AIR DUCTING VELOCITY REDUCTION											
94 - Cabin Service Bulletins											
941400 (941400) Airframe	Sb 941400 - FAA NEXTGEN Program Mandate: ADS-B Out Compliance		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		63			26 Sep 2019			
			MSC				-				
941401 (941401) Airframe	Sb 941401 - FAA NEXTGEN Program Mandate: FANS 1/A+ Compliance		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		63			26 Sep 2019			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CSB008	Sb Csb-6008 - CSB008 -Cabin Systems (ATA 44)		HRS		3133.7			388.7			0
	Advanced Cabin Server (Acs) System Software Upgrade		AFL		652			75			0
			MOS		111.4			15 Sep 2015			
			MSC				-				
(940080)											
Airframe											
CSB009	Ce-Csb-6009 - CSB009 - Gulfstream Cabin Management		HRS		3133.7			388.7			0
	Systems (ATA 44) Gcms Firmware Upgrade		AFL		652			75			0
			MOS		111.4			15 Sep 2015			
			MSC				-				
(940090)											
Airframe											
CSB010	Ce-Csb-6010 - Csb 010 - Cabin Systems (ATA 44) -		HRS		2755.9			766.5			0
	Advanced Cabin Server (Acs) System Software Upgrade		AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
(940100)											
Airframe											
Notes: PN: ACS-04-001 SN: ACS #1: 00684, ACS #2:..... REF. CE-CSB-6010 REV. --											
CSB011	Ce-Csb-6011 - CSB011 - Cabin Systems (ATA 44)		HRS		2755.9			766.5			0
	Gulfstream Cabin Management System (Gcms) Firmware		AFL		561			166			0
	Update		MOS		98.9			30 Sep 2016			
			MSC				-				
(940110)											
Airframe											
CSB012	Csb-6012 - Cabin Systems (ATA 44) - Gulfstream Cabin		HRS		2312.5			1209.9			0
	Management System (Gcms) Firmware Update		AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
(940120)											
Airframe											
Notes: REF G650 CE-CSB-6012 REV -											
CSB013	Ce-Csb-6013 - CSB013 - Cabin Systems (ATA 44) -		HRS		1912.8			1609.6			0
	Advanced Cabin Server (Acs) (Gen 4) - Cabinviewtm		AFL		397			330			0
	Software Upgrade		MOS		75			25 Sep 2018			
			MSC				-				
(940130)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CSB014	Csb-6014 - Cabin Systems (ATA 44) - Gulfstream Cabin Management System (Gcms 1) Firmware Update		HRS		3522.4			0		0	
			AFL		727			0		0	
			DATE								
			MSC				-				
(940140)											
Airframe											
CSB015	Ce-Csb-6015 - CSB015 - Cabin Systems (ATA 44) - Advanced Cabin Server (Acs) (Gen 4) Cabinview Software Upgrade		HRS		3522.4			0		0	
			AFL		727			0		0	
			DATE								
			MSC				-				
(940150)											
Airframe											
CSB017	Ce-Csb-6017 - Cabin Systems (ATA 44) - Gulfstream Cabin Management System - (Gcms 1) Firmware Update		HRS		3522.4			0		0	
			AFL		727			0		0	
			DATE								
			MSC				-				
(940170)											
Airframe											
CSB019	Ce-Csb-6019 - Cabin Systems (ATA 44) - Gen 1 to Gen 2 Controller Upgrade		HRS		113.9			3408.5		0	
			AFL		36			691		0	
			DATE		421 d		01 Nov 2023				
			MSC				-				
(940190)											
Airframe											
CSB021	Ce-Csb-6021 - Cabin Systems (ATA 44) - Advanced Cabin Server (Acs) (Gen 4) Cabinview Software Upgrade V2.2.3		HRS		1158			2364.4		0	
			AFL		239			488		0	
			DATE		1512 d		05 Nov 2020				
			MSC				-				
(940210)											
Airframe											
CSB022	Ce-Csb-6022 - Gulfstream Cabin Management System (Gcms 1) Firmware Update V1.10.6		HRS		3522.4			0		0	
			AFL		727			0		0	
			DATE								
			MSC				-				
(940220)											
Airframe											
CSB023	CSB023 - Gulfstream Cabin Management System - (Gcms 2) Firmware Update V2.2.3		HRS							0	
			AFL							0	
			DATE								
			MSC				-				
(940230)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CSB024	CSB024 - Gulfstream Cabin Management System (Gcms 1) Firmware Update V1.10.7		HRS		1158			2364.4	0		0
			AFL		239			488	0		0
			DATE		1512 d			05 Nov 2020			
			MSC				-				
(940240)											
Airframe											
CSB025	CSB025 - Ce-Csb-6025 - Gulfstream Cabin Management System (Gcms 2) - Firmware Update V2.3.0		HRS								0
			AFL								0
			DATE								
			MSC				-				
(940250)											
Airframe											
CSB026	CSB026 - Ce-Csb-6026 - Gulfstream Cabin Management System (Gcms 2) Firmware Update V2.4.0, Cabin Service Bulletin (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(940260)											
Airframe											
CSB027	CSB027 - Ce-Csb-6027 - Gulfstream Cabin Management System - (Gcms 1) Firmware Update V1.10.9, Cabin Service Bulletin (Recommended)		HRS		485.9			3036.5			0
			AFL		97			630			0
			DATE		759 d			28 Nov 2022			
			MSC				-				
(940270)											
Airframe											
CSB028	Ce-Csb-6028 - CSB028 - Cabin Systems - Gulfstream Cabin Management System (Gcms 2) Firmware Update, Cabin Service Bulletin (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(940280)											
Airframe											
CSB029	Ce-Csb-6029 - CSB029 - Cabin Systems - Advanced Cabin Server (Acs) (Gen 4) Cabin View Software Update V2.2.5, Cabin Service Bulletin (Cancelled)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(940290)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CSB029A	Ce-Csb-6029A - CSB029A - Cabin Systems - Advanced Cabin Server (Acs) (Gen 4) Cabin View Software Update V2.2.5, Cabin Service Bulletin (Recommended)		HRS		485.9			3036.5			0
			AFL		97		630		0		
			DATE		756 d		01 Dec 2022				
			MSC								
(940291)											
Airframe											
CSB030	Ce-Csb-6030 - CSB030 - Gulfstream Cabin Management System (Gcms 2) Firmware Update, Cabin Service Bulletin (Recommended)		HRS								0
			AFL						0		
			DATE								
			MSC								
(940300)											
Airframe											
CSB031	CSB031 - Ce-Csb-6031 - Cabin Systems - Gulfstream Cabin Management System (Gcms 2) Firmware Update V2.4.9, Cabin Service Bulletin (Recommended)		HRS								0
			AFL						0		
			DATE								
			MSC								
(940310)											
Airframe											
CSB-2015-007	Sb Csb-2015-007 - Cabin System Firmware Update V1.9.4		HRS		3522.4			0			0
			AFL		727		0		0		
			DATE								
			MSC								
(940070)											
Airframe											
MP-14-6511	Sb Mp-14-6511 - Microwave (Retrofit Program Rev T) (RD -15-6006)		HRS		2755.9			766.5			0
			AFL		561		166		0		
			MOS		98.9		29 Sep 2016				
			MSC								
(949001)											
Airframe											
MP-15-6502	Sb Mp-15-6502 - Pocket Door Noise Issue - Motor and Gears Drive (Retrofit Program)		HRS		2755.9			766.5			0
			AFL		561		166		0		
			MOS		99.2		20 Sep 2016				
			MSC								
(949012)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
MP-15-6504 R01	Sb Mp-15-6504 R01 - Aft Lav Door (Retrofit Program) (Mp -15-6504 Rev A)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.1			23 Sep 2016			
	(949101)		MSC					-			
Airframe											
Notes: ALL PORTIONS OF MP-15-6504 HAVE BEEN COMPLIED WITH EXCEPT STIFFENER MOD. DUE TO THE SIZE OF THE AFT LAV DOOR STIFFENER MOD CANNOT BE COMPLIED WITH.											
MP-15-6505	Sb Mp-15-6505 - Fwd Lh Lav & Crew Door Latches (Retrofit Program)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			18 Sep 2016			
	(949011)		MSC					-			
Airframe											
MP-15-6510 RA	Sb Mp-15-6510 Ra - Pocket Door Enflite Sb 52-10-02-014 Partial Compliance, Mods 1, 2, 3, 5 and 6 (Mp-15-6510 Rev A)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			21 Sep 2016			
	(949053)		MSC					-			
Airframe											
MP-15-6510.2	Sb Mp-15-6510.2 - Sb 52-10-02-013 - Motion Controller		HRS		2755.9			766.5			0
			AFL		561			166			0
	(949020)		MOS		99.2			21 Sep 2016			
	Airframe		MSC					-			
MP-15-6510.3	Sb Mp-15-6510.3 - Sb 52-10-02-015 - RAIL Replacement		HRS		2755.9			766.5			0
			AFL		561			166			0
	(949021)		MOS		99.2			21 Sep 2016			
	Airframe		MSC					-			
MP-15-6510.4	Sb Mp-15-6510.4 - Pocket Door Descender (Mp-15-6510)		HRS		2755.9			766.5			0
			AFL		561			166			0
	(949023)		MOS		99.2			20 Sep 2016			
	Airframe		MSC					-			
MP-15-6510.5	Sb Mp-15-6510.5 - Pocket Door Jamb		HRS		2755.9			766.5			0
			AFL		561			166			0
	(949024)		MOS		99			27 Sep 2016			
	Airframe		MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
MP-15-6512 (949018) Airframe	Sb Mp-15-6512 - Sb 52-10-02-012 - Descender Reel		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			21 Sep 2016			
			MSC				-				
MP-15-6514 (949022) Airframe	Sb Mp-15-6514 - Doors & Drawers Mechanism (Mp 15-6514)		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87.1			23 Sep 2017			
			MSC				-				
MP-16-6502.1 (949032) Airframe	Sb Mp-16-6502.1 - Sub-Woofer Wire Harness (No: Vmp-16-6502)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99			26 Sep 2016			
			MSC				-				
MP-16-6502.2 (949033) Airframe	Sb Mp-16-6502.2 - Passenger Service Unit (Psu) Lanyard and Panel Adjusters (No: Vmp-16-6502)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.1			23 Sep 2016			
			MSC				-				
MP-16-6505 (949036) Airframe	Sb Mp-16-6505 - Exit Signs (Mp-16-6505)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
Notes: COMPLIED WITH PER MP-16-6505 AND GDM732001020-501 REV (-)											
MP-16-6506 (949037) Airframe	Sb Mp-16-6506 - Galley Pullout Work Surface (Mp-16-6506)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			19 Sep 2016			
			MSC				-				
MP-16-6508 (949039) Airframe	Sb Mp-16-6508 - Aft Lavatory Ashtray (Mp 16-6508)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
Notes: COMPLIED WITH PER (MP 16-6508)											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
MP-16-6509 (949042) Airframe	Sb Mp-16-6509 - Credenza to Sidewall Interface (Mp 16-6509)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			17 Sep 2016			
			MSC				-				
MP-16-6510 (949043) Airframe	Sb Mp-16-6510 - Glass Rack Door Rattles (Mp 16-6510)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
Notes: COMPLIED WITH PER GDM324001028-501 REV (-) AND MP-16-6510.											
MP-16-6511 (949044) Airframe	Sb Mp-16-6511 - Acoustic Headliner (Mp 16- 6511)		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
MP-16-6512 (949045) Airframe	Sb Mp-16-6512 - Doors & Drawers: Trash Can Clips (Mp 16-6512)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			17 Sep 2016			
			MSC				-				
MP-16-6517 (949040) Airframe	Sb Mp-16-6517 - Decorative Coating and Covering Requirements (Mp-16-6517)		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
MP-16-6518 (949047) Airframe	Sb Mp-16-6518 - Cabin Acoustics Enhancement (Mp-16-6518)		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			27 Sep 2017			
			MSC				-				
MP-16-6520 (949049) Airframe	Sb Mp-16-6520 - Fwd Crew Door Pawl (Mp-16-6520)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			18 Sep 2016			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
MP-16-6523	Sb Mp-16-6523 - 60 HZ Dual Capacity Increase - (Mp-16-6523)		HRS		2312.5			1209.9		0	
			AFL		479		248		0		
			MOS		87		27 Sep 2017				
			MSC			-					
(949051)											
Airframe											
Notes: REFERENCE, GPM504001526-501 REV. A, GCE493000025 REV. C, GCD000003156 REV. D, GPE498000001 REV. J, GPM504001526-501A2 REV. (-), GPM504001526-501A4 REV. (-)											
MP-16-6524	Sb Mp-16-6524 - Manual Door Switch - (Mp-16-6524)		HRS		2755.9			766.5		0	
			AFL		561		166		0		
			MOS		99.1		22 Sep 2016				
			MSC			-					
(949052)											
Airframe											
MP-16-6525	Sb Mp-16-6525 - Aft Lav Door Enhancement Modification (Aft Lav Closet/Toilet Light Bleed) (Mp-16-6525)		HRS		3522.4			0		0	
			AFL		727		0		0		
			DATE								
			MSC			-					
(949054)											
Airframe											
MP-16-6526	Sb Mp-16-6526 - Aft Lav Door Enhancement Modification (Mp 16-6526)		HRS		3522.4			0		0	
			AFL		727		0		0		
			DATE								
			MSC			-					
(949055)											
Airframe											
MP-16-6529	Sb Mp-16-6529 - Rfu Super Galley - Mp-16-6529		HRS		3522.4			0		0	
			AFL		727		0		0		
			DATE								
			MSC			-					
(949059)											
Airframe											
MP-17-6501	Sb Mp-17-6501 - Aft Lavatory Door Magnetic Bumper Assembly - Hanging Mirror Configuration - Mp-17-6501		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		93.8		01 Mar 2017				
			MSC			-					
(949062)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
MP-17-6510	Sb Mp-17-6510 - Flight Control Computers (FCC) V7.1 Software Update		HRS		3522.4			0		0	
			AFL		727		0		0		
			DATE								
			MSC			-					
(949067)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
MP-17-6512 (949068) Airframe	Sb Mp-17-6512 - Emed Stop Bolts		HRS		1841.9			1680.5			0
			AFL		384			343			0
			MOS		73.8			01 Nov 2018			
			MSC					-			
MP-20-6501 (949071) Airframe	Sb Mp-20-6501 - G650 AIR Data Probe		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.4			13 Oct 2021			
			MSC					-			
95 - APU/Eng Service Bulletins											
2704554-49-2393 R01 (952394) APU	APU - Sb 2704554-49-2393 R01 - Airborne Auxiliary Power - Starter Motor Assembly - Modification of the Starter Motor Assembly from Pn 2704554-2, Series 2 to Pn 2704554-3, Series 1. the Instructions Are for the Replacement of the Brush Indicator Assembly and the Brush Access Cover Assembly, Service Bulletin (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC				E/OVH**				
49-7933 R05 (957935) APU	APU - Sb 49-7933 R05 - Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils		HRS		1704			0			0
			APUS		0			0			0
			MOS		106.9			29 Jan 2016			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
49-7933 R06 (957936) APU	APU - Sb 49-7933 R06 - Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils		HRS		1704			0			0
			APUS		0			0			0
			MOS		93.4			13 Mar 2017			
			MSC					-			
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
49-7933 R08 (957938) APU	APU - Sb 49-7933 R08 - Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils		HRS		1704			0			0
			APUS		0			0			0
			DATE								
			MSC				DUE**				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
49-8252 (958252) APU	APU - Sb 49-8252 - Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial Apus		HRS		1704			0			0
			APUS		0			0			0
			DATE								
			MSC				-				
APU-49 R12 (950011) APU	APU - Sil APU-49 R12 - Sil APU-49 R12 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus)		HRS								0
			APUS								0
			DATE								
			MSC				-				
APU-49 R13 (950012) APU	APU - Sil APU-49 R13 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC				-				
RE220/HGT400- 49-8383 (958383) APU	APU - Sb RE220/HGT400-49-8383 - Sb RE220/HGT400- 49-8383 - Airborne Auxiliary Power - Gas Turbine Engine - Inspect Specific Population of HGT400[G], RE220[Gvi] and RE220[Gx] Engines for Duplex Ball Bearing Damage Prevention		HRS								0
			APUS								0
			DATE								
			MSC				-				
RE220-49-8085 (958085) APU	APU - Sb RE220-49-8085 - Airborne Auxiliary Power - Gas Turbine Engine - Replace the (Return) Oil Transfer Tube Assembly, Pn WE3881884-1 With Oil Return Tube, Pn WE70721494-1, and (Supply) Oil Transfer Tube Assembly, Pn WE3881884-2 With Oil Supply Tube, Pn WE70721495-1		HRS		1704			0			0
			APUS		0			0			0
			MOS		107			25 Jan 2016			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
RE220-49-8120	APU - Sb RE220-49-8120 - Airborne Auxiliary Power - Gas Turbine Engine - Remove/Replace Ignition Exciter, Pn WE3876295-6 With Pn WE3876295-7, on the RE220 [Gvi] APU		HRS		1704			0			0
			APUS		0			0			0
			DATE								
			MSC				-				
(958120)											
APU											

97 - Aircraft Service Changes											
970440 ^U	ASC 044 Wing Link Replacement	HRS	3396.7			125.7				0	
		AFL	702			25				0	
		MOS	119.8			02 Jan 2015					
		MSC			-						
Airframe											
ASC001B	ASC 001B - G650 Dataplate - Installation	HRS	3522.4			0				0	
		AFL	727			0				0	
		MOS	128.2			21 Apr 2014					
		MSC			-						
(970012)											
Airframe											
ASC002A	ASC002A - Communications (ATA 23) Communication Management Function (Cmf) ARINC Direct (SM) Datalink Service Provider	HRS	3522.4			0				0	
		AFL	727			0				0	
		DATE									
		MSC			-						
(970021)											
Airframe											
ASC003A	ASC003A - Communications (ATA 23) Communication Management Function (Cmf) SATCOM Direct SM Datalink Service Provider	HRS	3506.4			16				0	
		AFL	721			6				0	
		MOS	122.4			14 Oct 2014					
		MSC			-						
(970031)											
Airframe											
ASC003B	ASC003B - Communication(ATA 23) - Communication Management Function (Cmf) SATCOM Direct Datalink Service Provider, Aircraft Service Change (Optional)	HRS								0	
		AFL								0	
		DATE									
		MSC			-						
(970032)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC004 (970040) Airframe	ASC004 - Information Systems (ATA 46) Aircraft Health and Trend Monitoring System (Ahtms) - Cell Phone Data Transmission Option		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		124.3		18 Aug 2014				
			MSC			-					
ASC004A (970041) Airframe	ASC004A - Information Systems (ATA 46) - Aircraft Health and Trend Monitoring System (Ahtms) - Cell Phone Data Transmission Option		HRS		3522.4			0			0
			AFL		727		0		0		
			DATE								
			MSC			-					
ASC004B (970042) Airframe	ASC004B - Information Systems (ATA 46) - Aircraft Health and Trend Monitoring System (Ahtms) – Cell Phone Data Transmission Option		HRS								0
			AFL							0	
			DATE								
			MSC			-					
ASC004C (970043) Airframe	ASC 004C - Information Systems (ATA 46) - Aircraft Health and Trend Monitoring System (Ahtms) - Cell Phone Data Transmission Option (Incorp Suspended By Mol-23-0001), Aircraft Service Change (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC			-					
ASC005B (970052) Airframe	ASC005B - Navigation (ATA 34) Runway Awareness Advisory System (Raas) - Installation		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		124.3		18 Aug 2014				
			MSC			-					
ASC005C (970053) Airframe	ASC005C - Navigation (ATA 34) - Runway Awareness Advisory System (Raas) Installation, Aircraft Service Change (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC			-					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC006B (970062) Airframe	ASC006B - Navigation (ATA 34) Lightning Sensor System (Lss) - Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		122.5			09 Oct 2014			
			MSC				-				
ASC006C (970063) Airframe	ASC006C - Navigation (ATA 34) - Lightning Sensor System (Lss) - Installation		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC006D (970064) Airframe	ASC006D - Navigation (ATA 34) - Lightning Sensor System (Lss) - Installation		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC007A (970071) Airframe	ASC007A - Navigation (ATA 34) Predictive Windshear (Pws) - Activation		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		122.6			07 Oct 2014			
			MSC				-				
ASC008A (970081) Airframe	ASC008A - Indicating / Recording (ATA 31) Xm Weather System - Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		123.1			24 Sep 2014			
			MSC				-				
ASC008A-CN (979081) Airframe	ASC008A-CN - Indicating/Recording (ATA 31) - Xm Weather System - Installation (New Installations Discontinued See All Mol-22-0016), Aircraft Service Change (Cancelled)		HRS								0
			AFL								0
			DATE								
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC010 PART 1	ASC010 Part 1 - Aircraft General (ATA 4) European Aviation Safety Agency (EASA) Certification BASIC Requirements		HRS		3522.4			0		0	
			AFL		727		0		0		
			DATE								
			MSC				-				
(970100)											
Airframe											
ASC010 PART 2	ASC010 Part 2 - Aircraft General (ATA 4) European Aviation Safety Agency (EASA) Certification BASIC Requirements		HRS		3522.4			0		0	
			AFL		727		0		0		
			DATE								
			MSC				-				
(970101)											
Airframe											
ASC010A PART 1	ASC010A Part 1 - Aircraft General (ATA 04) - European Aviation Safety Agency (EASA) Certification BASIC Requirements (Fqms In Lbs)		HRS							0	
			AFL						0		
			DATE								
			MSC				-				
(970102)											
Airframe											
ASC010A PART 2	ASC010A Part 2 - Aircraft General (ATA 04) - European Aviation Safety Agency (EASA) Certification BASIC Requirements (Fqms In Kgs)		HRS							0	
			AFL						0		
			DATE								
			MSC				-				
(970103)											
Airframe											
ASC014 PART 1	ASC014 Part 1 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		119.4		15 Jan 2015				
			MSC				-				
(970140)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC014 PART 2	ASC014 Part 2 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		119.4		15 Jan 2015				
			MSC				-				
(970141)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC014A PART 1	ASC014A Part 1 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		118.3			17 Feb 2015			
			MSC								
(970142)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC014A PART 2	ASC014A Part 2 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		118.3			17 Feb 2015			
			MSC								
(970143)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC014B PART 1	ASC014B Part 1 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		104.7			05 Apr 2016			
			MSC								
(970144)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC014B PART 2	ASC014B Part 2 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		104.7			05 Apr 2016			
			MSC								
(970145)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC014C PART 1	ASC014C Part 1 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		97.9			28 Oct 2016			
			MSC								
(970146)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC014C PART 2	ASC014C Part 2 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		97.9			28 Oct 2016			
			MSC								
(970147)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC014D PART 1 (970148) Airframe	ASC014D Part 1 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC014D PART 2 (970149) Airframe	ASC014D Part 2 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC015 (970150) Airframe	ASC015 - Equipment and Furnishings (ATA 25) Emergency Vision Assurance System (EVAS) - Provisions Installation		HRS		3396.7			125.7			0
			AFL		702			25			0
			MOS		120			26 Dec 2014			
			MSC				-				
ASC016 (970160) Airframe	ASC016 - Engine Fuel and Control (ATA 73), Engine Electronic Controller - K7.1.3 Software Upgrade		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
ASC018 (970180) Airframe	ASC018 - Indicating / Recording (ATA 31) Planeview li Avionics Enhancement		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		121.9			30 Oct 2014			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC018A (970181) Airframe	ASC018A - Indicating / Recording (ATA 31) Planeview li Avionics Enhancement		HRS		3396.7			125.7			0
			AFL		702			25			0
			MOS		119.7			04 Jan 2015			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC025 (970250) Airframe	ASC025 - Equipment and Furnishings (ATA 25), Flashlights - Replacement		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.4			15 Sep 2015			
			MSC				-				
ASC026 (970260) Airframe	ASC026 - Placards and Markings (ATA 11) - Airport Access - 74,900 Pound Weight Limitation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		97.9			28 Oct 2016			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC026A (970261) Airframe	ASC026A - Placards and Markings (ATA 11) - Airport Access 74,900 Pound Weight Limitation		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC027 (970270) Airframe	ASC027 - Placards and Markings (ATA 11) - Airport Access - 90,000 Pound Weight Limitation		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		124.3			18 Aug 2014			
			MSC				-				
ASC027A (970271) Airframe	ASC027A - Placards and Markings (ATA 11) - Airport Access - 90,000 Pound Weight Limitation		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC028 (970280) Airframe	ASC028 - Placards and Markings (ATA 11) - Airport Access - 95,000 Pound Weight Limitation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		97.9			28 Oct 2016			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC028A (970281) Airframe	ASC028A - Placards and Markings (ATA 11) - Airport Access - 95,000 Pound Weight Limitation		HRS		3522.4			0			0
			AFL		727			0		0	
			DATE								
			MSC				-				
ASC030 (970300) Airframe	ASC030 - Placards and Markings (ATA 11) - Maximum Zero Fuel Weight Reduction - 60,000 Pounds		HRS		3522.4			0			0
			AFL		727			0		0	
			DATE								
			MSC				-				
ASC033 (970330) Airframe	ASC033 - Equipment and Furnishing (ATA 25) Battery Charger Circuit Breaker Protective Covers Installation		HRS		3509.1			13.3			0
			AFL		722			5		0	
			MOS		122.6			07 Oct 2014			
			MSC				-				
ASC035 (970350) Airframe	ASC035 - Landing Gear (ATA 32) Nose Wheel Steering Control Unit - Upgrade		HRS		3396.7			125.7			0
			AFL		702			25		0	
			MOS		120			27 Dec 2014			
			MSC				-				
ASC036 (970360) Airframe	ASC036 - Navigation (ATA 34) - Automatic Dependent Surveillance-Broadcast (ADS-B) Out Version 2 Installation		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		102.4			15 Jun 2016			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC036A (970361) Airframe	ASC036A - Navigation (ATA 34) - Automatic Dependent Surveillance - Broadcast (ADS-B) Out Version 2INSTALLATION		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		100.1			24 Aug 2016			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC036B (970362) Airframe	ASC036B - Navigation (ATA 34) - Automatic Dependent Surveillance-Broadcast (ADS-B) Out Version 2 Installation		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75			25 Sep 2018			
			MSC				-				
ASC037 (970370) Airframe	ASC037 - Flight Controls (ATA 27) - FCC Software Update		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		101.9			29 Jun 2016			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC037A (970371) Airframe	ASC037A - Flight Controls (ATA 27) - FCC Software Update		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
ASC038 (970380) Airframe	ASC038 - Indicating / Recording (ATA 31) - Planeview li Avionics Enhancement		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		96.1			22 Dec 2016			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC038A (970381) Airframe	ASC038A - Indicating / Recording (ATA 31) - Planeview li Avionics Enhancement		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
ASC038B (970382) Airframe	ASC038B - Indicating / Recording (ATA 31) - Planeview li Avionics Enhancement		HRS		485.9			3036.5			0
			AFL		97			630			0
			DATE		808 d			10 Oct 2022			
			MSC				-				
ASC040 (970400) Airframe	ASC040 - Hydraulic Power (ATA 29) Hydraulic Replenisher Tank - Placard Installation		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.4			14 Sep 2015			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC042 (970420) Airframe	ASC042 - Structure (ATA 53), Fuselage Station (FS) 1083 - Gusset Installation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		114			26 Jun 2015			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC042A (970421) Airframe	ASC042A - Fuselage Structure (ATA 53) Fuselage Station (FS) 1083 - Gusset Installation		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.3			18 Sep 2015			
			MSC				-				
ASC043A (970431) Airframe	ASC043A - Placards (ATA 11) - Engine Operating Limits - Placard Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		124.2			20 Aug 2014			
			MSC				-				
ASC046 (970460) Airframe	ASC046 - Placards and Markings (ATA 11) - Maximum Zero Fuel Weight Reduction 59,500 Pounds		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC047 (970470) Airframe	ASC047 - Hydraulic Power (ATA 29) - Ecology Bottle Vent Drain Line - Installation		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		125.1			24 Jul 2014			
			MSC				-				
ASC048 PART 2 (970481) Airframe	ASC048 Part 2 - Flight Controls (ATA 27), Spoiler Joint Anti-Rotation Retention Washer - Installation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		86			26 Oct 2017			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC048A PART 2 (970483) Airframe	ASC048A Part 2 - Flight Controls (ATA 27) - Spoiler Joint		HRS		3522.4			0			0
	Anti-Rotation Retention Washer - Installation		AFL		727			0			0
			DATE								
			MSC				-				
ASC049A PART 1 (970493) Airframe	ASC049A Part 1 - Equipment and Furnishings (ATA 25)		HRS		3133.7			388.7			0
	Cockpit Improvements - Installation		AFL		652			75			0
			MOS		111.3			17 Sep 2015			
			MSC				-				
ASC049A PART 2 (970494) Airframe	ASC049A Part 2 - Equipment and Furnishings (ATA 25)		HRS		3133.7			388.7			0
	Cockpit Improvements - Installation		AFL		652			75			0
			MOS		111.3			17 Sep 2015			
			MSC				-				
ASC049A PART 3 (970495) Airframe	ASC049A Part 3 - Equipment and Furnishings (ATA 25)		HRS		3133.7			388.7			0
	Cockpit Improvements - Installation		AFL		652			75			0
			MOS		111.3			17 Sep 2015			
			MSC				-				
ASC049B PART 1 (970496) Airframe	ASC049B Part 1 - Equipment and Furnishings (ATA 25) -		HRS		3522.4			0			0
	Cockpit Improvements - Installation		AFL		727			0			0
			DATE								
			MSC				-				
ASC049B PART 2 (970497) Airframe	ASC049B Part 2 - Equipment and Furnishings (ATA 25) -		HRS		3522.4			0			0
	Cockpit Improvements - Installation		AFL		727			0			0
			DATE								
			MSC				-				
ASC049B PART 3 (970498) Airframe	ASC049B Part 3 - Equipment and Furnishings (ATA 25) -		HRS		3522.4			0			0
	Cockpit Improvements - Installation		AFL		727			0			0
			DATE								
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC050 (970500) Airframe	ASC050 - Doors (ATA 52), Fuel Servicing Door - Refueling Decal and Door Hold Open Installation		HRS		3133.7			388.7			0
			AFL		652		75		0		
			MOS		111.3		18 Sep 2015				
			MSC			-					
ASC050A (970501) Airframe	ASC050A - Doors (ATA 52), Fuel Servicing Door - Refueling Decal and Door Hold Open Installation		HRS		3522.4			0			0
			AFL		727		0		0		
			DATE								
			MSC			-					
ASC051 (970510) Airframe	ASC051 - Electrical Power (ATA 24) - Secondary Power Distribution - System (Spds) Software Update		HRS		2312.5			1209.9			0
			AFL		479		248		0		
			MOS		87		26 Sep 2017				
			MSC			-					
Notes: REF G650 ASC 51											
ASC051A (970511) Airframe	ASC051A - Electrical Power (ATA 24) - Secondary Power Distribution System (Spds) Software Update		HRS		1912.8			1609.6			0
			AFL		397		330		0		
			MOS		75.3		17 Sep 2018				
			MSC			-					
ASC052 (970520) Airframe	ASC052 - Doors (ATA 52) Main Entrance Door - Noise Reduction Modification		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		117.5		12 Mar 2015				
			MSC			-					
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC052A (970521) Airframe	ASC052A - Main Entrance Door - Noise Reduction Modification		HRS		3133.7			388.7			0
			AFL		652		75		0		
			MOS		111.3		18 Sep 2015				
			MSC			-					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC052B	ASC052B - Doors (ATA 52) - Main Entrance Door Noise Reduction Modification		HRS		2755.9			766.5		0	
			AFL		561		166		0		
			MOS		99.2		19 Sep 2016				
			MSC			-					
(970522)											
Airframe											
Notes: *** PREVIOUSLY COMPLIED WITH AT GAC SAVANNAH ON W.O. 431097 ITEM 5.31 ON 09/18/15. ***											
ASC053 PART 1	ASC053 Part 1 - Doors (ATA 52) Main Entrance Door - Bottom Folding Step Mechanism and Airstair Modifications		HRS		3133.7			388.7		0	
			AFL		652		75		0		
			MOS		111.4		15 Sep 2015				
			MSC			-					
(970530)											
Airframe											
ASC053 PART 3	ASC053 Part 3 - Doors (ATA 52) Main Entrance Door - Bottom Folding Step Mechanism and Airstair Modifications		HRS		3133.7			388.7		0	
			AFL		652		75		0		
			MOS		111.3		18 Sep 2015				
			MSC			-					
(970532)											
Airframe											
ASC054	ASC054 - Equipment and Furnishings (ATA 25) Emergency Vision Assurance System (EVAS) - Installation		HRS		3396.7			125.7		0	
			AFL		702		25		0		
			MOS		120		26 Dec 2014				
			MSC			-					
(970540)											
Airframe											
ASC054B	ASC054B - Equipment and Furnishings (ATA 25) - Emergency Vision Assurance System (EVAS) - Installation, Aircraft Service Change (Optional)		HRS		.4			3522		0	
			AFL		1		726		0		
			DATE		75 d		12 Oct 2024				
			MSC			-					
(970542)											
Airframe											
ASC055	ASC055 - Landing Gear (ATA 32) - Autobrake System - Installation		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		108.5		11 Dec 2015				
			MSC			-					
(970550)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC055A (970551) Airframe	ASC055A - Landing Gear (ATA 32) Autobrake System - Installation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		102.6			06 Jun 2016			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC055B (970552) Airframe	ASC055B - Landing Gear (ATA 32) - Autobrake System - Installation		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
ASC055C (970553) Airframe	ASC055C - Landing Gear (ATA 32) - Autobrake System - Installation		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
ASC056 (970560) Airframe	ASC056 - Engine Fuel and Control (ATA 73) Engine Electronic Controller-K6.2.2 Software Upgrade		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		124.3			18 Aug 2014			
			MSC				-				
ASC057 (970570) Airframe	ASC057 - Navigation (ATA 34) Enhanced Vision System (Evs) Head-Down Video Function - Installation		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.1			23 Sep 2015			
			MSC				-				
ASC058 (970580) Airframe	ASC058 - Doors (ATA 52) Main Entrance Door - Storage Box Spring Replacement		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.3			18 Sep 2015			
			MSC				-				
ASC059 (970590) Airframe	ASC059 - Doors (ATA 52), Main Entrance Door - Water Drainage Modification		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		110.9			29 Sep 2015			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC060 (970600) Airframe	ASC060 - Doors (ATA 52), Main Entrance Door - Water Intrusion Reduction Modification		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.3			18 Sep 2015			
			MSC				-				
ASC064 (970640) Airframe	ASC064 - Equipment and Furnishings (ATA 25), Aft Equipment Bay Water Shield - Installation		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87.1			22 Sep 2017			
			MSC				-				
ASC065 (970650) Airframe	ASC065 - Doors (ATA 52), Main Entrance Door Manual Operation Mechanism - Installation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		78.4			15 Jun 2018			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC065A (970651) Airframe	ASC065A - Doors (ATA 52) - Main Entrance Door Manual Operation Mechanism - Installation		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC066A (970661) Airframe	ASC066A - Doors (ATA 52) Main Entrance Door (Med) - Emed Rigging Improvement		HRS		1841.9			1680.5			0
			AFL		384			343			0
			MOS		73.8			01 Nov 2018			
			MSC				-				
ASC067 (970670) Airframe	ASC067 - Ice and Rain Protection (ATA 30) - Windshield Heat Temperature Sensing Element Bonding Jumper - Installation		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC068 (970680) Airframe	ASC068 - Equipment and Furnishings (ATA 25) - Baggage Compartment - Grab Handle - Installation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		98.5			12 Oct 2016			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC068A (970681) Airframe	ASC068A - Equipment and Furnishings (ATA 25) - Baggage Compartment Grab Handle - Installation		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC069 (970690) Airframe	ASC069 - Flight Controls (ATA 27) Primary Flight Control Actuation System (Pfcas) Remote Electronics Unit (Reu) Software Update		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.1			23 Sep 2018			
			MSC				-				
ASC070 (970700) Airframe	ASC070 - AIR Conditioning (ATA 21), Cockpit AIR Ducting - Velocity Reduction		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			25 Sep 2017			
			MSC				-				
Notes: REFERENCE SAVANNAH W/O SC470390.5.50 ASC 070 WAS COMPLIED WITH UNDER VALIDATION 09/27/2016 UNDER CMP CODE 920700											
ASC071 (970710) Airframe	ASC071 - Communication(ATA 23) - Communication Management Function (Cmf) Global Data Center (Gdc) Datalink Service Provider, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC072 (970720) Airframe	ASC072 - Electrical Power (ATA 24) - APU Power Feeder Cable Installation - Modification		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		93.3			16 Mar 2017			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC072A	ASC072A - Electrical Power (ATA 24) - APU Power		HRS		1722.5			1799.9			0
	Feeder Cable Installation - Modification		AFL		351			376			0
			MOS		68.7			05 Apr 2019			Gulfstream
			MSC								
(970721)											
Airframe											
Notes: PN: ASC 072A SN: <NONE>.											
ASC073	ASC073 - Landing Gear (ATA 32) - Tire Pressure		HRS		1912.8			1609.6			0
	Monitoring Unit (Tpmu) Software Upgrade		AFL		397			330			0
			MOS		75.3			16 Sep 2018			
			MSC								
(970730)											
Airframe											
ASC074	ASC074 - Landing Gear (ATA 32) - Nose Wheel Steering		HRS		3522.4			0			0
	System - Upgrade		AFL		727			0			0
			MOS		90.3			16 Jun 2017			
			MSC								
(970740)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC074A	ASC074A - Landing Gear (ATA 32) - Nose Wheel Steering		HRS		3522.4			0			0
	System - Upgrade		AFL		727			0			0
			MOS		88.4			15 Aug 2017			
			MSC								
(970741)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC074B	ASC074B - Landing Gear (ATA 32) - Nose Wheel Steering		HRS		3522.4			0			0
	System - Upgrade		AFL		727			0			0
			DATE								
			MSC								
(970742)											
Airframe											
ASC074C	ASC074C - Landing Gear (ATA 32) - Nose Wheel Steering		HRS		485.9			3036.5			0
	System - Upgrade		AFL		97			630			0
			DATE		794 d			24 Oct 2022			
			MSC								
(970743)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC075 (970750) Airframe	ASC075 - Placards and Markings (ATA 11) - Baggage Compartment Access Modification		HRS		3522.4			0			0
			AFL		727			0		0	
			DATE								
			MSC				-				
ASC076 (970760) Airframe	ASC076 - Information Systems (ATA 46) - Aircraft Health and Trend Monitoring System - Software Update 2		HRS		3522.4			0			0
			AFL		727			0		0	
			DATE								
			MSC				-				
ASC076A (970761) Airframe	ASC076A - Information Systems (ATA 46) - Aircraft Health and Trend Monitoring System - Software Update 2		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC076B (970762) Airframe	ASC076B - Information Systems (ATA 46) - Aircraft Health and Trend Monitoring System - Software Update 2		HRS		1158			2364.4			0
			AFL		239			488		0	
			DATE		1536 d			12 Oct 2020			
			MSC				-				
ASC078 (970780) Airframe	ASC078 - Communications (ATA 23) High-Definition (Hd) Camera System - Installation		HRS		3522.4			0			0
			AFL		727			0		0	
			DATE								
			MSC				-				
ASC079 (970790) Airframe	ASC079 - Landing Gear (ATA 32) - Landing Gear Control Unit MOD D Update		HRS		1508.2			2014.2			0
			AFL		311			416		0	
			MOS		63.2			19 Sep 2019			
			MSC				-				
Notes: PN: 60P3230090Z002 SN: 016LG01088C. COMPLIED WITH CMP G650 970790 AIRFRAME ASC 79 LANDING GEAR CONTROL UNIT MOD D UPDATE ***REF 11.9 OPS TEST***											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC081 (970810) Airframe	ASC081 - Doors (ATA 52), Main Entrance Door Latch Actuator - Upgrade		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		88.2			21 Aug 2017			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC081A (970811) Airframe	ASC081A - Doors (ATA 52), Main Entrance Door Latch Actuator - Upgrade		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		77.9			28 Jun 2018			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC081B (970812) Airframe	ASC081B - Doors (ATA 52) - Main Entrance Door Latch Actuator - Upgrade		HRS		1841.9			1680.5			0
			AFL		384			343			0
			MOS		73.9			29 Oct 2018			
			MSC				-				
ASC083 (970830) Airframe	ASC083 - Wings (ATA 57) - Flap Track D Rub Strips - Removal		HRS		1158			2364.4			0
			AFL		239			488			0
			DATE		1533 d			15 Oct 2020			
			MSC				-				
ASC083A (970831) Airframe	ASC083A - Wings (ATA 57) - Flap Track D Rub Strips - Removal, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC084 (970840) Airframe	ASC 084 Main Landing Gear and Brake Assembly - Modification		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		100.2			19 Aug 2016			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC084A (970841) Airframe	ASC 084A Main Landing Gear and Brake Assembly - Modification		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
ASC085 (970850) Airframe	ASC 085 Ka-Band Fin CAP Radome - Installation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		69.6			07 Mar 2019			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC085A (970851) Airframe	ASC 085A Ka-Band Fin CAP Radome - Installation		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC085B (970852) Airframe	Stabilizer (ATA 55) - Ka-Band Fin CAP Radome - Installation, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC086 (970860) Airframe	ASC 086 Main Entry Door - Service Door Panel Security Cover - Installation		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC087 (970870) Airframe	ASC 087 Modification (for Installation of 72P5210904Z005 Main Entrance Door Damper Assembly		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC088 (970880) Airframe	ASC 088 Engine Electronic Controller - K8.0.2 Software Upgrade		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		75			26 Sep 2018			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC088A (970881) Airframe	ASC 088A Engine Electronic Controller - K8.0.2 Software Upgrade		HRS		1722.5			1799.9			0
			AFL		351			376			0
			MOS		68.7			04 Apr 2019			
			MSC				-				
ASC089 (970890) Airframe	ASC 089 Doors (ATA 52), Main Entrance Door - Bottom Folding Step Stop Bolts - Replacement		HRS		2571.6			950.8			0
			AFL		520			207			0
			MOS		92.6			06 Apr 2017			
			MSC				-				
ASC090 (970900) Airframe	ASC 090 Hydraulic Filter Monitoring System - Installation and Activation		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC090A (970901) Airframe	ASC 090A Hydraulic Filter Monitoring System - Installation and Activation		HRS		873.6			2648.8			0
			AFL		166			561			0
			DATE		1175 d			08 Oct 2021			
			MSC				-				
ASC091 (970910) Airframe	ASC 091 Acoustic Door Noise Reduction - Modification		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		84.8			01 Dec 2017			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC091A (970911) Airframe	ASC 091A Acoustic Door Noise Reduction - Modification		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC092 (970920) Airframe	ASC 092 Primary Flight Control Actuation System (Pfcas) Motor Control Electronics (Mce) Software Update		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.1			23 Sep 2018			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC093 (970930) Airframe	ASC 093 Flight Controls (ATA 27) - FCC Software Update		HRS		1722.5			1799.9			0
			AFL		351			376			0
			MOS		68.7			05 Apr 2019			
			MSC					-			
ASC094 (970940) Airframe	ASC 094 Doors (ATA 52) - Electric Main Entrance Door (Emed) Wear PAD Modification		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC					-			
ASC095 (970950) Airframe	ASC 095 Auxiliary Power Unit Enclosure Installation - Modification		HRS								0
			AFL								0
			DATE								
			MSC					-			
ASC095A (970951) Airframe	ASC095A - Fuselage Structure (ATA 53) - Auxiliary Power Unit Enclosure Installation - Modification, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC					-			
ASC096 (970960) Airframe	ASC 096 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC					-			
ASC096A PART 1 (970961) Airframe	ASC 096A 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation (Part 1)		HRS								0
			AFL								0
			DATE								
			MSC					-			
ASC096A PART 2 (970962) Airframe	ASC 096A 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation (Part 2)		HRS								0
			AFL								0
			DATE								
			MSC					-			

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC097 (970970) Airframe	ASC 097 Primary Flight Control Actuation System (Pfcas)		HRS		1912.8			1609.6			0
	Remote Electronics Unit (Reu) Connector Updates		AFL		397			330			0
			MOS		75.1			23 Sep 2018			
			MSC				-				
ASC098 (970980) Airframe	ASC 098 Horizontal Stabilizer Control Unit (Hscu)		HRS		1912.8			1609.6			0
	Software Update		AFL		397			330			0
			MOS		75.1			23 Sep 2018			
			MSC				-				
ASC099 (970990) Airframe	ASC 099 Main Entrance Door - Bottom Folding Step		HRS		3522.4			0			0
	Mechanism Improvement		AFL		727			0			0
			MOS		83.3			16 Jan 2018			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC099A (970991) Airframe	ASC 099A Main Entrance Door - Bottom Folding Step		HRS		1841.9			1680.5			0
	Mechanism Improvement		AFL		384			343			0
			MOS		73.8			01 Nov 2018			
			MSC				-				
ASC100 (971000) Airframe	ASC100 - Indicating / Recording (ATA 31) - Planeview™ li		HRS		113.9			3408.5			0
	Avionics Enhancement, Aircraft Service Change		AFL		36			691			0
	(Optional)		DATE		421 d			01 Nov 2023			
			MSC				-				
ASC100A (971001) Airframe	ASC100A - Indicating / Recording (ATA 31) - Planeview™ li		HRS		.4			3522			0
	Avionics Enhancement, Aircraft Service Change		AFL		1			726			0
	(Optional)		DATE		83 d			04 Oct 2024			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC101 (971010) Airframe	ASC 101 Steep Approach to Landing Activation		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC101A (971011) Airframe	ASC101A - Flight Controls (ATA 27) - Steep Approach to Landing Activation, Aircraft Service Change (Optional)		HRS		485.9			3036.5			0
			AFL		97			630			0
			DATE		808 d			10 Oct 2022			
			MSC				-				
ASC102 (971020) Airframe	ASC 102 Modification FCC Software V8.2 Update		HRS		1722.5			1799.9			0
			AFL		351			376			0
			MOS		68.8			31 Mar 2019			
			MSC				-				
ASC103 (971030) Airframe	ASC 103 Auxiliary Hydraulic Pump - Grounding Installation		HRS		873.6			2648.8			0
			AFL		166			561			0
			DATE		1181 d			02 Oct 2021			
			MSC				-				
ASC105 (971050) Airframe	ASC 105 - Data LAN Management Unit Harness - Service Loop Installation		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		69.5			12 Mar 2019			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC105A (971051) Airframe	ASC 105A - Data LAN Management Unit Harness - Service Loop Installation		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				
ASC106 (971060) Airframe	ASC 106 Pilot Clock Wiring Harness - Service Loop Installation		HRS		3522.4			0			0
			AFL		727			0			0
			DATE								
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC108	ASC 108 Stabilizer (ATA 55) Kuka-Band Fin CAP Radome - Installation		HRS								0
			AFL								0
(971080)			DATE								
Airframe			MSC				-				
ASC109	ASC109 - Placards / Markings (ATA 11) - Category Ii Approach Enhancement, Aircraft Service Change (Cancelled)		HRS								0
			AFL								0
(971090)			DATE								
Airframe			MSC				-				
ASC109A	ASC109A - Placards / Markings (ATA 11) - Category Ii Approach Enhancement, Aircraft Service Change (Optional)		HRS								0
			AFL								0
(971091)			DATE								
Airframe			MSC				-				
ASC110	ASC 110 Flap Electronic Control Unit (Fecu) Software - Update		HRS		1508.2			2014.2			0
			AFL		311			416			0
(971100)			MOS		63			25 Sep 2019			
Airframe			MSC				-				
ASC110A	ASC 110A Flap Electronic Control Unit (Fecu) Software - Update		HRS								0
			AFL								0
(971101)			DATE								
Airframe			MSC				-				
ASC111	ASC 111 Engine FIRE Bottle Harness Installation - Modification		HRS		3522.4			0			0
			AFL		727			0			0
(971110)			MOS		69.1			22 Mar 2019			
Airframe			MSC				-				

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC111A (971111) Airframe	ASC 111A Engine FIRE Bottle Harness Installation - Modification		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		63			25 Sep 2019			
			MSC				-				
ASC113 (971130) Airframe	ASC 113 APU Exhaust Fairing Drainage - Modification		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		72.7			03 Dec 2018			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC113A (971131) Airframe	ASC 113A APU Exhaust Fairing Drainage - Modification		HRS		1158			2364.4			0
			AFL		239			488			0
			DATE		1519 d			29 Oct 2020			
			MSC				-				
ASC116 (971160) Airframe	ASC 116 Battery Charger MODE Control Relays and Electrical Backup Hydraulic Actuator Battery Charger No. 2 - Removal		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		68.5			10 Apr 2019			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC116A (971161) Airframe	ASC 116A Battery Charger MODE Control Relays and Electrical Backup Hydraulic Actuator Battery Charger No. 2 - Removal		HRS		1158			2364.4			0
			AFL		239			488			0
			DATE		1528 d			20 Oct 2020			
			MSC				-				
ASC117 (971170) Airframe	ASC 117 Hydraulic Line Support Bracket Installation - Modification to Provide Side Brace Actuator Clearance		HRS		1722.5			1799.9			0
			AFL		351			376			0
			MOS		68.8			01 Apr 2019			
			MSC				-				
ASC118 (971180) Airframe	ASC 118 Aft Equipment Bay Water Shield - Installation		HRS								0
			AFL								0
			DATE								
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC119 (971190) Airframe	ASC119 - Doors (ATA 52) Acoustic Door Damped Spring Reel - Installation, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC120 (971200) Airframe	ASC120 - Navigation (ATA 34) - Predictive Weather Activation, Aircraft Service Change (Optional)		HRS		113.9			3408.5			0
			AFL		36			691			0
			DATE		422 d			31 Oct 2023			
			MSC				-				
ASC121 (971210) Airframe	ASC121 - Navigation (ATA 34) - Situational Awareness Package Installation, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC122 (971220) Airframe	FIRE Protection (ATA 26) - Engine FIRE Extinguishing Bottle Cartridge - Wiring - Modification, Aircraft Service Change (Cancelled)		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.1			22 Oct 2023			
			MSC				-				
ASC122A (971221) Airframe	FIRE Protection (ATA 26) - Engine FIRE Extinguishing Bottle Cartridge Wiring - Modification, Aircraft Service Change (Optional)		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.6			06 Oct 2022			
			MSC				-				
ASC123 (971230) Airframe	ASC 123 APU Electronic Control Unit Software - Update		HRS		1722.5			1799.9			0
			AFL		351			376			0
			MOS		68.7			05 Apr 2019			
			MSC				-				
ASC123A (971231) Airframe	ASC 123A APU Electronic Control Unit Software - Update		HRS								0
			AFL								0
			DATE								
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC124 (971240) Airframe	ASC 124 Pylon Seal Retainer - Modification		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		70.6			08 Feb 2019			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC124A (971241) Airframe	ASC 124A Pylon Seal Retainer - Modification		HRS		485.9			3036.5			0
			AFL		97			630			0
			DATE		806 d			12 Oct 2022			
			MSC				-				
ASC125 (971250) Airframe	ASC125 - Navigation (ATA 34) - Heads Up Display (HUD) li Software Update, Aircraft Service Change (Optional)		HRS		113.9			3408.5			0
			AFL		36			691			0
			DATE		421 d			01 Nov 2023			
			MSC				-				
ASC127 (971270) Airframe	ASC127 - Navigation (ATA 34) - Predictive Landing Performance System (Plps) Package Installation, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC128 (971280) Airframe	ASC128 - Autoflight (ATA 22) - Auto-Pilot Coupled TCAS Activation, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC129 (971290) Airframe	ASC 129 Flap Track D Up-Stop Fitting - Improvement		HRS		1158			2364.4			0
			AFL		239			488			0
			DATE		1534 d			14 Oct 2020			
			MSC				-				
ASC131 (971310) Airframe	ASC 131 Flap Track C Roller Fitting - Rub PAD Installation		HRS		1158			2364.4			0
			AFL		239			488			0
			DATE		1533 d			15 Oct 2020			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC133 (971330) Airframe	ASC 133 Engine Electronic Controller - K9.0.1 Software Upgrade		HRS		1566.2			1956.2			0
			AFL		319			408			0
			MOS		64.5			10 Aug 2019			
			MSC				-				
ASC133A (971331) Airframe	ASC 133A Engine Electronic Controller - K9.0.1 Software Upgrade		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		63.3			17 Sep 2019			
			MSC				-				
ASC134 PART I (971340) Airframe	ASC 134 (Part 1) Wedge Installation - Trailing Edge, Rudder		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC134 PART II (971341) Airframe	ASC 134 (Part 2) Wedge Installation - Trailing Edge, Rudder		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC134A PART I (971342) Airframe	ASC 134A (Part 1) Wedge Installation - Trailing Edge, Rudder		HRS		1429.5			2092.9			0
			AFL		311			416			0
			DATE		1824 d			29 Dec 2019			
			MSC				-				
ASC134A PART II (971343) Airframe	ASC 134A (Part 2) Wedge Installation - Trailing Edge, Rudder		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC134B PART I (971344) Airframe	ASC 134B (Part 1) Wedge Installation - Trailing Edge, Rudder		HRS		1265.4			2257			0
			AFL		259			468			0
			MOS		56.8			31 Mar 2020			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC134B PART II (971345) Airframe	ASC 134B (Part 2) Wedge Installation - Trailing Edge, Rudder		HRS		1158			2364.4			0
			AFL		239			488			0
			DATE		1524 d			24 Oct 2020			
			MSC				-				
ASC135 (971350) Airframe	ASC 135 Flight Control Computer (FCC) Software Update V10.1		HRS		1158			2364.4			0
			AFL		239			488			0
			DATE		1516 d			01 Nov 2020			
			MSC				-				
ASC137 (971370) Airframe	ASC137 - Placards and Markings (ATA 11) - Category B Maximum Landing Weight Reduction - 65,000 Pound, Aircraft Service Change (Cancelled)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC137A (971371) Airframe	ASC137A - Placards and Markings (ATA 11) - Category B Maximum Landing Weight Reduction - 65,000 Pound, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC138 (971380) Airframe	ASC138 - Engine Fuel & Control (ATA 73) - Engine Electronic Controller - K10.1 Software Upgrade, Aircraft Service Change (Optional)		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7			05 Oct 2022			
			MSC				-				
ASC139 (971390) Airframe	ASC139 - Equipment and Furnishings (ATA 25) - Emergency Vision Assurance System (EVAS) - Removal, Aircraft Service Change (Optional)		HRS		.4			3522			0
			AFL		1			726			0
			DATE		74 d			13 Oct 2024			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC140 (971400) Airframe	ASC140 - Information Systems (ATA 46) - Aircraft Health and Trend Monitoring System (Ahtms) Software Update, Aircraft Service Change (Optional)		HRS		485.9			3036.5			0
			AFL		97		630			0	
			DATE		773 d		14 Nov 2022				
			MSC				-				
ASC141 (971410) Airframe	ASC141 - Communications (ATA 23) - Cockpit Voice Recorder (Cvr) 25-Hour Upgrade Installation, Aircraft Service Change (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
ASC141A (971411) Airframe	ASC141A - Communications (ATA 23) Cockpit Voice Recorder (Cvr) 25-Hour Upgrade Installation, Aircraft Service Change (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
ASC142 (971420) Airframe	ASC142 - Fuselage Structure (ATA 53) - Auxiliary Power Unit Enclosure - Exhaust Duct Fastener Pitch Modification, Aircraft Service Change (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
ASC143 (971430) Airframe	ASC143 - Communications (ATA 23) - Communication Management Function (Cmf) SATCOM Direct (Non-Sita) Datalink Service Provider, Aircraft Service Change (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
ASC144 (971440) Airframe	ASC144 - Navigation (ATA 34) - Attitude Heading Reference Unit Label Installation, Aircraft Service Change (Optional)		HRS		.4			3522			0
			AFL		1		726			0	
			DATE		93 d		24 Sep 2024				
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC146 (971460) Airframe	ASC146 - Equipment and Furnishings (ATA 25) - Ebha Pdb Terminal Bracket Cover - Installation, Aircraft Service Change (Optional)		HRS		113.9			3408.5			0
			AFL		36			691			0
			DATE		431 d			22 Oct 2023			
			MSC				-				
ASC151 (971510) Airframe	ASC151 - Stabilizer (ATA 55) - Kuka Lightweight Fin CAP Radome - Installation, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC152 (971520) Airframe	ASC152 - Engine Controls (ATA 76) - Engine Fuel Control Panel Connector - Harness Modification, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC155 (971550) Airframe	ASC155 - Hydraulic Power (ATA 29) - Hydraulic Replenisher Selector Valve Connector (082L1P1) - Harness Modification, Aircraft Service Change (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC156 (971560) Airframe	ASC156 - Oil (ATA 79) - Oil Servicing Selector Valve Connector (082L4P1) - Harness Modification, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
ASC901 (979010) Airframe	ASC901 - Indicating / Recording (ATA 31) - Planeview li Master Operating System Software Update		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		121.9			30 Oct 2014			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC901A (979011) Airframe	ASC901A - Indicating / Recording (ATA 31) - Planeview li Master Operating System Software Update		HRS		3396.7			125.7			0
			AFL		702			25			0
			MOS		119.7			04 Jan 2015			
			MSC				-				
ASC902 (979020) Airframe	ASC902 - Indicating / Recording (ATA 31) - Planeview li Master Operating System Software Update		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		96.1			22 Dec 2016			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC902A (979021) Airframe	ASC902A - Indicating / Recording (ATA 31) - Planeview li Master Operating System Software Update		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
ASC902B (979022) Airframe	ASC902B - Indicating / Recording (ATA) - Planeview li Master Operating System Software Update		HRS		485.9			3036.5			0
			AFL		97			630			0
			DATE		765 d			22 Nov 2022			
			MSC				-				
ASC903 (979030) Airframe	ASC903 - Indicating / Recording (ATA 31) - Planeview™ li Master Operating System Software Update, Service Bulletin (Optional)		HRS		113.9			3408.5			0
			AFL		36			691			0
			DATE		421 d			01 Nov 2023			
			MSC				-				
ASC903A (979031) Airframe	ASC903A - Indicating / Recording (ATA 31) - Planeview™ li Master Operating System Software Update, Service Bulletin (Optional)		HRS		.4			3522			0
			AFL		1			726			0
			DATE		82 d			05 Oct 2024			
			MSC				-				
98 - Customer/Service Bulletins											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB018A	CB018A - Placards and Markings (ATA 11) Installation - Engine Operating Limits Placard (ASC 043A)		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		124.2			20 Aug 2014			
			MSC				-				
(980181)											
Airframe											
CB027	CB027 - Hydraulic Power (ATA 29) Modification - Install Ecology Bottle Vent Drain Line (ASC 047)		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		125.1			24 Jul 2014			
			MSC				-				
(980270)											
Airframe											
CB033	CB033 - AIR (ATA 75) Modification - Revised Buffer AIR Valve and HP2 Restrictor Adaptor (Rolls-Royce Sb-BR700 -75-101844)		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		125.8			02 Jul 2014			
			MSC				-				
(980330)											
Airframe											
Notes: EFFECTIVITY: AIRCRAFT SERIAL NUMBERS 6001 THROUGH 6087 HAVING ENGINE SERIAL NUMBERS UP TO AND INCLUDING 25287. COMPLIANCE WITH THIS CUSTOMER BULLETIN IS REQUIRED WITHIN 18 MONTHS FROM THE ORIGINAL ISSUE DATE OF APRIL 23, 2014. AIRCRAFT HAVING PREVIO											
CB034	CB034 - Fuselage (ATA 53) Rework - Wing to Body Fairing Support		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		125.8			02 Jul 2014			
			MSC				-				
(980340)											
Airframe											
CB035	CB035 - Engine Fuel and Control (ATA 73) Modification- Engine Electronic Controller (Eec) K6.2.2 Software Upgrade (ASC 056)		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		124.3			18 Aug 2014			
			MSC				-				
(980350)											
Airframe											
CB036	CB036 - Wings (ATA 57) Inspection - Wing-to-Fuselage Link Hardware		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		125.8			02 Jul 2014			
			MSC				-				
(980360)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB037	CB037 - Engine Indicating (ATA 77) Installation-Speed Signal Attenuator (Rolls-Royce Sb BR700-77-101866)		HRS		3509.1			13.3			0
			AFL		722			5		0	
			MOS		125			26 Jul 2014			
			MSC				-				
(980370)											
Airframe											
Notes: COMPLIED WITH CB37 DATED 05-06-2014											
CB038	CB038 - Flight Controls (ATA 27) Inspection - Flight Control Manifold - Return Relief Valve Non-Conformance		HRS		3509.1			13.3			0
			AFL		722			5		0	
			MOS		125.8			02 Jul 2014			
			MSC				-				
(980380)											
Airframe											
CB039A	CB039A - Landing Gear (ATA 32) Inspection - Nose Landing Gear Shock Strut Cylinder (Pn C2M5200CA001) Surface Finish		HRS		3509.1			13.3			0
			AFL		722			5		0	
			MOS		125			25 Jul 2014			
			MSC				-				
(980391)											
Airframe											
CB040	CB040 - Flight Controls (ATA 27) Inspection - Left and Right Aileron Assembly Part Numbers		HRS		3509.1			13.3			0
			AFL		722			5		0	
			MOS		125.8			02 Jul 2014			
			MSC				-				
(980400)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB040A	CB040A - Flight Controls (ATA 27) Inspection - Left and Right Aileron Assembly Part Numbers		HRS		3509.1			13.3			0
			AFL		722			5		0	
			MOS		125.8			02 Jul 2014			
			MSC				-				
(980401)											
Airframe											
CB041	CB041 - Wings (ATA 57) Inspection - Forward Wing to Fuselage Fitting Installation		HRS		3509.1			13.3			0
			AFL		722			5		0	
			MOS		125.8			02 Jul 2014			
			MSC				-				
(980410)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB042	CB042 - Doors (ATA 52) Installation - Main Entrance Door		HRS		3509.1			13.3			0
	Drip Guard		AFL		722			5			0
			MOS		125.8			02 Jul 2014			
			MSC				-				
(980420)											
Airframe											
CB043	CB043 - Engine and Fuel Control (ATA 73) Inspection -		HRS		3509.1			13.3			0
	Fuel Low Pressure Sense Line Installation (Rolls-Royce		AFL		722			5			0
	Sb-BR700-73-900141)		MOS		125.8			02 Jul 2014			
			MSC				-				
(980430)											
Airframe											
CB044	CB044 - Fuel (ATA 28) - Replacement - Overwing Gravity		HRS		3509.1			13.3			0
	Fueling Port Adapter Flange Screws		AFL		722			5			0
			MOS		125.8			02 Jul 2014			
			MSC				-				
(980440)											
Airframe											
CB045A	CB045A - Aircraft Equipment and Furnishings (ATA 25),		HRS		3509.1			13.3			0
	Modification - Galley Tower - Espresso Maker Cooling Fan		AFL		722			5			0
	Installation		MOS		124.3			18 Aug 2014			
			MSC				-				
(980451)											
Airframe											
CB046	CB046 - Auxiliary Power Unit (ATA 49) Inspection -		HRS		3509.1			13.3			0
	Auxiliary Power Unit (APU) Starter Motor Terminal		AFL		722			5			0
			MOS		125.7			05 Jul 2014			
			MSC				-				
(980460)											
Airframe											
CB047	CB047 - Hydraulic Power (ATA 29) - Inspection - Hydraulic		HRS		3509.1			13.3			0
	Reservoir Feedback Position Sensor Electrical Bonding		AFL		722			5			0
			MOS		125			25 Jul 2014			
			MSC				-				
(980470)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB048	CB048 - Placards and Markings (ATA 11) Installation - Aft Lavatory Water Supply Valve Override Instruction Placards		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		124.7		04 Aug 2014				
			MSC				-				
(980480)											
Airframe											
CB049	CB049 - Navigation (ATA 34) Inspection - VOR Localizer Antenna Installation		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		124.7		04 Aug 2014				
			MSC				-				
(980490)											
Airframe											
CB050	CB050 - Engine Indication (ATA 77) Replacement - Turbine Oil FIRE Thermocouple and Oil FIRE Detection Adapter (Rolls-Royce Nmsb BR700-77-900176)		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		124.7		04 Aug 2014				
			MSC				-				
(980500)											
Airframe											
CB051	CB051 - Engine Indicating (ATA 77) Inspection - Engine Vibration Transducer Connectors		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		124.5		11 Aug 2014				
			MSC				-				
(980510)											
Airframe											
CB052	CB052 - Ignition (ATA 74) Replacement - Engine Igniter Plugs (Rolls-Royce Nmsb BR700-74-900166)		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		123.4		15 Sep 2014				
			MSC				-				
(980520)											
Airframe											
CB053	CB053 - Fuselage (ATA 53) Installation - Fasteners AT Left and Right Fuselage Stations (FS) 169 and 184		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		123.4		15 Sep 2014				
			MSC				-				
(980530)											
Airframe											
CB053A	CB053A - Fuselage (ATA 53), Installation - Fasteners AT Left and Right Fuselage Stations (FS) 169 and 184		HRS		3506.4			16			0
			AFL		721		6		0		
			MOS		122.4		13 Oct 2014				
			MSC				-				
(980531)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB054	CB054 - Fuselage (ATA 53) Inspection - Nose Radome Electrical Bonding		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		122.7			04 Oct 2014			
			MSC				-				
(980540)											
Airframe											
CB055	CB055 - Equipment / Furnishings (ATA 25) Installation - Battery Charger Circuit Breaker Cover (ASC 033)		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		122.8			02 Oct 2014			
			MSC				-				
(980550)											
Airframe											
CB056	CB056 - Flight Controls (ATA 27) Modification - Horizontal Stabilizer Control Unit		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		122.7			04 Oct 2014			
			MSC				-				
(980560)											
Airframe											
CB057	CB057 - Doors (ATA 52) Inspection - Main Entrance Door Guide Receiver Proximity Switch and Bayonet Receiver Switch Burnished Surface Over Coat		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		122.5			09 Oct 2014			
			MSC				-				
(980570)											
Airframe											
CB058	CB058 - Doors (ATA 52) Inspection - Installation of Emergency Exit Door Insulation		HRS		3509.1			13.3			0
			AFL		722			5			0
			MOS		122.5			09 Oct 2014			
			MSC				-				
(980580)											
Airframe											
CB059	CB059 - Doors (ATA 52) Modification - Main Entrance Door (ASC 053)		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.3			18 Sep 2015			
			MSC				-				
(980590)											
Airframe											
CB060	CB060 - Electrical Power (ATA 24), Modification - Battery Charger, P/N 100-1311-01		HRS		3396.7			125.7			0
			AFL		702			25			0
			MOS		119.8			02 Jan 2015			
			MSC				-				
(980600)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB060A	CB060A - Electrical Power (ATA 24), Modification - Battery Charger, P/N 100-1311-01		HRS		3026.3			496.1			0
			AFL		617			110			0
			MOS		107.7			04 Jan 2016			
			MSC				-				
(980601)											
Airframe											
CB061	CB061 - Engine Standard Practices (ATA 70), Inspection - Engine Driven Hydraulic and Fuel Pump V-Band Clamps (Rolls-Royce Nmsb BR700-71-900003 and BR700-73- 900009)		HRS		3396.7			125.7			0
			AFL		702			25			0
			MOS		120.1			23 Dec 2014			
			MSC				-				
(980610)											
Airframe											
CB062	CB062 - Navigation (ATA 34), Modification - Enhanced Vision System Processor - Software Upgrade		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.1			23 Sep 2015			
			MSC				-				
(980620)											
Airframe											
CB067	CB067 - Indicating/Recording Systems (ATA 31), Modification - CO-Pilots Crew Alerting System (CAS) Scroll Switch Wiring		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.3			17 Sep 2015			
			MSC				-				
(980670)											
Airframe											
CB067A	CB067A - Indicating/Recording Systems (ATA 31), Modification - CO-Pilots Crew Alerting System (CAS) Scroll Switch Wiring		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			19 Sep 2016			
			MSC				-				
(980671)											
Airframe											
Notes: *** PREVIOUSLY COMPLIED WITH AT GAC SAVANNAH ON W.O. 431097 ITEM 5.37 ON 09/17/15. ***											
CB068	CB068 - Hydraulic Power (ATA 29), Installation - Hydraulic Replenisher Tank Placard (ASC 040)		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.4			14 Sep 2015			
			MSC				-				
(980680)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB070 (980700) Airframe	CB070 - Fuselage (ATA 53), Modification - Install Gusset AT Fuselage Station 1083 (ASC 042)		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.3			18 Sep 2015			
			MSC				-				
CB072 (980720) Airframe	CB072 - Pneumatic Systems (ATA 36), Inspection - Cabin Pressurization Test Port Fitting CAP		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.4			14 Sep 2015			
			MSC				-				
CB074 (980740) Airframe	CB074 - Doors (ATA 52), Modification - Main Entrance Door Water Drainage (ASC 059)		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.3			18 Sep 2015			
			MSC				-				
CB075 (980750) Airframe	CB075 - Doors (ATA 52), Modification - Main Entrance Door Water Intrusion Reduction (ASC 060)		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.3			18 Sep 2015			
			MSC				-				
CB076 (980760) Airframe	CB076 - Communications (ATA 23), Modification - High Speed Data - Software Upgrade		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		117			27 Mar 2015			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB076A (980761) Airframe	CB076A - Communications (ATA 23), Modification - High Speed Data - Software Upgrade		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		113.4			15 Jul 2015			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB076B (980762) Airframe	CB076B - Communications (ATA 23), Modification - High Speed Data - Software Upgrade		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.3			18 Sep 2015			
			MSC				-				
CB077 (980770) Airframe	CB077 - Landing Gear (ATA 32), Replacement - Emergency Gear Extension Cable Hardware		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		114.5			12 Jun 2015			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB077A (980771) Airframe	CB077A - Landing Gear (ATA 32), Replacement - Emergency Gear Extension Cable Hardware		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			16 Sep 2016			
			MSC				-				
CB079 (980790) Airframe	CB079 - Fuel (ATA 28), Inspection - Heated Fuel Return Line Coupling Nut Subassembly		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.4			14 Sep 2015			
			MSC				-				
CB080 (980800) Airframe	CB080 - Landing Gear (ATA 32), Inspection - Parking Brake Cable		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.4			14 Sep 2015			
			MSC				-				
CB081 (980810) Airframe	CB081 - Engine Fuel and Control (ATA 73), Replacement - Fuel Cooled Oil Cooler (Fcoc) Tube		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.3			16 Sep 2015			
			MSC				-				
CB082A (980821) Airframe	CB082A - Placards and Markings (ATA 11), Installation - Hydraulic System Ground Service Panel Placard		HRS		3133.7			388.7			0
			AFL		652			75			0
			MOS		111.4			14 Sep 2015			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB084	CB084 - Doors (ATA 52), Installation - Fuel Servicing Door Refueling Decal and Hold Open (ASC 050)		HRS		3133.7			388.7			0
			AFL		652			75		0	
			MOS		111.3			18 Sep 2015			
			MSC				-				
(980840)											
Airframe											
CB087	CB087 - FIRE Protection (ATA 26), Inspection - Engine FIRE Bottle Cartridge (Squib) Electrical Connections		HRS		3133.7			388.7			0
			AFL		652			75		0	
			MOS		111.3			17 Sep 2015			
			MSC				-				
(980870)											
Airframe											
CB087A	CB087A - FIRE Protection (ATA 26) Inspection - Engine FIRE Bottle Cartridge (Squib) Electrical Connections		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.2			19 Sep 2016			
			MSC				-				
(980871)											
Airframe											
Notes: *** PREVIOUSLY COMPLIED WITH AT GAC SAVANNAH ON W.O. 431097 ITEM 5.47 ON 09/17/15. ***											
CB089	CB089 - Equipment and Furnishings (ATA 25), Replacement - Flashlights (ASC 025)		HRS		3133.7			388.7			0
			AFL		652			75		0	
			MOS		111.3			16 Sep 2015			
			MSC				-				
(980890)											
Airframe											
CB090	CB090 - Equipment and Furnishings (ATA 25), Inspection - Passenger Seat Restraint System (Amsafe Sb 504443- 25-02)		HRS		3133.7			388.7			0
			AFL		652			75		0	
			MOS		111.3			17 Sep 2015			
			MSC				-				
(980900)											
Airframe											
CB090A	CB090A - Equipment and Furnishings (ATA 25), Inspection - Passenger Seat Restraint System (Amsafe Sb 504443-25-02)		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		110.1			22 Oct 2015			
			MSC				-				
(980901)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB090B	CB090B - Equipment and Furnishings (ATA 25), Inspection - Passenger Seat Restraint System (Amsafe Sb 504443-25-02)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			19 Sep 2016			
			MSC				-				
(980902)											
Airframe											
Notes: *** PREVIOUSLY COMPLIED WITH AT GAC SAVANNAH ON W.O. 431097 ITEM 5.49 ON 09/17/15. NOTE: EQUIPMENT NOT INSTALLED ***											
CB094	CB094 - Ice and Rain Protection (ATA 30), Installation - Windshield Heat Temperature Sensing Element Bonding Jumper (ASC 067)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
(980940)											
Airframe											
CB095	CB095 - Water/Waste (ATA 38), Replacement - Water Sterilizer Filters		HRS		3026.3			496.1			0
			AFL		617			110			0
			MOS		107.8			31 Dec 2015			
			MSC				-				
(980950)											
Airframe											
CB098	CB098 - Ice and Rain Protection (ATA 30), Inspection - Inlet Cowl Anti-Ice Pressure Sensing Line		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			21 Sep 2016			
			MSC				-				
(980980)											
Airframe											
Notes: TW: 558063 DUE: 08/17											
CB102	CB102 - Flight Controls (ATA 27), Modification - Flight Control Computer (FCC) Software Upgrade 6.24 (ASC 037)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
(981020)											
Airframe											
CB103	CB103 - FIRE Protection (ATA 26), Inspection - Engine FIRE Bottle Electrical Harness Routing		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		104.4			15 Apr 2016			
			MSC				-				
(981030)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB103A (981031) Airframe	CB103A - FIRE Protection (ATA 26), Inspection - Engine FIRE Bottle Electrical Harness Routing		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
CB104 (981040) Airframe	CB104 - Electrical Power (ATA 24), Modification - Uninterruptible Power Supply (UPS) Battery Upgrade		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		109.2			20 Nov 2015			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB104A (981041) Airframe	CB104A - Electrical Power (ATA 24), Modification - Uninterruptible Power Supply (UPS) Battery Upgrade		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			19 Sep 2016			
			MSC				-				
Notes: *** A MOD LEVEL 4 BATTERY WAS INSTALLED ON W.O. 431097 ITEM 13.146 AT GAC SAVANNAH ON 09/17/15. ***											
CB108 (981080) Airframe	CB108 - Engine Fuel and Control (ATA 73) Replacement - Engine Driven Fuel Pump V-Band Clamp (Rolls-Royce Sb -BR700-73-101929)		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			19 Sep 2016			
			MSC				-				
Notes: *** PREVIOUSLY COMPLIED WITH AT GAC SAVANNAH ON W.O. 431097 ITEMS 5.36 AND 5.37 ON 09/15/15. ***											
CB109 (981090) Airframe	CB109 - Fuselage (ATA 53) Inspection - Aft Pressure Bulkhead Channel Beam Fasteners		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			16 Sep 2016			
CB110 (981100) Airframe	CB110 - Electrical Power (ATA 24) Inspection - Wire Harness to Support Bracket Contact		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			16 Sep 2016			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB111	CB111 - Electrical Power (ATA 24) Inspection - Electrical		HRS		2755.9			766.5			0
	Backup Hydraulic Actuator (Ebha) Distribution Box Power		AFL		561			166			0
	Cables		MOS		99.1			22 Sep 2016			
			MSC				-				
(981110)											
Airframe											
CB112	CB112 - Electrical Power (ATA 24) Inspection -		HRS		2312.5			1209.9			0
	Transformer Rectifier Unit (Tru) Electrical Connector		AFL		479			248			0
	Wiring		MOS		87			26 Sep 2017			
			MSC				-				
(981120)											
Airframe											
Notes: REF G650 CB 112REFER TO OPEN/CLOSE INDEX 05A FOR FLOORBOARDS 5A, 6A, AND 7A											
CB114	CB114 - Hydraulic Power (ATA 29) Inspection - Hydraulic		HRS		2312.5			1209.9			0
	Fittings AT Left Side Fuselage Station (FS) 739 Bulkhead		AFL		479			248			0
			MOS		87.2			19 Sep 2017			
			MSC				-				
(981140)											
Airframe											
Notes: TQ WR: 561050 / CAL DUE: 11/17TQ WR: 560295 / CAL DUE: 02/18											
CB115	CB115 - Doors (ATA 52) - Replacement - Main Entrance		HRS		2755.9			766.5			0
	Door Handrail Hardware		AFL		561			166			0
			MOS		99.1			22 Sep 2016			
			MSC				-				
(981150)											
Airframe											
Notes: TW#: 553005 DUE: 10/16											
CB116	CB116 - Water/Waste (ATA 38) Inspection - Water System		HRS		2755.9			766.5			0
	Tank Drain Hose Contact on Water Tank Shelf Support		AFL		561			166			0
			MOS		99.1			23 Sep 2016			
			MSC				-				
(981160)											
Airframe											
CB117	CB117 - Water / Waste (ATA 38) Inspection - Water Tank		HRS		2755.9			766.5			0
	Electrical Harness Installation		AFL		561			166			0
			MOS		99.1			23 Sep 2016			
			MSC				-				
(981170)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB118	CB118 - Powerplant (ATA 71) Replacement - Engine Driven Hydraulic Pump V-Band Clamp (Rolls-Royce Sb- BR700-71-101928)		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.2			20 Sep 2016			
			MSC				-				
(981180)											
Airframe											
Notes: (REF. 5.45 & 5.46)TW#:558138 DUE: 6/17											
CB120	CB120 - FIRE Protection (ATA 26) Inspection - Engine / Auxiliary Power Unit (APU) FIRE Bottle Thermal Relief Discharge Port		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		105.3			18 Mar 2016			
			MSC				-				
(981200)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB120A	CB120A - FIRE Protection (ATA 26), Inspection - Engine / Auxiliary Power Unit (APU) FIRE Bottle Thermal Relief Discharge Port		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.3			16 Sep 2016			
			MSC				-				
(981201)											
Airframe											
CB121	CB121 - Flight Controls (ATA 27), Inspection - Flap Torque Shafts Hardware		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.2			21 Sep 2016			
			MSC				-				
(981210)											
Airframe											
Notes: TW: 553005 DUE: 10/16											
CB122	CB122 - Electrical Power (ATA 24), Inspection - Ram AIR Turbine (RAT) Electrical Harness Missing Overbraid Ground		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.3			16 Sep 2016			
			MSC				-				
(981220)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB123	CB123 - Electrical Power (ATA 24) Inspection Hydraulic System Manifolds Wiring Installation		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		103.9			28 Apr 2016			
			MSC				-				
(981230)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB123A	CB123A - Electrical Power (ATA 24) - Inspection - Hydraulic System Manifolds - Wiring Installation		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.3			17 Sep 2016			
			MSC				-				
(981231)											
Airframe											
CB124	CB124 - Electrical Power (ATA 24) Inspection Electrical Harness AT Fuselage Station 321 Below Floors		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.3			17 Sep 2016			
			MSC				-				
(981240)											
Airframe											
CB126	CB126 - Powerplant (ATA 71), Replacement - Engine Driven Hydraulic Pump Depressurization Valve Connector		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.3			16 Sep 2016			
			MSC				-				
(981260)											
Airframe											
CB126A	CB126A - Powerplant (ATA 71), Replacement - Engine Driven Hydraulic Pump Depressurization Valve Connector		HRS		2584.1			938.3			0
			AFL		523			204		0	
			MOS		92.9			30 Mar 2017			
			MSC				-				
(981261)											
Airframe											
Notes: PREVIOUSLY COMPLIED WITH CB126 ON SEPT-16-2016 @ GULFSTREAM - SAVANNAH (TT 766.5 HR / 166 LDG)											
CB127	CB127 - Powerplant (ATA 71), Inspection - Right Engine General Services Harness Installation (Rolls-Royce Nmsb Sb-BR700-71-900578)		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.3			16 Sep 2016			
			MSC				-				
(981270)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB128	CB128 - Electrical Power (ATA 24), Inspection - Wire Harness Installation In Pilot S Side Console		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.4			15 Sep 2016			
			MSC				-				
(981280)											
Airframe											
CB129	CB129 - Electrical Power (ATA 24), Wiring Harness Clamp Installations AT Fuselage Station 893		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			16 Sep 2016			
			MSC				-				
(981290)											
Airframe											
CB131	CB131 - Ice and Rain Protection (ATA 30), Inspection - Wing Anti-Ice Overheat/Low Temperature Switch Wiring Contacting Bracket		HRS		1722.5			1799.9			0
			AFL		351			376			0
			MOS		69			27 Mar 2019			
			MSC				-				
(981310)											
Airframe											
CB132	CB132 - Doors (ATA 52), Modification - Wiring Installation - Tail Compartment Access Door Warning Switch		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.4			15 Sep 2016			
			MSC				-				
(981320)											
Airframe											
CB135	CB135 - Doors (ATA 52), Replacement - Main Entrance Door Bottom Folding Step Link Assembly, P/N 60P5260000A004		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.3			16 Sep 2016			
			MSC				-				
(981350)											
Airframe											
Notes: TW: 553005 DUE: 10/16D/I: 557218 DUE: 10/16											
CB136	CB136 - AIR Conditioning (ATA 21), Modification - Environmental Control System Harness Installation AT Fuselage Station 805		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			21 Sep 2016			
			MSC				-				
(981360)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB137	CB137 - Equipment / Furnishings (ATA 25), Inspection - Main Wheel Well Modular Harness Assembly - Clamp Installation		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.1			22 Sep 2016			
			MSC				-				
(981370)											
Airframe											
CB138	CB138 - Engine (ATA 72), Inspection - Accessory Gearbox Radial Drive Shaft Seal (Rolls-Royce Sb-BR700-72-900589)		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		104			27 Apr 2016			
			MSC				-				
(981380)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB138A	CB138A - Engine (ATA 72) - Inspection - Accessory Gearbox Radial Drive Shaft Seal(Rolls-Royce Nmsb Sb-BR700-72-900589)		HRS		1912.8			1609.6			0
			AFL		397			330		0	
			MOS		75.2			21 Sep 2018			
			MSC				-				
(981381)											
Airframe											
Notes: REF ROLLS ROYCE W.O. 0.001364464-8593 AND 0.001364464-8594 DATED 17/SEPT/2018											
CB139	CB139 - Auxiliary Power (ATA 49), Inspection - Inlet Door Actuator Support Fitting		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.2			21 Sep 2016			
			MSC				-				
(981390)											
Airframe											
CB140	CB140 - Electrical Power (ATA 24) - Inspection - Wire Harness Forward of Left Electronic Equipment Rack (Leer) Contacting Overhead Closeout Panel Support Bracket		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.3			17 Sep 2016			
			MSC				-				
(981400)											
Airframe											
Notes: UPON INSPECTION DISCOVERED EFFECTED WIRE HARNESSNOT ROUTED NEAR LEER UPPER FORWARD CLOSE OUT PANEL MOUNTING BRACKET. EFFECTED HARNESS HAS BEEN ROUTED AROUND THE AREA BY TIE WRAPS AND SADLE CLAMPS, PREVIOUSLY INSTALLED.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB141	CB141 - Hydraulic Power (ATA 29) - Inspection - Engine Driven Pump (Edp) Case Drain Hose Contact In Left and Right Engine Pylons		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.1			22 Sep 2016			
			MSC				-				
(981410)											
Airframe											
CB141A	CB141A - Hydraulic Power (ATA 29), Inspection - Engine Driven Pump (Edp) Case Drain Hose Contact In Left and Right Engine Pylons		HRS		2384			1138.4			0
			AFL		491			236		0	
			MOS		88.7			03 Aug 2017			
			MSC				-				
(981411)											
Airframe											
Notes: FOUND PCW CB141 ON 09-22-2016 (TT 766.5 HR / 166 LDG)											
CB142	CB142 - Fuel (ATA 28), Replacement - Pressure Fueling Shut-Off Valves, P/N L94-51-602, With P/N L94-51-603		HRS		3522.4			0			0
			AFL		727			0		0	
			MOS		74.3			17 Oct 2018			
			MSC				-				
(981420)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB142A	CB142A - Fuel (ATA 28) - Replacement - Pressure Fueling Shut-Off Valves, P/N L94-51-602, With P/N L94-51-603		HRS		1508.2			2014.2	0		0
			AFL		311			416	0	0	
			MOS		60.7			04 Dec 2019			
			MSC				-				
(981421)											
Airframe											
Notes: CB 142A is N/A, superseded by CB 142B											
CB142B	CB142B - Fuel (ATA 28) - Replacement - Pressure Fueling Shut-Off Valves, P/N L94-51-602, With P/N L94-51-603		HRS								0
			AFL							0	
			DATE								
			MSC				-				
(981422)											
Airframe											
CB142C	CB142C - Fuel (ATA 28) - Replacement - Pressure Fueling Shut-Off Valves, P/N L94-51-602, With P/N L94-51-603		HRS								0
			AFL							0	
			DATE								
			MSC				-				
(981423)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB143 (981430) Airframe	CB143 - Landing Gear (ATA 32) - Modification - Landing Gear Control Unit (Lgcu) MOD D Update (ASC 079)		HRS		3522.4			0			0
			AFL		727		0		0		
			MOS		103.5		10 May 2016				
			MSC			-					
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB143A (981431) Airframe	CB143A - Landing Gear (ATA 32) - Modification Landing Gear Control Unit (Lgcu) MOD D Update (ASC 079)		HRS		1508.2			2014.2			0
			AFL		311		416		0		
			MOS		63.2		19 Sep 2019		N/A		
			MSC			-					
Notes: PN: 60P3230090Z002 SN: 016LG01088C. COMPLIED WITH CMP G650 981431 AIRFRAME CB 143A MODIFICATION - LANDING GEAR CONTROL UNIT (LGCU) MOD D UPDATE (ASC 079) OFF: P/N 60P3230090Z002 (MOD C) S/N 016LG01053 ON: P/N 60P3230090Z002 (MOD D) S/N 016LG01088C ***REF 11.9 FOR OPS TEST***											
CB144 (981440) Airframe	CB144 - Fuselage Structure (ATA 53) - Inspection - Cockpit Windshield and Side Window Frame Corrosion		HRS		2755.9			766.5			0
			AFL		561		166		0		
			MOS		99.3		17 Sep 2016				
			MSC			-					
CB145 (981450) Airframe	CB145 - Electrical Power (ATA 24) - Inspection - Electrical Harness Support Bracket AT Fuselage Station 805		HRS		1841.9			1680.5			0
			AFL		384		343		0		
			MOS		73.7		03 Nov 2018				
			MSC			-					
CB147 (981470) Airframe	CB147 - Communications (ATA 23), Inspection - High Frequency Antenna Adapter Hardware		HRS		2312.5			1209.9			0
			AFL		479		248		0		
			MOS		87.3		18 Sep 2017				
			MSC			-					
CB150 (981500) Airframe	CB150 - Electrical Power (ATA 24), Inspection - 60 Hertz Outlets - 15 Ampere, P/N 106360-2		HRS		2755.9			766.5			0
			AFL		561		166		0		
			MOS		98.9		30 Sep 2016				
			MSC			-					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB152	CB152 - Stabilizers (ATA 55) Inspection - Horizontal		HRS		1508.2			2014.2			0
	Stabilizer Inboard Leading Edge Seal Installation		AFL		311			416			0
			MOS		63.3			16 Sep 2019			
	(981520)		MSC				-				
Airframe											
CB155	CB155 - Landing Gear (ATA 32), Modification - Main		HRS		3522.4			0			0
	Landing Gear and Brake Assembly (ASC 084)		AFL		727			0			0
			MOS		100.2			19 Aug 2016			
	(981550)		MSC				-				
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB155A	CB155A - Landing Gear (ATA 32) - Modification - Main		HRS		2755.9			766.5			0
	Landing Gear and Brake Assembly (ASC 084A)		AFL		561			166			0
			MOS		99.1			22 Sep 2016			
	(981551)		MSC				-				
Airframe											
CB155B	CB155B - Landing Gear (ATA 32), Modification - Main		HRS		2384			1138.4			0
	Landing Gear and Brake Assembly (ASC 084A)		AFL		491			236			0
			MOS		88.7			03 Aug 2017			
	(981552)		MSC				-				
Airframe											
Notes: FOUND PCW CB155 ON 09-21-2016 (TT 766.5 HR / 166 LDG)											
CB157	CB157 - Electrical Power (ATA 24), Installation - Auxiliary		HRS		3522.4			0			0
	Power Unit (APU) Generator Power Feeder Cables (ASC		AFL		727			0			0
	072)		MOS		93.3			16 Mar 2017			
	(981570)		MSC				-				
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB157A	CB157A - Electrical Power (ATA 24) - Installation Auxiliary		HRS		1722.5			1799.9			0
	Power Unit (APU) Generator Power Feeder Cables (ASC		AFL		351			376			0
	072)		MOS		68.7			05 Apr 2019			
	(981571)		MSC				-				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB158 (981580) Airframe	CB158 - Landing Gear (ATA 32), Modification - Tire Pressure Monitoring Unit (Tpmu) Software Upgrade		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.3			16 Sep 2018			
			MSC				-				
CB160 (981600) Airframe	CB160 - Engine and Fuel Control (ATA 73), Modification - Engine Electronic Controller (Eec) - K7.1.3 Software Upgrade (ASC 016)		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
CB160A (981601) Airframe	CB160A - Engine and Fuel Control (ATA 73), Modification - Engine Electronic Controller (Eec) - K7.1.3 Software Upgrade (ASC 016)		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			27 Sep 2017			
			MSC				-				
CB161 (981610) Airframe	CB161 - Engine and Fuel Control (ATA 73), Modification - Replacement of Fuel Low Pressure Switch (Rolls-Royce Sb-BR700-73-101965)		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
CB162 (981620) Airframe	CB162 - Engine and Fuel Control (ATA 73), Modification - Revised Fuel System (Rolls-Royce Sb-BR700-73-101957)		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			26 Sep 2017			
			MSC				-				
CB162A (981621) Airframe	CB162A - Engine and Fuel Control (ATA 73), Modification - Revised Fuel System (Rolls-Royce Sb-BR700-73-101957)		HRS		2312.5			1209.9			0
			AFL		479			248			0
			MOS		87			27 Sep 2017			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB164 (981640) Airframe	CB164 - Hydraulic Power (ATA 29), Inspection - Brake Hydraulic Lines AT Right Fuselage Station (FS) 761		HRS		1841.9			1680.5			0
			AFL		384			343			0
			MOS		73.7			03 Nov 2018			
			MSC				-				
CB165 (981650) Airframe	CB165 - Wings (ATA 57), Inspection - Flap Track D Fitting Fasteners		HRS		1841.9			1680.5			0
			AFL		384			343			0
			MOS		73.7			03 Nov 2018			
			MSC				-				
CB166 (981660) Airframe	CB166 - Electrical Power (ATA 24) - Modification - Secondary Power - Distribution System (Spds) Software - Update (ASC 051)		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		79.5			11 May 2018			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB166A (981661) Airframe	CB166A - Electrical Power (ATA 24) - Modification - Secondary Power Distribution System (Spds) Software Update (ASC 051)		HRS		1912.8			1609.6			0
			AFL		397			330			0
			MOS		75.3			17 Sep 2018			
			MSC				-				
CB167 (981670) Airframe	CB167 - Doors (ATA 52) - Inspection - Baggage Door Warning Switches		HRS		1841.9			1680.5			0
			AFL		384			343			0
			MOS		73.8			02 Nov 2018			
			MSC				-				
CB168 (981680) Airframe	CB168 - Doors (ATA 52), Inspection - Main Entrance Door Handrail Drive Fittings		HRS		2507.5			1014.9			0
			AFL		509			218			0
			MOS		91.1			22 May 2017			
			MSC				-				
Notes: CB176 HAS BEEN ACCOMPLISHED ON A/C S/N 6088											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB169A	CB169A - Equipment / Furnishings (ATA 25) - Modification - Forward Left Side Lavatory Wiring Installation		HRS		1508.2			2014.2		0	
			AFL		311		416		0		
			MOS		62.9		30 Sep 2019				
			MSC			-					
(981691)											
Airframe											
CB170	CB170 - Water / Waste (ATA 38), Modification - Removal of Water Sterilizer Filter End CAP SET Screw (Iwg-A6 Vendor Service Bulletin)		HRS		1722.5			1799.9		0	
			AFL		351		376		0		
			MOS		69		27 Mar 2019				
			MSC			-					
(981700)											
Airframe											
CB171	CB171 - Electrical Power (ATA 24), Inspection - Main Battery Ground Pads		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		95		26 Jan 2017				
			MSC			-					
(981710)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB171A	CB171A - Electrical Power (ATA 24) - Inspection - Main Battery Ground Pads		HRS		2312.5			1209.9		0	
			AFL		479		248		0		
			MOS		87.2		19 Sep 2017				
			MSC			-					
(981711)											
Airframe											
Notes: TW 558044DUE 1/18DLRO 570985DUE 2/18											
CB172	CB172 - Doors (ATA 52), Replacement - Main Entrance Door - Bottom Folding Step Stop Bolts (ASC 089)		HRS		2571.6			950.8		0	
			AFL		520		207		0		
			MOS		92.6		06 Apr 2017				
			MSC			-					
(981720)											
Airframe											
CB173	CB173 - Flight Controls (ATA 27) Inspection - Aileron Control Override Pushrod ROD End		HRS		1722.5			1799.9		0	
			AFL		351		376		0		
			MOS		69		26 Mar 2019				
			MSC			-					
(981730)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB174	CB174 - Flight Controls (ATA 27) - Inspection - Horizontal Stabilizer Trim Actuator Harness		HRS		1912.8			1609.6		0	
			AFL		397		330		0		
			MOS		75.1		23 Sep 2018				
			MSC			-					
(981740)											
Airframe											
CB175	CB175 - Electrical Power (ATA 24), Replacement Ram AIR Turbine (RAT) Control Handle Lockout Pin		HRS		2312.5			1209.9		0	
			AFL		479		248		0		
			MOS		87.3		18 Sep 2017				
			MSC			-					
(981750)											
Airframe											
CB176	CB176 - Doors (ATA 52), Replacement - Main Entrance Door Handrail Drive Fittings		HRS		2571.6			950.8		0	
			AFL		520		207		0		
			MOS		92.6		06 Apr 2017				
			MSC			-					
(981760)											
Airframe											
CB177	CB177 - Landing Gear (ATA 32), Inspection - Main Landing Gear Side Brace Actuator Band Clamps		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		70.6		07 Feb 2019				
			MSC			-					
(981770)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB177A	CB177A - Landing Gear (ATA 32) - Inspection - Main Landing Gear Side Brace Actuator Band Clamps (Rescinded and Superseded By CB239 & ASC117)		HRS		1722.5			1799.9		0	
			AFL		351		376		0		
			MOS		68.8		01 Apr 2019				
			MSC			-					
(981771)											
Airframe											
CB178	CB178 - Fuel (ATA 28), Inspection - Fuel Cell Over-Wing Wiring AT Fuselage Station 536		HRS		2312.5			1209.9		0	
			AFL		479		248		0		
			MOS		87.3		16 Sep 2017				
			MSC			-					
(981780)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB179 (981790) Airframe	CB179 - Electrical Power (ATA 24), Inspection - Tail Compartment Ground Pads		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		80.9			30 Mar 2018			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB179A (981791) Airframe	CB179A - Electrical Power (ATA 24) - Inspection - Tail Compartment Ground Pads		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		65.5			12 Jul 2019			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB179B (981792) Airframe	CB179B - Inspection – Tail Compartment Ground Pads		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		63.2			20 Sep 2019			
			MSC				-				
CB180 (981800) Airframe	CB180 - Fuselage (ATA 53), Inspection - Aft Mid Lower Drain Valves AT Fuselage Station 756		HRS		1722.5			1799.9			0
			AFL		351			376			0
			MOS		69			26 Mar 2019			
			MSC				-				
CB182 (981820) Airframe	CB182 - Doors (ATA 52), Replacement - Main Entrance Door Electrical Connectors		HRS		1841.9			1680.5			0
			AFL		384			343			0
			MOS		74			26 Oct 2018			
			MSC				-				
CB183 (981830) Airframe	CB183 - Doors (ATA 52), Inspection - Main Entrance Door Forward and Aft Lock Out Mechanical Stop Bracket Assemblies Sealing		HRS		1841.9			1680.5			0
			AFL		384			343			0
			MOS		73.9			29 Oct 2018			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB184	CB184 - Doors (ATA 52), Inspection - Main Entrance Door		HRS		2341.2			1181.2			0
	P-Clamp Orientation		AFL		484			243			0
			MOS		87.7			04 Sep 2017			
	(981840)		MSC				-				
Airframe											
Notes: FOUND INSTALLED CORRECTLY											
CB186 PART I	CB186 Part I - Flight Controls (ATA 27), Replacement -		HRS		2312.5			1209.9			0
	Flap Electronic Control Unit		AFL		479			248			0
			MOS		87.1			23 Sep 2017			
	(981860)		MSC				-				
Airframe											
CB186 PART II	CB186 Part II - Flight Controls (ATA 27), Replacement -		HRS		2312.5			1209.9			0
	Flap Electronic Control Unit		AFL		479			248			0
			MOS		87.1			23 Sep 2017			
	(981861)		MSC				-				
Airframe											
Notes: P/N: ON 60P2755001Z005 S/N: ON: 045											
CB187	CB187 - Landing Gear (ATA 32), Inspection - Nose		HRS		2341.2			1181.2			0
	Landing Gear Upper Torque ARM Pin		AFL		484			243			0
			MOS		87.7			04 Sep 2017			
	(981870)		MSC				-				
Airframe											
Notes: PN: C2E5251CA002 SN: 00642. REPLACED TORQUE ARM PIN. P/N OFF-ON C2E5251CA002, S/N OFF 00266, S/N ON 00642 (NEW)											
CB187A	CB187A - Landing Gear (ATA 32) - Inspection - Nose		HRS		1662			1860.4			0
	Landing Gear Upper Torque ARM Pin		AFL		340			387			0
			MOS		66.4			14 Jun 2019			
	(981871)		MSC				-				
Airframe											
Notes: PCW CB187 ON SEPT-04-2017, UNDER WO SAS380SE-17-039. NO FURTHER ACTION REQUIRED AT THIS TIME											
CB188	CB188 - Fuel (ATA 28), Inspection - Fuel Line Couplings		HRS		1903.6			1618.8			0
	In Pylon		AFL		397			330			0
			MOS		75.4			14 Sep 2018			
	(981880)		MSC				-				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB189 (981890) Airframe	CB189 - Landing Gear (ATA 32), Inspection - Main		HRS		3522.4			0			0
	Landing Gear Fairing Door Hinges		AFL		727			0			0
			MOS		73.8			02 Nov 2018			
			MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB189A (981891) Airframe	CB189A - Landing Gear (ATA 32) - Inspection - Main		HRS		1722.5			1799.9			0
	Landing Gear Fairing Door Hinges		AFL		351			376			0
			MOS		68.9			28 Mar 2019			
			MSC				-				
CB190 (981900) Airframe	CB190 - Pneumatic Systems (ATA 36), Inspection - Bleed		HRS		1722.5			1799.9			0
	AIR Manifold Gamah Couplers		AFL		351			376			0
			MOS		69			26 Mar 2019			
			MSC				-				
CB192 (981920) Airframe	CB192 - Electrical Wiring Installation (ATA 97) - Inspection		HRS		1912.8			1609.6			0
	- Electrical Wiring Secured to Hot AIR Ducts Below		AFL		397			330			0
	Baggage Floor		MOS		75.3			18 Sep 2018			
			MSC				-				
CB193 (981930) Airframe	CB193 - Landing Gear (ATA 32) Inspection - Nose		HRS		1722.5			1799.9			0
	Landing Gear Door Actuator Torque Tubes - Aft Bearings		AFL		351			376			0
			MOS		69			26 Mar 2019			
			MSC				-				
CB194 (981940) Airframe	CB194 - Hydraulic Power (ATA 29), Inspection - Hydraulic		HRS		1722.5			1799.9			0
	Return Tube AT Fuselage Station (FS) 1080 Left		AFL		351			376			0
			MOS		69			26 Mar 2019			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB195	CB195 - Doors (ATA 52), Replacement - Main Entrance		HRS		1841.9			1680.5			0
	Door Forward Hinge Water Closeout		AFL		384			343			0
			MOS		73.9			29 Oct 2018			
			MSC				-				
(981950)	Airframe										
CB196	CB196 - Doors (ATA 52) - Modification - Main Entrance		HRS		1841.9			1680.5			0
	Door Bottom Folding Step Mechanism Improvement (ASC 099)		AFL		384			343			0
			MOS		73.8			01 Nov 2018			
			MSC				-				
(981960)	Airframe										
CB197	CB197 - Flight Controls (ATA 27) Modification - Flight		HRS		1722.5			1799.9			0
	Control Computer (FCC) Software Upgrade 7.1 (ASC 093)		AFL		351			376			0
			MOS		68.9			29 Mar 2019			
			MSC				-				
(981970)	Airframe										
CB198	CB198 - Flight Controls (ATA 27) Inspection - Spoiler		HRS		1912.8			1609.6			0
	Electrical Backup Hydraulic Actuator (Ebha) Manifold		AFL		397			330			0
	(Parker Sb 479500-27-001)		MOS		75.1			23 Sep 2018			
			MSC				-				
(981980)	Airframe										
CB198A	CB198A - Flight Controls (ATA 27) - Inspection - Spoiler		HRS		1158			2364.4	0		0
	Electrical Backup Hydraulic Actuator (Ebha) Manifold		AFL		239			488	0		0
	(Parker Sb 479500-27-001) (Superseded By Cb 225)		DATE		1533 d			15 Oct 2020			
			MSC				-				
(981981)	Airframe										
CB199	CB199 - Flight Controls (ATA 27) Modification - Primary		HRS		1912.8			1609.6			0
	Flight Control Actuation System (Pfcas) Motor Control		AFL		397			330			0
	Electronics (Mce) Software Upgrade (ASC 092)		MOS		75.1			23 Sep 2018			
			MSC				-				
(981990)	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB200	CB200 - Flight Controls (ATA 27) Modification - Primary		HRS		1912.8			1609.6			0
	Flight Control Actuation System (Pfcas) Remote		AFL		397			330			0
	Electronics Unit (Reu) Connector Installation (ASC 097)		MOS		75.1			23 Sep 2018			
			MSC								
(982000)											-
Airframe											
CB201	CB201 - Flight Controls (ATA 27) Modification - Primary		HRS		1912.8			1609.6			0
	Flight Control Actuation System (Pfcas) Remote		AFL		397			330			0
	Electronics Unit (Reu) Software Upgrade (ASC 069)		MOS		75.1			23 Sep 2018			
			MSC								
(982010)											-
Airframe											
CB202	CB202 - Wings (ATA 57) - Inspection - Wiring Installation		HRS		1722.5			1799.9			0
	AT Outboard Flight Spoiler Attach Fittings		AFL		351			376			0
			MOS		68.9			28 Mar 2019			
			MSC								
(982020)											-
Airframe											
CB203	CB203 - Electrical Power (ATA 24) Inspection - Wire		HRS		1722.5			1799.9			0
	Routing on Reer Forward Bulkhead		AFL		351			376			0
			MOS		69			26 Mar 2019			
			MSC								
(982030)											-
Airframe											
CB204	CB204 - Flight Controls (ATA 27) Modification - Horizontal		HRS		3522.4			0			0
	Stabilizer Control Unit (Hscu) MOD 4 (ASC 098)		AFL		727			0			0
			MOS		79.1			24 May 2018			
			MSC								
(982040)											-
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB204A	CB204A - Flight Controls (ATA 27) - Modification -		HRS		1912.8			1609.6			0
	Horizontal Stabilizer Control Unit (Hscu) Hardware MOD 4		AFL		397			330			0
	Verification and Software Update (ASC 098)		MOS		75.1			23 Sep 2018			
			MSC								
(982041)											-
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB204B	CB204B - Flight Controls (ATA 27) Modification –		HRS		1765.6			1756.8			0
	Horizontal Stabilizer Control Unit (Hscu) Hardware MOD 4		AFL		363			364			0
	Verification and Software Update (ASC 098)		MOS		71			25 Jan 2019			
			MSC								
(982042)											
Airframe											
Notes: FOUND PREVIOUSLY COMPLIED WITH THRU INCORPORATION OF CB204A ON SEPT-23-2018 (ATT 1609.6 HR / 330 LDG) - GDAS SAV											
CB205	CB205 - Fuselage (ATA 53), Replacement - Cabin		HRS		485.9			3036.5			0
	Floorboard 7D		AFL		97			630			0
			MOS		26.3			18 Oct 2022			
			MSC								
(982050)											
Airframe	[End Of Month Item]										
CB206	CB206 - Equipment and Furnishings (ATA 25) - Life Raft		HRS		3522.4			0			0
	Gas Cylinder Replacement AT Overhaul (Utas Sb 25-470)		AFL		727			0			0
			MOS		79.3			18 May 2018			
			MSC								
(982060)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. ALIGNED WITH LIFE RAFT RESTORES											
CB206A	CB206A - Equipment and Furnishings (ATA 25) - Life Raft		HRS		388.2			3134.2			0
	Gas Cylinder Replacement AT Overhaul (Utas Sb 25-470)		AFL		76			651			0
			MOS		22.3			17 Feb 2023			
			MSC								
(982061)											
Airframe											
CB206B	CB206B - Equipment and Furnishings (ATA 25) - Life Raft		HRS		873.6			2648.8			0
	Gas Cylinder Replacement AT Overhaul (Utas Sb 25-470 /		AFL		166			561			0
	Sb 25-476)		MOS		38.6			08 Oct 2021			
			MSC								
(982062)											
Airframe											
CB207	CB207 - Electrical Power (ATA 24) - Inspection - Wire		HRS		1158			2364.4			0
	Routing Aft Equipment Bay and Wheel Well		AFL		239			488			0
			MOS		50.6			07 Oct 2020			
			MSC								
(982070)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB208	CB208 - Landing Gear (ATA 32) - Inspection - Main		HRS		1912.8			1609.6			0
	Landing Gear Axle Fitting Assembly (UTC Aerospace Sb		AFL		397			330			0
	C1A5400-32-009)		MOS		75			25 Sep 2018			
			MSC								
(982080)											-
Airframe											
CB208A	CB208A - Landing Gear (ATA 32) - Inspection - Main		HRS		1158			2364.4	0		0
	Landing Gear Axle Fitting Assembly (UTC Aerospace Sb		AFL		239			488	0		0
	C1A5400-32-009)		DATE		1533 d			15 Oct 2020			
			MSC								
(982081)											-
Airframe											
CB208B	CB208B - Landing Gear (ATA 32) - Inspection - Main		HRS		1158			2364.4			0
	Landing Gear Axle Fitting Assembly (UTC Aerospace Sb		AFL		239			488			0
	C1A5400-32-009)		MOS		50.2			19 Oct 2020			
			MSC								
(982082)											-
Airframe											
CB208C	CB208C - CB208C - Landing Gear (ATA 32) - Inspection -		HRS		339.5			3182.9			0
	Main Landing Gear Axle Fitting Assembly (UTC		AFL		69			658			0
	Aerospace Sb C1A5400-32-009), (No Longer Required.)		MOS		20.2			20 Apr 2023			
			MSC								
(982083)											-
Airframe											
CB211	CB211 - Flight Controls (ATA 27) Inspection - Flight		HRS		1508.2			2014.2			0
	Controls Wiring Harness Installation Under Electrical		AFL		311			416			0
	Backup Hydraulic Actuator (Ebha) Battery		MOS		63.2			19 Sep 2019			
			MSC								
(982110)											-
Airframe											
CB213A PART I	CB213A Part I - Flight Controls (ATA 27) - Replacement -		HRS		3522.4			0			0
	Flap Hydraulic Power Drive Unit		AFL		727			0			0
			MOS		73.8			01 Nov 2018			
			MSC								
(982132)											-
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB213A PART II	CB213A Part Ii - Flight Controls (ATA 27) - Replacement - Flap Hydraulic Power Drive Unit		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		73.8		01 Nov 2018				
			MSC			-					
(982133)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB213B PART I	CB213B Part I -		HRS		1722.5			1799.9		0	
			AFL		351		376		0		
			MOS		69		26 Mar 2019				
			MSC			-					
(982134)											
Airframe											
Notes: PDU S/N: 0059 (NOT AFFECTED)											
CB213B PART II	CB213B Part Ii -		HRS		1722.5			1799.9		0	
			AFL		351		376		0		
			MOS		69		26 Mar 2019				
			MSC			-					
(982135)											
Airframe											
CB214	CB214 - Equipment and Furnishings (ATA 25) - Electronic Control Unit (Ecu) Software for Vip Seats(RCO Sb RCO2017-10-12-1)		HRS		1912.8			1609.6		0	
			AFL		397		330		0		
			MOS		75.2		20 Sep 2018				
			MSC			-					
(982140)											
Airframe											
CB215	CB215 - Equipment / Furnishings (ATA 25) - Modification - Forward Left Side Lavatory Cabinet Wiring Installation (GPM412004707-301 Monument)		HRS		1508.2			2014.2		0	
			AFL		311		416		0		
			MOS		63		26 Sep 2019				
			MSC			-					
(982150)											
Airframe											
CB220	CB220 - FIRE Protection (ATA 26) - Modification - Engine FIRE Bottle Harness (ASC 111)		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		69.1		22 Mar 2019				
			MSC			-					
(982200)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB220A	CB220A - FIRE Protection (ATA 26) - Modification - Engine FIRE Bottle Harness (ASC 111)		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		63			26 Sep 2019			
			MSC					-			
(982201)											
Airframe											
CB221	CB221 - Hydraulic Power (ATA 29) - Modification - Auxiliary Hydraulic Pump Grounding Installation (ASC 103)		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.8			02 Oct 2021			
			MSC					-			
(982210)											
Airframe											
CB223	CB223 - Fuselage Structure (ATA 53) - Inspection / Modification - Fuselage Skin and APU Exhaust Fairing (ASC 113)		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.4			15 Oct 2020			
			MSC					-			
(982230)											
Airframe											
CB224	CB224 - Engine Fuel and Control (ATA 73) - Modification - Engine Electronic Controller (Eec) K8.0.2 Software Upgrade (ASC 088)		HRS		1722.5			1799.9			0
			AFL		351			376			0
			MOS		68.7			04 Apr 2019			
			MSC					-			
(982240)											
Airframe											
CB225	CB225 - Flight Controls (ATA 27) - Retrofit of Electrical Backup (Eb) Hydraulic Manifolds		HRS		3522.4			0	0		0
			AFL		727			0	0		0
			DATE								
			MSC					-			
(982250)											
Airframe											
CB225A	CB225A - Flight Controls (ATA 27) - Retrofit of Electrical Backup (Eb) Hydraulic Manifolds		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.9			29 Sep 2021			
			MSC					-			
(982251)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB226	CB226 - Flight Controls (ATA 27) - Inspection - Motor Control Electronics (Mce) J3 Connector (Parker Sb 469300-27-002 and Sb 469400-27-002)		HRS		873.6			2648.8		0	
			AFL		166		561		0		
			MOS		38.9		29 Sep 2021				
			MSC				-				
(982260)											
Airframe											
CB227	CB227 - Flight Controls (ATA 27) - Inspection - Aileron Motor Control Electronics (Mce) and Outboard Spoiler J-Box Connectors		HRS		873.6			2648.8		0	
			AFL		166		561		0		
			MOS		38.9		29 Sep 2021				
			MSC				-				
(982270)											
Airframe											
CB228	CB228 - Navigation (ATA 34) - AIR Data Probe Heat Fault Monitoring - Loadable Diagnostic Information(Ldi) Update		HRS		1508.2			2014.2		0	
			AFL		311		416		0		
			MOS		63		25 Sep 2019				
			MSC				-				
(982280)											
Airframe											
CB231	CB231 - Flight Controls (ATA 27) - Modification - Flight Control Computer (FCC) Software Upgrade 8.2 (ASC 102)		HRS		1722.5			1799.9		0	
			AFL		351		376		0		
			MOS		68.9		29 Mar 2019				
			MSC				-				
(982310)											
Airframe											
CB232	CB232 - FIRE Protection (ATA 26) - Inspection - Right Engine FIRE Bottle Electrical Harness		HRS		3522.4			0		0	
			AFL		727		0		0		
			MOS		72.7		05 Dec 2018				
			MSC				-				
(982320)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB232A	CB232A - FIRE Protection (ATA 26) - Inspection - Right Engine FIRE Bottle Electrical Harness		HRS		1722.5			1799.9		0	
			AFL		351		376		0		
			MOS		69		26 Mar 2019				
			MSC				-				
(982321)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB233	CB233 - Engine Starting (ATA 80) - Replacement - BR725		HRS		3522.4			0			0
	Engine Starter AIR Valve (Rolls Royce Nmsb Sb-BR700-80-900634)		AFL		727			0			0
			MOS		66.5			11 Jun 2019			
			MSC				-				
(982330)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB233A	CB233A -		HRS		1508.2			2014.2	0		0
			AFL		311			416	0		0
			MOS		63.2			20 Sep 2019			
			MSC				-				
(982331)											
Airframe											
CB233B	CB233B - Cb 233 - Engine Starting (ATA 80) -		HRS								0
	Replacement - BR725 Engine Starter AIR Valve - (Rolls		AFL								0
	Royce Nmsb Sb-BR700-80-900634)		DATE								
			MSC				-				
(982332)											
Airframe											
CB236	CB236 - Powerplant (ATA 71) - Inspection - Forward		HRS		3522.4			0			0
	Upper Engine Mount Fitting Contact With Pylon Seal		AFL		727			0			0
	Retainer (ASC 124)		MOS		70.8			01 Feb 2019			
			MSC				-				
(982360)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB236A	CB236A - Powerplant (ATA 71) - Inspection - Forward		HRS		485.9			3036.5			0
	Upper Engine Mount Fitting Contact With Pylon Seal		AFL		97			630			0
	Retainer (ASC 124)		MOS		26.5			12 Oct 2022			
			MSC				-				
(982361)											
Airframe											
CB239	CB239 - Landing Gear (ATA 32) - Modification - Main		HRS		1722.5			1799.9			0
	Landing Gear Side Brace Actuator Configuration and		AFL		351			376			0
	Clearance (ASC 117)		MOS		68.8			01 Apr 2019			
			MSC				-				
(982390)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB240	CB240 - Electrical Power (ATA 24) - Modification - Battery Charger, P/N 100-1311-01, Upgrade to MOD 11		HRS		1508.2			2014.2			0
			AFL		311			416			0
			MOS		62.9			29 Sep 2019			
			MSC				-				
(982400)											
Airframe											
CB241	CB241 - Landing Gear (ATA 32) - Replacement - Main Landing Gear Shock Struts		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.9			28 Oct 2022			
			MSC				-				
(982410)											
Airframe											
CB241A	CB241A - CB241A - Landing Gear (ATA 32) - Replacement - Main Landing Gear Shock Strut (No Longer Required)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(982411)											
Airframe											
CB242	CB242 - Electrical Power (ATA 24) - Modification - Remove Battery Charger MODE Control Relays (ASC 116)		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.2			20 Oct 2020			
			MSC				-				
(982420)											
Airframe											
CB245	CB245 - FIRE Protection (ATA 26) - Inspection - Left Engine FIRE Bottle Ground Terminals		HRS		3522.4			0			0
			AFL		727			0			0
			MOS		64.4			13 Aug 2019			
			MSC				-				
(982450)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
CB245A	CB245A - FIRE Protection (ATA 26) - Inspection - Left Engine FIRE Bottle Ground Terminals		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.6			07 Oct 2020			
			MSC				-				
(982451)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB246	CB246 - Engine (ATA 72) - Inspection - High Pressure Compressor Variable Stator Vanes Mechanism (Rolls-Royce Nmsb SBBR700-72-900178)		HRS		1585.8			1936.6			0
			AFL		321			406			0
			MOS		65			25 Jul 2019			
(982460)											
Airframe											
Notes: TW 574813 DUE 07/20TW 569509 DUE 09/19TW 561051 DUE 11/19											
CB247	CB247 - Wings (ATA 57) - Inspection - Wing Internal - Ignition Source Protection Sealant (Triumph G650 Wing Service Bulletin MAA7-71258-07_TGI)		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.1			24 Oct 2022			
(982470)											
Airframe											
CB248	CB248 - Electrical Power (ATA 24) - Inspection - Wire Routing Flight Deck and Vestibule		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.6			07 Oct 2020			
(982480)											
Airframe											
CB249	CB249 - Auxiliary Power Unit (ATA 49) - Update - APU Electronic Control Unit Software (ASC 123)		HRS		1722.5			1799.9	0		0
			AFL		351			376	0		0
			MOS		68.7			05 Apr 2019			
(982490)											
Airframe											
CB249A	CB249A - Auxiliary Power Unit (ATA 49) - Update - APU Electronic Control Unit Software (ASC 123)		HRS		1265.4			2257			0
			AFL		259			468			0
			MOS		55.6			08 May 2020			
(982491)											
Airframe											
CB250	CB250 - Electrical Power (ATA 24) - Inspection - Wire Routing Cabin and Baggage Compartment		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5			12 Oct 2022			
(982500)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB251	CB251 - Flight Controls (ATA 27) - Modification - Flap Electronic Control Unit (Fecu) Software (ASC 110)		HRS		1508.2			2014.2			0
			AFL		311			416		0	
			MOS		63			25 Sep 2019			
			MSC				-				
(982510)											
Airframe											
CB252	CB252 - Communications (ATA 23) - Modification - Jetwave System BLV7.1 Software Release (Honeywell Sb Jetwave-23-0007)		HRS		1263.9			2258.5			0
			AFL		258			469		0	
			MOS		53.8	-32		01 Jul 2020			
			MSC				-				
(982520)											
Airframe											
CB253	CB253 - Engine Fuel and Control (ATA 73) - Modification - Engine Electronic Controller (Eec) - K9.0.1 Software Upgrade (ASC 133)		HRS		1566.2			1956.2			0
			AFL		319			408		0	
			MOS		64.5			10 Aug 2019			
			MSC				-				
(982530)											
Airframe											
CB254	CB254 - Electrical Power (ATA 24) - Inspection - Wire Routing Vestibule Outboard of Left Electronic Equipment Rack (Leer)		HRS		1039.9			2482.5			0
			AFL		216			511		0	
			MOS		38.9			28 Sep 2021			
			MSC				-				
(982540)											
Airframe											
CB257	CB257 - Ignition (ATA 74) - Replacement of Engine Igniter Plugs With P/N CH34760-2 (Rolls-Royce Sb-BR700-74-102003)		HRS		1265.4			2257			0
			AFL		259			468		0	
			MOS		56.8			31 Mar 2020			
			MSC				-				
(982570)											
Airframe											
CB259	CB259 - Hydraulic Power (ATA 29) - Hydraulic Filter Monitoring System - Installation and Activation (ASC 090)		HRS		873.6			2648.8			0
			AFL		166			561		0	
			MOS		38.6			08 Oct 2021			
			MSC				-				
(982590)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB261	CB261 - Doors (ATA 52) - Inspection - Main Entrance		HRS								0
	Door Wiring Harness Installation		AFL								0
			MOS								
			MSC				-				
(982610)											
Airframe											
CB261A	CB261A - CB261A - Doors (ATA 52), Inspection - Main		HRS		873.6			2648.8			0
	Entrance Door Wiring Harness Installation		AFL		166			561			0
			MOS		38.9			29 Sep 2021			
			MSC				-				
(982611)											
Airframe											
CB262	CB262 - Wings (ATA 57) - Modification - Flap Track D Rub		HRS		1158			2364.4			0
	Strips Removal (ASC 083)		AFL		239			488			0
			MOS		49.7			05 Nov 2020			
			MSC				-				
(982620)											
Airframe											
CB263	CB263 - Information Systems (ATA 46) - Modification -		HRS		1158			2364.4			0
	Aircraft Health and Trend Monitoring System - Software		AFL		239			488			0
	Update 2 (ASC 076B)		MOS		50.5			12 Oct 2020			
			MSC				-				
(982630)											
Airframe											
CB264	CB264 - Wings (ATA 57) - Inspection - Winglet Attach		HRS								0
	Joints		AFL								0
			DATE								
			MSC				-				
(982640)											
Airframe											
CB264A	CB264A - Wings (ATA 57), Inspection - Winglet Attach		HRS		873.6			2648.8			0
	Joints		AFL		166			561			0
			MOS		38.9			29 Sep 2021			
			MSC				-				
(982641)											
Airframe											
CB265	CB265 - Flight Controls (ATA 27) , Modification of Rudder		HRS		1128.3			2394.1			0
	Trailing Edge (ASC 134)		AFL		232			495			0
			MOS		47.1			24 Jan 2021			
			MSC				-				
(982650)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB266	CB266 - Navigation (ATA 34) - Inspection - Ahru Connectors		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5			10 Oct 2022			
			MSC				-				
(982660)											
Airframe											
CB267	CB267 - Electrical Wiring Installations (ATA 97) - Inspection - Below-Floors Wiring Installation AT Fuselage Station (FS) 370		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5			10 Oct 2022			
			MSC				-				
(982670)											
Airframe											
CB268	CB268 - Nacelles and Pylons (ATA 54) - Inspection - Pylon Wiring Installation for Contact With Pylon Rib Openings		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.1			22 Oct 2020			
			MSC				-				
(982680)											
Airframe											
CB269	CB269 - Fuselage Structure (ATA 53) - Inspection - Horizontal Drag Brace Splice Fasteners AT Fuselage Station (FS) 245.5		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.4			13 Oct 2020			
			MSC				-				
(982690)											
Airframe											
CB271	CB271 - Lighting (ATA 33) - Replacement - Cockpit Lighting Control Panels - Connector Plate Retaining Screws		HRS		1158			2364.4			0
			AFL		239			488			0
			MOS		50.6			08 Oct 2020			
			MSC				-				
(982710)											
Airframe											
CB272	CB272 - Engine AIR (ATA 75) - Replacement - Stage 5 Handling Bleed Valves (Rolls-Royce Sb-BR700-75-900673)		HRS		1158			2364.4	0		0
			AFL		239			488	0		0
			MOS		50.4			15 Oct 2020			
			MSC				-				
(982720)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB272A	CB272A - Engine AIR (ATA 75) - Replacement - Stage 5		HRS		1158			2364.4			0
	Handling Bleed Valves (Rolls-Royce Sb-BR700-75-		AFL		239			488			0
	900673)		MOS		49.6			06 Nov 2020			
			MSC				-				
(982721)											
Airframe											
Notes: PCW ASC272A REF. WO SC649627 ITEM 14.2 FOR COMPLIANCE OF ASC272											
CB273	CB273 - Electrical Power (ATA 24) - Inspection - Busbar		HRS		873.6			2648.8			0
	for Ebha Battery Charger No. 1, Voltage Output Circuitry		AFL		166			561			0
			MOS		38.9			29 Sep 2021			
			MSC				-				
(982730)											
Airframe											
CB276	CB276 - Flight Controls (ATA 27) - Flight Control		HRS		873.6			2648.8			0
	Computer (FCC) Software Update V10.1 (ASC 135)		AFL		166			561			0
			MOS		38.9			29 Sep 2021			
			MSC				-				
(982760)											
Airframe											
CB277	CB277 - FIRE Protection (ATA 26) - Modification - Engine		HRS		113.9			3408.5			0
	FIRE Extinguishing Bottle Cartridge Wiring (ASC 122)		AFL		36			691			0
			MOS		14.1			22 Oct 2023			
			MSC				-				
(982770)											
Airframe											
CB277A	CB277A - CB277A - FIRE Protection (ATA 26) -		HRS		113.9			3408.5			0
	Modification - Engine FIRE Extinguishing Bottle Cartridge		AFL		36			691			0
	Wiring (ASC 122)		MOS		13.8			02 Nov 2023			
			MSC				-				
(982771)											
Airframe											
CB278	CB278 - Wings (ATA 57) - Inspection - Unprimed Wing		HRS								0
	Skin Fasteners Inboard of Rear Beam Station (Rbs) 62		AFL								0
			DATE								
			MSC				-				
(982780)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB278A	CB278A - Wings (ATA 57) - Inspection - Unprimed Wing Skin Fasteners Inboard of Rear Beam Station (Rbs) 62		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.2		19 Oct 2022				
			MSC				-				
(982781)											
Airframe											
CB279	CB279 - Landing Gear (ATA 32) - Inspection - Main Landing Gear Sponson Beam Upper Inboard Shim		HRS								0
			AFL							0	
			MOS								
			MSC				-				
(982790)											
Airframe											
CB279A	CB279A - Landing Gear (ATA 32) - Inspection - Main Landing Gear Sponson Beam Upper Inboard Shim		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.3		17 Oct 2022				
			MSC				-				
(982791)											
Airframe											
CB280	CB280 - Stabilizers (ATA 55) - Inspection - Right Side Horizontal Stabilizer - Clamp Installation (Fokker Sb Gf-20 -0011)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
(982800)											
Airframe											
CB281	CB281 - CB281 - FIRE Protection (ATA 26) - Inspection - Left FIRE Bottle/APU Cartridge Wire Harness Shield Ground		HRS		485.9			3036.5			0
			AFL		97			630		0	
			MOS		26.8		02 Oct 2022				
			MSC				-				
(982810)											
Airframe											
CB282	CB282 - CB282 - Wings (ATA 57) - Replacement - Flap Track B Close-Out Skin		HRS								0
			AFL							0	
			DATE								
			MSC				-				
(982820)											
Airframe											
CB282A	CB282A - CB282A - Wings (ATA 57) - Replacement - Flap Track B Close-Out Skin		HRS								0
			AFL							0	
			MOS								
			MSC				-				
(982821)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB282B	CB282B - CB282B - Wings (ATA 57) - Replacement - Flap Track B Close-Out Skin		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.9			28 Oct 2022			
			MSC				-				
(982822)											
Airframe											
CB282C	CB282C - CB282C - Wings (ATA 57) - Replacement - Flap Track B Close-Out Skin		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.1			22 Oct 2023			
			MSC				-				
(982823)											
Airframe											
CB283	CB283 - CB283 - Engine Fuel & Control (ATA 73) - Modification - Engine Electronic Controller (Eec) - K10.1 Software Upgrade (ASC 138)		HRS								0
			AFL								0
			MOS								
			MSC				-				
(982830)											
Airframe											
CB283A	CB283A - CB283A - Engine Fuel and Control (ATA 73) - Modification - Engine Electronic Controller (Eec) - K10.1 Software Upgrade (ASC 138)		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7			05 Oct 2022			
			MSC				-				
(982831)											
Airframe											
CB284	CB284 - CB284 - Hydraulic Power (ATA 29) - Inspection - Hydraulic Shut-Off Valve Actuator Mounting Screws		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.5			11 Nov 2022			
			MSC				-				
(982840)											
Airframe											
CB285	CB285 - Communications (ATA 23) - Modification - Jetwave System BLV8.1 Software Release (Honeywell Sb Jetwave-23-0009)		HRS								0
			AFL								0
			MOS								
			MSC				-				
(982850)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB285A	CB285A - Communications (ATA 23) - Modification - Jetwave System BLV8.1 Software Release (Honeywell Sb Jetwave-23-0009)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(982851)											
Airframe											
CB286	CB286 - CB286 - Fuselage Structure (ATA 53) Inspection - Wiring Mounting and Bracket Installation AT FS 942.5		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.8			02 Oct 2022			
			MSC				-				
(982860)											
Airframe											
CB287	CB287 - CB287 - Stabilizers (ATA 55) - Inspection - Horizontal Stabilizer Wiring Installation (Fokker Sb Gf-19- 0015)		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5			12 Oct 2022			
			MSC				-				
(982870)											
Airframe											
CB288	CB288 - CB288 - Flight Controls (ATA 27) - Inspection - Fly-By-Wire Harness - Clamp Installation AT Fuselage Stations 733.2 and 1019.19		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.8			02 Oct 2022			
			MSC				-				
(982880)											
Airframe											
CB289	CB289 - Powerplant (ATA 71) - Inspection - Engine Cowl Hinge Lines (Rolls-Royce Sb-BR700-71-900701)		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.1			22 Oct 2023			
			MSC				-				
(982890)											
Airframe											
CB289A	CB289A - Powerplant (ATA 71), Inspection - Engine Cowl Hinge Lines (Rolls-Royce Sb-BR700-71-900701)		HRS								0
			AFL								0
			MOS								
			MSC				-				
(982891)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB289B	CB289B - Powerplant (ATA 71), Inspection - Engine Cowl Hinge Lines (Rolls-Royce Sb-BR700-71-900701)		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.1			23 Nov 2022			
			MSC				-				
(982892)											
Airframe											
CB289D	Powerplant (ATA 71) - Inspection - Engine Cowl Hinge Lines (Rolls-Royce Sb-BR700-71-900701), Customer Bulletin (Mandatory)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.8			02 Oct 2024			
			MSC				-				
(982894)											
Airframe											
CB290	CB290 - CB290 - Flight Controls (ATA 27) - Inspection - Flap Track B Outboard Roller Fitting Hardware		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.1			23 Nov 2022			
			MSC				-				
(982900)											
Airframe											
CB291	CB291 - CB291 - Electrical Wiring Installations (ATA 97), Inspection - Vertical Fin Connectors		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.5			10 Oct 2022			
			MSC				-				
(982910)											
Airframe											
CB292	CB292 - CB292 - Fuselage Structure (ATA 53) - Inspection - Auxiliary Power Unit Enclosure		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		24.9			29 Nov 2022			
			MSC				-				
(982920)											
Airframe											
CB293	CB293 - Fuel (ATA 28) Inspection - Fuel Tank Distribution System Components - Sealant Application		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		25.1			23 Nov 2022			
			MSC				-				
(982930)											
Airframe											
CB293A	CB293A - Fuel (ATA 28) - Inspection - Fuel Tank Distribution System Components - Sealant Application, Customer Bulletin		HRS								0
			AFL								0
			MOS								
			MSC				-				
(982931)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB293B (982932) Airframe	CB293B - Fuel (ATA 28), Inspection - Fuel Tank Distribution System Components - Sealant Application		HRS								0
			AFL								0
			DATE								
			MSC				-				
CB293C (982933) Airframe	CB293C - Fuel (ATA 28), Inspection - Fuel Tank Distribution System Components - Sealant Application		HRS		485.9			3036.5			0
			AFL		97			630			0
			DATE		758 d			29 Nov 2022			
			MSC				-				
CB294 (982940) Airframe	CB294 - CB294 - Inspection – Engine FIRE Bottle Thermal Relief Discharge Port		HRS		485.9			3036.5			0
			AFL		97			630			0
			MOS		26.7			03 Oct 2022			
			MSC				-				
CB295 (982950) Airframe	CB295 - CB295 - Doors (ATA 52) - Inspection - Main Entrance Door Electrical Harness Installation		HRS		424.7			3097.7			0
			AFL		86			641			0
			MOS		23.1			23 Jan 2023			
			MSC				-				
CB296 (982960) Airframe	CB296 - Fuselage (ATA 53) - Inspection - Electrical Connector Identification Decal - FS 224		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.1			23 Oct 2023			
			MSC				-				
CB297 (982970) Airframe	CB297 - CB297 - Flight Controls (ATA 27) - Inspection - Horizontal Stabilizer Part Number		HRS		113.9			3408.5			0
			AFL		36			691			0
			MOS		14.1			22 Oct 2023			
			MSC				-				
CB298 (982980) Airframe	CB298 - Electrical Power (ATA 24) - Inspection - Aircraft Main Batteries (Saft SB0323), Customer Bulletin (Mandatory)		HRS		285.9			3236.5			0
			AFL		61			666			0
			MOS		18.4			15 Jun 2023			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB298B	Electrical Power (ATA 24) - Inspection - Aircraft Main Batteries (Saft SB0323), Customer Bulletin (Mandatory)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.8			02 Oct 2024			
			MSC				-				
(982982)											
Airframe											
CB299	CB299 - Information Systems (ATA 46) - Modification - Aircraft Health and Trend Monitoring System (Ahtms) - Software Update (ASC 140), Customer Bulletin (Mandatory)		HRS		234.4			3288			0
			AFL		55			672			0
			MOS		16.5			11 Aug 2023			
			MSC				-				
(982990)											
Airframe											
CB300	CB300 - Landing Gear (ATA 32) - Inspection - Nose Landing Gear Control Manifold Connector, Customer Bulletin (Mandatory)		HRS		234.4			3288			0
			AFL		55			672			0
			MOS		16.5			11 Aug 2023			
			MSC				-				
(983000)											
Airframe											
CB300A	CB300A - Landing Gear (ATA 32) - Inspection - Nose Landing Gear Control Manifold Connector, Customer Bulletin (Mandatory)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.8			02 Oct 2024			
			MSC				-				
(983001)											
Airframe											
CB301	CB301 - Electrical Power (ATA 24) - Inspection - Cockpit Electrical Wire Harness Terminations, Customer Bulletin (Mandatory)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			11 Oct 2024			
			MSC				-				
(983010)											
Airframe											
CB302	CB302 - Flight Controls (ATA 27) - Inspection - Flap Actuator Attach Fitting Hardware, Customer Bulletin (Mandatory)		HRS		.4			3522			0
			AFL		1			726			0
			MOS		2.5			11 Oct 2024			
			MSC				-				
(983020)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB303	CB303 - Navigation (ATA 34) - Modification - Weather		HRS		113.9			3408.5			0
	Radar System Processor V4 Software Release		AFL		36			691			0
	(Honeywell Sb 930-1003-34-0008), Customer Bulletin		MOS		13.8			02 Nov 2023			
	(Mandatory)		MSC				-				
(983030)											
Airframe											
CB303A	CB303A - Navigation (ATA 34) - Modification - Weather		HRS		.4			3522			0
	Radar System Processor V4 Software Release		AFL		1			726			0
	(Honeywell Sb 930-1003-34-0008), Customer Bulletin		MOS		2.4			13 Oct 2024			
	(Mandatory)		MSC				-				
(983031)											
Airframe											
CB304	CB304 - Equipment and Furnishings (ATA 25) -		HRS		113.9			3408.5			0
	Installation - Ebha Pdb Terminal Bracket Cover (ASC		AFL		36			691			0
	146), Customer Bulletin (Mandatory)		MOS		14.1			22 Oct 2023			
			MSC				-				
(983040)											
Airframe											
CB305	CB305 - Communications (ATA 23) - Replacement -		HRS		.4			3522			0
	Satellite Data Units (Sdu) DL150-00, Customer Bulletin		AFL		1			726			0
	(Mandatory)		MOS		2.8			02 Oct 2024			
			MSC				-				
(983050)											
Airframe											
CB306	CB306 - Navigation (ATA 34) Inspection - Ahru		HRS		.4			3522			0
	Connectors With Pitch and Roll Information Recorded and		AFL		1			726			0
	the Installation of Ahru Labels ASC 144, Customer Bulletin		MOS		3.1			23 Sep 2024			
	(Mandatory)		MSC				-				
(983060)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB307	CB307 - Water/Waste (ATA 38) - Inspection - Forward		HRS		13.2			3509.2			0
	(Fwd) Water Tank Attachment Clip and Sensor Connector		AFL		7			720			0
	Orientation, Customer Bulletin (Mandatory)		MOS		4.9			30 Jul 2024			
			MSC				-				
(983070)											
Airframe											
CB307A	CB307A - Water/Waste (ATA 38) - Inspection - Forward		HRS								0
	(Fwd) Water Tank Attachment Clip and Sensor Connector		AFL								0
	Orientation, Customer Bulletin (Mandatory)		MOS				24**		19 Jun 2026		
(983071)											
Airframe											
CB308	CB308 - Water / Waste (ATA 38) - Inspection - Water		HRS		13.2			3509.2			0
	Sterilizer Bonding Jumper Cable Installation, Customer		AFL		7			720			0
	Bulletin (Mandatory)		MOS		4.9			30 Jul 2024			
			MSC				-				
(983080)											
Airframe											
CB309	CB309 - Electrical Power (ATA 24) - Inspection - Electrical		HRS								0
	Backup Hydraulic Actuator (Ebha) Power Distribution Box		AFL								0
	(Pdb), Customer Bulletin (Mandatory)		MOS								
			MSC				-				
(983090)											
Airframe											
CB310	CB310 - Flight Controls (ATA 27), Inspection - Horizontal		HRS								0
	Stabilizer Trim Actuator (Hsta) Gearbox Leak Test (Safran		AFL								0
	Sb 822-2533-004-27-02), Customer Bulletin (Mandatory)		MOS								
			MSC				-				
(983100)											
Airframe											
CB311	CB311 - Landing Gear (ATA 32), Inspection - Nose		HRS								0
	Landing Gear (NLG) Weight on Wheels (Wow) Sensor		AFL								0
	Connectors, Customer Bulletin (Mandatory)		MOS								
			MSC				-				
(983110)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB312	CB312 - Landing Gear (ATA 32) - Replacement - Main		HRS								0
	Landing Gear (MLG) and Nose Landing Gear (NLG)		AFL								0
	Electrical Harnesses, Customer Bulletin (Mandatory)		MOS								
			MSC				-				
(983120)											
Airframe											
CB313	CB313 - Wings (ATA 57) - Replace - Leading Edge Vent		HRS								0
	Seal, Customer Bulletin (Mandatory)		AFL								0
			MOS								
			MSC				-				
(983130)											
Airframe											
CB314	CB314 - Flight Controls (ATA 27) - Replacement - Flight		HRS								0
	Control Computer (FCC) Channel B Com-Mon Modules,		AFL								0
	Customer Bulletin (Mandatory)		MOS								
			MSC				-				
(983140)											
Airframe											
CB315	CB315 - Equipment and Furnishings (ATA 25) -		HRS								0
	Replacement - Divan Seatbelt Inertia Reel Frame,		AFL								0
	Customer Bulletin (Mandatory)		MOS								
			MSC				-				
(983150)											
Airframe											
CB316	CB316 - Landing Gear (ATA 32) - Inspection - Nose		HRS								0
	Landing Gear Pins, Customer Bulletin (Mandatory)		AFL								0
			MOS								
			MSC				-				
(983160)											
Airframe											
CB316A	CB316A - Landing Gear (ATA 32) - Inspection - Nose		HRS								0
	Landing Gear Pins, Customer Bulletin (Mandatory)		AFL								0
			MOS				48**		31 Oct 2026		
(983161)											
Airframe											
99 - Airworthiness Directives											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ACB003A	ACB003A - Wings (ATA 57) Inspection - Flap Track Lower Attach Point Fasteners		HRS		3509.1			13.3			0
			AFL		722		5		0		
			MOS		124.7		04 Aug 2014				
			MSC			-					
(990031)											
Airframe											
ACB004A PART I	ACB004A Part I - Landing Gear (ATA 32), Inspection - Brake Inlet SELF-Sealing Couplings Torque		HRS		3099.7			422.7			0
			AFL		634		93		0		
			MOS		109.3		18 Nov 2015				
			MSC			-					
(990041)											
Airframe											
ACB004A PART II	ACB004A Part II - Landing Gear (ATA 32), Inspection - Brake Inlet SELF-Sealing Couplings Torque		HRS		2755.9			766.5			0
			AFL		561		166		0		
			MOS		99.2		20 Sep 2016				
			MSC			-					
(990042)											
Airframe											
Notes: TW ID# 558063, DUE 08/17											
ACB006	ACB006 - Engine (ATA 72), Inspection- High Pressure Compressor Variable Stator Vanes Mechanism (Rolls- Royce Nmsb Sb-BR700-72-900178)		HRS		1585.8			1936.6			0
			AFL		321		406		0		
			MOS		65		25 Jul 2019				
			MSC			-					
(990060)											
Airframe											
Notes: TW 574813 DUE 07/20TW 569509 DUE 09/19TW 561051 DUE 11/19											
ACB007	ACB007 - Fuselage Structure (ATA 53) - Operational Limitations - Auxiliary Power Unit Enclosure Installation		HRS		1017			2505.4			0
			AFL		214		513		0		
			MOS		43.2		20 May 2021				
			MSC			-					
(990070)											
Airframe											
ACB008	ACB008 - ACB008 - Fuselage Structure (ATA 53), Operational Limitations - Auxiliary Power Unit Enclosure Installation - Sealant Application		HRS								0
			AFL						0		
			DATE								
			MSC			-					
(990080)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ACB009	ACB009 - ACB009 - Fuselage Structure (ATA 53) -		HRS		862.3			2660.1			0
	Operational Limitations - Auxiliary Power Unit Enclosure		AFL		164			563			0
	Installation - Exhaust Duct Fastener Pitch		MOS		38.1			22 Oct 2021			
			MSC					-			
(990090)											
Airframe											
FAA 1974-08-09 R03	FAA 1974-08-09 R03 - Equipment/Furnishings -		HRS		113.9	-44.1	1000	3408.5	4364.4*		0
	Installation of Placards Prohibiting Smoking In the		AFL		36			691			0
	Lavatory and Disposal of Cigarettes In the Lavatory Waste		MOS		14.1			23 Oct 2023			
	Receptacles										
(994002)											
Airframe											
FAA 2012-02-08	FAA 2012-02-08 - Aviation Communication & Surveillance		HRS		3509.1			13.3			0
	Systems (Acss) Traffic Alert and Collision Avoidance		AFL		722			5			0
	System (TCAS) Units		MOS		117.7			04 Mar 2015			
			MSC					-			
(994001)											
Airframe											
Notes: N/A BY TCAS COMPUTER PART NUMBER INSTALLED.											
FAA 2013-12-03	No. 1 Engine - FAA 2013-12-03 - Engine Fuel and Control		HRS		3509.1			13.3			0
	- Spill Return to Fuel Pump Tube - Replacement		ENC		722			5			0
			MOS		122.5			10 Oct 2014			
			MSC					-			
(994003)											
Engine											
FAA 2013-12-03	No. 2 Engine - FAA 2013-12-03 - Engine Fuel and Control		HRS		3509.1			13.3			0
	- Spill Return to Fuel Pump Tube - Replacement		ENC		722			5			0
			MOS		122.5			10 Oct 2014			
			MSC					-			
(994003)											
Engine											
FAA 2014-12-03	No. 1 Engine - FAA 2014-12-03 - Engine Fuel and Control		HRS		2312.5			1209.9			0
	- Fuel Metering Units (Fmus) - Replacement		ENC		479			248			0
			DATE				30d**				
(990014)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2014-12-03	No. 2 Engine - FAA 2014-12-03 - Engine Fuel and Control - Fuel Metering Units (Fmus) - Replacement		HRS		2312.5			1209.9			0
			ENC		479			248		0	
			DATE				30d**				
(990014)											
Engine											
FAA 2015-08-07	FAA 2015-08-07 - Oxygen - Zodiac Aerotechnics (Formerly Intertechnique Aircraft Systems) Flightcrew Oxygen Mask Regulators - Inspection / Replacement of Inflatable Harnesses		HRS		2755.9			766.5			0
			AFL		561			166		0	
			MOS		99.1			23 Sep 2016			
			MSC				-				
(994018)											
Airframe											
FAA 2015-16-04	FAA 2015-16-04 - FIRE Protection - Modify All Kidde Graviner Hand-Operated FIRE Extinguishers Having Part Numbers 56412-001 (34H), 56411-001 (35H), and 56412- 002 (38H)		HRS		3082.6			439.8			0
			AFL		627			100		0	
			MOS		108.7			05 Dec 2015			
			MSC				-				
(994019)											
Airframe											
FAA 2015-20-10	AD 2015-20-10 Gulfstream Aerospace Corporation		HRS		3082.6			439.8			0
			AFL		627			100		0	
			MOS		108.7			05 Dec 2015			
			MSC				-				
(994020)											
Airframe											
FAA 2015-23-09 INSPECT	AD 2015-23-09 Zodiac Aerotechnics Flightcrew Oxygen Mask Regulators (Part 1 - Inspect)		HRS		3026.3			496.1			0
			AFL		617			110		0	
			MOS		107.6			06 Jan 2016			
			MSC				-				
(994021)											
Airframe											
FAA 2015-23-09 REPLACE	AD 2015-23-09 Zodiac Aerotechnics Flightcrew Oxygen Mask Regulators (Part 2 - Replace)		HRS		3082.6			439.8			0
			AFL		627			100		0	
			MOS		108.7			05 Dec 2015			
			MSC				-				
(994022)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2015-24-06 (994023) Airframe	AD 2015-24-06 Gulfstream Aerospace Corporation		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.1			23 Sep 2016			
			MSC				-				
Notes: ACFT IN COMPLIANCE WITH AMOC											
FAA 2016-11-20 (994026) Airframe	FAA 2016-11-20 - Oxygen - Inspection and Replacement of B/E Aerospace Protective Breathing Equipment (Pbe), Part Number 119003-11 that Are Installed on Airplanes. Superseded By FAA AD 2017-18-12		HRS		2755.9			766.5			0
			AFL		561			166			0
			MOS		99.2			20 Sep 2016			
			MSC				-				
Notes: B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), P/N 119003-11 IS NOT INSTALLED ON THIS AIRCRAFT AT THIS TIME.											
FAA 2017-04-01 (994035) Airframe	FAA 2017-04-01 - Flight Controls - Accomplish an FCC Software Update as Applicable		HRS		2584.1			938.3			0
			AFL		523			204			0
			MOS		92.9			30 Mar 2017			
			MSC				-				
Notes: COMPLIED WITH DUE TO PREVIOUS COMPLIANCE WITH ASC 37A ON SEPT-20-2016 @ GULFSTREAM - SAVANNAH (TT 766.5 HR / 166 LDG)											
FAA 2017-18-12 (994042) Airframe	FAA 2017-18-12 - Oxygen - Inspection and Replacement of B/E Aerospace Protective Breathing Equipment (Pbe), Part Number 119003-11 and 119003-21 that Are Installed on Airplanes		HRS		2261.3			1261.1			0
			AFL		466			261			0
			MOS		85.6			08 Nov 2017			
			MSC				-				
Notes: EQUIPMENT NOT INSTALLED											
FAA 2017-20-08 (994045) Airframe	FAA 2017-20-08 - Fuselage - Revise the Limitations Section of the Applicable Gulfstream Afm Specified In Paragraphs (H)(1) Through (H)(6) of This AD to Include the Information In the Applicable Gulfstream Afm Supplement (AFMS) Specified		HRS		2257.8			1264.6			0
			AFL		463			264			0
			MOS		84.9			30 Nov 2017			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2018-12-07	FAA 2018-12-07 - Landing Gear - Modification of the MLG and Brake Assemblies Following the Accomplishment of Gulfstream G650 CB155B, Dated July 26, 2017 and Gulfstream G650ER Customer Bulletin 155B Dated July 26, 2017		HRS		1973.6			1548.8			0
			AFL		411			316			0
			MOS		77.9			28 Jun 2018			
			MSC				-				
(994065)											
Airframe											
Notes: AD 2018-12-07 ALREADY COMPLIED WITH THRU PREVIOUSCOMPLIANCE WITH CB155A ON SEP-22-2016 (TT 766.5 HR / 166 LDG) AT GULFSTREAM - SAV. NO FURTHER ACTION REQUIRED											
FAA 2018-20-04	FAA 2018-20-04 - Flight Control - Revise the Normal Procedures and Abnormal Procedures Sections of the Airplane Flight Manual		HRS		1841.9			1680.5			0
			AFL		384			343			0
			MOS		73.7			03 Nov 2018			
			MSC				-				
(994068)											
Airframe											
FAA 2018-21-14	FAA 2018-21-14 - Oxygen - Oxygen Mask Regulator Harness Inflation Hoses - Inspection / Replacement		HRS		873.6			2648.8			0
			AFL		166			561			0
			MOS		38.9			29 Sep 2021			
			MSC				-				
(994070)											
Airframe											
FAA 2019-23-11	FAA 2019-23-11 - Flight Controls - Revise the Airplane Flight Manual (Afm) By Adding an Airplane Flight Manual Supplement (AFMS), Which Contains Operating Limitations and Abnormal Procedures for Loss of Rudder or Yaw Damper		HRS		1326.7			2195.7			0
			AFL		269			458			0
			DATE		1790 d			01 Feb 2020			
			MSC				-				
(994078)											
Airframe											
FAA 2020-02-18	FAA 2020-02-18 - Flight Controls - Revise the Airplane Flight Manual (Afm) By Attaching an Airplane Flight Manual Supplement (AFMS)		HRS		1294.7			2227.7			0
			AFL		265			462			0
			DATE		1772 d			19 Feb 2020			
			MSC				-				
(994079)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2020-11-01	FAA 2020-11-01 - Flight Controls - Pfcas Remote		HRS		1263.9			2258.5			0
	Electronics Unit (Reu) - Software Update		AFL		258			469			0
			MOS		53.8			01 Jul 2020			
	(994080)		MSC				-				
Airframe											
FAA 2021-23-12	FAA 2021-23-12 - Indicating / Recording / Navigation -		HRS		820.2			2702.2			0
	Radio (Radar) Altimeter - Afm Revision to Incorporate		AFL		155			572			0
	Limitations		MOS		36.3			16 Dec 2021			
	(992199)		MSC				-				
Airframe											
FAA 2023-10-02	Appliance AD - FAA 2023-10-02 - Indicating/Recording		HRS		285.9			3236.5			0
	System/Navigation - Radio Altimeter - Afm Revision		AFL		61			666			0
	(Mandatory)		MOS		18.4			15 Jun 2023			
	(992312)		MSC				-				
Airframe											
FAA 2023-10-02 PARA (H)	FAA 2023-10-02 Para (H) - Revise the Limitations Section		HRS		285.9			3236.5			0
	of the Existing Afm (until 30--June- 2023 - Satisfied By		AFL		61			666			0
	FAA 2021-23-12) (Mandatory)		MOS		18.4			15 Jun 2023			
	(992313)		MSC				-				
Airframe											
FAA 2023-10-02 PARA (I)	FAA 2023-10-02 Para (I) - Revise the Limitations Section		HRS		285.9			3236.5			0
	and Remove the Afm Revision Required By Para (H)		AFL		61			666			0
	(after 30 Jun 2023) (Mandatory)		MOS		18.4			15 Jun 2023			
	(992314)		MSC				-				
Airframe											