The Standard

Market Standard

A Residue Standard

ASA-SA-1

Aircraft Record General Infor	mation			
Manufacturer $\frac{BOE/NG}{Serial}$ Serial $\frac{75-8233}{19}$ Date of Manufacture $\frac{19}{19}$		Registration Numb	er <u>N 688</u>	37
Engine(s) currently installed:  Manufacturer				
Manufacturer		Model		
HUB Model	Serial	*	Serial	
Blade Model	Serial	Serial	Se	rial
Blade Model	_Serial	Serial	Se	rial

				T. I. Descine and Alterations
YEAR: 2.00	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair  Facility. (See back pages for other specific entries.)
DATE				r demily (coe and p
Mach 117	247.26	es 40	BBS	PERFORM AHAVAL INSPECTIVA ON
				AIRCRAFI AS POR ANDI-70AC ERUSIUM
				AND MAINTONACCO MANNILL INSPECT PUSCECAGE
				LUBRICATE CHOTEN RODS AND CARLES, TUSTED
				CANDING FEM. INSPECT BRAKES & Wheley
				INSPECT WINGLEST TAK GROUP.
				I CERTIFY THIS AIRCRAFT HAS
	1			BEEN INSPECTED IN ACCORDANCE
				WITH A ADVANCE INSPECTION AND
				WAS DETERMINED TO BE IN
		-	<b>-</b>	AIRWORTHY CONDITION.
				FRNEST PERSICH A + P 55878-2379
				Ene Thered AST 58.78-2379/

YEAR:  DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				certify that the Transponder test and inspection required by FAR 91.413 has been performed and found to comply
				with FAR 43. Appendix F.  UNITRODAN 258 S/N 1296020  WO#_image Redding Aerotronics Inc  C.R.S. LDZR339K
	,			signed Si
		·		
			- 1.ê. 	i.

YEAR: 2002 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair  Facility. (See back pages for other specific entries.)
Myrch 155	273.7	LUBB	\$	PERFORM AMAUNI IN SPECTION AS PER
				ANDI-70 AC ERECTION AND MATINTENANCE MANUAL CUBRILOTE ALL AULEYS ARED CASUS
				+ BEU CRAMIS. INSPICE WING GROUPS
			ŧ	FERR ELT BATTERIES CHANGE NUR 3/2005" "I CERTURY THIS HIR CRASS HAS BEEN
				Messey es IN ACCORATNOE WITH A
				TO BE IN AUR WOKILT CONSTITION
				Einest Pasid A+P 558-78-2378/A

YEAR:  2003  DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair  Facility. (See back pages for other specific entries.)
3/23	294.7	LOBBS		PERFORM ASSUME IN SPECTION AS
				PER ANDI-70AC ERECTION AND MAINTENANCE
				Mynux. INSPECT FUSE CAGE LLUBRICATE PULLETS
				INSPECT TAIL GROVP. 14 SPECT CAMPING
				GERR TOP OFF STRUIS WITH MIL H-5686
			<b></b>	REMOVE MUD WASP NEST FROM R. TAILERON.
	-			INSPORT WINGS "I CEATIFY THIS
	<b></b>			AIRCRAFT LAS BEEN INSTERTED IN
				ACCORDANCE WITH A ANNVAC INSPECTION
	<b> </b>			AND WAS DETERMINED TO DE IN AIRWORTH
				CONDITION
	<u></u> '			Ent Persut AAP 558-78-2379 1A

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE		•		
			9	VINTAGE WINGS & WHEELS LLC 90 SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181
		Date:	1-10-03 - Boeir	Date: 11-10-03 - Boeing Stearman A75N1 N68837 S/N75-8233 Hobbs: 330.1 TTA:- 330.1
	Replace right we engine cowl and	ng walkway I re-secure	/ material with n dzus on baggag	Replace right wing walkway material with new 3M #19285-510 Safety Walk material. Install new 6 1/5x50 dzus and dzus collar on left engine cowl and re-secure dzus on baggage door. Replace leaking fuel gauge P/N 10435.
	Replace right wi	ng walkway re-secure	material with ndzus on baggag	new 3M #19285-510 Safety Walk material. Install new 6 1/5x50 dzus and dzus collar on left ge door. Replace leaking fuel gauge P/N 10435.
	Replace right wing walkway rengine cowl and re-secure dz	ng walkway re-secure P 2112333 I	material with n dzus on baggag	new 3M #19285-510 Safety Walk material. Install new 6 1/5x50 dzus and dzus collar on left ge door. Replace leaking fuel gauge P/N 10435.
	Replace right wiengine cowl and engine cowl and Ernest Persich A/	ng walkway re-secure 2112333 I	material with n dzus on baggagu	new 3M #19285-510 Safety Walk material. Install new 6 1/5x50 dzus and dzus collar on left ge door. Replace leaking fuel gauge P/N 10435.
	Replace right wiengine cowl and engine cowl and Ernest Persich A	ng walkway re-secure 21123331.	material with n dzus on baggage	new 3M #19285-510 Safety Walk material. Install new 6 1/5x50 dzus and dzus collar on left ge door. Replace leaking fuel gauge P/N 10435.
	Replace right wiengine cowl and and Ermest Persich A/	ng walkway re-secure 2112333 I.	material with n dzus on baggage	new 3M #19285-510 Safety Walk material. Install new 6 1/5x50 dzus and dzus collar on left ge door. Replace leaking fuel gauge P/N 10435.

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair  Facility. (See back pages for other specific entries.)
DATE				A/C LOG
				VINTAGE WINGS & WHEELS LLC 90 SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181
	pulleys and inspected a	check cable as aircraft has	ion as per AN01 es, inspect wings s per FAR 91.20 s been inspecte	Deing Stearman A75N1 N68837 S/N75-8233 Hobbs: 335.8 TTASMOH: 335.8  L-70AC-2 erection and maintenance manual. Repack all wheel bearings. Inspect fuselage, lubricate s, flying wires, tail group. Inspect landing gear and brake system. Function tests normal. ELT 17. Check all AD's complied with 2004-08.  Indicate the system of

West &	CONDITION.	HAS BEEN			2005 7.	15 April 366.9	YEAR: RECORDING  PAOH- TIME  THERES
The second second	N A N	HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HA	Z'vis	Da Sw	S.M.O.H. 366.9	6.9	DING TODAY'S FLIGHT
IA 523748	NOTES CHECKED THROUGH	A IRCRAFT	exected	Herry Exp. C	366.9	8539.9	TOTAL TIME IN SERVICE
	HROUGH YOU A \$52376%	NICE Service in an airmorthy condition.	thight and eng controls. Lubed as required	Les Mar. 25, 2006. Fabric Test		100hr service for annual in accordance	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

of Jessey X Josevet	2/2, 1 (A 523748	118SUE 2000-18	CONDITION. A.D. NOTES CHECKED THROUGH	BLEN DETERMINED TO BE AIRWORTHY	WITH AN AMNUAL INSPECTION AND HAS	HAS BEEN INSPECTED IN ACCORDANCE	I CERTIFY THAT THIS ALECCACE					Acrirame rebuild	goob 393.2 hrs since	145epx 393.2 8566.9	TACH TIME TIME SERVICE
	$\rightarrow$	A87523748		RIM Mesley & Deven	ID HAS		to service in an airworthy andition,	on Sissons assys. Ground run and returned	Main gear New bushings, betts & Au hardware.	Cleaned and reparted Tout wheel, rest of Kight	 Test & mspection - sox/stac Jone, Discsembled	ETT batteries replaced-lexp date Sept 2012.	FAR 43, appard, Fabric Test-OK. You FAR 2000.	look service for annual in accordance with	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

		M							
1 hn							,	5/5/07	YEAR:
								5/5/67 393.2	RECORDING
									TODAY'S FLIGHT
								8566.9	TOTAL TIME IN SERVICE
CASE TO A			# 18the GORD II	See Probeller Los Book.	la	Sensenich Model W98AA-66, Sto 41223	the presently installed propeller.	Note: this entry is made to show	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

YEAR:	RECORDING	TODAY'S	TOTAL	Description of Inspections, Tests, Repairs and Alterations
	TACH	FLIGHT	SERVICE TIME IN	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Re
DATE	i			Facility. (See back pages for other specific entries.)

### VINTAGE WINGS & WHEELS LLC 90 SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181

Date: 6-1-2007 -- Boeing Stearman A75N1 -- N68837 -- S/N75-8233 -- Hobbs: 397.3 -- TTASMOH: 397.3

adjustment and for inertial reel locking. Normal at this time. Remove T-6 seat from rear cockpit in aircraft. Install repaired stock metal Stearman seat P/N E75N1-3601 and check function f

Remove both flying wire javelins, sand and remove old paint, revarnish and repaint with silver clear coat, reinstall. Check charging system output, generator normal at this time, but amp meter shows discharge. Check wiring at amp meter shu Check brakes, adjust left master cylinder, clearance on control rod, and adjust clearance on both sets of brake shoes

wires for meter to read correctly, reassemble cover plate.

Check fluid on right gear, refill with 1 (one) quart 5606 hydraulic fluid, tighten gland nut and resecure safety clip.

		YEAR: R
SIGNED J&R E 20511:	TRANSF INSPEC APPENI DATE	RECORDING TACH TIME
SIGNED J&R ELECTRONICS, F 20511 SKYWEST DR. HAYWARD, CA 94541	ONDERIS) H. TED AND FO DIX F OF PAR	TODAY'S FLIGHT
TRONICS, FAA CRS *XB3R965L WEST DR. CA 94541	TRANSPONDERIS) HAVE BEEN TESTED AND INSPECTED AND FOUND TO COMPLY WITH APPENDIX F OF PART 43 I.A.W. FAR 91.413	TOTAL TIME IN SERVICE
33R965L	TED AND Y WITH AR 91.413	Descript Entries markets Facility. (S
		Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
		sed with Nar jes for other
		Tests, Reme, Rating a specific entr
		pairs and And Certificate es.)
		Number of Te
		chnician or Rep

		YEAR:
TIME	TACH	RECORDI

FLIGHT TIME IN SERVICE

Facility. (See back pages for other specific entries.) Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Description of Inspections, Tests, Repairs and Alterations

## VINTAGE WINGS & WHEELS LLC 90 SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181

Date: 9-28-2007 -- Boeing Stearman A75N1 -- N68837 -- S/N75-8233 -- Hobbs: 425.0 -- TTA 8598.7

Perform annual inspection as per AN01-70AC-2 erection and maintenance manual, and FAR part 43 appendix D. Repack a gunnel, cover and lacing, reinstall on aircraft. Repair left wing tip, slight damage to wood. Recover and repaint with Stits I grommet on right lower firewall. Remove aileron torque tube arms and replace worn bearings with servicable KS4 bearings anchor nuts on intake pipe and resecure in place. Reinstall smoke tank with new MS21919-DG16 clamps. Install new A-122 firewall Remove safeties from all four pedal hangar bolts, tighten bolts to secure hangars and resafety, adjust control lock to engag Inspect fuselage, lubricate pulleys and check cables, inspect wings, flying wires, tail group. Inspect landing gear and brake system. Replace ELT inspected in accordance with FAR Part 91.207 (d) and found in airworthy condition. replace bent stop pin on lever to lock control system. Remove intake system, found loose segments, clean and resecure an left drum with new surplus P/N 56583. Remove left rear gunnel, strip paint, and repaint with DCC acrylic urethane custom e properly, paint. Reinstall id install new olytone #140 wheel bearings

I certify this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

Check all AD's complied with 2007-19.

	Benney or a Miller and	•	Michigan Committee	
				YEAR: DATE
	All work completed in accordance with Michael P Wyant A&P 2842700	Removed locking tail wheel cable, sheath, handle cables, cable guides, turnbuckles & eyelets to aft cables. Steering tail wheel ops check good.		RECORDING TACH TIME
	eted in acc	ng tail whe uides, turn ng tail whee		TODAY'S FLIGHT
	with	el cable, sheat buckles & eye el ops check g	Job #: <b>462</b> -	TOTAL TIME IN SERVICE
	AAFT.O. #01-70 AB-2 & AC43-13.1B	Removed locking tail wheel cable, sheath, handle and associated hardware. Installed new steering tail wheel LH & RH cables, cable guides, turnbuckles & eyelets to aft pilots rudder pedals mount lugs. Set cable tension & safetied cables. Steering tail wheel ops check good.	22005 SKYWEST DRIVE  HAYWARD, CA 94541  Job #: 462-1 Aircraft: Boeing Model: B75N1 S/N: 75-8233  Tach: 435.1 T/T: 8608.8 Date: 10/30/07	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

2-	Mi 2	Re l			YEAR: DATE
4-07	Michael P Wyant A&P 2842700	Replaced braking system with new Redline			RECORDING TACH TIME
436	A&P 284	system w	ر		TODAY'S FLIGHT
.6	2700	ith new Redlin	b #: 472-1 Air		TOTAL TIME IN SERVICE
Frstalled Buttery Coill-6355		Airframe Entry  Replaced braking system with new Redline brake STC#SA3320SO. See FAA form 337 dated 11/7/2007.  All work completed in accordance with AAF7 O #61-70 AB-2 AC43-13.1B & Redline installation Manual.	Job #: 472-1 Aircraft: N68837 Model: Boeing B75N1 S/N: 75-8233  Tach: 435-1 Date: 11/07/07	BUD FIELD AVIATION  22005 SKYWEST DRIVE  HAYWARD, CA 94541	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

EAR: ——— ATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Rep Facility. (See back pages for other specific entries.)
			90 S	VINTAGE WINGS & WHEELS LLC KYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181
	D	ate: 12-31-	2007 Boeing	g Stearman A75N1 N68837 S/N75-8233 Hobbs: 439.5 TTA 8613.2
US	na ANO1-70AC-	-3 structural	repair instructi	Recover and repaint with Stits Polytone #140. Work performed in accordance AC43.13-1B and ons as reference.
			1	and the single in cocknit. Cocure rear nicted grin in rear cocknit
	QT	PL	positioning of	control sticks in cockpit. Secure rear pistol grip in rear cockpit.
	just control stic	PL	positioning of	control sticks in cockpit. Secure rear pistol grip in rear cockpit.
	QT	PL	positioning of	control sticks in cockpit. Secure rear pistol grip in rear cockpit.

TACH FLIGHT	TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
		Removacle 4-57A replaced with St-40
		-
a.		5
		mike - phino Jack wines with shielded
		werens unit fested on sound power.
2		
		This Ask has been inspected and tested in accordance with
		SKINICE, SICH LEND COMMENTAL CONTRACTOR OF THE PROPERTY OF THE

							6-6	YEAR: 2008 DATE
		٠					1765h	RECORDING TACH TIME
								TODAY'S FLIGHT
		•	•	·				TOTAL TIME IN SERVICE
				Lon H 1	closed & Cleaned when	and Tail when Time STH 1017	Replace & Main Tire Mero 8.50	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

of the original and the

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Resilies (Cooks also as a second s	Repair
ATE				Facility. (See back pages for other specific entries.)	
•				VINTAGE WINGS & WHEELS LLC YLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181	,
app Insp tens ELT Che	form annual inspolicable to the air pect fuselage, lusion steerable call in accept all AD's compected in accept all AD's accept all AD	pection as parcraft.  Ibricate pulle ables from 1 accordance with 20 plied with 20 pli	er FAR part 43 eys and check of 0 lbs to 35 lbs. ith FAR Part 91 008-17.	Stearman A75N1 N68837 S/N75-8233 Hobbs: 476.1 TTA 8649.8  appendix D and using AN01-70AC-2 erection and maintenance manual as reference as cables, inspect wings, flying wires, tail group. Inspect landing gear and brake system. Re-207 (d) and found in airworthy condition.	
(		S	0		

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair  Facility. (See back pages for other specific entries.)
			Precision Static Testing #QJAR856X Livermore, CA
			In accordance with FAR 91.413 transponder(s) have been tested and inspected and found to comply with Appendix F of Part 43.
			Time: UNENTUN W/0# 4978 DATE 11/20/08
			Inspected by 37 N 68837
12.12.00			
	TACH	TACH FLIGHT	TACH FLIGHT TIME IN

VINTAGE WINGS & WHEELS LLC 90 SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023	-		
TIME IN SERVICE  Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repairs and Certificate Number of Technician or Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repairs and Alterations	TODAY'S FLIGHT	RECORDING TODAY'S TACH TIME	YEAR:
			,

# TEL: (831) 630-9025, FAX: (831) 637-6181

Date: 10-15-2009 -- Boeing Stearman A75N1 -- N68837 -- S/N75-8233 -- Hobbs: 520.8 -- TTA: 869

Perform annual inspection as per FAR part 43 appendix D and using AN01-70AC-2 erection and maintenance manual as reference as

applicable to the aircraft.

Inspect fuselage, lubricate pulleys and check cables, inspect wings, flying wires, tail group. Inspect landing gear and brake system. Remove corrosion from battery box, neutralize with baking soda and clean water, reseal with Par-Al-Ketone

Replace ELT batteries with new Duracell D batteries. ELT inspected in accordance with FAR Part 91.207 (d) and found in

Check all AD's complied with 2009-20.

I certify this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition

YEAR: RECORDING  LOIC TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
4-22-10 530.2	,		Replaced Tail Wheel With 10:00-Sc
			with new bearings + hace day the
mare to a seek sajabbagg			
			$\gamma$ .

YEAR:  DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Facility. (See back pages for other specific entries.)	Repair
		•	90	VINTAGE WINGS & WHEELS LLC SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181	_
_		Date: 11-1	1-2010 Boei	ng Stearman A75N1 N68837 S/N75-8233 Hobbs: 549.1 TTA: 8722.8	
	applicable to the Inspect fuselage Cut inspection	e aircraft. e, lubricate holes upper	pulleys and che wings and inst	eck cables, inspect wings, flying wires, tail group. all inspection plates P/N 09-18740.	
	Inspect landing ELT inspected in Check all AD's	gear and bein accordant complied with the compli	rake system. ce with FAR Par th 2010-22.	new bushing inserts, reinstall on aircraft with new hardware.  t 91.207 (d) and found in airworthy condition.  accordance with an Annual Inspection and was determined to be in airworthy condition.	
	Ernest Persich A	A	eul		

YEAR:  DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DAIL				TRANSPONDER(S) HAVE BEEN TESTED AND
				INSPECTED AND FOUND TO COMPLY WITH APPENDIX F OF PART 43 I.A.W. FAR 91.413
				DATE 12 16 (4 W.O.# 16 S 99)
				DATE 14 210 W.O." 10>1
				SIGNED J&R ELECTRONICS. PAA CRS #XB3R965L
				20511 SKYWEST DR. HAYWARD, CA 94541
	THE RESERVE			

YEAR:  DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
		,	90	VINTAGE WINGS & WHEELS LLC SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181
		Date: 11-1	I-2011 Boei	ng Stearman A75N1 N68837 S/N75-8233 Hobbs: 569.1 TTA: 8742.8
	applicable to the Inspect fuselage Inspect landing ELT inspected in Check all AD's of	e aircraft. e, lubricate gear and be n accordance complied with	pulleys and che rake system. te with FAR Part th 2011-22. en inspected in	t 43 appendix D and using AN01-70AC-2 erection and maintenance manual as reference as eck cables, inspect wings, flying wires, tail group.  t 91.207 (d) and found in airworthy condition.  accordance with an Annual Inspection and was determined to be in airworthy condition.

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Re Facility. (See back pages for other specific entries.)	pair
DATE				radility. (See back pages for other specific entires.)	
				TRANSPONDER(S) HAVE BEEN TESTED AND INSPECTED AND FOUND TO COMPLY WITH APPENDIX F OF PART 43 I.A.W. FAR 9I.4I3	
				DATE 2/21/12W.O.# 17012	
	-				
[ <del></del>				J&R ELECTRONICS, FAA CRS #XB3R965L	
				K//0037	
				N 68837	
		1			
					and the second
					COP-PRINTS IN LIGHT

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Refacility. (See back pages for other specific entries.)	pair
			90 S	VINTAGE WINGS & WHEELS LLC KYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181	_
	D	ate: 11-3-2	012 Boeing	Stearman A75N1 N68837 S/N75-8233 Hobbs: 581.2 TTA: 8754.9	-
ap In In	oplicable to the a spect fuselage, l spect landing ge	nircraft. Iubricate pul ear and brak	lleys and check e system.	B appendix D and using AN01-70AC-2 erection and maintenance manual as reference as cables, inspect wings, flying wires, tail group.	-
	•			N310-4 castle nuts and safety.  atteries. Now due November 2014. ELT inspected in accordance with FAR Part 91.207 (d) and	-
	ound in airworthy heck all AD's con		2012-21		-
		•		ccordance with an Annual Inspection and was determined to be in airworthy condition.	-
Er	rnest Persich A/P 2	112333 I.A.	eul		-

		 يعين أن	والمراج والمحمو		 		
		,				Mare	YEAR:
						4.285	RECORDING TACH TIME
							TODAY'S FLIGHT
							TOTAL TIME IN SERVICE
					Buttern # 400590679	In Halled a Concorde CB-AG-35/4/c	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

				DATE
Facility. (See back pages for other specific entries.)				
Elithes illust be elitorised with Ivalile, hattily and benilloate ivaliloci of recirillotarion to	SERVICE		IME	
•	TIME	FLIGHT	TACH	
Description of Inspections, Tests, Repairs and Alterations	Ś	TODAY'S	RECORDING	YEAR:

### VINTAGE WINGS & WHEELS LLC 90 SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181

Date: 11-1-2013 -- Boeing Stearman A75N1 -- N68837 -- S/N75-8233 -- Hobbs: 595.2 -- TTA: 8768.9

applicable to the aircraft Perform annual inspection as per FAR part 43 appendix D and using AN01-70AC-2 erection and maintenance manual as reference

Inspect fuselage, lubricate pulleys and check cables, inspect wings, flying wires, tail group.

Inspect landing gear and brake system. Replace brake pads with new P/N Cleveland brake linings 066-10800.

Replace worn lock pin P/N AG-114P used for AG-114 steering shaft.

ELT inspected in accordance with FAR Part 91.207 (d) and found in airworthy condition.

Check all AD's complied with 2013-21. [ certify this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair  Escilib (See back pages for other specific entries)
DA			90	VINTAGE WINGS & WHEELS LLC SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181
		Date: 11-1-	-2014 Boein	ng Stearman A75N1 N68837 S/N75-8233 Hobbs: 613.6 TTA: 8787.3
	applicable to the Replace fuel line engine and oil to Install new gase Inspect fuselage Inspect landing Replace ELT bat Check all AD's of the Replace Inspect landing Replace ELT bat Check all AD's of the Replace Inspect landing Replace ELT bat Check all AD's of the Replace Inspect landing Replace ELT bat Check all AD's of the Replace Inspect landing Replace Inspec	e aircraft. hoses between ank and ove culator gaskee, lubricate pear and bracketeries with recomplied with	veen gasculator rboard vent line et P/N C-2AG to bulleys and checake system.  The description of the latter of the	43 appendix D and using AN01-70AC-2 erection and maintenance manual as reference as ar and carburetor with new P/N MIL-H6000-8 hoses. Replace oil breather hoses between and new MIL-H6000-8 hoses. The original replace worn gasket. The original reck cables, inspect wings, flying wires, tail group.  The teries. ELT inspected in accordance with FAR Part 91.207 (d) and found in airworthy condition.
	Ernest Persich A/	es C		ern

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or I Facility. (See back pages for other specific entries.)	Repair
			90	VINTAGE WINGS & WHEELS LLC SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181	
_		Date: 11-28	-2015 Boei	ng Stearman A75N1 N68837 S/N75-8233 Hobbs: 620.5 TTA: 8794.2	-
	applicable to the Install new gase	e aircraft. ulator gaske e, lubricate p	et P/N C-2AG to oulleys and che	43 appendix D and using AN01-70AC-2 erection and maintenance manual as reference as replace worn gasket. ck cables, inspect wings, flying wires, tail group.	
-	ELT inspected in	accordance	with FAR Part	91.207 (d) and found in airworthy condition.	
	Check all AD's of I certify this airc			accordance with an Annual Inspection and was determined to be in airworthy condition.	
4	Ernest Persich A/F	2112833 I.A		sul	
*			1		

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repairs (See back pages for other energies entries)
DATE				Facility. (See back pages for other specific entries.)
In po	certify that the Anspections require erformed IAW FA	ed by FAR 9 AR 43 App. I	1.413 were	
			tic Testing	Livermore, CA
				ion #QJAR856X AX (925) 449-6081
I cer have	tify that transpore been performed	nder tests, in	cluding data c to comply with	orrespondence, required by § 91.413, 14 CFR Part 43, appendix E and F.
Time	e: <u>624.</u> 8	_ W/O# <u>/</u>	203 8	N 68837
	ected by	2		N 68837  Date 7/22/16

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician of Facility. (See back pages for other specific entries.)	or Repair
DATE			90 Sk	VINTAGE WINGS & WHEELS LLC (YLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181	
	D	ate: 11-1-2	016 Boeing	Stearman A75N1 N68837 S/N75-8233 Hobbs: 626.1 TTA: 8799.8	
app Ma Ins	plicable to the ai nufacture small spect fuselage, lo spect landing ge	ircraft. patch on lef ubricate pull ar and brake	ft upper cowl us leys and check e system.	appendix D and using AN01-70AC-2 erection and maintenance manual as reference as sing .040 2024 T3 aluminum in accordance with AC43.13-1B. cables, inspect wings, flying wires, tail group.  atteries. ELT inspected in accordance with FAR Part 91.207 (d) and found in airworthy	
Ch	ndition. eck all AD's com ertify this aircraf	plied with 2 It has been	016-21. inspected in acc	cordance with an Annual Inspection and was determined to be in airworthy condition.	
	est Persich A/P 2		P		

ו מכווונץ: (שכם במכת המשכם וכו כיווכו שהכטווים כו ווויכט:)				DATE
Escility (See back pages for other specific entries)	95.05			
Entries must be endorsed with Name, Rating and Certificate Number o	SERVICE	FLIGHT	TACH	
Description of Inspections, Tests, Repairs and Alteration	TOTAL	TODAY'S	RECORDING	YEAR:

### VINTAGE WINGS & WHEELS LLC 90 SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181

Date: 12-15-2017 — Boeing Stearman A75N1 — N68837 — S/N75-8233 — Hobbs: 626.9 8800.6

applicable to the aircraft Perform annual inspection as per FAR part 43 appendix D and using AN01-70AC-2 erection and maintenance manual as reference as

Inspect fuselage, lubricate pulleys and check cables, inspect wings, flying wires, tail group. Inspect landing gear and brake system.

Change tailwheel tube with new P/N 255 x 110 metal stem 10" tube.

Replace worn tailwheel shock absorber bolt with new AN5-22A bolt and AN365-524 stop nut.

ELT inspected in accordance with FAR Part 91.207 (d) and found in airworthy condition.

Check all AD's complied with 2017-24.

I certify this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician of Facility (See back pages for other specific entries.)	r Repair
			admity. (Occ back pages for other specific critics.)	
			VINTAGE WINGS & WHEELS LLC	
		90.5		
			1221 (002) 000 5025/1700 (002) 007 0202	_
	Date: 4-26-2	2019 Boeing	Stearman A75N1 N68837 S/N 75-8233 Hobbs: 628.3 TTA: 8802.0	
	•	per FAR part 4	3 appendix D and using AN01-70AC-2 erection and maintenance manual as reference as	_
6 . <b>.</b>		ullevs and check	k cables, inspect wings, flying wires, tail group.	_
	•			
			Tailwheel Tire Aero Classic 10.00 8 ply.	
ondition.			•	
heck all AD's cor	mplied with	2019-8.		
certify this aircra	aft has beer	n inspected in a	accordance with an Annual Inspection and was determined to be in airworthy condition.	
G.T	1	101		_
rnest Persich A/P	2112333 I.A.	Ny		
	erform annual in oplicable to the aspect fuselage, aspect landing ghange tailwheel eplace ELT batte ondition. heck all AD's concertify this aircrease.	Date: 4-26-2 erform annual inspection as oplicable to the aircraft. Inspect fuselage, lubricate purpose tailwheel tire with near thange tailwheel than thange tailwheel than than than than than than than than	Date: 4-26-2019 Boeing perform annual inspection as per FAR part 4 policable to the aircraft. Inspect fuselage, lubricate pulleys and check anspect landing gear and brake system. The hange tailwheel tire with new P/N Smooth performance ELT batteries with new Duracell "Direction." The hange tailwheel tire with new Duracell "Direction." The hange tailwheel tailwhee	Entries must be endorsed with Name, Rating and Certificate Number of Technician of Facility. (See back pages for other specific entries.)  VINTAGE WINGS & WHEELS LLC  90 SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023  TEL: (831) 630-9025, FAX: (831) 637-6181  Date: 4-26-2019 — Boeing Stearman A75N1 — N68837 — S/N 75-8233 — Hobbs: 628.3 — TTA: 8802.0  enform annual inspection as per FAR part 43 appendix D and using AN01-70AC-2 erection and maintenance manual as reference as opplicable to the aircraft.  Inspect fuselage, lubricate pulleys and check cables, inspect wings, flying wires, tail group.  Inspect landing gear and brake system.  Inange tailwheel tire with new P/N Smooth Tailwheel Tire Aero Classic 10.00 8 ply.  Peplace ELT batteries with new Duracell "D" batteries. ELT inspected in accordance with FAR Part 91.207 (d) and found in airworthy undition.  Inspect of the property of

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Re	epair
DATE			SERVICE	Facility. (See back pages for other specific entries.)	,
		•	90 Sk	VINTAGE WINGS & WHEELS LLC YLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181	
-	Da	te: 11-2-20	19 Boeing S	Stearman B75N1 N68837 S/N 75-8233 Hobbs: 629.7 TTA: 8803.4	_
Ins	licable to the all	rcraft. Ibricate pull	eys and check of	appendix D and using AN01-70AC-2 erection and maintenance manual as reference as cables, inspect wings, flying wires, tail group.	
Inst For ELT	tall uAvionix taill m 337 dated 11 inspected in ac	Beacon P/N -1-2918. Fu cordance wi	UAV-1002183-0 Inction test taill ith FAR Part 91.	001, Mod 1, S/N 2004676. Work performed in accordance with AC43.13-1B. See attached FAA Beacon, circuits operating normal at this time.  207 (d) and found in airworthy condition.	
Che	ck all ad's comp	plied with 20	019-21.	ordance with an Annual Inspection and was determined to be in airworthy condition.	
	est Persion A/P 211	12333 I.A.	W.		

YEAR: DATE	RECORDING TACH TIME	TODAY' FLIGHT		ns of Technician or Repair
			Certificate of Conformance	
			I hereby certify that the product/s enclosed herewith, manufactured by uAvionix Corporation, have been inspected and found to be in full accordance with the specifications of:  TSO-C154c B1S, TSO-C145e Beta 1 INCOMP, TSO-C88b, and TSO-C30c Type III.  Chris Palmer  Date: 10.003043-001 (Rev A)	
			SSID: Beacon-9360 Pass: RecipGlider	

		digenter (in		3		
YEAR:  DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair  Facility. (See back pages for other specific entries.)		
DATE		have been	FAA PHON hat transponder n performed and	ision Static Testing Livermore, CA A Certified Repair Station #QJAR856X IE: (925) 449-5904 FAX (925) 449-6081  Trests, including data correspondence, required by § 91.413, d found to comply with 14 CFR Part 43, Appendix E and F.  W/O# /6879 N 68737  Date /////9		

.

2

EAR:	RECORDING TODAY'S FLIGHT TOTAL TIME IN  Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name. Rating and Certificate Number of Technician of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name. Rating and Certificate Number of Technician of Inspections, Tests, Repairs and Alterations					
			90 SI	VINTAGE WINGS & WHEELS LLC (YLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181		
	,		Date: 6-19-20	21 Boeing Stearman N68837 S/N 75-8233 Hobbs:		
Th	is aircraft has be	een inspecte	d and has been	n found safe for the intended flight in accordance with Special Flight Permit dated 17/Jun/2021.		
(	Cont Part					
Em	est Persich A/P 21	12333 I.A.		t		
	1	]		1		
					nako dan mana anto kamu ngo kama	

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)			
DATE				VINTAGE WINGS & WHEELS LLC 90 SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023 TEL: (831) 630-9025, FAX: (831) 637-6181			
	Date: 7-26-2021 Boeing Stearman A75N1 N68837 S/N 75-8233 Hobbs: 634.0 TTA: 8807.7						
		the aircraft	: ite nullevs and	d check cables, inspect wings, flying wires, tail group.			
	Replace ELT condition.	ling gear and	d brake system				
	Replace ELT condition. Check all Al I certify this	ling gear and batteries w	with 2021-15 been inspect	n. cell "D" batteries. ELT inspected in accordance with FAR Part 91.207 (d) and found in airworthy ed in accordance with an Annual Inspection and was determined to be in airworthy condition.			

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Facility. (See back pages for other specific entries.)	Repair				
DATE	VINTAGE WINGS & WHEELS LLC  90 SKYLANE DRIVE, HANGAR 3, HOLLISTER, CA 95023  TEL: (831) 630-9025, FAX: (831) 637-6181								
_	Date: 8-11-2022 Boeing Stearman A75N1 N68837 S/N 75-8233 Hobbs: 637.1 TTA: 8810.8								
_	Perform annual inspection as per FAR part 43 appendix D and using AN01-70AC-2 erection and maintenance manual as reference as								
	applicable to the aircraft.								
_	Inspect fuselage, lubricate pulleys and check cables, inspect wings, flying wires, tail group.  Inspect landing gear and brake system.								
	Replace battery with new RG-35AXC S/N 41245409.  Replace vacuum hose between T-fitting and rear cockpit turn and bank with new Polyurethane ¼" tubing, P/N 0585-071.								
	ELT inspected in accordance with FAR Part 91.207 (d) and found in airworthy condition.								
	Check all AD's complied with 2022-16.  I certify this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.								
_	( A P )								
_	Ernest Persich A/P 2112333 I.A.								

-4