

SWIFT AIRCRAFT SERVICES

LOOSE LEAF LOGBOOK ENTRY

A/C REGISTRATION:	VH-XRD	JOB NO. 16370
COMPLETION DATE:	22/7/2022	TTIS: 3888.6

AIRWORTHINESS DIRECTIVES

- | | | |
|---|----------------------|-------------------|
| 1. AD/ENG 4/AMDT 11. Appendix APPA req 2 Engine Condition report | | C/O N/D |
| 2. AD/LYC/90. Fuel Injection Lines 2015-19-07 | | C/O N/D |
| 3. AD/AIRCON/12 AMDT 4 PI , 2 and 3 Heater Inspection | VDO 1095.7 | C/O N/D |
| 4. AD/AIRCON/12 AMDT 4 Heater O/H | VDO 1500 HRS | |
| 5. AD/PROP/2 AMDT 4 Feather Check | | C/O N/D |
| 6. CAO 100.5 all paragraphs Instrument Calibration | 22/7/24 JKT INST | C/O N/D |
| 7. AD/RAD 47 AMDT 4 Transponder Calibration CAO 100.5.14 | 22/7/24 JKT INST | C/O N/D |
| 8. AD/TSA 600/20. Fuel filler cap Leakage -Test | | C/O N/D |
| 9. AD/TSA 600/25 AMDT 2 AFT Horizontal/Vertical Stab Attach Fitting Inspection | | F/I |
| 10. AD/TSA 600/36 AMDT 4. Req. 2 & 3.Engine Exhaust System. | | C/O N/D |
| 11. AD/GEN/37 AMDT 10. Emergency Exits. | | C/O N/D |
| 12. AD/GAS/AMDT 7. Oxygen Bottle | 10/2/25 | |
| 13. AD/TSA 600/45 AMDT 1. Wing 55% Upper Spar Cap. | | C/O N/D |
| 14. AD/LYC.110/ Romac Fuel Pump | | C/O N/D |
| 15. AWB 26-003 FPE/6. Fire Extinguisher -new fitted 7/14 Weight Check Expiry 7/26 W/C | | C/O N/D |
| 16. AD/TSA600/38 AMDT 1. Fatigue Critical Components Retirement Lives
Windscreen - Cabin Windows 3300 Pressurized Flts. 6600 Pressurized Flts. | | |
| 17. AD/WHE/4 AMDT 4. Tyre inflation Nitrogen | | C/O N/D |
| 18. Main instrument Filter Replace | | Replaced |
| 19. Magnetos 500Hrly L/H & R/H Engine | 4156.7 | |
| 20. ENGINE TBO R/H s/n rl-28037-48e factory rebuild | | 5551.5 or 18/5/27 |
| 21. ENGINE TBO L/H s/n l-2199-48e bulkstrip c/o 29/5/98 tso 482.0 on cond | | 4500.0 or 6/12/05 |
| 22. AD/PROP/1 AMDT 2 TBO L/H. | 3/7/24 or 5656.7 | |
| 23. AD/PROP/1 AMDT 2 TBO R.H. | 3/7/24 or 5656.7 | |
| 24. TSA600-2020-24-10 Elevator & Aileron Balance Tubes - Insp | | C/O N/D |
| 25. AD/AIRCON/13 AMDT | | C/O N/D |
| 26. A/F Hoses Inspection on condition replaced 3/7/14 tt3656.7 | | C/O N/D |
| 27. Compass Swing | 22/7/24 | C/O Placarded |
| 28. Fuel Calibration | 22/7/26 | C/O Placarded |
| 29. Carbon Monoxide Detector | | Replaced |
| 30. L/H Engine Flexible Hoses | 28/8/25 | |
| 31. R/H Engine Flexible Hoses | 16/5/20 On Condition | O/C C/O N/D |
| 32. TSA-600/-39 As Main Cabin Upper Door SB 908 | | C/O N/D |
| 33. TSA/600/49 Aux Fuel Transfer Pumps | | C/O N/D |

Key Legend -

N/A - Not applicable, M/R - Maintenance Release, C/W - Complied with, N/D - Nil defects, W/C -Weight Check
F/I - Found incorporated, S/N -Serial Number, STC - Supplement Type Certificate, C/O-Carried

Coordinator's Certification

A signature on this document indicates that all work necessary for the completion of the inspection/work listed above and any additional maintenance required in the category has been carried out and properly certified for in accordance with Civil Aviation Regulations (1988) 42ZE or 42ZN.

L.A.M.F David Robins  **Lic. No: 178338**
Pearla Pty Ltd Trading As
SWIFT AIRCRAFT SERVICES

Date: 22/7/2022

Certificate of Approval No. C 548851