



The Standard

ENGINE LOG

ASA-541

SkyView Aviation →

SkyView Aviation, LLC
5749 South Tracy Blvd
Tracy, CA 95377
(209)830-7666

and Alterations
(Certificate Number of Technician or
tries.)

N Number: N3857G Tach: 1722.4 TSMOH: 1475.1

Complied with **100 Hour** inspection in accordance with scope and detail of FAR 43 Appendix 'D'. Installed 11 quarts of Phillips 20W50 Oil and Tempest oil filter P/N: AA48110-2. Inspected old oil filter for contamination, none found at this time. Compressions as follows: 1)64/80. 2)62/80. 3)74/80. 4)75/80. 5)60/80. 6)68/80. minimum orifice 44. Installed new airfilter BA-2505. Cleaned and gapped all plugs re-installed with all new M674 sparkplug gaskets.. Checked timing. Ground run up and leak check good. For AD compliance information see list dated 03/24/2015 and old aircraft records.

I certify this Engine has been inspected in accordance with a 100 Hour inspection and determined to be in Airworthy Condition. This Engine is Approved for return to service.

END

Richard Ortenheim A&P 2517877
Date: 05/18/2016 X



SkyView Aviation →

SkyView Aviation, LLC
5749 South Tracy Blvd
Tracy CA, 95377
(209)830-7666

and Alterations
(Certificate Number of Technician or
tries.)

N Number: N3857G Tach: 1764.5 TT: 1517.2 SMOH: 1517.2
SBOH: 0.0

Complied with **Annual inspection** in accordance with CFR 43 appendix "D". Removed engine and sent to One Stop Aviation for bottom-end overhaul; reinstalled engine with new Lord J-12453-1 and Lord J-12453-2 engine mounts and serviced with 10 quarts of Phillips 20w-50 M mineral oil and new 48110-2 oil filter. Removed, cleaned, inspected, tested, and re-installed spark plugs with 12 new M674 spark plug washers. Installed new Brackett BA-2405 air filter. Installed 6 new exhaust gaskets P/N: 652458. Installed new M-113K CHT probe S/N: 2517. Complied with AD96-12-22 oil filter adapter. For more AD information see AD list dated 02/23/2021 and old aircraft records. I certify that this engine has been inspected in accordance with an annual inspection and is approved for return to service.

Richard Ortenheim A&P 2517877 IA
Date: 02/23/2021 X





Skyview Aviation, LLC
5749 S Tracy Blvd.
Tracy, CA 95377
(209) 830-7666

Technician or

YEAR
20____
RECORD
TACH
TIME
DATE

N Number: N3857G **Tach:** ~~8387.2~~ 1764.5 **SMOH:** 1517.2 **Eng. TT:** 1517.2 **SBOH:** 0.0

Complied with Annual inspection in accordance with CFR 43 appendix "D". Changed oil and filter serviced with 10 quarts of Phillips 20w-50 M mineral oil and new AA48110-2 oil filter. Compression: #1 70/80 #2 65/80 #3 62/80 #4 70/80 #5 58/80 #6 69/80. Removed, cleaned, inspected, tested, and re-installed spark plugs with 12 new M674 spark plug washers. Installed new Brackett BA-2405 air filter. Complied with AD96-12-22 oil filter adapter, no defects noted. For more detailed AD information see AD list dated 06/28/2023 and old aircraft records. I certify that this engine has been inspected in accordance with an annual inspection and is approved for return to service.

-----END-----

Richard Ortenheim A&P 2517877 IA

Date: 07/01/2023 x