



# ***TIFFIN AIRE INC.***

**1778 West State Route 224  
Seneca County Airport (16G)  
Tiffin, Ohio 44883  
1-800-553-PROP (7767)  
1-419-447-4263  
Fax 419-448-0064  
E-mail [taiprop@tiffinaire.com](mailto:taiprop@tiffinaire.com)**

**Propeller Log Book**

**PROPELLER MAINTENANCE RECORD**

PITCH RANGE

High/Feather:

28.9°

Start Lock:

10.2°

Low:

Reverse:

—

Aircraft Manufacturer

Cessna

Aircraft Model

~~180~~ TV206B

S/N:

Registration:

Position:

Propeller Model: D3A34C401

Propeller S/N: 814222

Blade Design: H-90BFA-8

Blade S/N's:

No. 1 ACB26260

No. 2 ACB26265

No. 3 ACB26267

No. 4

—

No. 5

—

No. 6

Sinner Assembly Part No. \_\_\_\_\_

1. Approving Civil Aviation Authority/Country: FAA/United States

2

# AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

4. Organization Name and Address: Tiffin Air, Inc. 1778 West U.S. 224 Tiffin, Ohio 44883

5. Work Order/Invoice Number: 23385

(DTXR341D)

6. Item: 7. Description: 8. Part Number: 9. Quantity: 10. Serial Number: 11. Status/Work:

1	PROPELLER ASSEMBLY	D3A34C401	1	814222	OVERHAUL/D
---	--------------------	-----------	---	--------	------------

12. Remarks:

COMPLETELY OVERHAULED PROPELLER ASSEMBLY IN ACCORDANCE WITH McCAULEY SERVICE MANUAL, NUMBERS MPC400R04 (REV. 4, 10/15), SPM100R06 (REV. 6, 10/15) & MPC26-04 (REV. 4, 10/15).  
 COMPLIED WITH SERVICE LETTERS: 86-6, 87-3, 89-2C, 91-11A, 98-5, 13-1, 14-1H, 14-2.  
 COMPLIED WITH SERVICE BULLETINS: 119A, 145, 227B, 267.  
 BLADE MODEL NUMBER: H-90DFA-8 BLADE SERIAL NUMBERS: ACR26260, ACR26265, ACR26267.  
 PROPELLER TOTAL TIME SINCE NEW: UNKNOWN  
 PROPELLER TOTAL TIME SINCE OVERHAUL: 0.0  
 TIME BETWEEN OVERHAULS: 72 MONTHS OR 2000 HOURS WHICHEVER OCCURS FIRST.

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in a condition for safe operation.

Non-approved design data specified in Block 12.

14a.  14 CFR 43.9 Return to Service  Other regulation specified in Block 12  
 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval/Authorization No.:

*[Handwritten Signature]*

14c. Approval/Efficient No.: DTXR341D

14d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

PAUL B. FLAVELL


14e. Date (dd/mm/yyyy): 26/Jan/2018

### User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.  
 Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

thiness Directives, Service air, and Inspections.

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	-------------------------	------------	--

**SkyView Aviation**   
 SkyView Aviation, LLC  
 5749 South Tracy Blvd  
 Tracy CA, 95377  
 (209)830-7666

N Number: N3857G Tach: 1764.5 TT: Unknown SMOH: 0.0

Complied with **Annual inspection** in accordance with CFR 43 appendix "D". Installed overhauled propeller D3A34C401 S/N: 814222. Aircraft is approved for return to service for work performed above. For AD information see AD list dated 02/23/2021 and old aircraft records. I certify that this propeller has been inspected in accordance with an annual inspection and is approved for return to service.

Richard Ortenheim A&P 2517877 IA  
  
 Date: 02/23/2021 X