AIRCRAFT MAINTENANCE RECORDS

N 4472K

ENGINE

LOG BOOK



AIRCRAFT MAINTENANCE RECORD Page No.

		DESCRIPTION OF WORK PERFORMED		
Date	Total Time	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK		
ARRIED -				
RWARD				
		44731/ Nania (44 Table 104/ 00 TETCN, 121/ 0		
C		4472K Navion "A" Tach: 1246.80 TETSN: 1316.8 Mid Cycle oil service.		
		and oil filter, PN: CH48108-1 and added 10 Qts Aero Shell 100W.		
		Iter media, nothing found.		
	4. Oil sample t			
		nance turn performed satisfactory with no leaks noted at this time.		
	Aero Service of Winch			
	615 Airport Road Suit Winchester, VA 2260			
	540-665-0193	111111111111111111111111111111111111111		
		Lexi Sowers A&P 3951596		
	-			
July 29	0, 2020 N4472K	Navion "A" Tach: 1327.1 TETSN: 1397.10		
		our Inspection IAW the scope and detail of FAR 43 Appendix D.		
2.		ession check with the following results.		
		80 #3 62/80 #4 76/80 #5 66/80 #6 76/80		
3.		pped spark plugs (Fine wire on lower).		
4.		eto to engine timing satisfactory.		
5. 6.	Took oil sample.	e with 10 Qts Aeroshell 100W oil and CH48108-1 filter.		
0. 7.		nd lubricated controls.		
8.		cessories and hardware for security and serviceability.		
9.		ce turn performed satisfactory with no leaks noted at this time.		
Aero Se	rvices of Winchester, I	nc. I certify that this ENGINE has been		
615 Air	port Road Suite 107	inspected in accordance with a 100 Hour		
Winchester, VA 22602 540-665-0193		inspection and determined to be in airworthy condition.		
		11-105m)	To all	
		Lexi Sowers A&P 3951596		
		Lexi sowers A&F 3751570		
ntow by 11	2020 3741727	N		
ptember 11,	2020 N4472K	Navion "A" Tach: 1333.6		
	right magneto.	CTC// CDC 40 40 CV V V V C		
. Installed S	sureFly Sim6C ele	ctronic mag, STC# SE04349CH, IAW SureFly Document SF1003,	Rev C	
Filed 337		4.6.4.11		
. Operation	s check performed	satisfactorily.		
Service of Win				
Airport Road Schester, VA 226				
665-0193	02	1 W		
		Nicholas Bousquet AP3359966IA		

TOTAL - CARRY FORWARD TO NEXT PAGE

AIRCRAFT MAINTENANCE RECORD Page No.

	Total Time	Total Time DESCRIPTION OF WORK PERFORME SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORME		
ARD -				
	November 20, 20	20 N4472K Navion "A" Tach: 3105.5		
	1. Performed	I Mid Cycle oil service. oil and oil filter, PN: CH48108-1 and added	10 Ote Phillips 20w/50 Y/C	
	3. Post main	tenance turn performed satisfactory with no	leaks noted at this time.	
	Aero Service of Wine			
	 615 Airport Road St Winchester, VA 220 540-665-0193 			
	- 540-005-0193	Charlie Schoenduby A&P-3152411 IA		
			COCK 1444-C	
		N4472K Navion "A" Tach: 1371.9 TI		
	1 Performed		tail of EAD 42 Annualis D	
	2. Performed	100 Hour Inspection IAW the scope and decompression check with the following result:	S.	
	2. Performed 6 #1 62/80 #	compression check with the following results 42 44/80 #3 68/80 #4 70/80 #5 62/80 #6	s. 6 60/80	
	2. Performed 6 #1 62/80 # 3. Cleaned and	compression check with the following result: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in lov	s. 6 60/80	
	2. Performed 6 #1 62/80 # 3. Cleaned and 4 Checked ma	compression check with the following result: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in lowagneto to engine timing.	s. 6 60/80 wer position.	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked mass. Serviced en	compression check with the following results 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and results agreed to the second seco	s. 6 60/80 wer position.	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 l 7. Retrieved o	compression check with the following result: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and reported of Cam Guard. il sample.	s. 6 60/80 wer position.	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 to 7. Retrieved o 8. Washed eng	compression check with the following results 22 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and reportle of Cam Guard. il sample. gine and lubricated controls.	s. 660/80 wer position. new CH48408-1 filter.	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 to 7. Retrieved o 8. Washed eng 9. Inspected a	compression check with the following result: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and reported of Cam Guard. il sample.	s. 660/80 wer position. new CH48408-1 filter. serviceability.	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 l 7. Retrieved o 8. Washed eng 9. Inspected al 10. Post mainte Aero Service of Wi	compression check with the following results 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and reported of Cam Guard. il sample. gine and lubricated controls. Il accessories and hardware for security and mance turn performed satisfactorily with no nechester, Inc.	s. 6 60/80 wer position. new CH48408-1 filter. serviceability. leaks noted at this time. certify that this AIRCRAFT has been	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 li 7. Retrieved o 8. Washed eng 9. Inspected al 10. Post mainte Aero Service of Winchester, VA 2	compression check with the following results: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and resortle of Cam Guard. il sample. gine and lubricated controls. Il accessories and hardware for security and mance turn performed satisfactorily with no nechester, Inc. Suite 107 2602	s. 660/80 wer position. new CH48408-1 filter. serviceability. leaks noted at this time. certify that this AIRCRAFT has been aspected in accordance with a 100 HOUR aspection and determined to be in	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 l 7. Retrieved o 8. Washed eng 9. Inspected al 10. Post mainte Aero Service of Wi 615 Airport Road	compression check with the following results: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and resortle of Cam Guard. il sample. gine and lubricated controls. Il accessories and hardware for security and mance turn performed satisfactorily with no nechester, Inc. Suite 107 2602	s. 6 60/80 wer position. new CH48408-1 filter. serviceability. leaks noted at this time. certify that this AIRCRAFT has been aspected in accordance with a 100 HOUR	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 li 7. Retrieved o 8. Washed eng 9. Inspected al 10. Post mainte Aero Service of Winchester, VA 2	compression check with the following results: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and resortle of Cam Guard. il sample. gine and lubricated controls. Il accessories and hardware for security and mance turn performed satisfactorily with no nechester, Inc. Suite 107 2602	s. 660/80 wer position. new CH48408-1 filter. serviceability. leaks noted at this time. certify that this AIRCRAFT has been aspected in accordance with a 100 HOUR aspection and determined to be in	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 li 7. Retrieved o 8. Washed eng 9. Inspected al 10. Post mainte Aero Service of Winchester, VA 2	compression check with the following results: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and resortle of Cam Guard. il sample. gine and lubricated controls. Il accessories and hardware for security and mance turn performed satisfactorily with no nechester, Inc. Suite 107 2602	s. 660/80 wer position. new CH48408-1 filter. serviceability. leaks noted at this time. certify that this AIRCRAFT has been aspected in accordance with a 100 HOUR aspection and determined to be in invorthy condition.	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 li 7. Retrieved o 8. Washed eng 9. Inspected al 10. Post mainte Aero Service of Winchester, VA 2	compression check with the following results: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and resortle of Cam Guard. il sample. gine and lubricated controls. Il accessories and hardware for security and mance turn performed satisfactorily with no nechester, Inc. Suite 107 2602	s. 660/80 wer position. new CH48408-1 filter. serviceability. leaks noted at this time. certify that this AIRCRAFT has been aspected in accordance with a 100 HOUR aspection and determined to be in invorthy condition.	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 li 7. Retrieved o 8. Washed eng 9. Inspected al 10. Post mainte Aero Service of Winchester, VA 2	compression check with the following results: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and resortle of Cam Guard. il sample. gine and lubricated controls. Il accessories and hardware for security and mance turn performed satisfactorily with no nechester, Inc. Suite 107 2602	s. 660/80 wer position. new CH48408-1 filter. serviceability. leaks noted at this time. certify that this AIRCRAFT has been aspected in accordance with a 100 HOUR aspection and determined to be in invorthy condition.	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 li 7. Retrieved o 8. Washed eng 9. Inspected al 10. Post mainte Aero Service of Winchester, VA 2	compression check with the following results: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and resortle of Cam Guard. il sample. gine and lubricated controls. Il accessories and hardware for security and mance turn performed satisfactorily with no nechester, Inc. Suite 107 2602	s. 660/80 wer position. new CH48408-1 filter. serviceability. leaks noted at this time. certify that this AIRCRAFT has been aspected in accordance with a 100 HOUR aspection and determined to be in invorthy condition.	
	2. Performed of #1 62/80 # 3. Cleaned and 4. Checked may 5. Serviced en 6. Installed 1 li 7. Retrieved o 8. Washed eng 9. Inspected al 10. Post mainte Aero Service of Winchester, VA 2	compression check with the following results: 2 44/80 #3 68/80 #4 70/80 #5 62/80 #6 d gapped spark plugs. Fine wire plugs in low agneto to engine timing. gine with 10 Qts Phillips 20W/50 X/C and resortle of Cam Guard. il sample. gine and lubricated controls. Il accessories and hardware for security and mance turn performed satisfactorily with no nechester, Inc. Suite 107 2602	s. 660/80 wer position. new CH48408-1 filter. serviceability. leaks noted at this time. certify that this AIRCRAFT has been aspected in accordance with a 100 HOUR aspection and determined to be in invorthy condition.	

AIRCRAFT MAINTENANCE RECORD Page No.

Date	Total Time		RIPTION OF WORK PERFORMED FICATE NUMBER OF PERSON PERFORMING WORK				
CARRIED ->	January 19, 2023	N4472K Navion "A" Ta	ch: 1424.7 TETSN: 1424.7				
	 Performed 100 Hour Inspection IAW the scope and detail of FAR 43 Appendix D. Performed compression check with the following results. #1 60/80 #2 60/80 #3 72/80 #4 70/80 #5 62/80 #6 64/80 						
	 Cleaned and gapped spark plugs. Fine wire plugs in lower position. Checked magneto to engine timing. Serviced engine with 10 Qts Phillips 20W/50 X/C and new CH48408-1 filter. 						
		d oil sample. 1 bottle cam guard.					
	8. Washed	engine and lubricated controls					
		all accessories and hardware for security and serviceability. Itenance turn performed satisfactorily with no leaks noted at this time.					
	Aero Service of 615 Airport Ro Winchester, VA 540-665-0193		I certify that this AIRCRAFT has been inspected in accordance with a 100 HOUR inspection and determined to be in airworthy condition.				
	_		Malisen				
		- 1	Charlie Schoenduby A&P 3152411				
	February 8, 2024 N4472K Navion "A" Tach: 1441.9 TETSN: 1441.9						
	 Performed 100 Hour Inspection IAW the scope and detail of FAR 43 Appendix D. Performed compression check with the following results. #1 60/80 #2 60/80 #3 70/80 #4 68/80 #5 65/80 #6 60/80 Cleaned and gapped spark plugs. Fine wire plugs in lower position. 						
	5. Serv	cked magneto to engine timin riced engine with 10 Qts Phill rieved oil sample.	e with 10 Qts Phillips 20W/50 X/C and new CH48408-1 filter.				
	7. Insta	held 1 bottle cam guard. hed engine and lubricated controls. ected all accessories and hardware for security and serviceability.					
	8. Was						
	10. Post	10. Post maintenance turn performed satisfactorily with no leaks noted at this time.					
	615 Airp	ice of Winchester, Inc. ort Road Suite 107	I certify that this AIRCRAFT has been inspected in accordance with a 100 HO				
	Winchester, VA 22602 540-665-0193		inspection and determined to be in airworthy condition.				
			Olat Say				
			Charlie Schoenduby A&P 3152411				
		SUB-TOTAL THIS PAGE	SE TEXANTANA				
		TOTAL - CARRY FORM					