

Aircraft Propeller Works, Inc



(863) 875-4800

www.aircraftpropellerworks.com
FAA Repair Station 4TZR125D

506 Charlotte Rd.
Auburndale, FL. 33823

AIRCRAFT PROPELLER WORKS, INC
506 Charlotte Road, Auburndale, FL 33823 CRS# 4TZR125D

PROPELLER S/N BP7473 WORK PERFORMED Overhauled
PROPELLER M/N HC-E2YR-2RBSF F8465-7R

Propeller overhauled in accordance with Hartzell manuals 159-87, 202A V1-65, 202A V2-33, 202A V6-38, 202A V8-37, 202A V11-38, 117D-24. Hub overhauled by Johnson Propeller Service WO MS21-036, blades overhauled by Dominion Propeller Corporation. In compliance with SL-61-366 this propeller uses NYCO GN3058 grease, the use of any other grease during the maintenance of this propeller is prohibited. TTSN: Unknown TSO: 00.0

AD Compliance:

No AD's apply to this propeller at this time.

PERTINENT DETAILS ON FILE UNDER WORK ORDER: 081TFP

Adam Flake DATE: 2/6/2024

INSTALLER MUST CONFIRM ELIGIBILITY WITH APPLICABLE TECHNICAL DATA AND INSTALL I/A/W FAR 43.9



PROPELLER LIMITED WARRANTY

WORK ORDER: 081TFP
MODEL NUMBER: HC-E2YR-2RBSF
SERIAL NUMBER: BP7473

DATE: 2/6/2024

Hartzell Propellers overhauled by Aircraft Propeller Works, Inc. have a 18 month or 1000 hour warranty on Parts and Labor involved in the Overhaul Only. Propeller Repairs have a 12 month or 500 hour warranty on Parts and Labor involved in the Repair Only.

McCauley Threadless Propellers overhauled by Aircraft Propeller Works, Inc. have a 18 month or 1000 hour warranty on Parts and Labor involved in the Overhaul Only. Propeller Repairs have a 12 month or 500 hour warranty on Parts and Labor involved in the Repair Only.

McCauley Threaded Propellers overhauled by Aircraft Propeller Works, Inc. have a 12 month or 500 hour warranty on Parts and Labor involved in the Overhaul Only. Propeller Repairs have a 12 month or 500 hour warranty on Parts and Labor involved in the Repair Only.

All warranty periods are calendar time or flight time, whichever occurs first. All warranty work is to be performed by APWI unless approved in writing prior to the work being accomplished. APWI is not responsible for transporting the propeller for repair.

Warranty does not cover; misuse, accidents, neglect, normal wear and tear, corrosion, loss of business, loss of income, travel, lodging and food expenses, removal and installation of propeller, unauthorized changes and shipping.

506 Charlotte Road, Auburndale, FL 33823
863-875-4800 - office@aircraftpropellerworks.com
CRS# 4TZR125D