

PROPELLER LOG BOOK



**SENSENICH WOOD PROPELLER CO., INC.
PLANT CITY, FL**

www.sensenichprop.com

**This log book is to be kept with the propeller
for recording of all propeller maintenance performed**





Propeller Maintenance Record

Propeller Model Number W726K44U

Propeller Serial Number AH4630


Size of Steel Aircraft Bolt		Recommended Wrench Torque Range		
Spec.	Dia. (in.)	in.-lb.	ft.-lb.	n.-m.
AN4	1/4	120 to 140	10 to 12	14 to 16
AN5	5/16	130 to 160	11 to 13	15 to 18
x ✓ AN6	3/8	175 to 225	15 to 19	20 to 25
AN7	7/16	225 to 275	19 to 23	25 to 31
AN8	1/2	275 to 325	23 to 27	31 to 37
AN10	5/8	325 to 375	27 to 31	37 to 42

**DESCRIPTION OF ALL OPERATIONS PERTAINING TO
AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS,
SERVICE LETTERS AND MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		Installed propeller on Continental O-200 SN 256485, aircraft American Legend Cub SN AL-1143. Tachometer 0.0.  Pat Bowers American Legend Aircraft Company 11/25/2008	
26 Feb 09	26.5	chkd bolt torque / 17 ft/lbs O.K.	
7 Aug 09	50.8	chkd bolt torque / 17 ft/lbs	
20 June 10	75.8	chkd Bolt Torque / 12 ft/lbs	

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		CHECKED PROP MOUNT BOLTS	
		PER SENSENCH.	
<p>FOOTHILL AIRCRAFT SALES & SERVICE, INC. CABLE AIRPORT UPLAND, CA 91786 FAA APPROVED REPAIR STATION AJ4R052M I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH ANNUAL INSPECTION PER THE MANUFACTURES MAINTENANCE MANUAL. AND APPROVED FOR RETURN TO SERVICE DETAILS OF THIS INSPECTION ARE ON FILE AT THIS FACILITY.</p>			
<p>WO# <u>12158</u> DATE <u>4-2-2012</u> TAC <u>125.4</u> T.T. A/C <u>125.4</u> PROPELLER <u>125.4</u> NAME <u><i>[Signature]</i></u></p>			

PROP MODEL: W72GK44U
PROP S/N: AH4630
REG. NO: 79LC
WORK ORDER:
14382-04-2013



Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13Th St
Upland, CA 91786
Phone: 909-985-1977

DATE: 5/2/2013
A/C TSN: 184.2
PROP TT: 184.2
TACH: 184.2

Prop Entries

(3) COMPLIED WITH ANNUAL / 100 HOUR ON PROPELLER. VERIFIED CORRECT TOQUE OF PROP BOLTS.

Maintenance Release

I certify that the PROPELLER on 79LC was inspected in accordance with an 100hr./Annual inspection per the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 14382-04-2013, Dated 5/2/2013.

DATE: 5/2/2013

SIGNED:

[Signature]

Work Order: 14382-04-2013

Mike Hartman
Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
W72GK44U
PROP S/N: AH4630
REG. NO: 79LC
WORK ORDER:
14999-05-2014

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13Th St
Upland, CA 91786
Phone: 909-985-1977

DATE: 6/3/2014
A/C TSN: 242.9
PROP TT: 242.9
TACH: 242.9

GNATURE

DATE

Prop Entries


(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING AMERICAN LEGEND M.M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE.... (6) CHECK TORQUE ON PROPELLER PER SENSENICH M.M.

Maintenance Release

I certify that the PROPELLER on 79LC was inspected in accordance with an 100hr./Annual inspection per the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 14999-05-2014, Dated 6/3/2014.

DATE: 6/3/2014

SIGNED:



Work Order: 14999-05-2014

Don Wade
Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
W72GK44U
PROP S/N: AH4630
REG. NO: 79LC
WORK ORDER:
15622-06-2015

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13Th St
Upland, CA 91786
Phone: 909-985-1977

DATE: 7/10/2015
A/C TSN: 301.1
PROP TT: 301.1
TACH: 301.1

Prop Entries


(3) C/W ANNUAL/100 HR INSPECTION ON THIS PROPELLER I.A.W FAR 43 APPENDIX D USING AMERICAN LEGEND M.M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. ADs CHECK THROUGH 7/13/2015.... (9) CHECKED TORQUE ON PROP BOLTS. ALL GOOD

Maintenance Release

I certify that the PROPELLER on 79LC was inspected in accordance with an 100hr./Annual inspection per the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 15622-06-2015, Dated 7/10/2015.

DATE: 7/10/2015

SIGNED:



Work Order: 15622-06-2015

Mike Hartman
Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

DATE

PROP MODEL:
W72GK44U
PROP S/N: AH4630
REG. NO: 79LC
WORK ORDER:
16227-07-2016



Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13Th St
Upland, CA 91786
Phone: 909-985-1977

DATE: 8/1/2016
A/C TSN: 356
PROP TT: 356
TACH: 356

SIGNATURE

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING AMERICAN LEGEND INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED THROUGH 7/2016.

Maintenance Release

I certify that the PROPELLER on 79LC was inspected in accordance with an 100hr./Annual inspection per the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 16227-07-2016, Dated 8/1/2016.

DATE: 8/1/2016

SIGNED:

Work Order: 16227-07-2016

Joe Caliva
Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
W72GK44U
PROP S/N: AH4630
REG. NO: 79LC
WORK ORDER:
16916-08-2017

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13Th St
Upland, CA 91786
Phone: 909-985-1977

DATE: 9/1/2017
A/C TSN: 412.7
PROP TT: 412.7
TACH: 412.7

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING AMERICAN LEGEND INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED THROUGH 8/2017.

Maintenance Release

I certify that the PROPELLER on 79LC was inspected in accordance with an 100hr./Annual inspection per the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 16916-08-2017, Dated 9/1/2017.

DATE: 9/1/2017

SIGNED:

Work Order: 16916-08-2017

Joe Caliva
Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

DATE	TACH TIME	DESCRIPTION OF WORK	SIGN
------	-----------	---------------------	------

PROP MODEL:
W72GK44U
PROP S/N: AH4630
REG. NO: 79LC
WORK ORDER:
17548-10-2018



Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M
1749 W 13Th St
Upland, CA 91786
Phone: 909-985-1977

DATE: 10/11/2018
A/C TSN: 416.7
PROP TT: 416.7
TACH: 416.7

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING AMERICAN LEGEND INSPECTION CHECKLIST AS A GUIDE. PROP BOLTS TORQUE CHECKED

Maintenance Release

I certify that the PROPELLER on 79LC was inspected / repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 17548-10-2018, Dated 10/11/2018.

DATE: 10/11/2018

SIGNED:

Work Order: 17548-10-2018

Mike Hartman
Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
W72GK44
PROP S/N: AH4630
REG. NO: 79LC
WORK ORDER:
19678-11-2022



Foothill Aircraft Sales & Service, Inc.
Repair Station No. AJ4R052M
1749 W 13Th St
Upland, CA 91786
Phone: 909-985-1977

DATE: 1/13/2023
A/C TSN: 509.1
PROP TT: 509.1
TACH: 509.1

Prop Entries

(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING AMERICAN LEGEND INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED THROUGH 01/2023.

Maintenance Release

I certify that the PROPELLER on 79LC was inspected / repaired in accordance with the manufacturer's maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 19678-11-2022, Dated 1/13/2023.

DATE: 1/13/2023

SIGNED:

Mike Hartman
Certified Repair Station No. AJ4R052M

Work Order: 19678-11-2022

Printed by EBis 3 (datcomedia.com)