



CESCOM 20 - Projected Maintenance Due

Owner: **JETSONS AVIATION**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0643**
 Unit: **0293** Reg No: **N504SF**
 Airworthiness: **26-Nov-1975**
 Print Date: **18-Jul-2024 6:34PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	10316.6	7209	21-Jun-2024	.38	0.66	129.53	97	197	6
ENG 1	2405.4	1692	21-Jun-2024	.38	0.66	129.53	97	197	6
ENG 2	2405.4	1692	21-Jun-2024	.38	0.66	129.53	97	197	6
AIR COND	117.4		21-Jun-2024	.9	0.07	12.93		197	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Overdue Maintenance Tasks

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
351004 COPILOT	OXYGEN MASK	RNO	L,M,N,P	MC10-16-101 116538	MTH 02-Oct-2018 HRS 9738.5 LDG 6620		72	0	31-Jul-2023	-11 m 18 d
										Over Due
B243003	FUNCTIONAL CHECK BATTERY LEAD ACID BATTERY (CAPACITY CHECK): PHASE 54 INSPECTION	MQY		RG-380E/44 41040136	MTH 01-Mar-2024 HRS 10258.5 LDG 7155		3 200		30-Jun-2024 10458.5	-18 d 141.9
										Over Due

Scheduled Maintenance Tasks

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
B326003 051227	HYDROSTATIC TEST EMERGENCY GEAR AIR BOTTLE	KOJA		23111321 2106	MTH 05-Oct-2021		36		31-Oct-2024	3 m 13 d
053019	RE-WEIGH AIRCRAFT	RNO			MTH 16-Nov-2019 HRS 10000.6 LDG 6917		60		30-Nov-2024	4 m 12 d
5-12-0B 051218	PHASE B	MQY			MTH 01-Mar-2024 HRS 10258.5 LDG 7155		150		10408.5	91.9
052003 E1	FJ44 CHECK 3				MTH 29-Mar-2006 HRS 0	-12500	15000		(2500)10411.2	94.6
052003 E2	FJ44 CHECK 3				MTH 29-Mar-2006 HRS 0	-12500	15000		(2500)10411.2	94.6
SB WI-72-1008 R01 E1	HIGH PRESSURE TURBINE BLADES - REPLACE (SUPERSEDED BY SB WISB-72-1040)			MANDATORY	MTH HRS MSC				(2500)10411.2	94.6
SB WI-72-1008 R01 E2	HIGH PRESSURE TURBINE BLADES - REPLACE (SUPERSEDED BY SB WISB-72-1040)			MANDATORY	MTH HRS MSC				(2500)10411.2	94.6

Service Bulletins

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB FJ44-72-067 R02 E1	ENGINE- UPGRADE GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION				HRS		3500		(3500)11411.2	1094.6
SB FJ44-72-067 R02 E2	ENGINE- UPGRADE GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION				HRS		3500		(3500)11411.2	1094.6
SB FJ44-72-109 E1	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS MSC				(3500)11411.2	1094.6
SB FJ44-72-109 E2	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS MSC				(3500)11411.2	1094.6
SB FJ44-72-116 E1	DIFFUSER CASE ASSEMBLY - REWORK OR REPLACE			RECOMMENDED	HRS MSC				(3500)11411.2	1094.6



CESCOM 20 - Projected Maintenance Due

Owner: **JETSONS AVIATION**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0643**
 Unit: **0293** Reg No: **N504SF**
 Airworthiness: **26-Nov-1975**
 Print Date: **18-Jul-2024 6:34PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	10316.6	7209	21-Jun-2024	.38	0.66	129.53	97	197	6
ENG 1	2405.4	1692	21-Jun-2024	.38	0.66	129.53	97	197	6
ENG 2	2405.4	1692	21-Jun-2024	.38	0.66	129.53	97	197	6
AIR COND	117.4		21-Jun-2024	.9	0.07	12.93		197	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB FJ44-72-116 E2	DIFFUSER CASE ASSEMBLY - REWORK OR REPLACE				HRS MSC				(3500)11411.2	1094.6
				RECOMMENDED						
SB FJ44-72-133 R02 E1	REPLACE 1ST LP TURBINE NOZZLE				HRS MSC				(3500)11411.2	1094.6
				RECOMMENDED						
SB FJ44-72-133 R02 E2	REPLACE 1ST LP TURBINE NOZZLE				HRS MSC				(3500)11411.2	1094.6
				RECOMMENDED						
SB FJ44-72-143 E1	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-143 R01)				MTH HRS MSC				(3500)11411.2	1094.6
				RECOMMENDED						
SB FJ44-72-143 E2	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-143 R01)				MTH HRS MSC				(3500)11411.2	1094.6
				RECOMMENDED						
SB FJ44-72-143 R01 E1	BLEED VALVE SHAFT - REPLACE				MTH HRS MSC				(3500)11411.2	1094.6
				RECOMMENDED						
SB FJ44-72-143 R01 E2	BLEED VALVE SHAFT - REPLACE				MTH HRS MSC				(3500)11411.2	1094.6
				RECOMMENDED						
SB FJ44-72-143 R02 E1	BLEED VALVE SHAFT - REPLACE				MTH HRS MSC				(3500)11411.2	1094.6
				RECOMMENDED						
SB FJ44-72-143 R02 E2	BLEED VALVE SHAFT - REPLACE				MTH HRS MSC				(3500)11411.2	1094.6
				RECOMMENDED						
SB FJ44-72-115 E1	ENGINE - DAMPENER BRACKET ASSEMBLY - INSTALL				HRS MSC				(5000)12911.2	2594.6
				MANDATORY						
SB FJ44-72-115 E2	ENGINE - DAMPENER BRACKET ASSEMBLY - INSTALL				HRS MSC				(5000)12911.2	2594.6
				MANDATORY						
SB FJ44-79-011 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)				HRS MSC				(5000)12911.2	2594.6
				MANDATORY						
SB FJ44-79-011 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)				HRS MSC				(5000)12911.2	2594.6
				MANDATORY						
SB FJ44-79-011 R01 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)				MTH HRS MSC				(5000)12911.2	2594.6
				MANDATORY						
SB FJ44-79-011 R01 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)				MTH HRS MSC				(5000)12911.2	2594.6
				MANDATORY						
SB WI-73-1000 R01 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE				MTH HRS MSC				(5000)12911.2	2594.6
				RECOMMENDED						
SB WI-73-1000 R01 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE				MTH HRS MSC				(5000)12911.2	2594.6
				RECOMMENDED						



CESCOM 20 - Projected Maintenance Due

Owner: **JETSONS AVIATION**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0643**
 Unit: **0293** Reg No: **N504SF**
 Airworthiness: **26-Nov-1975**
 Print Date: **18-Jul-2024 6:34PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	10316.6	7209	21-Jun-2024	.38	0.66	129.53	97	197	6
ENG 1	2405.4	1692	21-Jun-2024	.38	0.66	129.53	97	197	6
ENG 2	2405.4	1692	21-Jun-2024	.38	0.66	129.53	97	197	6
AIR COND	117.4		21-Jun-2024	.9	0.07	12.93		197	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 500-32-51 REV 01	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS									
				MTH						
				RECOMMENDED	MSC					