

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J34F-2UF/FG 7663 B-2R

PROPELLER S/N ED 5650 B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position LH

PITCH RANGE

Propeller Model PIG-J3YF-2WF/FC763B-2R

High/Feather _____

Propeller S/N E05650D

Start Lock _____

Blade Design _____

Low _____

Blade S/N's

Reverse _____

No. 1 K 75519

No. 2 K 75518

No. 3 K 75520

No. 4 _____

No. 5 _____

No. 6 _____

Aircraft Manufacturer Beech

Aircraft Model _____

S/N J# 107

Registration N 9094Q

Spinner Assembly Part No. D7811-2P
S/N 0904723C

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
5/12/10	-0-		TT 6947.4	This Propeller # ED5650B was installed on Beech 58 N9094Q LH location in new washers and nuts. 237 Date 5/12/10 A & P 3355961 Robert D. Hebenstreit <i>(Signature)</i>

Associated Aero Service Inc

P. O. Box 1310 • Bethany, OK 73008 • (405) 789-5474 • FAA CRS SSWR186K

Beech 58 TH-107 N9094Q 06/02/2010
 Left Hand Prop SN: ED5650B ACTT: 6947.6 Prop TT: (New) -0-

Removed spinner, inspected hub and all plumbing, serviced ^{done}~~done~~ pressure to 41 psi with N2, reinstalled spinner.
 This propeller has been inspected in accordance with a 100 hour inspection and was determined to be in an
 airworthy condition. See airframe entry dated 06/02/2010.

(NF)

Robert D. Hebenstreit
 A&P 3355961 IA

(Signature)

Date	Propeller TSN	TSO	A/C Hrs	Description
10/5/12	397.4		7344.8	100hr. inspection completed this date IAW FAR 43 Appendix D. Lubed prop with Perashell #6. Checked dome pressure. I certify that this propeller has been inspected IAW a 100 hour inspection and was determined to be in airworthy condition this date. /s/ W W ATP 3245072
1/6/14	Hobbs 3272.0			100hr. inspection completed this date IAW FAR 43 Appendix D. Lubed prop with Perashell #6. Serviced prop dome with nitrogen. I certify that this propeller has been inspected IAW a 100hr. inspection + was completed this date. /s/ W W ATP 3245072

6/21/15	Hobbs	3360.0	612.7 SNEW	100 hr. inspection completed this date IAW FAR 43 Appendix D. Lubed prop with Perashell #6. Checked dome pressure. I certify that this propeller has been inspected IAW a 100hr. inspection + was determined to be in airworthy condition this date. /s/ W W ATP 3245072
---------	-------	--------	------------	---

Left Propeller Log: Hartzell PHC-J3YF-2UF N9094Q S/N: ED5653B May 8, 2017
 Hobbs: 3443.1 ETT: 695.8 TSOH: 695.8 ACTT: 7643.4

Complied with annual inspection in accordance with Beechcraft 58 Maintenance Manual and FAR 43 Appendix D. Filed minor burrs and nicks from blades. Checked all applicable and recurrent AD's through this date. See logbooks for updated AD compliance list. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition for return to service at this ACTT and date.

BY: Total Aircraft Services, Inc.
 17910 Airfield Lane
 Pearland, TX. 77581



Kirk B. Taylor
 Kirk B. Taylor, A 3525486

Date

Propeller
TSN TSO

AVC
Hrs

Description of all operations pertaining to
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Left Propeller Log: Hartzell PHC-J3YF-2UF N9094Q S/N: ED5653B
Hobbs: 3603.6 TSN: 856.3

June 8, 2018
ACTT: 7803.9

Complied with annual inspection in accordance with Beechcraft 58 Maintenance Manual and FAR 43 Appendix D. Filed minor burs and nicks from blades. Checked all applicable and recurrent AD's through this date. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition for return to service at this ACTT and date.

BY: Total Aircraft Services, Inc.
17910 Airfield Lane
Pearland, TX. 77581



Timothy M. Olson
Timothy M. Olson AP 3584136 IA

Left Propeller Log Entry

REG #	N9094Q	Date	8/11/19	Serial#	TH-107
MFG	Beech	Model	58	TTSOH	988

Compiled with an annual inspection IAW FAR 43 referencing Beech 58 MM
I certify that this Propeller has been inspected IAW an annual inspection
and was found to be in airworthy condition.

Brian Welling *Brian Welling* A/P 3692260 IA.

wo: 14877

Propeller L - page 1 of 1



Total Aircraft Services INC. · 17910 AIRFIELD LN · PEARLAND, Texas 77581-6295 · 281-993-1150

N9094Q Hartzell, PHC-J3YF-2UF/FC7663B-2R, S/N: ED5650B September 23, 2020
hobbs: 3853.6 PTSN: 1106.3

Complied with 100 hour inspection in accordance with Beechcraft 58 Maintenance Manual and FAR 43 Appendix D. Checked all applicable and recurrent AD's through this date.

I certify this Propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition for return to service this ACTT and date.

Kyle Taylor A&P 3795044 *Kyle Taylor*

Tango Charlie Aviation LLC

3093 Mitchell Drive Malden Mo 63863 (573) 281-2227

Propeller Left

Hartzell PHC-J3YF-2UF/FC766B-2R

Hobbs: 3962.7



SPOH: 1215.4

This date dressed leading edges and painted back of prop flat black.

I certify that this propeller has been inspected IAW FAR43.app(d) an annual inspection and was determined to be in an airworthy condition.

Terance Gromer IA3690972
Terance Gromer

N9094Q
S/N: ED5650B
Date: 10/22/2021
Total Time: 1215.4

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	Tango Charlie Aviation LLC		
	3093 Mitchell Drive Malden Mo 63863 (573) 281-2227		
	Propeller Left		
	Hartzell PHC-J3YF-2UF/FC766B-2R		
	Hobbs: 0.0		
	SPOH: 1223.0		
	This date dressed leading edges and painted back of prop flat black.		
	I certify that this propeller has been inspected IAW FAR43.app(d) an annual inspection and was determined to be in an airworthy condition.		
	N9094Q S/N: ED5650B Date: 1/2/2023 Total Time: 1223.0  Terance Gromer IA3690972		
	Tango Charlie Aviation LLC		
	3093 Mitchell Drive Malden Mo 63863 (573) 281-2227		
	Propeller Left		
	Hartzell PHC-J3YF-2UF/FC766B-2R		
	Hobbs: 29.3		
	SPOH: 1253.30		
	This date dressed leading edges and painted back of prop flat black.		
	I certify that this propeller has been inspected IAW FAR43.app(d) an annual inspection and was determined to be in an airworthy condition.		
	N9094Q S/N: ED5650B Date: 3/13/2024 Total Time: 1253.30  Terance Gromer IA3690972		