

1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 43533	
4. Organization Name and Address: New England Propeller Service, Inc FAA RSN RC2R130L EASA 145.5972				5. Work Order/Contract/Invoice Number: CR-43533	
6 Matthews Drive East Haddam, CT 06423-2388 (860) 873-1494 · Fax: (860) 873-2388					
Item:	7 Description:	8 Part Number:	9 Quantity:	10. Serial Number:	11. Status/Work:
1	HARTZELL PROPELLER	HC-C24F-2CUF FC 8468-3	1	AN 7136B	OVERHAUL
12 Remarks THIS PROPELLER WAS REPAIRED IN ACCORDANCE WITH MANUFACTURER'S MANUALS:			117DR16	133CR34	202A
			V2R24	V3R38	V6R34
			V8R32	V9R31	V10R34
			V11R36	V12R55	V17R43
			V18R32	V19R31	V110R34
Total Time <u>UNKNOWN</u> hrs			Time Since Overhaul: <u>00.00</u> hrs		
Details of work performed are on file at New England Propeller Service, Inc. under Repair Station Work Order Number: <u>CR-43533</u>					
The following work was performed: MAJOR OVERHAUL. BLADES REFINISHED. PARTS FLORESCENT PENETRANT INSPECTED, MAGNAFLUXED, & REPLACED WHERE REQUIRED. DEICER BOOTS INSTALLED. PROP TRACKED, BALANCED, GREASED, SET ANGLES & PAINTED. COMPLIES WITH AD'S & SB'S LISTED ON 8130-3 FORM. <u>BLADE KNOBS SHOTPEENED.</u>					
Blade Serial #'s:		1) <u>J 12687</u>	2) <u>J 12688</u>	3) _____	4) _____
		5) _____	6) _____		
MAJOR PARTS REPLACED					

PROPELLER MAINTENANCE RECORD

LEFT ENGINE	RIGHT ENGINE
Hub Model <u>HC-C24F-2CUF</u>	Hub Model _____
Blade Design <u>FC 8468-3</u>	Blade Design _____
Diameter _____	Diameter _____
Hub Ser. No. <u>AN 7136B</u>	Hub Ser. No. _____
Blade Ser. Nos.	Blade Ser. Nos. _____
No. 1 <u>J 12687</u>	No. 1 _____
No. 2 <u>J 12688</u>	No. 2 _____
No. 3 _____	No. 3 _____
No. 4 _____	No. 4 _____
No. 5 _____	No. 5 _____
PITCH RANGE	PITCH RANGE
High <u>18.0</u> Low <u>12.5</u>	High _____ Low _____
Feather <u>82.0</u> Reverse _____	Feather _____ Reverse _____
Governor Model _____	Governor Model _____


DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4-28-17	750 H 00.00	HC-224F-2CUF/FC 8468-3	S/N AN7136B
		MAJOR OVERHAUL. BLADES REFINISHED. PARTS FLORESCENT PENETRANT INSPECTED, MAGNAFLUXED, & REPLACED WHERE REQUIRED. DEICER BOOTS INSTALLED. PROP TRACKED, BALANCED, GREASED, SET ANGLES & PAINTED. COMPLIES WITH AD'S & SB'S LISTED ON 8130-3 FORM. BLADE KNOBS SHARPENED.	
		AUTHORIZED BY	W/ #CR-43533
		<i>[Signature]</i>	<i>[Signature]</i>
		For NEW ENGLAND PROPELLER SERVICE, INC.	
		EAST HADDAM, CT	
		FAA REPAIR STATION # RC2R130L	
		1-800-878-6377	


DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		LANSING FLIGHT SUPPORT 72 SICKER RD LATHAM, NY 12110 (518) 220-4444	N3641D HUB S/N #AN7136B BLADE S/N #J12687 - #J12688 INSTALLED #1 ENGINE
		3 AUG 2018 2432.2 ACTT (21.0 SMOH / TT = UNK) Completed Annual Inspection IAW Cessna / Hartzell Maintenance Manuals. Records Check revealed no new applicable AD's since last Annual Inspection (See AD Compliance Sheet). Ground run was completed and Leak Checks / Operational Checks were completed Satisfactory. I certify that this PROPELLER was inspected IAW an Annual Inspection and was found to be in an Airworthy Condition.	
			<i>[Signature]</i> Sean Healey A&P #31563531A

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		LANSING FLIGHT SUPPORT 72 SICKER RD LATHAM, NY 12110 (518) 220-4444	N3641D HUB S/N #AN7136B BLADE S/N #J12687 - #J12688 INSTALLED #1 ENGINE
17 SEP 2019	2460.4 ACTT (49.2 SMOH / TT = UNK)	Completed Annual Inspection IAW Cessna / Hartzell Maintenance Manuals. Records Check revealed no new applicable AD's since last Annual Inspection (See AD Compliance Sheet). Ground run was completed and Leak Checks / Operational Checks were completed Satisfactory. I certify that this PROPELLER was inspected IAW an Annual Inspection and was found to be in an Airworthy Condition.	 Sean Healey A&P #31563531A

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		LANSING FLIGHT SUPPORT 72 SICKER RD LATHAM, NY 12110 (518) 220-4444	N3641D HUB S/N #AN7136B BLADE S/N #J12687 - #J12688 INSTALLED #1 ENGINE
15 APR 2021	2488.3 ACTT (77.1 SMOH / TT = UNK)	Completed Annual Inspection IAW Cessna / Hartzell Maintenance Manuals. Records Check revealed no new applicable AD's since last Annual Inspection (See AD Compliance Sheet). Ground run was completed and Leak Checks / Operational Checks were completed Satisfactory. I certify that this PROPELLER was inspected IAW an Annual Inspection and was found to be in an Airworthy Condition.	 Sean Healey A&P #31563531A

