

# ENGINE LOG

Serial No

Engine · page 1 of 2

wo: 6424



Classic Aviation · 69 Aviation Circle · Weyers Cave, VA 24486 · (540)234-0226

<b>N5604W</b>	<b>LYCOMING, 0-320 SERIES, S/N: ENGINE SN TBD</b>	<b>February 19, 2024</b>
ENG TT: 3999.9	ACTT : 5318.0	PROP SINCE NEW:
PROP TT: 1525.9	TACH: 1614.4	1525.9

Complied with engine and propeller inspection in conjunction with the annual inspection ion Ref to title 14CFR 43.15, 43 appendix D, and in reference to Piper PA-28 MM 753-586, (01-31-2008). Compression checks. #1- 72/80, #2- 74/80, #3- 74/80, #4- 74/80. Master orifice 38/80. Complied with oil and filter change, took oil sample, drained engine oil. removed oil filter and cut open oil filter and inspected for foreign material, found no foreign material. Installed a serviceable new oil filter P/N: AA48110-2 and torqued filter to 18 inch pounds. Removed sump screen, cleaned and inspected screen found no defects. Reinstalled sump screen with new crush gasket P/N: AN900-16, Torqued and saftied. Serviced engine with 7 Quarts W15W50 engine oil. Complied with engine borescope inspection of the cylinders, found no defects. Complied with Mag timing, Timing at 25 degrees BTDC. Complied with post engine functional checks and leak checks, functional check, leak check good.

The aircraft, airframe, aircraft engine, propeller or appliance identified was repaired and/or inspected in accordance with current Regulation of the Federal Aviation Agency and is approved for return to service for the work performed.