

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-L34F-1RF

PROPELLER S/N PQ172B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position NOSE

Propeller Model PHC-L34F-1RF

Propeller S/N PQ172B

Blade Design _____

Blade S/N's

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Beechcraft

Aircraft Model N35

S/N ~~EE~~ D-6610

Registration N9431Y

SMOKY MOUNTAIN

AEROPLANES

BRENT PRESSLEY
523-273-3537

Installed prop on N9431Y. Torqued nuts. Reinstalled spinner. All work done IAW Hartzell owners manual Ops check for leaks. None found. I have inspected this prop IAW annual/100 hour inspection and found safe for return to service *Cal Smy 4141726 427X*

SOUTH COAST PROPELLER SERVICE, INC.
5750 DUROSE DRIVE, BESSEMER, AL 35022
205-426-7022
REPAIR STATION #S6PR302X

FACTORY NEW PROPELLER , BLADE ANGLES WERE CHANGED
FROM 11.5 (DEGREE) TO 13 (DEGREE).
THIS WAS THE ONLY WORK PERFORMED.

WORK ORDER # SR- 14224
MODEL # PHC-L3YF-1RF
BLADE MODEL # F8468A-6R
HUB SERIAL # PQ172B
DATE: 04/21/2021

JAMES M GAITHER,
GENERAL MANAGER