

The Standard

-X-AIRGRAFT LOG

ASA-SA-1

Sterlite blue Del Fleet / FDGH PPG #940698 Juno White Del Fleet PPG

FABRIC Ceconite 102



ASA-SA-1

The Standard Aircraft Log SA-1

© 1993-2000 Aviation Supplies & Acade

ISBN 1-56027-419-0 ASA-SA-1

All rights reserved.
Reproduction or use, without expressed permission, in any manner, is prohibited.

Published by Aviation Supplies & Academics, Inc. 7005 132nd Place SE Newcastle, WA 98059-3153

Printed in U.S.A.

ACCOMPLISHED SATISFACTORY PER AMERICAN CHAMPION AIRCRAFT SPECIFICATION CSL-1) THIS DATE 3-19-05 TITLEREPAIEMAN INSPECTED THIS AIRPLANE MODEL 766 AA, SERIAL NO. 461-2002 AIRWORTHY, AND RELEASED IT TO PRODUCTION FLIGHT TEST THIS DATE 03-116-02 SIG. TITLE QUI INSPECTOR. PRODUCTION FLIGHT TEST THIS DATE 3-19-02 FOUND IT MEETS THE REQUIREMENT FOR ISSUED A STANDARD AIRWORTHINESS ORM 8/00-Z FOR ACKONATIZ CATEGORY TITLE DMIRSO1214CE IS DUE THIS DATE 03-18-03 LE DIMITREOIZINEE






Aircraft Record General Information		pietored Owner Rocard
Janufacturer AMERICAN CHAMPION Jerial 401-2002	AMCMAT-T Model Registration	Number N 67 BF
Pate of Manufacture 03-15-200		
ingine(s) currently installed:		
Manufacturer Lycoming Model	0-320-BZB	Serial L-19628-39A
Manufacturer Model		Serial
Propeller(s) currently installed: Nanufacturer SENSENICH	Model	74DM658-1-56
NUB Model Serial	A59153	Serial
Blade ModelSerial	Seri	al Serial
Blade ModelSerial	Seri	al Serial

OR

DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
• Marine and America				
	Date, 03-1 Tach Time			

The following items have been installed in this aircraft in accordance with the manufactures specifications and AC43.13. A APOLLO SL-70 transponder with an ameriking AK350 blind encoder. Installed a APOLLO GX-65 GPS/COM/NAV. Installed a E.I.SR8A-4 egt/cht. Installed a airwolfe remote oil filter. Pertinent details of these installations are included in the FAA form 337's issued this date. Weight and balance data for these installations are included in the original equipment list and weight and balance. See FRA work order # 001221.

DALE L. GAUGER. Fox River Aviation CRS No. F35R977Y



YEAR: 2 002 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2-4-02	34.7		34.7	Installed Dauthon model 803 clock
				with volt meter And a At sensor
				Sensor installed in L Fuselage At
	and I			Base of windshield. All wiking And
	1			connections installed 11w Ac 43.13
				No change in w+B. Longers. Month
				Arp 233764403 IA
			100	
	. 4./.			
			1	

YEAR: 2003 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
3-4	64.0	Ø	64.0	this ACFT inspected in A Annual inspection
150	53 140	Aires	F F.	sel American champion 7GCAA Selvice
A. 70	1 1813	251	N Voi	Manual And checklist CHecked All coble
1.53	Also.	X2.355.3	M. 18.	trusions CHecked Elt Function 10 A'D's
	48	A. J.	N. Berra Mil	outstanding Lubricated All controlls
5	-8.7£			solviced tikes I contify that this Acit
la!	n Marin	A Cur	NV Vis	Has Been inspected IAW An Annual inspection
p-Si	510,000	A5 .	10,000	And Found to Be A Nwolthy Kongers Norton
2/4.	ا دارود	A.	100000	Ap 233764403 IA
3-22-04	100.0	8	1000	this test inspected I Aw An Annual inspection
4. 36	1 1216	· K.e.	Che	Jel Amelican Champion TGCAA Selvice
120	3 e/ c/ka	4 29	Hind	Manual And checklest. Lublicated All

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				Tacinty. (Ode back pages for other opening stimes)
A SOUR	Vallan	S 18.	10011	controlls cleaned, in sepected And Repulled
3-5	Sekle	SCAK	5 mg	wheel Bookings . Elt Function check
stole	5 118 C	eckee	Ro de	-ok I creptify that this Arst Has
26	110 19	Kom	L FUNC	Zeen inspected Itw An Annual raspection
	Aca115	453 N	Est A	And Found to be Askwolly Roughs Noto
10		1 16	FIFE FE	1-0233764483D
-21-05	123.0	9	123.0	this AcFt inspected IAW An Annual
The same	W.SM	Kenner	ORFA.	inspection jek American champion
63	F150 3K E	1/4/2	, Y	75CAA SERVICE Manual And check
defen	and was	BATTLE	Se Pre	Removed wheel Faikings apened
1	SIGNOS	9.86	in 250	Access openings, checked who
N	10 16	1 5.3	L. L. D	Blakes Lubed All Hinges - Belch

YEAR: 2005 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-				I cectify that this Aeft Has Been
				Inspected iten an Annual juspection And Found to be Aikworthy Remede Month Ap 237764403 IA
23Mnv	123.0	•	123.0	
				and impact operation Re-installed in pireral T
- 1			1	

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT TIME IN SERVICE Date: Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technici Facility. (See back pages for other specific entries.) Date: 4/27/2005 A/C Time 125 RegNo: N67BF WoNo: 0
1399	1125 B	A/C Make: AMERICAN CHAMP A/C Model: 7GCAA A/C SN: 461-2002
chon	3 W 2 W 1	Removed the following equipmen GX65, GPS ANT
Market of Parketin April 2007	the same	Installed the following equipment GNC420, GA56, MODEL 108
To see	64403	The new empty weight is: 1217.9 lbs.
		The new center of gravity is: 13.1 inches
		The new moment is: 15949.72
1000	Jr. 159.	The new useful load is: 532.1 lbs.
decad.	2. 2. 2 Mill	The installation was performed in accordance with manufacturers specifications and approved for return to service.
		Authorized Signature for: McKee Avionics Inc, 1838 Airport Dr, San Marcos, Tx 78666 CRS# EEKR429K

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alte Entries must be endorsed with Name, Rating and Certificate Nu Facility. (See back pages for other specific entries.)	
	1 650 360	The r	equired tests and	ANSPONDERS and ALTITUDE REPORTING Systems inspections as marked were performed in accordance with current and the equipment and/or systems complied with all requirements. F. TXP #1 SL 70 SN 6052/90ON +/27/05	1 + XX 304 / 4 / / / / / / / / / / / / / / / / /
st.	CHECK!	FOR	PT43. APPX PT43. APPX DETAILS. SE	E. C. INTEGRATED SYSTEM TEST ON 4/27/05 E WO NO 09030 DATED 4/27/05 TO COKE	
	the fried	SIGN	TNO. 27	ILLO 7 3 ICKEE AVIONICS INC., SAN MARCOS, TEXAS CRS-EEKR429K	
	1834 41	, The	1967 E.	Sales of the Art of the State o	ed constants
. N. 19	1.28 3	MONA	1,000	STREET ARE YES BUT OF THE	1/4-22
3	14 10.54	To also	2505	La Chi) squage a decid	ord Dayout 1
1.39	Contract to Berry	ne et	ekaur-	at the total of the said for	- Kneknel

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
9-06	151.4	ø	151.4	this Acet inspected iten An Anaval
	1 325,000		2 6 3	Inspection jet the Amelican champion
	4			7GCAA Selvice Manual And checklist
-				Replaced Brake pads cleaned, inspected
				And Lepached wheel Beakings ELT
			18 860	Function test-ox Duracell Batteries
				AD text And AMOC Dated 2-6-06.
				All Acceptess Swages that Did not
				Meet AD Specifications were Re-C
				1 Am Amoc (no sleeves Had All +
,				(Kimps out of toleRance) InFORM

RECORDING TODAY'S TOTAL Description of Inspections, Tests, Repairs and Alterations YEAR: FLIGHT TIME IN TACH Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair SERVICE TIME Facility. (See back pages for other specific entries.) DATE Concerning the Results of this inspection were provided to FAA IAW AD Instructions. Re-adjusted All cable tensions. I CARTIFY that this AcFt Hos Bean inspected the An Annual inspection And Found to Be AIRWORthy Knows North Ap233764403 IA 161.4 8-17-06 161.4 Removed Pleatronics Intermetional JRSD-4 INSTrum # 52538 and replaced with like unit # 28342 No change in acist & Balance common plugs checked secured ups thekgd

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
8-02	186:5	0 19/12	186:5	Inspected Aircraft In Accordance
Kur hon	30 145	Last	1 66	With AC-43-13-18 And American Champio
. 21	61842	1 3/10	/ Cal	Service Manual ELT Battey Due Repho
The com	9 30H1	15/0	115 /	MENT By Mar, 2008, Checked ALL Aircraft
-18 50	45,80c.	1 /2	From the	Systems Battery Master Brake Cylinder
: North	Homeston	stler.	in Ricia	Fligt Controls And Mountings, All ADS
9463 34	N. EET Ph.		,	Up to This Date, This Aircraft Has Bee
				Inspected IN Accordance With AN -
acat Tabaga	V- 4	5.70	antan.	ANNUAL INSpection And Was Determin
	16 C C C	2 14.	12 /2 x	To Be IN Airworthy Condition.
	Bulker	a This	May Ca	IA 1749653 Edgar D. Miller
	ma 1 , 1	2.44	1990	150 Specifical and a result of manufactures of the Construction of

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				1 1 1 1 1 1 1 1 1
5.19.09	233	994 30	233	replaced tall whee the and tube
		CF-SHCW.	1 00,000	P/N 2.89 x2,50 x4 removed main while
		35 15 25 SE		repeabled bearings and folgreed wheels services
		CH ARK	g Ajya	brakes regulat RH plak Ranel riplical
	96,879		CA	landing Ittl PN/4509 weplaced
				ELT lattable next dul- 0510 222
				Total Time
			4.00	Tachometer
				this (aircraft) (engine) has been inspected in
				accordance with a (annual) (100 hour) inspection
				and was determined to be in airworthy condition.
				Dated 5-19-09 W.D. No. 17.3
				Signed & 50k Lelw 1901964332 IA

ATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endo	rsed with Name, Rating an ges for other specific entries	nd Certificate Number of Technician or
On M Ame bee	nplied with March of 2 erican Cha n inspecte	n ELT che 017. Con mpion Se d in acco	ck in accor npleted an ervice Man ordance wit	Time: 280.1 rdance with FAR 9 nual inspection in nual. I certify that th an Annual inspection	this aircraft has ection and is	
	14-2012			ime: 313		Aircraft Time: 313
Manua batteri	l, accompl	ished EL7 022. I ce	check in a	accordance with FA his Aircraft has be	R 91.207, replaced	raft Corporation Service batteries, due date on ordance with An Annual

YEAR: REGION TAKE TIME		TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repairs Facility. (See back pages for other specific entries.)
1/02/2014	, Tach T	ime 334	.6, Total Ti	ime: 334. 6
and replace American C	d landii hampio	ng light 4 n Service	509, ops c	the with FAR 91.207 battery's due on March of 2017. Removed wheck good. Completed annual inspection in accordance with a certify that this aircraft has been inspected in accordance with y.
Charles R D	eLong		Chall	a R Det - A&P IA 2734865

Removed both left and right wings and reinstalled after completion of repairs and painting. Repaired right rear wing tip trailing edge damage (p/n 2-2259), fabric puback in damaged area and reattached and new 3" finish tape installed, removed an replaced the top 3" tapes at wing station 18. Removed and replaced the top leading edge/spar cap 3" fabric tape on left wing. Both left and right wings re-painted. Rehorizontal stabilizers, removed fabric and recovered and repainted, reinstalled. Ins LED landing light in cowl. Replaced strobe light power pack in right wing, s/n J14090823. Replaced brake linings, bleed brakes and lubricated parking brake cab Installed baggage door, see FAA form 337 dated this date for details. Replaced left
painting. Repaired right rear wing tip trailing edge damage (p/n 2-2259), fabric puback in damaged area and reattached and new 3" finish tape installed, removed an replaced the top 3" tapes at wing station 18. Removed and replaced the top leading edge/spar cap 3" fabric tape on left wing. Both left and right wings re-painted. Rehorizontal stabilizers, removed fabric and recovered and repainted, reinstalled. Ins LED landing light in cowl. Replaced strobe light power pack in right wing, s/n J14090823. Replaced brake linings, bleed brakes and lubricated parking brake cab
window catch. Touched up paint on fuselage. See FRA Enterprises WO 002719 for details of work. Patrick F Shelton Fox River Aviation Enterprises Inc. CRS F35R977Y

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with I	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Facility. (See back pages for other specific entries.)						
2/13/2	015, Tach Ti	ime 364.	5, Total Tir	me: 364.5							
Compli	ed with ELT	check in	accordance	ce with FAR 91.207 batter	y's due on March of 2017. Completed						
				200명 시간 및 기급을 하고 있는 것이 있는 것이 되는 것이 모든 것이 없어요? 하셨다면 모든 데디지 않다.	rice Manual. I certify that this aircraft						
	The second secon		,	h an Annual inspection an	nd is Airworthy.						
Charles	R DeLong	Ch	arla	R He Long	A&P IA 2734865						
-717		3.46									
17.45		4.27									
	24-										
	1										

^ - 1	1057300/, Date 1/24/2017. Maddux N67BF
Date: 01/25/2017 Hours: 401.6 Make: American Champion Model: 7GCAA Serviced and lubed aircraft IAW American Champion 7GG the Annual / 100 hour checklist. Checked ELT IAW FAR (batteries next due 01/2022. I certify this aircraft has been Inspection and was determined to be in an Airworthy con Kelley Babin IA2994200 01/25/2017.	91.207. Replaced ELT inspected IAW an Annual

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alter Entries must be endorsed with Name, Rating and Certificate Nur Facility. (See back pages for other specific entries.)	
ATE				racility. (See back pages for other specific entries.)	
	Date: 10	/30/2017	Hours: 4	15.2	
	Tail#: No				
	Make: An	nerican Ch	nampion Mo	odel: 7GCAA S/N: 461-2002	
	Serviced the Annua due 01/20 was deter				
	Kelley Ba	bin IA299	4200 10/30	0/2017	
		a surface Mark Control Statistics of			

*Installed RC Allen 2610-3 Series Electric Digital Horizon P/N: 102-0403-01-01, S/N: 917L462 in upper center existing mounting hole. Connected power to "Radio #2", 3 amp circuit breaker and connected ground to frame bus. Weight negligible, 337 form completed.

EPIX AVIATION 2802 Airport Drive, Suite 1 Chesapeake, Virginia 23323 T57-421-4973 EpixAviation.com Tach reads: 512.5 AFTT: 512.5 AIRFRAME Complied with an ANNUAL inspection in accordance with 14 CFR 43 Appendix D. Opened all panels, fairings, and interior components as required to facilitate inspection. Inspected fuselage, wings, tail surfaces, cabin, cockpit, landing gear, and all related systems. Serviced and lubricated components and systems as required. Inspected ELT in accordance with FAR 91.207(d).No defects noted. Battery due DEC 2025. Installed new Air Hawk tires on LH and RH main wheels. Installed new brake linings on RH and LH brakes. Installed new hardare on muffler heat shroud. Resecured jam nut on starter button. Installed new lamp in tail nav light. Repaired reinforcing strap for instrument panel. Adjusted mixture cable to assure proper travel. Checked idle speed and idle mixture. Washed enigne. Ground run and leak check OK I certify that this aircraft has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.	ATE	TACH	FLIGHT	TIME IN	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Residual Control of Technician Control of Control of Control of Technica Control of Control o				
Complied with an ANNUAL inspection in accordance with 14 CFR 43 Appendix D. Opened all panels, fairings, and interior components as required to facilitate inspection. Inspected fuselage, wings, tail surfaces, cabin, cockpit, landing gear, and all related systems. Serviced and lubricated components and systems as required. Inspected ELT in accordance with FAR 91.207(d).No defects noted. Battery due DEC 2025. Installed new Air Hawk tires on LH and RH main wheels. Installed new brake linings on RH and LH brakes. Installed new hardare on muffler heat shroud. Resecured jam nut on starter button. Installed new lamp in tail nav light. Repaired reinforcing strap for instrument panel. Adjusted mixture cable to assure proper travel. Checked idle speed and idle mixture. Washed enigne. Ground run and leak check OK I certify that this aircraft has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.	DATE		<i>E71</i>	XIION	2802 Airport Drive, Suite 1 Chesapeake, Virginia 23323 757-421-4973	wo 32517			
interior components as required to facilitate inspection. Inspected fuselage, wings, tail surfaces, cabin, cockpit, landing gear, and all related systems. Serviced and lubricated components and systems as required. Inspected ELT in accordance with FAR 91.207(d).No defects noted. Battery due DEC 2025. Installed new Air Hawk tires on LH and RH main wheels. Installed new brake linings on RH and LH brakes. Installed new hardare on muffler heat shroud. Resecured jam nut on starter button. Installed new lamp in tail nav light. Repaired reinforcing strap for instrument panel. Adjusted mixture cable to assure proper travel. Checked idle speed and idle mixture. Washed enigne. Ground run and leak check OK I certify that this aircraft has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.	3.9		ach reads: 5	12.5 AFTT: 512.5	5 AIRFRAME				
Tarribo E. Farminati 7 to SET 6 10 T I/ 1 T T T T T T T T T T T T T T T T T T		iii g a n F p r	nterior compo- pear, and all re- peccordance we main wheels. Resecured jar- panel. Adjuste un and leak concertify that the irworthy concertify	onents as required related systems. So with FAR 91.207(d) Installed new braken nut on starter bed mixture cable to check OK wis aircraft has bee dition.	d to facilitate inspection. Inspected fuselage, wings, to Serviced and lubricated components and systems as). No defects noted. Battery due DEC 2025. Installed ricke linings on RH and LH brakes. Installed new hardar outton. Installed new lamp in tail nav light. Repaired re to assure proper travel. Checked idle speed and idle notes inspected in accordance with an ANNUAL inspection.	ail surfaces, cabin, cockpit, landing required. Inspected ELT in new Air Hawk tires on LH and RH re on muffler heat shroud. Einforcing strap for instrument mixture. Washed enigne. Ground			
		THE RESIDENCE OF THE PROPERTY OF THE PARTY O	Control of the Contro	COLUMN DE LINE DE CAMBRICA PROCESSOR					

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technic Facility. (See back pages for other specific entries.)
ada a a				J.H.Sanders Jr. Aviation Services LLC.
				1026 Consolidated Rd.
Barrier of				Elizabeth City NC,27909
The state of the s		DATE	6/25/2019	21일 : 사람들은 마른 사람들은 사람들은 사람들은 다른 사람들은 다른 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은
		Tach:		Aircraft total time since New:
		Insta detaInsta deta	ils. Illed Garm Illed Garm Ils.aircraft	o SL70 in 345R with Waas, see FAA form 337 this date for in GA35 waas antenna S/N: 156052. in G-5 S/N: 4JQ025577, see FAA form 337 this date for t ops checked on ground all temps/pressures normal, no this time. John H. Sanders Jr.3527277A&P

AR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Na	ame, Rating and Certificate Number of Technician or Repairs						
TE	Facility. (See back pages for other specific entries.)										
	ENGINE MO O-320-B2B ENGINE S/N REG. NO: NO WORK ORD	L-19626-39A 37BF	Aerodyne V	Aerodyne Corporation Repair Station No. HO1R-199K 5198 West Military Highway Chesapeake, VA 23321 USA Phone: (757) 488-2898	DATE: 7/8/2019 A/C TSN: 561.6 ENG TT: 561.6 TSMOH: 561.6 TACH: 561.6						
2.0	Engine E	ntries									
	contamination. Cleaned engine. Perf			lled 7 quarts of Phillips 20W-50 oil and Termed engine ground run. Operational and	empest AA48109 filter. Inspected removed filter. No leak check satisfactory.						
			was inspected a or return to serv	and repaired in accordance with current Federal	al Aviation Regulations, was found to be airworthy for the work						
	DATE: 7/8/	2019	SIGN	NED: GIR Smill	Work Order: 22400						
			J.R. Sr Certifie	mith ed Repair Station No. HO1R-199K	Printed by EBis 3 (datcomedia.com)						
		- (%)	2 (g) (m) (m) (m) (m)		STEELE REAL PROPERTY OF STEELE STEEL						
		200 A 100 A									
					10.10 (7.00 (1.00						

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician Facility. (See back pages for other specific entries.)
TH	IS STR 345 BEEN TEST	ED AND FOUREMENT	TRANSPOND OUND TO BE I S OF FAR 91.	

YE

DAT

MAKE: American Champion

MGDEL: 7GCAA S/N: 461-2002 REG. NO: N67BF

WORK ORDER: 22547

Aerodyne Corporation

Repair Station No. HO1R-199K 5198 West Military Highway Chesapeake, VA 23321 USA Phone: (757) 488-2898 DATE: 11/14/2019 A/C TSN: 600.2 TACH: 600.2

or Rep

Airframe Entries

(1) Completed Annual Inspection in accordance with manufacturer's recommendations and a checklist conforming to Title 14 Code of Federal Regulations Chapter 43, Appendix D......(2) Completed engine 100 hour inspection in accordance with the manufacturer's recommendations and a checklist conforming to Title 14 Code of Federal Regulations Chapter 43 Appendix D. Compression check: #1-78/80, #2-78/80, #3-78/80, #4-76/80. Cleaned, gapped and tested spark plugs. Checked ignition timing. Cleaned engine......(3) Completed propeller 100 hour inspection in accordance with the manufacturer's recommendations and a checklist conforming to Title 14 Code of Federal Regulations Chapter 43 Appendix D. Denicked blades......(4) The Ameri-King AK-450 s/n: 455298 ELT system installed in this aircraft was inspected and tested according to the applicable ELT manufacturer's instructions and the requirements of 14 CFR 91.207 d) and was determined to be in an airworthy condition. ELT BATTERY EXPIRES JANUARY 2022.....(5) Changed engine oil and filter. Installed 7 quarts of Phillips 20W-50 oil and Tempest AA48109 filter. Inspected removed filter. No contamination. Cleaned engine. Performed engine ground run. Operational and leak check satisfactory......(6) Installed new engine air induction filter.....(7) Installed new aircraft battery RG35-AXC.....(8) Removed, disassembled, cleaned and inspected left main wheel assembly. Greased wheel bearings. Reassembled wheel with new customer supplied AirTrac 8.00-6 tire and inner tube. Reinstalled left main wheel assembly onto aircraft......(9) Installed new brake disc and pads onto left main wheel assembly.......(10) Removed, disassembled, cleaned and inspected left main wheel assembly. Greased wheel bearings. Reassembled wheel with new customer supplied AirTrac 8.00-6 tire and inner tube. Reinstalled left main wheel assembly onto aircraft......(11) Installed new brake disc and pads onto right main wheel assembly......(12) Re-attached interior fabric near air vents in cockpit......(14) Removed, cleaned and inspected left magneto due to corrosion on impulse coupling. Performed IRAN inspection, removed corrosion, reset E-gap, installed new carbon brush. Reassembled, reinstalled and timed magneto to engine. Operational check satisfactory......(16) Installed new left fuel cap gasket.

The aircraft identified hereon was inspected in accordance with an ANNUAL INSPECTION, found to be in an AIRWORTHY condition and approved for return to service.

DATE: 11/14/2019

SIGNED:

Work Graet: 22547

Denise Eaton Certified Repair Station No. HO1R-199K Printed by EBis 3 (datcomedia.com)

YEAR:	ACE
DATE	Flight Solutions

ACE Flight Solutions

95 Aviation Way Fredericksburg VA 22406

S/N_ 461-2002	Tach Time:_680.1 hrs	Airframe To	otal Time:680.1 hrs_	
Replaced left wing lo	wer strut fairing with new part (sup	oplied by owner)		
	action boot at carburetor airbox wi		rackett Air filter element (8:	103-1).
	travel (28 +0/-1 degrees) and eleva			
	earing and race on right wheel and			
	e Letter 432 on rear folding seat by		ining lanvards with new (p/	n 2-2352).
HREE HAR TO HE MEN NOT NOT HE SEE HE H	it breaker on power wire for the G5			
	ollowing repetitive (due every 100h			
	loose items), SL 438 Fuselage Fram			
	ollowing Service Letters for one time			3 Front Se
	at Frame Truss, SL 439 Carburetor			
	ections done referencing Citabria s			ers.
	tion Check per FAR 91.207(d). Batt			
	Inspection referencing FAR 43, Ap			ervice.
Signed: John	Calhoon	Date:Dec 21, 2	2020	
10005 (\$1040) 145000 (\$1.50) \$20.00 \$				



ACE Flight Solutions

95 Aviation Way Fredericksburg VA 22406

Aircraft Registration: N67BF Aircraft Make & Model: American Champion 7GCAA S/N: 461-2002

Tach Time: 682.1 Airframe TT: 682.1

- Secured nickel alloy magnetic shielding to underside of plastic glare shield.
- Replaced airframe bonded main grounding bus, behind instrument panel, with insulated unbonded grounding bus. Secured all grounding wire terminals from old bus to new and ran a dedicated grounding wire from bus to airframe ground at main battery grounding strap.
- Removed defective compass and installed new, S/N 60470, of same P/N PAI-700.
- Installed magnetic compass balancing ball set on new compass, P/N PBB-475.
- Performed compass calibration and compass swing, using master sight compass calibrated 10/29/2020.
 Balancing balls secured in position with glue and marked with torque putty. Compass correction card created and secured to instrument panel.
 - Results as follows:

For:	N	30	60	Е	120	150	S	210	240	w	300	330
Steer	005	30	50	80	125	157	189	218	249	268	293	327

Work periormed referencing compass and aircraft manufactures data.

Signed: _______ Date: 12/29/2020

Name (Printed): Peter A. Diaz

A&P License Number: 4364085

	AGE Flight Solutions 95 Aviation Way Fredericksburg VA 22406 Airframe Flight Solutions						
	Aircraft Registration: N67BF Aircraft Make & Model: American Champion 7GCAA 5/N: 461-2002 Engine Make/Model: Lycoming O-320-B1B Engine S/N: L-19628-39A						
	Tach Time: 750 Airframe TT: 750						
	 Performed Annual Inspection per FAR 91 Part 43 App-D. Checked MLG Wheel, Tire and Bearings. 						
	Lubed tall wheel.						
	• CW SL 435, SL 438, CW SL 446, CW SL 428, CW SL 433, CW SL 437, CW SL 439,						
	 Lubed flight control hinges and linkage. Checked flight control cables and pulleys. 						
	This Airframe has been found to be in airworthy condition at this time. All work performed Ref. Champion MM, Ref. Lycoming MM, Ref. AC 43.13, Ref. Sensenich MM.						
	Signed: Muhael Burar Dec 8, 2021						
	Name (Printed): MIR HAEL CRESS & License Number: 3658304 IA						
Property of the second							

Model_G Model_ I certify to CFR 91.4 Federal A Pertinent W/O#_2 Signed_ Shenando	that the above 413 in accordance Aviation Agendetails of this 2110701 and Avionics,	transpond ince with conspection Date LLC. Rep	Position Position er(s) has been current Regula	eturn to service. this repair station under	ed with Name, Rating and Certificate Nurs for other specific entries.)	그녀는 아들 경우, 젊은 말이다. 아무로 생생님이 보고 얼굴 살아야 되었다면 하고 있다면 모양하는 것 같다.
				图12-13		
			100			
						1

YEAR:	RECORDIN TACH TIME	Soli Marine	Eagle's Nest Flight Services 249 Aero Dr. Waynesboro, VA 22980	Annual Inspection	nician or Repair
DATE			N67BF Airframe Date: 12-19-2022	Tach: 807.9 AFTT: 807.9	
		December 20 2024. Check air vents with with three-in inspection co Greased taily	ith recurring AD17-26-01 by inspection of 023. Installed new Duracell "D" batteries and ELT in accordance with 14CFR91.207 in MS20257-2 aluminum piano hinge. Report pinked tape and current Poly-Fiber finitivers. Installed steel shim on tailwheel movel bearings and swivel. Cleaned and report poly-Fiber finitives.	in ELT, replacement recommended by D (d). Replaced plastic hinges on both for paired minor fabric damage on forward be shes and processes. Tightened several lo ount, and replaced tailwheel mounting bo egreased all main wheel bearings.	December ward cabin belly fabric bose blt and nut.
		in airworthy	this aircraft was inspected in accordance vectoristion. Arthur W. Salating Arthur W. Sal		nined to be
		in airworthy	condition.		nined to be
		in airworthy	condition.		mined to be
		in airworthy	condition.		mined to be

EAR:	RECOR TACH TIME		249 Aero Dr.	Flight Services Waynesboro, VA 22980 Tame Date: 11-27-2023 Tach: 863.5 AFTT: 863.5 echnician or Repair
		by Novembrecommend Greased tai Checked the I certify that	per 2024. Check led to be replace lwheel bearings at elevator trave	AD17-26-01 by inspection of Ameri-King ELT per paragraph (g), due again ked ELT in accordance with 14CFR91.207(d). ELT batteries are ed by December 2024. Cleaned and regreased all main wheel bearings. and swivel. Secured loose cannon plug on back of turn coordinator. el stops complied with service manual values. as inspected in accordance with an annual inspection, and was determined to
				Salatin A&P 2221823 IA
_				
_				

YEAR:	RECORDING TACH TIME		Eagle's Nest Fligh 249 Aero Dr. Way	t Services mesboro, VA 2298)	Annual Inspection	ician or Repair
DATE			N67BF Airframe	Date: 12-5-2024	Tach: 909.8	AFTT: 909.8	
		(g), due aga connecting shipped in 2 with 14CFR and greased plate. Repa inspection h new T1032 I certify that be jn airwor	Inplied with recurring AD17-26-01 (Eff. 06-17-11) by inspection of Ameri-King ELT per paragraph due again by December 2025. New AD2024-21-02 (Eff. 12-5-24) regarding Lycoming engine necting rod failures does not apply to this engine per Table I to par. (c); complete engine was ped in 2002. Installed new Duracell alkaline "D" batteries in ELT. Checked ELT in accordance 14CFR91.207(d). ELT batteries are recommended to be replaced by December 2026. Cleaned greased all main wheel bearings, greased tailwheel and swivel. Replaced rivets in wing inspection at Repaired right wing root fairing attaching hardware as needed. Opened one previously unused ection hole in lower fuselage to lubricate rudder pedals, painted and installed cover plate. Installed T1032 clip retainers under forward belly panel where needed. Tify that this aircraft was inspected in accordance with an annual inspection, and was determined to airworthy condition. Arthur W. Salatin A&P 2221823 IA				
	7 4 73	3 10 2					-
	1/2 533						
					4 45 76		