



The Standard

PROPELLER LOG

ASA SPL

TRANSPORTATION USD \$6.95

ISBN 978-1-56027-418-6

50695 >



9 781560 274186

Propeller Record General Information

Propeller Manufacturer Hartzell

Model HC-E24R-1BF

Hub Series # DK646

Date of Manufacture _____

Type _____

Blade # _____

Serial # _____

Make/Model

Aircraft Installed On: Rockwell 112A

N1382

13000

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS



Year: _____
Date: _____
Next Due: _____

Make HARTZELL Model HC-E2YR-1BF
Serial Number DK646

The propeller identified above has been
REPAIRED/OVERHAULED/INSPECTED

In accordance with manual 113B
and is approved for return to service.
Details on file under work order and 8130-3 number 10099

Signature *[Signature]* 03/MAR/2022
Fosters Propeller Service Inc, Repair Station F3PR014N
26650 Hwy 62 Boynton, OK 74422 Ph. 918-733-2131
FOSTERPROPELLER@WINDSTREAM.NET FOSTERSPROPELLER.COM

Year: _____
Date: _____
Next Due: _____

Year: _____
Date: _____
Next Due: _____

Date: *July 23, 2022*
Next Inspection Due: _____
Time Since Overhaul: _____

Mech. Cert. # or Repair Station # _____

Was installed after overhaul by Fosters.
[Signature] 340097614

Year: _____	Total T in Serv _____
Date: _____	Time S Overhaul _____
Next Inspection Due: _____	
Year: _____	Total T in Serv _____
Date: _____	Time S Overhaul _____
Next Inspection Due: _____	
Year: _____	Total T in Serv _____
Date: _____	Time S Overhaul _____
Next Inspection Due: _____	

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Year: _____	Total Time in Service _____	Description _____
Date: _____	Time Since Overhaul _____	Mech. Cert. # or Repair Station _____
Next Inspection Due: _____		

Year: _____	Total Time in Service _____	Description _____
Date: _____	Time Since Overhaul _____	Mech. Cert. # or Repair Station _____
Next Inspection Due: _____		

Year: _____	Total Time in Service _____	Description _____
Date: _____	Time Since Overhaul _____	Mech. Cert. # or Repair Station _____
Next Inspection Due: _____		

DATE July 23 TACH 622.19
 I CERTIFY THAT THIS Prop HAS BEEN
 INSPECTED IN ACCORDANCE WITH 100hr
 INSPECTION AND WAS DETERMINED TO BE IN
 AIRWORTHY CONDITION AND WAS RETURNED TO
 SERVICE 34009767A
 Phillip O. Brenner BrenAir Inc.

DATE 8-25-21 TACH 622.32
 I CERTIFY THAT THIS Prop HAS BEEN
 INSPECTED IN ACCORDANCE WITH 100hr
 INSPECTION AND WAS DETERMINED TO BE IN
 AIRWORTHY CONDITION AND WAS RETURNED TO
 SERVICE 34009767A
 Phillip O. Brenner BrenAir Inc.

1 HC-E2YR-1BF

has been

INSPECTED

3B

service.

and 8130-3 number 10099

03/MAR/2022

Repair Station F3PR014N

422 Ph. 918-733-2131

FOSTERSPROPELLER.COM

over overhaul by Fosters.
34009767A

TRANSPORTATION USD \$6.95

ISBN 978-1-56027-418-6

