

A/C REG: C-FALD
 A/C MODEL: GBAIR 7T
 A/C S/N: 001

AFTT: 339.5hrs
 ETT: 2664.5hrs
 PTT: 339.5hrs

No.	Defect Rectification	Initial
1	Annual inspection C/Out IAW CAR 625.86 Appendix B&C	RL
2	First Aid Kit inspection C/Cout	RL
3	Recertification of ELT C/Out WO Handfield Aviation #22103174-16 (next battery due Nov 2022)	RL
4	Compass Calibration check & residual swing C/Out	RL
5	Fire Ex inspection & weight check C/Cout	RL
6	Engine 100hrs inspections C/Out IAW Rolls-Royce MM	RL
7	Engine Run, Leak check C/Out, No fault found	RL
8	Annual/150hrs Propeller check C/Out IAW MT Propeller E-610, No fault found	RL
9	Found tail cone fixing holes elongated. Tail cone repair IAW AC43-13, 1B Chap 4 WO Handfield Aviation #2210383-400	RL
10	Fire wall need to be repair, some unused holes need to be plugged. Holes plugged with stainless steel doubler IAW AC43-13, 1B Chap 4 WO Handfield Aviation #2210383-401	RL
11	R/H Elevator top skin loose rivets need to be replaced. All loose rivets replaced with next size rivet IAW AC43-13, 1B Chap 4 WO Handfield Aviation #2210383-402	RL
12	Found unused wires not cap and loose out of bundle. Wires cap and attach to bundle.	RL

FOR	N	030	060	E	120	150
STEER	003	033	063	092	212	151
FOR	S	210	240	W	300	330
STEER	180	212	242	270	302	333

I certify that that the maintenance described above has been performed in accordance with the applicable standards of airworthiness.

A/C Release: **Richard Langlois** **M733586** Date: 19 Apr 2021