



3330 AIRPORT LOOP  
SALISBURY, NC 28147  
INFO@SOUTHTECAVIATION.COM  
OFFICE: (704)-431-6862

DATE: DECEMBER 15, 2022 | Sensenich 2A0R5R70E | S/N: 228790G | REG: **N25HV**  
Tach: 771.8 HRS. TTE: 0.0 HRS.


Installed Propeller, new Sensenich 2A0R5R70E, two blade composite blades with metal edge.

Installed Propeller I/A/W Sensenich manual. Using Spacer B-1805-81 and using A-1269 extended Rotax Bushing. Propeller bolts BOLTS-AN5-50A. Track and balance checked. Started engine for check of proper operations of Propeller,

RETORQUED PROPELLER BOLTS.

PERFORMED SATISFACTORY ENGINE RUN UP. NO FAULTS NOTED.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN CONDITION INSPECTION AND WAS DETERMINED TO BE IN CONDITION FOR SAFE OPERATION

  
Glenn Lawler

A&P 2151829 IA