


The aircraft and or component identified below was repaired and inspected in accordance with current Federal Air Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under Work Order Number: 72245

Engine Model TSIO-550-G Serial Number: 915011

Date: 03/10/2017 Signed: *[Signature]*

F.A.A. ERS MW2R020L
1701 E. Main Street
Griffith, IN 46319
(219)924-7110



03/10/17 11:22:29 DISASSEMBLED, CLEANED, INSPECTED, REPAIRED PAGE 1
AS NEEDED, REASSEMBLED, & DYNO TESTED
USING THE FOLLOWING PARTS:

Item Num.	Item Description	Quantity
AA48109	Oil Filter	1
AS3578-016	O Ring	2
BQ7003	CAMSHAFT KIT OPTION 2	1
LW-16266-10-13	Clamp	6
MS29513-011	O Ring **	4
MS9970-116	O Ring	1
MS9970-117	O Ring	1
NAS1805-4	Nut-Selflocking	2
RG-632459	TCM V/C Gasket	12
RHB32E	Spark Plug **	12
S539800M15	Spring	1
X1473	Washer **	6
10-357520	Gasket	2
350998	Bushing **	8
501868	Washer Lock Tab	24
530658	Bushing	6
628556	Washer	2
629104	Ring	16
630680	Bearing	1
630979-11	O Ring	1
630979-14	O Ring	1
630979-24	O'Ring	1
630979-9	O Ring	1
632977-R	Shaft Housing - Reconditioned	6
633189	Plug	1
633958-2	Seal **	3
633958-3	Seal **	6
633958-5	Seal **	2
637817	Bearing - Ball	1
639193	Bushing	16
640612	Washer Flat	6
641250	Seal	1
641909	Tablock **	2
642398	Bearing	12
642644	Diaphragm	1
643584	Tube	1
643626-103	Pin	1
643626-104	Pin	2
643626-105	Pin	2
643629	Plate	4
646448-1	Washer	16
646550A1	Gasket Set	8
646592A2	Bearing Set	1
646605	Nut	1
649205	Bolts	6
649703	Piston Pin	4
649924	Nut	6
653171	Seal	1

ntenan
Directives, S
2010-11-14

END
MSB09-8A