


Book 3

MCCAWLEY™

**PROPELLER
OPERATOR'S
MANUAL
&
LOG**



**MPC-10, MPC-11, MPC-12,
MPC-13, MPC-14, MPC-15,
CMM500-1**

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
7/8/14	<i>[Signature]</i>	<i>[Signature]</i>	3A36C434-A	THIS PROPELLER WAS MANUFACTURED NEW AT McCAULEY PROPELLER SYSTEMS. INSPECTED AND FOUND TO BE AIR-WORTHY ON THIS DATE.	<i>[Signature]</i> 6050
		S/N	130978		

Registration	N513R	Make	McCauley
Hub S/N	130978	Model	3A36C434-A
TTP	0	Tach	4684.2
Date	8/2/2014		

This propeller was installed per McCauley instructions and STC SA00718CH. I certify that this new propeller installation was inspected in accordance with McCauley instructions and found to be in airworthy condition.



Authorized signature *[Signature]*
 Jeary Vogt IA 1915627
 Phone: 610-692-7106

PROPELLER BLADE LOG

PAGE NUMBER _____

Blade Model A-80VEA-0

Blade Serial No. A1D26032

Date	Total Time	Installed In Hub Model/Serial Number	Aircraft Type & Serial Number	Maintenance & Service History	Signature & Certificate Number
7/9/14	0				
		N513R	Tach: 4774.2	1/08/2021	
Annual inspection Prop,checked blade tightness,dressed blades with file,checked spinner and bulkhead for cracks.Shimmed spinner.I certify this propeller has been inspected iaw an annual inspection and found to be airworthy.					
		IA3686133			
		N513R	Tach:4791.3	2/02/2022	
Annual inspection Prop,checked blade tightness,dressed blades with file,checked spinner and bulkhead for cracks.I certify this propeller has been inspected iaw an annual inspection and found to be airworthy.					
		IA3686133	