



The Standard

PROPELLER LOG

ASA-SP-1

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
Date: 11/17/2011	Aircraft # N2161R McCauley	Serial # 911628	
Tach: 3640.33	Total Time: 664.33	SMOH: 664.33	

Next Insj

Comments:

Date

ANNUAL INSPECTION WAS COMPLETED ON McCAULEY PROPELLER D3A32C411-0 IAW FAR 43 APPENDIX D. NO AD'S TO THIS DATE APPLY TO THIS MODEL PROPELLER. I CERTIFY THAT THIS COMPONENT HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.

Next Insj

FERNANDO G. NUNEZ Certification # A&P 2749192 IA
 FOUR SEASONS AVIATION-ALBUQUERQUE, NM (KABQ)
 (505)307-3918

Fernando G. Nunez
 11/17/2011

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date: 05/01/2013	Aircraft # N2161R McCauley	Serial # 911628
Tach: 3645.33	Total Time: 669.33	SMOH: 669.33

Comments:

ANNUAL INSPECTION WAS COMPLETED ON McCAULEY PROPELLER D3A32C411-0 IAW FAR 43 APPENDIX D. DRESSED PROP. NO AD'S TO THIS DATE APPLY TO THIS MODEL PROPELLER. I CERTIFY THAT THIS COMPONENT HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.

FERNANDO G. NUNEZ
 Certification # A&P 2749192 IA
 (505)307-3918

Fernando G. Nunez
 5-1-13

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
Date: 02/25/2015	Aircraft # N2161R	McCauley	Serial # 911628
Tach: 3645.77	Total Time: 669.77	SMOH: 669.77	

Next Insp _____
Date _____

Comments:
ANNUAL INSPECTION WAS COMPLETED ON McCAULEY PROPELLER D3A32C411-0 IAW FAR 43 APPENDIX D. DRESSED PROP. NO AD'S TO THIS DATE APPLY TO THIS MODEL PROPELLER. I CERTIFY THAT THIS COMPONENT HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.


Next Insp _____
Date _____

FERNANDO G. NUNEZ
Certification # A&P 2749192 IA
(505)307-3918

Fernando Nunez 2/25/15

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

ATIONS



New Mexico Aero Service LLC
Licensed - Insured

New Mexico Aero Service LLC.

April 19, 2016 N2161R Tach: 3646.1 Hobbs: PTT: 670.1 PTSO: 670.1

Performed annual inspection per Title 14CFR chapter 43, appendix D. I certify that this prop has been inspected IAW annual inspection and was determined to be in an airworthy condition. I certify this propeller has been inspected IAW an annual inspection and was determined to be in an Airworthy condition. Details of work performed are on file with New Mexico Aero Service LLC. under work order: NMA_WO-8.

Fernando Nunez IA/AP 2749192 *Fernando Nunez*
4/19/16

McCAULEY, D3A32411-0, S/N: 911628 Propeller wo: NMA_WO-8

HUB

Date

Next Inspe

Date

Next Inspe

Date

Next Inspe



New Mexico Aero Service LLC • (505)307-3918

August 25, 2017 N2161R Tach: 3649.27 PTT: 673.27 PTSO: 673.27

Performed Annual inspection per Title 14CFR chapter 43, appendix D. I certify that this prop has been inspected IAW annual inspection and was determined to be in an airworthy condition. I certify this propeller has been inspected IAW an annual inspection and was determined to be in an Airworthy condition. Details of work performed are on file with New Mexico Aero Service LLC. under work order: NMA_WO-112.

Fernando Nunez IA/AP 2749192

[Handwritten Signature]

McCAULEY, D3A32411-0, S/N: 911628

Propeller

wo: NMA_WO-112

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

wo: NMA_WO-263

Propeller - page 1 of 1



New Mexico Aero Service LLC • (505)307-3918

N2161R McCAULEY, D3A32411-0, S/N: 911628 January 10, 2019

Tach: 3656.1 PTT: 680.1 PTSO: 680.1

1. Performed Annual inspection per Title 14CFR chapter 43, appendix D. I certify that this propeller has been inspected IAW annual inspection and was determined to be in an airworthy condition.
2. Propeller dynamically balanced with Dyna-vibe classic to .05 IPS. Added 12 grams weight @110.

With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with New Mexico Aero Service LLC. under work order: NMA_WO-263.

Fernando Nunez IA/AP 2749192

[Handwritten Signature]

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

