DATE	TACH TIME	DESCRIP	TION OF W	ORK			SI	GNATURE	
3/16/06	+1.Appoving National / Authority/Country FAA/UNITED ST  4. Organization Name STOCKTON PR 2478 WILCOX F STOCKTON, CX	IFICATE OVAL TAG	3. Form Tracking Number.  P3101  5. Work Order/Contract/invoice Number:  P3101						
	6. Item: 7. Desc 1 MCCA PROPE	ription: 8. Part Number: ULEY D3A34C402-C/	9. Eligibility:*	10. Quantity:	9620	83	12. StatusWork: OVERHAUL		_
	DISASSEMBLED, ALUMINUM PAR ADJUSTED, LUB WITH SB 119A, 1	CLEANED AND INSPECTED ALL. ITS REFINISHED, PENETRANT INS RICATED, BALANCED AND SAFETIE	PARTS, STEE PECTED, ALOU D. NO A.D. NO	L PARTS MA DINED AND I TES APPLY.	AGNAFLUXED PAINTED, NEW DE-ICEI	AND CA PROPELL RS INSTAL	DMIUM PLATED. ER ASSEMBLED,	L-10-14-14-14-14-14-14-14-14-14-14-14-14-14-	
	1	and are in a condition for safe operation.	Certifies that 12 and descr Code of Fede	unless otherwise ibed in Block 13	specified in Blo was accomplis	ck 13, the w	ork identified in Block ordance with Title 14, in the work, the items are		
	15. Authorized Signature  17. Name (Typed or Print		de	er Signature:	nd		oval/Certificate No: 07R333Y		
	ir. Name (Typed of Prin			L O. BELMO	NT		(m/d/y): 03/16/06		
		nd that the existence of this Document alone	does not automatic	ally constitute au	•				
	the country specified in Bi	erforms work in accordance with the national lock 1 it is essential that the user/installer en- y of the country specified in Block 1.	regulations of an a sures that his/her ai	ilrworthiness auth irworthiness auth	nority different th ority accepts par	an the alrwo rts/componer	rthiness authority of nts/assemblies from		
	issued in accordance with	and 19 do not constitute installation certificati the national regulation by the user/installer b	efore the aircraft ma	ay be flown.				<del></del>	
	FAA Form 8130-3 (6-01)	* Installer must cross check	eligibility with applic	abie technical da	ita	NSN:	0052-00-012-9005		

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
3/8/06	264.9		REMOVED PROPELLER	
			FOR CHERHAUL BY STOCKBOL PROPELER	Frank Lynna
			#UD7R333Y	AFP2497572
3/17/	6.764.9	0,0	INSTALLED OH PROP	
			JAW ACCALLEY SERVICE INSTRUCTIONS	Paul Lag
			* CESSNA MMM-	AP 297572
NOTE:	Enter Complia	nce With All Appli	cable FAA A.D. & Factory Service Bul	letins On Pages 11 & 12

Date	Date Total Propeller Time Description Of Work		Authorized Signatures Repairman and Station Certificate Numbers				
		Pro	p Log N32RL				
	I	Model McCauley	Ser. No. 962083				
	Date: 4/26/07	Total Time Pro	op: 350.2 Prop SOH: 85.3 Tach: 3	50.2			
— Dynamically balanced prop & spinner assy to 0.01 IPS with ACES balance equipment. By permanently							
installing 12.5gr in spinner bulkhead.							
Authorized Signature License No. Act 1826 Sc 4 TA  AERO RESOURCES, LEC 1000 Technology Dr., Ste. C, Columbia, CA 95310							
- AEF	O RESOURCES	, LEC 1000 Techn	ology Dr., Ste. C, Columbia, CA 95310				
-		Pr	op Log N32RL				
_	Model: M	cCauley D3A340	C402-C/90DFA-10 Ser. No. 9620	083			
	<b>Date: 8-1-07</b>	Total Time Pro	op: 369.6 Prop SOH: 104.7 Tach:	369.6			
Anr	ual inspection comp	oleted in accordance	with Cessna 206 Maintenance Manual. Checke	ed tach &			
<ul> <li>adjusted governor to set maximum rpm to 2700. Ops check satisfactory.</li> </ul>							
For AL	compliance, see A	D compliance list in a	urcraft records.				
I certify that this <i>engine</i> has been inspected in accordance with an <i>annual inspection</i> and was determined to be in <i>airworthy condition</i> , and is approved for return to service.							
in airw	orthy condition, and	is approved for retu	rn to service.				
AUINOR	zea Signature 📝 DESOUDCES LI	C1000 Tooknology	Dr. Ste. C. Columbia CA 95310	42114			

### **MAINTENANCE & SERVICE HISTORY**

Date	Total Propeller Time Description Of Work		Authorized Signatures Repairman and Station Certificate Numbers	
For I cer in ai	Date: 8/1 Annual inspection condition condition configuration and the second condition and the second condition are second condition.	McCauley D3A3 4/08Total Time P completed in accordance and is approved for re	rop: 414.8 Prop SOH: 149.9  e with FAR 43 Appendix D. Ops check in aircraft records.  a accordance with an annual inspection eturn to service.  License No. A-D > \$2	and was determined to be
AEF	RO RESOURCES,	ALC 1000 Technolog	gy Dr., Ste. C, Columbia, CA 95310	

Date	Total Propeller	Time		Authorized Signatures			
Date			Prop Log N32RL				
9-22-09	M	odel: McCaule	y D3A34C402-C/90DFA-10	Ser. No. 962083			
1 7/20/	Date	: 9-30-09 Total	Time Prop: 492.3 Prop SOH	I: 227.4 Tach: 2089.4			
	Annual inspec	ction completed in	accordance with FAR 43 Appendix D	. Ops check satisfactory.			
	For AD compliance, see AD compliance list in aircraft records.  I certify that this engine has been inspected in accordance with an annual inspection and was determined to be						
	in airworthy condition, and is approved for return to service.  Authorized Signature 12.4 License No. A 2/3053 772 IA						
	AERO RESOU	RCES, LLC 4000	Technology Dr., Ste. C, Columbia, C.	A 95310			
<b></b> ,			Prop Log N32RL				
	Mo	del: McCaulev	D3A34C402-C/90DFA-10	Ser. No. 962083			
	Dates	10-5-10 Total	Time Prop: 525.7 Prop SOF	I:260.8 Tach:2122.8			
İ	Annual inspect	ion completed in a	ccordance with FAR 43 Appendix D.	Ops check satisfactory.			
	E- AD compliance see AD compliance list in aircraft records.						
NOTE	I certify that this e	engine has been insp	pected in accordance with an annual i	inspection and was determined to be			
NOTE:	in airworthy cond	<i>lition</i> , and is approv	ved for return to service.				
8	Authorized Signat	ure The	Echnology Dr., Ste. C, Columbia, CA	95310			

### **MAINTENANCE & SERVICE HISTORY**

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Repairman and	Authorized Signatures Repairman and Station Certificate Numbers	
			Prop Log N32RL			
	Me	odel: McCaulev D	3A34C402-C/90DFA-10 Ser. No. 9	62083		
			ne Prop: 575.0 Prop SOH:310.1 Ta			
			nce with FAR 43 Appendix D. Ops check			
		ee AD compliance lis				
I certify that this <i>engine</i> has been inspected in accordance with an <i>annual inspection</i> and was determined to be						
in <i>a</i>	airworthy condition	, and is approved for	return to service.			
Au	thorized Signature	Mr 03ms	License No. A V 287 logy Dr., Ste. C, Columbia, CA 95310	SOLYIA		
AE	RO RESOURCES	S, LLC 1000 Techno	logy Dr., Ste. C, Columbia, CA 95310		N	
□   Pr	op Log N32RL	Model: McCauley		o. 962083		
—   Da	ate: January 19, 20	113 Total Time	Prop: 637.1 Prop SOH: 372.2	Tach: 2234.2		
Annual Inspection completed IAW FAR 43 Appendix D.						
For AD compliance, see AD compliance list in aircraft records. I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition, and is approved for return to service.						
	th an Annual Inspection	and was determined to be	in Airworiny Condition, and is approved for return	777 1/4		
$\mathbf{O} \mid Ai$	ithorizea Signature	C 1000 Tobboology	Dr., Ste. C, Columbia, CA 95310	151	1 & 12	
A	とない KESUUKCE	is rood recimology	Dr., Bio. C, Columbia, Cr. 75510			

Date	Prop Log N32RL Date: March 3, 2014 Annual Inspection con	Model: McCauley D3A34C4 Total Time Prop: 683.1 npleted IAW FAR 43 Appendix	Prop SOH: 418.2	per	ion			
	For AD compliance, see AD compliance list in aircraft records. I certify that this Propeller has been inspected in accordance							
	with an Annual Inspection and was determined to be in Airworthy Condition, and is approved for return to service.  Authorized Signature License No. 1 4733772   A  AERO RESOURCES 1000 Technology Dr., Ste. C, Columbia, CA 95310							
	AERO RESOURCES	S 1000 Technology Dr., Ste. C,	Columbia, CA 95310		-			
_	D I N/22DY	MIMING	I P2121C102 C	G N 0/0003				
	Prop Log N32RL Date: June 1, 2015	Make/Model: McCau Total Time Prop: 730.3	•	Ser. No. 962083 —— Tach: 2327.4				
		npleted IAW FAR 43 Appendix						
	with an Annual Inspection	D compliance list in aircraft records. and was determined to be in Airworthy		eturn to service.				
:	AERO RESOURCES	S 1000 Technology Dr., Ste. C,	Columbia, CA 95310	105011211				
	1							
NOTE:	Enter Compliance	With All Applicable FAA	A.D. & Factory Service	Bulletins On Pages 11 & 1	12			

10

#### F.A.A. AIRWORTHINESS DIRECTIVE AND SERVICE BULLETIN/ LETTER COMPLIANCE RECORD

Dat	Prop Log N32RL	Make/Model: McCauley D		Ser. No. 962083 Tach: 2349.0	atures				
Dat	Date: August 10, 2010	Total Time Prop: 751.9	Prop SOH: 487.0	1acii. 2549.0	4 .				
	<ul> <li>Annual Inspection compl</li> </ul>	eted IAW FAR 43 Appendix D.			ibers				
	En AD compliance see AD c	ompliance list in aircraft records   Leer	tify that this Propeller has bee	n inspected in accordance					
	with an Annual Inspection and was determined to be in Airworthy Condition, and is approved for return to service.								
	Authorized Signature Market License No. 1 17 1053 172 1/4								
	AERO RESOURCES 1	000 Technology Dr., Ste. C, Colum	mbia, CA 95310 '	·					
	ALKO ILEGO CITO								
	Prop Log N32RL	Make/Model: McCauley D3	A34C402-C S	er. No. 962083					
	Date: August 15, 2017	Total Time Prop: 790.4	Prop SOH: 525.5	Tach: 2387.5					
	Date: August 15, 2017			-					
	Annual Inspection complete	ed IAW FAR 43 Appendix D.  pliance list in aircraft records. 1 certify	that this Propeller has been ins	spected in accordance -					
:	For AD compliance, see AD com	vas determined to be in Airworthy Condition	on and is approved for return to	service.					
	with an Annual Inspection and v	As determined to be in the world, commended	cense No. A 3V 305	3772 1A -					
1	Authorized Signature	Sto C Colum	hia CA 95310						
	AERO RESOURCES 100	00 Technology Dr., Ste. C, Colum	01a, CA 95510						
L_,		35 1 25 1 1 DC 1 D242	4C402 C Sov	No. 962083					
	rop Log N32RL	Make/Model: McCauley D3A3		I					
D	ate: October 20, 2018		Prop SOH: 556.7 Tac	ch: 2418.7					
A	nnual Inspection completed	IAW FAR 43 Appendix D.		<u> </u>					
F.	y AD compliance see AD complia	nce list in aircraft records. I certify that	this Propeller has been inspec	ted in accordance					
wi	th an Annual Inspection and was o	letermined to be in Airworthy Condition, a	and is approved for return to ser	vice.					
- $A$	uthorized Signature	2 Homoson Licen.	se No. 1721 705317	/ <u>2_1/4_</u>					
A	ERO RESOURCES 1000	Technology Dr., Ste. C, Columbia	, CA 95310		11				

F.A	Prop Log N32RL	Make/Model: McCauley D3		Ser. No. 962083	ETIN
	Date: December 16, 2019	Total Time Prop: 830.2	Prop SOH: 565.3	Tach: 2427.3	
	Annual Inspection completed	IAW FAR 43 Appendix D.			
Dat	with an Annual Inspection and was Authorized Signature	determined to be in Airworthy Condition  Technology Dr., Ste. C, Column	on, and is approved for return cense No.	m to service.	gnatures I Station ambers
		• •			
	09/01/2021 Cessna U206G N3	32RL S/N U20605551 – Tach: :	2446.3 Prop TT 849.2	TSMOH 584.3	
	Tracked and dressed blades				

All work performed IAW the Cessna and McCauley service manual.

I certify that this propeller has been inspected AW an annual inspection as per Cessna and McCauley service manual and FAR's and was determined to be in Airworth condition.

Jejoen Bakker A&P Mechanic # 2539593

	_			· .	
1					
1			1		
	1	i			
	1		i i		
4			l l		

12

12/06/2022

U-206G

N32RL SN: U2060551

Current Tach: 2455.4

Propeller TT: 858.3 SMOH: 593.4

Checked spinner and back plate for cracks and distortion. Checked blades for nicks. No anomalies noted at this time.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition at this time and date only.

Greg Ference A & P Mechanic 3920219 IA

Date: 06/11/2024

Hours: Current tach time: 2456.2 PTT:858.3 SMOH:593.4

Tail#: N32RL

Make: McCauley

Model: G-90DFA-10

S/N: 962083

(Annual inspection) Inspect spinner and back plate cracks and distortion. inspect blades. replaced de-ice tape at root of blades. P/N B-40531. I certify that this propeller has been inspected IAW with an annual inspection and was found to be in airworthy condition at this time.

Greg Ference A&P mechanic 3920219 IA