

**N284BC**

**PROPELLER**

**LOGBOOKS**

**Next  
Due:**

11  
a  
B

AP3681757IA

# EPIC AERO

10/13/2020 N284BC Rans S20  
 S/N: 12140030 TTAF: 261.5 Eng Hrs: 169.2  
 Propeller: Whirlwind RZ3B-RZ3 S/N: 1164

1. Performed prop. 100hr. Inspection IAW FAR 43 Appendix D referencing Rans Condition Inspection Requirements.  
 I Certify this Propeller has been Inspected IAW a Condition inspection and found to be in Airworthy Condition.

Matthew Retzer  A&P3669005

Due:	Overhaul	Mech. Cert. # or Repair Station #
Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #

# EPIC AERO

3/23/2021 N284BC Rans S20  
 S/N: 12140030 TTAF: 346.4 Eng Hrs: 220.0 Prop. TTSN: 346.4

1. Performed a TTAF and Engine Hour Meter Reprogram to correct a programing Issue From a Past update.  
 The Correct AFTT and Engine Times are as Stated above and the Hour Meters have been set IAW the  
 Garmin G3X Installation Manyal.

Matthew Retzer  A&P3669005IA

# EPIC AERO

03/03/2022 N284BC Rans S20  
 S/N: 12140030 TTAF: 370.7 Eng. Hrs.: 236.7  
 Propeller: Whirlwind RZ3B-RZ3 S/N: 1164 PTT: 236.7

1. Performed prop. 100hr. Inspection IAW FAR 43 Appendix D referencing Rans Condition Inspection Requirements.  
 I Certify this Propeller has been Inspected IAW a Condition inspection and found to be in Airworthy Condition.

Matthew Retzer  A&P3669005

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS



07/27/2024 N284BC Rans S20  
S/N: 12140030 TTAF: 570.3 Eng. Hrs. : 413.2  
Propeller: Whirlwind RZ3B-RZ3 S/N: 1164 PTT: 310.0

1. Performed prop. 100hr. Inspection IAW FAR 43 Appendix D referencing Rans Condition Inspection Requirements.  
I Certify this Propeller has been Inspected IAW a Condition inspection and found to be in Airworthy Condition.

Matthew Retzer

A handwritten signature in black ink, appearing to read "Matthew Retzer".

A&P3669005

Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #
Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #