

Cessna[®]



AIRCRAFT LOG

AND MAINTENANCE RECORD

N 9650X

SERIAL NO. 21657950



AIRCRAFT LOG AND MAINTENANCE RECORD

Record of	<u>Cessna</u>	<u>210</u>	<u>21057950</u>	<u>N 9650X</u>
	Make	Model	Serial	Certificate
With Engine	<u>Continental</u>	<u>IO-470-S</u>	<u>109066-7-SR</u>	
	Make	Model	Serial	
From		<u>19</u>	to	<u>19</u>
Detailing Time From			To	
		Hours		Hours
Owner				
Address				

VOR Receiver operation checked in accordance with FAR 91.25				DATE	REMARKS
Date	Bearing error VOR 1 VOR 2	Place	Signature	19 ____	
					4-7-67 annual insp Time 6 44 hrs AD notes checked through 6-7-8 Date <u>4-7-67</u> T. Time <u>6 44 hrs.</u> I certify that this aircraft has been inspected in accordance with <u>annual</u> inspection and was determined to be in air- worthy condition. Name <u>Levin B. Paine</u> Auth. Insp. A/P 449276 9-20-67 Time 674 Ins noted new vore time YAP done 46E 449276

Enter here general data with reference to "Line" and "Periodic" inspections - Rigging Changes - Alterations - Repairs - Service Letters - and changes in propeller or engine - as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.

[illegible]

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

[illegible]

[illegible]

AIRCRAFT LOG

[illegible]

AIRCRAFT LOG

[illegible]

[illegible]

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25				DATE	REMARKS
Date	Bearing error VOR 1 VOR 2	Place	Signature		
				19 ____	Enter here general data with reference to "Line" and "Periodic" inspections — Rigging Changes — Alterations — Repairs — Service Letters — and changes in propeller or engine — as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
25	761375	TACH	242.08		A/C TT 1193:48 AIRSPEED INDICATOR - ALTIMETER - Rate of Climb TESTED & CALIBRATED By AIR MARINE SALES INSTALLED FAR 91.170 Complied with, REPLACED NOSE WHEEL BEARINGS CLEARED WHEEL REPLACED TIRE & TUBE REPLACED RH MAIN TUBE REPLACED RH MAIN TIRE & TUBE. RESEALED BOTH BRAKES INSTALLED NEW LINING: REPLACE BOTH FUEL CELLS FWD STRAINER CAP ADAPTER & CAPS REPLACED RH TANK TRANSMITTER: REPLACED RADIO SPEAKER: INSTALL NEW BATTERY.
5	MAR 75	TACH	242.08		I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED in ACCORDANCE with AN ANNUAL INSPECTION and determined TO BE IN AIRWORTHY condition AD NOTE CHECK THEN CARD 75-2 U.S. D. Hq. - AP 1853405 7 MAR 75 TACH 242:08 COMPASS OVERHAULED BY AIR MARINE SALES # 708-24 COMPASS swing OK U.S. D. Hq. - AP 1853405

[illegible]

19

[illegible]

AIRCRAFT LOG

DATE	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME		SIGNATURE OF PILOT
					HOURS	IOths	
1976-77							
	I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.						Serviced battery, brakes & retraction test on gear OK Jack Steffen
	25 Sept 76 Time in service 1224 hrs						New ELT battery installed June 77
	Jack Steffen	IA 1011252	Tach Time	274 hrs			
1978	Installed Gear Ext Kit 1209000-1 R&L to C/w AD 76-04-01. Also installed new gear struts P/N 12910041 & 2 to C/w AD 76-14-07 A/c Time 1229 hrs						
	Nose gear actuator overhauled & replaced flap by 6 wires. Jack Steffen IA 1011252						
	Fuel tank AD 78-05-02 N/A New tanks installed 75						
	I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.						
	1 July 78 Time in service 1229 hrs						
	Jack Steffen	IA 1011252	Tach Time	279 hr.			

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25				DATE	REMARKS
Date	Bearing error	Place	Signature		
	VOR 1	VOR 2		19	
					THE TRANSPONDER(S) IDENTIFIED BELOW HAVE BEEN INSPECTED AND MEET ALL REQUIREMENTS CONTAINED IN FAR 91.177 AND FAR 43 APPENDIX F.
					No. 1 S/N 22030 No. 2 S/N N/A
					TECHNICIAN C. Chapman DATE 22/07/78
					INSPECTOR C. Chapman 296-18-1066 DATE 22/07/78
1979					New ELT Battery installed Jan 79 EIT Ser # 15711 March
					Repacked nose gear strut Jan 79 Jack Steffen IA 1011252
					AD 71-16-5 N/A 79-08-03 N/A & AD 79-10-14 P/cw
					I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.
					17 July 79 Time in service 1239 hrs TT Tach Time 289 hrs
					Jack Steffen IA 1011252

DATE	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME		SIGNATURE OF PILOT
					HOURS	IOTHS	
1980							
THE TRANSPONDER(S) IDENTIFIED BELOW HAVE BEEN INSPECTED AND MEET ALL REQUIREMENTS CONTAINED IN FAR 91.177 AND FAR 43 APPENDIX F.				AIR ADS OF DAYTON B800 CLEARVIEW DR. DAYTON, OHIO 45439			
No. 1 S/N	22030	No. 2 S/N	N/A	EAA CRS C05-11 RADIO SHOP			
TECHNICIAN	C. Chapman	DATE	02 July 80				
INSPECTOR	C. Chapman	DATE	02 July 80				
Annual Insp Comp This Date. Checked controls serviced battery ELT batt on order Lubed where necessary. Gear swing OK AD 79-15-01 NA 79-25-07 NA 80-09-09 NA							
I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition,						ELT battery replaced July due Jan 82	
23 July 80 Time in service 1261.7 hrs T24 Time 311.7 hrs							
James R. Stefanie IA 1011252							
CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE							

19 *so*

VOR Receiver operation checked in accordance with FAR 91.25				DATE	REMARKS
Date	Bearing error VOR 1 VOR 2	Place	Signature		
				19 <u>81</u>	Enter here general data with reference to "Line" and "Periodic" inspections - Rigging Changes - Alterations - Repairs - Service Letters - and changes in propeller or engine - as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.
		<u>7-31-81</u>			FAR 91.177 complied with this date. Transponder(s) checked as per Appendix F, Part 43 of Federal Air Regulations. <u>Brad Pruitt</u> Ref W.O. 802038 for Capital Aircraft Electronics FAA Repair Station #1106A
<u>7-31-81</u>					Installed KMA-24, KX170B, KR86, KI209, KI208, KN75. Removed KX160, MP400, 204A, anal Audio amp. See FAA form 337 for details, dated 7-31-81
					NEW E.W. 1860.55 NEW MOM 62307.572 NEW EWCG 33.99 NEW Useful 1139.45
					<u>R.L. Pinter</u> CAPITAL AIRCRAFT ELECTRONICS, INC. 4808 East Fifth Avenue P. O. Box 19741 AMF Columbus, Ohio 43219 CRS 1106

AIRCRAFT LOG

DATE	FLIGHT FROM	TO	NATURE OF FLIGHT	DURATION OF FLIGHT	ACCUMULATED TOTAL FLYING TIME		SIGNATURE OF PILOT
					HOURS	IOths	
19							
6 Aug 81	Ann-21 Insp Comp		This date Checked controls, cables, lubed zerks, Gear swing OK. Checked battery, brakes & serviced cylinders. No A.D's				
			I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition,				
6 Aug 81	Time in service	1297.5 hrs	Tach 347.5 hr				
	John R. Stefanis	IA 1011252					
21 Sept 81	Replaced wheels & brakes with Cleveland	STC # SA 5292	Kit # 199-60				
	No weight & balance change	Tach time 350.5 hr	John R. Stefanis	IA 1011252			
3 Nov 81	Replaced Seat belts with metal to metal latches						John R. Stefanis IA 1011252
March 82	Replaced ELT Battery Due to 483						
CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE							

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25				DATE	REMARKS
Date	Bearing error	Place	Signature		
	VOR 1	VOR 2		19	
5-25-82					Installed King KW-64 DME + King KA-60 DME Antenna. See FAA Form 337 for details dated this date
					New Moment 62372.212 CAPITAL AIRCRAFT ELECTRONICS, INC.
					New E.W. CG 33.47 FAA Repair Station #1100
					New Useful load 1136.85
					New Empty Weight 1863.15 QZ Pinter
				12 Aug 82	Annual Insp Comp this date. Checked controls, brakes, serviced battery, cylinders, lubed zerks.
					I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition,
				12 Aug 82	Time in service 1317.7 hrs Tach 367.7 prop 86.7 hrs
					John R. Stefanis IA 1011252
				16 May 83	Tach 390.8 hr New Fuel Transm. the inst. Left tank Both LT & RT Fuel tank reservoirs cleaned, repaired & quick drains installed. John R. Stefanis IA 1011252
This is to certify that this Altitude measuring system has been tested and insp. to 22,000 ft. and found to comply with appendix E, Part 25, FAA Regulations. This date 9/1/83					
VELTRON CO.					
CRS NO. C05-17					
JAMESTOWN, OHIO 45335					
John R. Stefanis					

MEMORANDA

Date 8/2

I certify that the transponder check
as required by FAR 91.172 has been

performed. S/N 22030

Test Date 8/2/83

Signature Robert J Paul

Clinton Co. Avionics, Inc.

C05-30

10 Aug 83 Annual Insp. Completed this date. Repacked nose wheel bearings,
Lubed Zerk, Serviced Hydraulic systems. Checked battery Gear Swing OK.

76-1407 c/w p/g C

I certify that this aircraft has been inspected
in accordance with an annual inspection and
was determined to be in airworthy condition.

10 Aug 83 Time in service 1367.7 hrs Tach Time 417.7 Prop 136.7 hrs

Jesse R. Stefarnis IA 1011252

ELT battery replaced due Sept 85

~~ADS~~ Completed with ^{Next page} MEMORANDA

Date

~~11 May 88~~

~~67-31-5~~

~~68-8-1~~

Tach 422 hrs

17 Oct 83 Installed FT100 Fuel Flow Indicating System in accordance with STC

SA 3835 WE NO W&B change Indicator weight only 502 gms. Refin IA 1011252

20 Aug 84 Replaced battery, Serviced Hydraulic Syst. Checked controls, Lubed,
Swing Gear, Serviced brake cyls. Checked gearbox saddle etc. AD 84-101 c/w

I certify that this aircraft has been inspected
in accordance with an annual inspection and
was determined to be in airworthy condition,

15 Sept 84 Time in service 1386.6 hrs Tach 436.6 Prop 155.6 hrs

Jesse R. Stefarnis IA 1011252

11 Oct 84 Installed New Directional Gyro Ser# 40365 gms. Refin IA 1011252

22 Aug 85 changed LT tire Adj Gear down for doors, swing gear OK gms. Refin IA 1011252

MEMORANDA

[illegible]

Victor Three Aviation, Inc.

DRAWER 217
TITUSVILLE, FLORIDA 32780
(305) 269-6840

AIRWORTHINESS DIRECTIVE COMPLIANCE RECORD

Aircraft Make CESSNA Model 210B Ser. No. 2105
Engine Make Cont Model IO-470-S Ser. No. 1090
Prop. Make McCoy Model D2A-36C-35 Ser. No. 62
Appl./Comp. Make _____ Model 34C580 Ser. No. _____

AD Number	Subject	Date & Hrs. at Compl.	Method of Compliance	1-Time	Recurr.	Aut and
69-8-11	FUEL BOOST PUMP		N/A			wh AP
71-9-7	EXHAUST IN CABIN		N/A			wh AP
71-24-4	HOSE		N/A			wh AP
71-24-7	MAIN GEAR EXT		N/A			wh AP
72-3-3	FLAP		N/A			wh AP
72-7-9	RUDDER		N/A By A/C S/N			wh AP
74-08-01	ARC AUTO PILOT		N/A			wh AP
70-14-7	CONT		N/A			wh AP
72-20-2	CONT		N/A			wh AP
74-24-13	UNITED ALTIMETER		N/A By MFC			wh AP
74-18-05	Stick Mzy	1 July 78	N/A Mzy repl 2			ge IA
76-04-01	Ld. 1229 hrs Gear Ext. Kit	Tech 279 1 July 78	R4L Installed Kit 1209005 V			ge IA
76-14-07	Ld. Gear 5 2d Ld 1229 hrs	Tech 279 1 July 78	Installed new rddls 1241004-18-2			ge IA
77-16-05	Fuel Valve	1 July 78	N/A			ge IA
78-05-06	Fuel Tanks	1 July 78	N/A Fuel Cells Replaced 1975			ge IA
79-08-03	Circuit lighter wiring change	12 July 78	N/A Serial #			ge IA
79-10-14	Fuel Cap & Vents	12 July 79	P/c/w			ge IA



FLITE CENTER