

HARTZELL

Bill Weber
Pitts SIT
N6RX

Propeller Owner's Manual & Log Book

#1

AIRCRAFT
ownership
solutions 765-456-1772

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4-26-91	79.6	REMOVED GOVERNOR FOR S/A D4370TJ	
		FOR bench check & RPM check OK	
		REINSTALLED GOVERNOR S/A D4370TJ	
		HARTZELL REPAIR Station #SJ3R843L	
		R. Bailey REPAIRMAN CERT #2397411	
4-26-91	79.6	DYNAMICALLY BALANCED PROP	
		S/A DN3604 START 2 IPS.	
		FINISHED .05 IPS	
		HARTZELL REPAIR Station SJ3R843L	
		R. Bailey REPAIRMAN CERT #2397411	

5-14-91	82.0	Completed Annual Inspection	
		EW AD 90-02-23 E-Poser 1468367 AI	
5-12-92	117.4	Completed Annual Inspection	
		EW AD 90-02-23 E-Poser 1468367 AI	
5-26-93	147.8	Completed Annual Inspection	
		EW AD 90-02-23 E-Poser 1468367 AI	
6-9-94	165.0	Completed Annual Inspection	
		EW AD 90-02-23 E-Poser 1468367 AI	

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
6-29-95	187.8	Completed ANNUAL INSPECTION	E. Passero 1468367 AT
		EW AD 90-02-23	
5-17-96	203.2	Completed ANNUAL Inspection	
		EW AD-90-02-23 Chris Passero 1468367 AT	
5-26-97	209.2	Completed Annual Insp	
		EW AD-90-02-23 E. Passero 1468367 AT	
5-22-98	216.8	Completed Annual Insp	
		EW AD 90-02-23 E. Passero 1468367 AT	
		TOTAL 221.6 TIME Since New	5-3-99
		THAT THIS Propeller HAS BEEN INSPECTED IN ACCORDANCE WITH AN	
		Annual INSPECTION PROCEDURE AND WAS DETERMINED TO BE IN AN	
		AWORTHY CONDITION AT TIME OF ENSP.	
		EW AD # 90-02-23 DELCIN	
		Hub Cracks By Visual AP20482857 IN	

6-12-09 227.6 Completed Annual

6-12-00 Inspection

EW AD 9002-23

Chris Passero

1468367 AL

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
06-01-01	232.4	Accomplished on Annual Inspection CW AD 90-02-23	
		Charles Passero 1468382 AI	